



CAMP SYSTEMS INTERNATIONAL, LLC
LONG ISLAND MAC ARTHUR AIRPORT
999 MARCONI AVE.
RONKONKOMA, NY 11779


POSTAL

R&S AIRCRAFT INVESTMENTS, LLC
ATTN: YANDELL ROGERS III
P.O. BOX 43
HOUSTON, TX 77001-0043

ModelName: 1124A WESTWIND 368

RegNo: N368MD

1124 WESTWIND



WORK COMPLIANCE FORMS

CAMP

Aviation from the ground up™

OWNER: R&S AIRCRAFT INVESTMENTS, LLC
ADDRESS: P.O. BOX 43 HOUSTON TX 77001-0043

OPERATOR: R&S AIRCRAFT INVESTMENTS, LLC
ADDRESS: P.O. BOX 43 HOUSTON TX 77001-0043

PHONE: 713-830-9584
FAX: 713-918-5925

PHONE: 713-830-9584
FAX: 713-918-5925

PROJECTED : 2 MOS. to 14-MAY-2002

AIRCRAFT

S/N: 368 **REG NO:** N368MD **MODEL:** 1124A WESTWIND **MANUFACTURER:** GULFSTREAM AEROSPACE CORPORATION

NOTE:
INSPECTION PROGRAM: 3
CERTIFICATE DATE: 11-FEB-1982

UOM	LAST ACTUAL	LAST ACTUAL DATE	PROJECTED
HRS	7806	28-FEB-2002	7895.2
AFL	5706	28-FEB-2002	5795

ENGINE NO. 1

S/N: P-77482 **PART NO:** 3072500-2 **MODEL:** TFE731-3 **MANUFACTURER:** HONEYWELL

INSTALLED DATE: 4/3/1989
A/C HRS: 4215
ENGINE HRS: 3972
ENGINE CYCLES: 2456

UOM	LAST ACTUAL	LAST ACTUAL DATE	PROJECTED
HRS	7806	28-FEB-2002	7895.2
ENC	0		0
(AFL)	5706	28-FEB-2002	5795

ENGINE NO. 2

S/N: P77488 **PART NO:** 3072500-2 **MODEL:** TFE731-3 **MANUFACTURER:** HONEYWELL

INSTALLED DATE: 5/31/1993
A/C HRS: 5278
ENGINE HRS: 5227
ENGINE CYCLES: 3867

UOM	LAST ACTUAL	LAST ACTUAL DATE	PROJECTED
HRS	7806	28-FEB-2002	7895.2
ENC	0		0
(AFL)	5706	28-FEB-2002	5795



Maintenance Due List/Time Remaining - AIRCRAFT(CALENDAR)

Aircraft Model - 1124A WESTWIND

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORK CARD WORK ORDER	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL TIME-----AT-----INSTALLATION COMPLIANCE				DISPOSITION NEXT DUE (ENH) AFH (xEXT)	TIME REMAINING OVD = Overdue	AREA PRICE LABOR
			TSN	TSO	TSR	WARR EXP			
AD 2000-15-09	NO. 1 ENGINE - HPC IMPELLER AIRWORTHINESS DIRECTIVE						10-OCT-2000	New Reqmt	
	REF:	DUE NEXT	MOS HRS/MSC ENC	4200					
AD 2000-15-09	NO. 2 ENGINE - HPC IMPELLER AIRWORTHINESS DIRECTIVE						10-OCT-2000	New Reqmt	
	REF:	DUE NEXT	MOS HRS/MSC ENC	4200					
260169 26.060	VISUAL INSPECTION COCKPIT PORTABLE EXTINGUISHER COCKPIT FIRE EXTINGUISHER		DAYS HRS/MSC AFL	30		06-NOV-2001 7774 5641	06-DEC-2001	OVD	F3
	REF: NO REF								
260180 26.060	VISUAL INSPECTION CABIN PORTABLE EXTINGUISHER CABIN FIRE EXTINGUISHER		DAYS HRS/MSC AFL	30		06-NOV-2001 7774 5641	06-DEC-2001	OVD	F3
	REF: NO REF								
330228 33.100	CHARGE EMERGENCY LIGHT BATTERY		MOS HRS/MSC AFL	3 200		06-NOV-2001 7774 5641	06-FEB-2002 7974	OVD 168	F4
	REF: AMM 12-10-06								
344616 34.370	INSPECT EMERGENCY GYRO POWER SUPPLY BATTERY EMERGENCY POWER SUPPLY BATTERY/STAND-BY ATTITUDE GYRO		MOS HRS/MSC AFL	3 200		06-NOV-2001 7774 5641	06-FEB-2002 7974	OVD 168	F5
	REF: AMM NO REF								
320118 32.540	INSPECT/LUBRICATE NOSE GEAR ASSEMBLY UPPER/LOWER STRUT BEARINGS BODY		MOS HRS/MSC AFL	24 1200		22-FEB-2000 7107 5232	22-FEB-2002 8307	OVD 501	L3
	REF: AMM 32-20-01								
230400 23.130	CLEAN/TEST COCKPIT VOICE RECORDER BEACON		MOS HRS/MSC AFL	6		06-NOV-2001 7774 5641	06-MAY-2002	1.57	T1
	REF: NO REF								

Total Labor Hours
Total Price :

R - Task was due on previous due lists
(xEXT) - Extension incorporated in the next due calculation



Maintenance Due List/Time Remaining - AIRCRAFT(HOURS)

Aircraft Model - 1124A WESTWIND

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORK CARD WORK ORDER	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL TIME-----AT-----INSTALLATION COMPLIANCE				DISPOSITION NEXT DUE (ENH) AFH (xEXT)	TIME REMAINING OVD = Overdue	AREA PRICE LABOR
			TSN	TSO	TSR	WARR EXP			
AD 2002-01-26	TO PREVENT FAILURE OF ATTACHMENT BOLTS DUE TO FATIGUE, WHICH COULD RESULT IN SEPARATION OF THE ENGINE INLET COWL AND AFT NACELLE, AND CONSEQUENT DAMAGE TO THE HORIZONTAL OR VERTICAL STABILIZER AIRWORTHINESS DIRECTIVE						MANDATORY		
	REF:	MOS HRS/MSC AFL	DUE				50	New Reqmt	
AD 1989-12-08	TO DETECT CRACKS IN THE HINGE LUGS OF THE HORIZONTAL STABILIZER AFT SPAR SPLICE FITTING (HINGE ASSEMBLY) AIRWORTHINESS DIRECTIVE								
	REF: See Workcard	MOS HRS/MSC AFL	300			17-JAN-2001 7494 5466	7794	OVD	
SB 1124-30-036 PART II	ICE AND RAIN PROTECTION SERVICE BULLETIN								F3
	REF: See Workcard	MOS HRS/MSC AFL	150			26-JUN-2001 7687 5594	7837	31	
057110U	NO. 1 ENGINE - 150HR #1 ENGINE INSP								
	REF:	MOS HRS/MSC ENC (AFL)	150			26-JUN-2001 7687 5594	7837	31	1
057110U	NO. 2 ENGINE - 150HR #2 ENGINE INSP								
	REF:	MOS HRS/MSC ENC (AFL)	150			26-JUN-2001 7687 5594	7837	31	1
R 057120U	NO. 1 ENGINE - 300HR #1 ENGINE INSP								
	REF:	MOS HRS/MSC ENC (AFL)	300			16-FEB-2001 7551 5515	7851	45	1.5
R 057120U	NO. 2 ENGINE - 300HR #2 ENGINE INSP								
	REF:	MOS HRS/MSC ENC (AFL)	300			16-FEB-2001 7551 5515	7851	45	1.5
R 050150U	200 HOUR INSPECTION								
	REF:	MOS HRS/MSC AFL	200			26-JUN-2001 7687 5594	7887	81	31
SB 950920	SL WW-2492 HYD HOSE INSP SERVICE BULLETIN								
	REF:	MOS HRS/MSC AFL	200			26-JUN-2001 7687 5594	7887	81	
Total Labor Hours 36:0									
Total Price :									

R - Task was due on previous due lists
(xEXT) - Extension incorporated in the next due calculation



Maintenance Due List/Time Remaining - AIRCRAFT(AFL)

Aircraft Model - 1124A WESTWIND

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORK CARD WORK ORDER	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL TIME-----AT-----INSTALLATION COMPLIANCE				DISPOSITION NEXT DUE (ENH) AFH (xEXT)	TIME REMAINING OVD = Overdue	AREA PRICE LABOR
			TSN	TSO	TSR	WARR EXP			

SB 972B40U SERVICE BULLETIN GSBA72-3569 R/E FAN ROTOR

MOS
HRS/MSC A/R
AFL

5722

16

REF:

Total Labor Hours
Total Price :

R - Task was due on previous due lists
(xEXT) - Extension incorporated in the next due calculation



Aircraft Model - 1124A WESTWIND

Serial #: 368 Reg. #: N368MD

Maintenance Due List/Time Remaining - ENGINE((AFL))

Report Date 14-MAR-2002

ITEM NO	TASK DESCRIPTION	UNIT	INTERVAL TIME-----AT-----INSTALLATION COMPLIANCE				DISPOSITION	TIME	AREA
			WORK CARD	PART NUMBER/PKG	TSN	TSO			
WORK ORDER	SERIAL NUMBER						(ENH) AFH (xEXT)	OVD = Overdue	LABOR
R 725050	NO. 2 ENGINE - CHANGE FAN ROTOR DISC						LIFE LIMIT		
72.090	3073539-2 0-18040-4768 REF: NO REF	MOS HRS/MSC ENC (AFL)	4100	2660		20-MAY-1993 5278 3928	5368	OVD	
R 725030	NO. 2 ENGINE - CHANGE STAGE 3 LOW PRESSURE TURBINE DISC						LIFE LIMIT		
72.060	3072544-2 6-18040-4905 REF: NO REF	MOS HRS/MSC ENC (AFL)	3000	0		31-MAY-1989 4265 2793	5793	87	

Total Labor Hours
Total Price :

R - Task was due on previous due lists
(xEXT) - Extension incorporated in the next due calculation

OWNER: R&S AIRCRAFT INVESTMENTS, LLC
ADDRESS: P.O. BOX 43 HOUSTON TX 77001-0043
PHONE: 713-830-9584
FAX: 713-918-5925

OPERATOR: R&S AIRCRAFT INVESTMENTS, LLC
ADDRESS: P.O. BOX 43 HOUSTON TX 77001-0043
PHONE: 713-830-9584
FAX: 713-918-5925

PROJECTED : 2 MOS. to 14-JUL-2002

EXTENDED DUE LIST - FOR PLANNING PURPOSES ONLY - Scheduled Work Cards were not issued with this Report.

AIRCRAFT

S/N: 368 **REG NO:** N368MD **MODEL:** 1124A WESTWIND **MANUFACTURER:** GULFSTREAM AEROSPACE CORPORATION

NOTE:
INSPECTION PROGRAM: 3
CERTIFICATE DATE: 11-FEB-1982

UOM	LAST ACTUAL	LAST ACTUAL DATE	PROJECTED
HRS	7806	28-FEB-2002	7965.2
AFL	5706	28-FEB-2002	5865

ENGINE NO. 1

S/N: P-77482 **PART NO:** 3072500-2 **MODEL:** TFE731-3 **MANUFACTURER:** HONEYWELL

INSTALLED DATE: 4/3/1989
A/C HRS: 4215
ENGINE HRS: 3972
ENGINE CYCLES: 2456

UOM	LAST ACTUAL	LAST ACTUAL DATE	PROJECTED
HRS	7806	28-FEB-2002	7965.2
ENC	0		0
(AFL)	5706	28-FEB-2002	5865

ENGINE NO. 2

S/N: P77488 **PART NO:** 3072500-2 **MODEL:** TFE731-3 **MANUFACTURER:** HONEYWELL

INSTALLED DATE: 5/31/1993
A/C HRS: 5278
ENGINE HRS: 5227
ENGINE CYCLES: 3867

UOM	LAST ACTUAL	LAST ACTUAL DATE	PROJECTED
HRS	7806	28-FEB-2002	7965.2
ENC	0		0
(AFL)	5706	28-FEB-2002	5865



Extended Due List - AIRCRAFT(CALENDAR)

Aircraft Model - 1124A WESTWIND

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

EXTENDED DUE LIST - FOR PLANNING PURPOSE ONLY - Scheduled Work Cards were not issued with this Report.

ITEM NO WORK CARD WORK ORDER	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL TIME-----AT-----INSTALLATION				COMPLIANCE		DISPOSITION		AREA PRICE LABOR
			TSN	TSO	TSR	WARR	EXP	NEXT DUE	(ENH)	AFH (xEXT)	
270080	X-RAY INSPECT LEFT AILERON CONTROL ROD	LEFT AILERON CONTROL ROD ASSEMBLIES									W1
27.530	513506-503 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	60 5000					16-JUN-1997 6135 4707	16-JUN-2002 11135		
270081	X-RAY INSPECT RIGHT AILERON CONTROL ROD	ASSEMBLY									W2
27.535	513506-503 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	60 5000					16-JUN-1997 6135 4707	16-JUN-2002 11135		
270150	X-RAY INSPECT RUDDER CONTROL ROD	ASSEMBLY									T1
27.560		MOS HRS/MSC AFL	60 5000					16-JUN-1997 6135 4707	16-JUN-2002 11135		
270210	VISUAL INSPECT ELEVATOR CONTROL	BELLCRANK ASSEMBLY									
27.570		MOS HRS/MSC AFL	60 5000					16-JUN-1997 6135 4707	16-JUN-2002 11135		
320110	X-RAY INSPECT NOSE GEAR ASSEMBLY	NOSE GEAR SHAFT AND DOOR ASSEMBLIES									L3
32.560		MOS HRS/MSC AFL	60 5000					16-JUN-1997 6135 4707	16-JUN-2002 11135		
260171	WEIGHT CHECK COCKPIT PORTABLE EXTINGUISHER	COCKPIT FIRE EXTINGUISHER									F3
26.030		MOS HRS/MSC AFL	12					26-JUN-2001 7687 5594	26-JUN-2002		
260181	WEIGHT CHECK CABIN PORTABLE EXTINGUISHER	CABIN FIRE EXTINGUISHER									F4
26.030		MOS HRS/MSC AFL	12					26-JUN-2001 7687 5594	26-JUN-2002		
350168U	CHECK PILOT OXYGEN MASK										F3
35.070		MOS HRS/MSC AFL	12 600					26-JUN-2001 7687 5594	26-JUN-2002 8287		
350169U	CHECK COPILOT OXYGEN MASK										F3
35.070		MOS HRS/MSC AFL	12 600					26-JUN-2001 7687 5594	26-JUN-2002 8287		

Total Labor Hours
Total Price :

R - Task was due on previous due lists
(xEXT) - Extension incorporated in the next due calculation

Aircraft Model - 1124A WESTWIND

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

EXTENDED DUE LIST - FOR PLANNING PURPOSE ONLY - Scheduled Work Cards were not issued with this Report.

ITEM NO WORK CARD WORK ORDER	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL TIME-----AT-----INSTALLATION				COMPLIANCE	DISPOSITION		AREA PRICE LABOR
			TSN	TSO	TSR	WARR EXP		NEXT DUE (ENH)	AFH (xEXT)	
710120 71.010	NO. 2 ENGINE - MAJOR PERIODIC INSPECTION	MOS HRS/MS ENC (AFL)	1400				17-OCT-1998 6520	7920		
	REF: EMM 72-00-00						4889			
724120 72.030	NO. 2 ENGINE - INSPECT COMBUSTION PLENUM CASE	MOS HRS/MS ENC (AFL)	1400				17-SEP-1998 6520	7920		
	REF: EMM 72-40-04						4889			
790120 79.020	NO. 2 ENGINE - CHANGE OIL	MOS HRS/MS ENC (AFL)	1400				17-OCT-1998 6520	7920		
	REF: See Workcard						4889			
AD 1996-24-11 LEFT AILERON	TO PREVENT EXCESSIVE WEAR OF THE AILERON PUSH-PULL TUBE, WHICH COULD RESULT IN UNEVEN MOVEMENT OF THE CONTROL WHEEL, PERFORATION OF THE AILERON PUSH-PULL TUBE, AND CONSEQUENT REDUCED ROLL CONTROL OF THE AIRPLANE AIRWORTHINESS DIRECTIVE	MOS HRS/MS AFL	600				26-JUL-2000 7325 5360	7925	W1	
	REF: AD									
AD 1996-24-11 RIGHT AILERON	TO PREVENT EXCESSIVE WEAR OF THE AILERON PUSH-PULL TUBE, WHICH COULD RESULT IN UNEVEN MOVEMENT OF THE CONTROL WHEEL, PERFORATION OF THE AILERON PUSH-PULL TUBE, AND CONSEQUENT REDUCED ROLL CONTROL OF THE AIRPLANE AIRWORTHINESS DIRECTIVE	MOS HRS/MS AFL	600				26-JUL-2000 7325 5360	7925	W2	
	REF: AD									
SB 1124-27-129 LEFT AILERON	FLIGHT CONTROLS SERVICE BULLETIN	MOS HRS/MS AFL	600				26-JUL-2000 7325 5360	7925	W1	
	REF: BULLETINS									
SB 1124-27-129 RIGHT AILERON	FLIGHT CONTROLS SERVICE BULLETIN	MOS HRS/MS AFL	600				26-JUL-2000 7325 5360	7925	W2	
	REF: BULLETINS									

Total Labor Hours
Total Price :

R - Task was due on previous due lists
(xEXT) - Extension incorporated in the next due calculation

MODEL NAME : 1124A WESTWIND

SERIAL : 368

REG NO : N368MD

Each item on the Insufficient Information report has missing information needed to properly update the items(s). Missing information will be one or more of the following:

*TSN and/or

*Airframe Hours, Landings, Engine Cycles,

*Apu Hours or Starts

*Date of Manufacture

*Date of Expiration

For each item (code number) in the left hand column, please supply the missing information indicated by the question mark under the appropriate column heading, sign the authorization area



Insufficient Information Report

Aircraft Model - 1124A WESTWIND

Report Date 14-MAR-2002

Serial #: 368 Reg. #: N368MD

ITEM NO WORK CARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL TIME		AT	INSTALLATION TSR/TAC Warr Exp	COMPLIANCE	NEXT DUE	TIME REMAINING	AREA PRICE LABOR
			TSN	TSO						
230450U	-- REPLACE BEACON BATTERY	MOS					17-OCT-1998	?		
	REF: _____	HRS/MSC					6520			
	AFL						4889			
ENTER MISSING	MANUAL NEXTDUE: _____									
270251	CHANGE LEFT INBOARD FLAP ACTUATOR	MOS					16-JUN-1997			W1
27.210	1390T100-5	HRS/MSC	10000	?	?		6135	8329		\$1006.00
	610A	AFL					4707			8
	REF: AMM 27-50-00									
ENTER MISSING	TSN HOURS, TSO HOURS: _____									
240116	CHANGE NO. 1 STARTER GENERATOR	MOS					06-NOV-2001			E1
24.010	23065-018-1	HRS/MSC	1000	?	?		7774	968		\$813.00
	3684	AFL					5641			1
	REF: AMM 80-10-00									
ENTER MISSING	TSN HOURS, TSO HOURS: _____									
240126	CHANGE NO. 2 STARTER GENERATOR	MOS					06-NOV-2001			E2
24.010	23065-018-1	HRS/MSC	1000	?	?		7774	968		\$813.00
	2562	AFL					5641			1
	REF: AMM 80-10-00									
ENTER MISSING	TSN HOURS, TSO HOURS: _____									
230207	REPLACE COCKPIT VOICE RECORDER BATTERY	MOS					17-OCT-1998	?		T1
23.130		HRS/MSC					6520			
		AFL					4889			
	REF: NO REF									
ENTER MISSING	MANUAL NEXTDUE: _____									

AUTHORIZED BY _____

CERT.# _____

DATE _____

OWNER: R&S AIRCRAFT INVESTMENTS, LLC
ADDRESS: P.O. BOX 43 HOUSTON TX 77001-0043

OPERATOR: R&S AIRCRAFT INVESTMENTS, LLC
ADDRESS: P.O. BOX 43 HOUSTON TX 77001-0043

PHONE: 713-830-9584
FAX: 713-918-5925

PHONE: 713-830-9584
FAX: 713-918-5925

AIRCRAFT

S/N: 368 **REG NO:** N368MD **MODEL:** 1124A WESTWIND **MANUFACTURER:** GULFSTREAM AEROSPACE CORPORATION

NOTE:
INSPECTION PROGRAM: 3
CERTIFICATE DATE: 11-FEB-1982

UOM	LAST ACTUAL	LAST ACTUAL DATE
HRS	7806	28-FEB-2002
AFL	5706	28-FEB-2002

ENGINE NO. 1

S/N: P-77482 **PART NO:** 3072500-2 **MODEL:** TFE731-3 **MANUFACTURER:** HONEYWELL

INSTALLED DATE: 4/3/1989
A/C HRS: 4215
ENGINE HRS: 3972
ENGINE CYCLES: 2456

UOM	LAST ACTUAL	LAST ACTUAL DATE
HRS	7806	28-FEB-2002
ENC	0	
(AFL)	5706	28-FEB-2002

ENGINE NO. 2

S/N: P77488 **PART NO:** 3072500-2 **MODEL:** TFE731-3 **MANUFACTURER:** HONEYWELL

INSTALLED DATE: 5/31/1993
A/C HRS: 5278
ENGINE HRS: 5227
ENGINE CYCLES: 3867

UOM	LAST ACTUAL	LAST ACTUAL DATE
HRS	7806	28-FEB-2002
ENC	0	
(AFL)	5706	28-FEB-2002



AIRCRAFT Status Report (Work Packages)

Report Date **14-MAR-2002**

Aircraft Model - 1124 WESTWIND
 Owner Name R&S AIRCRAFT INVESTMENTS, LLC
 A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PKG NUMBER	UNT	ACT	INTERVAL TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
AIRCRAFT												
CHAPTER 05												
TIME LIMITS/MAINTENANCE CHECKS												
+ 050150U	200 HOUR INSPECTION											
	PKG 1 in PKG 2, 3	MOS	R						26-JUN-2001			
		HRS/MSC		200					7687	7887	31	
	REF:	AFL							5594			
+ 050300U	400/200 HOUR INSPECTION											
	PKG 2 in PKG 3	MOS	R						26-JUN-2001			
		HRS/MSC		400					7687	8087	45.5	
	REF:	AFL							5594			
+ 050600U	800/400/200 HOUR INSPECT											
	PKG 3	MOS	R						26-JUL-2000			
		HRS/MSC		800					7325	8087	45.5	
	REF:	AFL					-38		5360			
+ 057110U	150HR #1 ENGINE INSP NO. 1										E1	
	PKG 4	MOS							26-JUN-2001			
		HRS/MSC		150					7687		1.5	
	REF:	AFL							5594			
+ 057110U	150HR #2 ENGINE INSP NO. 2										E2	
	PKG 5	MOS							26-JUN-2001			
		HRS/MSC		150					7687		1	
	REF:	AFL							5594			
+ 057120U	300HR #1 ENGINE INSP NO. 1										E1	
	PKG 6	MOS							16-FEB-2001			
		HRS/MSC		300					7551			
	REF:	AFL							5515			
+ 057120U	300HR #2 ENGINE INSP NO. 2										E2	
	PKG 7	MOS							16-FEB-2001			
		HRS/MSC		300					7551			
	REF:	AFL							5515			

Engine Model - TFE731-3

Report Date **14-MAR-2002**

Owner Name **R&S AIRCRAFT INVESTMENTS, LLC**
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PKG NUMBER	UNT	ACT INTERVAL TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
			TSN	TSO	TSR	TSI	ADJ				
ENGINE NO. 1											
CHAPTER 05											
TIME LIMITS/MAINTENANCE CHECKS											
+ 057110U	NO. 1 ENGINE - 150HR #1 ENGINE INSP PKG 4 in PKG 4,6, 6	MOS HRS/MSC		150				26-JUN-2001 7687	7837	1	
	REF:	ENC (AFL)						5594			
+ 057120U	NO. 1 ENGINE - 300HR #1 ENGINE INSP PKG 6 in PKG 6	MOS HRS/MSC		300				16-FEB-2001 7551	7851	1.5	
	REF:	ENC (AFL)						5515			



AIRCRAFT Status Report
(Work Packages)

Engine Model-TFE731-3
 Owner Name R&S AIRCRAFT INVESTMENTS, LLC
 A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PKG NUMBER	UNT	ACT INTERVAL TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
			TSN	TSO	TSR	TSI	ADJ				
ENGINE NO. 2											
CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS											
+ 057110U	NO. 2 ENGINE - 150HR #2 ENGINE INSP PKG 5 in PKG 5, 7, 7	MOS HRS/MSC	150					26-JUN-2001 7687	7837	1	
	REF:	ENC (AFL)						5594			
+ 057120U	NO. 2 ENGINE - 300HR #2 ENGINE INSP PKG 7 in PKG 7	MOS HRS/MSC	300					16-FEB-2001 7551	7851	1.5	
	REF:	ENC (AFL)						5515			

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNT	INTERVAL	TIME-----AT----- TSN TSO TSR TSI ADJ	INSTALLATION	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
AIRCRAFT									
CHAPTER 00 INFORMATION									
000004U	-- ICON HEALTH AND FITNESS							11-FEB-1982	
	REF:	MOS							
		HRS/MSC	N/R						
		AFL							
CHAPTER 10 PARKING, MOORING, STORE AND RET TO SERV									
+ 100310	CHECK AIRWORTHY DIRECTIVES								
10.010	PKG 1, 2, 3	MOS						26-JUN-2001	
	REF: NO REF	HRS/MSC	200					7687	
		AFL						5594	
+ 100320	CHECK SERVICE BULLETINS								
10.020	PKG 1, 2, 3	MOS						26-JUN-2001	
	REF: NO REF	HRS/MSC	200					7687	
		AFL						5594	
+ 100330	CHECK SERVICE LETTERS								
10.030	PKG 1, 2, 3	MOS						26-JUN-2001	
	REF: NO REF	HRS/MSC	200					7687	
		AFL						5594	
CHAPTER 12 SERVICING									
+ 120160	CHECK NO.1 ENGINE PREFLIGHT COMPLETE								E1
12.020	PKG 4	MOS						26-JUN-2001	
	REF: AMM 5-21-00	HRS/MSC	150					7687	
		AFL						5594	
+ 120161	CHECK NO.2 ENGINE PREFLIGHT COMPLETE								E2
12.020	PKG 5	MOS						26-JUN-2001	
	REF: AMM 5-21-00	HRS/MSC	150					7687	
		AFL						5594	
+ 120150	CHECK PRE-FLIGHT								
12.010	PKG 1, 2, 3	MOS						26-JUN-2001	
	REF: AMM 5-30-00	HRS/MSC	200					7687	
		AFL						5594	
CHAPTER 21 AIR CONDITIONING									
210280	CHECK BLEED AIR DUCT OVERPRESSURE SWITCH								F3
21.270	PKG 3	MOS						26-JUL-2000	
	REF: AMM 21-00-00	HRS/MSC	800					7325	
		AFL						5360	
+ 210276	OPERATIONAL CHECK PRESSURIZATION SWITCHES AND VALVES								F3
21.030	PKG 2, 3	MOS						26-JUN-2001	
	REF: AMM 21-00-00	HRS/MSC	400					7687	
		AFL						5594	
210641	ANTICIPATOR, TEMPERATURE SENSOR								F4
21.310	548486-1	MOS						11-FEB-1982	
	SN-UNKNOWN	HRS/MSC	O/C	0					
	REF: AMM 21-60-00	AFL							

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME-----AT-----INSTALLATION	DISPOSITION	AREA
WORKCARD	PART NUMBER/PKG SERIAL NUMBER			TSN TSO TSR TSI ADJ	NEXT DUE	PRICE LABOR HRS
					COMPLIANCE	
210673	ASPIRATOR, ENVIRONMENTAL CONTROL SYSTEM					
21.430	PN SN-UNKNOWN REF: AMM 21-50-00	MOS HRS/MSC AFL	O/C	0	11-FEB-1982	F5
210661	BULB, CABIN TEMPERATURE INDICATOR SENSOR					
21.350	PN SN-UNKNOWN REF: AMM 21-60-00	MOS HRS/MSC AFL	O/C	0	11-FEB-1982	F4
210626	CONTROL BOX, CABIN TEMPERATURE					
21.450	548482-5 030C154 REF: AMM 21-60-00	MOS HRS/MSC AFL	O/C	0	11-FEB-1982	F4
210118	CONTROL UNIT, BLEED AIR CONTROL RIGHT					
21.360	3213894-4-1 P402C REF: NO REF	MOS HRS/MSC AFL		0 0 0	06-NOV-1990 4731 3324	F5
210108	CONTROL UNIT, BLEED AIR LEFT					
21.360	32131894-4-1 P336C REF: NO REF	MOS HRS/MSC AFL	O/C		06-NOV-1990 4731 3324	F5
210176	CONTROLLER, CABIN AIR PRESSURE					
21.180	130398-3 31340 REF: AMM 21-30-00	MOS HRS/MSC AFL	O/C	0	11-FEB-1982	F3 \$1455. 3
210178	CLEAN FILTER					
21.480	PKG 3 REF: AMM 21-30-00	MOS HRS/MSC AFL	800		26-JUL-2000 7325 5360	F3
210606	EXCHANGER, REFRIGERATION UNIT HEAT					
21.240	PN SN-UNKNOWN REF: AMM 21-50-00	MOS HRS/MSC AFL	O/C	0	11-FEB-1982	F5 20
210636	FAN, CABIN TEMPERATURE					
21.300	5783661-5 120713 REF: AMM 21-60-00	MOS HRS/MSC AFL	O/C		04-APR-1996 5747 4430	F4 \$302.
210208	INDICATOR, CABIN ALTITUDE/PRESSURE					
21.390	4883747-1 495 REF: AMM 21-31-00	MOS HRS/MSC AFL	O/C	0	11-FEB-1982	F3
210208	INDICATOR, CABIN RATE-OF-CLIMB					
21.400	4883788 SN-UNKNOWN REF: AMM 21-31-00	MOS HRS/MSC AFL	O/C	0	11-FEB-1982	F3

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
210633 21.410	INDICATOR, CABIN TEMPERATURE 883767-501 197 REF: AMM 21-60-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982	F3	
210156 21.160	PLENUM, MIXING 5-783584-1 SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL	O/C	0						11-FEB-1982	F4	
210241 21.200	REGULATOR, ABSOLUTE AIR PRESSURE LOWER 102466-1 1203419 REF: AMM 21-30-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982	F3 4	
210221 21.080	REPLACE LOWER INLET AIR FILTER ELEMENT PKG 3 1203419 REF: AMM 21-30-00	MOS HRSMSC AFL	800							26-JUL-2000 7325 5360	F3	
210236 21.200	REGULATOR, ABSOLUTE AIR PRESSURE UPPER 102466-1 313613 REF: AMM 21-30-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982	F3 4	
210621 21.280	REGULATOR, PNEUMATIC PRESSURE PN SN-UNKNOWN REF: AMM 21-50-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982	F5	
210246 21.210	RELAY, PNEUMATIC 107312-2 11-9440 REF: AMM 21-30-00	MOS HRSMSC AFL	O/C	0						22-OCT-1982 482	F3 \$383. 4	
210619 21.420	SENSOR, 35 DEGREE TEMPERATURE 783649-1 071C730 REF: AMM 21-50-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982	F5	
+ 210622 21.420	INSPECT 35 DEGREE DUCT SENSOR PKG 1, 2, 3 REF: AMM 21-50-00	MOS HRSMSC AFL	200							26-JUN-2001 7687 5594	F5	
210631 21.460	SENSOR, CABIN TEMPERATURE 548484-1 070C482 REF: AMM 21-60-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982	F4	
210646 21.320	SENSOR, HIGH TEMPERATURE 627962-2 011C955 REF: AMM 21-60-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982	F4	

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
210665 21.440	SENSOR, REFRIGERATION TEMPERATURE CONTROL 3783649-1 11166 REF: NO REF	MOS HRS/MSC AFL	O/C	0					03-NOV-1984 2044	F3	
210666 21.050	SEPARATOR, WATER 179510-1 31535 REF: AMM 21-70-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5	
+ 210671 21.050	CLEAN/REPLACE CONDENSER/FILTER PKG 1, 2, 3 REF: AMM 21-70-00	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594	F5 1	
210286 21.380	SWITCH, CABIN AIR SELECTOR 823073-501 8128133 REF: NO REF	MOS HRS/MSC AFL	O/C	0 0					11-FEB-1982	F3	
210656 21.340	SWITCH, OVERPRESSURE 3-783646-2 194 REF: AMM 21-60-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5	
210651 21.330	SWITCH, OVERTEMPERATURE 3-783645-1 211 REF: AMM 21-60-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F4	
210623 21.440	TANK, AUXILIARY ENVIRONMENTAL CONTROL SYSTEM VOLUME 131358-1 311533 REF: NO REF	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F2	
210677 21.290	TURBINE, COOLING 572375-2 56-133 REF: AMM 21-50-00	MOS HRS/MSC AFL	O/C		0				15-MAR-1995 5585 4260	F5	
210681 21.290	CHANGE OIL PKG 1, 2, 3 REF: AMM 21-50-00	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594	F5	
210601 21.230	UNIT, REFRIGERATION 3783648-1 120-333 REF: AMM 21-50-00	MOS HRS/MSC AFL	O/C	0					21-AUG-1983 1200 667	F5	
210616 21.260	VALVE, 35 DEGREE TEMPERATURE CONTROL 898730-1 SN-UNKNOWN REF: AMM 21-50-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5	

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
210121 21.060	VALVE, AIR CONDITIONING PRESSURE RELIEF 3-783644-1 162 REF: AMM 21-11-00	MOS HRS/MSC AFL							11-FEB-1982	F5	
210101 21.010	VALVE, BLEED AIR SWITCHING LEFT 3783647-3 P511 REF: AMM 21-11-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5 \$1698.	
+ 210102 21.500	VISUALLY INSPECT PKG 2, 3 REF: AMM WCF 21.500	MOS HRS/MSC AFL		400					26-JUN-2001 7687 5594	F5	
210111 21.010	VALVE, BLEED AIR SWITCHING RIGHT 3783647-3 P506 REF: AMM 21-11-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5 \$1698.	
+ 210112 21.500	VISUALLY INSPECT PKG 2, 3 REF: AMM WCF 21.500	MOS HRS/MSC AFL		400					26-JUN-2001 7687 5594	F5	
210146 21.130	VALVE, CABIN AIR CHECK LEFT PN SN-UNKNOWN REF: AMM 21-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F4	
210151 21.130	VALVE, CABIN AIR CHECK RIGHT PN SN-UNKNOWN REF: AMM 21-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F4	
210153 21.370	VALVE, COLD AIR CHECK PN SN-UNKNOWN REF: AMM 21-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5	
210166 21.150	VALVE, CONDITION AIR PILOT PN SN-UNKNOWN REF: AMM 21-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3	
210143 21.470	VALVE, EMERGENCY AIR CHECK PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5	
210141 21.120	VALVE, EMERGENCY AIR SHUTOFF 321760-2-1 P1222 REF: AMM 21-14-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5 \$1099.	

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
210161 21.140	VALVE, FLOOD DUCT PN SN-UNKNOWN REF: AMM 21-20-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F4	
210136 21.110	VALVE, GROUND BY-PASS 4-783622-1 P4380 REF: AMM 21-13-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5 \$1099.	
210211 21.080	REPLACE UPPER INLET AIR FILTER ELEMENT PKG 3 REF: AMM 21-30-00	MOS HRS/MSC AFL	800							26-JUL-2000 7325 5360	F3	
210611 21.250	VALVE, HOT AIR 321760-2-1 P1108 REF: AMM 21-60-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5 \$1099.	
210158 21.380	VALVE, HOT AIR CHECK PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F4	
210226 21.070	VALVE, ISOBARIC SHUTOFF 3-783105 SN-UNKNOWN REF: AMM 21-30-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3	
210171 21.170	VALVE, MANUAL DEFOG PN SN-UNKNOWN REF: AMM 21-20-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3	
210181 21.190	VALVE, MANUAL DUMP 5-723018-401 21563 REF: AMM 21-30-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3	
210186 21.040	VALVE, NORMAL OUTFLOW 130374-6 110870 REF: AMM 21-30-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F4	
210256 21.220	VALVE, PRESSURE SOLENOID LOWER 3783686 175 REF: AMM 21-30-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3	
210251 21.220	VALVE, PRESSURE SOLENOID UPPER 3783686 214 REF: AMM 21-30-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3	

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L



AIRCRAFT Status Report

Aircraft Model - 1124 WESTWIND
 Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
 A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
210131 21.100	VALVE, RAM AIR SHUTOFF 398712-1-1 P222 REF: AMM 21-12-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5	
210196 21.040	VALVE, SAFETY OUTFLOW 103278-8 11905 REF: AMM 21-30-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F4	
210261 21.160	VENTURI, AIRFLOW 131052-1 703075 REF: NO REF	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3	
210266 21.090	INSPECT/CLEAN SCREEN REF: NO REF	MOS HRS/MSC AFL	O/C						11-FEB-1982	F3	
CHAPTER 22 AUTO FLIGHT											
220166 22.020	AMPLIFIER, NO.1 AUTOPILOT SERVO 622-3108-016 2120LNR REF: AMM 22-10-03	MOS HRS/MSC AFL	O/C						27-AUG-1996	F3 1	
220156 22.050	COMPUTER, AUTO PILOT 522-2901-016 2198 REF: AMM 22-13-13	MOS HRS/MSC AFL	O/C		4165 3382			15-FEB-1995 5554 4242		F3	
220163 22.040	COMPUTER, AUTOPILOT YAW DAMPER 622-3167-028 4078 REF: AMM 22-10-05	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3	
221021 22.030	CONTROLLER, AIR DATA NO. 1 590A-3J SN-UNKNOWN REF: AMM 22-10-04	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3	
+ 340146 34.050 ASSOCIATED	LEAK CHECK LEFT STATIC SYSTEM REF: AMM 34-10-01	MOS HRS/MSC AFL	24						18-JAN-2001 18-JAN-2003 7494 5466	MANDATORY F1	
+ 340151 34.050 ASSOCIATED	LEAK CHECK RIGHT STATIC SYSTEM REF: AMM 34-10-01	MOS HRS/MSC AFL	24						18-JAN-2001 18-JAN-2003 7494 5466	MANDATORY F1	
221031 22.030	CONTROLLER, AIR DATA NO. 2 590A-3J1 SN-UNKNOWN REF: AMM 22-10-04	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3	

? - Insufficient Information
 + Task exists in FAA Manual
 3/19/2002 11:40:05 PM

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT----- TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS	
+ 340146	LEAKCHECK LEFT STATIC SYSTEM						MANDATORY	F1	
34.050		MOS	24			18-JAN-2001	18-JAN-2003		
	ASSOCIATED	HRS/MSC				7494			
	REF: AMM 34-10-01	AFL				5466			
+ 340151	LEAKCHECK RIGHT STATIC SYSTEM						MANDATORY	F1	
34.050		MOS	24			18-JAN-2001	18-JAN-2003		
	ASSOCIATED	HRS/MSC				7494			
	REF: AMM 34-10-01	AFL				5466			
222001	CONTROLLER, ALTITUDE PRESELECT							F3	
22.090	622-2923-066	MOS				11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C	0					
	REF: NO REF	AFL		0					
220161	CONTROLLER, AUTOPILOT							F3	
22.010	792-6348-002	MOS				11-FEB-1982			
	2759	HRS/MSC	O/C	0				1	
	REF: AMM 22-10-02	AFL							
220181	MOUNT, AUTOPILOT AILERON SERVO							F5	
22.080	792-6783-001	MOS				11-FEB-1982			
	1191	HRS/MSC	O/C	0					
	REF: AMM WCF 22.080	AFL							
220191	MOUNT, AUTOPILOT ELEVATOR SERVO							F5	
22.080	792-6783-001	MOS				11-FEB-1982			
	1160	HRS/MSC	O/C	0					
	REF: AMM WCF 22.080	AFL							
220201	MOUNT, AUTOPILOT RUDDER SERVO							F5	
22.080	792-6783-001	MOS				11-FEB-1982			
	1166	HRS/MSC	O/C	0					
	REF: AMM WCF 22.070	AFL							
220150	PANEL, AUTOPILOT							F3	
22.060	622-0141-023	MOS				11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C						
	REF: AMM 22-11-02	AFL							
220176	SERVO, AUTOPILOT AILERON							F5	
22.070	792-6781-001	MOS				15-FEB-1995			
	726	HRS/MSC	O/C	5554		5554			
	REF: AMM WCF 22.070	AFL		4242		4242			
220186	SERVO, AUTOPILOT ELEVATOR							F5	
22.070	792-6781-001	MOS				15-FEB-1995			
	791	HRS/MSC	O/C	5554		5554			
	REF: AMM WCF 22.070	AFL		4242		4242			
220196	SERVO, AUTOPILOT RUDDER							F5	
22.070	792-6781-001	MOS				11-FEB-1982			
	3915	HRS/MSC	O/C	0					
	REF: AMM WCF 22.070	AFL							
CHAPTER 23		COMMUNICATIONS							

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME-----AT-----	INSTALLATION	DISPOSITION	AREA
WORKCARD	PART NUMBER/PKG SERIAL NUMBER			TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE NEXT DUE	PRICE LABOR HRS
230450U	- REPLACE BEACON BATTERY	MOS				17-OCT-1998 ?	
	REF:	HRS/MSC				6520	
		AFL				4889	
+ 230218	INSPECT/CHECK STATIC DISCHARGE WICK RESISTANCE	MOS					F1
23.120	PKG 2, 3	MOS				26-JUN-2001	
	REF: AMM 23-60-00	HRS/MSC	400			7687	
		AFL				5594	
230166	RENEW FCC RADIO/TELEPHONE LICENSE	MOS	60			27-OCT-1999 27-OCT-2004	F3
23.100		HRS/MSC				6961	
	REF: See Workcard	AFL				5135	
238004U	--, INTERCOM, COPILOTS NAT LTD	MOS				15-APR-1993	
	AA80-020	HRS/MSC	O/C			5252	
	9688	AFL				3907	
	REF:						
238006U	--, INTERCOM, PILOTS NAT LTD.	MOS				15-APR-1993	
	AA80020	HRS/MSC	O/C	0		5252	
	9689	AFL				3907	
	REF:						
230111	AMPLIFIER, HF POWER	MOS				26-SEP-1995	F3
23.030	622-2883-001	HRS/MSC	O/C			5707	
	1033	AFL				4380	
	REF: AMM WCF 23.030						
230156	ANTENNA, RADIO/TELEPHONE	MOS				11-FEB-1982	F1
23.110	121-0011-000	HRS/MSC	O/C	0			
	3272	AFL					
	REF: AMM 23-21-00						
230136	ANTENNA, VHF BLADE	MOS				11-FEB-1982	F1
23.070	DMC-81-1	HRS/MSC	O/C	0			
	387	AFL					
	REF: AMM 23-20-00						
230131	ANTENNA, VHF FIN CAP	MOS				11-FEB-1982	F1
23.060	VFS-10-90-2	HRS/MSC	O/C	0			5
	866	AFL					
	REF: AMM 23-20-00						
230399	BEACON, VOICE RECORDER	MOS				09-NOV-1996	T1
23.130	DK-100	HRS/MSC	O/C			5951	
	DL4928	AFL				4589	
	REF: NO REF						
230171	CONTROL, COMMUNICATION 1	MOS				09-JAN-1986	F3
23.140	622-4523-011	HRS/MSC	O/C	0		2812	
	SN-UNKNOWN	AFL				1743	
	REF: NO REF						

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
230181 23.140	CONTROL, COMMUNICATION 2 622-4523-003 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0						09-JAN-1986 2812 1743	F3	
230196 23.150	CONTROL, NO.1 AUDIO CENTER 522-3763-001 3747 REF: AMM 23-50-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3	
230201 23.150	CONTROL, NO.2 AUDIO CENTER 522-3763-001 3749 REF: AMM 23-50-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3	
230116 23.040	COUPLER, HF ANTENNA 622-2884-001 2427 REF: AMM WCF 23.040	MOS HRS/MSC AFL	O/C	5702 4372						16-AUG-1995 5702 4372	F3	
230101 23.010	PANEL, HF CONTROL 622-4545-001 SN-UNKNOWN REF: AMM WCF 23.010	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3	
230106 23.020	RECEIVER/EXCITER, HF 622-5337-001 1554 REF: AMM WCF 23.020	MOS HRS/MSC AFL	O/C							26-SEP-1995 5707 4380	F3	
230151 23.100	RECEIVER/TRANSMITTER, RADIO/TELEPHONE 400-0033-000 603 REF: AMM 23-21-00	MOS HRS/MSC AFL	O/C							29-JUL-1994 5472 4150	F3	
230206 23.130	RECORDER, COCKPIT VOICE 89094-003111 A01001 REF: NO REF	MOS HRS/MSC AFL	O/C							16-AUG-1995 5702 4372	T1	
230400 23.130	CLEAN/TEST BEACON REF: NO REF	MOS HRS/MSC AFL	6							06-NOV-2001 7774 5641	06-MAY-2002 T1	
230207 23.130	REPLACE BATTERY REF: NO REF	MOS HRS/MSC AFL								17-OCT-1998 6520 4889	? T1	
230121 23.050	TRANSCEIVER, VHF NO. 1 622-1334-002 4589 REF: AMM 23-20-00	MOS HRS/MSC AFL	O/C	0						24-JUN-1991 4880 3495	F3	

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
230126	TRANSCIVER, VHF NO. 2									F3	
23.050	622-1879-002	MOS							28-MAY-1991		
	16718	HRS/MSC	O/C						4877		
	REF: AMM 23-20-00	AFL							3493		
230146	UNIT, RADIO/TELEPHONE CABIN									F4	
23.090	400-0030-004	MOS							06-FEB-1989		
	77790	HRS/MSC	O/C	0					4149		
	REF: AMM 23-21-00	AFL							2658		
230141	UNIT, RADIO/TELEPHONE COCKPIT									F3	
23.080	400-0032-002	MOS							11-FEB-1982		
	2506	HRS/MSC	O/C	0							
	REF: AMM 23-21-00	AFL									
230191	UNIT, UHF COMMUNICATION REMOTE DISPLAY									F3	
23.140	622-1945-011	MOS							11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C	0							
	REF: NO REF	AFL		0							
CHAPTER 24	ELECTRICAL POWER										
+ 241653	CHECK CIRCUIT BREAKER RESISTANCE/INSPECT BUS									F3	
24.140	PKG 3	MOS							26-JUL-2000		
		HRS/MSC	800						7325		
	REF: AMM 24-50-00	AFL							5360		
+ 241655	INSPECT DISTRIBUTION BUS CIRCUIT BREAKER									F3	
24.150	PKG 3	MOS							26-JUL-2000		
		HRS/MSC	800						7325		
	REF: AMM 24-50-00	AFL							5360		
+ 241657	INSPECT TEST PRIORITY BUS DIODES									F3	
24.160	PKG 3	MOS							26-JUL-2000		
		HRS/MSC	800						7325		
	REF: AMM 24-50-00	AFL							5360		
240156	BATTERY, LEFT									F2	
24.030	4833517-1	MOS							09-NOV-1996	\$2100.	
	8812674	HRS/MSC	O/C						5951	1	
	REF: AMM 24-30-00	AFL							4589		
240168	ANALYZE									F2	
24.030		MOS							09-NOV-1996		
		HRS/MSC	C/C						5951		
	REF: NO REF	AFL							4589		
+ 240161	CHECK ELECTROLYTE LEVEL									F2	
24.030	PKG 1, 2, 3	MOS							26-JUN-2001		
		HRS/MSC	200						7687	1	
	REF: AMM 12-10-06	AFL							5594		
240166	DEEP CYCLE									F2	
24.030	PKG 1, 2, 3	MOS							06-NOV-2001		
		HRS/MSC	200						7774	2	
	REF: AMM 12-10-06	AFL							5641		

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
240171	BATTERY, RIGHT										F2	
24.020	4833517-1	MOS							09-NOV-1996		\$2100.	
	8506152	HRS/MSC	O/C						5951		1	
	REF: AMM 24-30-00	AFL							4589			
240184	ANALYZE										F2	
24.020		MOS							09-NOV-1996			
		HRS/MSC	C/C						5951			
	REF: NO REF	AFL							4589			
+ 240176	CHECK ELECTROLYTE LEVEL										F2	
24.020	PKG 1, 2, 3	MOS							26-JUN-2001			
		HRS/MSC	200						7687		1	
	REF: AMM 12-10-06	AFL							5594			
240181	DEEP CYCLE										F2	
24.020	PKG 1, 2, 3	MOS							06-NOV-2001			
		HRS/MSC	200						7774		2	
	REF: AMM 12-10-06	AFL							5641			
240111	BLOWER, INVERTER COOLING										F2	
24.100	M125J-9A1	MOS							11-FEB-1982			
	200	HRS/MSC	O/C				0					
	REF: AMM 24-20-00	AFL										
240136	BOX, D.C. CONTACTOR LEFT										F5	
24.050	PN	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C				0					
	REF: NO REF	AFL										
240141	BOX, D.C. CONTACTOR RIGHT										F5	
24.050	PN	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C				0					
	REF: NO REF	AFL										
240146	CONTROL UNIT, GENERATOR NO. 1										F5	
24.040	5833515-1	MOS							30-NOV-1989			
	6681927M1	HRS/MSC	O/C						4430		1	
	REF: AMM 24-30-00	AFL							2987			
240151	CONTROL UNIT, GENERATOR NO. 2										F5	
24.040	5833515-1	MOS							01-MAY-1990			
	663958M1	HRS/MSC	O/C						4578		1	
	REF: AMM 24-30-00	AFL							3154			
240116	GENERATOR, STARTER NO. 1									OVERHAUL	E1	
24.010	23065-018-1	MOS							06-NOV-2001		\$813.	
	3684	HRS/MSC	1000						7774	?	1	
	REF: AMM 80-10-00	AFL							5641			
+ 240121	CHECK BRUSH WEAR/TENSION										E1	
24.010	PKG 4	MOS							06-NOV-2001			
		HRS/MSC	150						7774		.5	
	REF: See Workcard	AFL							5641			

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
+ 240118 24.170	INSPECT PKG 4	MOS							06-NOV-2001	E1	
	REF: AMM 5-21-00	HRS/MSC	150						7774		
		AFL							5641		
+ 240123 24.010	INSPECT SPLINE PKG 4	MOS							06-NOV-2001	E1	
	REF: AMM	HRS/MSC	150						7774	1	
		AFL							5641		
240126 24.010	GENERATOR, STARTER NO. 2 23065-018-1	MOS							06-NOV-2001	OVERHAUL E2	
	2562	HRS/MSC	1000						7774	?	
	REF: AMM 80-10-00	AFL							5641	1	
+ 240131 24.010	CHECK BRUSH WEAR/TENSION PKG 5	MOS							06-NOV-2001	E2	
	REF: See Workcard	HRS/MSC	150						7774		
		AFL							5641		
+ 240128 24.170	INSPECT PKG 5	MOS							06-NOV-2001	E2	
	REF: AMM 5-21-00	HRS/MSC	150						7774		
		AFL							5641		
+ 240133 24.010	INSPECT SPLINE PKG 5	MOS							06-NOV-2001	E2	
	REF: AMM 80-10-00	HRS/MSC	150						7774	1	
		AFL							5641		
240196 24.050	INDICATOR, BATTERY TEMPERATURE 4883754-501	MOS							11-FEB-1982	F3	
	1955	HRS/MSC	O/C	0							
	REF: NO REF	AFL									
240101 24.080	INVERTER, NO. 1 6833508-501	MOS							12-JUL-1989	F2	
	C0253094	HRS/MSC	O/C	0					4305	\$1150.	
	REF: AMM 24-20-00	AFL		0					2845	1	
240106 24.080	INVERTER, NO. 2 6833508-501	MOS							09-DEC-1985	F2	
	1135	HRS/MSC	O/C	0					2762	\$1150.	
	REF: AMM 24-20-00	AFL							1713	1	
241651 24.120	METER, VOLT/AMP 6883091-513	MOS							11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C								
	REF: NO REF	AFL									
241601 24.130	POWER SUPPLY, VHF EMERGENCY COMMUNICATION 501-1015-02	MOS							11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C	0							
	REF: NO REF	AFL									

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
241606 24.130	INSPECT BATTERY	MOS HRS/MSC AFL	O/C							11-OCT-1990 4718 3309		
240211 24.060	RECEPTACLE, EXTERNAL POWER PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F1	
+ 240203 24.070	FUNCTIONALLY CHECK BATTERY TEMPERATURE AND WARNING SYSTEM PKG 1, 2, 3 SN-UNKNOWN REF: AMM 24-40-00	MOS HRS/MSC AFL	200							26-JUN-2001 7687 5594	F3	
240186 24.030	THERMISTOR, BATTERY LEFT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	0						11-JAN-1989 4127 2632	F2	
240191 24.020	THERMISTOR, BATTERY RIGHT PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-JAN-1989 4127 2632	F2	
240103	VOLTMETER, AC LEFT 3883035-501 HH9400 REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3	
240108 24.090	VOLTMETER, AC RIGHT 3883035-501 JC1215 REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3	
240143 24.110	VOLTMETER, DC LEFT 6883091-505 H69513 REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3	
240148 24.110	VOLTMETER, DC RIGHT 6883091-505 JD1421 REF: NO REF	MOS HRS/MSC AFL	O/C	0						25-FEB-1994 5408 4066	F3	
CHAPTER 25	EQUIPMENT/FURNISHINGS											
+ 250162 25.050	INSPECT FIRST AID KIT REF: NO REF	MOS HRS/MSC AFL	12							06-NOV-2001 7774 5641	06-NOV-2002 F4	
+ 250156 25.050	INSPECT LIFE PRESERVERS REF: NO REF	MOS HRS/MSC AFL	12							06-NOV-2001 7774 5641	06-NOV-2002 F4	

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
250141 25.040	DISPLAY, CABIN INFORMATION 32940-004	MOS							11-FEB-1982	F4	
	SN-UNKNOWN REF: NO REF	HRS/MSC AFL	O/C	0							
250146 25.040	OPERATIONAL CHECK	MOS							11-FEB-1982	F4	
	REF: NO REF	HRS/MSC AFL	O/C								
250116 25.020	INERTIA REEL, COPILOT PN	MOS							11-FEB-1982	F3	
	SN-UNKNOWN REF: NO REF	HRS/MSC AFL	O/C	0							
250111 25.020	INERTIA REEL, PILOT PN	MOS							11-FEB-1982	F3	
	SN-UNKNOWN REF: NO REF	HRS/MSC AFL	O/C	0							
250106 25.010	SEAT, COPILOT 1024-0	MOS							11-FEB-1982	F3	
	SN-UNKNOWN REF: AMM 25-10-01	HRS/MSC AFL	O/C	0							
250101 25.010	SEAT, PILOT 1025-0	MOS							11-FEB-1982	F3	
	SN-UNKNOWN REF: AMM 25-10-01	HRS/MSC AFL	O/C	0							
250131 25.030	SEATBELT, COPILOT PN	MOS							11-FEB-1982	F3	
	SN-UNKNOWN REF: NO REF	HRS/MSC AFL	O/C	0							
250121 25.030	SEATBELT, PILOT PN	MOS							11-FEB-1982	F3	
	SN-UNKNOWN REF: NO REF	HRS/MSC AFL	O/C	0							
250186 25.060	TRANSMITTER, EMERGENCY LOCATOR 607690-2	MOS							11-FEB-1982	F4	
	SN-UNKNOWN REF: NO REF	HRS/MSC AFL	O/C	0							
CHAPTER 26	FIRE PROTECTION										
+ 260186 26.020	OPERATIONAL CHECK FIRE PROTECTION SYSTEM PKG 2, 3	MOS							26-JUN-2001	F3	
	REF: AMM 26-00-00	HRS/MSC AFL	400					7687 5594			
+ 260148 26.010	REPLACE LEFT FIRE EXTINGUISHER NO.1 CARTRIDGE	MOS							SCRAP	F5	
	REF: AMM 26-20-00	HRS/MSC AFL	48					17-JAN-2001	17-JAN-2005		

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
+ 260153 26.010	REPLACE LEFT FIRE EXTINGUISHER NO.2 CARTRIDGE	MOS	48							17-JAN-2001	SCRAP 17-JAN-2005	F5
	REF: AMM 26-20-00	HRS/MSC AFL										
+ 260158 26.015	REPLACE RIGHT FIRE EXTINGUISHER NO.1 CARTRIDGE	MOS	48							17-JAN-2001	SCRAP 17-JAN-2005	F5
	REF: AMM 26-20-00	HRS/MSC AFL										
+ 260163 26.015	REPLACE RIGHT FIRE EXTINGUISHER NO.2 CARTRIDGE	MOS	48							17-JAN-2001	SCRAP 17-JAN-2005	F5
	REF: AMM 26-20-00	HRS/MSC AFL										
260176 26.030	EXTINGUISHER, CABIN PORTABLE MODEL 2-10	MOS				13				21-JAN-1989		F4
	U-329516	HRS/MSC	O/C			0				4131		
	REF: AMM 5-10-00	AFL								2636		
260182 26.030	DISCHARGE /VALVE OVERHAUL AND REFILL CABIN FIRE EXINGUISHER	MOS	72							06-NOV-2001	06-NOV-2007	F3
	REF: MSC SIL 1124-25-059R1	HRS/MSC AFL								7774		
260183 26.030	HYDROSTATIC TEST CABIN FIRE EXTINGUISHER	MOS	144							01-JAN-1995	01-JAN-2007	F4
	REF: See Workcard	HRS/MSC AFL								5641		
+ 260184 26.030	INSPECT CABIN FIRE EXTINGUISHER PKG 1, 2, 3	MOS								26-JUN-2001		F4
	REF: AMM 26-20-00	HRS/MSC AFL				200				7687		
										5594		
+ 260180 26.060	VISUAL INSPECTION CABIN FIRE EXTINGUISHER	DAYS	30							06-NOV-2001	06-DEC-2001	F3
	REF: NO REF	HRS/MSC AFL								7774		
										5641		
260181 26.030	WEIGHT CHECK CABIN FIRE EXTINGUISHER	MOS	12							26-JUN-2001	26-JUN-2002	F4
	REF: AMM 5-10-00	HRS/MSC AFL								7687		
										5594		
260166 26.030	EXTINGUISHER, COCKPIT PORTABLE MODEL 2-10	MOS				13				21-JAN-1989		F3
	U-329659	HRS/MSC	O/C			0				4131		
	REF: AMM 5-10-00	AFL								2636		
260172 26.030	DISCHARGE /VALVE OVERHAUL AND REFILL COCKPIT FIRE EXTINGUISHER	MOS	72							06-NOV-2001	06-NOV-2007	F3
	REF: MSC SIL 1124-25-059R1	HRS/MSC AFL								7774		
										5641		

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
260173 26.030	HYDROSTATIC TEST COCKPIT FIRE EXTINGUISHER	MOS HRS/MSC AFL	144						01-JAN-1995	01-JAN-2007	F3
	REF: MSC SIL 1124-25-059R1										
+ 260174 26.030	INSPECT COCKPIT FIRE EXTINGUISHER PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594		F3
	REF: AMM 26-20-00										
+ 260169 26.060	VISUAL INSPECTION COCKPIT FIRE EXTINGUISHER	MOS HRS/MSC AFL	30						06-NOV-2001 7774 5641	06-DEC-2001	F3
	REF: NO REF										
260171 26.030	WEIGHT CHECK COCKPIT FIRE EXTINGUISHER	MOS HRS/MSC AFL	12						26-JUN-2001 7687 5594	26-JUN-2002	F3
	REF: AMM 5-10-00										
260111 26.010	EXTINGUISHER, FIRE LEFT 3643507-1 02447C1	MOS HRS/MSC AFL	O/C	0					11-FEB-1982		F5 \$795.
	REF: AMM 26-20-00										
260121 26.010	HYDROSTATIC TEST	MOS HRS/MSC AFL	60						06-NOV-2001 7774 5641	MANDATORY 06-NOV-2006	F5
	REF: AMM 5-10-00										
+ 260146 26.010	RECORD DATE STAMPED ON NEW CARTRIDGE (SERVICE LIFE)	MOS HRS/MSC AFL	72						17-JAN-2001	LIFE LIMIT 17-JAN-2007	F5
	REF: AMM 26-20-00										
+ 260151 26.010	RECORD DATE STAMPED ON NEW CARTRIDGE (SERVICE LIFE)	MOS HRS/MSC AFL	72						17-JAN-2001	LIFE LIMIT 17-JAN-2007	F5
	REF: AMM 26-20-00										
+ 260148 26.010 ASSOCIATED	REPLACE LEFT FIRE EXTINGUISHER NO.1 CARTRIDGE	MOS HRS/MSC AFL	48						17-JAN-2001	SCRAP 17-JAN-2005	F5
	REF: AMM 26-20-00										
+ 260153 26.010 ASSOCIATED	REPLACE LEFT FIRE EXTINGUISHER NO.2 CARTRIDGE	MOS HRS/MSC AFL	48						17-JAN-2001	SCRAP 17-JAN-2005	F5
	REF: AMM 26-20-00										
260116 26.010	WEIGHT CHECK	MOS HRS/MSC AFL	O/C						17-JAN-2001 7494 5466		F5
	REF: See Workcard										

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME-----AT-----	INSTALLATION	COMPLIANCE	DISPOSITION	AREA
WORKCARD	PART NUMBER/PKG SERIAL NUMBER			TSN TSO TSR TSI ADJ	Warr Exp	Warr Exp	NEXT DUE	PRICE LABOR HRS
260126	EXTINGUISHER, FIRE RIGHT							F5
26.015	23700004	MOS				10-JAN-1994		\$795.
	02429C1	HRS/MSC	O/C	0		5382		
	REF: AMM 26-20-00	AFL				4036		
260136	HYDROSTATIC TEST						MANDATORY	F5
26.015		MOS	60			07-APR-1999	07-APR-2004	
		HRS/MSC				6727		
	REF: AMM 5-10-00	AFL				4999		
+ 260156	RECORD DATE STAMPED ON NEW CARTRIDGE (SERVICE LIFE)						LIFE LIMIT	F5
26.015		MOS	72			17-JAN-2001	17-JAN-2007	
		HRS/MSC						
	REF: AMM 26-20-00	AFL						
+ 260161	RECORD DATE STAMPED ON NEW CARTRIDGE (SERVICE LIFE)						LIFE LIMIT	F5
26.015		MOS	72			17-JAN-2001	17-JAN-2007	
		HRS/MSC						
	REF: AMM 26-20-00	AFL						
+ 260158	REPLACE RIGHT FIRE EXTINGUISHER NO.1 CARTRIDGE						SCRAP	F5
26.015		MOS	48			17-JAN-2001	17-JAN-2005	
	ASSOCIATED	HRS/MSC						
	REF: AMM 26-20-00	AFL						
+ 260163	REPLACE RIGHT FIRE EXTINGUISHER NO.2 CARTRIDGE						SCRAP	F5
26.015		MOS	48			17-JAN-2001	17-JAN-2005	
	ASSOCIATED	HRS/MSC						
	REF: AMM 26-20-00	AFL						
260131	WEIGHT CHECK							F5
26.015		MOS				17-JAN-2001		
		HRS/MSC	O/C			7494		
	REF: See Workcard	AFL				5466		
260101	FIRE DETECTOR, LEFT							E1
26.040	4643506-3	MOS				11-FEB-1982		
	19491	HRS/MSC	O/C	0				
	REF: AMM 26-10-00	AFL						
260106	FIRE DETECTOR, RIGHT							E2
26.040	4643506-3	MOS				11-FEB-1982		
	19503	HRS/MSC	O/C	0				
	REF: AMM 26-10-00	AFL						
260141	INDICATOR, EXTINGUISHER DISCHARGE							F5
26.050	PN	MOS				11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C	0				
	REF: NO REF	AFL						
CHAPTER 27	FLIGHT CONTROLS							
+ 270271	ADJUST/TEST FLAP COMPARATOR							F3
27.430	PKG 3	MOS				26-JUL-2000		
		HRS/MSC	800			7325		
	REF: AMM 27-50-00	AFL				5360		

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
+ 270140 27.070	CHECK AILERON CONTROL SYSTEM FREEPLAY PKG 3	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360		F5	
	REF: AMM 27-10-00											
+ 270341 27.440	CHECK CABLE TENSION AFT FUSELAGE PKG 2, 3	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594		F5	
	REF: AMM 27-00-00											
+ 270340 27.440	CHECK CABLE TENSION FLIGHT/PASSENGER COMPARTMENT PKG 3	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360		F3	
	REF: AMM 27-00-00											
+ 270280 27.230	CLEAN/INSPECT/LUBRICATE LEFT INBOARD/OUTBOARD FLEXIBLE SHAFT PKG 3	MOS HRS/MSC AFL	1200						16-FEB-2001 7551 5515	8751	W1	
	REF: AMM 27-50-00											
+ 270285 27.230	CLEAN/INSPECT/LUBRICATE RIGHT INBOARD/OUTBOARD FLEXIBLE SHAFT PKG 3	MOS HRS/MSC AFL	1200						16-FEB-2001 7551 5515	8751	W2	
	REF: AMM 27-50-00											
+ 270248 27.200	FUNCTIONAL CHECK FLAP TIME EXCEED RELAY PKG 2, 3	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594		F3	
	REF: AMM 27-50-00											
+ 270211 27.500	INSPECT SCISSORS ASSEMBLY PKG 2, 3	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594		T1	
	REF: See Workcard											
+ 270351 27.380	INSPECT/LUBRICATE PRESSURE SEALS PKG 3	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360		F4	
	REF: AMM WCF 27.380											
270214 27.195	LUBRICATE AFT HINGE FITTING BEARINGS PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594		T1	
	REF: NO REF											
270179 27.350	LUBRICATE CONTROL COLUMNS PKG 3	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360		F3	
	REF: AMM 12-20-00											
270213 27.190	LUBRICATE ELEVATOR ATTACH POINTS PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594		T1	
	REF: AMM 12-20-00											

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
270346 27.360	LUBRICATE FLIGHT CONTROL FORWARD/AFT BELLCRANKS PKG 3	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360		F4	
	REF: AMM 12-20-00	AFL										
270215 27.195	LUBRICATE FORWARD SCISSOR ASSEMBLY PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594		T1	
	REF: NO REF	AFL										
270356 27.370	LUBRICATE GUST LOCK PKG 3	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360		F3	
	REF: AMM 12-20-00	AFL										
270176 27.340	LUBRICATE RUDDER PEDAL ARMS PKG 3	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360		F3	
	REF: AMM 12-20-00	AFL										
+ 270335 27.280	OPERATIONAL CHECK SPEED BRAKES AND LIFT DUMPERS PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594		F2	
	REF: AMM 27-60-00	AFL										
270145 27.045	STATIC FRICTION TEST AILERON AND RUDDER PKG 3	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360			
	REF: AMM 27-00-00	AFL										
270210 27.570	VISUAL INSPECT ELEVATOR CONTROL BELLCRANK ASSEMBLY PKG 3	MOS HRS/MSC AFL	60 5000						16-JUN-1997 6135 4707	16-JUN-2002 11135		
	REF: AMM 5-10-00	AFL										
270331 27.320	ACCUMULATOR, LIFT DUMPER RIGHT WING 3-713515-501	INBOARD MOS HRS/MSC AFL	O/C	0					11-FEB-1982		W2	
	REF: AMM 27-60-00	AFL										
270116 27.060	ACTUATOR, AILERON TRIM TAB 5793500-1 1010	MOS HRS/MSC AFL	O/C						09-NOV-1996 5951 4589		W1	
	REF: AMM 27-10-00	AFL										
270251 27.210	ACTUATOR, FLAP LEFT INBOARD 1390T100-5 610A	MOS HRS/MSC AFL	10000						16-JUN-1997 6135 4707	LIFE LIMIT ?	W1 \$1006. 8	
	REF: AMM 27-50-00	AFL										
270256 27.220	ACTUATOR, FLAP LEFT OUTBOARD 1391T100-7 519A	MOS HRS/MSC AFL	10000		0				06-APR-1998 6346 4787	OVERHAUL 16346	W1 \$1046.	
	REF: AMM 27-50-00	AFL										

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
270261 27.210	ACTUATOR, FLAP RIGHT INBOARD 193544-1 749A REF: AMM 27-50-00	MOS HRS/MSC AFL	10000	0					15-JUL-1986 3201 1972	OVERHAUL 13201 8	W2 \$1006. 8
270266 27.220	ACTUATOR, FLAP RIGHT OUTBOARD 193544-502 120 REF: AMM 27-50-00	MOS HRS/MSC AFL	10000	0				22-OCT-1982 482	LIFE LIMIT 10482	W2 \$1046.	
270216 27.170	ACTUATOR, HORIZONTAL STABILIZER TRIM 21164-005 0481-11AA REF: AMM 27-40-00	MOS HRS/MSC AFL	2500	0				06-APR-1998 6346 4787	OVERHAUL 7287	T1 \$4158.	
+ 270217 27.170	INSPECT PKG 2, 3 REF: See Workcard	MOS HRS/MSC AFL	400					26-JUN-2001 7687 5594		T1	
270328 27.310	ACTUATOR, LIFT DUMPER LEFT WING INBOARD 3-713515-501 SN-UNKNOWN REF: AMM 27-60-00	MOS HRS/MSC AFL	O/C	0				11-FEB-1982		W1	
270326 27.310	ACTUATOR, LIFT DUMPER LEFT WING OUTBOARD 3-713515-501 SN-UNKNOWN REF: AMM 27-60-00	MOS HRS/MSC AFL	O/C	0				11-FEB-1982		W1	
270333 27.320	ACTUATOR, LIFT DUMPER RIGHT WING OUTBOARD 3-713515-501 SN-UNKNOWN REF: AMM 27-60-00	MOS HRS/MSC AFL	O/C	0				11-FEB-1982		W2	
270166 27.090	ACTUATOR, LOWER RUDDER TRIM 5793500-501 3219 REF: AMM 27-20-00	MOS HRS/MSC AFL	O/C	0				11-FEB-1982		T1 \$1000. 16	
270301 27.260	ACTUATOR, SPEED BRAKE LEFT 3713515-503 1L-466P REF: AMM 27-60-00	MOS HRS/MSC AFL	O/C	0				11-FEB-1982		W1	
270306 27.260	ACTUATOR, SPEED BRAKE RIGHT 3713515-503 1L-470P REF: AMM 27-60-00	MOS HRS/MSC AFL	O/C	0				11-FEB-1982		W2	
270161 27.090	ACTUATOR, UPPER RUDDER TRIM 5793500-503 5220 REF: AMM 27-20-00	MOS HRS/MSC AFL	O/C	0				11-FEB-1982		T1 \$1000. 16	

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME-----AT-----INSTALLATION	DISPOSITION	AREA
WORKCARD	PART NUMBER/PKG SERIAL NUMBER			TSN TSO TSR TSI ADJ	NEXT DUE	PRICE LABOR HRS
				Warr Exp	COMPLIANCE	
270101	AILERON, LEFT					W1
27.010	5183003-407-2	MOS			11-FEB-1982	
	4376	HRS/MSC	O/C	0		
	REF: AMM 27-10-00	AFL				
+ 270140	CHECK AILERON CONTROL SYSTEM FREEPLAY					F5
27.070	PKG 3	MOS			26-JUL-2000	
ASSOCIATED		HRS/MSC	800		7325	
	REF: AMM 27-10-00	AFL			5360	
+ 270264	CLEAN/CHECK LEFT GUIDE ROLLERS					W1
27.550	PKG 2, 3	MOS			26-JUN-2001	
		HRS/MSC	400		7687	
	REF: AMM 5-20-03	AFL			5594	
SB 1124-27-100 R2 L/H RODS	FLIGHT CONTROLS SERVICE BULLETIN					W1
		MOS				
ASSOCIATED		HRS/MSC	A/R			
	REF: BULLETINS	AFL				
	Method of Compliance: OPEN					
SB 1124-27-129 LEFT AILERON	FLIGHT CONTROLS SERVICE BULLETIN					W1
		MOS			26-JUL-2000	
ASSOCIATED		HRS/MSC	600		7325	7925
	REF: BULLETINS	AFL			5360	
	Method of Compliance: OPEN					
+ 570106	INSPECT BELLCRANK					W1
57.020	PKG 1, 2, 3	MOS			26-JUN-2001	
		HRS/MSC	200		7687	
	REF: AMM 5-20-03	AFL			5594	
+ 270262	INSPECT LEFT EXTERNAL PUSH-PULL TUBE					W1
27.540	PKG 2, 3	MOS			26-JUN-2001	
		HRS/MSC	400		7687	
	REF: AMM 5-20-03	AFL			5594	
AD 1996-24-11 LEFT AILERON	TO PREVENT EXCESSIVE WEAR OF THE AILERON PUSH-PULL TUBE, WHICH COULD RESULT IN UNEVEN MOVEMENT OF THE CONTROL WHEEL, PERFORATION OF THE AILERON PUSH-PULL TUBE, AND CONSEQUENT REDUCED ROLL CONTROL OF THE AIRPLANE AIRWORTHINESS DIRECTIVE					W1
		MOS			26-JUL-2000	
ASSOCIATED		HRS/MSC	600		7325	7925
	REF: AD	AFL			5360	
	Method of Compliance: OPEN					
AD 1992-12-02 LEFT AILERON	TO PREVENT REDUCED CONTROLLABILITY OF THE AIRPLANE AIRWORTHINESS DIRECTIVE					W1
		MOS				
ASSOCIATED		HRS/MSC	150			
	REF: AD	AFL				
	Method of Compliance: OPEN					
270106	AILERON, RIGHT					W2
27.010	5183003-406-2	MOS			11-FEB-1982	
	4376	HRS/MSC	O/C	0		
	REF: AMM 27-10-00	AFL				

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
					TSN	TSO	TSR	TSI	ADJ			
+ 270140		CHECK AILERON CONTROL SYSTEM FREEPLAY										F5
	27.070	PKG 3	MOS						26-JUL-2000			
	ASSOCIATED		HRS/MSC	800					7325			
		REF: AMM 27-10-00	AFL						5360			
+ 270265		CLEAN/CHECK RIGHT GUIDE ROLLERS										W2
	27.550	PKG 2, 3	MOS						26-JUN-2001			
		REF: AMM 5-20-03	HRS/MSC	400					7687			
			AFL						5594			
SB 1124-27-100 R2 R/H		FLIGHT CONTROLS SERVICE BULLETIN										W2
	RODS		MOS									
	ASSOCIATED		HRS/MSC	A/R								
		REF: BULLETINS	AFL									
		Method of Compliance: OPEN										
SB 1124-27-129 RIGHT		FLIGHT CONTROLS SERVICE BULLETIN										W2
	AILERON		MOS						26-JUL-2000			
	ASSOCIATED		HRS/MSC	600					7325	7925		
		REF: BULLETINS	AFL						5360			
		Method of Compliance: OPEN										
+ 270263		INSPECT RIGHT EXTERNAL PUSH-PULL TUBE										W2
	27.540	PKG 2, 3	MOS						26-JUN-2001			
		REF: AMM 5-20-03	HRS/MSC	400					7687			
			AFL						5594			
AD 1996-24-11 RIGHT		TO PREVENT EXCESSIVE WEAR OF THE AILERON PUSH-PULL TUBE, WHICH COULD RESULT IN UNEVEN MOVEMENT OF THE CONTROL WHEEL,										W2
	AILERON	PERFORATION OF THE AILERON PUSH-PULL TUBE, AND CONSEQUENT REDUCED ROLL CONTROL OF THE AIRPLANE AIRWORTHINESS DIRECTIVE	MOS						26-JUL-2000			
	ASSOCIATED		HRS/MSC	600					7325	7925		
		REF: AD	AFL						5360			
		Method of Compliance: OPEN										
AD 1992-12-02 RIGHT		TO PREVENT REDUCED CONTROLLABILITY OF THE AIRPLANE AIRWORTHINESS DIRECTIVE										W2
	AILERON		MOS									
	ASSOCIATED		HRS/MSC	150								
		REF: AD	AFL									
		Method of Compliance: OPEN										
270291		BRAKE, SPEED LEFT										W1
	27.250	5-20 3007-507	MOS						11-FEB-1982			
		SN-UNKNOWN	HRS/MSC	O/C	0							
		REF: AMM 27-60-00	AFL									
+ 270335		OPERATIONAL CHECK SPEED BRAKES AND LIFT DUMPERS										F2
	27.280	PKG 1, 2, 3	MOS						26-JUN-2001			
	ASSOCIATED		HRS/MSC	200					7687			
		REF: AMM 27-60-00	AFL						5594			
270296		BRAKE, SPEED RIGHT										W2
	27.250	5-20 3007-506	MOS						11-FEB-1982			
		SN-UNKNOWN	HRS/MSC	O/C	0							
		REF: AMM 27-60-00	AFL									

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
+ 270335	OPERATIONAL CHECK SPEED BRAKES AND LIFT DUMPERS										F2	
27.280	PKG 1, 2, 3	MOS							26-JUN-2001			
	ASSOCIATED	HRS/MSC	200						7687			
	REF: AMM 27-60-00	AFL							5594			
270138	CHAIN, AILERON LEFT										F3	
27.080	3533516-1	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C	0								
	REF: AMM 27-30-00	AFL										
270139	CHAIN, AILERON RIGHT										F3	
27.080	3533516-1	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C	0								
	REF: AMM 27-30-00	AFL										
270186	COLUMN, CONTROL COPILOT										F3	
27.140	PN	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C	0								
	REF: AMM 27-30-00	AFL										
270181	COLUMN, CONTROL PILOT										F3	
27.140	PN	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C	0								
	REF: AMM 27-30-00	AFL										
270191	ELEVATOR, LEFT										T1	
27.150	5463012-401-1	MOS							11-FEB-1982			
	4381	HRS/MSC	O/C	0								
	REF: AMM 27-30-00	AFL										
+ 270193	INSPECT SKIN SEPARATION										T1	
27.150	PKG 1, 2, 3	MOS							26-JUN-2001			
		HRS/MSC	200						7687			
	REF: AMM 27-30-00	AFL							5594			
270213	LUBRICATE ELEVATOR ATTACH POINTS										T1	
27.190	PKG 1, 2, 3	MOS							26-JUN-2001			
	ASSOCIATED	HRS/MSC	200						7687			
	REF: AMM 12-20-00	AFL							5594			
270210	VISUAL INSPECT ELEVATOR CONTROL BELLCRANK ASSEMBLY											
27.570		MOS	60						16-JUN-1997	16-JUN-2002		
	ASSOCIATED	HRS/MSC	5000						6135	11135		
	REF: AMM 5-10-00	AFL							4707			
270201	ELEVATOR, RIGHT										T1	
27.150	5463012-402-1	MOS							11-FEB-1982			
	4381	HRS/MSC	O/C	0								
	REF: AMM 27-30-00	AFL										
+ 270203	INSPECT SKIN SEPARATION										T1	
27.150	PKG 1, 2, 3	MOS							26-JUN-2001			
		HRS/MSC	200						7687			
	REF: AMM 27-30-00	AFL							5594			

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
270213	LUBRICATE ELEVATOR ATTACH POINTS										
27.190	PKG 1, 2, 3	MOS						26-JUN-2001		T1	
	ASSOCIATED	HRS/MSC	200					7687			
	REF: AMM 12-20-00	AFL						5594			
270210	VISUAL INSPECT ELEVATOR CONTROL BELLCRANK ASSEMBLY										
27.570		MOS	60					16-JUN-1997	16-JUN-2002		
	ASSOCIATED	HRS/MSC	5000					6135	11135		
	REF: AMM 5-10-00	AFL						4707			
270233	FLAP ASSEMBLY, CONTROL BOX									F3	
27.490	2813521-	MOS						11-FEB-1982			
	286	HRS/MSC	O/C	0							
	REF: NO REF	AFL		0							
270236	FLAP/VANE, LEFT									W1	
27.200	5193502-401	MOS						11-FEB-1982			
	4369	HRS/MSC	O/C	0							
	REF: AMM 27-50-00	AFL									
+ 270248	FUNCTIONAL CHECK FLAP TIME EXCEED RELAY									F3	
27.200	PKG 2, 3	MOS						26-JUN-2001			
	ASSOCIATED	HRS/MSC	400					7687			
	REF: AMM 27-50-00	AFL						5594			
+ 270240	INSPECT LEFT FLAP HINGE AND BEARING 200 HOURS									W1	
27.200	PKG 1, 2, 3	MOS						26-JUN-2001			
		HRS/MSC	200					7687			
	REF: AMM 27-50-00	AFL						5594			
+ 270244	INSPECT LEFT FLAP HINGE AND BEARING 800 HOURS									W1	
27.200	PKG 3	MOS						26-JUL-2000			
		HRS/MSC	800					7325			
	REF: AMM 27-50-00	AFL						5360			
+ 270237	INSPECT LEFT FLAP VANE									W1	
27.200	PKG 1, 2, 3	MOS						26-JUN-2001			
		HRS/MSC	200					7687			
	REF: AMM 27-50-00	AFL						5594			
+ 270238	TAP TEST LEFT FLAP									W1	
27.200	PKG 2, 3	MOS						26-JUN-2001			
		HRS/MSC	400					7687		.5	
	REF: AMM 27-50-00	AFL						5594			
270241	FLAP/VANE, RIGHT									W2	
27.200	5193502-402	MOS						11-FEB-1982			
	4370	HRS/MSC	O/C	0							
	REF: AMM 27-50-00	AFL									
+ 270248	FUNCTIONAL CHECK FLAP TIME EXCEED RELAY									F3	
27.200	PKG 2, 3	MOS						26-JUN-2001			
	ASSOCIATED	HRS/MSC	400					7687			
	REF: AMM 27-50-00	AFL						5594			

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
+ 270247 27.200	INSPECT PKG 1, 2, 3	MOS								W1	
	REF: AMM 27-50-00	HRS/MSC AFL	200					26-JUN-2001 7687 5594			
+ 270242 27.200	INSPECT RIGHT FLAP HINGE AND BEARING PKG 1, 2, 3	MOS								W2	
	REF: AMM 27-50-00	HRS/MSC AFL	200					26-JUN-2001 7687 5594			
+ 270245 27.200	INSPECT RIGHT FLAP HINGE AND BEARING PKG 3	MOS								W2	
	REF: AMM 27-50-00	HRS/MSC AFL	800					26-JUL-2000 7325 5360			
+ 270243 27.200	TAP TEST PKG 2, 3	MOS								W2	
	REF: AMM 27-50-00	HRS/MSC AFL	400					26-JUN-2001 7687 5594		.5	
270276 27.400	GEARBOX, COMPARATOR LEFT 5-703541-501	MOS								W1	
	SN-UNKNOWN	HRS/MSC	O/C	0				11-FEB-1982		\$1570.	
	REF: AMM 27-50-00	AFL									
+ 270271 27.430 ASSOCIATED	ADJUST/TEST FLAP COMPARATOR PKG 3	MOS								F3	
	REF: AMM 27-50-00	HRS/MSC AFL	800					26-JUL-2000 7325 5360			
270281 27.400	GEARBOX, COMPARATOR RIGHT 5-703541-502	MOS								W2	
	SN-UNKNOWN	HRS/MSC	O/C	0				11-FEB-1982			
	REF: AMM 27-50-00	AFL									
+ 270271 27.430 ASSOCIATED	ADJUST/TEST FLAP COMPARATOR PKG 3	MOS								F3	
	REF: AMM 27-50-00	HRS/MSC AFL	800					26-JUL-2000 7325 5360			
270121 27.030	INDICATOR, AILERON TRIM TAB 3883026-515	MOS								F3	
	S0451	HRS/MSC	O/C	0				11-FEB-1982			
	REF: AMM 27-10-00	AFL									
271101 27.470	INDICATOR, ANGLE-OF-ATTACK LEFT 3883765-501	MOS								F3	
	JN1066	HRS/MSC	O/C	0				11-FEB-1982			
	REF: AMM 34-10-05	AFL		0							
271106 27.470	INDICATOR, ANGLE-OF-ATTACK RIGHT 3883765-501	MOS								F3	
	SN-UNKNOWN	HRS/MSC	O/C	0				11-FEB-1982			
	REF: AMM 34-10-05	AFL		0							

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
270288 27.420	INDICATOR, FLAP POSITION COPILOT 6883739-1 SN-UNKNOWN REF: AMM 27-50-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3	
270286 27.420	INDICATOR, FLAP POSITION PILOT 6883789-1 81090110 REF: AMM 27-50-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3 \$338.	
270226 27.160	INDICATOR, HORIZONTAL STABILIZER TRIM 3883026-525 T0119 REF: AMM 27-40-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3 \$306.	
270171 27.120	INDICATOR, RUDDER TRIM 3883026-517 T0163 REF: AMM 27-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3	
270224 27.185	JACKSCREW, HORIZONTAL STABILIZER ACTUATOR NO.1 21164-005 (ACT.ASSY) 0481-11A REF: NO REF	MOS HRS/MSC AFL		0	10000	0			06-APR-1998 6346 4787	LIFE LIMIT T1 14787	
270225 27.185	JACKSCREW, HORIZONTAL STABILIZER ACTUATOR NO.2 21164-005 (ACT.ASSY) 0481-11AA REF: NO REF	MOS HRS/MSC AFL		0	10000	0			06-APR-1998 6346 4787	LIFE LIMIT T1 14787	
270318 27.290	LIFT DUMPER, LEFT WING INBOARD 3713515-501 1L-900 REF: AMM 27-60-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	W1	
270316 27.290	LIFT DUMPER, LEFT WING OUTBOARD 3713515-501 1L887P REF: AMM 27-60-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	W1	
270321 27.300	LIFT DUMPER, RIGHT WING INBOARD 3713515-501 1L862P REF: AMM 27-60-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	W2	
270323 27.300	LIFT DUMPER, RIGHT WING OUTBOARD 5-203007-510 1L881P REF: AMM 27-60-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	W2	
270119 27.450	MOTOR, AILERON TRIM PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	W1	

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
270246 27.180	MOTOR, FLAP PRIME 193543-1 160 REF: AMM 27-50-00	MOS HRS/MSC AFL	10000		0				06/01/1993	01-DEC-1992 5188 3829	OVERHAUL 15188	F5 \$4235. 1
270221 27.460	MOTOR, PRIMARY HORIZONTAL STABILIZER PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C		0					11-FEB-1982		T1
270169 27.450	MOTOR, RUDDER TRIM PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C		0					11-FEB-1982		T1
270223 27.460	MOTOR, SECONDARY HORIZONTAL STABILIZER PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C		0					11-FEB-1982		T1
270274 27.410	POTENTIOMETER, LINEAR LEFT 833523-501 SN-UNKNOWN REF: AMM 27-50-00	MOS HRS/MSC AFL	O/C							10-AUG-1986 3515		W1
270282 27.410	POTENTIOMETER, LINEAR RIGHT 833523-501 589 REF: AMM 27-50-00	MOS HRS/MSC AFL	O/C							10-AUG-1986 3515		W2
270128 27.530	ROD, CONTROL LEFT AILERON 513506-503 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C							11-FEB-1982		W1
+ 270080 27.530	X-RAY INSPECT LEFT AILERON CONTROL ROD ASSEMBLIES SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	60 5000							16-JUN-1997 6135 4707	16-JUN-2002 11135	W1
270129 27.535	ROD, CONTROL RIGHT AILERON 513506-503 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C							11-FEB-1982		W2
+ 270081 27.535	X-RAY INSPECT ASSEMBLY SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	60 5000							16-JUN-1997 6135 4707	16-JUN-2002 11135	W2
270141 27.100	RUDDER, 5423026-402-2 4370 REF: AMM 27-20-00	MOS HRS/MSC AFL	O/C		0					11-FEB-1982		T1

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEMNO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
+ 270150 27.560	X-RAY INSPECT CONTROL ROD ASSEMBLY	MOS	60						16-JUN-1997	16-JUN-2002	T1
	REF: NO REF	HRS/MSC AFL	5000						6135 4707	11135	
270279 27.230	SHAFT, FLEXIBLE INBOARD LEFT 193545-501	MOS							11-FEB-1982	LIFE LIMIT	W1
	1200269 REF: AMM 27-50-00	HRS/MSC AFL	10000	0						10000	
+ 270280 27.230	CLEAN/INSPECT/LUBRICATE LEFT INBOARD/OUTBOARD FLEXIBLE SHAFT	MOS							16-FEB-2001		W1
	ASSOCIATED REF: AMM 27-50-00	HRS/MSC AFL	1200						7551 5515	8751	
270284 27.240	SHAFT, FLEXIBLE INBOARD RIGHT 193545-505	MOS							11-FEB-1982	LIFE LIMIT	W2
	1200241 REF: AMM 27-50-00	HRS/MSC AFL	10000	0						10000	
+ 270285 27.230	CLEAN/INSPECT/LUBRICATE RIGHT INBOARD/OUTBOARD FLEXIBLE SHAFT	MOS							16-FEB-2001		W2
	ASSOCIATED REF: AMM 27-50-00	HRS/MSC AFL	1200						7551 5515	8751	
270278 27.230	SHAFT, FLEXIBLE OUTBOARD LEFT 193545-501	MOS							11-FEB-1982	LIFE LIMIT	W1
	1200446 REF: AMM 27-50-00	HRS/MSC AFL	10000	0						10000	
+ 270280 27.230	CLEAN/INSPECT/LUBRICATE LEFT INBOARD/OUTBOARD FLEXIBLE SHAFT	MOS							16-FEB-2001		W1
	ASSOCIATED REF: AMM 27-50-00	HRS/MSC AFL	1200						7551 5515	8751	
270283 27.240	SHAFT, FLEXIBLE OUTBOARD RIGHT 193545-501	MOS							11-FEB-1982	LIFE LIMIT	W2
	1200514 REF: AMM 27-50-00	HRS/MSC AFL	10000	0						10000	
+ 270285 27.230	CLEAN/INSPECT/LUBRICATE RIGHT INBOARD/OUTBOARD FLEXIBLE SHAFT	MOS							16-FEB-2001		W2
	ASSOCIATED REF: AMM 27-50-00	HRS/MSC AFL	1200						7551 5515	8751	
270126 27.040	TAB, AILERON SERVO 5-183005-505	MOS							11-FEB-1982		W2
	SN-UNKNOWN REF: AMM 27-10-00	HRS/MSC AFL	O/C	0							
270111 27.020	TAB, AILERON TRIM 5-183005-503	MOS							11-FEB-1982		W1
	SN-UNKNOWN REF: AMM 27-10-00	HRS/MSC AFL	O/C	0							

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
270156 27.110	TAB, RUDDER TRIM PN SN-UNKNOWN REF: AMM 27-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	T1	
+ 270158 27.130	INSPECT FREEPLAY PKG 1, 2, 3 REF: AMM 27-20-00	MOS HRS/MSC AFL	200					26-JUN-2001 7687 5594		T1	
271111 27.480	TRANSMITTER, ANGLE-OF-ATTACK LEFT SLZ7259 KE1141 REF: AMM 34-10-05	MOS HRS/MSC AFL	O/C					06-APR-1998 6346 4787		W1	
271116 27.480	TRANSMITTER, ANGLE-OF-ATTACK RIGHT SLZ-9280 SN-UNKNOWN REF: AMM 34-10-05	MOS HRS/MSC AFL	O/C	0				11-FEB-1982		W2	
270231 27.390	TRANSMITTER, TRIM POSITION INDICATOR 8TJ39-BAR-2 T1353 REF: AMM 27-40-00	MOS HRS/MSC AFL	O/C	0				11-FEB-1982		T1 \$543.	
270336 27.330	VALVE, LIFT DUMPER CONTROL 723573-1 698 REF: AMM 27-60-00	MOS HRS/MSC AFL	O/C	0				11-FEB-1982		F5 \$362.	
270311 27.270	VALVE, SPEED BRAKE CONTROL 723573-1 845 REF: AMM 27-60-00	MOS HRS/MSC AFL	O/C	0				11-FEB-1982		F5 \$362.	
270136 27.050	WHEEL, CONTROL COPILOT 5-533060-35 SN-UNKNOWN REF: AMM 27-10-00	MOS HRS/MSC AFL	O/C	0				11-FEB-1982		F3	
270131 27.050	WHEEL, CONTROL PILOT 5-533060-37 SN-UNKNOWN REF: AMM 27-10-00	MOS HRS/MSC AFL	O/C	0				11-FEB-1982		F3	
CHAPTER 28	FUEL										
+ 281150 28.010	CHECK OPERATION OF FUEL BOOST PUMPS PKG 1, 2, 3 REF: AMM 28-00-00	MOS HRS/MSC AFL	200					26-JUN-2001 7687 5594		F5	
+ 281603 28.090	FUNCTIONAL CHECK FUEL DUMP SYSTEM REF: AMM 28-00-00	MOS HRS/MSC AFL	1200					22-FEB-2000 7107 5232	8307	F5	

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
+ 281602 28.090	OPERATIONAL CHECK FUEL DUMP SYSTEM PKG 3	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360	F5	
281101 28.200	INDICATOR, FUEL QUANTITY LEFT 6883707-1	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3 \$444. 1	
281106 28.200	INDICATOR, FUEL QUANTITY RIGHT 6883707-1	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3 \$444. 1	
281108 28.210	INDICATOR, FUEL STATUS 6883710-501	MOS HRS/MSC AFL	O/C						11-FEB-1982	F3	
280626 28.160	PROBE, LEFT TIP TANK 6653505-519	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	W1	
280616 28.140	PROBE, LEFT WING INBOARD 5653505-507	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	W1	
280621 28.140	PROBE, LEFT WING OUTBOARD 5653505-505	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	W1	
280646 28.160	PROBE, RIGHT TIP TANK 6653505-519	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	W2	
280636 28.150	PROBE, RIGHT WING INBOARD 5653505-507	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	W2	
280641 28.150	PROBE, RIGHT WING OUTBOARD 5653505-505	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	W2	
280611 28.130	PROBE, FUSELAGE LEFT 3653505-509	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5	

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
280631 28.130	PROBE, FUSELAGE RIGHT 6653505-509 291 REF: AMM 28-40-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5	
280126 28.020	PUMP, ALTERNATE BOOST LEFT 5653744-505 T514 REF: AMM 28-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	W1	
280128 28.020	CHECK BRUSH WEAR REF: See Workcard	MOS HRS/MSC AFL	O/C						11-FEB-1982	W1	
+ 281150 28.010 ASSOCIATED	CHECK OPERATION OF FUEL BOOST PUMPS PKG 1, 2, 3 REF: AMM 28-00-00	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594	F5	
280136 28.020	PUMP, ALTERNATE BOOST RIGHT 5653744 853 REF: AMM 28-20-00	MOS HRS/MSC AFL	O/C						30-OCT-1989 4401 2956	W2	
280138 28.020	CHECK BRUSH WEAR REF: See Workcard	MOS HRS/MSC AFL	O/C						11-FEB-1982	W2	
+ 281150 28.010 ASSOCIATED	CHECK OPERATION OF FUEL BOOST PUMPS PKG 1, 2, 3 REF: AMM 28-00-00	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594	F5	
280161 28.110	PUMP, FUSELAGE JET LEFT 3-653015 1095 REF: AMM 28-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5	
280166 28.110	PUMP, FUSELAGE JET RIGHT 3-653015 1099 REF: AMM 28-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5	
280181 28.100	PUMP, JET LEFT TIP TANK 3-653015 1309 REF: AMM 28-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	W1	
280186 28.100	PUMP, JET RIGHT TIP TANK 3-653015 1311 REF: AMM 28-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	W2	

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
280167 28.230	PUMP, LONG RANGE BOOST 653009-513 SN-UNKNOWN REF: AMM 28-50-00	MOS HRS/MSC AFL	O/C							11-FEB-1982	F4	
280121 28.010	PUMP, MAIN BOOST LEFT 2070C01T3 T-330 REF: AMM 28-20-00	MOS HRS/MSC AFL	O/C		0					24-APR-2000 7233 5301	W1	
280123 28.010	CHECK BRUSH WEAR REF: NO REF	MOS HRS/MSC AFL	O/C							24-APR-2000 7233 5301	W1	
+ 281150 28.010 ASSOCIATED	CHECK OPERATION OF FUEL BOOST PUMPS PKG 1, 2, 3 REF: AMM 28-00-00	MOS HRS/MSC AFL	200							26-JUN-2001 7687 5594	F5	
280131 28.010	PUMP, MAIN BOOST RIGHT 2070C01T3 T1222 REF: AMM 28-20-00	MOS HRS/MSC AFL	O/C		0 0 0					26-AUG-1992 5151 3777	W2	
280133 28.010	CHECK BRUSH WEAR REF: See Workcard	MOS HRS/MSC AFL	O/C							26-AUG-1992 5151 3777	W2	
+ 281150 28.010 ASSOCIATED	CHECK OPERATION OF FUEL BOOST PUMPS PKG 1, 2, 3 REF: AMM 28-00-00	MOS HRS/MSC AFL	200							26-JUN-2001 7687 5594	F5	
281121 28.210	SIGNAL CONDITIONER, FUEL 883711-501 157 REF: NO REF	MOS HRS/MSC AFL	O/C		0					11-FEB-1982	F2	
280281 28.190	SWITCH, FUEL FLOAT LEFT 833006 A966 REF: NO REF	MOS HRS/MSC AFL	O/C		0					11-FEB-1982	F5	
280286 28.190	SWITCH, FUEL FLOAT RIGHT 833006 A920 REF: NO REF	MOS HRS/MSC AFL	O/C		0					11-FEB-1982	F5	
281141 28.170	SWITCH, LOW-LEVEL WARNING LEFT 3833006 SN-UNKNOWN REF: AMM 28-40-00	MOS HRS/MSC AFL	O/C		0					11-FEB-1982	F5	

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
281146 28.170	SWITCH, LOW-LEVEL WARNING RIGHT 3833006 SN-UNKNOWN REF: AMM 28-40-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5	
281139 28.240	SWITCH, PRESSURE(LONG RANGE) 833010-518 A-149 REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F4	
280250 28.220	TANK, FUEL (LONG RANGE) CMA61032-501 NSN REF: AMM 28-50-00	MOS HRS/MSC AFL				0				07-DEC-1989 4437 2994	F5	
281110 28.240	TRANSMITTER, QUANTITY (LONG RANGE) DA515A050 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F4	
280191 28.090	VALVE, DUMP LEFT 3653014 168 REF: AMM 28-30-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	W1 \$725.	
+ 281603 28.090 ASSOCIATED	FUNCTIONAL CHECK FUEL DUMP SYSTEM REF: AMM 28-00-00	MOS HRS/MSC AFL		1200						22-FEB-2000 7107 5232	8307 F5	
+ 281602 28.090 ASSOCIATED	OPERATIONAL CHECK FUEL DUMP SYSTEM PKG 3 REF: AMM 28-00-00	MOS HRS/MSC AFL		800						26-JUL-2000 7325 5360	F5	
280196 28.090	VALVE, DUMP RIGHT 3653014 31360 REF: AMM 28-30-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	W2 \$725.	
+ 281603 28.090 ASSOCIATED	FUNCTIONAL CHECK FUEL DUMP SYSTEM REF: AMM 28-00-00	MOS HRS/MSC AFL		1200						22-FEB-2000 7107 5232	8307 F5	
+ 281602 28.090 ASSOCIATED	OPERATIONAL CHECK FUEL DUMP SYSTEM PKG 3 REF: AMM 28-00-00	MOS HRS/MSC AFL		800						26-JUL-2000 7325 5360	F5	
280141 28.040	VALVE, FIREWALL SHUTOFF LEFT 3653012 L38199 REF: AMM 28-20-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	E1	

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
280151 28.040	VALVE, FIREWALL SHUTOFF RIGHT 3-653012 L35008 REF: AMM 28-20-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	E2 \$725.	
280251 28.050	VALVE, FUEL AUTO SHUTOFF LEFT 3653669 0114 REF: AMM 28-10-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5	
280256 28.050	VALVE, FUEL AUTO SHUTOFF RIGHT 3653669 0087 REF: AMM 28-10-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5	
280106 28.030	VALVE, FUEL INTERCONNECT AFT 3653014 31395 REF: AMM 28-10-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5 \$725.	
280101 28.030	VALVE, FUEL INTERCONNECT FORWARD AV16B1683 L18181 REF: AMM 28-10-00	MOS HRS/MSC AFL	O/C							16-JUN-1997 6135 4707	F5 \$725.	
280261 28.060	VALVE, FUEL PILOT LEFT 3653671 7732 REF: AMM 28-10-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5	
280266 28.060	VALVE, FUEL PILOT RIGHT 3653671 7728 REF: AMM 28-10-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5	
280194 28.070	VALVE, FUEL PRECHECK LEFT PN SN-UNKNOWN REF: AMM 28-10-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5	
280203 28.070	VALVE, FUEL PRECHECK RIGHT PN SN-UNKNOWN REF: AMM 28-10-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5	
280206 28.180	VALVE, FUEL SOLENOID LEFT MS-29527-1 744 REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5	
280211 28.180	VALVE, FUEL SOLENOID RIGHT MS-29527-1 752 REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5	

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
280171 28.120	VALVE, FUEL TRANSFER LEFT 4653572 101 REF: AMM 28-20-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5 \$805.	
280176 28.120	VALVE, FUEL TRANSFER RIGHT 4653572 126 REF: AMM 28-20-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5 \$805.	
280290 28.250	VALVE, SINGLE POINT REFUEL ADAPTER 3653670 205 REF: NO REF	MOS HRS/MSC AFL	O/C							11-FEB-1982	F5	
280271 28.080	VALVE, SINGLE POINT REFUEL VENT LEFT 3653672 SN-UNKNOWN REF: AMM 28-10-00	MOS HRS/MSC AFL	O/C	0 0						11-FEB-1982	F5	
280276 28.080	VALVE, SINGLE POINT REFUEL VENT RIGHT 3653672 SN-UNKNOWN REF: AMM 28-10-00	MOS HRS/MSC AFL	O/C	0 0						11-FEB-1982	F5	
CHAPTER 29 HYDRAULIC POWER												
290221 29.080	ACCUMULATOR, EMERGENCY 3713008 601 REF: AMM 29-20-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5 \$472.	
290151 29.130	ACCUMULATOR, LEFT HYDRAULIC 4-713569-1 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5	
290186 29.130	ACCUMULATOR, RIGHT HYDRAULIC 4-713569-1 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5	
290261 29.040	ATTENUATOR, NO.1 ENG HYDRAULIC 3713562-1 0601 REF: AMM 29-10-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5	
290266 29.040	ATTENUATOR, NO.2 ENG HYDRAULIC 3713562-1 0591 REF: AMM 29-10-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5	
290119 29.180	CHECK VALVE, RESERVOIR BLEED AIR PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5	

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
290248 29.110	FUSE, EMERGENCY HYDRAULIC 3713047 3383 REF: AMM 29-30-00	MOS HRS/MSC AFL							11-FEB-1982	F2	
290246 29.100	GAUGE, EMERGENCY HYDRAULIC PRESSURE 4883746-1 SN-UNKNOWN REF: AMM 29-30-00	MOS HRS/MSC AFL	O/C						11-FEB-1982	F3	
290148 29.140	GAUGE, LEFT ACCUMULATOR PRESSURE 7253014-501 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C						11-FEB-1982	F5	
290183 29.140	GAUGE, RIGHT ACCUMULATOR PRESSURE 7253014-501 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C						11-FEB-1982	F5	
290236 29.160	INDICATOR, HYDRAULIC PRESSURE 4883746-1 8007104 REF: AMM 29-30-00	MOS HRS/MSC AFL	O/C						11-FEB-1982	F3	
290211 29.060	PUMP, EMERGENCY HYDRAULIC 3713010-505 13747 REF: AMM 29-20-00	MOS HRS/MSC AFL	O/C						11-FEB-1982	F5 \$805.	
290215 29.110	FUNCTIONAL TEST EMERGENCY HYDRAULIC FUSE REF: AMM 29-30-06	MOS HRS/MSC AFL	36 1200						30-NOV-1999 6991 5163	30-NOV-2002 8191	
290141 29.120	PUMP, HYDRAULIC NO. 1 5713524-507 B1-58 REF: AMM 29-10-00	MOS HRS/MSC AFL							09-OCT-1990 4718 3309	E1	
+ 290143 29.120	INSPECT/LUBRICATE NO.1 ENGINE HYDRAULIC PUMP SPLINES PKG 1, 2, 3 REF: AMM 29-10-00	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594	E1 1	
290176 29.120	PUMP, HYDRAULIC NO. 2 5713524-507 A2-84 REF: AMM 29-10-00	MOS HRS/MSC AFL	O/C						04-FEB-1994 5390 4040	E2 1	
+ 290178 29.120	INSPECT/LUBRICATE NO.2 ENGINE HYDRAULIC PUMP SPLINES PKG 1, 2, 3 REF: AMM 29-10-00	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594	E2 1	

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
					TSN	TSO	TSR	TSI	ADJ				
290121		REGULATOR, RESERVOIR AIR PRESSURE										F5	
	29.050	3713015	MOS								11-FEB-1982	\$1046.	
		509	HRS/MSC	O/C	0								
		REF: AMM 29-10-00	AFL										
290118		CLEAN/CHECK HYDRAULIC RESERVOIR AIR PRESSURE CHECK VALVE										F5	
	29.050	PKG 2, 3	MOS								26-JUN-2001		
		509	HRS/MSC	400							7687		
		REF: AMM 5-20-00	AFL								5594		
+ 290131		INSPECT/REPLACE RESERVOIR AIR PRESSURE FILTER										F5	
	29.050	PKG 3	MOS								26-JUL-2000		
		509	HRS/MSC	800							7325		
		REF: AMM 29-10-00	AFL								5360		
+ 290116		INSPECT/REPLACE RESERVOIR AIR VENT FILTER										F5	
	29.050	PKG 3	MOS								26-JUL-2000		
		509	HRS/MSC	800							7325		
		REF: AMM 29-10-10	AFL								5360		
290171		REPLACE NO.1 ENGINE HIGH PRESSURE HYDRAULIC FILTER ELEMENT										F5	
	29.050	PKG 3	MOS								26-JUL-2000		
		509	HRS/MSC	800							7325		
		REF: AMM 29-10-10	AFL								5360		
290206		REPLACE NO.2 ENGINE HIGH PRESSURE HYDRAULIC FILTER ELEMENT										F5	
	29.050	PKG 3	MOS								26-JUL-2000		
		509	HRS/MSC	800							7325		
		REF: AMM 29-10-10	AFL								5360		
290101		RESERVOIR, HYDRAULIC										F5	
	29.010	5713014-505	MOS								11-FEB-1982		
		SN-UNKNOWN	HRS/MSC	O/C	0								
		REF: AMM 29-10-00	AFL										
290106		REPLACE FILTER										F5	
	29.010	PKG 3	MOS								26-JUL-2000		
		509	HRS/MSC	800							7325		
		REF: AMM 29-10-00	AFL								5360		
290226		SWITCH, EMERGENCY HYDRAULIC PRESSURE										F5	
	29.090	4833010-515	MOS								11-FEB-1982		
		872	HRS/MSC	O/C	0								
		REF: AMM 29-20-00	AFL										
290241		SWITCH, NO.1 LOW HYDRAULIC PRESSURE WARNING										F5	
	29.170	4713533-1	MOS								11-FEB-1982		
		798	HRS/MSC	O/C	0							1	
		REF: AMM 29-30-00	AFL										
290243		SWITCH, NO.2 LOW HYDRAULIC PRESSURE WARNING										F5	
	29.170	4713533-1	MOS								11-FEB-1982		
		788	HRS/MSC	O/C	0								
		REF: AMM 29-30-00	AFL										

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
290231 29.150	TRANSMITTER, HYDRAULIC PRESSURE 3883028 8005119 REF: AMM 29-30-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5 \$507.	
290133 29.180	VALVE, BLEED RETURN PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5	
290216 29.070	VALVE, EMERGENCY THERMAL RELIEF 4713011-1 1L82 REF: NO REF	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5	
290138 29.190	VALVE, HYDRAULIC PRESSURE RELIEF 373596-501 158 REF: NO REF	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5	
290146 29.020	VALVE, LEFT HYDRAULIC SHUTOFF 713020- 080 REF: AMM 29-10-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	E1 \$322.	
290136 29.030	VALVE, MANUAL HIGH-PRESSURE RELIEF 3723628 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5	
290181 29.020	VALVE, RIGHT HYDRAULIC SHUTOFF 713020- 074 REF: AMM 29-10-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	E2 \$322.	
290271 29.190	VALVE, THERMAL HYDRAULIC RELIEF 3713554 0168 REF: NO REF	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5	
CHAPTER 30	ICE AND RAIN PROTECTION										
+ 300133 30.100	FUNCTIONAL CHECK PNEUMATIC DE-ICER BOOTS. PKG 3 REF: AMM 30-10-00	MOS HRS/MSC AFL		800					26-JUL-2000 7325 5360	F3	
+ 300150 30.140	INSPECT COPILOT WINDSHIELD CYCLING CONTACTOR PKG 1, 2, 3 REF: AMM 30-40-00	MOS HRS/MSC AFL		200					26-JUN-2001 7687 5594	F3	
+ 300147 30.140	INSPECT PILOT WINDSHIELD CYCLING CONTACTOR PKG 1, 2, 3 REF: AMM 30-40-00	MOS HRS/MSC AFL		200					26-JUN-2001 7687 5594	F3	

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
+ 300163 30.160	INSPECT WINDSHIELD WIPER ASSEMBLY PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594			
	REF: AMM 30-40-00											
300170 30.150	OPERATIONAL TEST P2T2 SENSOR HEATER PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594			
	REF: AMM 30-20-00											
300165 30.170	REPLACE WIPER BLADE ELEMENT NOTE: IT IS RECOMMENDED TO REPLACE WIPER BLADE ELEMENT EVERY 6 MONTHS OR 250 HOURS.	MOS HRS/MSC AFL							06-NOV-2001 7774 5641			
	REF: AMM 30-40-00											
300101 30.010	CHECK VALVE, DE-ICER LEFT PN SN-UNKNOWN REF: AMM 30-10-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982		F4	
+ 300102 30.010	INSPECT PKG 2, 3	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594		F4	
	REF: AMM 30-10-00											
300103 30.010	CHECK VALVE, DE-ICER RIGHT PN SN-UNKNOWN REF: AMM 30-10-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982		F4	
+ 300104 30.010	INSPECT PKG 2, 3	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594		F4	
	REF: AMM 30-10-00											
300146 30.110	CONTROLLER, WINDSHIELD TEMPERATURE LEFT HYLZ9661 982B REF: AMM 30-40-00	MOS HRS/MSC AFL	O/C	0					22-FEB-2000 7107 5232		F3	
	REF: AMM 30-40-00											
300148 30.110	CONTROLLER, WINDSHIELD TEMPERATURE RIGHT 833034-1 SN-UNKNOWN REF: AMM 30-40-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982		F3	
	REF: AMM 30-40-00											
300111 30.030	EJECTOR, AIR 850278-1 RF3295 REF: AMM 30-10-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982		F4	
	REF: AMM 30-10-00											
300156 30.130	MOTOR, WINDSHIELD WIPER LEFT XW21126-315-R32 2-22826 REF: AMM 30-40-00	MOS HRS/MSC AFL	O/C	0					26-JUL-2000 7325 5360		F3 \$354. 7	
	REF: AMM 30-40-00											

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
300161 30.130	MOTOR, WINDSHIELD WIPER RIGHT 5823099-402 213743 REF: AMM 30-40-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3	
300106 30.020	REGULATOR, PRESSURE 4753042-501 3300U REF: AMM 30-10-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F4 \$403.	
300116 30.040	SWITCH, PRESSURE 3753045-507 287 REF: AMM 30-10-00	MOS HRS/MSC AFL	O/C	0					31-OCT-1992 5170 3802	F4	
300141 30.090	SWITCH, PRESSURE INDICATOR NO. 1 ENGINE 12299 SN-UNKNOWN REF: AMM 30-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	E1	
300144 30.090	SWITCH, PRESSURE INDICATOR NO. 2 ENGINE 12299 1246 REF: AMM 30-20-00	MOS HRS/MSC AFL	O/C	0			06/29/1993		29-DEC-1992 5203 4938	E2	
300121 30.050	SWITCH, VACUUM 3-753064-501 277 REF: AMM 30-10-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F4	
300151 30.120	SWITCH, WINDSHIELD THERMOSTAT LEFT PN SN-UNKNOWN REF: AMM 30-40-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3	
300153 30.120	SWITCH, WINDSHIELD THERMOSTAT RIGHT PN SN-UNKNOWN REF: AMM 30-40-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3	
300131 30.070	TIMER, DE-ICER 3-753046-1 G426 REF: AMM 30-10-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F4	
300126 30.060	VALVE, DISTRIBUTOR 753511-1 41359U REF: AMM 30-10-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F4	
300136 30.080	VALVE, NO.1 NACELLE ANTI-ICE F10A-5-SCP-102-5 193RW REF: AMM 30-20-00	MOS HRS/MSC AFL	O/C	0					30-JAN-1984 1468 908	E1	

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
300138 30.080	VALVE, NO.2 NACELLE ANTI-ICE F10A-5-SCP-102-5	MOS									E2	
	8100435	HRS/MSC	O/C	0					12-OCT-1983			
	REF: AMM 30-20-00	AFL							1321			
									810			
CHAPTER 31	INDICATING/RECORDING SYSTEMS											
310101 31.010	CLOCK, COCKPIT DIGITAL 811-B	MOS									F3	
	15324	HRS/MSC	O/C	0					11-FEB-1982			
	REF: NO REF	AFL										
CHAPTER 32	LANDING GEAR											
321189U	- REPL SPARE MAIN WHEEL BLT	MOS										
		HRS/MSC	O/C						26-NOV-1989			
	REF:	AFL							4427			
									2984			
322136 32.400	BLEED BRAKE SYSTEM	MOS									L2	
		HRS/MSC	O/C						17-JAN-2001			
	REF: AMM 32-43-00	AFL							7494			
									5466			
320678 32.550	DYE PENETRANT CHECK LEFT WHEEL AXLE PKG 2, 3	MOS									L1	
		HRS/MSC	400						26-JUN-2001			
	REF: AMM 5-20-04	AFL							7687			
									5594			
321178 32.550	DYE PENETRANT CHECK RIGHT WHEEL AXLE PKG 2, 3	MOS									L2	
		HRS/MSC	400						26-JUN-2001			
	REF: AMM 5-20-04	AFL							7687			
									5594			
+ 322176 32.420	FUNCTIONAL CHECK ANTI-SKID DETECTOR SYSTEM PKG 2, 3	MOS									F3	
		HRS/MSC	400						26-JUN-2001			
	REF: AMM 32-44-00	AFL							7687		1	
									5594			
+ 322211 32.450	FUNCTIONAL TEST EMERGENCY GEAR EXTENSION PKG 3	MOS									F3	
		HRS/MSC	800						26-JUL-2000			
	REF: AMM 32-30-00	AFL							7325			
									5360			
+ 322206 32.440	FUNCTIONAL TEST EMERGENCY GEAR EXTENSION CONTROL CABLE PKG 1, 2, 3	MOS									F3	
		HRS/MSC	200						26-JUN-2001			
	REF: AMM 32-30-00	AFL							7687		1	
									5594			
+ 322191 32.430	FUNCTIONAL TEST LANDING GEAR (NORMAL) PKG 2, 3	MOS									F3	
		HRS/MSC	400						26-JUN-2001			
	REF: AMM 32-30-00	AFL							7687			
									5594			
+ 322201 32.430	FUNCTIONAL TEST LANDING GEAR FREE FALL PKG 2, 3	MOS									F3	
		HRS/MSC	400						26-JUN-2001			
	REF: See Workcard	AFL							7687			
									5594			

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
+ 320691 32.020	INSPECT LEFT MAIN GEAR/WELL (A) PKG 1, 2, 3	MOS HRS/MSC AFL	200							26-JUN-2001 7687 5594	L1 1.5	
	REF: AMM WCF 32.020											
+ 320201 32.0101	INSPECT NOSE GEAR (A) PKG 1, 2, 3	MOS HRS/MSC AFL	200							26-JUN-2001 7687 5594	L3 1.5	
	REF: AMM WCF 32.0101											
+ 320206 32.0102	INSPECT NOSE GEAR (B) PKG 2, 3	MOS HRS/MSC AFL	400							26-JUN-2001 7687 5594	L3	
	REF: AMM WCF 32.0202											
+ 322156 32.410	INSPECT/CLEAN LEFT ANTI-SKID DETECTOR PKG 1, 2, 3	MOS HRS/MSC AFL	200							26-JUN-2001 7687 5594	L1 1	
	REF: AMM 5-20-04											
+ 322171 32.410	INSPECT/CLEAN RIGHT ANTI-SKID DETECTOR PKG 1, 2, 3	MOS HRS/MSC AFL	200							26-JUN-2001 7687 5594	L2 1	
	REF: AMM 5-20-04											
320607 32.570	LUBRICATE LEFT ACTUATOR BOLTS PKG 2, 3	MOS HRS/MSC AFL	400							26-JUN-2001 7687 5594	L1	
	REF: AMM WCF 32.570											
321107 32.570	LUBRICATE RIGHT ACTUATOR BOLTS PKG 2, 3	MOS HRS/MSC AFL	400							26-JUN-2001 7687 5594	L2	
	REF: AMM WCF 32.570											
+ 322174 32.425	OPERATIONAL CHECK ANTI-SKID LIGHTS PKG 1, 2, 3	MOS HRS/MSC AFL	200							26-JUN-2001 7687 5594	F3 .5	
	REF: AMM 32-44-00											
320686 32.180	REPLACE LEFT MAIN WHEEL BOLTS	MOS HRS/MSC AFL	O/C							09-NOV-1996 5951 4589	L1	
	REF: NO REF											
321186 32.180	REPLACE RIGHT MAIN WHEEL BOLTS	MOS HRS/MSC AFL	O/C							09-NOV-1996 5951 4589	L2	
	REF: NO REF											
320186 32.150	RIG STEERING SYSTEM	MOS HRS/MSC AFL	C/C							11-FEB-1982	L3	
	REF: AMM 32-50-00											

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
320621 32.220	AXLE, PISTON ROD FORK/ LEFT ES12908-503 SN-UNKNOWN REF: AMM 32-20-01	MOS HRS/MSC AFL	O/C	0					11-FEB-1982		L1	
321121 32.220	AXLE, PISTON ROD FORK/ RIGHT ES12908-504 SN-UNKNOWN REF: AMM 32-20-01	MOS HRS/MSC AFL	O/C	0					11-FEB-1982		L2	
321611 32.350	BOTTLE, EMERGENCY STORAGE 3753015-501 07510A1 REF: AMM 32-30-12	MOS HRS/MSC AFL	288	0					11-FEB-1982	LIFE LIMIT 11-FEB-2006	F5 1	
+ 321616 32.350	CHECK LANDING GEAR EMERGENCY SYSTEM PRESSURE PKG 2, 3 REF: AMM 12-10-04	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594		F5	
+ 321613 32.350	HYDROSTATIC TEST REF: AMM 32-30-12	MOS HRS/MSC AFL	36						26-OCT-1999 6961 5135	26-OCT-2002	F5	
320171 32.240	BRACE ASSEMBLY, DRAG NOSE GEAR PN SN-UNKNOWN REF: AMM 32-20-02	MOS HRS/MSC AFL	O/C	0					11-FEB-1982		L3	
320173 32.240	ADJUST PRELOAD REF: AMM 32-20-02	MOS HRS/MSC AFL	C/C						11-FEB-1982		L3	
320611 32.230	BRACE ASSEMBLY, SIDE/JURY LEFT MAIN GEAR EA1681-503 SN-UNKNOWN REF: AMM 32-10-02	MOS HRS/MSC AFL	O/C	0					11-FEB-1982		L1	
320616 32.230	ADJUST LEFT JURY BRACE PRELOAD REF: AMM 32-10-02	MOS HRS/MSC AFL	C/C						11-FEB-1982		L1	
321111 32.230	BRACE ASSEMBLY, SIDE/JURY RIGHT MAIN GEAR EA1681-503 SN-UNKNOWN REF: AMM 32-10-02	MOS HRS/MSC AFL	O/C	0					11-FEB-1982		L2	
321116 32.230	ADJUST RIGHT JURY BRACE PRELOAD REF: AMM 32-10-02	MOS HRS/MSC AFL	C/C						11-FEB-1982		L2	

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
320232 32.600	BRACKET, LOWER STEERING NOSE GEAR A0122360300-001 SN-UNKNOWN REF: AMM 32-50-08	MOS HRS/MSC AFL	O/C							22-FEB-2000 7107 5232	L3	
+ 320238 32.600	INSPECT REF: AMM 32-50-08	MOS HRS/MSC AFL	1600							22-FEB-2000 7107 5232	L3 8707	
SB 911391 ASSOCIATED	SB1124-32-139 LWR STRG SERVICE BULLETIN REF: Method of Compliance: OPEN	MOS HRS/MSC AFL	A/R									
320231 32.600	BRACKET, UPPER STEERING NOSE GEAR A01223603000-001 SN-UNKNOWN REF: AMM 32-50-08	MOS HRS/MSC AFL	O/C							22-FEB-2000 7107 5232	L3	
+ 320237 32.600	INSPECT REF: AMM 32-50-08	MOS HRS/MSC AFL	1600							22-FEB-2000 7107 5232	L3 8707	
SB 911390 ASSOCIATED	SB1124-32-139 UPR STRG SERVICE BULLETIN PKG 3 REF: Method of Compliance: OPEN	MOS HRS/MSC AFL	800							26-JUL-2000 7325 5360	8125	
322113 32.390	BRAKE, LEFT MAIN GEAR 5002805-3 21139-1 REF: AMM 32-43-01	MOS HRS/MSC AFL	O/C	0	0	0				17-JAN-2001 7494 5466	L1 \$1978. 2	
322136 32.400 ASSOCIATED	BLEED BRAKE SYSTEM REF: AMM 32-43-00	MOS HRS/MSC AFL	O/C							17-JAN-2001 7494 5466	L2	
+ 322116 32.390	INSPECT/CHECK LEFT BRAKE LININGS PKG 1, 2, 3 REF: AMM 32-43-01	MOS HRS/MSC AFL	200							26-JUN-2001 7687 5594	L1 1	
322128 32.390	BRAKE, RIGHT MAIN GEAR 5002805-3 JAN86-531 REF: AMM 32-43-01	MOS HRS/MSC AFL	O/C	0	0	0				17-JAN-2001 7494 5466	L2 \$1978. 2	
322136 32.400 ASSOCIATED	BLEED BRAKE SYSTEM REF: AMM 32-43-00	MOS HRS/MSC AFL	O/C							17-JAN-2001 7494 5466	L2	

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
+ 322131 32.390	INSPECT/CHECK RIGHT BRAKE LININGS PKG 1, 2, 3	MOS HRS/MSC AFL	200							26-JUN-2001 7687 5594	L2 1	
	REF: AMM 32-43-01	AFL										
322141 32.490	CONTROL BOX, ANTI-SKID 5-823519-503	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5 2	
	REF: AMM 32-44-01	AFL										
+ 322176 32.420 ASSOCIATED	FUNCTIONAL CHECK ANTI-SKID DETECTOR SYSTEM PKG 2, 3	MOS HRS/MSC AFL	400							26-JUN-2001 7687 5594	F3 1	
	REF: AMM 32-44-00	AFL										
320121 32.060	CYLINDER, ACTUATOR NOSE GEAR 5713059-505	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	L3 \$483. 3	
	REF: AMM 32-30-06	AFL										
320646 32.310	CYLINDER, AFT ACTUATING LEFT MAIN GEAR 5713061-505	MOS HRS/MSC AFL	O/C							09-JUN-1989 4274 2800	L1 \$443.	
	SN-UNKNOWN	HRS/MSC										
	REF: AMM 32-30-03	AFL										
321146 32.310	CYLINDER, AFT ACTUATING RIGHT MAIN GEAR 5713061-505	MOS HRS/MSC AFL	O/C		0					13-NOV-1995 5718 4397	L2 \$443.	
	REF: AMM 32-30-03	AFL										
320641 32.300	CYLINDER, FORWARD ACTUATING LEFT MAIN GEAR 5713061-505	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	L1 \$443.	
	REF: AMM 32-30-03	AFL										
321141 32.300	CYLINDER, FORWARD ACTUATING RIGHT MAIN GEAR 5713061-505	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	L2 \$443.	
	REF: AMM 32-30-03	AFL										
320181 32.140	CYLINDER, STEERING ACTUATING LEFT 4713096-509	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	L3 5	
	REF: AMM 32-50-02	AFL										
320184 32.140	CYLINDER, STEERING ACTUATING RIGHT 4713096-509	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	L3 5	
	REF: AMM 32-50-02	AFL										
320651 32.260	CYLINDER, UNLOCK LEFT MAIN GEAR 4713058-505	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	L1	
	REF: AMM 32-30-05	AFL										

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L



AIRCRAFT Status Report

Aircraft Model - 1124 WESTWIND
 Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
 A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
321151 32.260	CYLINDER, UNLOCK RIGHT MAIN GEAR 4713058-505 1091 REF: AMM 32-30-05	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	L2	
320126 32.070	CYLINDER, UPLOCK NOSE GEAR 4713005-501 0567 REF: AMM 32-30-08	MOS HRS/MSC AFL	O/C		0			06/08/1995		08-DEC-1994 5526 4218	L3	
322151 32.410	DETECTOR, ANTI-SKID LEFT MAIN GEAR 5-713513-503 200 REF: AMM 32-44-06	MOS HRS/MSC AFL	O/C	0						13-JUL-1988 3978 2511	L1 \$1064. 1	
+ 322176 32.420 ASSOCIATED	FUNCTIONAL CHECK ANTI-SKID DETECTOR SYSTEM PKG 2, 3 REF: AMM 32-44-00	MOS HRS/MSC AFL	400							26-JUN-2001 7687 5594	F3 1	
+ 322156 32.410 ASSOCIATED	INSPECT/CLEAN LEFT ANTI-SKID DETECTOR PKG 1, 2, 3 REF: AMM 5-20-04	MOS HRS/MSC AFL	200							26-JUN-2001 7687 5594	L1 1	
+ 322174 32.425 ASSOCIATED	OPERATIONAL CHECK ANTI-SKID LIGHTS PKG 1, 2, 3 REF: AMM 32-44-00	MOS HRS/MSC AFL	200							26-JUN-2001 7687 5594	F3 .5	
322166 32.410	DETECTOR, ANTI-SKID RIGHT MAIN GEAR 5-713513-504 553 REF: AMM 32-44-06	MOS HRS/MSC AFL	O/C	0						17-DEC-1983 1454 878	L2 \$1064. 1	
+ 322176 32.420 ASSOCIATED	FUNCTIONAL CHECK ANTI-SKID DETECTOR SYSTEM PKG 2, 3 REF: AMM 32-44-00	MOS HRS/MSC AFL	400							26-JUN-2001 7687 5594	F3 1	
+ 322171 32.410 ASSOCIATED	INSPECT/CLEAN RIGHT ANTI-SKID DETECTOR PKG 1, 2, 3 REF: AMM 5-20-04	MOS HRS/MSC AFL	200							26-JUN-2001 7687 5594	L2 1	
+ 322174 32.425 ASSOCIATED	OPERATIONAL CHECK ANTI-SKID LIGHTS PKG 1, 2, 3 REF: AMM 32-44-00	MOS HRS/MSC AFL	200							26-JUN-2001 7687 5594	F3 .5	
322111 32.380	FUSE, BRAKE HYDRAULIC LEFT 3-713047 1797 REF: AMM 32-43-04	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	W1	

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNT	INTERVAL	TIME-----AT-----	INSTALLATION	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
					TSN TSO TSR TSI ADJ					
322126		FUSE, BRAKE HYDRAULIC RIGHT								W2
	32.380	3-71 3047	MOS						11-FEB-1982	
		3371	HRS/MSC	O/C	0					
		REF: AMM 32-43-04	AFL							
320601		GEAR ASSEMBLY, MAIN LEFT								L1
	32.210	400-144-511	MOS						11-FEB-1982	
		1L195	HRS/MSC	O/C	0					
		REF: AMM 32-10-01	AFL							
320631		CHECK MAIN GEAR PARALLELISM								L1
	32.470		MOS						11-FEB-1982	
			HRS/MSC	C/C						
		REF: AMM 32-10-01	AFL							
320634		CHECK LEFT MAIN GEAR CLEARANCE								L1
	32.480		MOS						11-FEB-1982	
			HRS/MSC	C/C						
		REF: AMM 32-10-01	AFL							
+ 322211		FUNCTIONAL TEST EMERGENCY GEAR EXTENSION								F3
	32.450	PKG 3	MOS						26-JUL-2000	
		ASSOCIATED	HRS/MSC	800					7325	
		REF: AMM 32-30-00	AFL						5360	
+ 322206		FUNCTIONAL TEST EMERGENCY GEAR EXTENSION CONTROL CABLE								F3
	32.440	PKG 1, 2, 3	MOS						26-JUN-2001	
		ASSOCIATED	HRS/MSC	200					7687	1
		REF: AMM 32-30-00	AFL						5594	
+ 322191		FUNCTIONAL TEST LANDING GEAR (NORMAL)								F3
	32.430	PKG 2, 3	MOS						26-JUN-2001	
		ASSOCIATED	HRS/MSC	400					7687	
		REF: AMM 32-30-00	AFL						5594	
+ 322201		FUNCTIONAL TEST LANDING GEAR FREE FALL								F3
	32.430	PKG 2, 3	MOS						26-JUN-2001	
		ASSOCIATED	HRS/MSC	400					7687	
		REF: See Workcard	AFL						5594	
320606		LUBRICATE LEFT MAIN GEAR								L1
	32.030	PKG 1, 2, 3	MOS						26-JUN-2001	
			HRS/MSC	200					7687	.5
		REF: AMM 12-20-00	AFL						5594	
320636		SERVICE LEFT MAIN GEAR SHOCK STRUT								L1
	32.040	PKG 2, 3	MOS						26-JUN-2001	
			HRS/MSC	400					7687	2
		REF: AMM 12-10-04	AFL						5594	
SB 951030		SL WW-24103 L/H SERVICE BULLETIN								L1
		ASSOCIATED	MOS							
			HRS/MSC	A/R						
		REF:	AFL							
		Method of Compliance: OPEN								

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L



AIRCRAFT Status Report

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
SB 950941	SLWW-2494 REV 3 LMG BOLTS SERVICE BULLETIN	MOS							26-JUN-2001	L1	
ASSOCIATED	REF: See Workcard	HRS/MSC	300					7687	7987		
	Method of Compliance: OPEN	AFL						5594			
321101	GEAR ASSEMBLY, MAIN RIGHT	MOS							11-FEB-1982	L2	
32.210	400-144-512	HRS/MSC	O/C	0							
	1L195	AFL									
	REF: AMM 32-10-01										
321134	CHECK RIGHT MAIN GEAR CLEARANCE	MOS							11-FEB-1982	L2	
32.480		HRS/MSC	C/C								
	REF: AMM 32-10-01	AFL									
+ 322211	FUNCTIONAL TEST EMERGENCY GEAR EXTENSION	MOS							26-JUL-2000	F3	
32.450	PKG 3	HRS/MSC	800					7325			
ASSOCIATED	REF: AMM 32-30-00	AFL						5360			
+ 322206	FUNCTIONAL TEST EMERGENCY GEAR EXTENSION CONTROL CABLE	MOS							26-JUN-2001	F3	
32.440	PKG 1, 2, 3	HRS/MSC	200					7687		1	
ASSOCIATED	REF: AMM 32-30-00	AFL						5594			
+ 322191	FUNCTIONAL TEST LANDING GEAR (NORMAL)	MOS							26-JUN-2001	F3	
32.430	PKG 2, 3	HRS/MSC	400					7687			
ASSOCIATED	REF: AMM 32-30-00	AFL						5594			
+ 322201	FUNCTIONAL TEST LANDING GEAR FREE FALL	MOS							26-JUN-2001	F3	
32.430	PKG 2, 3	HRS/MSC	400					7687			
ASSOCIATED	REF: See Workcard	AFL						5594			
321106	LUBRICATE RIGHT MAIN GEAR	MOS							26-JUN-2001	L2	
32.030	PKG 1, 2, 3	HRS/MSC	200					7687		.5	
	REF: AMM 12-20-00	AFL						5594			
321136	SERVICE RIGHT MAIN GEAR SHOCK STRUT	MOS							26-JUN-2001	L2	
32.040	PKG 2, 3	HRS/MSC	400					7687		2	
	REF: AMM 12-10-04	AFL						5594			
SB 951031	SL WW-24103 R/H SERVICE BULLETIN	MOS								L2	
ASSOCIATED	REF:	HRS/MSC	A/R								
	Method of Compliance: OPEN	AFL									
SB 950942	SLWW-2494 REV 3 RMG BOLTS SERVICE BULLETIN	MOS							26-JUN-2001	L2	
ASSOCIATED	REF: See Workcard	HRS/MSC	300					7687	7987		
	Method of Compliance: OPEN	AFL						5594			

? - Insufficient Information
 + Task exists in FAA Manual
 3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
320101 32.050	NOSE GEAR ASSEMBLY, 400-143-511 1L184 REF: AMM 32-20-01	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	L3	
320179 32.580	INSPECT NOSE STEERING CABLES PKG 3 REF: AMM 32-50-07	MOS HRS/MSC AFL		800						26-JUL-2000 7325 5360	L1	
320120 32.520	INSPECT OUTER STRUT BODY FORGING REF: AMM 32-20-01	MOS HRS/MSC AFL		1200						22-FEB-2000 7107 5232	L3 8307	
320118 32.540	INSPECT/LUBRICATE UPPER/LOWER STRUT BEARINGS BODY REF: AMM 32-20-01	MOS HRS/MSC AFL		24 1200						22-FEB-2000 7107 5232	L3 8307	
320106 32.030	LUBRICATE NOSE GEAR/DOORS PKG 1, 2, 3 REF: AMM 12-20-00	MOS HRS/MSC AFL		200						26-JUN-2001 7687 5594	L3 .5	
320180 32.590	LUBRICATE NOSE STEERING CONTROL CABLES PKG 3 REF: AMM 12-20-00	MOS HRS/MSC AFL		800						26-JUL-2000 7325 5360	L1	
SB 900280 ASSOCIATED	SB WW 24-28A SERVICE BULLETIN REF: See Workcard Method of Compliance: OPEN	MOS HRS/MSC AFL		1200						22-FEB-2000 7107 5232	L3	
320116 32.040	SERVICE SHOCK STRUT PKG 2, 3 REF: AMM 12-10-04	MOS HRS/MSC AFL		400						26-JUN-2001 7687 5594	L3 2.5	
320172 32.240	TEST DRAG BRACE DOWNLOCK TENSION PKG 3 REF: AMM 32-20-02	MOS HRS/MSC AFL		800						26-JUL-2000 7325 5360	L3	
+ 320110 32.560	X-RAY INSPECT NOSE GEAR SHAFT AND DOOR ASSEMBLIES REF: AMM 5-10-00	MOS HRS/MSC AFL		60 5000						16-JUN-1997 6135 4707	L3 16-JUN-2002 11135	
321603 32.200	SELECTOR, GEAR VALVE 713025-501 IL-41 REF: NO REF	MOS HRS/MSC AFL	O/C		0			06/09/1995	09-DEC-1994	5526 4218	F3	

COPYRIGHT 2001 CAMP SYSTEMS INT'L

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
320661 32.280	SWITCH, DOWNLOCK LEFT MAIN GEAR 4-823051	MOS								11-FEB-1982	L1	
	SN-UNKNOWN REF: NO REF	HRS/MS AFL	O/C	0								
320663 32.280	ADJUST	MOS								11-FEB-1982	L1	
	REF: AMM 32-60-00	HRS/MS AFL	C/C									
320131 32.080	SWITCH, DOWNLOCK NOSE GEAR 4-823012-501	MOS								11-FEB-1982	L3	
	SN-UNKNOWN REF: AMM 32-60-00	HRS/MS AFL	O/C	0								
320133 32.080	ADJUST	MOS								11-FEB-1982	L3	
	REF: AMM 32-60-00	HRS/MS AFL	C/C									
321161 32.280	SWITCH, DOWNLOCK RIGHT MAIN GEAR 4-823051	MOS								11-FEB-1982	L2	
	SN-UNKNOWN REF: NO REF	HRS/MS AFL	O/C	0								
321163 32.280	ADJUST	MOS								11-FEB-1982	L2	
	REF: AMM 32-60-00	HRS/MS AFL	C/C									
320666 32.290	SWITCH, GROUND CONTACT LEFT MAIN GEAR 4-823051	MOS								11-FEB-1982	L1	
	SN-UNKNOWN REF: NO REF	HRS/MS AFL	O/C	0								
320668 32.290	ADJUST	MOS								11-FEB-1982	L1	
	REF: AMM 32-60-00	HRS/MS AFL	C/C									
320141 32.100	SWITCH, GROUND CONTACT NOSE GEAR 4-823053-501	MOS								11-FEB-1982	L3	
	SN-UNKNOWN REF: See Workcard	HRS/MS AFL	O/C	0								
320143 32.100	ADJUST	MOS								11-FEB-1982	L3	
	REF: AMM 32-60-00	HRS/MS AFL	C/C									
321166 32.290	SWITCH, GROUND CONTACT RIGHT MAIN GEAR 4-823024-505	MOS								11-FEB-1982	L2	
	SN-UNKNOWN REF: See Workcard	HRS/MS AFL	O/C	0								

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
321168 32.290	ADJUST	MOS HRS/MSC AFL	C/C						11-FEB-1982	L2	
	REF: AMM 32-60-00										
320656 32.270	SWITCH, UPLOCK LEFT MAIN GEAR 3-823003	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	L1	
	SN-UNKNOWN REF: NO REF										
320658 32.270	ADJUST	MOS HRS/MSC AFL	C/C						11-FEB-1982	L1	
	REF: AMM 32-60-00										
320136 32.090	SWITCH, UPLOCK NOSE GEAR 3-823003	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	L3	
	SN-UNKNOWN REF: AMM 32-60-00										
320138 32.090	ADJUST	MOS HRS/MSC AFL	C/C						11-FEB-1982	L3	
	REF: AMM 32-60-00										
321156 32.270	SWITCH, UPLOCK RIGHT MAIN GEAR 3-823003	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	L2	
	SN-UNKNOWN REF: NO REF										
321158 32.270	ADJUST	MOS HRS/MSC AFL	C/C						11-FEB-1982	L2	
	REF: AMM 32-60-00										
320681 32.180	TIRE, LEFT MAIN GEAR 249K83-3	MOS HRS/MSC AFL	O/C	0					09-NOV-1996 5951 4589	L1 2	
	SN-UNKNOWN REF: AMM 32-41-00										
321181 32.190	TIRE, RIGHT MAIN GEAR 249K83-3	MOS HRS/MSC AFL	O/C	0					09-NOV-1996 5951 4589	L2 2	
	SN-UNKNOWN REF: AMM 32-41-00										
320161 32.110	TIRE, LEFT NOSE GEAR 164F43-2	MOS HRS/MSC AFL	O/C	0					22-NOV-1995 5720 4401	L3	
	31162139 REF: AMM 32-42-00										
320166 32.120	TIRE, RIGHT NOSE GEAR 164F43-2	MOS HRS/MSC AFL	O/C	0					29-NOV-1995 5720 4401	L3	
	22051064 REF: AMM 32-42-00										

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
320626 32.250	UPLOCK, LEFT MAIN GEAR 5-173057-501 SN-UNKNOWN REF: AMM 32-32-04	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	L1	
321126 32.250	UPLOCK, RIGHT MAIN GEAR 5-173057-502 SN-UNKNOWN REF: AMM 32-30-04	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	L2	
320176 32.130	VALVE ASSEMBLY, STEERING BA1801-2 1L185 REF: AMM 32-50-01	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	L3	
322146 32.500	VALVE, ANTI-SKID CONTROL LEFT 5723578-1 313A REF: AMM 32-44-02	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5	
322149 32.500	CLEAN FILTERS REF: AMM 32-41-00	MOS HRS/MSC AFL	1200						22-FEB-2000 7107 5232	8307	F5	
+ 322176 32.420 ASSOCIATED	FUNCTIONAL CHECK ANTI-SKID DETECTOR SYSTEM PKG 2, 3 REF: AMM 32-44-00	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594		F3 1	
322161 32.500	VALVE, ANTI-SKID CONTROL RIGHT 5723578-1 503A REF: AMM 32-44-02	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5	
322169 32.500	CLEAN FILTERS REF: AMM 32-41-00	MOS HRS/MSC AFL	1200						22-FEB-2000 7107 5232	8307	F5	
+ 322176 32.420 ASSOCIATED	FUNCTIONAL CHECK ANTI-SKID DETECTOR SYSTEM PKG 2, 3 REF: AMM 32-44-00	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594		F3 1	
322106 32.370	VALVE, BRAKE SHUTTLE LEFT 4-713066 2752 REF: AMM 32-43-03	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	W1	
322121 32.370	VALVE, BRAKE SHUTTLE RIGHT 4-713066 2775 REF: AMM 32-43-03	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	W2	

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
321606 32.340	VALVE, EMERGENCY GEAR EXTENSION 874521B SN-UNKNOWN REF: AMM 32-30-11	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5	
321601 32.320	VALVE, LANDING GEAR CONTROL 4753036 372 REF: AMM 32-30-01	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F2 \$644. 25	
320177 32.170	VALVE, NOSE STEERING SOLENOID 713557-501 SN-UNKNOWN REF: AMM 32-50-00	MOS HRS/MSC AFL	O/C							11-FEB-1982	L3	
320191 32.160	OPERATIONAL CHECK NOSE STEERING REF: AMM 32-50-00	MOS HRS/MSC AFL	C/C							11-FEB-1982	L3	
322181 32.510	VALVE, PARKING MOTOR 3-713551 L34900 REF: AMM 32-44-03	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5	
+ 322176 32.420 ASSOCIATED	FUNCTIONAL CHECK ANTI-SKID DETECTOR SYSTEM PKG 2, 3 REF: AMM 32-44-00	MOS HRS/MSC AFL		400						26-JUN-2001 7687 5594	F3 1	
322101 32.360	VALVE, POWER BRAKE 5713001-501 617AB REF: AMM 32-43-02	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F2 \$1932. 5	
320221 32.330	VALVE, SHUTTLE NOSE GEAR 4713066 SN-UNKNOWN REF: AMM 32-30-07	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	L3	
320671 32.180	WHEEL HALF, INBOARD LEFT MAIN GEAR 5002806-2 JUN89-537 REF: AMM 32-41-00	MOS HRS/MSC AFL	O/C							09-NOV-1996 5951 4589	L1 1	
320681 32.180 ASSOCIATED	CHANGE LEFT MAIN GEAR TIRE 249K83-3 SN-UNKNOWN REF: AMM 32-41-00	MOS HRS/MSC AFL	O/C	0 0 0						09-NOV-1996 5951 4589	L1 2	
320672 32.180 ASSOCIATED	CHANGE LEFT MAIN GEAR OUTBOARD WHEEL HALF 5002806-2 JUN89-537 REF: AMM 32-41-00	MOS HRS/MSC AFL	O/C							09-NOV-1996 5951 4589	L1 1	

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
320678	DYE PENETRANT CHECK LEFT WHEEL AXLE									L1	
32.550	PKG 2, 3	MOS						26-JUN-2001			
	ASSOCIATED	HRS/MSC	400					7687			
	REF: AMM 5-20-04	AFL						5594			
+ 320691	INSPECT LEFT MAIN GEAR/WELL (A)									L1	
32.020	PKG 1, 2, 3	MOS						26-JUN-2001			
	ASSOCIATED	HRS/MSC	200					7687	1.5		
	REF: AMM WCF 32.020	AFL						5594			
+ 322156	INSPECT/CLEAN LEFT ANTI-SKID DETECTOR									L1	
32.410	PKG 1, 2, 3	MOS						26-JUN-2001			
	ASSOCIATED	HRS/MSC	200					7687	1		
	REF: AMM 5-20-04	AFL						5594			
+ 320676	INSPECT/LUBRICATE LEFT MAIN GEAR INBOARD WHEEL BEARINGS									L1	
32.180	PKG 1, 2, 3	MOS						26-JUN-2001			
	ASSOCIATED	HRS/MSC	200					7687	1		
	REF: AMM 32-41-00	AFL						5594			
+ 322174	OPERATIONAL CHECK ANTI-SKID LIGHTS									F3	
32.425	PKG 1, 2, 3	MOS						26-JUN-2001			
	ASSOCIATED	HRS/MSC	200					7687	.5		
	REF: AMM 32-44-00	AFL						5594			
320686	REPLACE LEFT MAIN WHEEL BOLTS									L1	
32.180		MOS						09-NOV-1996			
	ASSOCIATED	HRS/MSC	O/C					5951			
	REF: NO REF	AFL						4589			
321171	WHEEL HALF, INBOARD RIGHT MAIN GEAR									L2	
32.190	5002806-2	MOS						09-NOV-1996			
	MAR84-662	HRS/MSC	O/C					5951	1		
	REF: AMM 32-41-00	AFL						4589			
321181	CHANGE RIGHT MAIN GEAR TIRE									L2	
32.190	249K83-3	MOS				0		09-NOV-1996			
	ASSOCIATED	HRS/MSC	O/C			0		5951	2		
	REF: AMM 32-41-00	AFL				0		4589			
321172	CHANGE RIGHT MAIN GEAR OUTBOARD WHEEL HALF									L2	
32.190	5002806-2	MOS						09-NOV-1996			
	ASSOCIATED	HRS/MSC	O/C					5951	1		
	MAR84-662	HRS/MSC	O/C					5951			
	REF: AMM 32-41-00	AFL						4589			
321178	DYE PENETRANT CHECK RIGHT WHEEL AXLE									L2	
32.550	PKG 2, 3	MOS						26-JUN-2001			
	ASSOCIATED	HRS/MSC	400					7687			
	REF: AMM 5-20-04	AFL						5594			
+ 322171	INSPECT/CLEAN RIGHT ANTI-SKID DETECTOR									L2	
32.410	PKG 1, 2, 3	MOS						26-JUN-2001			
	ASSOCIATED	HRS/MSC	200					7687	1		
	REF: AMM 5-20-04	AFL						5594			

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO	WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
					TSN	TSO	TSR	TSI	ADJ				
+ 321176		INSPECT/LUBRICATE RIGHT MAIN GEAR INBOARD WHEEL BEARINGS										L2	
	32.180	PKG 1, 2, 3	MOS								26-JUN-2001		
		REF: AMM 32-41-00	HRS/MSC	200							7687	1	
			AFL								5594		
+ 322174		OPERATIONAL CHECK ANTI-SKID LIGHTS										F3	
	32.425	PKG 1, 2, 3	MOS								26-JUN-2001		
	ASSOCIATED		HRS/MSC	200							7687	.5	
		REF: AMM 32-44-00	AFL								5594		
321186		REPLACE RIGHT MAIN WHEEL BOLTS										L2	
	32.180		MOS								09-NOV-1996		
	ASSOCIATED		HRS/MSC	O/C							5951		
		REF: NO REF	AFL								4589		
320672		WHEEL HALF, OUTBOARD LEFT MAIN GEAR										L1	
	32.180	5002806-2	MOS								09-NOV-1996		
		JUN89-537	HRS/MSC	O/C							5951	1	
		REF: AMM 32-41-00	AFL								4589		
320681		CHANGE LEFT MAIN GEAR TIRE										L1	
	32.180	249K83-3	MOS			0					09-NOV-1996		
	ASSOCIATED	SN-UNKNOWN	HRS/MSC	O/C		0					5951	2	
		REF: AMM 32-41-00	AFL			0					4589		
320678		DYE PENETRANT CHECK LEFT WHEEL AXLE										L1	
	32.550	PKG 2, 3	MOS								26-JUN-2001		
	ASSOCIATED		HRS/MSC	400							7687		
		REF: AMM 5-20-04	AFL								5594		
+ 320691		INSPECT LEFT MAIN GEAR/WELL (A)										L1	
	32.020	PKG 1, 2, 3	MOS								26-JUN-2001		
	ASSOCIATED		HRS/MSC	200							7687	1.5	
		REF: AMM WCF 32.020	AFL								5594		
+ 322156		INSPECT/CLEAN LEFT ANTI-SKID DETECTOR										L1	
	32.410	PKG 1, 2, 3	MOS								26-JUN-2001		
	ASSOCIATED		HRS/MSC	200							7687	1	
		REF: AMM 5-20-04	AFL								5594		
+ 320680		INSPECT/LUBRICATE LEFT MAIN GEAR OUTBOARD WHEEL BEARINGS										L1	
	32.180	PKG 1, 2, 3	MOS								26-JUN-2001		
		REF: AMM 32-41-00	HRS/MSC	200							7687		
			AFL								5594		
+ 322174		OPERATIONAL CHECK ANTI-SKID LIGHTS										F3	
	32.425	PKG 1, 2, 3	MOS								26-JUN-2001		
	ASSOCIATED		HRS/MSC	200							7687	.5	
		REF: AMM 32-44-00	AFL								5594		
320686		REPLACE LEFT MAIN WHEEL BOLTS										L1	
	32.180		MOS								09-NOV-1996		
	ASSOCIATED		HRS/MSC	O/C							5951		
		REF: NO REF	AFL								4589		

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
321172	WHEEL HALF, OUTBOARD RIGHT MAIN GEAR									L2	
32.190	5002806-2	MOS						09-NOV-1996			
	MAR84-662	HRS/MSC	O/C					5951		1	
	REF: AMM 32-41-00	AFL						4589			
321181	CHANGE RIGHT MAIN GEAR TIRE									L2	
32.190	249K83-3	MOS						09-NOV-1996			
ASSOCIATED	SN-UNKNOWN	HRS/MSC	O/C					5951		2	
	REF: AMM 32-41-00	AFL						4589			
321178	DYE PENETRANT CHECK RIGHT WHEEL AXLE									L2	
32.550	PKG 2, 3	MOS						26-JUN-2001			
ASSOCIATED		HRS/MSC	400					7687			
	REF: AMM 5-20-04	AFL						5594			
+ 321191	INSPECT RIGHT MAIN GEAR/WELL (A)									L2	
32.020	PKG 1, 2, 3	MOS						26-JUN-2001			
		HRS/MSC	200					7687		1.5	
	REF: AMM WCF 32.020	AFL						5594			
+ 322171	INSPECT/CLEAN RIGHT ANTI-SKID DETECTOR									L2	
32.410	PKG 1, 2, 3	MOS						26-JUN-2001			
ASSOCIATED		HRS/MSC	200					7687		1	
	REF: AMM 5-20-04	AFL						5594			
321180	INSPECT/LUBRICATE RIGHT MAIN GEAR OUTBOARD WHEEL BEARINGS									L2	
32.180	PKG 1, 2, 3	MOS						26-JUN-2001			
		HRS/MSC	200					7687		1	
	REF: AMM 32-41-00	AFL						5594			
+ 322174	OPERATIONAL CHECK ANTI-SKID LIGHTS									F3	
32.425	PKG 1, 2, 3	MOS						26-JUN-2001			
ASSOCIATED		HRS/MSC	200					7687		.5	
	REF: AMM 32-44-00	AFL						5594			
321186	REPLACE RIGHT MAIN WHEEL BOLTS									L2	
32.180		MOS						09-NOV-1996			
ASSOCIATED		HRS/MSC	O/C					5951			
	REF: NO REF	AFL						4589			
320146	WHEEL LEFT NOSE GEAR									L3	
32.110	41874	MOS						22-NOV-1995			
	APR66-109	HRS/MSC	O/C			0		5720		4	
	REF: AMM 32-42-00	AFL						4401			
320161	CHANGE NOSE GEAR LEFT TIRE									L3	
32.110	164F43-2	MOS						22-NOV-1995			
ASSOCIATED	31162139	HRS/MSC	O/C			0		5720			
	REF: AMM 32-42-00	AFL						4401			
+ 320156	INSPECT/CLEAN/LUBRICATE BEARINGS									L3	
32.110	PKG 1, 2, 3	MOS						26-JUN-2001			
		HRS/MSC	200					7687		1.5	
	REF: AMM 5-20-01	AFL						5594			

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
320151	WHEEL, RIGHT NOSE GEAR										L3	
32.120	9541874	MOS								29-NOV-1995		
	OCT75-64 1	HRS/MSC	O/C		0					5720	4	
	REF: AMM 32-42-00	AFL								4401		
320166	CHANGE NOSE GEAR RIGHT TIRE										L3	
32.120	164F43-2	MOS								29-NOV-1995		
ASSOCIATED	22051064	HRS/MSC	O/C		0					5720		
	REF: AMM 32-42-00	AFL								4401		
+ 320158	INSPECT/CLEAN/LUBRICATE BEARINGS										L3	
32.120	PKG 1, 2, 3	MOS								26-JUN-2001		
	REF: AMM 5-20-01	HRS/MSC	200							7687	1.5	
		AFL								5594		
CHAPTER 33	LIGHTS											
330226	BATTERY, EMERGENCY LIGHT										F4	
33.100	AD-2058	MOS			0					06-OCT-1998		
	SN-UNKNOWN	HRS/MSC	O/C		0					6520		
	REF: AMM 33-50-00	AFL			0					4889		
330320	INVERTER, LIGHT POWER (CF-38-3)										F2	
33.070	CF-38-3	MOS								11-FEB-1982		
	291	HRS/MSC	O/C		0							
	REF: NO REF	AFL										
330111	LIGHT, TAIL CONE										F1	
33.020	4-823006-501	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C		0							
	REF: AMM 33-40-00	AFL										
330161	LIGHT, ANTI-COLLISION LOWER										F1	
33.030	G-9950-11	MOS						10/28/1989		28-APR-1989	\$635.	
	11709	HRS/MSC	O/C							4240		
	REF: AMM 33-40-00	AFL								2767		
330156	LIGHT, ANTI-COLLISION UPPER										T1	
33.030	G9950-11	MOS			0					26-JUL-2000	\$635.	
	11709	HRS/MSC	O/C		0					7325		
	REF: AMM 33-40-00	AFL			0					5360		
330221	LIGHT, EMERGENCY										F4	
33.090	3-823551-503	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C		0							
	REF: AMM 33-50-00	AFL										
330226	CHANGE EMERGENCY LIGHT BATTERY										F4	
33.100	AD-2058	MOS			0					06-OCT-1998		
ASSOCIATED	SN-UNKNOWN	HRS/MSC	O/C		0					6520		
	REF: AMM 33-50-00	AFL			0					4889		
330228	CHARGE BATTERY										F4	
33.100		MOS	3							06-NOV-2001	06-FEB-2002	
		HRS/MSC	200							7774	7974	
	REF: AMM 12-10-06	AFL								5641		

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
330136 33.060	LIGHT, LANDING LEFT 5-213004-1 SN-UNKNOWN REF: AMM 33-40-00	MOS HRSMSC AFL	O/C	0					11-FEB-1982	W1	
330146 33.060	LIGHT, LANDING RIGHT 5-213004-2 SN-UNKNOWN REF: AMM 33-40-00	MOS HRSMSC AFL	O/C	0					11-FEB-1982	W2	
330101 33.010	LIGHT, POSITION LEFT WING 301085-1 4224 REF: AMM 33-40-00	MOS HRSMSC AFL	O/C	0					11-FEB-1982	W1	
330106 33.010	LIGHT, POSITION RIGHT WING 301085-2 5772 REF: AMM 33-40-00	MOS HRSMSC AFL	O/C	0					11-FEB-1982	W2	
330166 33.040	LIGHT, STROBE LEFT WING 31-3172-11 SN-UNKNOWN REF: AMM 33-40-00	MOS HRSMSC AFL	O/C	0					11-FEB-1982	W1	
330171 33.040	LIGHT, STROBE RIGHT WING 31-3172-11 SN-UNKNOWN REF: AMM 33-40-00	MOS HRSMSC AFL	O/C	0					11-FEB-1982	W2	
330116 33.050	LIGHT, TAXI LEFT 5-823521-1 GE-4587 REF: AMM 33-40-00	MOS HRSMSC AFL	O/C						30-AUG-1989 4350 2898	L1	
330126 33.050	LIGHT, TAXI RIGHT 5-823521-2 GE-4587 REF: AMM 33-40-00	MOS HRSMSC AFL	O/C						30-AUG-1989 4350 2898	L2	
330505 33.085	POWER SUPPLY, 60-2799-1 SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL	O/C						11-FEB-1982	W1	
330241 33.080	POWER SUPPLY, NO. 1 60-2799-1 6701 REF: NO REF	MOS HRSMSC AFL	O/C	0					11-FEB-1982	W1	
330246 33.080	POWER SUPPLY, NO. 2 60-2799-1 SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL	O/C	0					25-APR-1984 1641 1010	W2	

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
330522 33.085	POWER SUPPLY, NO.4 60-2799-1	MOS							11-FEB-1982	W2	
	SN-UNKNOWN REF: NO REF	HRS/MSC AFL	O/C								
330325 33.070	UNIT, LIGHT POWER (CV-38) CV-38	MOS							11-FEB-1982	F2	
	6125 REF: NO REF	HRS/MSC AFL	O/C								
CHAPTER 34 NAVIGATION											
340121 34.060	DRAIN PITOT/STATIC SYSTEM PKG 1, 2, 3	MOS							26-JUN-2001	F2	
	REF: AMM 34-10-00	HRS/MSC AFL	200					7687 5594		1.5	
340111 34.040	LEAK CHECK LEFT PITOT SYSTEM	MOS							26-MAR-1996	F1	
	REF: AMM 34-10-01	HRS/MSC AFL	O/C								
+ 340146 34.050	LEAK CHECK LEFT STATIC SYSTEM	MOS	24						18-JAN-2001	MANDATORY 18-JAN-2003	
	REF: AMM 34-10-01	HRS/MSC AFL						7494 5466		F1	
340116 34.040	LEAK CHECK RIGHT PITOT SYSTEM	MOS							11-FEB-1982	F1	
	REF: AMM 34-10-01	HRS/MSC AFL	O/C								
+ 340151 34.050	LEAK CHECK RIGHT STATIC SYSTEM	MOS	24						18-JAN-2001	MANDATORY 18-JAN-2003	
	REF: AMM 34-10-01	HRS/MSC AFL						7494 5466		F1	
343141 34.390	SWING CHECK NO.1 COMPASS	MOS							11-FEB-1982	F3	
	REF: AMM 34-20-08	HRS/MSC AFL	O/C								
343186 34.390	SWING CHECK NO.2 COMPASS	MOS							11-FEB-1982	F3	
	REF: AMM 34-20-08	HRS/MSC AFL	O/C								
345101 34.490	ADVISORY, FLIGHT PROFILE 622-4569-001	MOS							11-FEB-1982	F3	
	SN-UNKNOWN REF: NO REF	HRS/MSC AFL	O/C	0				0			
345629 34.310	ALERTER, AL TITUDE 540-25100-004	MOS							11-FEB-1982	F3	
	SN-UNKNOWN REF: AMM 34-10-03	HRS/MSC AFL	O/C	0							

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
341111	ALTIMETER, COPILOT										F3	
34.071	4883778-501	MOS							11-FEB-1982			
	3008	HRS/MSC	O/C	0								
	REF: NO REF	AFL										
+ 340151	LEAK CHECK RIGHT STATIC SYSTEM									MANDATORY	F1	
34.050		MOS	24						18-JAN-2001	18-JAN-2003		
	ASSOCIATED	HRS/MSC							7494			
	REF: AMM 34-10-01	AFL							5466			
+ 341116	TEST FAR 91.411									MANDATORY	F3	
34.071		MOS	24						18-JAN-2001	18-JAN-2003		
		HRS/MSC							7494			
	REF:	AFL							5466			
341101	ALTIMETER, PILOT										F3	
34.070	622-3975-003	MOS							11-FEB-1982			
	1323	HRS/MSC	O/C	0								
	REF: AMM 34-10-03	AFL										
+ 340146	LEAK CHECK LEFT STATIC SYSTEM									MANDATORY	F1	
34.050		MOS	24						18-JAN-2001	18-JAN-2003		
	ASSOCIATED	HRS/MSC							7494			
	REF: AMM 34-10-01	AFL							5466			
+ 341106	TEST FAR 91.411									MANDATORY	F3	
34.070		MOS	24						18-JAN-2001	18-JAN-2003		
		HRS/MSC							7494			
	REF:	AFL							5466			
341121	ALTIMETER, STAND-BY										F3	
34.075	622-3975-003	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C	0								
	REF: NO REF	AFL										
+ 340146	LEAK CHECK LEFT STATIC SYSTEM									MANDATORY	F1	
34.050		MOS	24						18-JAN-2001	18-JAN-2003		
	ASSOCIATED	HRS/MSC							7494			
	REF: AMM 34-10-01	AFL							5466			
+ 340151	LEAK CHECK RIGHT STATIC SYSTEM									MANDATORY	F1	
34.050		MOS	24						18-JAN-2001	18-JAN-2003		
	ASSOCIATED	HRS/MSC							7494			
	REF: AMM 34-10-01	AFL							5466			
343176	ANNUNCIATOR, COMPASS COPILOT										F3	
34.170	PN	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C	0								
	REF: AMM 34-20-08	AFL										
343131	ANNUNCIATOR, COMPASS PILOT										F3	
34.170	PN	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C	0								
	REF: AMM 34-20-08	AFL										

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
346681 34.640	ANTENNA, #1 VLF 10085-2 6025 REF: AMM 34-60-02	MOS HRS/MSC AFL	O/C	0						03-APR-1989 4215 2745	F5	
347681 34.570	ANTENNA, GLIDESLOPE DMN-25-1 1896 REF: AMM 34-50-01	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F2	
346611 34.350	ANTENNA, NO.1 ADF LOOP 522-3761-001 4428 REF: AMM 34-50-03/04	MOS HRS/MSC AFL	O/C	0						31-JAN-1986 2855 1770	F1	
346131 34.330	ANTENNA, NO.1 ATC TRANSPONDER DMNI-50-6 323 REF: AMM 34-50-06	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F1	
347121 34.360	ANTENNA, NO.1 DME 4-87 3127-501 3234 REF: AMM 34-50-02	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F1 2	
348111 34.660	ANTENNA, NO.1 LRN 42804-000 100-00 1346 REF: AMM 34-60-04	MOS HRS/MSC AFL	O/C	0						11-FEB-1982		
346206 34.550	ANTENNA, NO.1 MARKER BEACON DMN-27-1/A 1919 REF: AMM 34-50-01	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5	
346546 34.580	ANTENNA, NO.1 VOR DMN-4-15-3/D 10987 REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5	
346636 34.350	ANTENNA, NO.2 ADF LOOP 522-3761-001 SN-UNKNOWN REF: AMM 34-50-03/04	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F1	
346136 34.330	ANTENNA, NO.2 ATC TRANSPONDER DMNI-50-6 3259 REF: AMM 34-50-06	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F1	
347621 34.360	ANTENNA, NO.2 DME 4-87 3127-503 3242 REF: AMM 34-50-02	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F1 2	

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
348114 34.700	ANTENNA, NO.2 LRN 42804-000 100-00 SN-UNKNOWN REF: AMM 34-60-04	MOS HRS/MSC AFL								11-FEB-1982		
346216 34.550	ANTENNA, NO.2 MARKER BEACON PN SN-UNKNOWN REF: AMM 34-50-01	MOS HRS/MSC AFL								11-FEB-1982	F5	
346576 34.600	ANTENNA, NO.2 VOR DMN-4-15-3A 10993 REF: NO REF	MOS HRS/MSC AFL								11-FEB-1982	F3	
345626 34.340	ANTENNA, RADIO ALTIMETER RECEIVER 522-4140-001 509 REF: AMM 34-10-04	MOS HRS/MSC AFL								11-FEB-1982	F1	
345621 34.340	ANTENNA, RADIO ALTIMETER TRANSMIT 622-4550-001 459 REF: AMM 34-10-04	MOS HRS/MSC AFL								11-FEB-1982	F1	
345831 34.520	ANTENNA, WEATHER RADAR 622-2504-001 270 REF: AMM WCF 34.520	MOS HRS/MSC AFL							04/19/1993	19-FEB-1993 5222 3870	F2	
344611 34.370	BATTERY, EMERGENCY GYRO POWER SUPPLY 501-1075-05PS823A/T 1186 REF: AMM 34-20-09	MOS HRS/MSC AFL								06-APR-1998 6346 4787	F5 1	
344621 34.370	DEEP CYCLE POWER SUPPLY GNS-500 NAV SYSTEM REF: AMM WCF 34.370	MOS HRS/MSC AFL								06-APR-1998 6346 4787	F5	
+ 344616 34.370	INSPECT EMERGENCY POWER SUPPLY BATTERY/STAND-BY ATTITUDE GYRO REF: AMM NO REF	MOS HRS/MSC AFL		3 200						06-NOV-2001 7774 5641	06-FEB-2002 7974	F5
347626 34.150	BOX, DME DUAL CONTROL PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL								11-FEB-1982	F2 1	
347641 34.580	BOX, HORIZONTAL SITUATION INDICATOR CONTROL 622-4569-001 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL								11-FEB-1982	F4	



Aircraft Model - 1124 WESTWIND
 Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
 A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
346551 34.590	BOX, NO.1 VOR CONTROL 622-2899-012 SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL	O/C	0						11-FEB-1982	F3	
346581 34.590	BOX, NO.2 VOR CONTROL DMN-4-15-3/D SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL	O/C	0						11-FEB-1982	F3	
342601 34.100	COMPASS, STAND-BY MAGNETIC 2-883023-501 1A234 REF: NO REF	MOS HRSMSC AFL	O/C	0						11-FEB-1982	F3	
342611 34.100	SWING CHECK REF: CMM	MOS HRSMSC AFL	O/C							11-FEB-1982	F3	
343113 34.440	COMPENSATOR, NO.1 656767 81082033 REF: NO REF	MOS HRSMSC AFL	O/C	0 0						11-FEB-1982		
343158 34.440	COMPENSATOR, NO.2 656767 81092117 REF: NO REF	MOS HRSMSC AFL	O/C	0 0						11-FEB-1982		
344131 34.220	COMPUTER, FLIGHT COPILOT 622-5224-005 SN-UNKNOWN REF: AMM 4-20-04/21-04	MOS HRSMSC AFL	O/C	0						11-FEB-1982	F2	
343631 34.220	COMPUTER, FLIGHT PILOT 622-5224-004 5128 REF: AMM 4-20-04/21-04	MOS HRSMSC AFL	O/C	0						11-FEB-1982	F2 1	
340201 34.460	COMPUTER, NAVIGATION 622-5107-001 SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL	O/C	0 0						11-FEB-1982	F3	
343671 34.480	COMPUTER, NO.1 AIR DATA 622-5465-214 1080 REF: AMM 22-20-00	MOS HRSMSC AFL	O/C							26-MAR-1996	F3	
+ 343672 34.480	CALIBRATE FAR 91.411 REF: See Workcard	MOS HRSMSC AFL	24							18-JAN-2001 7494 5466	MANDATORY F3 18-JAN-2003	

? - Insufficient Information
 + Task exists in FAA Manual
 3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
341604 34.410	COMPUTER, SAT TAS 630-30980-135 1589 REF: NO REF	MOS HRS/MSC AFL								11-FEB-1982	F3	
346616 34.260	CONTROL, NO.1 ADF 622-4526-003 10601 REF: NO REF	MOS HRS/MSC AFL	O/C							11-FEB-1982	F3	
346641 34.260	CONTROL, NO.2 ADF PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C							11-FEB-1982	F3	
346251 34.470	CONTROLLER, NO.1 NAVIGATION 622-4524-079 7898 REF: NO REF	MOS HRS/MSC AFL	O/C							14-JAN-1992 5012 3648	F3	
346261 34.470	CONTROLLER, NO.2 NAVIGATION 622-4524-079 7863 REF: NO REF	MOS HRS/MSC AFL	O/C							07/15/1992 15-JAN-1992 5012 3648	F3	
346141 34.540	CONTROLLER, TRANSPONDER 622-4527-011 6475 REF: NO REF	MOS HRS/MSC AFL	O/C							11-FEB-1982	F4	
346306 34.460	CONVERTER, NAV RECEIVER/VHF POWER 622-2093-001 17233 REF: NO REF	MOS HRS/MSC AFL	O/C							11-FEB-1982	F3	
347201 34.650	CONVERTER, NO.1 DME SYNCHRO 622-1920-001 SN-UNKNOWN REF: AMM 34-50-02	MOS HRS/MSC AFL	O/C							11-FEB-1982	F3	
347211 34.650	CONVERTER, NO.2 DME SYNCHRO 622-1920-001 SN-UNKNOWN REF: AMM 34-50-02	MOS HRS/MSC AFL	O/C							11-FEB-1982	F3	
341096 34.420	CONVERTER, RADIO ALTIMETER 995-29400-112 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C							11-FEB-1982	F3	
343641 34.230	COUPLER, NO.1 FLIGHT DIRECTOR MODE 161E-2A SN-UNKNOWN REF: AMM 22-03-06	MOS HRS/MSC AFL	O/C							11-FEB-1982	F2	

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
348146 34.740	COUPLER, NO.1 LRN 42807-001 100-001 1585 REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982		
344141 34.230	COUPLER, NO.2 FLIGHT DIRECTOR MODE 161E-2A SN-UNKNOWN REF: AMM 22-03-06	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F2	
348151 34.740	COUPLER, NO.2 LRN 42807-001 100-001 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982		
345833 34.530	DISH, WEATHER RADAR FLAT ANT-318 270 REF: AMM 34-40-01	MOS HRS/MSC AFL	O/C	5222 3870				04/19/1993		19-FEB-1993 5222 3870	F2	
348116 34.670	DISPLAY, NO.1 LRN CONTROL 622-5493-001 040 REF: AMM 34-60-04	MOS HRS/MSC AFL	O/C	0						11-FEB-1982		
348121 34.670	DISPLAY, NO.2 LRN CONTROL 622-5493-001 SN-UNKNOWN REF: AMM 34-60-04	MOS HRS/MSC AFL	O/C	0						11-FEB-1982		
345631 34.300	GENERATOR, TONE (ALERTER) 540-25100-004 SN-UNKNOWN REF: AMM 34-10-03	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3	
343101 34.110	GYRO, NO.1 DIRECTIONAL 622-4176-004 871 REF: AMM 34-20-08	MOS HRS/MSC AFL	O/C		0			04/02/1992		02-OCT-1991 4931 3454	F4	
343106 34.110	BENCH CHECK REF: CMM	MOS HRS/MSC AFL	O/C							11-FEB-1982	F4	
343651 34.200	GYRO, NO.1 VERTICAL 792-6694-001 6381 REF: AMM WCF 34.200	MOS HRS/MSC AFL	O/C	0						06-JAN-1986 2808 1739	F3 2	
343146 34.110	GYRO, NO.2 DIRECTIONAL 2587193-43 81095980 REF: AMM 34-20-08	MOS HRS/MSC AFL	O/C	0						24-SEP-1987 3737 2345	F4	

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
343151 34.110	BENCH CHECK	MOS HRSMSC AFL								11-FEB-1982	F4	
	REF: CMM											
344151 34.200	GYRO, NO.2 VERTICAL 792-6694-001	MOS HRSMSC AFL					0			11-FEB-1982	F3	
	SN-UNKNOWN REF: AMM WCF 34.200											
347611 34.140	INDICATOR, DME COPILOT PN	MOS HRSMSC AFL					0			11-FEB-1982	F3	
	SN-UNKNOWN REF: NO REF											
347111 34.140	INDICATOR, DME PILOT PN	MOS HRSMSC AFL					0			11-FEB-1982	F3	
	SN-UNKNOWN REF: NO REF											
344101 34.280	INDICATOR, FLIGHT DIRECTOR COPILOT 622-4808-004	MOS HRSMSC AFL					0			11-FEB-1982	F3	
	SN-UNKNOWN REF: AMM 4-20-01/21-02											
343601 34.280	INDICATOR, FLIGHT DIRECTOR PILOT 622-4808-004	MOS HRSMSC AFL					0			11-FEB-1982	F3	
	823 REF: AMM 4-20-01/21-02											
341601 34.080	INDICATOR, LEFT MACH/AIRSPEED 622-4382-013	MOS HRSMSC AFL					0			07-APR-1987 3676 2288	F3	
	1302 REF: NO REF											
341606 34.080	CALIBRATE	MOS HRSMSC AFL								10-APR-1990 4560 3132	F3	
	REF: CMM											
340111 34.040	LEAKCHECK LEFT PITOT SYSTEM	MOS HRSMSC AFL								26-MAR-1996	F1	
	ASSOCIATED REF: AMM 34-10-01											
+ 340146 34.050	LEAKCHECK LEFT STATIC SYSTEM	MOS HRSMSC AFL	24							18-JAN-2001 7494 5466	MANDATORY F1 18-JAN-2003	
	ASSOCIATED REF: AMM 34-10-01											
342090 34.380	INDICATOR, LEFT VERTICAL NAV/SPEED 622-4782-003/VNI-80	MOS HRSMSC AFL					0			22-OCT-1982 482	F3	
	SN-UNKNOWN REF: NO REF											

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----	INSTALLATION	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
					TSN	TSO	TSR	TSI	ADJ	
342101		INDICATOR, LEFT VERTICAL SPEED								
	34.090	4883748-1	MOS							F3
		640	HRS/MSC	O/C	0					\$486.
		REF: AMM 34-10-03	AFL							11-FEB-1982
342106		BENCH CHECK								F3
	34.090		MOS							11-FEB-1982
			HRS/MSC	O/C						
		REF: See Workcard	AFL							
+ 340146		LEAK CHECK LEFT STATIC SYSTEM								MANDATORY F1
	34.050		MOS	24						18-JAN-2001
	ASSOCIATED		HRS/MSC							18-JAN-2003
		REF: AMM 34-10-01	AFL							7494
										5466
342801		INDICATOR, NO.1 GYRO ATTITUDE								F3
	34.430	4020531-170	MOS			0				25-MAR-1991
		80110830	HRS/MSC	O/C		0				4830
		REF: NO REF	AFL			0				3441
347651		INDICATOR, NO.1 HORIZONTAL SITUATION								F3
	34.560	622-4176-004	MOS							10-MAR-1987
		871	HRS/MSC	O/C	0					3623
		REF: AMM 4-20-02/21-02	AFL		0					2255
342811		INDICATOR, NO.2 GYRO ATTITUDE								F3
	34.430	4020531-170	MOS							19-MAR-1991
		6020225	HRS/MSC	O/C						4827
		REF: NO REF	AFL							3439
347655		INDICATOR, NO.2 HORIZONTAL SITUATION								F3
	34.560	622-4176-004	MOS							11-FEB-1982
		1854	HRS/MSC	O/C	0					
		REF: AMM 4-20-02/21-02	AFL							
340601		INDICATOR, OUTSIDE AIR TEMPERATURE								F3
	34.380	4883753-3	MOS							14-APR-1984
		64128-13	HRS/MSC	O/C	0					1645
		REF: NO REF	AFL							
345611		INDICATOR, RADIO ALTIMETER								F3
	34.250	521-29007-203	MOS							11-FEB-1982
		SN-UNKNOWN	HRS/MSC	O/C	0					
		REF: NO REF	AFL							
343166		INDICATOR, RADIO MAGNETIC COPILOT								F3
	34.160	622-2506-002	MOS							14-DEC-1986
		1546	HRS/MSC	O/C	0					3484
		REF: AMM 34-50-05	AFL							2157
343121		INDICATOR, RADIO MAGNETIC PILOT								F3
	34.160	622-2506-002	MOS							05-NOV-1986
		1213	HRS/MSC	O/C	0					3385
		REF: AMM 34-50-05	AFL							2098

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
341056 34.400	INDICATOR, RATE OF CLIMB COPILOT 229-0324-010 SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL			0 0				11-FEB-1982	F3	
341046 34.400	INDICATOR, RATE OF CLIMB PILOT 622-7689-003 166 REF: NO REF	MOS HRSMSC AFL			0			31-MAY-1993 5278 3928		F3	
341611 34.080	INDICATOR, RIGHT MACH/AIRSPEED 883615-513 149 REF: NO REF	MOS HRSMSC AFL			0			11-FEB-1982		F3	
341616 34.080	CALIBRATE REF: CMM VENDOR	MOS HRSMSC AFL						11-FEB-1982		F3	
340116 34.040 ASSOCIATED	LEAK CHECK RIGHT PITOT SYSTEM REF: AMM 34-10-01	MOS HRSMSC AFL						11-FEB-1982		F1	
+ 340151 34.050 ASSOCIATED	LEAK CHECK RIGHT STATIC SYSTEM REF: AMM 34-10-01	MOS HRSMSC AFL	24					18-JAN-2001 7494 5466	MANDATORY 18-JAN-2003	F1	
342111 34.090	INDICATOR, RIGHT VERTICAL SPEED RCS-60-IL-10 MD12158 REF: AMM 34-10-03	MOS HRSMSC AFL			0			11-FEB-1982		F3 \$486.	
342116 34.090	BENCH CHECK REF: See Workcard	MOS HRSMSC AFL						11-FEB-1982		F3	
+ 340151 34.050 ASSOCIATED	LEAK CHECK RIGHT STATIC SYSTEM REF: AMM 34-10-01	MOS HRSMSC AFL	24					18-JAN-2001 7494 5466	MANDATORY 18-JAN-2003	F1	
341605 34.410	INDICATOR, SAT TAS 622-2294-002 SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL			0 0			11-FEB-1982		F3	
344601 34.290	INDICATOR, STAND-BY HORIZON 501-1105-03 6010212 REF: AMM 34-20-09	MOS HRSMSC AFL			0			18-NOV-1984 2085 1284		F3	

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
345801 34.500	INDICATOR, WEATHER RADAR 622-4331-001 176 REF: AMM WCF 34.500	MOS HRS/MSC AFL	O/C		0				09/18/1993 18-MAR-1993 5231 3880	F3	
347101 34.270	INTERROGATOR, NO.1 DME 622-1233-001 13710 REF: AMM 34-50-02	MOS HRS/MSC AFL	O/C		0				11-FEB-1982	F2	
347601 34.270	INTERROGATOR, NO.2 DME 622-1233-001 15123 REF: AMM 34-50-02	MOS HRS/MSC AFL	O/C		0				11-FEB-1982	F2	
343663 34.190	PANEL, NO.1 FLIGHT GUIDANCE 622-2313-029 2661 REF: AMM 34-21-03	MOS HRS/MSC AFL	O/C		0 0				11-FEB-1982	F3	
343665 34.190	PANEL, NO.2 FLIGHT GUIDANCE 622-2265-030 SN-UNKNOWN REF: AMM 34-21-03	MOS HRS/MSC AFL	O/C		0 0				11-FEB-1982	F3	
345811 34.540	PANEL, WEATHER RADAR CONTROL DCP-320 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C		0 0				11-FEB-1982	F3	
340126 34.020	PORT, LEFT HEATED STATIC 3-883053-501 SN-UNKNOWN REF: AMM 34-10-01	MOS HRS/MSC AFL	O/C		0				11-FEB-1982	F1	
340121 34.060 ASSOCIATED	DRAIN PITOT/STATIC SYSTEM PKG 1, 2, 3 REF: AMM 34-10-00	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594	F2 1.5	
+ 340146 34.050 ASSOCIATED	LEAK CHECK LEFT STATIC SYSTEM REF: AMM 34-10-01	MOS HRS/MSC AFL	24						18-JAN-2001 7494 5466	MANDATORY F1 18-JAN-2003	
340131 34.030	PORT, LEFT UNHEATED STATIC 4-883050 SN-UNKNOWN REF: AMM 34-10-01	MOS HRS/MSC AFL	O/C		0				11-FEB-1982	F1	
340121 34.060 ASSOCIATED	DRAIN PITOT/STATIC SYSTEM PKG 1, 2, 3 REF: AMM 34-10-00	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594	F2 1.5	

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
+ 340 146	LEAK CHECK LEFT STATIC SYSTEM										
34.050		MOS	24					18-JAN-2001	MANDATORY	F1	
	ASSOCIATED	HRS/MSC						7494	18-JAN-2003		
	REF: AMM 34-10-01	AFL						5466			
340 136	PORT, RIGHT HEATED STATIC									F1	
34.020	3-883053-502	MOS						11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C	0							
	REF: AMM 34-10-01	AFL									
340 121	DRAIN PITOT/STATIC SYSTEM									F2	
34.060	PKG 1, 2, 3	MOS						26-JUN-2001			
	ASSOCIATED	HRS/MSC	200					7687		1.5	
	REF: AMM 34-10-00	AFL						5594			
+ 340 151	LEAK CHECK RIGHT STATIC SYSTEM									MANDATORY F1	
34.050		MOS	24					18-JAN-2001	18-JAN-2003		
	ASSOCIATED	HRS/MSC						7494			
	REF: AMM 34-10-01	AFL						5466			
340 141	PORT, RIGHT UNHEATED STATIC									F1	
34.030	4-883050	MOS						11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C	0							
	REF: AMM 34-10-01	AFL									
340 121	DRAIN PITOT/STATIC SYSTEM									F2	
34.060	PKG 1, 2, 3	MOS						26-JUN-2001			
	ASSOCIATED	HRS/MSC	200					7687		1.5	
	REF: AMM 34-10-00	AFL						5594			
+ 340 151	LEAK CHECK RIGHT STATIC SYSTEM									MANDATORY F1	
34.050		MOS	24					18-JAN-2001	18-JAN-2003		
	ASSOCIATED	HRS/MSC						7494			
	REF: AMM 34-10-01	AFL						5466			
340 606	PROBE, OUTSIDE AIR TEMPERATURE									F1	
34.380	MS28038-1	MOS						11-FEB-1982			
	9223	HRS/MSC	O/C	0							
	REF: NO REF	AFL									
347 659	PROGRAMMER, RNS										
34.740	622-5110-001	MOS						11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C	0							
	REF: NO REF	AFL						0			
346 601	RECEIVER, NO.1 ADF									F4	
34.130	622-2362-001	MOS						11-FEB-1982			
	8945	HRS/MSC	O/C	0						1	
	REF: AMM 34-50-03/04	AFL									
346 301	RECEIVER, NO.1 VHF NAVIGATION									F3	
34.450	622-0876-001	MOS						11-FEB-1982			
	16803	HRS/MSC	O/C	0							
	REF: AMM 34-50-01	AFL						0			

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
346536 34.580	RECEIVER, NO.1 VOR PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3	
346626 34.130	RECEIVER, NO.2 ADF 622-2362-001 8946 REF: AMM 34-50-03/04	MOS HRS/MSC AFL	O/C	0						06-APR-1985 2317 1423	F4	
346311 34.450	RECEIVER, NO.2 VHF NAVIGATION 622-0876-001 SN-UNKNOWN REF: AMM 34-50-01	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3	
346566 34.600	RECEIVER, NO.2 VOR PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3	
345608 34.420	RECEIVER, RADIO ALTIMETER 622-3201-001 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3	
346201 34.540	RECEIVER/TRANSMITTER, MARKER BEACON PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3	
345601 34.240	RECEIVER/TRANSMITTER, RADIO ALTIMETER 622-3201-001 3652 REF: AMM 34-10-04	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F2	
345821 34.510	RECEIVER/TRANSMITTER, WEATHER RADAR 622-4022-001 2126 REF: AMM WCF 34.510	MOS HRS/MSC AFL	O/C							12-APR-1995 5613 4281	F3	
344161 34.210	SELECTOR, MODE COPILOT 614E-23R SN-UNKNOWN REF: AMM 34-20-03	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3	
343661 34.210	SELECTOR, MODE PILOT 614E-20R SN-UNKNOWN REF: AMM 34-20-03	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3 1	
343677 34.490	SELECTOR, NO.1 REMOTE 622-4178-003 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3	

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
344177 34.490	SELECTOR, NO.2 REMOTE 622-4178-003	MOS								11-FEB-1982		
	SN-UNKNOWN REF: NO REF	HRS/MSC AFL	O/C	0								
344121 34.180	SENSOR, RATE-OF-TURN COPILOT 622-0181-001	MOS								11-FEB-1982	F3	
	SN-UNKNOWN REF: AMM WCF 34.180	HRS/MSC AFL	O/C	0								
343621 34.180	SENSOR, RATE-OF-TURN PILOT 772-5140-001	MOS								05-OCT-1983	F3	
	3984 REF: AMM WCF 34.180	HRS/MSC AFL	O/C	0						1300 794		
346101 34.320	TRANSPONDER, NO.1 ATC 622-1270-001	MOS							06/11/1996	11-DEC-1995	F3	
	9608 REF: AMM 34-50-06	HRS/MSC AFL	O/C							5726 4410	1	
346106 34.320	BENCH CHECK	MOS								25-SEP-1991	F3	
	REF: See Workcard	HRS/MSC AFL	O/C									
+ 346111 34.320	TEST FAR 91.413	MOS	24							18-JAN-2001	MANDATORY 18-JAN-2003	F3
	REF: CMM FAR 91.413	HRS/MSC AFL								7494 5466		
346116 34.320	TRANSPONDER, NO.2 ATC 622-1270-001	MOS								11-FEB-1982	F3	
	13112 REF: AMM 34-50-06	HRS/MSC AFL	O/C	0							3	
346121 34.320	BENCH CHECK	MOS								25-SEP-1991	F3	
	REF: CMM VENDOR MM	HRS/MSC AFL	O/C								4	
+ 346126 34.320	TEST FAR 91.413	MOS	24							18-JAN-2001	MANDATORY 18-JAN-2003	F3
	REF: CMM FAR 91.413	HRS/MSC AFL								7494 5466		
340101 34.010	TUBE, LEFT PITOT 4883049-1	MOS								11-FEB-1982	F1	
	59912 REF: AMM 34-10-01	HRS/MSC AFL	O/C	0								
340121 34.060	DRAIN PITOT/STATIC SYSTEM PKG 1, 2, 3	MOS								26-JUN-2001	F2	
ASSOCIATED	REF: AMM 34-10-00	HRS/MSC AFL	200							7687 5594	1.5	

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
340111	LEAK CHECK LEFT PITOT SYSTEM										F1	
34.040		MOS							26-MAR-1996			
	ASSOCIATED	HRS/MSC	O/C									
	REF: AMM 34-10-01	AFL										
340106	TUBE, RIGHT PITOT										F1	
34.010	4883049-1	MOS							11-FEB-1982			
	58348	HRS/MSC	O/C	0								
	REF: AMM 34-10-01	AFL										
340121	DRAIN PITOT/STATIC SYSTEM										F2	
34.060	PKG 1, 2, 3	MOS							26-JUN-2001			
	ASSOCIATED	HRS/MSC	200						7687		1.5	
	REF: AMM 34-10-00	AFL							5594			
340116	LEAK CHECK RIGHT PITOT SYSTEM										F1	
34.040		MOS							11-FEB-1982			
	ASSOCIATED	HRS/MSC	O/C									
	REF: AMM 34-10-01	AFL										
346648	UNIT, CONTROL DISPLAY PROCESS										F3	
34.460	622-2899-016	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C	0								
	REF: NO REF	AFL		0								
348165	UNIT, FMS AUXILIARY EQUIPMENT										F3	
34.770	622-5615-001/AEU-90	MOS						10/27/1989	27-JUL-1989			
	92	HRS/MSC	O/C						4311			
	REF: AMM 34-60-03	AFL							2856			
348160	UNIT, FMS COMPUTER RECEIVER										F3	
34.760	622-5614-020/CRU-90	MOS							12-FEB-1990			
	52	HRS/MSC	O/C						4504			
	REF: AMM 34-60-03	AFL							3073			
348170	UNIT, FMS CONTROL DISPLAY										F3	
34.790	622-5611-001/CDU-90	MOS							11-FEB-1982			
	040	HRS/MSC	O/C	0								
	REF: AMM 34-60-03	AFL										
348175	UNIT, FMS DATA ENTRY										F3	
34.780	622-5613-001/DEU-90	MOS							16-AUG-1984			
	183	HRS/MSC	O/C	0					1890			
	REF: NO REF	AFL										
348155	UNIT, FMS RADIO TUNING										F3	
34.750	622-5612-007/RTU-90	MOS							10-MAR-1987			
	50	HRS/MSC	O/C	0					3623			
	REF: AMM 34-60-03	AFL							2255			
348136	UNIT, NO. 1 LRN EQUIPMENT										F3	
34.690	622-5494-001	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C	0								
	REF: AMM 34-60-04	AFL		0								

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
348126 34.680	UNIT, NO.1 LRN RECEIVER COMP 622-5492-001 SN-UNKNOWN REF: AMM 34-60-04	MOS HRS/MSC AFL		O/C	0				11-FEB-1982		
348141 34.690	UNIT, NO.2 LRN EQUIPMENT 622-5494-001 SN-UNKNOWN REF: AMM 34-60-04	MOS HRS/MSC AFL		O/C	0				11-FEB-1982		
348131 34.720	UNIT, NO.2 LRN RECEIVER COMP 622-5494-001 SN-UNKNOWN REF: AMM 34-60-04	MOS HRS/MSC AFL		O/C	0				11-FEB-1982		
346651 34.610	UNIT, VLF CONTROL DISPLAY 10060-6 2579 REF: AMM 34-10-06	MOS HRS/MSC AFL		O/C	0			24-SEP-1987 3737 2345		F3	
346671 34.630	UNIT, VLF OPTIONAL EQUIPMENT 10600-2-210 2695 REF: AMM 34-60-02	MOS HRS/MSC AFL		O/C	0			05-SEP-1989 4355 2904		F3	
346661 34.620	UNIT, VLF RECEIVER COMPUTER 10050-4-4A-3140 1937 REF: AMM 34-60-02	MOS HRS/MSC AFL		O/C	0			05-SEP-1989 4355 2904		F5	
343111 34.120	VALVE, NO.1 FLUX 2594484 81096488 REF: AMM 34-20-01	MOS HRS/MSC AFL		O/C	0			11-FEB-1982		W1	
343156 34.120	VALVE, NO.2 FLUX 2594484 81096489 REF: AMM 34-20-08	MOS HRS/MSC AFL		O/C	0			11-FEB-1982		W2	
CHAPTER 35	OXYGEN										
350101 35.010	CYLINDER, OXYGEN 6350A25-EE-Z 49928W REF: AMM 35-00-00	MOS HRS/MSC AFL		288	0			04-FEB-1982	LIFE LIMIT 04-FEB-2006	F2	
350106 35.010	HYDROSTATIC TEST REF: AMM 35-00-00	MOS HRS/MSC AFL		36 3000				26-JUL-2000 7325 5360	26-JUL-2003 10325	F2	
350141 35.040	GAUGE, OXYGEN PRESSURE PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL		O/C	0			11-FEB-1982		F3	

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
350126 35.040	INDICATOR, OXYGEN DISCHARGE 118082 SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL	O/C	0						11-FEB-1982	F1	
350181 35.080	MASK, PASSENGER OXYGEN L1 PN SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL	O/C	0						11-FEB-1982	F4	
350191 35.080	MASK, PASSENGER OXYGEN L2 PN SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL	O/C	0						11-FEB-1982	F4	
350201 35.090	MASK, PASSENGER OXYGEN R1 PN SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL	O/C	0						11-FEB-1982	F4	
350211 35.090	MASK, PASSENGER OXYGEN R2 PN SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL	O/C	0						11-FEB-1982	F4	
350221 35.090	MASK, PASSENGER OXYGEN R3 PN SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL	O/C	0						11-FEB-1982	F4	
350246 35.120	OUTLET, THERAPEUTIC OXYGEN 23599-11 SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL	O/C	0						11-FEB-1982	F4	
350158 35.120	REGULATOR, MASK COPILOT MC-1013-02 8161 REF: NO REF	MOS HRSMSC AFL	72	0					09-NOV-1996 5951 4589	OVERHAUL 09-NOV-2002	F3	
+ 350169U 35.070	CHECK REF: AMM 35-00-00	MOS HRSMSC AFL	12 600						26-JUN-2001 7687 5594	26-JUN-2002 8287	F3	
350148 35.120	REGULATOR, MASK PILOT MC-1013-02 7750 REF: NO REF	MOS HRSMSC AFL	72	0					09-NOV-1996 5951 4589	OVERHAUL 09-NOV-2002	F3	
+ 350166U 35.070	CHECK REF: AMM 35-00-00	MOS HRSMSC AFL	12 600						26-JUN-2001 7687 5594	26-JUN-2002 8287	F3	

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
350241 35.110	REGULATOR, OXYGEN DEMAND CONTROL PANEL (PURITAN) COPILOT 101202-11 SN-UNKNOWN REF: AMM 35-10-00	MOS HRS/MSC AFL		O/C	0				11-FEB-1982	F3	
350236 35.110	REGULATOR, OXYGEN DEMAND CONTROL PANEL (PURITAN) PILOT 101202-11 SN-UNKNOWN REF: AMM 35-10-00	MOS HRS/MSC AFL		O/C	0				11-FEB-1982	F3	
350116 35.030	REGULATOR, PRESSURE REDUCER 112031-06 670A REF: AMM 35-00-00	MOS HRS/MSC AFL		O/C	0				11-FEB-1982	F3 \$970. 8	
350136 35.060	SWITCH, ALTITUDE PRESSURE 101800 8024154 REF: AMM 35-00-00	MOS HRS/MSC AFL		O/C	0				11-FEB-1982	F3	
350231 35.100	SYSTEM, PASSENGER OXYGEN SUPPLY 5753004-400 189 REF: AMM 35-20-00	MOS HRS/MSC AFL		O/C	0				11-FEB-1982	F3 \$950. 6	
350163 35.140	INSPECT/SERVICE OXYGEN SYSTEM 189 REF: AMM 35-00-00	MOS HRS/MSC AFL		O/C					13-NOV-1995 5718 4397	F3	
+ 350243 35.130	TEST PKG 3 REF: AMM 35-00-00	MOS HRS/MSC AFL		800					26-JUL-2000 7325 5360	F4	
350103 35.150	VALVE, OXYGEN CYLINDER 6350-A25-DDC SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL		O/C					11-DEC-1984 2119 1302	F2	
350111 35.020	VALVE, OXYGEN FILLER 26875-48 SN-UNKNOWN REF: AMM 35-00-00	MOS HRS/MSC AFL		O/C	0				11-FEB-1982	F1	
350131 35.050	VALVE, OXYGEN SHUTOFF 110115 SN-UNKNOWN REF: AMM 35-00-00	MOS HRS/MSC AFL		O/C	0				11-FEB-1982	F2	
350108 35.150	VALVE, TOGGLE 170001 8894 REF: NO REF	MOS HRS/MSC AFL		O/C	0				11-FEB-1982	F2	
CHAPTER 49 AIRBORNE AUXILIARY POWER											

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
49APU1	APU, PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	E/C								
CHAPTER 52	DOORS										
520181 52.020	LUBRICATE CABIN ENTRANCE STEP	MOS HRS/MSC AFL	O/C						11-FEB-1982	F4	
	REF: AMM 12-20-00	AFL									
520161 52.040	DOOR, COMPARTMENT CMA21212-002 SN-UNKNOWN REF: AMM 52-30-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5	
520171 52.050	DOOR, COMPARTMENT REAR BAGGAGE CMA22211-001 SN-UNKNOWN REF: AMM 52-30-01	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5	
520101 52.010	DOOR, ENTRANCE CABIN 333045-505 SN-UNKNOWN REF: AMM 52-10-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F4	
+ 520106 52.010	INSPECT/LUBRICATE PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594	F4	
+ 520116 52.010	OPERATIONAL CHECK PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594	F4	
520136 52.030	HATCH, EMERGENCY EXIT LEFT 5-333031-501 SN-UNKNOWN REF: AMM 52-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F4	
+ 520141 52.030	INSPECT/LUBRICATE SEAL PKG 3	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360	F4	
520146 52.030	HATCH, EMERGENCY EXIT RIGHT 5-333031-501 SN-UNKNOWN REF: AMM 52-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F4	
+ 520151 52.030	INSPECT/LUBRICATE SEAL PKG 3	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360	F4	
	REF: See Workcard	AFL									

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
520166 52.060	SEAL, COMPARTMENT DOOR CMA21212-057 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5	
520173 52.060	SEAL, COMPARTMENT DOOR REAR BAGGAGE CMA22211-006 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5	
520126 52.010	SEAL, ENTRANCE DOOR CABIN 333045-181 SN-UNKNOWN REF: AMM 52-10-00	MOS HRS/MSC AFL	O/C	0					01-DEC-1995 5727 4410	F4	
520176 52.020	STEP, ENTRANCE CABIN 5-123580-1 SN-UNKNOWN REF: AMM 52-60-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F4	
CHAPTER 53 FUSELAGE											
+ 530121 53.0202	INSPECT NOSE COMPARTMENT (B) PKG 2, 3 REF: AMM WCF 53.0302	MOS HRS/MSC AFL		400					26-JUN-2001 7687 5594	F2	
+ 530300 53.170	INSPECT AFT FUSELAGE STRUCTURE REF: AMM 5-40-02	MOS HRS/MSC AFL		4800					24-AUG-1993 5326 3975	MANDATORY F5 10126	
+ 530235 53.120	INSPECT AFT PRESSURE BULKHEAD AFT WEBS REF: AMM 5-40-01	MOS HRS/MSC AFL		15000						MANDATORY F5 15000	
+ 530230 53.110	INSPECT AFT PRESSURE BULKHEAD FORWARD WEBS REF: AMM 5-40-01	MOS HRS/MSC AFL		9600						MANDATORY F5 9600	
+ 530250 53.150	INSPECT AFT PRESSURE BULKHEAD J-BEAM SPLICE FROM CABIN SIDE REF: AMM 5-40-01	MOS HRS/MSC AFL		9600						MANDATORY F5 9600	
+ 530255 53.160	INSPECT AFT PRESSURE BULKHEAD J-BEAM SPLICE FROM FUEL COMPARTMENT REF: AMM 5-40-01	MOS HRS/MSC AFL		15000						MANDATORY F5 15000	
+ 530240 53.130	INSPECT AFT PRESSURE BULKHEAD PERIPHERAL SECTION FROM CABIN SIDE REF: AMM 5-40-01	MOS HRS/MSC AFL		9600						MANDATORY F5 9600	

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
+ 530245 53.140	INSPECT AFT PRESSURE BULKHEAD PERIPHERAL SECTION FROM FUEL COMPARTMENT	MOS HRS/MSC AFL	15000							MANDATORY	F5 15000
	REF: AMM 5-40-01	AFL									
+ 530176 53.060	INSPECT AUXILIARY FUEL TANK STRUCTURE	MOS HRS/MSC AFL	800						26-JUL-2000		F5 7325 5360
	REF: AMM 5-20-09	AFL									
+ 530146 53.0401	INSPECT CABIN (A)	MOS HRS/MSC AFL	200						26-JUN-2001		F4 7687 5594
	REF: AMM WCF 53.0401	AFL									
+ 530156 53.0402	INSPECT CABIN (C)	MOS HRS/MSC AFL	800						26-JUL-2000		F4 7325 5360
	REF: AMM WCF 53.0402	AFL									
+ 530131 53.0301	INSPECT COCKPIT (A)	MOS HRS/MSC AFL	200						26-JUN-2001		F3 7687 5594
	REF: AMM WCF 53.0301	AFL									
+ 530136 53.0302	INSPECT COCKPIT (B)	MOS HRS/MSC AFL	400						26-JUN-2001		F3 7687 5594
	REF: AMM WCF 53.0302	AFL									
+ 530141 53.0303	INSPECT COCKPIT (C)	MOS HRS/MSC AFL	800						26-JUL-2000		F3 7325 5360
	REF: AMM WCF 53.0303	AFL									
+ 530220 53.100	INSPECT ENTRY DOOR STOPS	MOS HRS/MSC AFL	5400						24-AUG-1993		F4 5326 3975 10726
	REF: AMM 5-40-01	AFL									
+ 530205 53.180	INSPECT FORWARD TO AFT MAIN FRAME	MOS HRS/MSC AFL	800						26-JUL-2000		F4 7325 5360 8125
	REF: AMM 5-40-01	AFL									
+ 530200 53.080	INSPECT FORWARD TO AFT PRESSURE BULKHEAD-FUSELAGE	MOS HRS/MSC AFL	800						26-JUL-2000		MANDATORY F4 7325 5360 8125
	REF: AMM 5-40-01	AFL									
+ 530101 53.010	INSPECT FUSELAGE (A)	MOS HRS/MSC AFL	200						26-JUN-2001		F1 7687 5594
	REF: AMM 5-20-02	AFL									

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
+ 530210 53.090	INSPECT FUSELAGE SKINS FLIGHT COMPARTMENT SIDE WINDOW	MOS HRS/MSC AFL	4800						24-AUG-1993 5326 3975	MANDATORY 10126	F4	
	REF: AMM 5-40-01											
+ 530116 53.0201	INSPECT NOSE COMPARTMENT (A) PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594		F2	
	REF: AMM WCF 53.0201											
+ 530161 53.0501	INSPECT REAR COMPARTMENT (A) PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594		F5	
	REF: AMM WCF 53.0501											
+ 530166 53.0502	INSPECT REAR COMPARTMENT (B) PKG 2, 3	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594		F5	
	REF: AMM WCF 53.0502											
531101 53.070	CONE, NOSE F10A-5-RD5-20000-7 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0					11-FEB-1982		F2	
	REF: NO REF			0								
CHAPTER 54	NACELLES/PYLONS											
+ 540200 54.020	INSPECT ENGINE SUPPORT INSTALLATION	MOS HRS/MSC AFL	4800						24-AUG-1993 5326 3975	MANDATORY 10126		
	REF: AMM 5-40-04											
+ 540101U 54.0101	INSPECT NO. 1 ENGINE NACELLE/PYLON (A) PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594		E1	
	REF: AMM WCF 54.0101											
+ 540106U 54.0102	INSPECT NO. 1 ENGINE NACELLE/PYLON (B) PKG 2, 3	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594		E1 3	
	REF: AMM WCF 54.0102											
+ 540111U 54.0103	INSPECT NO. 1 ENGINE NACELLE/PYLON (C) PKG 3	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360		E1	
	REF: AMM WCF 54.0103											
+ 540121U 54.0101	INSPECT NO. 2 ENGINE NACELLE/PYLON (A) PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594		E2	
	REF: AMM WCF 54.0101											
+ 540126U 54.0102	INSPECT NO. 2 ENGINE NACELLE/PYLON (B) PKG 2, 3	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594		E2 3	
	REF: AMM WCF 54.0102											

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----	INSTALLATION	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
					TSN	TSO	TSR	TSI	ADJ	
+ 540131U	54.0103	INSPECT NO. 2 ENGINE NACELLE/PYLON (C) PKG 3	MOS HRS/MSC AFL	800						E2
		REF: AMM WCF 54.0103								26-JUL-2000 7325 5360
CHAPTER 55 STABILIZERS										
+ 550101	55.0101	INSPECT EMPENNAGE (A) PKG 1, 2, 3	MOS HRS/MSC AFL	200						T1
		REF: AMM WCF 55.0101								26-JUN-2001 7687 5594
+ 550106	55.0102	INSPECT EMPENNAGE (B) PKG 2, 3	MOS HRS/MSC AFL	400						T1
		REF: AMM WCF 55.0102								26-JUN-2001 7687 5594
+ 550200	55.060	INSPECT EMPENNAGE (MAJOR)	MOS HRS/MSC AFL	4800						MANDATORY T1
		REF: AMM 5-40-03								24-AUG-1993 5326 3975 10126
550651	55.030	STABILIZER, HORIZONTAL 5453015-413-1 SN-UNKNOWN REF: AMM 55-10-00	MOS HRS/MSC AFL	O/C	0					T1
		REF: AMM 55-10-00								11-FEB-1982
550656	55.040	CHECK AFT SPAR SPLICE-HINGE FITTING OUTBOARD LUGS FOR CRACKS PKG 1, 2, 3	MOS HRS/MSC AFL	200						T1
		REF: AMM 55-10-00								26-JUN-2001 7687 5594
550658	55.050	CHECK ASSEMBLY RADIAL/AXIAL PLAY PKG 3	MOS HRS/MSC AFL	800						T1
		REF: See Workcard								26-JUL-2000 7325 5360
270214	27.195 ASSOCIATED	LUBRICATE AFT HINGE FITTING BEARINGS PKG 1, 2, 3	MOS HRS/MSC AFL	200						T1
		REF: NO REF								26-JUN-2001 7687 5594
270215	27.195 ASSOCIATED	LUBRICATE FORWARD SCISSOR ASSEMBLY PKG 1, 2, 3	MOS HRS/MSC AFL	200						T1
		REF: NO REF								26-JUN-2001 7687 5594
SB 1124-55-097	ASSOCIATED	STABILIZER SCISSR SERVICE BULLETIN	MOS HRS/MSC AFL	A/R						T1
		REF: See Workcard								
		Method of Compliance: OPEN								
550601	55.020	STABILIZER, VERTICAL 5413027-411 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	0					T1
		REF: See Workcard								11-FEB-1982

CHAPTER 56 WINDOWS

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
561601 56.075	WINDOW, EMERGENCY EXIT NO.L3 LEFT PN SN-UNKNOWN REF: AMM 56-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F4	
561606 56.075	WINDOW, EMERGENCY EXIT NO.R4 RIGHT PN SN-UNKNOWN REF: AMM 56-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F4	
560601 56.050	WINDOW, NO.L1 LEFT 5-343016-501 SN-UNKNOWN REF: AMM 56-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F4	
560606 56.060	WINDOW, NO.L2 LEFT 5-343016-501 SN-UNKNOWN REF: AMM 56-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F4	
560611 56.070	WINDOW, NO.L4 LEFT 5-343016-501 SN-UNKNOWN REF: AMM 56-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F4	
560616 56.080	WINDOW, NO.L5 LEFT 5-343016-501 SN-UNKNOWN REF: AMM 56-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F4	
561101 56.050	WINDOW, NO.R1 RIGHT 5-343016-501 SN-UNKNOWN REF: AMM 56-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F4	
561106 56.060	WINDOW, NO.R2 RIGHT 5-343016-501 SN-UNKNOWN REF: AMM 56-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F4	
561111 56.070	WINDOW, NO.R3 RIGHT 5-343016-501 SN-UNKNOWN REF: AMM 56-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F4	
561116 56.080	WINDOW, NO.R5 RIGHT 5-343016-501 SN-UNKNOWN REF: AMM 56-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F4	
561121 56.080	WINDOW, NO.R6 RIGHT 5-343016-501 SN-UNKNOWN REF: AMM 56-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F4	

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT----- TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
560121 56.040	WINDOW, OVERHEAD 5-343021-1 SN-UNKNOWN REF: AMM 56-10-02	MOS HRS/MSC AFL	O/C	0 0		11-FEB-1982		F3
560126 56.040	WINDOW, OVERHEAD 5-343021-2 SN-UNKNOWN REF: AMM 56-10-02	MOS HRS/MSC AFL	O/C	0 0		11-FEB-1982		F3
560116 56.030	WINDOW, SIDE COPILOT 5-343003-501 SN-UNKNOWN REF: AMM 56-10-04	MOS HRS/MSC AFL	O/C	0 0		11-FEB-1982		F3
+ 560118 56.030	INSPECT PKG 3 REF: See Workcard	MOS HRS/MSC AFL			800	26-JUL-2000 7325 5360		F3
560111 56.030	WINDOW, SIDE PILOT 5-343017-505 SN-UNKNOWN REF: AMM 56-10-03	MOS HRS/MSC AFL	O/C	0 0		11-FEB-1982		F3
+ 560112 56.030	INSPECT PKG 3 REF: AMM 56-10-03	MOS HRS/MSC AFL			800	26-JUL-2000 7325 5360		F3
560107 56.020	WINDSHIELD, INNER COPILOT 5343035 SN-UNKNOWN REF: AMM 56-10-01	MOS HRS/MSC AFL	O/C	0		11-FEB-1982		F3
560102 56.020	WINDSHIELD, INNER PILOT 5343035 SN-UNKNOWN REF: AMM 56-10-01	MOS HRS/MSC AFL	O/C	0		11-FEB-1982		F3
560106 56.010	WINDSHIELD, OUTER COPILOT PPG 343030-2 99064H0109 REF: AMM 56-10-01	MOS HRS/MSC AFL	O/C	0 0 0		26-AUG-2000 7352 5381		F3
560101 56.010	WINDSHIELD, OUTER PILOT 343030-1 98342H0422 REF: AMM 56-10-01	MOS HRS/MSC AFL	O/C	0 0 0		22-FEB-2000 7107 5232		F3
CHAPTER 57	WINGS							
+ 570220 57.050	INSPECT LEFT OUTER WING PANELS REF: AMM 5-40-05	MOS HRS/MSC AFL			4800	24-AUG-1993 5326 3975	MANDATORY 10126	W1

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND

Report Date **14-MAR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
+ 570101 57.0101	INSPECT LEFT WING (A) PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594	W1 1.5	
	REF: AMM WCF 57.0101										
+ 570104 57.0102	INSPECT LEFT WING (B) PKG 2, 3	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594	W1	
	REF: AMM WCF 57.0102										
+ 570200 57.040	INSPECT LEFT WING STRUCTURE	MOS HRS/MSC AFL	15000							MANDATORY W1 15000	
	REF: AMM 5-40-05										
+ 570120 57.020	INSPECT RIGHT AILERON BELL CRANK PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594	W2	
	REF: AMM 5-20-03										
+ 570221 57.050	INSPECT RIGHT OUTER WING PANELS	MOS HRS/MSC AFL	4800						24-AUG-1993 5326 3975	MANDATORY W2 10126	
	REF: AMM 5-40-05										
+ 570116 57.0101	INSPECT RIGHT WING (A) PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594	W2 1.5	
	REF: AMM WCF 57.0101										
+ 570119 57.0102	INSPECT RIGHT WING (B) PKG 2, 3	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594	W2	
	REF: AMM WCF 57.0102										
+ 570201 57.040	INSPECT RIGHT WING STRUCTURE	MOS HRS/MSC AFL	15000							MANDATORY W2 15000	
	REF: AMM 5-40-05										
570031 57.030	TANK TIP LEFT 5213003-405 SN-UNKNOWN REF: AMM 57-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	W1	
570041 57.030	TANK TIP RIGHT 5213003-406 SN-UNKNOWN REF: AMM 57-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	W2	
CHAPTER 71	POWER PLANT										
+ 710650U	- INSP #1 ENG INLET NACELLE PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594	E1	
	REF:										

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT----- TSN TSO TSR TSI ADJ	INSTALLATION	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
+ 713650U	INSP #2 ENG INLET NACELLE PKG 1, 2, 3	MOS						26-JUN-2001	E2
	REF:	HRS/MSC	200				7687		
		AFL					5594		
71EN1	ENGINE, NO. 1 3072500-2	MOS							
	P-77482	HRS/MSC	E/C						
	REF:	AFL							
71EN2	ENGINE, NO. 2 3072500-2	MOS							
	P77488	HRS/MSC	E/C						
	REF:	AFL							
CHAPTER 73 ENGINE FUEL AND CONTROL									
731101U	COMPUTER, FUEL CONT ENG #1 2101144-1	MOS						03-APR-1989	F5
	SN-UNKNOWN	HRS/MSC	O/C	3972			4215		\$4400.
	REF:	AFL		2456			2745		3
733601U	COMPUTER, FUEL CONT ENG #2 2101144-1	MOS						31-MAY-1989	F5
	51-2172	HRS/MSC	O/C	4215			4265		\$4400.
	REF:	AFL		2745			2793		3
732106U	INDICATOR, FUEL FLO ENG #1 6-883708-1	MOS						30-JUL-1986	F3
	SN-UNKNOWN	HRS/MSC	O/C	3209			3209		\$372.
	REF:	AFL		1976			1976		
734606U	INDICATOR, FUEL FLO ENG #2 6-883708-1	MOS						30-JUL-1986	F3
	SN-UNKNOWN	HRS/MSC	O/C	3017			3209		\$372.
	REF:	AFL		1772			1976		
CHAPTER 75 AIR									
750116	SENSOR, TEMPERATURE INLET 3070816-2	MOS						03-APR-1989	E1
75.030	SN-UNKNOWN	HRS/MSC	O/C	3972			4215		
	REF: See Workcard	AFL		2456			2745		
750616	SENSOR, TEMPERATURE INLET 3070816-2	MOS						31-MAY-1989	E2
75.030	15594	HRS/MSC	O/C	1592			4265		
	REF: See Workcard	AFL					2793		
CHAPTER 77 ENGINE INDICATING									
771606	INDICATOR, (N1) LOW-PRESSURE NO. 2 ENGINE 6-883619-1	MOS						11-FEB-1982	F3
77.020	4162	HRS/MSC	O/C	0					\$1100.
	REF: AMM 77-00-00	AFL							

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
770106 77.020	INDICATOR, (N1) LOW-PRESSURE NO. 1 ENGINE 6883619-1 SN-UNKNOWN REF: AMM 77-00-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3 \$1100.	
770606 77.040	INDICATOR, (N2) HIGH-PRESSURE NO. 1 ENGINE 6883620-1 SN-UNKNOWN REF: AMM 77-00-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3	
772106 77.040	INDICATOR, (N2) HIGH-PRESSURE NO. 2 ENGINE 6-883620-1 SN-UNKNOWN REF: AMM 77-00-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3	
771106 77.060	INDICATOR, ITT NO. 1 ENGINE 6883621-503 R0097 REF: AMM 77-00-00	MOS HRS/MSC AFL	O/C		0				31-MAY-1993 5278 3928	F3 \$507.	
772606 77.060	INDICATOR, ITT NO. 2 ENGINE 6883621-503 R0031R REF: AMM 77-00-00	MOS HRS/MSC AFL	O/C		0				31-MAY-1993 5278 3928	F3 \$507.	
CHAPTER 78	EXHAUST										
+ 780119 78.140	CHECK #1 THRUST REVERSER SECONDARY LATCH SOLENOID SWITCH PKG 3 REF: AMM 78-30-00	MOS HRS/MSC AFL		800					26-JUL-2000 7325 5360	E1	
+ 780120 78.140	CHECK #2 THRUST REVERSER SECONDARY LATCH SOLENOID SWITCH PKG 3 REF: AMM 78-30-00	MOS HRS/MSC AFL		800					26-JUL-2000 7325 5360	E2	
+ 780116 78.110	OPERATIONAL CHECK NO.1 THRUST REVERSER PKG 3 REF: AMM 78-30-00	MOS HRS/MSC AFL		800					26-JUL-2000 7325 5360	E1	
+ 780616 78.110	OPERATIONAL CHECK NO.2 THRUST REVERSER PKG 3 REF: AMM 78-30-00	MOS HRS/MSC AFL		800					26-JUL-2000 7325 5360	E2	
780156 78.040	ACCUMULATOR, THRUST REVERSER 4723565-1 SN-UNKNOWN REF: AMM 78-34-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5	
780146 78.020	ACTUATOR, THRUST REVERSER NO. 1 F10A-5-SCH203-1 0419 REF: AMM 78-34-00	MOS HRS/MSC AFL	O/C	0					02-JAN-1987 3504 2168	E1	

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
780646		ACTUATOR, THRUST REVERSER NO. 2							E2
	78.020	F10A-5-SCH203-1 SN-UNKNOWN REF: AMM 78-34-00	MOS HRS/MSC AFL	O/C	0		11-FEB-1982		
780161		BOTTLE, THRUST REVERSER GAS STORAGE						LIFE LIMIT	F5
	78.050	3753015-501 07511A1 REF: AMM 78-34-00	MOS HRS/MSC AFL	288	0		11-FEB-1982	11-FEB-2006	
+ 780163		HYDROSTATIC TEST							F5
	78.050		MOS HRS/MSC AFL	36			26-OCT-1999 6961 5135	26-OCT-2002	
		REF: See Workcard							
780131		CONTROL ASSEMBLY, THROTTLE RETARDER FEEDBACK NO. 1						LIFE LIMIT	E1
	78.090	F10A-5SCP203-1 SN-UNKNOWN REF: AMM 78-32-00	MOS HRS/MSC AFL	10000	0		11-FEB-1982	10000	
780136		CLEAN/LUBRICATE NO.1 THROTTLE RETARDER CABLE AND CASING							E1
	78.090		MOS HRS/MSC AFL	36			06-NOV-2001 7774 5641	06-NOV-2004	
		REF: AMM 12-20-00							
780631		CONTROL ASSEMBLY, THROTTLE RETARDER FEEDBACK NO. 2						LIFE LIMIT	E2
	78.090	F10A-5SCP203-2 SN-UNKNOWN REF: AMM 78-32-00	MOS HRS/MSC AFL	10000	0		11-FEB-1982	10000	
780636		CLEAN/LUBRICATE NO.2 THROTTLE RETARDER CABLE AND CASING							E2
	78.090		MOS HRS/MSC AFL	36			06-NOV-2001 7774 5641	06-NOV-2004	
		REF: AMM 78-32-00							
780171		RELEASE VALVE, THRUST REVERSER							F5
	78.070	3723581-1 SN-UNKNOWN REF: AMM 78-34-00	MOS HRS/MSC AFL	O/C	0		11-FEB-1982		
780158		SWITCH, THRUST REVERSER LOW-PRESSURE							F5
	78.080	4713533-1 SN-UNKNOWN REF: AMM 78-34-00	MOS HRS/MSC AFL	O/C	0		11-FEB-1982		
780141		THRUST REVERSER ASSEMBLY, NO. 1							E1
	78.010	F10A-5-B20202-1 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0		11-FEB-1982		
+ 780148		INSPECT						INSPECT	E1
	78.130		MOS HRS/MSC AFL	5000			20-AUG-1991 4906	9906	
		REF: See Workcard							

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
780143 78.100	LUBRICATE PKG 3	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360	E1	
	REF: AMM 12-20-00										
780641 78.011	THRUST REVERSER ASSEMBLY, NO. 2 F10A-5-B20202-2 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	E2	
+ 780648 78.130	INSPECT	MOS HRS/MSC AFL	5000						20-AUG-1991 4906 9906	INSPECT E2	
	REF: See Workcard										
780643 78.100	LUBRICATE PKG 3	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360	E2	
	REF: AMM 12-20-00										
780166 78.060	VALVE, RELIEF PN SN-UNKNOWN REF: AMM 78-34-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5	
780151 78.030	VALVE, THRUST REVERSER CONTROL NO. 1 723573 525 REF: AMM 78-34-00	MOS HRS/MSC AFL	O/C	0					08-APR-1987 3684 2293	F5 \$588. 2	
780651 78.030	VALVE, THRUST REVERSER CONTROL NO. 2 723573 SN-UNKNOWN REF: AMM 78-34-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5 \$588. 2	
CHAPTER 79	OIL										
791121U	IND, PRESS/TEMP ENG #1 6-883706-1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3 \$805.	
792621U	IND, PRESS/TEMP ENG #2 6-883706-1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3 \$805.	
790616U	VALVE, OIL TEMP ENG #1 157025-2 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	3972 2456					03-APR-1989 4215 2745	E1	
792116U	VALVE, OIL TEMP ENG #2 157025-2 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	4215					31-MAY-1989 4265 2793	E2	

Report Date **14-MAR-2002**

Engine Model - TFE731-3
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT----- TSN TSO TSR TSI ADJ	INSTALLATION	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
ENGINE NO. 1									
CHAPTER 71									
POWER PLANT									
710140U	NO. 1 ENGINE - -- RUN ADJ/TEST #1 ENG								
		MOS						13-NOV-1999	
		HRS/MSC	C/C					6961	
	REF:	ENC							
		(AFL)						5135	
+ 714010	NO. 1 ENGINE - CHECK ELECTRICAL WIRES AND CONNECTIONS								
71.040		MOS						26-JUL-2000	
		HRS/MSC	800					7325	8125
	REF: EMM 72-00-00 TR 72-61	ENC							
		(AFL)						5360	
+ 715010	NO. 1 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS								
71.050		MOS						26-JUL-2000	
		HRS/MSC	800					7325	8125
	REF: EMM 72-00-00 TR 72-61	ENC							
		(AFL)						5360	
+ 710130	NO. 1 ENGINE - INSPECT FAN ROTOR ASSEMBLY BLADES								
71.020	PKG 6, 6	MOS						16-FEB-2001	
		HRS/MSC	300					7551	.5
	REF: EMM 72-00-00 TR 72-61	ENC							
		(AFL)						5515	
+ 710120	NO. 1 ENGINE - MAJOR PERIODIC INSPECTION								
71.010		MOS						13-NOV-1999	
		HRS/MSC	1400					6961	8361
	REF: EMM 72-00-00	ENC							
		(AFL)						5135	
710110U	NO. 1 ENGINE - ENGINE, #1								
	3072500-2	MOS						03-APR-1989	
	P-77482	HRS/MSC	O/C	3972				4215	
	REF:	ENC							
		(AFL)		2456				2745	
CHAPTER 72									
ENGINE									
+ 724120	NO. 1 ENGINE - INSPECT COMBUSTION PLENUM CASE								
72.030		MOS						13-NOV-1999	
		HRS/MSC	1400					6961	8361
	REF: EMM 72-40-04	ENC							
		(AFL)						5135	
+ 723110	NO. 1 ENGINE - INSPECT COMPRESSOR CORE								
72.010		MOS						26-APR-1994	
		HRS/MSC	4200					5442	9642
	REF: NO REF	ENC							
		(AFL)						4106	

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Engine Model - TFE731-3

Report Date **14-MAR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
+ 727110 72.300	NO. 1 ENGINE - PERIODIC INSPECT FAN SUPPORT ASSEMBLY	MOS							26-APR-1994		
	REF: EMM 72-70-06	HRS/MSC ENC (AFL)	4200					5442	9642		
724110 72.020	NO. 1 ENGINE - CASE, COMBUSTION PLENUM 3072443-4	MOS							03-APR-1989		
	IP8088	HRS/MSC	O/C	3972				4215			
	REF: NO REF	ENC (AFL)		2456				2745			
+ 724120 72.030 ASSOCIATED	NO. 1 ENGINE - INSPECT COMBUSTION PLENUM CASE	MOS							13-NOV-1999		
	REF: EMM 72-40-04	HRS/MSC ENC (AFL)	1400					6961	8361		
725050 72.090	NO. 1 ENGINE - DISC, FAN ROTOR 3073563-2	MOS							13-NOV-1999	LIFE LIMIT	
	970322902451	HRS/MSC		0				6961			
	REF: NO REF	ENC (AFL)	10000	0				5135	15135		
725060 72.100	NO. 1 ENGINE - DISC, STAGE 1 LOW PRESSURE COMPRESSOR 3072395	MOS							03-APR-1989	LIFE LIMIT	
	1-12112-1531	HRS/MSC		3972				4215			
	REF: NO REF	ENC (AFL)	10000	2456				2745	10289		
725010 72.040	NO. 1 ENGINE - DISC, STAGE 1 LOW PRESSURE TURBINE 3072352-4	MOS							12-JUL-1991	LIFE LIMIT	
	0-03229-1212	HRS/MSC		0				4879			
	REF: NO REF	ENC (AFL)	3000	0				3494	6494		
725070 72.110	NO. 1 ENGINE - DISC, STAGE 2 LOW PRESSURE COMPRESSOR 3072396	MOS							03-APR-1989	LIFE LIMIT	
	1-12112-429	HRS/MSC		3972				4215			
	REF: NO REF	ENC (AFL)	10000	2456				2745	10289		
725020 72.050	NO. 1 ENGINE - DISC, STAGE 2 LOW PRESSURE TURBINE 3072351-5	MOS							20-MAY-1993	LIFE LIMIT	
	1-03226-1486	HRS/MSC		0				5278			
	REF: NO REF	ENC (AFL)	3000	0				3928	6928		
725080 72.120	NO. 1 ENGINE - DISC, STAGE 3 LOW PRESSURE COMPRESSOR 3072397	MOS							03-APR-1989	LIFE LIMIT	
	0-12112-4057	HRS/MSC		3972				4215			
	REF: NO REF	ENC (AFL)	10000	2456				2745	10289		

Engine Model - TFE731-3

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
725030 72.060	NO. 1 ENGINE - DISC, STAGE 3 LOW PRESSURE TURBINE 3074097-1 975332202025 REF: NO REF	MOS HRS/MSC ENC (AFL)	7000		0					13-NOV-1999 6961	LIFE LIMIT	
725090 72.130	NO. 1 ENGINE - DISC, STAGE 4 LOW PRESSURE COMPRESSOR 3072398 0-03160-3697 REF: NO REF	MOS HRS/MSC ENC (AFL)			3972					5135 4215	LIFE LIMIT	
725160 72.200	NO. 1 ENGINE - DUCT, TURBINE INTERSTAGE TRANSITION 3072318 SN-UNKNOWN REF: EMM 72-50-05	MOS HRS/MSC ENC (AFL)	O/C							2456 4215	10289	
726110 72.250	NO. 1 ENGINE - GEARBOX, ACCESSORY 3070003-5 SN-UNKNOWN REF: EMM 72-60-01	MOS HRS/MSC ENC (AFL)	O/C		3972					2745 4215	03-APR-1989	
+ 726120 72.260	NO. 1 ENGINE - INSPECT REF: EMM 72-60-02	MOS HRS/MSC ENC (AFL)	4200							2456 5442	26-APR-1994 9642	
726130 72.270	NO. 1 ENGINE - GEARBOX, TRANSFER 3070093-3 P-2768 REF: EMM 72-60-01	MOS HRS/MSC ENC (AFL)	O/C		0					2745 4215	03-APR-1989	
725110 72.150	NO. 1 ENGINE - IMPELLER, HIGH PRESSURE 3073398-1 4-23365-1094 REF: NO REF	MOS HRS/MSC ENC (AFL)	10000		3972					2456 4215	LIFE LIMIT	
725180 72.220	NO. 1 ENGINE - NOZZLE, STAGE 1 LOW PRESSURE TURBINE 3072319-11 990134506659 REF: NO REF	MOS HRS/MSC ENC (AFL)	O/C		0					0 6961	13-NOV-1999	
725140 72.180	NO. 1 ENGINE - PLATE, HIGH PRESSURE ROTOR SEAL 3072411-1 7-18040-2569 REF: NO REF	MOS HRS/MSC ENC (AFL)	10000		3816					0 6961	LIFE LIMIT	
					2507					5135	12628	

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Engine Model - TFE731-3

Report Date **14-MAR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
725040 72.070	NO. 1 ENGINE - ROTOR, HIGH PRESSURE TURBINE 3072316 1-18040-598 REF: EMM 72-50-06	MOS HRS/MSC ENC (AFL)	7000		3972				03-APR-1989 4215	LIFE LIMIT	
					2456			2745	7289		
725170 72.210	NO. 1 ENGINE - SEAL PLATE, STAGE 1 LOW PRESSURE TURBINE 3073552 SN-UNKNOWN REF: NO REF	MOS HRS/MSC ENC (AFL)	O/C					11-FEB-1982			
725190 72.230	NO. 1 ENGINE - SEAL, LOW PRESSURE TURBINE ROTATING AIR 3073355 SN-UNKNOWN REF: NO REF	MOS HRS/MSC ENC (AFL)	O/C		0						
725120 72.160	NO. 1 ENGINE - SEAL, ROTATING 3072729-1 0-23151-343 REF: NO REF	MOS HRS/MSC ENC (AFL)	O/C		0			12-JUL-1991 4879			
					0			3494			
725150 72.190	NO. 1 ENGINE - SHAFT, FAN DRIVE 3071955-3 1P-39726 REF: NO REF	MOS HRS/MSC ENC (AFL)	O/C		3972			03-APR-1989 4215			
					2456			2745			
725130 72.170	NO. 1 ENGINE - SHAFT, HIGH PRESSURE SHOULDERED 3072545-1 1P-39446 REF: NO REF	MOS HRS/MSC ENC (AFL)	12000		3456			03-APR-1989 4215		LIFE LIMIT	
								2745	11289		
725191 72.240	NO. 1 ENGINE - SUPPORT, LOW PRESSURE TURBINE ROTATING AIR SEAL 3073764 SN-UNKNOWN REF: NO REF	MOS HRS/MSC ENC (AFL)	O/C								
725091 72.140	NO. 1 ENGINE - TIE ROD, LOW PRESSURE 3073049-1 1P-15433 REF: EMM 72-30-10	MOS HRS/MSC ENC (AFL)	O/C		3972			03-APR-1989 4215			
					2456			2745			
CHAPTER 73	ENGINE FUEL AND CONTROL										
+ 731120 73.020	NO. 1 ENGINE - REMOVE AND REPLACE FILTER ELEMENT PKG 6, 6 REF: See Workcard	MOS HRS/MSC ENC (AFL)	300					16-FEB-2001 7551			
								5515			

Engine Model - TFE731-3

Report Date **14-MAR-2002**

Owner Name - **R&S AIRCRAFT INVESTMENTS, LLC**
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
732110 73.060	NO. 1 ENGINE - CONTROL UNIT, FUEL 3070800-8 SN-UNKNOWN REF: EMM 73-20-01	MOS HRSMSC ENC (AFL)	O/C	3972						18-MAY-1989 4215		
				2456						2745		
732120 73.070 ASSOCIATED	NO. 1 ENGINE - CHANGE PRESSURE LIMITER VALVE 3070685-4 SN-UNKNOWN REF: NO REF	MOS HRSMSC ENC (AFL)	O/C	3972						03-APR-1989 4215		
				2456						2745		
731150 73.050	NO. 1 ENGINE - COOLER, FUEL/OIL 158610-5 SN-UNKNOWN REF: EMM 79-20-07	MOS HRSMSC ENC (AFL)	O/C	3972						03-APR-1989 4215		
				2456						2745		
731140 73.040	NO. 1 ENGINE - HEATER, FUEL 158670-3 SN-UNKNOWN REF: EMM 73-10-04	MOS HRSMSC ENC (AFL)	O/C	3972						03-APR-1989 4215		
				2456						2745		
731110 73.010	NO. 1 ENGINE - PUMP, ENGINE FUEL 3070850-8 SN-UNKNOWN REF: EMM 73-20-01	MOS HRSMSC ENC (AFL)	O/C	3972						03-APR-1989 4215		
				2456						2745		
+ 731120 73.020 ASSOCIATED	NO. 1 ENGINE - REMOVE AND REPLACE FILTER ELEMENT PKG 6, 6 REF: See Workcard	MOS HRSMSC ENC (AFL)	300							16-FEB-2001 7551		
										5515		
732160 73.110	NO. 1 ENGINE - TRANSMITTER, FUEL FLOW 6883709-1 564 REF: NO REF	MOS HRSMSC ENC (AFL)		0						06-MAY-1992 5105		
				0						3725		
731130 73.030	NO. 1 ENGINE - VALVE, FLOW DIVIDER/DRAIN 394366-4 SN-UNKNOWN REF: NO REF	MOS HRSMSC ENC (AFL)	O/C	3972						03-APR-1989 4215		
				2456						2745		
732110 73.060 ASSOCIATED	NO. 1 ENGINE - CHANGE FUEL CONTROL UNIT 3070800-8 SN-UNKNOWN REF: EMM 73-20-01	MOS HRSMSC ENC (AFL)	O/C	3972						18-MAY-1989 4215		
				2456						2745		

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Engine Model - TFE731-3

Report Date **14-MAR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
732120	NO. 1 ENGINE - CHANGE PRESSURE LIMITER VALVE											
73.070	3070685-4	MOS							03-APR-1989			
ASSOCIATED	SN-UNKNOWN	HRS/MSC	O/C	3972					4215			
	REF: NO REF	ENC										
		(AFL)		2456					2745			
732120	NO. 1 ENGINE - VALVE, PRESSURE LIMITER											
73.070	3070685-4	MOS							03-APR-1989			
	SN-UNKNOWN	HRS/MSC	O/C	3972					4215			
	REF: NO REF	ENC										
		(AFL)		2456					2745			
732140	NO. 1 ENGINE - VALVE, SOLENOID CONTROL											
73.090	109696-3-1	MOS							03-APR-1989			
	SN-UNKNOWN	HRS/MSC	O/C	3972					4215			
	REF: EMM 76-10-01	ENC										
		(AFL)		2456					2745			
732130	NO. 1 ENGINE - VALVE, SURGE BLEED											
73.080	978812-4-1	MOS							03-APR-1989			
	SN-UNKNOWN	HRS/MSC	O/C	3972					4215			
	REF: EMM 76-10-01	ENC										
		(AFL)		2456					2745			
CHAPTER 74	IGNITION											
+ 742120	NO. 1 ENGINE - INSPECT 6 O'CLOCK IGNITER PLUG											
74.040		MOS							26-JUL-2000			
	REF: See Workcard	HRS/MSC	800						7325	8125		
		ENC										
		(AFL)							5360			
+ 742140	NO. 1 ENGINE - INSPECT 7 O'CLOCK IGNITER PLUG											
74.060		MOS							26-JUL-2000			
	REF: See Workcard	HRS/MSC	800						7325	8125		
		ENC										
		(AFL)							5360			
+ 741120	NO. 1 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM											
74.020		MOS							26-JUL-2000			
	REF: EMM 74-00-01	HRS/MSC	800						7325	8125	1	
		ENC										
		(AFL)							5360			
742110	NO. 1 ENGINE - IGNITER PLUG, 6 O'CLOCK											
74.030	3071589-2	MOS							03-APR-1989			
	SN-UNKNOWN	HRS/MSC	O/C	3972					4215			
	REF: EMM 74-00-01	ENC										
		(AFL)		2456					2745			
+ 742120	NO. 1 ENGINE - INSPECT 6 O'CLOCK IGNITER PLUG											
74.040		MOS							26-JUL-2000			
ASSOCIATED	REF: See Workcard	HRS/MSC	800						7325	8125		
		ENC										
		(AFL)							5360			

Engine Model - TFE731-3

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
742130 74.050	NO. 1 ENGINE - IGNITER PLUG, 7 O'CLOCK 3071589-2 SN-UNKNOWN REF: EMM 74-00-01	MOS HRS/MSC ENC (AFL)	O/C	3972					03-APR-1989 4215		
+ 742140 74.060 ASSOCIATED	NO. 1 ENGINE - INSPECT 7 O'CLOCK IGNITER PLUG REF: See Workcard	MOS HRS/MSC ENC (AFL)	800						26-JUL-2000 7325 8125		
741110 74.010	NO. 1 ENGINE - UNIT, IGNITION 3070378-2 SN-UNKNOWN REF: EMM 74-00-01	MOS HRS/MSC ENC (AFL)	O/C	3972					03-APR-1989 4215		
+ 741120 74.020 ASSOCIATED	NO. 1 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM REF: EMM 74-00-01	MOS HRS/MSC ENC (AFL)	800						26-JUL-2000 7325 8125	1	
CHAPTER 75	AIR										
751010 75.010	NO. 1 ENGINE - VALVE, ANTI-ICE SHUTOFF 978944-1-1 SN-UNKNOWN REF: EMM 75-10-01	MOS HRS/MSC ENC (AFL)	O/C	3972					03-APR-1989 4215		
CHAPTER 77	ENGINE INDICATING										
772110 77.030	NO. 1 ENGINE - HARNESS, ITT THERMOCOUPLE 3073595-1 1-20219-407 REF: EMM 77-20-01	MOS HRS/MSC ENC (AFL)	O/C	0					12-JUL-1991 4879		
771120 77.020	NO. 1 ENGINE - TRANSDUCER, HIGH PRESSURE (N2) 3070722-2 SN-UNKNOWN REF: EMM 77-10-05	MOS HRS/MSC ENC (AFL)	O/C	3972					03-APR-1989 4215		
771110 77.010	NO. 1 ENGINE - TRANSDUCER, LOW PRESSURE (N1) 3071928-5 SN-UNKNOWN REF: EMM 77-10-03	MOS HRS/MSC ENC (AFL)	O/C	3972					03-APR-1989 4215		
CHAPTER 79	OIL										

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Engine Model - TFE731-3

Report Date **14-MAR-2002**

Owner Name - **R&S AIRCRAFT INVESTMENTS, LLC**
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
+ 790110 79.010	NO. 1 ENGINE - ANALYZE ENGINE OIL PKG 4, 4,6, 6	MOS HRS/MSC ENC (AFL)	150						26-JUN-2001 7687	1	
	REF: EMM 72-00-00 TR 72-61								5594		
790120 79.020	NO. 1 ENGINE - CHANGE OIL	MOS HRS/MSC ENC (AFL)	1400						13-NOV-1999 6961	8361	
	REF: See Workcard								5135		
+ 790130 79.030	NO. 1 ENGINE - INSPECT CHIP DETECTOR PKG 4, 4,6, 6	MOS HRS/MSC ENC (AFL)	150						26-JUN-2001 7687		
	REF: EMM 72-00-00 TR 72-61								5594		
792150 79.080	NO. 1 ENGINE - COOLER, OIL LOWER LEFT 159900-1 SN-UNKNOWN REF: EMM 79-20-09	MOS HRS/MSC ENC (AFL)	O/C	3972					03-APR-1989 4215		
									2745		
792160 79.090	NO. 1 ENGINE - COOLER, OIL LOWER RIGHT 159910-1 SN-UNKNOWN REF: EMM 79-20-09	MOS HRS/MSC ENC (AFL)	O/C	3972					03-APR-1989 4215		
									2745		
792140 79.070	NO. 1 ENGINE - COOLER, OIL UPPER 158600-4 SN-UNKNOWN REF: EMM 79-20-09	MOS HRS/MSC ENC (AFL)	O/C	3972					03-APR-1989 4215		
									2745		
792110 79.040	NO. 1 ENGINE - PUMP, OIL 3071949-7 SN-UNKNOWN REF: EMM 79-20-03	MOS HRS/MSC ENC (AFL)	O/C	3972					03-APR-1989 4215		
									2745		
790120 79.020 ASSOCIATED	NO. 1 ENGINE - CHANGE OIL	MOS HRS/MSC ENC (AFL)	1400						13-NOV-1999 6961	8361	
	REF: See Workcard								5135		
793120 79.120	NO. 1 ENGINE - SWITCH, OIL PRESSURE 3833518 SN-UNKNOWN REF: NO REF	MOS HRS/MSC ENC (AFL)	O/C	3972					03-APR-1989 4215		
									2745		

Engine Model - TFE731-3

Report Date **14-MAR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
793110 79.110	NO. 1 ENGINE - TRANSMITTER, OIL PRESSURE 101-412-80-13 SN-UNKNOWN REF: NO REF	MOS HRS/MSC ENC (AFL)	O/C	3972						03-APR-1989 4215		
792120 79.050	NO. 1 ENGINE - VALVE, OIL FILTER BYPASS 3070000NP69 SN-UNKNOWN REF: EMM 79-30-01	MOS HRS/MSC ENC (AFL)	O/C	3972						03-APR-1989 4215		
792130 79.060	NO. 1 ENGINE - VALVE, PRESSURE BREATHER 3071564-8 SN-UNKNOWN REF: EMM 79-20-02	MOS HRS/MSC ENC (AFL)	O/C	2456						18-MAY-1989 4215		
				2456						2745		
										2745		

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Engine Model - TFE731-3

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT----- TSN TSO TSR TSI ADJ	INSTALLATION	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
ENGINE NO. 2									
CHAPTER 71									
POWER PLANT									
710140U	NO. 2 ENGINE - --- RUN ADJ/TEST #2 ENG								
		MOS						31-MAY-1993	
		HRS/MSC	C/C					5278	
	REF:	ENC							
		(AFL)						3928	
+ 714010	NO. 2 ENGINE - CHECK ELECTRICAL WIRES AND CONNECTIONS								
71.040		MOS						26-JUL-2000	
		HRS/MSC	800					7325	8125
	REF: EMM 72-00-00 TR 72-61	ENC							
		(AFL)						5360	
+ 715010	NO. 2 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS								
71.050		MOS						26-JUL-2000	
		HRS/MSC	800					7325	8125
	REF: EMM 72-00-00 TR 72-61	ENC							
		(AFL)						5360	
+ 710130	NO. 2 ENGINE - INSPECT FAN ROTOR ASSEMBLY BLADES								
71.020	PKG 7, 7	MOS						16-FEB-2001	
		HRS/MSC	300					7551	.5
	REF: EMM 72-00-00 TR 72-61	ENC							
		(AFL)						5515	
+ 710120	NO. 2 ENGINE - MAJOR PERIODIC INSPECTION								
71.010		MOS						17-OCT-1998	
		HRS/MSC	1400					6520	7920
	REF: EMM 72-00-00	ENC							
		(AFL)						4889	
710110U	NO. 2 ENGINE - ENGINE, #2								
	3072500-2	MOS						31-MAY-1993	
	P77488	HRS/MSC	O/C	5227				5278	
	REF:	ENC							
		(AFL)		3867				3928	
CHAPTER 72									
ENGINE									
+ 724120	NO. 2 ENGINE - INSPECT COMBUSTION PLENUM CASE								
72.030		MOS						17-SEP-1998	
		HRS/MSC	1400					6520	7920
	REF: EMM 72-40-04	ENC							
		(AFL)						4889	
+ 723110	NO. 2 ENGINE - INSPECT COMPRESSOR CORE								
72.010		MOS						17-OCT-1998	
		HRS/MSC	4200					6520	10720
	REF: NO REF	ENC							
		(AFL)						4889	

Engine Model - TFE731-3

Report Date **14-MAR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION			Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR				
+ 727110 72.300	NO. 2 ENGINE - PERIODIC INSPECT FAN SUPPORT ASSEMBLY	MOS						17-MAY-1989		
	REF: EMM 72-70-06	HRS/MSC ENC (AFL)	4200					4265 8465 2793		
724110 72.020	NO. 2 ENGINE - CASE, COMBUSTION PLENUM 3072443-4	MOS						31-MAY-1989		
	OP-52337 REF: NO REF	HRS/MSC ENC (AFL)	O/C	4215				4265 2793		
+ 724120 72.030 ASSOCIATED	NO. 2 ENGINE - INSPECT COMBUSTION PLENUM CASE	MOS						17-SEP-1998		
	REF: EMM 72-40-04	HRS/MSC ENC (AFL)	1400					6520 7920 4889		
725050 72.090	NO. 2 ENGINE - DISC, FAN ROTOR 3073539-2	MOS						20-MAY-1993	LIFE LIMIT	
	0-18040-4768 REF: NO REF	HRS/MSC ENC (AFL)		4087				5278 3928 5368		
725060 72.100	NO. 2 ENGINE - DISC, STAGE 1 LOW PRESSURE COMPRESSOR 3072395	MOS						31-MAY-1989	LIFE LIMIT	
	1-12112-1647 REF: NO REF	HRS/MSC ENC (AFL)	4100	2660				4265 2793 10048		
725010 72.040	NO. 2 ENGINE - DISC, STAGE 1 LOW PRESSURE TURBINE 3072351-5	MOS						20-MAY-1993	LIFE LIMIT	
	1-03229-1486 REF: NO REF	HRS/MSC ENC (AFL)	3000	0				5278 3928 6928		
725070 72.110	NO. 2 ENGINE - DISC, STAGE 2 LOW PRESSURE COMPRESSOR 3072396	MOS						31-MAY-1989	LIFE LIMIT	
	1-12112-581 REF: NO REF	HRS/MSC ENC (AFL)	10000	2745				4265 2793 10048		
725020 72.050	NO. 2 ENGINE - DISC, STAGE 2 LOW PRESSURE TURBINE 3072542-5	MOS						20-MAY-1993	LIFE LIMIT	
	1-03229-1277 REF: NO REF	HRS/MSC ENC (AFL)	3000	0				5278 3928 6928		
725080 72.120	NO. 2 ENGINE - DISC, STAGE 3 LOW PRESSURE COMPRESSOR 3072397	MOS						31-MAY-1989	LIFE LIMIT	
	0-12112-1718 REF: NO REF	HRS/MSC ENC (AFL)	10000	2745				4265 2793 10048		

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Engine Model - TFE731-3

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
725030 72.060	NO. 2 ENGINE - DISC, STAGE 3 LOW PRESSURE TURBINE 3072544-2 6-18040-4905 REF: NO REF	MOS HRS/MSC ENC (AFL)	3000		0					31-MAY-1989 4265 2793	LIFE LIMIT 5793	
725090 72.130	NO. 2 ENGINE - DISC, STAGE 4 LOW PRESSURE COMPRESSOR 3072398 0-12112-3229 REF: NO REF	MOS HRS/MSC ENC (AFL)	10000		4215		2745			31-MAY-1989 4265 2793	LIFE LIMIT 10048	
725160 72.200	NO. 2 ENGINE - DUCT, TURBINE INTERSTAGE TRANSITION 3072318 SN-UNKNOWN REF: EMM 72-50-05	MOS HRS/MSC ENC (AFL)	O/C							31-MAY-1989 4265 2793		
726110 72.250	NO. 2 ENGINE - GEARBOX, ACCESSORY 3070003-5 P-948 REF: EMM 72-60-01	MOS HRS/MSC ENC (AFL)	O/C		4215		2745			31-MAY-1989 4265 2793		
+ 726120 72.260	NO. 2 ENGINE - INSPECT REF: EMM 72-60-02	MOS HRS/MSC ENC (AFL)	4200							17-MAY-1989 4265 2793	8465	
726130 72.270	NO. 2 ENGINE - GEARBOX, TRANSFER 3070093-3 P-3691 REF: EMM 72-60-01	MOS HRS/MSC ENC (AFL)	O/C		4215		2745			31-MAY-1989 4265 2793		
725110 72.150	NO. 2 ENGINE - IMPELLER, HIGH PRESSURE 3073394-1 0-23369-4190 REF: NO REF	MOS HRS/MSC ENC (AFL)	10000		0		0			31-MAY-1989 4265 2793	LIFE LIMIT 12793	
725180 72.220	NO. 2 ENGINE - NOZZLE, STAGE 1 LOW PRESSURE TURBINE 3072319 SN-UNKNOWN REF: NO REF	MOS HRS/MSC ENC (AFL)	O/C							31-MAY-1989 4265 2793		
725140 72.180	NO. 2 ENGINE - PLATE, HIGH PRESSURE ROTOR SEAL 3072411-1 1-18040-5077 REF: NO REF	MOS HRS/MSC ENC (AFL)	10000		4215		2745			31-MAY-1989 4265 2793	LIFE LIMIT 10048	

Engine Model - TFE731-3

Report Date **14-MAR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
725040 72.070	NO. 2 ENGINE - ROTOR, HIGH PRESSURE TURBINE 307 2316 1-18040-451 REF: EMM 72-50-06	MOS HRSMSC ENC (AFL)	7000	4215						31-MAY-1989 4265 2793	LIFE LIMIT 7048	
725170 72.210	NO. 2 ENGINE - SEAL PLATE, STAGE 1 LOW PRESSURE TURBINE 307 3552 SN-UNKNOWN REF: NO REF	MOS HRSMSC ENC (AFL)	O/C							11-FEB-1982		
725190 72.230	NO. 2 ENGINE - SEAL, LOW PRESSURE TURBINE ROTATING AIR 307 3355 SN-UNKNOWN REF: NO REF	MOS HRSMSC ENC (AFL)		0								
725120 72.160	NO. 2 ENGINE - SEAL, ROTATING 307 2729-1 7-23 151-1814 REF: NO REF	MOS HRSMSC ENC (AFL)	O/C	0						31-MAY-1989 4265 2793		
725150 72.190	NO. 2 ENGINE - SHAFT, FAN DRIVE 307 1955-3 IP-41464 REF: NO REF	MOS HRSMSC ENC (AFL)	O/C	4215						31-MAY-1989 4265 2793		
725130 72.170	NO. 2 ENGINE - SHAFT, HIGH PRESSURE SHOULDERED 307 2545-1 1P-39469 REF: NO REF	MOS HRSMSC ENC (AFL)	12000	4215						31-MAY-1989 4265 2793	LIFE LIMIT 12048	
725191 72.240	NO. 2 ENGINE - SUPPORT, LOW PRESSURE TURBINE ROTATING AIR SEAL 307 3764 SN-UNKNOWN REF: NO REF	MOS HRSMSC ENC (AFL)	O/C									
725091 72.140	NO. 2 ENGINE - TIE ROD, LOW PRESSURE 307 3049-1 1P- 15412 REF: EMM 72-30-10	MOS HRSMSC ENC (AFL)	O/C	4215						31-MAY-1989 4265 2793		
CHAPTER 73	ENGINE FUEL AND CONTROL											
+ 731120 73.020	NO. 2 ENGINE - REMOVE AND REPLACE FILTER ELEMENT PKG 7, 7 REF: See Workcard	MOS HRSMSC ENC (AFL)	300							16-FEB-2001 7551 5515		

COPYRIGHT 2001 CAMP SYSTEMS INT'L

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

Engine Model - TFE731-3

Report Date **14-MAR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
732110	NO. 2 ENGINE - CONTROL UNIT, FUEL											
73.060	3070800-2	MOS								31-MAY-1989		
	A3593PT	HRS/MSC	O/C							4265		
	REF: EMM 73-20-01	ENC								2793		
	(AFL)											
732120	NO. 2 ENGINE - CHANGE PRESSURE LIMITER VALVE											
73.070	3070685-4	MOS								31-MAY-1989		
ASSOCIATED	A6760	HRS/MSC	O/C	4215						4265		
	REF: NO REF	ENC								2793		
	(AFL)			2745								
731150	NO. 2 ENGINE - COOLER, FUEL/OIL											
73.050	158610-7	MOS								31-MAY-1989		
	21-3736	HRS/MSC	O/C	4215						4265		
	REF: EMM 79-20-07	ENC								2793		
	(AFL)			2745								
731140	NO. 2 ENGINE - HEATER, FUEL											
73.040	158670-3	MOS								31-MAY-1989		
	71-2903	HRS/MSC	O/C	4215						4265		
	REF: EMM 73-10-04	ENC								2793		
	(AFL)			2745								
731110	NO. 2 ENGINE - PUMP, ENGINE FUEL											
73.010	3070850-8	MOS								31-MAY-1989		
	MX364112	HRS/MSC	O/C	4215						4265		
	REF: EMM 73-20-01	ENC								2793		
	(AFL)			2745								
+ 731120	NO. 2 ENGINE - REMOVE AND REPLACE FILTER ELEMENT											
73.020	PKG 7, 7	MOS								16-FEB-2001		
ASSOCIATED	REF: See Workcard	HRS/MSC	300							7551		
		ENC								5515		
	(AFL)											
732160	NO. 2 ENGINE - TRANSMITTER, FUEL FLOW											
73.110	883709-1	MOS								31-MAY-1989		
	SN-UNKNOWN	HRS/MSC	O/C	4215						4265		
	REF: NO REF	ENC								2793		
	(AFL)			2745								
731130	NO. 2 ENGINE - VALVE, FLOW DIVIDER/DRAIN											
73.030	394366-4	MOS								31-MAY-1989		
	SN-UNKNOWN	HRS/MSC	O/C	4215						4265		
	REF: NO REF	ENC								2793		
	(AFL)			2745								
732110	NO. 2 ENGINE - CHANGE FUEL CONTROL UNIT											
73.060	3070800-2	MOS								31-MAY-1989		
ASSOCIATED	A3593PT	HRS/MSC	O/C							4265		
	REF: EMM 73-20-01	ENC								2793		
	(AFL)											

Engine Model - TFE731-3

Report Date **14-MAR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
732120	NO. 2 ENGINE - CHANGE PRESSURE LIMITER VALVE										
73.070	3070685-4	MOS							31-MAY-1989		
ASSOCIATED	A6760	HRS/MSC	O/C	4215				4265			
	REF: NO REF	ENC (AFL)		2745				2793			
732120	NO. 2 ENGINE - VALVE, PRESSURE LIMITER										
73.070	3070685-4	MOS							31-MAY-1989		
	A6760	HRS/MSC	O/C	4215				4265			
	REF: NO REF	ENC (AFL)		2745				2793			
732140	NO. 2 ENGINE - VALVE, SOLENOID CONTROL										
73.090	109696-3-1	MOS							31-MAY-1989		
	P-3683	HRS/MSC	O/C	4215				4265			
	REF: EMM 76-10-01	ENC (AFL)		2745				2793			
732130	NO. 2 ENGINE - VALVE, SURGE BLEED										
73.080	978812-4-1	MOS							31-MAY-1989		
	P-3683	HRS/MSC	O/C	4215				4265			
	REF: EMM 76-10-01	ENC (AFL)		2745				2793			
CHAPTER 74	IGNITION										
+ 742120	NO. 2 ENGINE - INSPECT 6 O'CLOCK IGNITER PLUG										
74.040		MOS							26-JUL-2000		
	REF: See Workcard	HRS/MSC	800					7325	8125		
		ENC (AFL)						5360			
+ 742140	NO. 2 ENGINE - INSPECT 7 O'CLOCK IGNITER PLUG										
74.060		MOS							26-JUL-2000		
	REF: See Workcard	HRS/MSC	800					7325	8125		
		ENC (AFL)						5360			
+ 741120	NO. 2 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM										
74.020		MOS							26-JUL-2000		
	REF: EMM 74-00-01	HRS/MSC	800					7325	8125	1	
		ENC (AFL)						5360			
742110	NO. 2 ENGINE - IGNITER PLUG, 6 O'CLOCK										
74.030	3071589-2	MOS							17-OCT-1998		
	SN-UNKNOWN	HRS/MSC	O/C					6520			
	REF: EMM 74-00-01	ENC (AFL)						4889			
+ 742120	NO. 2 ENGINE - INSPECT 6 O'CLOCK IGNITER PLUG										
74.040		MOS							26-JUL-2000		
ASSOCIATED		HRS/MSC	800					7325	8125		
	REF: See Workcard	ENC (AFL)						5360			

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Engine Model - TFE731-3

Report Date **14-MAR-2002**

Owner Name - **R&S AIRCRAFT INVESTMENTS, LLC**

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
742130	NO. 2 ENGINE - IGNITER PLUG, 7 O'CLOCK											
74.050	3071589-2	MOS							09-NOV-1996			
	SN-UNKNOWN	HRS/MSC	O/C						5951			
	REF: EMM 74-00-01	ENC										
		(AFL)							4589			
+ 742140	NO. 2 ENGINE - INSPECT 7 O'CLOCK IGNITER PLUG											
74.060		MOS							26-JUL-2000			
	ASSOCIATED	HRS/MSC	800						7325	8125		
	REF: See Workcard	ENC										
		(AFL)							5360			
741110	NO. 2 ENGINE - UNIT, IGNITION											
74.010	3070378-2	MOS							31-MAY-1989			
	SN-UNKNOWN	HRS/MSC	O/C	1142					4265			
	REF: EMM 74-00-01	ENC										
		(AFL)							2793			
+ 741120	NO. 2 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM											
74.020		MOS							26-JUL-2000			
	ASSOCIATED	HRS/MSC	800						7325	8125	1	
	REF: EMM 74-00-01	ENC										
		(AFL)							5360			
CHAPTER 75	AIR											
751010	NO. 2 ENGINE - VALVE, ANTI-ICE SHUTOFF											
75.010	978944-1-1	MOS							31-MAY-1989			
	SN-UNKNOWN	HRS/MSC	O/C	4215					4265			
	REF: EMM 75-10-01	ENC										
		(AFL)							2793			
CHAPTER 77	ENGINE INDICATING											
772110	NO. 2 ENGINE - HARNESS, ITT THERMOCOUPLE											
77.030	3071849-3	MOS							31-MAY-1989			
	9-20219-358	HRS/MSC	O/C						4265			
	REF: EMM 77-20-01	ENC										
		(AFL)							2793			
771120	NO. 2 ENGINE - TRANSDUCER, HIGH PRESSURE (N2)											
77.020	3070722-2	MOS							31-MAY-1989			
	SN-UNKNOWN	HRS/MSC	O/C	4215					4265			
	REF: EMM 77-10-05	ENC										
		(AFL)							2793			
771110	NO. 2 ENGINE - TRANSDUCER, LOW PRESSURE (N1)											
77.010	3071928-5	MOS							31-MAY-1989			
	SN-UNKNOWN	HRS/MSC	O/C	4215					4265			
	REF: EMM 77-10-03	ENC										
		(AFL)							2793			
CHAPTER 79	OIL											

Engine Model - TFE731-3

Report Date **14-MAR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
+ 790110 79.010	NO. 2 ENGINE - ANALYZE ENGINE OIL PKG 5, 5,7, 7	MOS HRS/MSC ENC (AFL)	150							26-JUN-2001 7687	1 5594	
	REF: EMM 72-00-00 TR 72-61											
790120 79.020	NO. 2 ENGINE - CHANGE OIL	MOS HRS/MSC ENC (AFL)	1400							17-OCT-1998 6520	7920 4889	
	REF: See Workcard											
+ 790130 79.030	NO. 2 ENGINE - INSPECT CHIP DETECTOR PKG 5, 5,7, 7	MOS HRS/MSC ENC (AFL)	150							26-JUN-2001 7687	5594	
	REF: EMM 72-00-00 TR 72-61											
792150 79.080	NO. 2 ENGINE - COOLER, OIL LOWER LEFT 159900-1 SN-UNKNOWN REF: EMM 79-20-09	MOS HRS/MSC ENC (AFL)	O/C							31-MAY-1989 4265	2793	
792160 79.090	NO. 2 ENGINE - COOLER, OIL LOWER RIGHT 159910-1 SN-UNKNOWN REF: EMM 79-20-09	MOS HRS/MSC ENC (AFL)	O/C	4215						31-MAY-1989 4265	2793	
792140 79.070	NO. 2 ENGINE - COOLER, OIL UPPER 158600-4 SN-UNKNOWN REF: EMM 79-20-09	MOS HRS/MSC ENC (AFL)	O/C	4215						31-MAY-1989 4265	2793	
792110 79.040	NO. 2 ENGINE - PUMP, OIL 3071949-7 0683 REF: EMM 79-20-03	MOS HRS/MSC ENC (AFL)	O/C							31-MAY-1989 4265	2793	
790120 79.020 ASSOCIATED	NO. 2 ENGINE - CHANGE OIL REF: See Workcard	MOS HRS/MSC ENC (AFL)	1400							17-OCT-1998 6520	7920 4889	
793120 79.120	NO. 2 ENGINE - SWITCH, OIL PRESSURE 3-833518 1041 REF: NO REF	MOS HRS/MSC ENC (AFL)	O/C	482						31-MAY-1989 4265	2793	

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Engine Model - TFE731-3

Report Date **14-MAR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
793110 79.110	NO. 2 ENGINE - TRANSMITTER, OIL PRESSURE 101-412-80-13 SN-UNKNOWN REF: NO REF	MOS HRS/MSC ENC (AFL)	O/C	4215						31-MAY-1989 4265 2793		
792120 79.050	NO. 2 ENGINE - VALVE, OIL FILTER BYPASS 3070000NP69 SN-UNKNOWN REF: EMM 79-30-01	MOS HRS/MSC ENC (AFL)	O/C	4215						31-MAY-1989 4265 2793		
792130 79.060	NO. 2 ENGINE - VALVE, PRESSURE BREATHER 3075323-1 6376 REF: EMM 79-20-02	MOS HRS/MSC ENC (AFL)	O/C		0					04-FEB-1994 5390 4040		

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
AIRCRAFT											
AD 1974-08-09 R2	AIRWORTHINESS DIRECTIVE TO PREVENT POSSIBLE FIRES THAT COULD RESULT FROM SMOKING MATERIALS BEING DROPPED INTO LAVATORY PAPER OR LINEN WASTE RECEPTACLES									F4	
		MOS						17-JAN-2001			
		HRS/MSC	1000					7494	8494		
	REF:	AFL						5466			
	Method of Compliance: OPEN										
AD 1989-12-08	AIRWORTHINESS DIRECTIVE TO DETECT CRACKS IN THE HINGE LUGS OF THE HORIZONTAL STABILIZER AFT SPAR SPLICE FITTING (HINGE ASSEMBLY)										
		MOS						17-JAN-2001			
		HRS/MSC	300					7494	7794		
	REF: See Workcard	AFL						5466			
	Method of Compliance: OPEN										
AD 1996-24-11 LEFT AILERON	AIRWORTHINESS DIRECTIVE TO PREVENT EXCESSIVE WEAR OF THE AILERON PUSH-PULL TUBE, WHICH COULD RESULT IN UNEVEN MOVEMENT OF THE CONTROL WHEEL, PERFORATION OF THE AILERON PUSH-PULL TUBE, AND CONSEQUENT REDUCED ROLL CONTROL OF THE AIRPLANE									W1	
		MOS						26-JUL-2000			
		HRS/MSC	600					7325	7925		
	REF: AD	AFL						5360			
	Method of Compliance: OPEN										
SB 1124-27-129 LEFT AILERON	FLIGHT CONTROLS SERVICE BULLETIN									W1	
		MOS						26-JUL-2000			
ASSOCIATED		HRS/MSC	600					7325	7925		
	REF: BULLETINS	AFL						5360			
	Method of Compliance: OPEN										
AD 1996-24-11 RIGHT AILERON	AIRWORTHINESS DIRECTIVE TO PREVENT EXCESSIVE WEAR OF THE AILERON PUSH-PULL TUBE, WHICH COULD RESULT IN UNEVEN MOVEMENT OF THE CONTROL WHEEL, PERFORATION OF THE AILERON PUSH-PULL TUBE, AND CONSEQUENT REDUCED ROLL CONTROL OF THE AIRPLANE									W2	
		MOS						26-JUL-2000			
		HRS/MSC	600					7325	7925		
	REF: AD	AFL						5360			
	Method of Compliance: OPEN										
SB 1124-27-129 RIGHT AILERON	FLIGHT CONTROLS SERVICE BULLETIN									W2	
		MOS						26-JUL-2000			
ASSOCIATED		HRS/MSC	600					7325	7925		
	REF: BULLETINS	AFL						5360			
	Method of Compliance: OPEN										
AD 1998-06-10	AIRWORTHINESS DIRECTIVE TO PREVENT FAILURE OF THE HYDRAULIC FUSE TO OPERATE PROPERLY IN THE EVENT OF AN EXTERNAL LEAK DOWNSTREAM OF THE FUSE, WHICH COULD RESULT IN LOSS OF HYDRAULIC SYSTEMS										
		MOS	36					06-NOV-2001	06-NOV-2004		
		HRS/MSC	1200					7774	8974		
	REF: AD	AFL						5641			
	Method of Compliance: OPEN										

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
					TSN	TSO	TSR	TSI	ADJ			
AD	2002-01-26	AIRWORTHINESS DIRECTIVE TO PREVENT FAILURE OF ATTACHMENT BOLTS DUE TO FATIGUE, WHICH COULD RESULT IN SEPARATION OF THE ENGINE INLET COWL AND AFT NACELLE, AND CONSEQUENT DAMAGE TO THE HORIZONTAL OR VERTICAL STABILIZER	MOS								MANDATORY	
		REF:	HRS/MS	DUE							50	
		Method of Compliance: OPEN	AFL									
SB	ASB1124-54A-138	SERVICE BULLETIN	MOS								MANDATORY	
	ASSOCIATED	REF:	HRS/MS	A/R								
		Method of Compliance: OPEN	AFL									
SB	1124-27-129 LEFT AILERON	SERVICE BULLETIN FLIGHT CONTROLS	MOS									W1
		REF: BULLETINS	HRS/MS	600					26-JUL-2000			
		Method of Compliance: OPEN	AFL						7325	7925		
									5360			
SB	1124-27-129 RIGHT AILERON	SERVICE BULLETIN FLIGHT CONTROLS	MOS									W2
		REF: BULLETINS	HRS/MS	600					26-JUL-2000			
		Method of Compliance: OPEN	AFL						7325	7925		
									5360			
SB	1124-30-036 PART II	SERVICE BULLETIN ICE AND RAIN PROTECTION	MOS									F3
		PKG 1, 2, 3	HRS/MS	150					26-JUN-2001			
		REF: See Workcard	AFL						7687	7837		
		Method of Compliance: OPEN							5594			
SB	1124-55-020 R2	SERVICE BULLETIN STABILIZERS	MOS									T1
		PKG 2, 3	HRS/MS	300					26-JUN-2001			
		REF: See Workcard	AFL						7687	7987		
		Method of Compliance: OPEN							5594			
SB	900280	SERVICE BULLETIN SB WW-24-28A	MOS									L3
		REF: See Workcard	HRS/MS	1200					22-FEB-2000			
		Method of Compliance: OPEN	AFL						7107			
									5232			
SB	911390	SERVICE BULLETIN SB1124-32-139 UPR STRG	MOS									
		PKG 3	HRS/MS	800					26-JUL-2000			
		REF:	AFL						7325	8125		
		Method of Compliance: OPEN							5360			
SB	950920	SERVICE BULLETIN SL WW-2492 HYD HOSE INSP	MOS									
		PKG 1, 2, 3	HRS/MS	200					26-JUN-2001			
		REF:	AFL						7687	7887		
		Method of Compliance: OPEN							5594			

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:41:14 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
SB 950941	SERVICE BULLETIN SLWW-2494 REV 3 LMG BOLTS	MOS									L1	
		HRSMSC	300						26-JUN-2001			
	REF: See Workcard	AFL							7687	7987		
	Method of Compliance: OPEN								5594			
SB 950942	SERVICE BULLETIN SLWW-2494 REV 3 RMG BOLTS	MOS									L2	
		HRSMSC	300						26-JUN-2001			
	REF: See Workcard	AFL							7687	7987		
	Method of Compliance: OPEN								5594			
SB 972850U	SERVICE BULLETIN SB 731-A72-3668 #1 ENG	MOS									RECOMMENDED	
		HRSMSC	A/R								31-DEC-2002	
	REF:	AFL										
SB 972851U	SERVICE BULLETIN SB 731-A72-3668 #2 ENG	MOS									RECOMMENDED	
		HRSMSC	A/R								31-DEC-2002	
	REF:	AFL										
SB 972B40U	SERVICE BULLETIN GSBA72-3569 R/E FAN ROTOR	MOS										
		HRSMSC	A/R									
	REF:	AFL									5722	
	Method of Compliance: OPEN											

Engine Model - TFE731-3

Report Date **14-MAR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
ENGINE NO. 1												
AD 2000-15-09	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE HPC IMPELLER	MOS									10-OCT-2000	
	REF:	HRS/MS	4200									
	ENC											
	Method of Compliance: OPEN											
AD 2001-23-09	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE TO PREVENT FAILURE OF THE FAN ROTOR DISC DUE TO FATIGUE CRACKING IN THE DOVETAIL SLOTS	MOS									MANDATORY 31-DEC-2002	
	REF:	HRS/MS	DUE									
	ENC											
	Method of Compliance: OPEN											
SB TFE731-A72-3668	NO. 1 ENGINE - REMOVE FAN ROTOR DISC FROM SERVICE SERVICE BULLETIN	MOS									MANDATORY 31-DEC-2002	
ASSOCIATED	REF: BULLETINS	HRS/MS	A/R									
	ENC											
	Method of Compliance: OPEN											

Engine Model - TFE731-3

Report Date **14-MAR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
ENGINE NO. 2												
AD 2000-15-09	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE HPC IMPELLER											
		MOS									10-OCT-2000	
		HRS/MS	4200									
	REF:	ENC										
	Method of Compliance: OPEN											
AD 2001-23-09	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE TO PREVENT FAILURE OF THE FAN ROTOR DISC DUE TO FATIGUE CRACKING IN THE DOVETAIL SLOTS										MANDATORY	
		MOS									31-DEC-2002	
		HRS/MS	DUE									
	REF:	ENC										
	Method of Compliance: OPEN											
SB TFE731-A72-3668	NO. 2 ENGINE - REMOVE FAN ROTOR DISC FROM SERVICE SERVICE BULLETIN										MANDATORY	
		MOS									31-DEC-2002	
	ASSOCIATED	HRS/MS	A/R									
	REF: BULLETINS	ENC										
	Method of Compliance: OPEN											

A/C Serial No.: 368 A/C Regn No.: N368MD Model:1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

Report Date **14-MAR-2002**

Compliance From 01/01/2001 To 3/14/2002

ITEM NO PART NO.	DESCRIPTION SERIAL NO.	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED				COMPONENT TIMES AFTER REMOVAL			
		C/W	TSN	TSO	TSR	C/W	TSN	TSO	TSR
CHAPTER --GENERAL									
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN								
		MOS	1/17/2001			TECH :		INSP :	
		HRS	7494					LABOR HRS :	
		AFL	5466					SERVICE REMARKS	--
CHAPTER 05-TIME LIMITS/MAINTENANCE CHECKS									
050150U	200 HOUR INSPECTION								
		MOS	1/17/2001			TECH :		INSP :	
		HRS	7494					LABOR HRS :	
		AFL	5466					SERVICE REMARKS	--
CHAPTER 10-PARKING, MOORING, STORE AND RET TO SERV									
100310	CHECK AIRWORTHY DIRECTIVES								
		MOS	1/17/2001			TECH :		INSP :	
		HRS	7494					LABOR HRS :	
		AFL	5466					SERVICE REMARKS	--
100320	CHECK SERVICE BULLETINS								
		MOS	1/17/2001			TECH :		INSP :	
		HRS	7494					LABOR HRS :	
		AFL	5466					SERVICE REMARKS	--
100330	CHECK SERVICE LETTERS								
		MOS	1/17/2001			TECH :		INSP :	
		HRS	7494					LABOR HRS :	
		AFL	5466					SERVICE REMARKS	--
CHAPTER 12-SERVICING									
120150	CHECK PRE-FLIGHT								
		MOS	1/17/2001			TECH :		INSP :	
		HRS	7494					LABOR HRS :	
		AFL	5466					SERVICE REMARKS	--
120160	CHECK NO.1 ENGINE PREFLIGHT COMPLETE								
		MOS	2/16/2001			TECH :		INSP :	
		HRS	7551					LABOR HRS :	
		AFL	5515					SERVICE REMARKS	--
120161	CHECK NO.2 ENGINE PREFLIGHT COMPLETE								
		MOS	2/16/2001			TECH :		INSP :	
		HRS	7551					LABOR HRS :	
		AFL	5515					SERVICE REMARKS	--
CHAPTER 21-AIR CONDITIONING									
210622	INSPECT 35 DEGREE TEMPERATURE SENSOR 35 DEGREE DUCT SENSOR								
		MOS	1/17/2001			TECH :		INSP :	
		HRS	7494					LABOR HRS :	
		AFL	5466					SERVICE REMARKS	--
210671	CLEAN/REPLACE WATER SEPARATOR CONDENSER/FILTER								
		MOS	1/17/2001			TECH :		INSP :	
		HRS	7494					LABOR HRS :	
		AFL	5466					SERVICE REMARKS	--
210681	CHANGE COOLING TURBINE OIL								
		MOS	1/17/2001			TECH :		INSP :	
		HRS	7494					LABOR HRS :	
		AFL	5466					SERVICE REMARKS	--
CHAPTER 24-ELECTRICAL POWER									

A/C Serial No.: 368 A/C Regn No.: N368MD Model:1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

Report Date 14-MAR-2002

Compliance

From 01/01/2001

To 3/14/2002

ITEM NO PART NO.	DESCRIPTION SERIAL NO.	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED				COMPONENT TIMES AFTER REMOVAL				TECH :	INSP :
		C/W	TSN	TSO	TSR	C/W	TSN	TSO	TSR		
240116 23065-018-1	CHANGE NO. 1 STARTER GENERATOR 3684	MOS	1/17/2001	0		11/6/2001	10			REASON : WORN	LABOR HRS :
		HRS	7494	0		7774	280			PRICE : 0	
		AFL	5466	0		5641	175				
240118	INSPECT NO. 1 STARTER GENERATOR	MOS	6/26/2001								
		HRS	7687								
		AFL	5594								SERVICE REMARKS --
240121	CHECK NO. 1 STARTER GENERATOR BRUSH WEAR/TENSION	MOS	6/26/2001								
		HRS	7687								
		AFL	5594								SERVICE REMARKS --
240123	INSPECT NO. 1 STARTER GENERATOR SPLINE	MOS	6/26/2001								
		HRS	7687								
		AFL	5594								SERVICE REMARKS --
240128	INSPECT NO. 2 STARTER GENERATOR	MOS	6/26/2001								
		HRS	7687								
		AFL	5594								SERVICE REMARKS --
240131	CHECK NO. 2 STARTER GENERATOR BRUSH WEAR/TENSION	MOS	6/26/2001								
		HRS	7687								
		AFL	5594								SERVICE REMARKS --
240133	INSPECT NO. 2 STARTER GENERATOR SPLINE	MOS	6/26/2001								
		HRS	7687								
		AFL	5594								SERVICE REMARKS --
240161	CHECK LEFT BATTERY ELECTROLYTE LEVEL	MOS	1/17/2001								
		HRS	7494								
		AFL	5466								SERVICE REMARKS --
240166	DEEP CYCLE LEFT BATTERY	MOS	6/26/2001								
		HRS	7687								
		AFL	5594								SERVICE REMARKS --
240176	CHECK RIGHT BATTERY ELECTROLYTE LEVEL	MOS	1/17/2001								
		HRS	7494								
		AFL	5466								SERVICE REMARKS --
240181	DEEP CYCLE RIGHT BATTERY	MOS	6/26/2001								
		HRS	7687								
		AFL	5594								SERVICE REMARKS --
240203	FUNCTIONALLY CHECK EXTERNAL POWER RECEPTACLE BATTERY TEMPERATURE AND WARNING SYSTEM	MOS	1/17/2001								
		HRS	7494								
		AFL	5466								SERVICE REMARKS --

CHAPTER 26-FIRE PROTECTION

260169 VISUAL INSPECTION COCKPIT PORTABLE EXTINGUISHER COCKPIT FIRE EXTINGUISHER

A/C Serial No.: 368 A/C Regn No.: N368MD Model:1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

Report Date 14-MAR-2002

Compliance From 01/01/2001 To 3/14/2002

ITEM NO PART NO.	DESCRIPTION SERIAL NO.	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED				COMPONENT TIMES AFTER REMOVAL				TECH :	INSP :	LABOR HRS :	SERVICE REMARKS
		C/W	TSN	TSO	TSR	C/W	TSN	TSO	TSR				
		MOS	6/26/2001										
		HRS	7687										
		AFL	5594										
260174	INSPECT COCKPIT PORTABLE EXTINGUISHER COCKPIT FIRE EXTINGUISHER	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
260180	VISUAL INSPECTION CABIN PORTABLE EXTINGUISHER CABIN FIRE EXTINGUISHER	MOS	6/26/2001										
		HRS	7687										
		AFL	5594										
260184	INSPECT CABIN PORTABLE EXTINGUISHER CABIN FIRE EXTINGUISHER	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
CHAPTER 27-FLIGHT CONTROLS													
270158	INSPECT RUDDER TRIM TAB FREEPLAY	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
270193	INSPECT LEFT ELEVATOR SKIN SEPARATION	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
270203	INSPECT RIGHT ELEVATOR SKIN SEPARATION	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
270213	LUBRICATE ELEVATOR ATTACH POINTS	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
270214	LUBRICATE AFT HINGE FITTING BEARINGS	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
270215	LUBRICATE FORWARD SCISSOR ASSEMBLY	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
270237	INSPECT LEFT FLAP/VANE LEFT FLAP VANE	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
270240	INSPECT LEFT FLAP/VANE LEFT FLAP HINGE AND BEARING 200 HOURS	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
270242	INSPECT RIGHT FLAP/VANE RIGHT FLAP HINGE AND BEARING 200 HOURS	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										

A/C Serial No.: 368 A/C Regn No.: N368MD Model:1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

Report Date 14-MAR-2002

Compliance

From 01/01/2001

To 3/14/2002

ITEM NO PART NO.	DESCRIPTION SERIAL NO.	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED				COMPONENT TIMES AFTER REMOVAL			
		C/W	TSN	TSO	TSR	C/W	TSN	TSO	TSR
270247	INSPECT RIGHT FLAP/VANE								
	MOS	1/17/2001				TECH :		INSP :	
	HRS	7494						LABOR HRS :	
	AFL	5466						SERVICE REMARKS	--
270335	OPERATIONAL CHECK SPEED BRAKES AND LIFT DUMPERS								
	MOS	1/17/2001				TECH :		INSP :	
	HRS	7494						LABOR HRS :	
	AFL	5466						SERVICE REMARKS	--
CHAPTER 28-FUEL									
281150	CHECK OPERATION OF FUEL BOOST PUMPS								
	MOS	1/17/2001				TECH :		INSP :	
	HRS	7494						LABOR HRS :	
	AFL	5466						SERVICE REMARKS	--
CHAPTER 29-HYDRAULIC POWER									
290143	INSPECT/LUBRICATE NO. 1 HYDRAULIC PUMP NO.1 ENGINE HYDRAULIC PUMP SPLINES								
	MOS	1/17/2001				TECH :		INSP :	
	HRS	7494						LABOR HRS :	
	AFL	5466						SERVICE REMARKS	--
290178	INSPECT/LUBRICATE NO. 2 HYDRAULIC PUMP NO.2 ENGINE HYDRAULIC PUMP SPLINES								
	MOS	1/17/2001				TECH :		INSP :	
	HRS	7494						LABOR HRS :	
	AFL	5466						SERVICE REMARKS	--
CHAPTER 30-ICE AND RAIN PROTECTION									
300147	INSPECT PILOT WINDSHIELD CYCLING CONTACTOR								
	MOS	1/17/2001				TECH :		INSP :	
	HRS	7494						LABOR HRS :	
	AFL	5466						SERVICE REMARKS	--
300150	INSPECT COPILOT WINDSHIELD CYCLING CONTACTOR								
	MOS	1/17/2001				TECH :		INSP :	
	HRS	7494						LABOR HRS :	
	AFL	5466						SERVICE REMARKS	--
300163	INSPECT WINDSHIELD WIPER ASSEMBLY								
	MOS	1/17/2001				TECH :		INSP :	
	HRS	7494						LABOR HRS :	
	AFL	5466						SERVICE REMARKS	--
300170	OPERATIONAL TEST P2T2 SENSOR HEATER								
	MOS	1/17/2001				TECH :		INSP :	
	HRS	7494						LABOR HRS :	
	AFL	5466						SERVICE REMARKS	--
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN								
	MOS	1/17/2001				TECH :		INSP :	
	HRS	7494						LABOR HRS :	
	AFL	5466						SERVICE REMARKS	--
CHAPTER 32-LANDING GEAR									
320106	LUBRICATE NOSE GEAR ASSEMBLY NOSE GEAR/DOORS								
	MOS	1/17/2001				TECH :		INSP :	
	HRS	7494						LABOR HRS :	
	AFL	5466						SERVICE REMARKS	--
320156	INSPECT/CLEAN/LUBRICATE NOSE GEAR LEFT WHEEL BEARINGS								

A/C Serial No.: 368 A/C Regn No.: N368MD Model:1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

Report Date **14-MAR-2002**

Compliance

From 01/01/2001

To 3/14/2002

ITEM NO PART NO.	DESCRIPTION SERIAL NO.	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED				COMPONENT TIMES AFTER REMOVAL				TECH :	INSP :	LABOR HRS :	SERVICE REMARKS
		C/W	TSN	TSO	TSR	C/W	TSN	TSO	TSR				
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
320158	INSPECT/CLEAN/LUBRICATE NOSE GEAR RIGHT WHEEL BEARINGS												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
320201	INSPECT NOSE GEAR (A)												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
320606	LUBRICATE LEFT MAIN GEAR ASSEMBLY LEFT MAIN GEAR												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
320676	INSPECT/LUBRICATE LEFT MAIN GEAR INBOARD WHEEL HALF LEFT MAIN GEAR INBOARD WHEEL BEARINGS												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
320680	INSPECT/LUBRICATE LEFT MAIN GEAR OUTBOARD WHEEL HALF LEFT MAIN GEAR OUTBOARD WHEEL BEARINGS												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
320691	INSPECT LEFT MAIN GEAR/WELL (A)												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
321106	LUBRICATE RIGHT MAIN GEAR ASSEMBLY RIGHT MAIN GEAR												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
321176	INSPECT/LUBRICATE RIGHT MAIN GEAR INBOARD WHEEL HALF RIGHT MAIN GEAR INBOARD WHEEL BEARINGS												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
321180	INSPECT/LUBRICATE RIGHT MAIN GEAR OUTBOARD WHEEL HALF RIGHT MAIN GEAR OUTBOARD WHEEL BEARINGS												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
321191	INSPECT RIGHT MAIN GEAR OUTBOARD WHEEL HALF RIGHT MAIN GEAR/WELL (A)												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
322113	CHANGE LEFT MAIN GEAR BRAKE												
5002805-3	12153-6												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
322116	INSPECT/CHECK LEFT MAIN GEAR BRAKE LEFT BRAKE LININGS												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
322128	CHANGE RIGHT MAIN GEAR BRAKE												

A/C Serial No.: 368 A/C Regn No.: N368MD Model:1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

Report Date 14-MAR-2002

Compliance

From 01/01/2001

To 3/14/2002

ITEM NO PART NO.	DESCRIPTION SERIAL NO.	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED				COMPONENT TIMES AFTER REMOVAL				TECH :	REASON :	INSP :	LABOR HRS :	PRICE :
		C/W	TSN	TSO	TSR	C/W	TSN	TSO	TSR					
5002805-3	1140	MOS				1/17/2001								
		HRS												
		AFL												
322131	INSPECT/CHECK RIGHT MAIN GEAR BRAKE RIGHT BRAKE LININGS	MOS				1/17/2001								
		HRS												
		AFL												
322156	INSPECT/CLEAN LEFT ANTI-SKID DETECTOR	MOS				1/17/2001								
		HRS												
		AFL												
322171	INSPECT/CLEAN RIGHT ANTI-SKID DETECTOR	MOS				1/17/2001								
		HRS												
		AFL												
322174	OPERATIONAL CHECK ANTI-SKID LIGHTS	MOS				1/17/2001								
		HRS												
		AFL												
322206	FUNCTIONAL TEST EMERGENCY GEAR EXTENSION CONTROL CABLE	MOS				1/17/2001								
		HRS												
		AFL												
CHAPTER 33-LIGHTS														
330228	CHARGE EMERGENCY LIGHT BATTERY	MOS				6/26/2001								
		HRS												
		AFL												
CHAPTER 34-NAVIGATION														
340121	DRAIN PITOT/STATIC SYSTEM	MOS				1/17/2001								
		HRS												
		AFL												
344616	INSPECT EMERGENCY GYRO POWER SUPPLY BATTERY EMERGENCY POWER SUPPLY BATTERY/STAND-BY ATTITUDE GYRO	MOS				6/26/2001								
		HRS												
		AFL												
CHAPTER 52-DOORS														
520106	INSPECT/LUBRICATE CABIN ENTRANCE DOOR	MOS				1/17/2001								
		HRS												
		AFL												
520116	OPERATIONAL CHECK CABIN ENTRANCE DOOR	MOS				1/17/2001								
		HRS												
		AFL												
CHAPTER 53-FUSELAGE														
530101	INSPECT FUSELAGE (A)	MOS				1/17/2001								
		HRS												
		AFL												

A/C Serial No.: 368 A/C Regn No.: N368MD Model:1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

Report Date **14-MAR-2002**

Compliance From 01/01/2001 To 3/14/2002

ITEM NO PART NO.	DESCRIPTION SERIAL NO.	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED				COMPONENT TIMES AFTER REMOVAL				TECH :	INSP :	LABOR HRS :	SERVICE REMARKS
		C/W	TSN	TSO	TSR	C/W	TSN	TSO	TSR				
530116	INSPECT NOSE COMPARTMENT (A)	MOS	1/17/2001										
		HRS	7494										
		AFL	5466									--	
530131	INSPECT COCKPIT (A)	MOS	1/17/2001										
		HRS	7494										
		AFL	5466									--	
530146	INSPECT CABIN (A)	MOS	1/17/2001										
		HRS	7494										
		AFL	5466									--	
530161	INSPECT REAR COMPARTMENT (A)	MOS	1/17/2001										
		HRS	7494										
		AFL	5466									--	
CHAPTER 54-NACELLES/PYLONS													
540101U	INSPECT NO. 1 ENGINE NACELLE/PYLON (A)	MOS	1/17/2001										
		HRS	7494										
		AFL	5466									--	
540121U	INSPECT NO. 2 ENGINE NACELLE/PYLON (A)	MOS	1/17/2001										
		HRS	7494										
		AFL	5466									--	
CHAPTER 55-STABILIZERS													
550101	INSPECT EMPENNAGE (A)	MOS	1/17/2001										
		HRS	7494										
		AFL	5466									--	
550656	CHECK HORIZONTAL STABILIZER AFT SPAR SPLICE-HINGE FITTING OUTBOARD LUGS FOR CRACKS	MOS	1/17/2001										
		HRS	7494										
		AFL	5466									--	
CHAPTER 57-WINGS													
570101	INSPECT LEFT WING (A)	MOS	1/17/2001										
		HRS	7494										
		AFL	5466									--	
570106	INSPECT LEFT AILERON BELLCRANK	MOS	1/17/2001										
		HRS	7494										
		AFL	5466									--	
570116	INSPECT RIGHT WING (A)	MOS	1/17/2001										
		HRS	7494										
		AFL	5466									--	
570120	INSPECT RIGHT AILERON BELLCRANK	MOS	1/17/2001										
		HRS	7494										
		AFL	5466									--	

A/C Serial No.: 368 A/C Regn No.: N368MD Model:1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

Report Date **14-MAR-2002**

Compliance

From 01/01/2001

To 3/14/2002

ITEM NO PART NO.	DESCRIPTION SERIAL NO.	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED				COMPONENT TIMES AFTER REMOVAL				
		C/W	TSN	TSO	TSR	C/W	TSN	TSO	TSR	
CHAPTER 71-POWER PLANT										
710650U	-- INSP #1 ENG INLET NACELLE									
		MOS	1/17/2001						TECH :	INSP :
		HRS	7494							LABOR HRS :
		AFL	5466							SERVICE REMARKS --
713650U	-- INSP #2 ENG INLET NACELLE									
		MOS	1/17/2001						TECH :	INSP :
		HRS	7494							LABOR HRS :
		AFL	5466							SERVICE REMARKS --

Aircraft Model - 1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

MASTER & C/W
THE FOLLOWING INFORMATION IS ACCURATE AND CURRENT TO THE BEST KNOWLEDGE AND ABILITY OF CSI
HOWEVER, CAMP SHALL NOT BE RESPONSIBLE OR LIABLE FOR ANY ERRORS CONTAINED IN THIS REPORT.

ITEM NO	EFFECTIVE DATE	TASK DESCRIPTION	C/W Date	DISPOSITION
		METHOD OF COMPLIANCE		
AIRCRAFT				
AD	1972-19-04	AIRWORTHINESS DIRECTIVE TO PREVENT A POSSIBLE BATTERY FIRE THAT MAY RESULT FROM OVERHEATING CAUSED BY AN UNDETECTED BATTERY FAILURE	No Data	
		OPEN		
AD	1974-08-09 R2	AIRWORTHINESS DIRECTIVE TO PREVENT POSSIBLE FIRES THAT COULD RESULT FROM SMOKING MATERIALS BEING DROPPED INTO LAVATORY PAPER OR LINEN WASTE RECEPTACLES	01/17/2001	
		REPEAT OPEN		
AD	1980-01-05 R1	AIRWORTHINESS DIRECTIVE TO PREVENT FAILURE TO OPEN OF THE FLIGHT CREW AND ATTENDANTS' SEAT BELTS	No Data	
		OPEN		
AD	1980-18-08	AIRWORTHINESS DIRECTIVE TO PREVENT LOSS OF EMERGENCY ELECTRICAL POWER AND POSSIBLE CORROSIVE OR THERMAL DAMAGE TO THE AIRCRAFT	No Data	
		OPEN		
AD	1980-19-15	AIRWORTHINESS DIRECTIVE TO PREVENT THE UPPER HOT LIQUID CONTAINER IN THE GALLEY FROM RUBBING AGAINST THE ELECTRICAL WIRE BUNDLE AND CAUSING A FIRE WHICH COULD RESULT IN THE LOSS OF THRUST REVERSERS, FLAPS, SPOILERS, AND SOME AIRPLANE LIGHTS	No Data	
		OPEN		
AD	1980-19-19	AIRWORTHINESS DIRECTIVE TO PREVENT POSSIBLE CONFLICT WITH OTHER IFR TRAFFIC	No Data	
		OPEN		
AD	1981-01-08	AIRWORTHINESS DIRECTIVE TO PRECLUDE THE POSSIBILITY OF STRUCTURAL FAILURE OF THE 25 PERCENT WING SPAR	No Data	
		OPEN		
AD	1981-07-07 PARA A	AIRWORTHINESS DIRECTIVE TO PREVENT FIRE DUE TO OVERHEATING OF THE INTERCOM SYSTEM	No Data	
		OPEN		
AD	1981-07-07 PARA B	AIRWORTHINESS DIRECTIVE TO PREVENT FIRE DUE TO OVERHEATING OF THE INTERCOM SYSTEM	No Data	
		OPEN		
AD	1981-21-05	AIRWORTHINESS DIRECTIVE APPLIES TO ARTEX REPLACEMENT BATTERY PACKS, P/N 00-21-006, WHICH ARE DESIGNED FOR USE IN THE EMERGENCY BEACON CORPORATION EMERGENCY LOCATOR TRANSMITTER.	No Data	
		OPEN		
AD	1984-02-08	AIRWORTHINESS DIRECTIVE TO PREVENT POSSIBLE USE OF IMPROPERLY CHARGED OXYGEN CYLINDERS, BLEED DOWN (DISCHARGE) THE CYLINDERS, AND RECHARGE WITH AVIATOR'S BREATHING OXYGEN	No Data	
		OPEN		
AD	1984-18-07	AIRWORTHINESS DIRECTIVE TO PREVENT HAZARDS IN FLIGHT ASSOCIATED WITH THE NON-OPERATION OF THE FIRE EXTINGUISHER CAUSED BY NON-FIRING OF THE DISCHARGE CARTRIDGE(S)	No Data	
		OPEN		
AD	1985-26-03	AIRWORTHINESS DIRECTIVE TO PREVENT THE BLOCKAGE OF OXYGEN FLOW DUE TO INCOMPLETELY DRILLED OXYGEN CONNECTORS	No Data	
		OPEN		
AD	1986-14-02	AIRWORTHINESS DIRECTIVE SUPERSEDED BY AD1989-12-08	No Data	
		OPEN		
AD	1986-22-10	AIRWORTHINESS DIRECTIVE TO PREVENT DISPLAY OF ERRONEOUS DME-42 INFORMATION	No Data	
		OPEN		
AD	1986-25-01	AIRWORTHINESS DIRECTIVE TO PREVENT DEVIATION OUTPUT SIGNAL OSCILLATION THAT MAY CAUSE UNDETECTED ERRONEOUS VOR AND ILS LOCALIZER DEVIATION DISPLAY, FLIGHT DIRECTOR COMMANDS, AND/OR AUTOPILOT TRACKING	No Data	
		OPEN		

Aircraft Model - 1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

MASTER & C/W
THE FOLLOWING INFORMATION IS ACCURATE AND CURRENT TO THE BEST KNOWLEDGE AND ABILITY OF CSI
HOWEVER, CAMP SHALL NOT BE RESPONSIBLE OR LIABLE FOR ANY ERRORS CONTAINED IN THIS REPORT.

ITEM NO	EFFECTIVE DATE	METHOD OF COMPLIANCE	TASK DESCRIPTION	C/W Date	DISPOSITION
AD	1987-06-09		AIRWORTHINESS DIRECTIVE TO PREVENT POSSIBLE LOSS OF ESSENTIAL EQUIPMENT, ELECTRICAL FIRE, OR ELECTRICAL SHOCK HAZARD ON AIRCRAFT	No Data	
		OPEN			
AD	1987-16-07		AIRWORTHINESS DIRECTIVE TO ELIMINATE ERRONEOUS DISPLAY OF THE ANGLE OF ATTACK FAST/SLOW PRESENTATION	No Data	
		OPEN			
AD	1987-17-06		AIRWORTHINESS DIRECTIVE TO ELIMINATE RESTRAINT SYSTEM CONNECTORS WITH THE INCORRECT DIMENSIONS, WHICH COULD ALLOW INADVERTENT OPENING OF OCCUPANT RESTRAINT SYSTEM ASSEMBLIES	No Data	
		OPEN			
AD	1987-20-05		AIRWORTHINESS DIRECTIVE TO ELIMINATE LAP BELT ASSEMBLIES WITH BELT RETRACTOR SHAFTS WHICH DO NOT PROVIDE ADEQUATE STRENGTH	No Data	
		OPEN			
AD	1989-02-10 R1		AIRWORTHINESS DIRECTIVE TO PREVENT FMS POSITION JUMPS WHILE CROSSING THE 180 DEGREE MERIDIAN	No Data	
		OPEN			
AD	1989-09-02		AIRWORTHINESS DIRECTIVE TO PREVENT THE POSSIBILITY OF THE APPLICABLE SAFETY-BELTS FROM BECOMING DIFFICULT TO RELEASE OR BECOMING COMPLETELY JAMMED WHEN ACTUATED THROUGH 90 DEGREES	No Data	
		OPEN			
AD	1989-12-08		AIRWORTHINESS DIRECTIVE TO DETECT CRACKS IN THE HINGE LUGS OF THE HORIZONTAL STABILIZER AFT SPAR SPLICE FITTING (HINGE ASSEMBLY)	01/17/2001	
		REPEAT OPEN			
AD	1989-20-06		AIRWORTHINESS DIRECTIVE TO PREVENT FMS NAVIGATION ERRORS CAUSED BY AN ERRONEOUS OMEGA/VLF SENSOR	No Data	
		OPEN			
AD	1990-03-02		AIRWORTHINESS DIRECTIVE SUPERSEDED BY AD1990-06-13	No Data	
		OPEN			
AD	1990-07-08 R1		AIRWORTHINESS DIRECTIVE TO PREVENT SMOKE, FIRE, AND POSSIBLE ELECTRICAL SHOCK, OR ELECTROMAGNETIC INTERFERENCE TO FLIGHT CRITICAL OR ESSENTIAL SYSTEMS	No Data	
		OPEN			
AD	1990-10-04 LEFT AILERON		AIRWORTHINESS DIRECTIVE SUPERSEDED BY AD1992-12-02	No Data	
		OPEN			
AD	1990-10-04 RIGHT AILERON		AIRWORTHINESS DIRECTIVE SUPERSEDED BY AD1992-12-02	No Data	
		OPEN			
AD	1990-14-06		AIRWORTHINESS DIRECTIVE SUPERSEDED BY AD1995-22-01	No Data	
		OPEN			
AD	1991-13-08		AIRWORTHINESS DIRECTIVE TO PREVENT THE INABILITY TO EXTEND THE NOSE LANDING GEAR FOR LANDING	No Data	
		OPEN			
AD	1992-12-02 LEFT AILERON		AIRWORTHINESS DIRECTIVE TO PREVENT REDUCED CONTROLLABILITY OF THE AIRPLANE	No Data	
		OPEN			
AD	1992-12-02 RIGHT AILERON		AIRWORTHINESS DIRECTIVE TO PREVENT REDUCED CONTROLLABILITY OF THE AIRPLANE	No Data	
		OPEN			
AD	1993-04-02 PARA A		AIRWORTHINESS DIRECTIVE TO PREVENT A MID-AIR COLLISION OR A NEAR-MISS SITUATION CAUSED BY FAILURE OF THESE MODE S TRANSPONDERS	No Data	
		OPEN			
AD	1993-04-02 PARA B		AIRWORTHINESS DIRECTIVE TO PREVENT A MID-AIR COLLISION OR A NEAR-MISS SITUATION CAUSED BY FAILURE OF THESE MODE S TRANSPONDERS	No Data	
		OPEN			
AD	1994-21-06		AIRWORTHINESS DIRECTIVE TO PREVENT THE INABILITY OF PASSENGERS OR CREW TO EGRESS FROM THEIR SEATS DURING AN EMERGENCY SITUATION, DUE TO PROBLEMS ASSOCIATED WITH THE LAP BELT ASSEMBLY	No Data	
		OPEN			

Aircraft Model - 1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date **14-MAR-2002**

MASTER & C/W
THE FOLLOWING INFORMATION IS ACCURATE AND CURRENT TO THE BEST KNOWLEDGE AND ABILITY OF CSI
HOWEVER, CAMP SHALL NOT BE RESPONSIBLE OR LIABLE FOR ANY ERRORS CONTAINED IN THIS REPORT.

ITEM NO	EFFECTIVE DATE	TASK DESCRIPTION	C/W Date	DISPOSITION
		METHOD OF COMPLIANCE		
AD	1995-22-01	AIRWORTHINESS DIRECTIVE TO PREVENT SMOKE, FIRE, ELECTRICAL SHOCK, AND POSSIBLE ELECTROMAGNETIC INTERFERENCE CAUSED BY HIGH VOLTAGE ARCING IN THE CABIN WHICH, IF UNDETECTED, COULD RESULT IN PERSONAL HAZARD OR LOSS OF THE AIRCRAFT	No Data	
		OPEN		
AD	1996-24-11 LEFT AILERON	AIRWORTHINESS DIRECTIVE TO PREVENT EXCESSIVE WEAR OF THE AILERON PUSH-PULL TUBE, WHICH COULD RESULT IN UNEVEN MOVEMENT OF THE CONTROL WHEEL, PERFORATION OF THE AILERON PUSH-PULL TUBE, AND CONSEQUENT REDUCED ROLL CONTROL OF THE AIRPLANE	07/26/2000	
		REPEAT OPEN		
SB	1124-27-129 LEFT AILERON	FLIGHT CONTROLS SERVICE BULLETIN	07/26/2000	
		REPEAT OPEN		
AD	1996-24-11 RIGHT AILERON	AIRWORTHINESS DIRECTIVE TO PREVENT EXCESSIVE WEAR OF THE AILERON PUSH-PULL TUBE, WHICH COULD RESULT IN UNEVEN MOVEMENT OF THE CONTROL WHEEL, PERFORATION OF THE AILERON PUSH-PULL TUBE, AND CONSEQUENT REDUCED ROLL CONTROL OF THE AIRPLANE	07/26/2000	
		REPEAT OPEN		
SB	1124-27-129 RIGHT AILERON	FLIGHT CONTROLS SERVICE BULLETIN	07/26/2000	
		REPEAT OPEN		
AD	1997-05-03 R1	AIRWORTHINESS DIRECTIVE TO PREVENT DEVIATION FROM AN INTENDED FLIGHT PATH DURING A NON-PRECISION APPROACH TO AN AIRPORT CAUSED BY INACCURATE INFORMATION FROM THE GPS FLIGHT MANAGEMENT SYSTEM	No Data	MANDATORY
		OPEN		
AD	1997-11-10	AIRWORTHINESS DIRECTIVE TO PREVENT RESTRICTED OXYGEN FLOW, WHICH, IF NOT CORRECTED, COULD CAUSE SERIOUS INJURY TO A PASSENGER IN NEED OF EMERGENCY OR FIRST AID OXYGEN DURING FLIGHT	No Data	
		OPEN		
AD	1998-05-09	AIRWORTHINESS DIRECTIVE 98-20-35 ISRAEL AIRCRAFT INDUSTRIES (IAI), LTD.: AMENDMENT 39-10802. DOCKET 98-NM-108-AD. SUPERSEDES AD 98-05-09, AMENDMENT 39-10370.	No Data	SUPERSEDED
		OPEN		
AD	1998-06-10	AIRWORTHINESS DIRECTIVE TO PREVENT FAILURE OF THE HYDRAULIC FUSE TO OPERATE PROPERLY IN THE EVENT OF AN EXTERNAL LEAK DOWNSTREAM OF THE FUSE, WHICH COULD RESULT IN LOSS OF HYDRAULIC SYSTEMS	11/06/2001	
		REPEAT OPEN		
AD	1998-20-35 PART 1	AIRWORTHINESS DIRECTIVE TO PREVENT FAILURE OF THE TRIM ACTUATOR OF THE HORIZONTAL STABILIZER DUE TO FAILURE OF THE JACKSCREWS, WHICH COULD RESULT IN REDUCED CONTROLLABILITY OF THE AIRPLANE	No Data	MANDATORY
		OPEN		
AD	1998-20-35 PART 2	AIRWORTHINESS DIRECTIVE TO PREVENT FAILURE OF THE TRIM ACTUATOR OF THE HORIZONTAL STABILIZER DUE TO FAILURE OF THE JACKSCREWS, WHICH COULD RESULT IN REDUCED CONTROLLABILITY OF THE AIRPLANE	No Data	MANDATORY
		OPEN		
AD	1998-25-10 R1	AIRWORTHINESS DIRECTIVE TO PREVENT FAILURE OF THE SEAT RESTRAINT SYSTEM DUE TO THE BUCKLE ASSEMBLY (BUCKLE) LOCKING MECHANISM NOT ENGAGING PROPERLY, WHICH COULD RESULT IN THE SEAT RESTRAINT SYSTEM FAILING TO PROPERLY SECURE THE OCCUPANT DURING TURBULENCE OR LANDING	No Data	MANDATORY
		OPEN		
AD	1999-18-80	AIRWORTHINESS DIRECTIVE TO PREVENT LOSS OF THE HYDRAULIC LOW PRESSURE WARNING LIGHTS WHICH COULD RESULT IN UNKNOWN LOW PRESSURE IN THE HYDRAULIC SYSTEM AND CONSEQUENT REDUCED CONTROLLABILITY OF THE AIRPLANE	No Data	
		OPEN		
AD	1999-23-22 R2	AIRWORTHINESS DIRECTIVE RESCISSION	No Data	
		OPEN		

Aircraft Model - 1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

MASTER & C/W
THE FOLLOWING INFORMATION IS ACCURATE AND CURRENT TO THE BEST KNOWLEDGE AND ABILITY OF CSI
HOWEVER, CAMP SHALL NOT BE RESPONSIBLE OR LIABLE FOR ANY ERRORS CONTAINED IN THIS REPORT.

ITEM NO	EFFECTIVE DATE	METHOD OF COMPLIANCE	TASK DESCRIPTION	C/W Date	DISPOSITION
AD	2000-10-04		AIRWORTHINESS DIRECTIVE TO PREVENT CRACKING OF THE AILERON SKIN DUE TO MISSING RIVETS, WHICH COULD RESULT IN REDUCED STRUCTURAL INTEGRITY OF THE AILERON AND CONSEQUENT REDUCED CONTROLLABILITY OF THE AIRPLANE AIRWORTHINESS DIRECTIVE	No Data	MANDATORY
SB	911450	OPEN	ASB 1124-27A-145 SERVICE BULLETIN	No Data	MANDATORY
AD	2000-10-04U	OPEN	AIRWORTHINESS DIRECTIVE TO PREVENT CRACKING OF THE AILERON SKIN DUE TO MISSING RIVETS, WHICH COULD RESULT IN REDUCED STRUCTURAL INTEGRITY OF THE AILERON AND CONSEQUENT REDUCED CONTROLLABILITY OF THE AIRPLANE	No Data	MANDATORY
AD	2000-15-09#1ENG	OPEN	AIRWORTHINESS DIRECTIVE	No Data	MANDATORY
AD	2000-15-09#2ENG	OPEN	AIRWORTHINESS DIRECTIVE	No Data	MANDATORY
AD	2000-21-03	OPEN	AIRWORTHINESS DIRECTIVE TO PREVENT THE CONTROL LINK OF THE AILERON AUTOPILOT SERVO FROM BEING DRIVEN OVERCENTER, WHICH COULD RESULT IN ROLL OSCILLATIONS WHEN THE AUTOPILOT IS ENGAGED	No Data	MANDATORY
AD	2000-23-13	OPEN	AIRWORTHINESS DIRECTIVE TO PREVENT JAMMING OR DISCONNECTION OF THE HORIZONTAL STABILIZER TRIM ACTUATOR, WHICH COULD RESULT IN REDUCED PITCH CONTROL OF THE AIRPLANE	No Data	MANDATORY
SB	911470	OPEN	ASB 1124-27A-147 SERVICE BULLETIN	No Data	MANDATORY
AD	2000-23-13U	OPEN	AIRWORTHINESS DIRECTIVE TO PREVENT JAMMING OR DISCONNECTION OF THE HORIZONTAL STABILIZER TRIM ACTUATOR, WHICH COULD RESULT IN REDUCED PITCH CONTROL OF THE AIRPLANE	No Data	MANDATORY
AD	2001-03-01	OPEN	AIRWORTHINESS DIRECTIVE TO PREVENT THE MAIN ENTRY DOOR FROM JAMMING, WHICH COULD IMPEDE THE SAFE EVACUATION OF PASSENGERS AND CREW DURING AN EMERGENCY	No Data	MANDATORY
AD	2001-03-01U	OPEN	AIRWORTHINESS DIRECTIVE TO PREVENT THE MAIN ENTRY DOOR FROM JAMMING, WHICH COULD IMPEDE THE SAFE EVACUATION OF PASSENGERS AND CREW DURING AN EMERGENCY	No Data	MANDATORY
AD	2002-01-26	OPEN	AIRWORTHINESS DIRECTIVE TO PREVENT FAILURE OF ATTACHMENT BOLTS DUE TO FATIGUE, WHICH COULD RESULT IN SEPARATION OF THE ENGINE INLET COWL AND AFT NACELLE, AND CONSEQUENT DAMAGE TO THE HORIZONTAL OR VERTICAL STABILIZER	No Data	MANDATORY
SB	07-MAR-02 ASB 1124-54A-138	OPEN	SERVICE BULLETIN	No Data	MANDATORY
AD	990010U		AIRWORTHINESS DIRECTIVE AD72-19-04	02/03/1982	
AD	990025	OPEN	AIRWORTHINESS DIRECTIVE AD75-07-10	No Data	
AD	990027	OPEN	AIRWORTHINESS DIRECTIVE AD78-22-10	No Data	
AD	990040U	OPEN	AIRWORTHINESS DIRECTIVE AD80-01-05R1	No Data	
AD	990045	OPEN	AIRWORTHINESS DIRECTIVE AD80-16-04	No Data	
AD	990045U	NOT APPLICABLE N/A	AIRWORTHINESS DIRECTIVE AD80-16-04	08/07/1980	

Aircraft Model - 1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

MASTER & C/W
THE FOLLOWING INFORMATION IS ACCURATE AND CURRENT TO THE BEST KNOWLEDGE AND ABILITY OF CSI
HOWEVER, CAMP SHALL NOT BE RESPONSIBLE OR LIABLE FOR ANY ERRORS CONTAINED IN THIS REPORT.

ITEM NO	EFFECTIVE DATE	TASK DESCRIPTION	METHOD OF COMPLIANCE	C/W Date	DISPOSITION
AD 990048U		AIRWORTHINESS DIRECTIVE AD80-18-08		02/05/1985	
			COMPLIED WITH C/W		
AD 990050U		AIRWORTHINESS DIRECTIVE AD80-19-15		09/11/1980	
			NOT APPLICABLE N/A		
AD 990060U		AIRWORTHINESS DIRECTIVE AD80-19-19		No Data	
AD 990065U		AIRWORTHINESS DIRECTIVE AD81-01-08		No Data	
AD 990070U		AIRWORTHINESS DIRECTIVE AD81-07-07 PARA A		01/03/1985	
			NOT APPLICABLE N/A		
AD 990075U		AIRWORTHINESS DIRECTIVE AD81-07-07 PARA B		01/03/1985	
			NOT APPLICABLE N/A		
AD 990080U		AIRWORTHINESS DIRECTIVE AD81-21-05		No Data	
AD 990085U		AIRWORTHINESS DIRECTIVE AD81-24-08 #1 ENGINE		07/12/1991	
			NOT APPLICABLE N/A		
AD 990090U		AIRWORTHINESS DIRECTIVE AD81-24-08 #2 ENGINE		01/06/1982	
			NOT APPLICABLE N/A		
AD 990095		AIRWORTHINESS DIRECTIVE TO PREVENT A FALSE INDICATION, THAT EMERGENCY POWER IS AVAILABLE		No Data	
			OPEN		
AD 990100U		AIRWORTHINESS DIRECTIVE AD84-02-08		04/10/1990	
			NOT APPLICABLE N/A		
AD 990105U		AIRWORTHINESS DIRECTIVE AD84-18-07		No Data	
AD 990120U		AIRWORTHINESS DIRECTIVE AD86-03-01 #1 ENGINE		07/28/1986	
			NOT APPLICABLE N/A		
AD 990121U		AIRWORTHINESS DIRECTIVE AD86-03-01 #2 ENGINE		No Data	
			OPEN		
AD 990130U		AIRWORTHINESS DIRECTIVE AD86-14-02		01/20/1989	
AD 990140U		AIRWORTHINESS DIRECTIVE AD86-22-10		No Data	
AD 990145U		AIRWORTHINESS DIRECTIVE AD86-25-01		No Data	
AD 990150U		AIRWORTHINESS DIRECTIVE AD87-16-07		No Data	
AD 990155U		AIRWORTHINESS DIRECTIVE AD87-17-06		No Data	
AD 990160U		AIRWORTHINESS DIRECTIVE AD87-20-05		No Data	
AD 990165U		AIRWORTHINESS DIRECTIVE AD88-18-03 #1 ENGINE		01/20/1989	
			COMPLIED WITH C/W		
AD 990166U		AIRWORTHINESS DIRECTIVE AD88-18-03 #2 ENGINE		01/20/1989	
			COMPLIED WITH C/W		
AD 990821U		AIRWORTHINESS DIRECTIVE AD82-23-03 R1 #1 ENGINE		11/13/1999	
			NOT APPLICABLE N/A		
AD 990822U		AIRWORTHINESS DIRECTIVE AD82-23-03 R1 #2 ENGINE		05/17/1989	
AD 990960U		AIRWORTHINESS DIRECTIVE AD89-02-10R1		No Data	
			NOT APPLICABLE N/A		

Aircraft Model - 1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

MASTER & C/W
THE FOLLOWING INFORMATION IS ACCURATE AND CURRENT TO THE BEST KNOWLEDGE AND ABILITY OF CSI
HOWEVER, CAMP SHALL NOT BE RESPONSIBLE OR LIABLE FOR ANY ERRORS CONTAINED IN THIS REPORT.

ITEM NO	EFFECTIVE DATE	TASK DESCRIPTION	METHOD OF COMPLIANCE	C/W Date	DISPOSITION
AD 990970U		AIRWORTHINESS DIRECTIVE	AD89-20-06	No Data	
AD 990980U		AIRWORTHINESS DIRECTIVE	AD90-03-02	03/21/1990	
AD 990982U		NOT APPLICABLE N/A			
AD 990983U		AIRWORTHINESS DIRECTIVE	AD90-03-04 #1 ENGINE	03/21/1990	
AD 990983U		NOT APPLICABLE N/A			
AD 990983U		AIRWORTHINESS DIRECTIVE	AD90-03-04 #2 ENGINE	03/21/1990	
AD 990985U		NOT APPLICABLE N/A			
AD 990985U		AIRWORTHINESS DIRECTIVE	AD90-10-04 LEFT AILERON	11/01/1992	
AD 990986U		NOT APPLICABLE N/A			
AD 990986U		AIRWORTHINESS DIRECTIVE	AD90-10-04 RIGHT AILERON	11/01/1992	
AD 990987U		NOT APPLICABLE N/A			
AD 990987U		AIRWORTHINESS DIRECTIVE	AD90-14-06	06/19/1991	
AD 990988U		COMPLIED WITH C/W			
AD 990988U		AIRWORTHINESS DIRECTIVE	AD90-07-08R1	07/11/1990	
AD 991020U		NOT APPLICABLE N/A			
AD 991020U		AIRWORTHINESS DIRECTIVE	AD91-08-13 #1 ENGINE	04/26/1994	
AD 991030U		AIRWORTHINESS DIRECTIVE	AD91-08-13 #2 ENGINE	05/31/1993	
AD 991040U		AIRWORTHINESS DIRECTIVE	AD91-13-08	11/09/1996	
AD 991065U		COMPLIED WITH C/W			
AD 991065U		AIRWORTHINESS DIRECTIVE	AD92-12-09 #1 ENGINE	06/23/1992	
AD 991070U		COMPLIED WITH C/W			
AD 991070U		AIRWORTHINESS DIRECTIVE	AD92-12-02 LEFT AILERON	11/01/1992	
AD 991071U		COMPLIED WITH C/W			
AD 991071U		AIRWORTHINESS DIRECTIVE	AD92-12-02 RIGHT AILERON	11/01/1992	
AD 991090U		COMPLIED WITH C/W			
AD 991090U		AIRWORTHINESS DIRECTIVE	AD92-26-09 #1 ENGINE	09/30/1993	
AD 991091U		NOT APPLICABLE N/A			
AD 991091U		AIRWORTHINESS DIRECTIVE	AD92-26-09 #2 ENGINE	04/26/1994	
AD 991100U		NOT APPLICABLE N/A			
AD 991100U		AIRWORTHINESS DIRECTIVE	AD93-04-02 PARA A	04/19/1993	
AD 991105U		NOT APPLICABLE N/A			
AD 991105U		AIRWORTHINESS DIRECTIVE	AD93-04-02 PARA B	04/19/1993	
AD 991115U		NOT APPLICABLE N/A			
AD 991115U		AIRWORTHINESS DIRECTIVE	AD93-10-10 #1 ENGINE	09/29/1993	SUPERSEDED
AD 991120U		OPEN			
AD 991120U		AIRWORTHINESS DIRECTIVE	AD93-10-10 #2 ENGINE	09/29/1993	SUPERSEDED
AD 991350U		OPEN			
AD 991350U		AIRWORTHINESS DIRECTIVE	AD93-25-16 #1 ENGINE	04/26/1994	
AD 991351U		NOT APPLICABLE N/A			
AD 991351U		AIRWORTHINESS DIRECTIVE	AD93-25-16 #2 ENGINE	03/07/1994	
AD 991370		NOT APPLICABLE N/A			
AD 991370		AIRWORTHINESS DIRECTIVE	AD94-07-03 PARA A	No Data	
AD 991370U		OPEN			
AD 991370U		AIRWORTHINESS DIRECTIVE	AD94-07-03 PARA A	07/27/1994	
AD 991400U		NOT APPLICABLE N/A			
AD 991400U		AIRWORTHINESS DIRECTIVE	AD94-21-06	02/21/1995	
		NOT APPLICABLE N/A			

Aircraft Model - 1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

MASTER & C/W
THE FOLLOWING INFORMATION IS ACCURATE AND CURRENT TO THE BEST KNOWLEDGE AND ABILITY OF CSI
HOWEVER, CAMP SHALL NOT BE RESPONSIBLE OR LIABLE FOR ANY ERRORS CONTAINED IN THIS REPORT.

ITEM NO	EFFECTIVE DATE	TASK DESCRIPTION	C/W Date	DISPOSITION
		METHOD OF COMPLIANCE		
AD 991510U		AIRWORTHINESS DIRECTIVE AD95-22-01 COMPLIED WITH C/W	07/26/2000	
AD 991570U		AIRWORTHINESS DIRECTIVE AD97-05-03R1 NOT APPLICABLE N/A	06/16/1997	
AD 991580U		AIRWORTHINESS DIRECTIVE AD97-04-03 #1 ENGINE NOT APPLICABLE N/A	10/17/1998	
AD 991581U		AIRWORTHINESS DIRECTIVE AD97-04-03 #2 ENGINE NOT APPLICABLE N/A	10/17/1998	
AD 991590U		AIRWORTHINESS DIRECTIVE AD97-11-10 NOT APPLICABLE N/A	10/17/1998	
AD 991610U		AIRWORTHINESS DIRECTIVE AD98-05-09 OPEN	10/17/1998	SUPERSEDED
AD 991620U		AIRWORTHINESS DIRECTIVE AD98-17-01 R1 L/E NOT APPLICABLE N/A	10/06/1998	MANDATORY
AD 991625U		AIRWORTHINESS DIRECTIVE AD98-17-01 R1 R/E NOT APPLICABLE N/A	10/06/1998	MANDATORY
AD 991634U		AIRWORTHINESS DIRECTIVE AD98-20-35 PART 1 OPEN	04/07/1998	
AD 991635U		AIRWORTHINESS DIRECTIVE AD98-20-35 PART 2 COMPLIED WITH C/W	04/06/1998	MANDATORY
AD 991640U		AIRWORTHINESS DIRECTIVE AD98-25-10 OPEN	04/07/1999	MANDATORY
AD 991645U		AIRWORTHINESS DIRECTIVE AD98-25-02 OPEN	04/07/1999	MANDATORY
AD 991755U		AIRWORTHINESS DIRECTIVE AD99-08-21 OPEN	10/27/1999	MANDATORY
AD 991765U		AIRWORTHINESS DIRECTIVE AD99-18-08 OPEN	10/17/1998	
AD 991770U		AIRWORTHINESS DIRECTIVE AD99-23-22 R2	02/22/2000	
AD 991775U		AIRWORTHINESS DIRECTIVE AD98-25-10 R1 OPEN	02/22/2000	MANDATORY
AD 991845U		AIRWORTHINESS DIRECTIVE AD2000-23-13	01/17/2001	MANDATORY
AD 991850U		AIRWORTHINESS DIRECTIVE AD2001-03-01	11/06/2001	MANDATORY
AD 991855U		AIRWORTHINESS DIRECTIVE AD2001-15-17	11/06/2001	MANDATORY
ASB 1124-78A-134		ALERT SERVICE BULLETIN THRUST REVERSER OPEN	No Data	MANDATORY
SB 1124-27-100 R2 L/H RODS		SERVICE BULLETIN FLIGHT CONTROLS OPEN	No Data	
SB 1124-27-100 R2 R/H RODS		SERVICE BULLETIN FLIGHT CONTROLS OPEN	No Data	
SB 1124-27-129 LEFT AILERON		SERVICE BULLETIN FLIGHT CONTROLS REPEAT OPEN	07/26/2000	
SB 1124-27-129 RIGHT AILERON		SERVICE BULLETIN FLIGHT CONTROLS REPEAT OPEN	07/26/2000	
SB 1124-27-133 R1		SERVICE BULLETIN FLIGHT CONTROLS OPEN	No Data	MANDATORY

Aircraft Model - 1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

MASTER & C/W
THE FOLLOWING INFORMATION IS ACCURATE AND CURRENT TO THE BEST KNOWLEDGE AND ABILITY OF CSI
HOWEVER, CAMP SHALL NOT BE RESPONSIBLE OR LIABLE FOR ANY ERRORS CONTAINED IN THIS REPORT.

ITEM NO	EFFECTIVE DATE	METHOD OF COMPLIANCE	TASK DESCRIPTION	C/W Date	DISPOSITION
SB 1124-30-036 PART II		REPEAT OPEN	SERVICE BULLETIN ICE AND RAIN PROTECTION	06/26/2001	
SB 1124-55-020 R2		REPEAT OPEN	SERVICE BULLETIN STABILIZERS	06/26/2001	
SB 1124-55-021 R3		OPEN	SERVICE BULLETIN STABILIZERS	No Data	
SB 1124-55-097		OPEN	SERVICE BULLETIN STABILIZER SCISSR	No Data	
SB 1124-71-091 R2 #1 ENG		OPEN	SERVICE BULLETIN INSPECT ENG MOUNT FASTENERS	No Data	
SB 1124-71-091 R2 #2 ENGINE		OPEN	SERVICE BULLETIN INSPECT ENG MOUNT FASTENERS	No Data	
SB 1124-79-093 PART A		OPEN	SERVICE BULLETIN OIL	No Data	
SB 900280 30-JAN-02		OPEN	SERVICE BULLETIN SB WW 24-28A	02/22/2000	
SB 910100U		NOT APPLICABLE N/A	SERVICE BULLETIN SB1124-27-100R2 L/H RODS	11/01/1992	
SB 910101U			SERVICE BULLETIN SB1124-27-100R2 R/H RODS	11/01/1992	
SB 910210U			SERVICE BULLETIN SB1124-55-021 REV 3	10/13/1985	
SB 910911U		COMPLIED WITH C/W	SERVICE BULLETIN SB 1124-71-091 PART II	04/12/1989	
SB 910912U		COMPLIED WITH C/W	SERVICE BULLETIN SB 1124-71-091 PART II	05/31/1989	
SB 910970U		COMPLIED WITH C/W	SERVICE BULLETIN SB 1124-55-097STAB SCISSR	04/30/1990	
SB 911160U		NOT APPLICABLE N/A	SERVICE BULLETIN SB1124-32-116 L/G NW STR	06/01/1995	
SB 911190U		COMPLIED WITH C/W	SERVICE BULLETIN SB1124-26-119 FIRE EXTGHR	09/29/1993	
SB 911230U		COMPLIED WITH C/W	SERVICE BULLETIN SB1124-53-123 DRAIN/CABIN	10/26/1999	
SB 911320U		OPEN	SERVICE BULLETIN SB1124-29-132 HYD FUS TST	No Data	MANDATORY
SB 911330U		COMPLIED WITH C/W	SERVICE BULLETIN SB1124-27-133R1 INSP HORZ	11/09/1996	MANDATORY
SB 911340U		COMPLIED WITH C/W	SERVICE BULLETIN ASB1124-78A-134	10/26/1999	MANDATORY
SB 911360		OPEN	SERVICE BULLETIN SB1124-27-136 HORZ TRIM	No Data	MANDATORY
SB 911360U		OPEN	SERVICE BULLETIN SB1124-27-136 HORZ TRIM	04/07/1998	
SB 911380		OPEN	SERVICE BULLETIN ASB1124-54A-138	No Data	MANDATORY
SB 911380U		OPEN	SERVICE BULLETIN ASB1124-54A-138	11/06/2001	MANDATORY

Aircraft Model - 1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date **14-MAR-2002**

MASTER & C/W
THE FOLLOWING INFORMATION IS ACCURATE AND CURRENT TO THE BEST KNOWLEDGE AND ABILITY OF CSI
HOWEVER, CAMP SHALL NOT BE RESPONSIBLE OR LIABLE FOR ANY ERRORS CONTAINED IN THIS REPORT.

ITEM NO	EFFECTIVE DATE	METHOD OF COMPLIANCE	TASK DESCRIPTION	C/W Date	DISPOSITION
SB 911390		REPEAT OPEN	SERVICE BULLETIN SB1124-32-139 UPR STRG	07/26/2000	
SB 911391		OPEN	SERVICE BULLETIN SB1124-32-139 LWR STRG	No Data	
SB 911400U		COMPLIED WITH C/W	SERVICE BULLETIN ASB 1124-29A-140	10/06/1998	MANDATORY
SB 911420		OPEN	SERVICE BULLETIN ASB1124-30A-142	No Data	MANDATORY
SB 911450		OPEN	SERVICE BULLETIN ASB1124-27A-145	No Data	MANDATORY
SB 911470		OPEN	SERVICE BULLETIN ASB1124-27A-147	No Data	MANDATORY
SB 911470U		OPEN	SERVICE BULLETIN ASB1124-27A-147	01/17/2001	MANDATORY
SB 950035		OPEN	SERVICE BULLETIN SL-2406 R1 G.E. START GEN	No Data	
SB 950491		OPEN	SERVICE BULLETIN SL WW-2449R1 INSP ECU MT	No Data	
SB 950911		OPEN	SERVICE BULLETIN SL WW-2491 REV 1 NLG BRGS	No Data	
SB 950911U		OPEN	SERVICE BULLETIN SL WW-2491 REV 1 NLG BRGS	02/22/2000	
SB 950920		REPEAT OPEN	SERVICE BULLETIN SL WW-2492 HYD HOSE INSP	06/26/2001	
SB 950941		REPEAT OPEN	SERVICE BULLETIN SLWW-2494 REV 3 LMG BOLTS	06/26/2001	
SB 950942		REPEAT OPEN	SERVICE BULLETIN SLWW-2494 REV 3 RMG BOLTS	06/26/2001	
SB 951010		OPEN	SERVICE BULLETIN SLWW-24101 R1 LEFT SIDE	No Data	
SB 951011		OPEN	SERVICE BULLETIN SLWW-24101 R1 RIGHT SIDE	No Data	
SB 951030		OPEN	SERVICE BULLETIN SL WW-24103 L/H	No Data	
SB 951030U		OPEN	SERVICE BULLETIN SL WW-24103 L/H	08/15/1988	
SB 951031		OPEN	SERVICE BULLETIN SL WW-24103 R/H	No Data	
SB 951031U		OPEN	SERVICE BULLETIN SL WW-24103 R/H	08/15/1988	
SB 951060		OPEN	SERVICE BULLETIN SL WW-24106	No Data	
SB 951060U		OPEN	SERVICE BULLETIN SL WW-24106	No Data	
SB 960078		OPEN	SERVICE BULLETIN SIL1124-21-078 R2 35D SEN	No Data	
SB 960078U		OPEN	SERVICE BULLETIN SIL1124-21-078 R2 35D SEN	11/13/1995	

Aircraft Model - 1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

MASTER & C/W
THE FOLLOWING INFORMATION IS ACCURATE AND CURRENT TO THE BEST KNOWLEDGE AND ABILITY OF CSI
HOWEVER, CAMP SHALL NOT BE RESPONSIBLE OR LIABLE FOR ANY ERRORS CONTAINED IN THIS REPORT.

ITEM NO	EFFECTIVE DATE	TASK DESCRIPTION	C/W Date	DISPOSITION
		METHOD OF COMPLIANCE		
SB 971279U		SERVICE BULLETIN TFE731-72-3640 R3 ENG #1 NOT APPLICABLE N/A	11/13/1999	
SB 971280U		SERVICE BULLETIN TFE731-72-3640 R3 ENG #2	10/26/1999	RECOMMENDED
SB 972200U		SERVICE BULLETIN TFE731-A72-3388 LEFT ENG NOT APPLICABLE N/A	12/05/1989	
SB 972202U		SERVICE BULLETIN TFE731-A72-3388 RIGHT ENG NOT APPLICABLE N/A	12/05/1989	
SB 972655U		SERVICE BULLETIN GSBA72-3328 R5 LEFT ENG NOT APPLICABLE N/A	10/31/1995	
SB 972656U		SERVICE BULLETIN GSBA72-3328 R5 RIGHT ENG NOT APPLICABLE N/A	10/31/1995	
SB 972847U		SERVICE BULLETIN GSB TFE 731-A72-3432 L/H NOT APPLICABLE N/A	07/05/2000	
SB 972848U		SERVICE BULLETIN GSB TFE 731-A72-3432 R/H NOT APPLICABLE N/A	06/07/1991	
SB 972850U		SERVICE BULLETIN SB 731-A72-3668 #1 ENG	No Data	RECOMMENDED
SB 972851U		SERVICE BULLETIN SB 731-A72-3668 #2 ENG	No Data	RECOMMENDED
SB 972863U		SERVICE BULLETIN GSBA72-3432 R5 L/ENGINE	No Data	
SB 972864U		SERVICE BULLETIN GSBA72-3432 R5 R/ENGINE	No Data	
SB 972A03U		SERVICE BULLETIN G/SB72-3502 #1 ENGINE COMPLIED WITH C/W	05/31/1993	
SB 972A04U		SERVICE BULLETIN G/SB72-3502 #2 ENGINE COMPLIED WITH C/W	05/31/1993	
SB 972A07U		SERVICE BULLETIN G/SBA72-3504 L/ENG REV 1 NOT APPLICABLE N/A	02/25/1994	
SB 972A08U		SERVICE BULLETIN G/SBA72-3504 R/ENG REV 1 NOT APPLICABLE N/A	02/25/1994	
SB 972A87U		SERVICE BULLETIN SB TFE731-A72-3544 LH ENG NOT APPLICABLE N/A	02/17/1994	
SB 972A88U		SERVICE BULLETIN SB TFE731-A72-3544 RH ENG NOT APPLICABLE N/A	02/17/1994	
SB 972B07U		SERVICE BULLETIN G/SBA72-3504 L/ENG REV 1 NOT APPLICABLE N/A	09/30/1993	
SB 972B08U		SERVICE BULLETIN G/SBA72-3504 R/ENG REV 1 NOT APPLICABLE N/A	09/30/1993	
SB 972B13U		SERVICE BULLETIN REPL LE 1ST STG LP TURB NOT APPLICABLE N/A	07/27/1994	RECOMMENDED
SB 972B14U		SERVICE BULLETIN REPL LE 2ND STG LP TURB NOT APPLICABLE N/A	07/27/1994	RECOMMENDED
SB 972B15U		SERVICE BULLETIN REPL RE 1ST STG LP TURB NOT APPLICABLE N/A	07/27/1994	RECOMMENDED
SB 972B16U		SERVICE BULLETIN REPL RE 2ND STG LP TURB NOT APPLICABLE N/A	07/27/1994	RECOMMENDED
SB 972B39U		SERVICE BULLETIN GSBA72-3569 L/E FAN ROTOR NOT APPLICABLE N/A	11/13/1999	



Aircraft Model - 1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

MASTER & C/W
THE FOLLOWING INFORMATION IS ACCURATE AND CURRENT TO THE BEST KNOWLEDGE AND ABILITY OF CSI
HOWEVER, CAMP SHALL NOT BE RESPONSIBLE OR LIABLE FOR ANY ERRORS CONTAINED IN THIS REPORT.

ITEM NO	EFFECTIVE DATE	METHOD OF COMPLIANCE	TASK DESCRIPTION	C/W Date	DISPOSITION
SB 972B40U		OPEN	SERVICE BULLETIN GSBA72-3569 R/E FAN ROTOR	No Data	
SB 972B53U		NOT APPLICABLE N/A	SERVICE BULLETIN GSBA72-3578 LEFT ENGINE	10/31/1995	
SB 972B54U		NOT APPLICABLE N/A	SERVICE BULLETIN GSBA72-3578 RIGHT ENGINE	10/31/1995	
SB 973241U		NOT APPLICABLE N/A	SERVICE BULLETIN GSB 73-3121 L/E FUEL CONT	03/07/1994	
SB 973242U		NOT APPLICABLE N/A	SERVICE BULLETIN GSB 73-3121 R/E FUEL CONT	03/07/1994	
SB 973636U		OPEN	SERVICE BULLETIN SB731-A72-3636R1 L/E	10/17/1998	
SB 973665U		OPEN	SERVICE BULLETIN SB731-A72-3636R1 R/E	10/17/1998	
SB 977039U		NOT APPLICABLE N/A	SERVICE BULLETIN SBTFE731-A77-3020 L/H	06/11/1991	
SB 977040U		NOT APPLICABLE N/A	SERVICE BULLETIN SBTFE 731-A77-3020 R/H	06/11/1991	
SB ASB1124-27A-145		OPEN	SERVICE BULLETIN	No Data	MANDATORY
SB ASB1124-27A-147		OPEN	SERVICE BULLETIN	No Data	MANDATORY
SB ASB1124-30A-142		OPEN	SERVICE BULLETIN	No Data	MANDATORY
SB ASB1124-54A-138		OPEN	SERVICE BULLETIN	No Data	MANDATORY
SB SB731-A72-3636L/E		OPEN	SERVICE BULLETIN	No Data	MANDATORY SCRAP
SB SB731-A72-3636R/E		OPEN	SERVICE BULLETIN	No Data	MANDATORY SCRAP
SB SB731-A72-3636R1L/E		OPEN	SERVICE BULLETIN	No Data	
SB SB731-A72-3636R1R/E		OPEN	SERVICE BULLETIN	No Data	
SB SB731-A72-3668L/E		OPEN	SERVICE BULLETIN	No Data	MANDATORY SCRAP
SB SB731-A72-3668R/E		OPEN	SERVICE BULLETIN	No Data	MANDATORY SCRAP

Aircraft Model - 1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

MASTER & C/W
THE FOLLOWING INFORMATION IS ACCURATE AND CURRENT TO THE BEST KNOWLEDGE AND ABILITY OF CSI
HOWEVER, CAMP SHALL NOT BE RESPONSIBLE OR LIABLE FOR ANY ERRORS CONTAINED IN THIS REPORT.

ITEM NO	EFFECTIVE DATE	TASK DESCRIPTION	C/W Date	DISPOSITION
		METHOD OF COMPLIANCE		
ENGINE NO. 1				
AD	1978-22-10 22-SEP-78	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE LOW PRESSURE ROTOR THRUST BALL BEARINGS	No Data	
		OPEN		
AD	1980-16-04 07-AUG-80	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE TIE ROD	No Data	
		OPEN		
AD	1981-24-08 06-JAN-82	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE TURBINE INTERSTAGE TRANSITION DUCTS	No Data	
		OPEN		
AD	1982-23-03 09-DEC-83	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE HIGH PRESSURE COMPRESSOR IMPELLERS	No Data	
		OPEN		
AD	1986-03-01 24-FEB-86	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE TURBINE INTERSTAGE TRANSITION DUCTS	No Data	
		OPEN		
PRIORITY LETTER	1986-04-02 14-FEB-86	NO. 1 ENGINE - PRIORITY LETTER FAN ROTOR DISCS	No Data	SUPERSEDED
		OPEN		
AD	1986-11-05	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE FAN ROTOR DISCS	No Data	SUPERSEDED
		OPEN		
AD	1986-21-05	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE FORWARD ENGINE MOUNTS	No Data	
		OPEN		
AD	1988-18-03 30-AUG-88	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE HIGH PRESSURE TURBINE ROTOR DISC	No Data	
		OPEN		
AD	1990-03-04 22-FEB-90	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE HIGH PRESSURE TURBINE ROTOR DISCS	No Data	
		OPEN		
AD	1990-24-06 13-NOV-90	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE THERMOCOUPLE LEAD ASSEMBLIES	No Data	
		OPEN		
AD	1991-08-13 16-APR-91	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE FAN ROTOR DISK	No Data	SUPERSEDED
		OPEN		
AD	1992-21-06 27-NOV-92	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE LOW PRESSURE TURBINE (LPT) ROTOR DISKS	No Data	MANDATORY
		OPEN		
AD	1992-26-09 22-DEC-92	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE FAN ROTOR DISK	No Data	SUPERSEDED
		OPEN		
AD	1993-10-10 29-JUN-93	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE FUEL LINE CLAMP ASSEMBLY	No Data	SUPERSEDED
		OPEN		
AD	1993-25-16 02-JUN-93	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE FAN DISK	No Data	SUPERSEDED
		OPEN		
AD	1994-07-03 06-JUN-94	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE TURBINE NOZZLES	No Data	
		OPEN		
AD	1994-14-15 05-AUG-94	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE EXHAUST DUCT ATTACHMENT CLAMPS	No Data	
		OPEN		
AD	1995-07-02 19-JUN-95	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE LOW PRESSURE TURBINE DISKS	No Data	
		OPEN		
AD	1995-07-02 1ST STAGE 19-JUN-95	NO. 1 ENGINE - ACCOMPLISH	No Data	
		OPEN		
AD	1995-07-02 2ND STAGE 19-JUN-95	NO. 1 ENGINE - ACCOMPLISH	No Data	
		OPEN		

Aircraft Model - 1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

MASTER & C/W
THE FOLLOWING INFORMATION IS ACCURATE AND CURRENT TO THE BEST KNOWLEDGE AND ABILITY OF CSI
HOWEVER, CAMP SHALL NOT BE RESPONSIBLE OR LIABLE FOR ANY ERRORS CONTAINED IN THIS REPORT.

ITEM NO	EFFECTIVE DATE	METHOD OF COMPLIANCE	TASK DESCRIPTION	C/W Date	DISPOSITION
AD	1996-04-01 15-MAR-96	OPEN	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE FAN ROTOR ASSEMBLY	No Data	
AD	1996-05-03 02-APR-96	OPEN	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE FAN ROTOR DISKS	No Data	
AD	1996-18-13	OPEN	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE FAN ROTOR DISK	No Data	SUPERSEDED
AD	1998-17-01 13-OCT-98	OPEN	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE FLEX FUEL TUBE	No Data	
AD	1998-17-01 REV.1 29-NOV-99	OPEN	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE FLEX FUEL TUBE	No Data	MANDATORY
AD	2000-15-09 10-OCT-00	REPEAT OPEN	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE HPC IMPELLER	No Data	
AD	2001-23-09 21-DEC-01	OPEN	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE TO PREVENT FAILURE OF THE FAN ROTOR DISC DUE TO FATIGUE CRACKING IN THE DOVETAIL SLOTS	No Data	MANDATORY
SB	TFE731-A72-3668 25-OCT-00	OPEN	NO. 1 ENGINE - REMOVE FAN ROTOR DISC FROM SERVICE SERVICE BULLETIN	No Data	MANDATORY
AD	990100U	OPEN	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE AD86-11-05 #1 ENGINE	04/26/1994	
AD	990101U	NOT APPLICABLE N/A	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE AD90-24-06 #1 ENGINE	06/11/1991	
AD	990102U	NOT APPLICABLE N/A	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE AD92-21-06 #1 ENGINE	12/28/1992	
AD	990103U	NOT APPLICABLE N/A	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE AD94-07-03 #1 ENGINE	07/27/1994	
AD	990104U	NOT APPLICABLE N/A	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE AD95-07-02 #1E #1 LPT DSK	09/26/1995	
AD	990105U	NOT APPLICABLE N/A	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE AD95-07-02 #1E #2 LPT DSK	09/26/1995	
AD	990106U	NOT APPLICABLE N/A	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE AD96-04-01 #1 ENGINE	03/27/1996	
AD	990107U	NOT APPLICABLE N/A	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE AD96-05-03 #1 ENGINE	07/05/2000	
AD	990108U	NOT APPLICABLE N/A	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE AD96-18-13 #1 ENGINE	11/13/1999	
SB	TFE-731-A72-3504	OPEN	NO. 1 ENGINE - SERVICE BULLETIN INSPECT FAN ROTOR ASSEMBLY	No Data	
SB	TFE731-73-3137	OPEN	NO. 1 ENGINE - SERVICE BULLETIN REPLACE FUEL HEATER CHECK VALVES	No Data	
SB	TFE731-A72-3126	OPEN	NO. 1 ENGINE - SERVICE BULLETIN REPLACE/REWORK PLANET GEAR ASSEMBLY	No Data	
SB	TFE731-A72-3169	OPEN	NO. 1 ENGINE - SERVICE BULLETIN REPLACE IDENTIFIED HP ROTOR #5 THRUST BEARING	No Data	
SB	TFE731-A72-3306	OPEN	NO. 1 ENGINE - SERVICE BULLETIN IDENTIFY 1ST STAGE LOW PRESSURE DISC	No Data	

Aircraft Model - 1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

MASTER & C/W
THE FOLLOWING INFORMATION IS ACCURATE AND CURRENT TO THE BEST KNOWLEDGE AND ABILITY OF CSI
HOWEVER, CAMP SHALL NOT BE RESPONSIBLE OR LIABLE FOR ANY ERRORS CONTAINED IN THIS REPORT.

ITEM NO	EFFECTIVE DATE	METHOD OF COMPLIANCE	TASK DESCRIPTION	C/W Date	DISPOSITION
SB	TFE731-A72-3328	OPEN	NO. 1 ENGINE - SERVICE BULLETIN REPLACE ENGINE FAN ROTOR ASSEMBLY	No Data	
SB	TFE731-A72-3376	OPEN	NO. 1 ENGINE - SERVICE BULLETIN REPLACE ENGINE TURBINE ROTOR DISC	No Data	
SB	TFE731-A72-3388	OPEN	NO. 1 ENGINE - SERVICE BULLETIN REPLACE HIGH PRESSURE TURBINE ROTOR DISC	No Data	
SB	TFE731-A72-3424	OPEN	NO. 1 ENGINE - SERVICE BULLETIN REPLACE ENGINE FAN ROTOR ASSEMBLY	No Data	
SB	TFE731-A72-3432	OPEN	NO. 1 ENGINE - SERVICE BULLETIN INSPECT ENGINE FAN ROTOR DISC ASSEMBLY	No Data	
SB	TFE731-A72-3474	OPEN	NO. 1 ENGINE - SERVICE BULLETIN REPLACE LOW PRESSURE TURBINE STAGE #3 DISC	No Data	
SB	TFE731-A72-3502	OPEN	NO. 1 ENGINE - SERVICE BULLETIN INSTALL/REWORK LOW PRESSURE FIRST STAGE TURBINE NOZZLE ASSEMBLY	No Data	
SB	TFE731-A72-3544	OPEN	NO. 1 ENGINE - SERVICE BULLETIN REPLACE 1ST AND 2ND STAGE LOW PRESSURE TURBINE DISCS	No Data	
SB	TFE731-A72-3557	OPEN	NO. 1 ENGINE - SERVICE BULLETIN REPLACE 2ND STAGE LOW PRESSURE TURBINE	No Data	
SB	TFE731-A72-3569	OPEN	NO. 1 ENGINE - SERVICE BULLETIN REPLACE 1ST AND 2ND STAGE LOW PRESSURE TURBINE DISCS	No Data	
SB	TFE731-A72-3578	OPEN	NO. 1 ENGINE - SERVICE BULLETIN INSPECT FAN ROTOR DISCS	No Data	
SB	TFE731-A72-3636 R1	OPEN	NO. 1 ENGINE - SERVICE BULLETIN INSPECT HP COMPRESSOR IMPELLAR SEAL/RELIEF/BORE FOR FATIGUE CRACKING	No Data	
SB	TFE731-A72-3640 R3	OPEN	NO. 1 ENGINE - SERVICE BULLETIN CHANGE ENGINE OIL CHANGE INTERVAL TO 450 HOURS	No Data	
SB	TFE731-A72-3641 R3	OPEN	NO. 1 ENGINE - SERVICE BULLETIN PERFORM EDDY CURRENT INSPECTION ON HP COMPRESSOR IMPELLAR	No Data	
SB	TFE731-A72-3668 25-OCT-00	OPEN	NO. 1 ENGINE - SERVICE BULLETIN REMOVE FAN ROTOR DISC FROM SERVICE	No Data	MANDATORY
SB	TFE731-A73-3135 24-AUG-00	OPEN	NO. 1 ENGINE - SERVICE BULLETIN INSPECT/REPLACE FLEX TUBE ASSEMBLY	No Data	RECOMMENDED
SB	TFE731-A77-3020	OPEN	NO. 1 ENGINE - SERVICE BULLETIN REPLACE THERMOCOUPLE LEADS	No Data	

Aircraft Model - 1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

MASTER & C/W
THE FOLLOWING INFORMATION IS ACCURATE AND CURRENT TO THE BEST KNOWLEDGE AND ABILITY OF CSI
HOWEVER, CAMP SHALL NOT BE RESPONSIBLE OR LIABLE FOR ANY ERRORS CONTAINED IN THIS REPORT.

ITEM NO	EFFECTIVE DATE	TASK DESCRIPTION	C/W Date	DISPOSITION
METHOD OF COMPLIANCE				
ENGINE NO. 2				
AD	1978-22-10 22-SEP-78	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE LOW PRESSURE ROTOR THRUST BALL BEARINGS	No Data	
	OPEN			
AD	1980-16-04 07-AUG-80	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE TIE ROD	No Data	
	OPEN			
AD	1981-24-08 06-JAN-82	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE TURBINE INTERSTAGE TRANSITION DUCTS	No Data	
	OPEN			
AD	1982-23-03 09-DEC-83	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE HIGH PRESSURE COMPRESSOR IMPELLERS	No Data	
	OPEN			
AD	1986-03-01 24-FEB-86	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE TURBINE INTERSTAGE TRANSITION DUCTS	No Data	
	OPEN			
PRIORITY LETTER	1986-04-02 14-FEB-86	NO. 2 ENGINE - PRIORITY LETTER FAN ROTOR DISCS	No Data	SUPERSEDED
	OPEN			
AD	1986-11-05	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE FAN ROTOR DISCS	No Data	SUPERSEDED
	OPEN			
AD	1986-21-05	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE FORWARD ENGINE MOUNTS	No Data	
	OPEN			
AD	1988-18-03 30-AUG-88	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE HIGH PRESSURE TURBINE ROTOR DISC	No Data	
	OPEN			
AD	1990-03-04 22-FEB-90	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE HIGH PRESSURE TURBINE ROTOR DISCS	No Data	
	OPEN			
AD	1990-24-06 13-NOV-90	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE THERMOCOUPLE LEAD ASSEMBLIES	No Data	
	OPEN			
AD	1991-08-13 16-APR-91	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE FAN ROTOR DISK	No Data	SUPERSEDED
	OPEN			
AD	1992-21-06 27-NOV-92	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE LOW PRESSURE TURBINE (LPT) ROTOR DISKS	No Data	MANDATORY
	OPEN			
AD	1992-26-09 22-DEC-92	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE FAN ROTOR DISK	No Data	SUPERSEDED
	OPEN			
AD	1993-10-10 29-JUN-93	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE FUEL LINE CLAMP ASSEMBLY	No Data	SUPERSEDED
	OPEN			
AD	1993-25-16 02-JUN-93	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE FAN DISK	No Data	SUPERSEDED
	OPEN			
AD	1994-07-03 06-JUN-94	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE TURBINE NOZZLES	No Data	
	OPEN			
AD	1994-14-15 05-AUG-94	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE EXHAUST DUCT ATTACHMENT CLAMPS	No Data	
	OPEN			
AD	1995-07-02 19-JUN-95	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE LOW PRESSURE TURBINE DISKS	No Data	
	OPEN			
AD	1995-07-02 1ST STAGE 19-JUN-95	NO. 2 ENGINE - ACCOMPLISH	No Data	
	OPEN			
AD	1995-07-02 2ND STAGE 19-JUN-95	NO. 2 ENGINE - ACCOMPLISH	No Data	
	OPEN			

Aircraft Model - 1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

MASTER & C/W
THE FOLLOWING INFORMATION IS ACCURATE AND CURRENT TO THE BEST KNOWLEDGE AND ABILITY OF CSI
HOWEVER, CAMP SHALL NOT BE RESPONSIBLE OR LIABLE FOR ANY ERRORS CONTAINED IN THIS REPORT.

ITEM NO	EFFECTIVE DATE	METHOD OF COMPLIANCE	TASK DESCRIPTION	C/W Date	DISPOSITION
AD	1996-04-01 15-MAR-96	OPEN	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE FAN ROTOR ASSEMBLY	No Data	
AD	1996-05-03		NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE FAN ROTOR DISKS	No Data	
	02-APR-96	OPEN			
AD	1996-18-13	OPEN	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE FAN ROTOR DISK	No Data	SUPERSEDED
AD	1998-17-01 13-OCT-98	OPEN	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE FLEX FUEL TUBE	No Data	
AD	1998-17-01 REV.1 29-NOV-99	OPEN	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE FLEX FUEL TUBE	No Data	MANDATORY
AD	2000-15-09		NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE HPC IMPELLER	No Data	
	10-OCT-00	REPEAT OPEN			
AD	2001-23-09		NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE TO PREVENT FAILURE OF THE FAN ROTOR DISC DUE TO FATIGUE CRACKING IN THE DOVETAIL SLOTS	No Data	MANDATORY
	21-DEC-01	OPEN			
SB	TFE731-A72-3668 25-OCT-00	OPEN	NO. 2 ENGINE - REMOVE FAN ROTOR DISC FROM SERVICE SERVICE BULLETIN	No Data	MANDATORY
AD	990100U		NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE AD86-11-05 #2 ENGINE	No Data	
		OPEN			
AD	990101U		NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE AD90-24-06 #2 ENGINE	06/11/1991	
		NOT APPLICABLE N/A			
AD	990102U		NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE AD92-21-06 #2 ENGINE	01/25/1993	
		COMPLIED WITH C/W			
AD	990103U		NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE AD94-07-03 #2 ENGINE	07/27/1994	
		NOT APPLICABLE N/A			
AD	990104U		NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE AD95-07-02 #2E #2 LPT DSK	09/26/1995	
		NOT APPLICABLE N/A			
AD	990105U		NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE AD95-07-02 #2E #1 LPT DSK	09/26/1995	
		NOT APPLICABLE N/A			
AD	990106U		NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE AD96-04-01 #2 ENGINE	10/06/1998	
		NOT APPLICABLE N/A			
AD	990107U		NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE AD96-05-03 #2 ENGINE	03/27/1996	
		NOT APPLICABLE N/A			
AD	990108U		NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE AD96-18-13 #2 ENGINE	10/06/1998	
		NOT APPLICABLE N/A			
SB	TFE-731-A72-3504		NO. 2 ENGINE - SERVICE BULLETIN INSPECT FAN ROTOR ASSEMBLY	No Data	
		OPEN			
SB	TFE731-73-3137		NO. 2 ENGINE - SERVICE BULLETIN REPLACE FUEL HEATER CHECK VALVES	No Data	
		OPEN			
SB	TFE731-A72-3126		NO. 2 ENGINE - SERVICE BULLETIN REPLACE/REWORK PLANET GEAR ASSEMBLY	No Data	
		OPEN			
SB	TFE731-A72-3169		NO. 2 ENGINE - SERVICE BULLETIN REPLACE IDENTIFIED HP ROTOR #5 THRUST BEARING	No Data	
		OPEN			
SB	TFE731-A72-3306		NO. 2 ENGINE - SERVICE BULLETIN IDENTIFY 1ST STAGE LOW PRESSURE DISC	No Data	
		OPEN			

Aircraft Model - 1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date **14-MAR-2002**

MASTER & C/W
THE FOLLOWING INFORMATION IS ACCURATE AND CURRENT TO THE BEST KNOWLEDGE AND ABILITY OF CSI
HOWEVER, CAMP SHALL NOT BE RESPONSIBLE OR LIABLE FOR ANY ERRORS CONTAINED IN THIS REPORT.

ITEM NO	EFFECTIVE DATE	METHOD OF COMPLIANCE	TASK DESCRIPTION	C/W Date	DISPOSITION
SB	TFE731-A72-3328	OPEN	NO. 2 ENGINE - SERVICE BULLETIN REPLACE ENGINE FAN ROTOR ASSEMBLY	No Data	
SB	TFE731-A72-3376	OPEN	NO. 2 ENGINE - SERVICE BULLETIN REPLACE ENGINE TURBINE ROTOR DISC	No Data	
SB	TFE731-A72-3388	OPEN	NO. 2 ENGINE - SERVICE BULLETIN REPLACE HIGH PRESSURE TURBINE ROTOR DISC	No Data	
SB	TFE731-A72-3424	OPEN	NO. 2 ENGINE - SERVICE BULLETIN REPLACE ENGINE FAN ROTOR ASSEMBLY	No Data	
SB	TFE731-A72-3432	OPEN	NO. 2 ENGINE - SERVICE BULLETIN INSPECT ENGINE FAN ROTOR DISC ASSEMBLY	No Data	
SB	TFE731-A72-3474	OPEN	NO. 2 ENGINE - SERVICE BULLETIN REPLACE LOW PRESSURE TURBINE STAGE #3 DISC	No Data	
SB	TFE731-A72-3502	OPEN	NO. 2 ENGINE - SERVICE BULLETIN INSTALL/REWORK LOW PRESSURE FIRST STAGE TURBINE NOZZLE ASSEMBLY	No Data	
SB	TFE731-A72-3544	OPEN	NO. 2 ENGINE - SERVICE BULLETIN REPLACE 1ST AND 2ND STAGE LOW PRESSURE TURBINE DISCS	No Data	
SB	TFE731-A72-3557	OPEN	NO. 2 ENGINE - SERVICE BULLETIN REPLACE 2ND STAGE LOW PRESSURE TURBINE	No Data	
SB	TFE731-A72-3569	OPEN	NO. 2 ENGINE - SERVICE BULLETIN REPLACE 1ST AND 2ND STAGE LOW PRESSURE TURBINE DISCS	No Data	
SB	TFE731-A72-3578	OPEN	NO. 2 ENGINE - SERVICE BULLETIN INSPECT FAN ROTOR DISCS	No Data	
SB	TFE731-A72-3636 R1	OPEN	NO. 2 ENGINE - SERVICE BULLETIN INSPECT HP COMPRESSOR IMPELLAR SEAL/RELIEF/BORE FOR FATIGUE CRACKING	No Data	
SB	TFE731-A72-3640 R3	OPEN	NO. 2 ENGINE - SERVICE BULLETIN CHANGE ENGINE OIL CHANGE INTERVAL TO 450 HOURS	No Data	
SB	TFE731-A72-3641 R3	OPEN	NO. 2 ENGINE - SERVICE BULLETIN PERFORM EDDY CURRENT INSPECTION ON HP COMPRESSOR IMPELLAR	No Data	
SB	TFE731-A72-3668 25-OCT-00	OPEN	NO. 2 ENGINE - SERVICE BULLETIN REMOVE FAN ROTOR DISC FROM SERVICE	No Data	MANDATORY
SB	TFE731-A73-3135 24-AUG-00	OPEN	NO. 2 ENGINE - SERVICE BULLETIN INSPECT/REPLACE FLEX TUBE ASSEMBLY	No Data	RECOMMENDED
SB	TFE731-A77-3020	OPEN	NO. 2 ENGINE - SERVICE BULLETIN REPLACE THERMOCOUPLE LEADS	No Data	



AIRCRAFT Updates Report

Serial #: 368 Reg. #: N368MD
 Model: 1124A WESTWIND

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
AIRCRAFT Serial #: 368 Reg #: N368MD								
910080	SB 1124-24-008							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 04-NOV-1987 12:00:00					
MOS	06-JUN-1986		REASON: --					MOS
HRS	3108		TECH:					HRS
AFL	1422		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: C/W								
910650	SB 1124-24-065							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 04-NOV-1987 12:00:00					
MOS	06-JUN-1986		REASON: --					MOS
HRS	3108		TECH:					HRS
AFL	1422		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: C/W								
910720	SB 1124-22-072 A/P							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 04-NOV-1987 12:00:00					
MOS	28-MAY-1986		REASON: --					MOS
HRS	3099		TECH:					HRS
AFL			INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: C/W								
910880	SB 1124-11-088A							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 04-NOV-1987 12:00:00					
MOS	18-SEP-1987		REASON: --					MOS
HRS	3734		TECH:					HRS
AFL			INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: C/W								
950930	SL WW-2493 FLAP POTENT							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 04-NOV-1987 12:00:00					
MOS	10-AUG-1986		REASON: --					MOS
HRS	3515		TECH:					HRS
AFL			INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: C/W								
950840	SL WW-2484							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 04-NOV-1987 12:00:00					
MOS	05-JAN-1987		REASON: --					MOS
HRS/MS			TECH:					HRS/MS
AFL			INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: C/W								
910100	ACCOMPLISH SB1124-27-100R2 L/H RODS BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 06-NOV-1987 12:00:00					
MOS	14-NOV-1985		REASON: --					MOS
HRS	2702		TECH:					HRS
AFL	1681		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: C/W								

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
910290	SB 1124-21-029					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 06-NOV-1987 12:00:00						
MOS	20-JAN-1986	REASON: --				MOS		
HRS	2832	TECH:				HRS		
AFL	1755	INSP:		LABOR HRS: 0		COST: \$0.00		AFL
Note: C/W								
910250	SB 1124-22-025					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 06-NOV-1987 12:00:00						
MOS	09-JAN-1986	REASON: --				MOS		
HRS	2812	TECH:				HRS		
AFL	1743	INSP:		LABOR HRS: 0		COST: \$0.00		AFL
Note: C/W								
910910	ACCOMPLISH INSP #2 ENG MT FASTENERS BULLETIN					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 06-NOV-1987 12:00:00						
MOS	18-SEP-1987	REASON: --				MOS		
HRS	3734	TECH:				HRS		
AFL		INSP:		LABOR HRS: 0		COST: \$0.00		AFL
Note: C/W								
910860	SB 1124-27-086					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 06-NOV-1987 12:00:00						
MOS	18-SEP-1987	REASON: --				MOS		
HRS/MS		TECH:				HRS/MS		
AFL		INSP:		LABOR HRS: 0		COST: \$0.00		AFL
Note: C/W								
910620	SB 1124-27-062					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 06-NOV-1987 12:00:00						
MOS	18-SEP-1987	REASON: --				MOS		
HRS	3734	TECH:				HRS		
AFL		INSP:		LABOR HRS: 0		COST: \$0.00		AFL
Note: C/W								
910450	SB 1124-32-045					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 06-NOV-1987 12:00:00						
MOS	06-DEC-1985	REASON: --				MOS		
HRS	2758	TECH:				HRS		
AFL	1709	INSP:		LABOR HRS: 0		COST: \$0.00		AFL
Note: C/W								
910400	SB 1124-57-004					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 06-NOV-1987 12:00:00						
MOS	25-AUG-1985	REASON: --				MOS		
HRS	2564	TECH:				HRS		
AFL	1584	INSP:		LABOR HRS: 0		COST: \$0.00		AFL
Note: C/W								
910300	SB 1124-32-030					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 06-NOV-1987 12:00:00						
MOS	06-DEC-1985	REASON: --				MOS		
HRS	2758	TECH:				HRS		
AFL	1709	INSP:		LABOR HRS: 0		COST: \$0.00		AFL
Note: C/W								

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
990085U	ACCOMPLISH AIRWORTHINESS DIRECTIVE AD81-24-08 #1 ENGINE			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
C/W	WARR	TRANSACTION DATE: 24-NOV-1987 12:00:00						
MOS	06-JAN-1982	REASON: --					MOS	
HRS/MS		TECH:					HRS/MS	
AFL		INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
Note: INSP L/E TURB DUCT - N/A BY S/N								
1981-07-07 PARA B	TO PREVENT FIRE DUE TO OVERHEATING OF THE INTERCOM SYSTEM AIRWORTHINESS DIRECTIVE							
C/W	WARR	TRANSACTION DATE: 24-NOV-1987 12:00:00						
MOS		REASON: --					MOS	
MSC		TECH:					MSC	
AFL	0	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
990120U	AIRWORTHINESS DIRECTIVE AD86-03-01 #1 ENGINE							
C/W	WARR	TRANSACTION DATE: 24-NOV-1987 12:00:00						
MOS	28-JUL-1986	REASON: --					MOS	
HRS		TECH:					HRS	
AFL		INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
990090U	AIRWORTHINESS DIRECTIVE AD81-24-08 #2 ENGINE							
C/W	WARR	TRANSACTION DATE: 24-NOV-1987 12:00:00						
MOS	06-JAN-1982	REASON: --					MOS	
MSC		TECH:					MSC	
AFL		INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
1981-07-07 PARA A	TO PREVENT FIRE DUE TO OVERHEATING OF THE INTERCOM SYSTEM AIRWORTHINESS DIRECTIVE							
C/W	WARR	TRANSACTION DATE: 24-NOV-1987 12:00:00						
MOS		REASON: --					MOS	
MSC		TECH:					MSC	
AFL	0	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
990130	ACCOMPLISH AD86-14-02 AIRWORTHINESS DIRECTIVE			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
C/W	WARR	TRANSACTION DATE: 24-NOV-1987 12:00:00						
MOS	13-OCT-1985	REASON: --					MOS	
HRS/MS		TECH:					HRS/MS	
AFL		INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
Note: REF CODE 550656								
990045	AD80-16-04 AIRWORTHINESS DIRECTIVE							
C/W	WARR	TRANSACTION DATE: 24-NOV-1987 12:00:00						
MOS		REASON: --					MOS	
MSC		TECH:					MSC	
AFL	0	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
1980-18-08	TO PREVENT LOSS OF EMERGENCY ELECTRICAL POWER AND POSSIBLE CORROSIVE OR THERMAL DAMAGE TO THE AIRCRAFT AIRWORTHINESS DIRECTIVE							
C/W	WARR	TRANSACTION DATE: 24-NOV-1987 12:00:00						
MOS		REASON: --					MOS	
MSC		TECH:					MSC	
AFL	0	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR	
1980-19-15	TO PREVENT THE UPPER HOT LIQUID CONTAINER IN THE GALLEY FROM RUBBING AGAINST THE ELECTRICAL WIRE BUNDLE AND CAUSING A FIRE WHICH COULD RESULT IN THE LOSS OF THRUST REVERSERS, FLAPS, SPOILERS, AND SOME AIRPLANE LIGHTS AIRWORTHINESS DIRECTIVE						
CW	WARR	TRANSACTION DATE: 24-NOV-1987 12:00:00					
MOS		REASON: --				MOS	
MSC		TECH:				MSC	
AFL	0	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
1972-19-04	TO PREVENT A POSSIBLE BATTERY FIRE THAT MAY RESULT FROM OVERHEATING CAUSED BY AN UNDETECTED BATTERY FAILURE AIRWORTHINESS DIRECTIVE						
CW	WARR	TRANSACTION DATE: 24-NOV-1987 12:00:00					
MOS		REASON: --				MOS	
MSC		TECH:				MSC	
AFL	0	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
990095	ACCOMPLISH AD82-21-04 AIRWORTHINESS DIRECTIVE						
CW	WARR	TRANSACTION DATE: 24-NOV-1987 12:00:00				Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
MOS	22-JAN-1985	REASON: --				MOS	
HRS/MSQ		TECH:				HRS/MSQ	
AFL		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: PS823 INSTALLED							
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN						
CW	WARR	TRANSACTION DATE: 23-JUN-1988 12:00:00				Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
MOS	25-MAR-1988	REASON: --				MOS	
HRS	3883	TECH:				HRS	
AFL	2442	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3							
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN						
CW	WARR	TRANSACTION DATE: 23-JUN-1988 12:00:00				Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
MOS	25-MAR-1988	REASON: --				MOS	
HRS	3883	TECH:				HRS	
AFL	2442	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3							
950785	SL WW-2478 R HYD PUMP						
CW	WARR	TRANSACTION DATE: 23-JUN-1988 12:00:00				Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
MOS	25-MAR-1988	REASON: --				MOS	
HRS	3883	TECH:				HRS	
AFL	2442	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3							
950780	SL WW-2478 L HYD PUMP						
CW	WARR	TRANSACTION DATE: 23-JUN-1988 12:00:00				Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
MOS	25-MAR-1988	REASON: --				MOS	
HRS	3883	TECH:				HRS	
AFL	2442	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3							
950570	SL WW-2457 PART A,R/H						
CW	WARR	TRANSACTION DATE: 23-JUN-1988 12:00:00				Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
MOS	25-MAR-1988	REASON: --				MOS	
HRS	3883	TECH:				HRS	
AFL	2442	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3 - RPT 160 HRS							



AIRCRAFT Updates Report

Serial #: 368 Reg. #: N368MD
 Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
950569	SL WW-2457 PART A,L/H							
	C/W	WARR	TRANSACTION DATE: 23-JUN-1988 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	25-MAR-1988		REASON: --					MOS
HRS	3883		TECH:					HRS
AFL	2442		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - RPT 150 HRS								
910170	SB 1124-27-017							
	C/W	WARR	TRANSACTION DATE: 02-SEP-1988 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	15-AUG-1988		REASON: --					MOS
HRS	3988		TECH:					HRS
AFL	2523		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: C/W								
910300	SB 1124-32-030							
	C/W	WARR	TRANSACTION DATE: 02-SEP-1988 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	15-AUG-1988		REASON: --					MOS
HRS	3988		TECH:					HRS
AFL	2523		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: C/W								
910920	SB 1124-57-092							
	C/W	WARR	TRANSACTION DATE: 02-SEP-1988 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	15-AUG-1988		REASON: --					MOS
HRS	3988		TECH:					HRS
AFL	2523		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: C/W								
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN							
	C/W	WARR	TRANSACTION DATE: 08-SEP-1988 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	16-AUG-1988		REASON: --					MOS
HRS	3988		TECH:					HRS
AFL	2523		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
910930	ACCOMPLISH SB 1124-79-093 PART A BULLETIN							
	C/W	WARR	TRANSACTION DATE: 08-SEP-1988 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	15-AUG-1988		REASON: --					MOS
HRS	3988		TECH:					HRS
AFL	2523		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: UNTIL PART B C/W - C/W PART II								
910940	SB1124-32-094 LG SELECTOR							
	C/W	WARR	TRANSACTION DATE: 08-SEP-1988 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	15-AUG-1988		REASON: --					MOS
HRS	3988		TECH:					HRS
AFL	2523		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: C/W								
910960	SB 1124-32-096							
	C/W	WARR	TRANSACTION DATE: 08-SEP-1988 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	15-AUG-1988		REASON: --					MOS
HRS	3988		TECH:					HRS
AFL	2523		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: C/W								

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model : 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
910950	SB 1124-27-095						
C/W	WARR	TRANSACTION DATE: 08-SEP-1988 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	15-AUG-1988	REASON: --					MOS
HRS	3988	TECH:					HRS
AFL	2523	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: C/W							
951031	SL WW-24103 R/H SERVICE BULLETIN						
C/W	WARR	TRANSACTION DATE: 08-SEP-1988 12:00:00					
MOS		REASON: --					MOS
MSC		TECH:					MSC
AFL	0	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
951030	SL WW-24103 L/H SERVICE BULLETIN						
C/W	WARR	TRANSACTION DATE: 08-SEP-1988 12:00:00					
MOS		REASON: --					MOS
MSC		TECH:					MSC
AFL	0	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
990020	ACCOMPLISH AD74-08-09 R2 AIRWORTHINESS DIRECTIVE						
C/W	WARR	TRANSACTION DATE: 08-SEP-1988 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	15-AUG-1988	REASON: W - FREQUENCY OK AS IS					MOS
HRS	3989	TECH:					HRS
AFL	2523	INSP:	LABOR HRS: .2	COST: \$0.00			AFL
Note: AD 74-08-09 - RPT 1000 HRS							
950942	ACCOMPLISH SLWW-2494 REV 3 RMG BOLTS BULLETIN						
C/W	WARR	TRANSACTION DATE: 08-SEP-1988 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	29-DEC-1987	REASON: --					MOS
HRS	3767	TECH:					HRS
AFL	2367	INSP:	LABOR HRS: 3	COST: \$0.00			AFL
Note: OP 2,3							
950942	ACCOMPLISH SLWW-2494 REV 3 RMG BOLTS BULLETIN						
C/W	WARR	TRANSACTION DATE: 08-SEP-1988 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	06-AUG-1988	REASON: --					MOS
HRS	3988	TECH:					HRS
AFL	2523	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3							
950941	ACCOMPLISH SLWW-2494 REV 3 LMG BOLTS BULLETIN						
C/W	WARR	TRANSACTION DATE: 08-SEP-1988 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	29-DEC-1987	REASON: --					MOS
HRS	3767	TECH:					HRS
AFL	2367	INSP:	LABOR HRS: 3	COST: \$0.00			AFL
Note: OP 2,3							
950941	ACCOMPLISH SLWW-2494 REV 3 LMG BOLTS BULLETIN						
C/W	WARR	TRANSACTION DATE: 08-SEP-1988 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	06-AUG-1988	REASON: --					MOS
HRS	3988	TECH:					HRS
AFL	2523	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3							

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 08-SEP-1988 12:00:00						
MOS	15-AUG-1988	REASON: --						MOS
HRS	3988	TECH:						HRS
AFL	2523	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
950911	ACCOMPLISH SL WW-2491 REV 1 NLG BRGS BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 08-SEP-1988 12:00:00						
MOS	29-DEC-1987	REASON: --						MOS
HRS	3767	TECH:						HRS
AFL	2367	INSP:		LABOR HRS: 8	COST: \$0.00			AFL
Note: RPT 1200 HRS								
950910	SL WW-2491A							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 08-SEP-1988 12:00:00						
MOS	15-AUG-1988	REASON: --						MOS
HRS	3988	TECH:						HRS
AFL	2523	INSP:		LABOR HRS: 2	COST: \$0.00			AFL
Note: C/W								
950785	SL WW-2478 R HYD PUMP							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 08-SEP-1988 12:00:00						
MOS	06-AUG-1988	REASON: --						MOS
HRS	3988	TECH:						HRS
AFL	2523	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
950780	SL WW-2478 L HYD PUMP							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 08-SEP-1988 12:00:00						
MOS	06-AUG-1988	REASON: --						MOS
HRS	3988	TECH:						HRS
AFL	2523	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
950570	SL WW-2457 PART A,R/H							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 08-SEP-1988 12:00:00						
MOS	12-AUG-1988	REASON: --						MOS
HRS	3988	TECH:						HRS
AFL	2523	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - RPT 150 HRS								
950569	SL WW-2457 PART A,L/H							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 08-SEP-1988 12:00:00						
MOS	12-AUG-1988	REASON: --						MOS
HRS	3988	TECH:						HRS
AFL	2523	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - RPT 150 HRS								
910931	SB1124-79-093 PART B							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 08-SEP-1988 12:00:00						
MOS	15-AUG-1988	REASON: --						MOS
HRS	3988	TECH:						HRS
AFL	2523	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: C/W								

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model : 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
910200	ACCOMPLISH SB 1124-55-020 REV 2 BULLETIN				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 07-FEB-1989 12:00:00					
MOS	20-JAN-1989	REASON: --			MOS		
HRS	4130	TECH:			HRS		
AFL	2635	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
950911	ACCOMPLISH SL WW-2491 REV 1 NLG BRGS BULLETIN				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 07-FEB-1989 12:00:00					
MOS	29-DEC-1987	REASON: --			MOS		
HRS	3797	TECH:			HRS		
AFL	2386	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: REF TO CODE 320118 - RPT 1200 HRS							
990166U	AIRWORTHINESS DIRECTIVE AD88-18-03 #2 ENGINE						
CW	WARR	TRANSACTION DATE: 07-FEB-1989 12:00:00					
MOS	20-JAN-1989	REASON: --			MOS		
MSC		TECH:			MSC		
AFL	2635	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
990165U	AIRWORTHINESS DIRECTIVE AD88-18-03 #1 ENGINE						
CW	WARR	TRANSACTION DATE: 07-FEB-1989 12:00:00					
MOS	20-JAN-1989	REASON: --			MOS		
HRS	4130	TECH:			HRS		
AFL	2635	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
1986-14-02	SUPERSEDED BY AD1989-12-08 AIRWORTHINESS DIRECTIVE						
CW	WARR	TRANSACTION DATE: 07-FEB-1989 12:00:00					
MOS		REASON: --			MOS		
MSC		TECH:			MSC		
AFL	0	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 07-FEB-1989 12:00:00					
MOS	20-JAN-1989	REASON: --			MOS		
HRS	4130	TECH:			HRS		
AFL	2635	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
950500	SL WW-2450B INSP NACL CWL				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 07-FEB-1989 12:00:00					
MOS	20-JAN-1989	REASON: --			MOS		
HRS	4130	TECH:			HRS		
AFL	2635	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3 - RPT 150 HRS							
950785	SL WW-2478 R HYD PUMP				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 07-FEB-1989 12:00:00					
MOS	20-JAN-1989	REASON: --			MOS		
HRS	4130	TECH:			HRS		
AFL	2635	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
950780	SL WW-2478 L HYD PUMP							
C/W	WARR	TRANSACTION DATE: 07-FEB-1989 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	20-JAN-1989	REASON: --						MOS
HRS	4130	TECH:						HRS
AFL	2635	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
950570	SL WW-2457 PART A,R/H							
C/W	WARR	TRANSACTION DATE: 07-FEB-1989 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	20-JAN-1989	REASON: --						MOS
HRS	4130	TECH:						HRS
AFL	2635	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - RPT 150 HRS								
950569	SL WW-2457 PART A,L/H							
C/W	WARR	TRANSACTION DATE: 07-FEB-1989 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	20-JAN-1989	REASON: --						MOS
HRS	4130	TECH:						HRS
AFL	2635	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - RPT 150 HRS								
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN							
C/W	WARR	TRANSACTION DATE: 07-FEB-1989 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	20-JAN-1989	REASON: --						MOS
HRS	4130	TECH:						HRS
AFL	2635	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
950940	SL WW-2494							
C/W	WARR	TRANSACTION DATE: 02-MAR-1989 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	20-JAN-1989	REASON: --						MOS
HRS	4130	TECH:						HRS
AFL	2635	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
950180	SL WW-2424D,L FLEX SHAFT							
C/W	WARR	TRANSACTION DATE: 09-MAY-1989 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	06-APR-1989	REASON: --						MOS
HRS	4215	TECH:						HRS
AFL	2745	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: REF: CODE 270280								
950185	SL WW-2424D,R FLEX SHAFT							
C/W	WARR	TRANSACTION DATE: 09-MAY-1989 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	06-APR-1989	REASON: --						MOS
HRS	4215	TECH:						HRS
AFL	2745	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: REF:CODE 270285								
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN							
C/W	WARR	TRANSACTION DATE: 13-JUN-1989 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	09-JUN-1989	REASON: --						MOS
HRS	4274	TECH:						HRS
AFL	2800	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
950500	SL WW-2450B INSP NACL CWL				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 13-JUN-1989 12:00:00					
MOS	09-JUN-1989	REASON: --					MOS
HRS	4274	TECH:					HRS
AFL	2800	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - RPT 150 HRS							
950571	SL WW-2457 PART B,L/H				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 13-JUN-1989 12:00:00					
MOS	09-JUN-1989	REASON: --					MOS
HRS	4274	TECH:					HRS
AFL	2800	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 3 - RPT 600 HRS							
950780	SL WW-2478 L HYD PUMP				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 13-JUN-1989 12:00:00					
MOS	09-JUN-1989	REASON: --					MOS
HRS	4274	TECH:					HRS
AFL	2800	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 13-JUN-1989 12:00:00					
MOS	09-JUN-1989	REASON: --					MOS
HRS	4274	TECH:					HRS
AFL	2800	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
950942	ACCOMPLISH SLWW-2494 REV 3 RMG BOLTS BULLETIN				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 13-JUN-1989 12:00:00					
MOS	09-JUN-1989	REASON: --					MOS
HRS	4274	TECH:					HRS
AFL	2800	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3							
910911U	SERVICE BULLETIN SB 1124-71-091 PART II				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 13-JUN-1989 12:00:00					
MOS	12-APR-1989	REASON: --					MOS
HRS	4218	TECH:					HRS
AFL		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
950941	ACCOMPLISH SLWW-2494 REV 3 LMG BOLTS BULLETIN				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 13-JUN-1989 12:00:00					
MOS	09-JUN-1989	REASON: --					MOS
HRS	4274	TECH:					HRS
AFL	2800	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3							
950785	SL WW-2478 R HYD PUMP				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 13-JUN-1989 12:00:00					
MOS	09-JUN-1989	REASON: --					MOS
HRS	4274	TECH:					HRS
AFL	2800	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
950572	SL WW-2457 PART B,R/H							
	C/W	WARR	TRANSACTION DATE: 13-JUN-1989 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	09-JUN-1989		REASON: --					MOS
HRS	4274		TECH:					HRS
AFL	2800		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 3								
950570	SL WW-2457 PART A,R/H							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 13-JUN-1989 12:00:00					
MOS	09-JUN-1989		REASON: --					MOS
HRS	4274		TECH:					HRS
AFL	2800		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - RPT 150 HRS								
950569	SL WW-2457 PART A,L/H							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 13-JUN-1989 12:00:00					
MOS	09-JUN-1989		REASON: --					MOS
HRS	4274		TECH:					HRS
AFL	2800		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - RPT 150 HRS								
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 07-JUL-1989 12:00:00					
MOS	09-JUN-1989		REASON: --					MOS
HRS	4273		TECH:					HRS
AFL	2800		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
950942	ACCOMPLISH SLWW-2494 REV 3 RMG BOLTS BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 07-JUL-1989 12:00:00					
MOS	09-JUN-1989		REASON: --					MOS
HRS	4273		TECH:					HRS
AFL	2800		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
950941	ACCOMPLISH SLWW-2494 REV 3 LMG BOLTS BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 07-JUL-1989 12:00:00					
MOS	09-JUN-1989		REASON: --					MOS
HRS	4273		TECH:					HRS
AFL	2800		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 07-JUL-1989 12:00:00					
MOS	09-JUN-1989		REASON: --					MOS
HRS	4273		TECH:					HRS
AFL	2800		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
950500	SL WW-2450B INSP NACL CWL							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 07-JUL-1989 12:00:00					
MOS	09-JUN-1989		REASON: --					MOS
HRS	4273		TECH:					HRS
AFL	2800		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - RPT 150 HRS								

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
950570	SL WW-2457 PART A,R/H				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 07-JUL-1989 12:00:00					
MOS	09-JUN-1989	REASON: --			MOS		
HRS	4273	TECH:			HRS		
AFL	2800	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3 - RPT 150 HRS							
950572	SL WW-2457 PART B,R/H				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 07-JUL-1989 12:00:00					
MOS	09-JUN-1989	REASON: --			MOS		
HRS	4273	TECH:			HRS		
AFL	2800	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 3							
950785	SL WW-2478 R HYD PUMP				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 07-JUL-1989 12:00:00					
MOS	09-JUN-1989	REASON: --			MOS		
HRS	4273	TECH:			HRS		
AFL	2800	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
950780	SL WW-2478 L HYD PUMP				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 07-JUL-1989 12:00:00					
MOS	09-JUN-1989	REASON: --			MOS		
HRS	4273	TECH:			HRS		
AFL	2800	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
950571	SL WW-2457 PART B,L/H				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 07-JUL-1989 12:00:00					
MOS	09-JUN-1989	REASON: --			MOS		
HRS	4273	TECH:			HRS		
AFL	2800	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 3 - RPT 600 HRS							
950569	SL WW-2457 PART A,L/H				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 07-JUL-1989 12:00:00					
MOS	09-JUN-1989	REASON: --			MOS		
HRS	4273	TECH:			HRS		
AFL	2800	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3 - RPT 160 HRS							
910090	SB 1124-32-009				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 12-JUL-1989 12:00:00					
MOS	06-SEP-1989	REASON: --			MOS		
HRS	4272	TECH:			HRS		
AFL	2800	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: C/W							
910912U	SERVICE BULLETIN SB 1124-71-091 PART II				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 10-AUG-1989 12:00:00					
MOS	31-MAY-1989	REASON: --			MOS		
MSC		TECH:			MSC		
AFL	2793	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002** From Date : To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
990822U	AIRWORTHINESS DIRECTIVE AD82-23-03 R1 #2 ENGINE							
C/W	WARR	TRANSACTION DATE: 12-OCT-1989 12:00:00						
MOS	17-MAY-1989	REASON: --					MOS	
MSC		TECH:					MSC	
AFL	2793	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 07-DEC-1989 12:00:00						
MOS	30-NOV-1989	REASON: --					MOS	
HRS	4430	TECH:					HRS	
AFL	2987	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3								
950569	SL WW-2457 PART A,L/H							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 07-DEC-1989 12:00:00						
MOS	30-NOV-1989	REASON: --					MOS	
HRS	4430	TECH:					HRS	
AFL	2987	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3 - RPT 150 HRS								
950500	SL WW-2450B INSP NAACL CWL							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 07-DEC-1989 12:00:00						
MOS	30-NOV-1989	REASON: --					MOS	
HRS	4430	TECH:					HRS	
AFL	2987	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3 - RPT 150 HRS								
950570	SL WW-2457 PART A,R/H							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 07-DEC-1989 12:00:00						
MOS	30-NOV-1989	REASON: --					MOS	
HRS	4430	TECH:					HRS	
AFL	2987	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3 - RPT 150 HRS								
950785	SL WW-2478 R HYD PUMP							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 07-DEC-1989 12:00:00						
MOS	30-NOV-1989	REASON: --					MOS	
HRS	4430	TECH:					HRS	
AFL	2987	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3								
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 07-DEC-1989 12:00:00						
MOS	30-NOV-1989	REASON: --					MOS	
HRS	4430	TECH:					HRS	
AFL	2987	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3								
950911	ACCOMPLISH SL WW-2491 REV 1 NLG BRGS BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 07-DEC-1989 12:00:00						
MOS	30-NOV-1989	REASON: --					MOS	
HRS	4430	TECH:					HRS	
AFL	2987	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
Note: REF TO CODE 320118 - RPT								

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
950780	SL WW-2478 L HYD PUMP						
		Done By: CAMP SYSTEMS INTERNATIONAL, LLC					
C/W	WARR	TRANSACTION DATE: 07-DEC-1989 12:00:00					
MOS	30-NOV-1989	REASON: --					MOS
HRS	4430	TECH:					HRS
AFL	2987	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
972202U	SERVICE BULLETIN TFE731-A72-3388 RIGHT ENG						
C/W	WARR	TRANSACTION DATE: 07-DEC-1989 12:00:00					
MOS	05-DEC-1989	REASON: --					MOS
MSC		TECH:					MSC
AFL	2994	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
972200U	SERVICE BULLETIN TFE731-A72-3388 LEFT ENG						
C/W	WARR	TRANSACTION DATE: 07-DEC-1989 12:00:00					
MOS	05-DEC-1989	REASON: --					MOS
HRS	4436	TECH:					HRS
AFL	2994	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
990100	ACCOMPLISH AD84-02-08 AIRWORTHINESS DIRECTIVE						
C/W	WARR	TRANSACTION DATE: 11-APR-1990 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	20-JAN-1989	REASON: --					MOS
HRS	4130	TECH:					HRS
AFL	2635	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: SCOTT OXYGEN CYLIND - N/A							
1984-02-08	TO PREVENT POSSIBLE USE OF IMPROPERLY CHARGED OXYGEN CYLINDERS, BLEED DOWN (DISCHARGE) THE CYLINDERS, AND RECHARGE WITH AVIATOR'S BREATHING OXYGEN AIRWORTHINESS DIRECTIVE						
C/W	WARR	TRANSACTION DATE: 12-APR-1990 12:00:00					
MOS		REASON: --					MOS
MSC		TECH:					MSC
AFL	0	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
1990-03-02	SUPERSEDED BY AD1990-06-13 AIRWORTHINESS DIRECTIVE						
C/W	WARR	TRANSACTION DATE: 12-APR-1990 12:00:00					
MOS		REASON: --					MOS
MSC		TECH:					MSC
AFL	0	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
990982U	ACCOMPLISH AIRWORTHINESS DIRECTIVE AD90-03-04 #1 ENGINE						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 23-APR-1990 12:00:00					
MOS	05-DEC-1989	REASON: --					MOS
HRS	4436	TECH:					HRS
AFL	2994	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: C/W 731-A72-3388 - N/A							
990983U	ACCOMPLISH AIRWORTHINESS DIRECTIVE AD90-03-04 #2 ENGINE						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 23-APR-1990 12:00:00					
MOS	05-DEC-1989	REASON: --					MOS
HRS	4436	TECH:					HRS
AFL	2994	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: C/W731-A72-3388 - N/A							

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
990982U	AIRWORTHINESS DIRECTIVE AD90-03-04 #1 ENGINE							
	C/W	WARR	TRANSACTION DATE: 02-MAY-1990 12:00:00					
MOS	21-MAR-1990		REASON: --					MOS
MSC			TECH:					MSC
AFL			INSP:	LABOR HRS: 0	COST: \$0.00			AFL
990983U	AIRWORTHINESS DIRECTIVE AD90-03-04 #2 ENGINE							
	C/W	WARR	TRANSACTION DATE: 02-MAY-1990 12:00:00					
MOS	21-MAR-1990		REASON: --					MOS
MSC			TECH:					MSC
AFL			INSP:	LABOR HRS: 0	COST: \$0.00			AFL
910200	ACCOMPLISH SB 1124-55-020 REV 2 BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 24-MAY-1990 12:00:00					
MOS	30-APR-1990		REASON: --					MOS
HRS	4578		TECH:					HRS
AFL	3154		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
950500	SL WW-2450B INSP NACL CWL							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 24-MAY-1990 12:00:00					
MOS	30-APR-1990		REASON: --					MOS
HRS	4578		TECH:					HRS
AFL	3154		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - RPT 150 HRS								
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 24-MAY-1990 12:00:00					
MOS	30-APR-1990		REASON: --					MOS
HRS	4578		TECH:					HRS
AFL	3154		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
950780	SL WW-2478 L HYD PUMP							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 24-MAY-1990 12:00:00					
MOS	30-APR-1990		REASON: --					MOS
HRS	4578		TECH:					HRS
AFL	3154		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
950942	ACCOMPLISH SLWW-2494 REV 3 RMG BOLTS BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 24-MAY-1990 12:00:00					
MOS	30-APR-1990		REASON: --					MOS
HRS	4578		TECH:					HRS
AFL	3154		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
950941	ACCOMPLISH SLWW-2494 REV 3 LMG BOLTS BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 24-MAY-1990 12:00:00					
MOS	30-APR-1990		REASON: --					MOS
HRS	4578		TECH:					HRS
AFL	3154		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model : 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN						
CW	WARR	TRANSACTION DATE: 24-MAY-1990 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS 30-APR-1990		REASON: --					MOS
HRS 4578		TECH:					HRS
AFL 3154		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
950785	SL WW-2478 R HYD PUMP						
CW	WARR	TRANSACTION DATE: 24-MAY-1990 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS 30-APR-1990		REASON: --					MOS
HRS 4578		TECH:					HRS
AFL 3154		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
950570	SL WW-2457 PART A,R/H						
CW	WARR	TRANSACTION DATE: 24-MAY-1990 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS 30-APR-1990		REASON: --					MOS
HRS 4578		TECH:					HRS
AFL 3154		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - RPT 150 HRS							
950569	SL WW-2457 PART A,L/H						
CW	WARR	TRANSACTION DATE: 24-MAY-1990 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS 30-APR-1990		REASON: --					MOS
HRS 4578		TECH:					HRS
AFL 3154		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - RPT 150 HRS							
990131	ACCOMPLISH AD89-12-08 AIRWORTHINESS DIRECTIVE						
CW	WARR	TRANSACTION DATE: 11-JUN-1990 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS 30-APR-1990		REASON: --					MOS
HRS 4578		TECH:					HRS
AFL 3154		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: SUPS AD 86-14-02 - REF:550656							
910100	ACCOMPLISH SB1124-27-100R2 L/H RODS BULLETIN						
CW	WARR	TRANSACTION DATE: 06-JUL-1990 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS 20-JUN-1990		REASON: --					MOS
HRS 4621		TECH:					HRS
AFL 3211		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: SEE CODE 990985 - RPT 150 HRS							
1990-07-08 R1	TO PREVENT SMOKE, FIRE, AND POSSIBLE ELECTRICAL SHOCK, OR ELECTROMAGNETIC INTERFERENCE TO FLIGHT CRITICAL OR ESSENTIAL SYSTEMS AIRWORTHINESS DIRECTIVE						
CW	WARR	TRANSACTION DATE: 06-AUG-1990 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS		REASON: --					MOS
MSC		TECH:					MSC
AFL 0		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN						
CW	WARR	TRANSACTION DATE: 06-DEC-1990 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS 06-NOV-1990		REASON: --					MOS
HRS 4731		TECH:					HRS
AFL 3324		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							



AIRCRAFT Updates Report

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
950500	SL WW-2450B INSP NACL CWL							
	C/W	WARR	TRANSACTION DATE: 06-DEC-1990 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	06-NOV-1990		REASON: --					MOS
HRS	4731		TECH:					HRS
AFL	3324		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - RPT 150 HRS								
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN							
	C/W	WARR	TRANSACTION DATE: 06-DEC-1990 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	06-NOV-1990		REASON: --					MOS
HRS	4731		TECH:					HRS
AFL	3324		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
960078	ACCOMPLISH SIL1124-21-078 R2 35D SEN BULLETIN							
	C/W	WARR	TRANSACTION DATE: 06-DEC-1990 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	06-NOV-1990		REASON: --					MOS
HRS	4731		TECH:					HRS
AFL	3324		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: REPEAT								
1124-55-021 R3	STABILIZERS SERVICE BULLETIN							
	C/W	WARR	TRANSACTION DATE: 04-JUN-1991 12:00:00					
MOS			REASON: --					MOS
HRS	0		TECH:					HRS
AFL	0		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
900280	ACCOMPLISH SB WW 24-28A BULLETIN							
	C/W	WARR	TRANSACTION DATE: 09-JUL-1991 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	07-JUN-1991		REASON: --					MOS
HRS	4878		TECH:					HRS
AFL	3494		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: REF CODE 320120								
910101	ACCOMPLISH SB1124-27-100R2 R/H RODS BULLETIN							
	C/W	WARR	TRANSACTION DATE: 09-JUL-1991 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	07-JUN-1991		REASON: --					MOS
HRS	4878		TECH:					HRS
AFL	3494		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: SEE CODE 990986 - RPT 150 HRS								
910100	ACCOMPLISH SB1124-27-100R2 L/H RODS BULLETIN							
	C/W	WARR	TRANSACTION DATE: 09-JUL-1991 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	07-JUN-1991		REASON: --					MOS
HRS	4878		TECH:					HRS
AFL	3494		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: SEE CODE 990985 - RPT 150 HRS								
977040U	SERVICE BULLETIN SBTFE 731-A77-3020 R/H							
	C/W	WARR	TRANSACTION DATE: 09-JUL-1991 12:00:00					
MOS	11-JUN-1991		REASON: --					MOS
MSC			TECH:					MSC
AFL	3494		INSP:	LABOR HRS: 0	COST: \$0.00			AFL

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
977039U	SERVICE BULLETIN SBTFE731-A77-3020 L/H						
MOS	CW	WARR					
	11-JUN-1991						
MSC							MOS
AFL	3494						MSC
							AFL
			LABOR HRS: 0	COST: \$0.00			
972848U	SERVICE BULLETIN GSB TFE 731-A72-3432 R/H						
MOS	CW	WARR					
	07-JUN-1991						
MSC							MOS
AFL							MSC
							AFL
			LABOR HRS: 0	COST: \$0.00			
990986	ACCOMPLISH AD90-10-04 RIGHT AILERON AIRWORTHINESS DIRECTIVE						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	CW	WARR					
	07-JUN-1991						
HRS	4878						MOS
AFL	3494						HRS
							AFL
			LABOR HRS: 0	COST: \$0.00			
990985	ACCOMPLISH AD90-10-04 LEFT AILERON AIRWORTHINESS DIRECTIVE						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	CW	WARR					
	07-JUN-1991						
HRS	4878						MOS
AFL	3494						HRS
							AFL
			LABOR HRS: 0	COST: \$0.00			
Note: RPT							
990131	ACCOMPLISH AD89-12-08 AIRWORTHINESS DIRECTIVE						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	CW	WARR					
	07-JUN-1991						
HRS	4878						MOS
AFL	3494						HRS
							AFL
			LABOR HRS: 0	COST: \$0.00			
Note: SUPS AD 86-14-02 - REF:550656							
972847U	ACCOMPLISH BULLETIN GSB TFE 731-A72-3432 L/H						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	CW	WARR					
	07-JUN-1991						
HRS/MS							MOS
AFL							HRS/MS
							AFL
			LABOR HRS: 0	COST: \$0.00			
Note: N/A BY S/N							
960078	ACCOMPLISH SIL1124-21-078 R2 35D SEN BULLETIN						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	CW	WARR					
	07-JUN-1991						
HRS	4878						MOS
AFL	3494						HRS
							AFL
			LABOR HRS: 0	COST: \$0.00			
Note: REPEAT							
950942	ACCOMPLISH SLWW-2494 REV 3 RMG BOLTS BULLETIN						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	CW	WARR					
	07-JUN-1991						
HRS	4878						MOS
AFL	3494						HRS
							AFL
			LABOR HRS: 0	COST: \$0.00			
Note: OP 2,3							

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
950941	ACCOMPLISH SLWW-2494 REV 3 LMG BOLTS BULLETIN			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
C/W	WARR	TRANSACTION DATE: 09-JUL-1991 12:00:00						
MOS	07-JUN-1991	REASON: --					MOS	
HRS	4878	TECH:					HRS	
AFL	3494	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 2,3								
950500	SL WW-2450B INSP NACL CWL			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
C/W	WARR	TRANSACTION DATE: 09-JUL-1991 12:00:00						
MOS	11-JUN-1991	REASON: --					MOS	
HRS	4878	TECH:					HRS	
AFL	3494	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3 - RPT 150 HRS								
910200	ACCOMPLISH SB 1124-55-020 REV 2 BULLETIN			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
C/W	WARR	TRANSACTION DATE: 09-JUL-1991 12:00:00						
MOS	07-JUN-1991	REASON: --					MOS	
HRS	4878	TECH:					HRS	
AFL	3494	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
C/W	WARR	TRANSACTION DATE: 09-JUL-1991 12:00:00						
MOS	07-JUN-1991	REASON: --					MOS	
HRS	4878	TECH:					HRS	
AFL	3494	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3								
1124-55-097	STABILIZER SCISSR SERVICE BULLETIN			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
C/W	WARR	TRANSACTION DATE: 11-JUL-1991 12:00:00						
MOS		REASON: --					MOS	
MSC		TECH:					MSC	
AFL	0	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
990085U	AIRWORTHINESS DIRECTIVE AD81-24-08 #1 ENGINE			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
C/W	WARR	TRANSACTION DATE: 30-AUG-1991 12:00:00						
MOS	12-JUL-1991	REASON: --					MOS	
HRS	4879	TECH:					HRS	
AFL	3494	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
C/W	WARR	TRANSACTION DATE: 08-JAN-1992 12:00:00						
MOS	20-JUN-1991	REASON: --					MOS	
HRS	4878	TECH:					HRS	
AFL	3494	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3								
950942	ACCOMPLISH SLWW-2494 REV 3 RMG BOLTS BULLETIN			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
C/W	WARR	TRANSACTION DATE: 08-JAN-1992 12:00:00						
MOS	20-JUN-1991	REASON: --					MOS	
HRS	4878	TECH:					HRS	
AFL	3494	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 2,3								

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
950941	ACCOMPLISH SLWW-2494 REV 3 LMG BOLTS BULLETIN						
CW	WARR	TRANSACTION DATE: 08-JAN-1992 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	20-JUN-1991	REASON: --					MOS
HRS	4878	TECH:					HRS
AFL	3494	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3							
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN						
CW	WARR	TRANSACTION DATE: 08-JAN-1992 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	20-JUN-1991	REASON: --					MOS
HRS	4878	TECH:					HRS
AFL	3494	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
950500	SL WW-2450B INSP NACL CWL						
CW	WARR	TRANSACTION DATE: 08-JAN-1992 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	20-JUN-1991	REASON: --					MOS
HRS	4878	TECH:					HRS
AFL	3494	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - RPT 150 HRS							
950911	ACCOMPLISH SL WW-2491 REV 1 NLG BRGS BULLETIN						
CW	WARR	TRANSACTION DATE: 09-JAN-1992 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	19-JUN-1991	REASON: --					MOS
HRS	4878	TECH:					HRS
AFL	3478	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: REF TO CODE 320118 - RPT							
991040	ACCOMPLISH AD91-13-08 AIRWORTHINESS DIRECTIVE						
CW	WARR	TRANSACTION DATE: 09-JAN-1992 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	24-DEC-1991	REASON: --					MOS
HRS	5007	TECH:					HRS
AFL	3641	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: AD 91-13-08 - CW							
1990-14-06	SUPERSEDED BY AD1995-22-01 AIRWORTHINESS DIRECTIVE						
CW	WARR	TRANSACTION DATE: 09-JAN-1992 12:00:00					
MOS		REASON: --					MOS
MSC		TECH:					MSC
AFL	0	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN						
CW	WARR	TRANSACTION DATE: 05-FEB-1992 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	23-JAN-1992	REASON: --					MOS
HRS	5021	TECH:					HRS
AFL	3654	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
950500	SL WW-2450B INSP NACL CWL						
CW	WARR	TRANSACTION DATE: 05-FEB-1992 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	23-JAN-1992	REASON: --					MOS
HRS	5021	TECH:					HRS
AFL	3654	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - RPT 150 HRS							



AIRCRAFT Updates Report

Serial #: 368 Reg. #: N368MD
 Model: 1124A WESTWIND

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
990986	ACCOMPLISH AD90-10-04 RIGHT AILERON AIRWORTHINESS DIRECTIVE						
C/W	WARR	TRANSACTION DATE: 05-FEB-1992 12:00:00					
MOS	23-JAN-1992	REASON: --				MOS	
HRS	5021	TECH:				HRS	
AFL	3654	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3							
990985	ACCOMPLISH AD90-10-04 LEFT AILERON AIRWORTHINESS DIRECTIVE						
C/W	WARR	TRANSACTION DATE: 05-FEB-1992 12:00:00					
MOS	23-JAN-1992	REASON: --				MOS	
HRS	5021	TECH:				HRS	
AFL	3654	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3 - RPT							
990020	ACCOMPLISH AD74-08-09 R2 AIRWORTHINESS DIRECTIVE						
C/W	WARR	TRANSACTION DATE: 05-FEB-1992 12:00:00					
MOS	22-JAN-1992	REASON: --				MOS	
HRS	5021	TECH:				HRS	
AFL	3654	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: AD 74-08-09 - RPT 1000 HRS							
960078	ACCOMPLISH SIL1124-21-078 R2 35D SEN BULLETIN						
C/W	WARR	TRANSACTION DATE: 05-FEB-1992 12:00:00					
MOS	22-JAN-1992	REASON: --				MOS	
HRS	5021	TECH:				HRS	
AFL	3654	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3 - REPEAT							
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN						
C/W	WARR	TRANSACTION DATE: 05-FEB-1992 12:00:00					
MOS	23-JAN-1992	REASON: --				MOS	
HRS	5021	TECH:				HRS	
AFL	3654	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3							
960920	SIL1124-78-092						
C/W	WARR	TRANSACTION DATE: 07-AUG-1992 12:00:00					
MOS	29-JUL-1992	REASON: --				MOS	
HRS	5124	TECH:				HRS	
AFL	3746	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: C/W							
991065U	AIRWORTHINESS DIRECTIVE AD92-12-09 #1 ENGINE						
C/W	WARR	TRANSACTION DATE: 07-AUG-1992 12:00:00					
MOS	23-JUN-1992	REASON: --				MOS	
HRS	5122	TECH:				HRS	
AFL	3742	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
910200	ACCOMPLISH SB 1124-55-020 REV 2 BULLETIN						
C/W	WARR	TRANSACTION DATE: 10-NOV-1992 12:00:00					
MOS	29-OCT-1992	REASON: --				MOS	
HRS	5170	TECH:				HRS	
AFL	3802	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 2,3							

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
950500	SL WW-2450B INSP NACL CWL						
	C/W WARR	TRANSACTION DATE: 10-NOV-1992 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	01-NOV-1992	REASON: --					MOS
HRS	5170	TECH:					HRS
AFL	3802	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - RPT 150 HRS							
950942	ACCOMPLISH SLWW-2494 REV 3 RMG BOLTS BULLETIN						
	C/W WARR	TRANSACTION DATE: 10-NOV-1992 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	01-NOV-1992	REASON: --					MOS
HRS	5170	TECH:					HRS
AFL	3802	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3							
960078	ACCOMPLISH SIL1124-21-078 R2 35D SEN BULLETIN						
	C/W WARR	TRANSACTION DATE: 10-NOV-1992 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	01-NOV-1992	REASON: --					MOS
HRS	5170	TECH:					HRS
AFL	3802	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - REPEAT							
950941	ACCOMPLISH SLWW-2494 REV 3 LMG BOLTS BULLETIN						
	C/W WARR	TRANSACTION DATE: 10-NOV-1992 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	01-NOV-1992	REASON: --					MOS
HRS	5170	TECH:					HRS
AFL	3802	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3							
1992-12-02 RIGHT AILERON	TO PREVENT REDUCED CONTROLLABILITY OF THE AIRPLANE AIRWORTHINESS DIRECTIVE						
	C/W WARR	TRANSACTION DATE: 10-NOV-1992 12:00:00					
MOS		REASON: --					MOS
HRS	0	TECH:					HRS
AFL	0	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
1992-12-02 LEFT AILERON	TO PREVENT REDUCED CONTROLLABILITY OF THE AIRPLANE AIRWORTHINESS DIRECTIVE						
	C/W WARR	TRANSACTION DATE: 10-NOV-1992 12:00:00					
MOS		REASON: --					MOS
HRS	0	TECH:					HRS
AFL	0	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
1990-10-04 RIGHT AILERON	SUPERSEDED BY AD1992-12-02 AIRWORTHINESS DIRECTIVE						
	C/W WARR	TRANSACTION DATE: 10-NOV-1992 12:00:00					
MOS		REASON: --					MOS
HRS	0	TECH:					HRS
AFL	0	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
1990-10-04 LEFT AILERON	SUPERSEDED BY AD1992-12-02 AIRWORTHINESS DIRECTIVE						
	C/W WARR	TRANSACTION DATE: 10-NOV-1992 12:00:00					
MOS		REASON: --					MOS
MSC		TECH:					MSC
AFL	0	INSP:	LABOR HRS: 0	COST: \$0.00			AFL



AIRCRAFT Updates Report

Serial #: 368 Reg. #: N368MD
 Model: 1124A WESTWIND

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
990986	ACCOMPLISH AD90-10-04 RIGHT AILERON AIRWORTHINESS DIRECTIVE							
C/W	WARR	TRANSACTION DATE: 10-NOV-1992 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	29-OCT-1992	REASON: --						MOS
HRS/MSC		TECH:						HRS/MSC
AFL		INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: SUPSD BY AD92-12-02 - N/A								
990985	ACCOMPLISH AD90-10-04 LEFT AILERON AIRWORTHINESS DIRECTIVE							
C/W	WARR	TRANSACTION DATE: 10-NOV-1992 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	29-OCT-1992	REASON: --						MOS
HRS/MSC		TECH:						HRS/MSC
AFL		INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: SUPSD BY AD92-12-02 - N/A								
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN							
C/W	WARR	TRANSACTION DATE: 10-NOV-1992 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	01-NOV-1992	REASON: --						MOS
HRS	5170	TECH:						HRS
AFL	3802	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN							
C/W	WARR	TRANSACTION DATE: 10-NOV-1992 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	29-OCT-1992	REASON: --						MOS
HRS	5170	TECH:						HRS
AFL	3802	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
991070	ACCOMPLISH AD92-12-02 LEFT AILERON AIRWORTHINESS DIRECTIVE							
C/W	WARR	TRANSACTION DATE: 30-NOV-1992 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	20-JUN-1992	REASON: --						MOS
HRS	4878	TECH:						HRS
AFL	3494	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: REPLACED RODS - C/W								
991071	ACCOMPLISH AD92-12-02 RIGHT AILERON AIRWORTHINESS DIRECTIVE							
C/W	WARR	TRANSACTION DATE: 30-NOV-1992 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	20-JUN-1991	REASON: --						MOS
HRS	4878	TECH:						HRS
AFL	3494	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: REPLACED RODS - C/W								
972A07U	ACCOMPLISH BULLETIN G/SBA72-3504 L/ENG REV 1							
C/W	WARR	TRANSACTION DATE: 07-JAN-1993 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	28-DEC-1992	REASON: --						MOS
HRS	5201	TECH:						HRS
AFL	3842	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: N/A								
1124-27-100 R2 L/H RODS	FLIGHT CONTROLS SERVICE BULLETIN							
C/W	WARR	TRANSACTION DATE: 07-JAN-1993 12:00:00						
MOS		REASON: --						MOS
MSC		TECH:						MSC
AFL	0	INSP:		LABOR HRS: 0	COST: \$0.00			AFL

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
1124-27-100 R2	R/H RODS	FLIGHT CONTROLS SERVICE BULLETIN					
	C/W	WARR	TRANSACTION DATE: 07-JAN-1993 12:00:00				
MOS			REASON: --				MOS
HRS	0		TECH:				HRS
AFL	0		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
972547		731-A72-3474 RTR DISC L/H					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 07-JAN-1993 12:00:00				
MOS	28-DEC-1992		REASON: --				MOS
HRS	5201		TECH:				HRS
AFL	3842		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
			Note: N/A BY S/N				
972548		731-A72-3474 RTR DISC R/H					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 07-JAN-1993 12:00:00				
MOS	28-DEC-1992		REASON: --				MOS
HRS	5201		TECH:				HRS
AFL	3842		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
			Note: N/A BY S/N				
972220		G/SB73-3110 RIGHT ENGINE					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 07-JAN-1993 12:00:00				
MOS	28-DEC-1992		REASON: --				MOS
HRS	5201		TECH:				HRS
AFL	3842		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
			Note: N/A				
972A08U		ACCOMPLISH BULLETIN G/SBA72-3504 R/ENG REV 1					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 07-JAN-1993 12:00:00				
MOS	28-DEC-1992		REASON: --				MOS
HRS	5201		TECH:				HRS
AFL	3842		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
			Note: N/A				
972219		G/SB73-3110 LEFT ENGINE					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 07-JAN-1993 12:00:00				
MOS	28-DEC-1992		REASON: --				MOS
HRS	5201		TECH:				HRS
AFL	3842		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
			Note: N/A				
991090U		ACCOMPLISH AIRWORTHINESS DIRECTIVE AD92-26-09 #1 ENGINE					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 08-FEB-1993 12:00:00				
MOS	25-JAN-1993		REASON: --				MOS
HRS	5209		TECH:				HRS
AFL	3855		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
			Note: N/A				
991091U		ACCOMPLISH AIRWORTHINESS DIRECTIVE AD92-26-09 #2 ENGINE					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 08-FEB-1993 12:00:00				
MOS	25-JAN-1993		REASON: --				MOS
HRS	5209		TECH:				HRS
AFL	3855		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
			Note: N/A				

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
	C/W	WARR	TRANSACTION DATE: 01-MAR-1993 12:00:00					
MOS	08-FEB-1993		REASON: --					MOS
HRS	5216		TECH:					HRS
AFL	3864		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1 THRU 12								
1993-04-02 PARA A	TO PREVENT A MID-AIR COLLISION OR A NEAR-MISS SITUATION CAUSED BY FAILURE OF THESE MODE S TRANSPONDERS AIR WORTHINESS DIRECTIVE							
	C/W	WARR	TRANSACTION DATE: 03-MAY-1993 12:00:00					
MOS			REASON: --					MOS
MSC			TECH:					MSC
AFL	0		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
1993-04-02 PARA B	TO PREVENT A MID-AIR COLLISION OR A NEAR-MISS SITUATION CAUSED BY FAILURE OF THESE MODE S TRANSPONDERS AIR WORTHINESS DIRECTIVE							
	C/W	WARR	TRANSACTION DATE: 03-MAY-1993 12:00:00					
MOS			REASON: --					MOS
MSC			TECH:					MSC
AFL	0		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
	C/W	WARR	TRANSACTION DATE: 04-MAY-1993 12:00:00					
MOS	30-APR-1993		REASON: --					MOS
HRS	5270		TECH:					HRS
AFL	3920		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,5,8,11								
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
	C/W	WARR	TRANSACTION DATE: 04-MAY-1993 12:00:00					
MOS	30-APR-1993		REASON: --					MOS
HRS	5270		TECH:					HRS
AFL	3920		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1 THRU 12								
960078	ACCOMPLISH SIL1124-21-078 R2 35D SEN BULLETIN			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
	C/W	WARR	TRANSACTION DATE: 04-MAY-1993 12:00:00					
MOS	30-APR-1993		REASON: --					MOS
HRS	5270		TECH:					HRS
AFL	3920		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,5,8,11 - REPEAT								
972A03U	SERVICE BULLETIN G/SB72-3502 #1 ENGINE							
	C/W	WARR	TRANSACTION DATE: 08-JUN-1993 12:00:00					
MOS	31-MAY-1993		REASON: --					MOS
MSC			TECH:					MSC
AFL	3928		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
991030U	AIR WORTHINESS DIRECTIVE AD91-08-13 #2 ENGINE							
	C/W	WARR	TRANSACTION DATE: 08-JUN-1993 12:00:00					
MOS	31-MAY-1993		REASON: --					MOS
MSC			TECH:					MSC
AFL	3928		INSP:	LABOR HRS: 0	COST: \$0.00			AFL

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model : 1124A WESTWIND

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
972A04U	SERVICE BULLETIN G/SB72-3502 #2 ENGINE							
CW	WARR	TRANSACTION DATE: 08-JUN-1993 12:00:00						
MOS	31-MAY-1993	REASON: --				MOS		
HRS	527.8	TECH:				HRS		
AFL	392.8	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
950911	ACCOMPLISH SL WW-2491 REV 1 NLG BRGS BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
CW	WARR	TRANSACTION DATE: 09-JUL-1993 12:00:00						
MOS	24-JUN-1993	REASON: --				MOS		
HRS	528.8	TECH:				HRS		
AFL	394.7	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: REF TO CODE 320118 - RPT								
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
CW	WARR	TRANSACTION DATE: 08-OCT-1993 12:00:00						
MOS	03-AUG-1993	REASON: --				MOS		
HRS	531.8	TECH:				HRS		
AFL	397.3	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1 THRU 12								
991091U	ACCOMPLISH AIRWORTHINESS DIRECTIVE AD92-26-09 #2 ENGINE							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
CW	WARR	TRANSACTION DATE: 08-OCT-1993 12:00:00						
MOS	30-SEP-1993	REASON: --				MOS		
HRS	534.3	TECH:				HRS		
AFL	399.7	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: N/A								
972B07U	SERVICE BULLETIN G/SBA72-3504 L/ENG REV 1							
CW	WARR	TRANSACTION DATE: 08-OCT-1993 12:00:00						
MOS	30-SEP-1993	REASON: --				MOS		
HRS	534.3	TECH:				HRS		
AFL	399.7	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
991115U	AIRWORTHINESS DIRECTIVE AD93-10-10 #1 ENGINE							
CW	WARR	TRANSACTION DATE: 08-OCT-1993 12:00:00						
MOS	29-SEP-1993	REASON: --				MOS		
MSC		TECH:				MSC		
AFL	399.7	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
991090U	AIRWORTHINESS DIRECTIVE AD92-26-09 #1 ENGINE							
CW	WARR	TRANSACTION DATE: 08-OCT-1993 12:00:00						
MOS	30-SEP-1993	REASON: --				MOS		
MSC		TECH:				MSC		
AFL		INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
972B08U	SERVICE BULLETIN G/SBA72-3504 R/ENG REV 1							
CW	WARR	TRANSACTION DATE: 08-OCT-1993 12:00:00						
MOS	30-SEP-1993	REASON: --				MOS		
HRS	534.3	TECH:				HRS		
AFL	399.7	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
911190U	SERVICE BULLETIN SB1124-26-119 FIRE EXTGHR							
CW	WARR	TRANSACTION DATE: 08-OCT-1993 12:00:00						
MOS	29-SEP-1993	REASON: --				MOS		
MSC		TECH:				MSC		
AFL	399.7	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
991120U	AIRWORTHINESS DIRECTIVE AD93-10-10 #2 ENGINE							
	C/W	WARR	TRANSACTION DATE: 08-OCT-1993 12:00:00					
MOS	29-SEP-1993		REASON: --				MOS	
HRS	5343		TECH:				HRS	
AFL	3997		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
950180	SL WW-2424D,L FLEX SHAFT							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 04-NOV-1993 12:00:00					
MOS	01-DEC-1992		REASON: --				MOS	
HRS	5188		TECH:				HRS	
AFL	3829		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: REF: CODE 270280								
950185	SL WW-2424D,R FLEX SHAFT							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 04-NOV-1993 12:00:00					
MOS	01-DEC-1992		REASON: --				MOS	
HRS	5188		TECH:				HRS	
AFL	3829		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: REF: CODE 270285								
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 25-JAN-1994 12:00:00					
MOS	24-NOV-1993		REASON: --				MOS	
HRS	5367		TECH:				HRS	
AFL	4023		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1 THRU 12								
972A07U	SERVICE BULLETIN G/SBA72-3504 L/ENG REV 1							
	C/W	WARR	TRANSACTION DATE: 08-MAR-1994 12:00:00					
MOS	25-FEB-1994		REASON: --				MOS	
HRS	5408		TECH:				HRS	
AFL	4066		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
972A87U	SERVICE BULLETIN SB TFE731-A72-3544 LH ENG							
	C/W	WARR	TRANSACTION DATE: 08-MAR-1994 12:00:00					
MOS	17-FEB-1994		REASON: --				MOS	
HRS	5404		TECH:				HRS	
AFL	4062		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
972A88U	SERVICE BULLETIN SB TFE731-A72-3544 RH ENG							
	C/W	WARR	TRANSACTION DATE: 08-MAR-1994 12:00:00					
MOS	17-FEB-1994		REASON: --				MOS	
HRS	5404		TECH:				HRS	
AFL	4062		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
972A08U	SERVICE BULLETIN G/SBA72-3504 R/ENG REV 1							
	C/W	WARR	TRANSACTION DATE: 08-MAR-1994 12:00:00					
MOS	25-FEB-1994		REASON: --				MOS	
HRS	5408		TECH:				HRS	
AFL	4066		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model : 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR	
910200	ACCOMPLISH SB 1124-55-020 REV 2 BULLETIN						
CW	WARR						
MOS	24-MAR-1994	TRANSACTION DATE: 07-APR-1994 12:00:00				Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
HRS	5417	REASON: --				MOS	
AFL	4076	TECH:				HRS	
		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 5,11							
991351U	AIRWORTHINESS DIRECTIVE AD93-25-16 #2 ENGINE						
CW	WARR						
MOS	07-MAR-1994	TRANSACTION DATE: 07-APR-1994 12:00:00				MOS	
HRS	5411	REASON: --				HRS	
AFL	4070	TECH:	LABOR HRS: 0	COST: \$0.00		AFL	
		INSP:					
973242U	SERVICE BULLETIN GSB 73-3121 R/E FUEL CONT						
CW	WARR						
MOS	07-MAR-1994	TRANSACTION DATE: 07-APR-1994 12:00:00				MOS	
HRS	5411	REASON: --				HRS	
AFL	4070	TECH:	LABOR HRS: 0	COST: \$0.00		AFL	
		INSP:					
973241U	SERVICE BULLETIN GSB 73-3121 L/E FUEL CONT						
CW	WARR						
MOS	07-MAR-1994	TRANSACTION DATE: 07-APR-1994 12:00:00				MOS	
MSC		REASON: --				MSC	
AFL	4070	TECH:	LABOR HRS: 0	COST: \$0.00		AFL	
		INSP:					
991350U	ACCOMPLISH AIRWORTHINESS DIRECTIVE AD93-25-16 #1 ENGINE						
CW	WARR						
MOS	07-MAR-1994	TRANSACTION DATE: 07-APR-1994 12:00:00				Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
HRS	5411	REASON: --				MOS	
AFL	4070	TECH:	LABOR HRS: 0	COST: \$0.00		HRS	
		INSP:				AFL	
Note: SUPSDS AD92-26-09 - N/A							
960078	ACCOMPLISH SIL1124-21-078 R2 35D SEN BULLETIN						
CW	WARR						
MOS	24-MAR-1994	TRANSACTION DATE: 07-APR-1994 12:00:00				Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
HRS	5417	REASON: --				MOS	
AFL	4076	TECH:	LABOR HRS: 0	COST: \$0.00		HRS	
		INSP:				AFL	
Note: OP 2,5,8,11 - REPEAT							
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN						
CW	WARR						
MOS	24-MAR-1994	TRANSACTION DATE: 07-APR-1994 12:00:00				Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
HRS	5417	REASON: --				MOS	
AFL	4076	TECH:	LABOR HRS: 0	COST: \$0.00		HRS	
		INSP:				AFL	
Note: OP 1 THRU 12							
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN						
CW	WARR						
MOS	24-MAR-1994	TRANSACTION DATE: 07-APR-1994 12:00:00				Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
HRS	5417	REASON: --				MOS	
AFL	4076	TECH:	LABOR HRS: 0	COST: \$0.00		HRS	
		INSP:				AFL	
Note: OP 2,5,8,11							

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
C/W	WARR	TRANSACTION DATE: 12-JUL-1994 12:00:00						
MOS	02-JUL-1994	REASON: --				MOS		
HRS	5463	TECH:				HRS		
AFL	4135	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1 THRU 12								
972B13U	SERVICE BULLETIN REPL LE 1ST STG LP TURB							
C/W	WARR	TRANSACTION DATE: 08-AUG-1994 12:00:00						
MOS	27-JUL-1994	REASON: --				MOS		
HRS	5472	TECH:				HRS		
AFL	4150	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
972B14U	SERVICE BULLETIN REPL LE 2ND STG LP TURB							
C/W	WARR	TRANSACTION DATE: 08-AUG-1994 12:00:00						
MOS	27-JUL-1994	REASON: --				MOS		
HRS	5472	TECH:				HRS		
AFL	4150	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
972B15U	SERVICE BULLETIN REPL RE 1ST STG LP TURB							
C/W	WARR	TRANSACTION DATE: 08-AUG-1994 12:00:00						
MOS	27-JUL-1994	REASON: --				MOS		
MSC		TECH:				MSC		
AFL	4150	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
972B16U	SERVICE BULLETIN REPL RE 2ND STG LP TURB							
C/W	WARR	TRANSACTION DATE: 08-AUG-1994 12:00:00						
MOS	27-JUL-1994	REASON: --				MOS		
HRS	5472	TECH:				HRS		
AFL	4150	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
991370	AD94-07-03 PARA A AIRWORTHINESS DIRECTIVE							
C/W	WARR	TRANSACTION DATE: 10-AUG-1994 12:00:00						
MOS		REASON: --				MOS		
HRS	0	TECH:				HRS		
AFL	0	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
950911	ACCOMPLISH SL WW-2491 REV 1 NLG BRGS BULLETIN			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
C/W	WARR	TRANSACTION DATE: 09-SEP-1994 12:00:00						
MOS	10-AUG-1994	REASON: --				MOS		
HRS	5476	TECH:				HRS		
AFL	4158	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: REF TO CODE 320118 - RPT								
950942	ACCOMPLISH SLWW-2494 REV 3 RMG BOLTS BULLETIN			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
C/W	WARR	TRANSACTION DATE: 09-SEP-1994 12:00:00						
MOS	10-AUG-1994	REASON: --				MOS		
HRS	5476	TECH:				HRS		
AFL	4158	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: RPT 300 HRS								

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
950941	ACCOMPLISH SLWW-2494 REV 3 LMG BOLTS BULLETIN				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 09-SEP-1994 12:00:00					
MOS	10-AUG-1994	REASON: --			MOS		
HRS	5476	TECH:			HRS		
AFL	4158	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: RPT 300 HRS							
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 11-JAN-1995 12:00:00					
MOS	24-NOV-1994	REASON: --			MOS		
HRS	5516	TECH:			HRS		
AFL	4206	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1 THRU 12							
1994-21-06	TO PREVENT THE INABILITY OF PASSENGERS OR CREW TO EGRESS FROM THEIR SEATS DURING AN EMERGENCY SITUATION, DUE TO PROBLEMS ASSOCIATED WITH THE LAP BELT ASSEMBLY AIRWORTHINESS DIRECTIVE						
CW	WARR	TRANSACTION DATE: 07-MAR-1995 12:00:00					
MOS		REASON: --			MOS		
MSC		TECH:			MSC		
AFL	0	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
991020U	AIRWORTHINESS DIRECTIVE AD91-08-13 #1 ENGINE						
CW	WARR	TRANSACTION DATE: 22-MAR-1995 12:00:00					
MOS	26-APR-1994	REASON: --			MOS		
MSC		TECH:			MSC		
AFL	4106	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
991350U	AIRWORTHINESS DIRECTIVE AD93-25-16 #1 ENGINE						
CW	WARR	TRANSACTION DATE: 22-MAR-1995 12:00:00					
MOS	26-APR-1994	REASON: --			MOS		
HRS	5442	TECH:			HRS		
AFL	4106	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
991091U	AIRWORTHINESS DIRECTIVE AD92-26-09 #2 ENGINE						
CW	WARR	TRANSACTION DATE: 22-MAR-1995 12:00:00					
MOS	26-APR-1994	REASON: --			MOS		
MSC		TECH:			MSC		
AFL	4106	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 12-APR-1995 12:00:00					
MOS	02-MAR-1995	REASON: --			MOS		
HRS	5570	TECH:			HRS		
AFL	4251	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 2,5,8,11							
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 12-APR-1995 12:00:00					
MOS	02-MAR-1995	REASON: --			MOS		
HRS	5570	TECH:			HRS		
AFL	4251	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1 THRU 12							

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
960078	ACCOMPLISH SIL1124-21-078 R2 35D SEN BULLETIN					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 12-APR-1995 12:00:00						
MOS	02-MAR-1995	REASON: --				MOS		
HRS	5570	TECH:				HRS		
AFL	4251	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 2,5,8,11 - REPEAT								
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 06-JUN-1995 12:00:00						
MOS	14-APR-1995	REASON: --				MOS		
HRS	5618	TECH:				HRS		
AFL	4287	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1 THRU 12								
911160U	SERVICE BULLETIN SB1124-32-116 L/G N/W STR							
C/W	WARR	TRANSACTION DATE: 08-JUN-1995 12:00:00						
MOS	01-JUN-1995	REASON: --				MOS		
MSC		TECH:				MSC		
AFL	4310	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 28-JUL-1995 12:00:00						
MOS	23-JUN-1995	REASON: --				MOS		
HRS	5666	TECH:				HRS		
AFL	4331	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1 THRU 12								
911290	ACCOMPLISH SB1124-27-129 L AILERON BULLETIN					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 09-NOV-1995 12:00:00						
MOS	16-AUG-1995	REASON: --				MOS		
HRS	5702	TECH:				HRS		
AFL	4372	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 6 - RPT								
911291	ACCOMPLISH SB1124-27-129 R AILERON BULLETIN					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 09-NOV-1995 12:00:00						
MOS	16-AUG-1995	REASON: --				MOS		
HRS	5702	TECH:				HRS		
AFL	4372	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 6 - RPT								
972B53U	SERVICE BULLETIN GSBA72-3578 LEFT ENGINE							
C/W	WARR	TRANSACTION DATE: 10-NOV-1995 12:00:00						
MOS	31-OCT-1995	REASON: --				MOS		
MSC		TECH:				MSC		
AFL	4390	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
972656U	SERVICE BULLETIN GSBA72-3328 R5 RIGHT ENG							
C/W	WARR	TRANSACTION DATE: 10-NOV-1995 12:00:00						
MOS	31-OCT-1995	REASON: --				MOS		
HRS	5714	TECH:				HRS		
AFL	4390	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
972B54U	SERVICE BULLETIN GSBA72-3578 RIGHT ENGINE						
C/W	WARR	TRANSACTION DATE: 10-NOV-1995 12:00:00					
MOS	31-OCT-1995	REASON: --					MOS
HRS	5714	TECH:					HRS
AFL	4390	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
972655U	SERVICE BULLETIN GSBA72-3328 R5 LEFT ENG						
C/W	WARR	TRANSACTION DATE: 10-NOV-1995 12:00:00					
MOS	31-OCT-1995	REASON: --					MOS
HRS	5714	TECH:					HRS
AFL	4390	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
910200	ACCOMPLISH SB 1124-55-020 REV 2 BULLETIN						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 08-DEC-1995 12:00:00					
MOS	13-NOV-1995	REASON: --					MOS
HRS	5718	TECH:					HRS
AFL	4397	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 5,11							
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 08-DEC-1995 12:00:00					
MOS	13-NOV-1995	REASON: --					MOS
HRS	5718	TECH:					HRS
AFL	4397	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1 THRU 12							
960078	SIL1124-21-078 R2 35D SEN SERVICE BULLETIN						
C/W	WARR	TRANSACTION DATE: 08-DEC-1995 12:00:00					
MOS		REASON: --					MOS
MSC		TECH:					MSC
AFL	0	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 08-DEC-1995 12:00:00					
MOS	13-NOV-1995	REASON: --					MOS
HRS	5718	TECH:					HRS
AFL	4397	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,5,8,11							
911140	SB1124-78-114						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 30-JAN-1996 12:00:00					
MOS	08-DEC-1995	REASON: --					MOS
HRS	5718	TECH:					HRS
AFL	4397	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: C/W							
991510	ACCOMPLISH AD95-22-01 AIRWORTHINESS DIRECTIVE						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 02-FEB-1996 12:00:00					
MOS	04-JAN-1996	REASON: --					MOS
HRS	5718	TECH:					HRS
AFL	4397	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: C/W							

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
900280	ACCOMPLISH SB WW 24-28A BULLETIN							
	C/W	WARR	TRANSACTION DATE: 13-NOV-1996 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	09-NOV-1996		REASON: --					MOS
HRS	5951		TECH:					HRS
AFL	4589		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: REF CODE 320120								
1124-27-133 R1	FLIGHT CONTROLS SERVICE BULLETIN							
	C/W	WARR	TRANSACTION DATE: 13-NOV-1996 12:00:00					
MOS			REASON: --					MOS
HRS	0		TECH:					HRS
AFL	0		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
950911	ACCOMPLISH SL WW-2491 REV 1 NLG BRGS BULLETIN							
	C/W	WARR	TRANSACTION DATE: 13-NOV-1996 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	09-NOV-1996		REASON: --					MOS
HRS	5951		TECH:					HRS
AFL	4589		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: REF TO CODE 320118 - RPT								
990020	ACCOMPLISH AD74-08-09 R2 AIRWORTHINESS DIRECTIVE							
	C/W	WARR	TRANSACTION DATE: 13-NOV-1996 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	09-NOV-1996		REASON: --					MOS
HRS	5951		TECH:					HRS
AFL	4589		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: EFFECTIVE 07-29-96 - RPT 1000 HRS								
1991-13-08	TO PREVENT THE INABILITY TO EXTEND THE NOSE LANDING GEAR FOR LANDING AIRWORTHINESS DIRECTIVE							
	C/W	WARR	TRANSACTION DATE: 13-NOV-1996 12:00:00					
MOS			REASON: --					MOS
MSC			TECH:					MSC
AFL	0		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
910200	ACCOMPLISH SB 1124-55-020 REV 2 BULLETIN							
	C/W	WARR	TRANSACTION DATE: 15-NOV-1996 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	09-NOV-1996		REASON: --					MOS
HRS	5951		TECH:					HRS
AFL	4589		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN							
	C/W	WARR	TRANSACTION DATE: 15-NOV-1996 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	09-NOV-1996		REASON: --					MOS
HRS	5951		TECH:					HRS
AFL	4589		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
911291	ACCOMPLISH SB1124-27-129 R AILERON BULLETIN							
	C/W	WARR	TRANSACTION DATE: 15-NOV-1996 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	09-NOV-1996		REASON: --					MOS
HRS	5951		TECH:					HRS
AFL	4589		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 3 - RPT								

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR	
911290	ACCOMPLISH SB1124-27-129 L AILERON BULLETIN						
C/W	WARR						
	TRANSACTION DATE: 15-NOV-1996 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
MOS	09-NOV-1996					MOS	
HRS	5951					HRS	
AFL	4589					AFL	
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Note: OP 3 - RPT						
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN						
C/W	WARR						
	TRANSACTION DATE: 15-NOV-1996 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
MOS	09-NOV-1996					MOS	
HRS	5951					HRS	
AFL	4589					AFL	
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Note: OP 1,2,3						
910200	ACCOMPLISH SB 1124-55-020 REV 2 BULLETIN						
C/W	WARR						
	TRANSACTION DATE: 01-JUL-1997 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
MOS	16-JUN-1997					MOS	
HRS	6135					HRS	
AFL	4707					AFL	
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Note: OP 2,3						
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN						
C/W	WARR						
	TRANSACTION DATE: 01-JUL-1997 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
MOS	16-JUN-1997					MOS	
HRS	6135					HRS	
AFL	4707					AFL	
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Note: OP 1,2,3						
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN						
C/W	WARR						
	TRANSACTION DATE: 01-JUL-1997 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
MOS	16-JUN-1997					MOS	
HRS	6135					HRS	
AFL	4707					AFL	
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Note: OP 1,2,3						
910860	SB 1124-27-086						
C/W	WARR						
	TRANSACTION DATE: 01-JUL-1997 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
MOS	09-NOV-1996					MOS	
HRS	5951					HRS	
AFL	4589					AFL	
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Note: C/W						
911290	ACCOMPLISH SB1124-27-129 L AILERON BULLETIN						
C/W	WARR						
	TRANSACTION DATE: 07-JUL-1997 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
MOS	16-JUN-1997					MOS	
HRS	6135					HRS	
AFL	4707					AFL	
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Note: RPT						
911291	ACCOMPLISH SB1124-27-129 R AILERON BULLETIN						
C/W	WARR						
	TRANSACTION DATE: 07-JUL-1997 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
MOS	16-JUN-1997					MOS	
HRS	6135					HRS	
AFL	4707					AFL	
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Note: RPT						



AIRCRAFT Updates Report

Serial #: 368 Reg. #: N368MD
 Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
990131	ACCOMPLISH AD89-12-08 AIRWORTHINESS DIRECTIVE							
	C/W	WARR	TRANSACTION DATE: 07-JUL-1997 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	16-JUN-1997		REASON: --					MOS
HRS	6135		TECH:					HRS
AFL	4707		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: EFFECTIVE 07-10-89 - REF:550656								
991561	ACCOMPLISH AD96-24-11 RIGHT AILERON AIRWORTHINESS DIRECTIVE							
	C/W	WARR	TRANSACTION DATE: 07-JUL-1997 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	16-JUN-1997		REASON: --					MOS
HRS	6135		TECH:					HRS
AFL	4707		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: EFFECTIVE 01-06-97								
1997-05-03 R1	TO PREVENT DEVIATION FROM AN INTENDED FLIGHT PATH DURING A NON-PRECISION APPROACH TO AN AIRPORT CAUSED BY INACCURATE INFORMATION FROM THE GPS FLIGHT MANAGEMENT SYSTEM AIRWORTHINESS DIRECTIVE							
	C/W	WARR	TRANSACTION DATE: 07-JUL-1997 12:00:00					
MOS			REASON: --					MOS
HRS	0		TECH:					HRS
AFL	0		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
991560	ACCOMPLISH AD96-24-11 LEFT AILERON AIRWORTHINESS DIRECTIVE							
	C/W	WARR	TRANSACTION DATE: 07-JUL-1997 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	16-JUN-1997		REASON: --					MOS
HRS	6135		TECH:					HRS
AFL	4707		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: EFFECTIVE 01-06-97								
990280	ACCOMPLISH SB WW 24-28A BULLETIN							
	C/W	WARR	TRANSACTION DATE: 08-APR-1998 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	06-APR-1998		REASON: --					MOS
HRS	6346		TECH:					HRS
AFL	4787		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: REF CODE 320120								
9950911	ACCOMPLISH SL WW-2491 REV 1 NLG BRGS BULLETIN							
	C/W	WARR	TRANSACTION DATE: 08-APR-1998 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	06-APR-1998		REASON: --					MOS
HRS	6346		TECH:					HRS
AFL	4787		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: REF TO CODE 320118 - RPT								
991510	ACCOMPLISH AD95-22-01 AIRWORTHINESS DIRECTIVE							
	C/W	WARR	TRANSACTION DATE: 08-APR-1998 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	06-APR-1998		REASON: --					MOS
HRS	6346		TECH:					HRS
AFL	4787		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: EFFECTIVE 12-04-95 - C/W								
9950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN							
	C/W	WARR	TRANSACTION DATE: 08-APR-1998 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	06-APR-1998		REASON: --					MOS
HRS	6346		TECH:					HRS
AFL	4787		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN						
C/W	WARR	TRANSACTION DATE: 08-APR-1998 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	06-APR-1998	REASON: --					MOS
HRS	6346	TECH:					HRS
AFL	4787	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
911360	ACCOMPLISH SB1124-27-136 HORZ TRIM BULLETIN						
C/W	WARR	TRANSACTION DATE: 11-JUN-1998 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	06-APR-1998	REASON: --					MOS
HRS	6346	TECH:					HRS
AFL	4787	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
911390	ACCOMPLISH SB1124-32-139 UPR STRG BULLETIN						
C/W	WARR	TRANSACTION DATE: 11-JUN-1998 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	06-APR-1998	REASON: --					MOS
HRS	6346	TECH:					HRS
AFL	4787	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: RPT C CHECK							
910200	ACCOMPLISH SB 1124-55-020 REV 2 BULLETIN						
C/W	WARR	TRANSACTION DATE: 02-DEC-1998 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-OCT-1998	REASON: --					MOS
HRS	6520	TECH:					HRS
AFL	4889	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3							
911390	ACCOMPLISH SB1124-32-139 UPR STRG BULLETIN						
C/W	WARR	TRANSACTION DATE: 02-DEC-1998 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-OCT-1998	REASON: --					MOS
HRS	6520	TECH:					HRS
AFL	4889	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 3 - RPT C CHECK							
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN						
C/W	WARR	TRANSACTION DATE: 02-DEC-1998 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-OCT-1998	REASON: --					MOS
HRS	6520	TECH:					HRS
AFL	4889	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
973665U	SERVICE BULLETIN SB731-A72-3636R1 R/E						
C/W	WARR	TRANSACTION DATE: 02-DEC-1998 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-OCT-1998	REASON: --					MOS
HRS	6520	TECH:					HRS
AFL	4889	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
973636U	SERVICE BULLETIN SB731-A72-3636R1 L/E						
C/W	WARR	TRANSACTION DATE: 02-DEC-1998 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-OCT-1998	REASON: --					MOS
MSC		TECH:					MSC
AFL	4889	INSP:	LABOR HRS: 0	COST: \$0.00			AFL



AIRCRAFT Updates Report

Serial #: 368 Reg. #: N368MD
 Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN							
	C/W	WARR	TRANSACTION DATE: 02-DEC-1998 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-OCT-1998		REASON: --					MOS
HRS	6520		TECH:					HRS
AFL	4889		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
911290	ACCOMPLISH SB1124-27-129 L AILERON BULLETIN							
	C/W	WARR	TRANSACTION DATE: 03-DEC-1998 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-OCT-1998		REASON: --					MOS
HRS	6520		TECH:					HRS
AFL	4889		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: RPT								
990020	ACCOMPLISH AD74-08-09 R2 AIRWORTHINESS DIRECTIVE							
	C/W	WARR	TRANSACTION DATE: 03-DEC-1998 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-OCT-1998		REASON: --					MOS
HRS	6520		TECH:					HRS
AFL	4889		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: EFFECTIVE 07-29-96 - RPT 1000 HRS								
991560	ACCOMPLISH AD96-24-11 LEFT AILERON AIRWORTHINESS DIRECTIVE							
	C/W	WARR	TRANSACTION DATE: 03-DEC-1998 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-OCT-1998		REASON: --					MOS
HRS	6520		TECH:					HRS
AFL	4889		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: EFFECTIVE 01-06-97								
991625U	AIRWORTHINESS DIRECTIVE AD98-17-01 R1 R/E							
	C/W	WARR	TRANSACTION DATE: 03-DEC-1998 12:00:00					
MOS	06-OCT-1998		REASON: --					MOS
MSC			TECH:					MSC
AFL	4889		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
991620U	AIRWORTHINESS DIRECTIVE AD98-17-01 R1 L/E							
	C/W	WARR	TRANSACTION DATE: 03-DEC-1998 12:00:00					
MOS	06-OCT-1998		REASON: --					MOS
MSC			TECH:					MSC
AFL	4889		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
991581U	AIRWORTHINESS DIRECTIVE AD97-04-03 #2 ENGINE							
	C/W	WARR	TRANSACTION DATE: 03-DEC-1998 12:00:00					
MOS	17-OCT-1998		REASON: --					MOS
MSC			TECH:					MSC
AFL	4889		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
991580U	AIRWORTHINESS DIRECTIVE AD97-04-03 #1 ENGINE							
	C/W	WARR	TRANSACTION DATE: 03-DEC-1998 12:00:00					
MOS	17-OCT-1998		REASON: --					MOS
HRS	6520		TECH:					HRS
AFL	4889		INSP:	LABOR HRS: 0	COST: \$0.00			AFL

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
911400U	SERVICE BULLETIN ASB 1124-29A-140						
C/W	WARR	TRANSACTION DATE: 03-DEC-1998 12:00:00					
MOS	06-OCT-1998	REASON: --					MOS
MSC		TECH:					MSC
AFL	4889	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
1998-05-09	98-20-35 ISRAEL AIRCRAFT INDUSTRIES (IAI), LTD.: AMENDMENT 39-10802. DOCKET 98-NM-108-AD. SUPERSEDES AD 98-05-09, AMENDMENT 39-10370.						
	AIRWORTHINESS DIRECTIVE						
C/W	WARR	TRANSACTION DATE: 03-DEC-1998 12:00:00					
MOS		REASON: --					MOS
MSC		TECH:					MSC
AFL	0	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
1997-11-10	TO PREVENT RESTRICTED OXYGEN FLOW, WHICH, IF NOT CORRECTED, COULD CAUSE SERIOUS INJURY TO A PASSENGER IN NEED OF EMERGENCY OR FIRST AID OXYGEN DURING FLIGHT						
	AIRWORTHINESS DIRECTIVE						
C/W	WARR	TRANSACTION DATE: 03-DEC-1998 12:00:00					
MOS		REASON: --					MOS
HRS	0	TECH:					HRS
AFL	0	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
991615	ACCOMPLISH AD98-06-10 AIRWORTHINESS DIRECTIVE						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 03-DEC-1998 12:00:00					
MOS	17-OCT-1998	REASON: --					MOS
HRS	6520	TECH:					HRS
AFL	4889	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: EFFECTIVE 04/17/98 - RPT							
991561	ACCOMPLISH AD96-24-11 RIGHT AILERON AIRWORTHINESS DIRECTIVE						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 03-DEC-1998 12:00:00					
MOS	17-OCT-1998	REASON: --					MOS
HRS	6520	TECH:					HRS
AFL	4889	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: EFFECTIVE 01-06-97							
990131	ACCOMPLISH AD89-12-08 AIRWORTHINESS DIRECTIVE						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 03-DEC-1998 12:00:00					
MOS	17-OCT-1998	REASON: --					MOS
HRS	6520	TECH:					HRS
AFL	4889	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: EFFECTIVE 07-10-89 - REF:550656							
973665U	ACCOMPLISH BULLETIN SB731-A72-3636R1 R/E						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 03-DEC-1998 12:00:00					
MOS	06-OCT-1998	REASON: --					MOS
HRS	6520	TECH:					HRS
AFL	4889	INSP:	LABOR HRS: 0	COST: \$0.00			AFL

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
911291	ACCOMPLISH SB1124-27-129 R AILERON BULLETIN					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 03-DEC-1998 12:00:00						
MOS	17-OCT-1998	REASON: --				MOS		
HRS	6520	TECH:				HRS		
AFL	4889	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: RPT								
950941	ACCOMPLISH SLWW-2494 REV 3 LMG BOLTS BULLETIN					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 03-DEC-1998 12:00:00						
MOS	06-OCT-1998	REASON: --				MOS		
HRS	6520	TECH:				HRS		
AFL	4889	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: RPT 300 HRS								
973636U	ACCOMPLISH BULLETIN SB731-A72-3636R1 L/E					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 03-DEC-1998 12:00:00						
MOS	06-OCT-1998	REASON: --				MOS		
HRS	6520	TECH:				HRS		
AFL	4889	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
950942	ACCOMPLISH SLWW-2494 REV 3 RMG BOLTS BULLETIN					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 03-DEC-1998 12:00:00						
MOS	06-OCT-1998	REASON: --				MOS		
HRS	6520	TECH:				HRS		
AFL	4889	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: RPT 300 HRS								
320231	CHANGE NOSE GEAR UPPER STEERING BRACKET					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 06-JAN-1999 12:00:00		Off. ES12970-7	SN-UNKNOWN			
MOS	06-APR-1998	REASON: A - TIME		On:		MOS	0	
HRS	6346	TECH:				HRS	0	
AFL	4787	INSP:		LABOR HRS: 0	COST: \$0.00	AFL	0	
050150U	200 HOUR INSPECTION					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --				MOS		
HRS	6912	TECH:				HRS		
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 2,3								
260136	HYDROSTATIC TEST RIGHT FIRE EXTINGUISHER					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	07-APR-1999	REASON: --				MOS		
HRS	6727	TECH:				HRS		
AFL	4999	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
050300U	400/200 HOUR INSPECTION					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --				MOS		
HRS	6912	TECH:				HRS		
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 3								

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
100320	CHECK SERVICE BULLETINS				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --			MOS		
HRS	6912	TECH:			HRS		
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
120150	CHECK PRE-FLIGHT				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --			MOS		
HRS	6912	TECH:			HRS		
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
120160	CHECK NO.1 ENGINE PREFLIGHT COMPLETE				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	14-JUL-1999	REASON: --			MOS		
HRS	6828	TECH:			HRS		
AFL	5070	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 4,6							
120161	CHECK NO.2 ENGINE PREFLIGHT COMPLETE				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	14-JUL-1999	REASON: --			MOS		
HRS	6828	TECH:			HRS		
AFL	5070	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 5,7							
210112	VISUALLY INSPECT RIGHT BLEED AIR SWITCHING VALVE				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --			MOS		
HRS	6912	TECH:			HRS		
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 2,3							
210622	INSPECT 35 DEGREE TEMPERATURE SENSOR 35 DEGREE DUCT SENSOR				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --			MOS		
HRS	6912	TECH:			HRS		
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
210681	CHANGE COOLING TURBINE OIL				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --			MOS		
HRS	6912	TECH:			HRS		
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
240131	CHECK NO. 2 STARTER GENERATOR BRUSH WEAR/TENSION				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	14-JUL-1999	REASON: --			MOS		
HRS	6828	TECH:			HRS		
AFL	5070	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 5,7							

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
240123	INSPECT NO. 1 STARTER GENERATOR SPLINE							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	14-JUL-1999		REASON: --					MOS
HRS	6828		TECH:					HRS
AFL	5070		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 4,6								
240121	CHECK NO. 1 STARTER GENERATOR BRUSH WEAR/TENSION							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	14-JUL-1999		REASON: --					MOS
HRS	6828		TECH:					HRS
AFL	5070		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 4,6								
230400	CLEAN/TEST COCKPIT VOICE RECORDER BEACON							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
230218	INSPECT/CHECK STATIC DISCHARGE WICK RESISTANCE							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
210671	CLEAN/REPLACE WATER SEPARATOR CONDENSER/FILTER							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
210276	OPERATIONAL CHECK PRESSURIZATION SWITCHES AND VALVES							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
210102	VISUALLY INSPECT LEFT BLEED AIR SWITCHING VALVE							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
270158	INSPECT RUDDER TRIM TAB FREEPLAY							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR	
260186	OPERATIONAL CHECK FIRE PROTECTION SYSTEM						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:					AFL
		LABOR HRS: 0	COST: \$0.00				
Note: OP 2,3							
260184	INSPECT CABIN PORTABLE EXTINGUISHER CABIN FIRE EXTINGUISHER						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:					AFL
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3							
260181	WEIGHT CHECK CABIN PORTABLE EXTINGUISHER CABIN FIRE EXTINGUISHER						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	07-APR-1999	REASON: --					MOS
HRS	6727	TECH:					HRS
AFL	4999	INSP:					AFL
		LABOR HRS: 0	COST: \$0.00				
260180	VISUAL INSPECTION CABIN PORTABLE EXTINGUISHER CABIN FIRE EXTINGUISHER						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:					AFL
		LABOR HRS: 0	COST: \$0.00				
260174	INSPECT COCKPIT PORTABLE EXTINGUISHER COCKPIT FIRE EXTINGUISHER						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:					AFL
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3							
260171	WEIGHT CHECK COCKPIT PORTABLE EXTINGUISHER COCKPIT FIRE EXTINGUISHER						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	07-APR-1999	REASON: --					MOS
HRS	6727	TECH:					HRS
AFL	4999	INSP:					AFL
		LABOR HRS: 0	COST: \$0.00				
260169	VISUAL INSPECTION COCKPIT PORTABLE EXTINGUISHER COCKPIT FIRE EXTINGUISHER						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:					AFL
		LABOR HRS: 0	COST: \$0.00				
250162	INSPECT FIRST AID KIT						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	07-APR-1999	REASON: --					MOS
HRS	6727	TECH:					HRS
AFL	4999	INSP:					AFL
		LABOR HRS: 0	COST: \$0.00				

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
270262	INSPECT LEFT AILERON LEFT EXTERNAL PUSH-PULL TUBE					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --				MOS		
HRS	6912	TECH:				HRS		
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 2,3								
270248	FUNCTIONAL CHECK FLAP TIME EXCEED RELAY					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --				MOS		
HRS	6912	TECH:				HRS		
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 2,3								
270247	INSPECT RIGHT FLAP/VANE					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --				MOS		
HRS	6912	TECH:				HRS		
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3								
270243	TAP TEST RIGHT FLAP/VANE					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --				MOS		
HRS	6912	TECH:				HRS		
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 2,3								
270242	INSPECT RIGHT FLAP/VANE RIGHT FLAP HINGE AND BEARING 200 HOURS					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --				MOS		
HRS	6912	TECH:				HRS		
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3								
270240	INSPECT LEFT FLAP/VANE LEFT FLAP HINGE AND BEARING 200 HOURS					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --				MOS		
HRS	6912	TECH:				HRS		
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3								
270238	TAP TEST LEFT FLAP/VANE LEFT FLAP					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --				MOS		
HRS	6912	TECH:				HRS		
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 2,3								
270237	INSPECT LEFT FLAP/VANE LEFT FLAP VANE					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --				MOS		
HRS	6912	TECH:				HRS		
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3								

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
270217	INSPECT HORIZONTAL STABILIZER TRIM ACTUATOR				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --			MOS		
HRS	6912	TECH:			HRS		
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 2,3							
250156	INSPECT LIFE PRESERVERS				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	07-APR-1999	REASON: --			MOS		
HRS	6727	TECH:			HRS		
AFL	4999	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
240203	FUNCTIONALLY CHECK EXTERNAL POWER RECEPTACLE BATTERY TEMPERATURE AND WARNING SYSTEM				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --			MOS		
HRS	6912	TECH:			HRS		
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
240181	DEEP CYCLE RIGHT BATTERY				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --			MOS		
HRS	6912	TECH:			HRS		
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
240176	CHECK RIGHT BATTERY ELECTROLYTE LEVEL				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --			MOS		
HRS	6912	TECH:			HRS		
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
240166	DEEP CYCLE LEFT BATTERY				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --			MOS		
HRS	6912	TECH:			HRS		
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
240161	CHECK LEFT BATTERY ELECTROLYTE LEVEL				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --			MOS		
HRS	6912	TECH:			HRS		
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
240133	INSPECT NO. 2 STARTER GENERATOR SPLINE				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	14-JUL-1999	REASON: --			MOS		
HRS	6828	TECH:			HRS		
AFL	5070	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 5,7							

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
100330	CHECK SERVICE LETTERS					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --				MOS		
HRS	6912	TECH:				HRS		
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3								
270341	CHECK CABLE TENSION AFT FUSELAGE					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --				MOS		
HRS	6912	TECH:				HRS		
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 2,3								
270335	OPERATIONAL CHECK SPEED BRAKES AND LIFT DUMPERS					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --				MOS		
HRS	6912	TECH:				HRS		
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3								
270265	CLEAN/CHECK RIGHT AILERON RIGHT GUIDE ROLLERS					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --				MOS		
HRS	6912	TECH:				HRS		
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 2,3								
270264	CLEAN/CHECK LEFT AILERON LEFT GUIDE ROLLERS					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --				MOS		
HRS	6912	TECH:				HRS		
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 2,3								
270263	INSPECT RIGHT AILERON RIGHT EXTERNAL PUSH-PULL TUBE					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --				MOS		
HRS	6912	TECH:				HRS		
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 2,3								
270213	LUBRICATE ELEVATOR ATTACH POINTS					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --				MOS		
HRS	6912	TECH:				HRS		
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3								
270211	INSPECT SCISSORS ASSEMBLY					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --				MOS		
HRS	6912	TECH:				HRS		
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 2,3								

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
270203	INSPECT RIGHT ELEVATOR SKIN SEPARATION						
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
270193	INSPECT LEFT ELEVATOR SKIN SEPARATION						
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
320607	LUBRICATE LEFT ACTUATOR BOLTS						
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3							
320606	LUBRICATE LEFT MAIN GEAR ASSEMBLY LEFT MAIN GEAR						
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
320206	INSPECT NOSE GEAR (B)						
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3							
320201	INSPECT NOSE GEAR (A)						
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
320158	INSPECT/CLEAN/LUBRICATE NOSE GEAR RIGHT WHEEL BEARINGS						
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
320156	INSPECT/CLEAN/LUBRICATE NOSE GEAR LEFT WHEEL BEARINGS						
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
320116	SERVICE NOSE GEAR ASSEMBLY SHOCK STRUT							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
320106	LUBRICATE NOSE GEAR ASSEMBLY NOSE GEAR/DOORS							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
300170	OPERATIONAL TEST P2T2 SENSOR HEATER							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
322171	INSPECT/CLEAN RIGHT ANTI-SKID DETECTOR							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
322156	INSPECT/CLEAN LEFT ANTI-SKID DETECTOR							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
322131	INSPECT/CHECK RIGHT MAIN GEAR BRAKE RIGHT BRAKE LININGS							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
322116	INSPECT/CHECK LEFT MAIN GEAR BRAKE LEFT BRAKE LININGS							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
321616	CHECK EMERGENCY STORAGE BOTTLE LANDING GEAR EMERGENCY SYSTEM PRESSURE							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model : 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR	
321191	INSPECT RIGHT MAIN GEAR OUTBOARD WHEEL HALF RIGHT MAIN GEAR/WELL (A)						
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS 04-OCT-1999		REASON: --		MOS			
HRS 6912		TECH:		HRS			
AFL 5124		INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3							
321180	INSPECT/LUBRICATE RIGHT MAIN GEAR OUTBOARD WHEEL HALF RIGHT MAIN GEAR OUTBOARD WHEEL BEARINGS						
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS 04-OCT-1999		REASON: --		MOS			
HRS 6912		TECH:		HRS			
AFL 5124		INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3							
321178	DYE PENETRANT CHECK RIGHT WHEEL AXLE						
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS 04-OCT-1999		REASON: --		MOS			
HRS 6912		TECH:		HRS			
AFL 5124		INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
Note: OP 2,3							
321176	INSPECT/LUBRICATE RIGHT MAIN GEAR INBOARD WHEEL HALF RIGHT MAIN GEAR INBOARD WHEEL BEARINGS						
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS 04-OCT-1999		REASON: --		MOS			
HRS 6912		TECH:		HRS			
AFL 5124		INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3							
991645U	AIRWORTHINESS DIRECTIVE AD98-25-02						
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS 07-APR-1999		REASON: --		MOS			
HRS 6727		TECH:		HRS			
AFL 4999		INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
991640U	AIRWORTHINESS DIRECTIVE AD98-25-10						
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS 07-APR-1999		REASON: --		MOS			
HRS 6727		TECH:		HRS			
AFL 4999		INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
950942	ACCOMPLISH SLWW-2494 REV 3 RMG BOLTS BULLETIN						
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS 04-OCT-1999		REASON: --		MOS			
HRS 6912		TECH:		HRS			
AFL 5124		INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
Note: RPT 300 HRS							
950941	ACCOMPLISH SLWW-2494 REV 3 LMG BOLTS BULLETIN						
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS 04-OCT-1999		REASON: --		MOS			
HRS 6912		TECH:		HRS			
AFL 5124		INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
Note: RPT 300 HRS							

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
713650U	-- INSP #2 ENG INLET NACELLE							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
710650U	-- INSP #1 ENG INLET NACELLE							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
570120	INSPECT RIGHT AILERON BELLCRANK							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
570119	INSPECT RIGHT WING (B)							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
570116	INSPECT RIGHT WING (A)							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
570106	INSPECT LEFT AILERON BELLCRANK							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
570104	INSPECT LEFT WING (B)						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3							
570101	INSPECT LEFT WING (A)						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
550106	INSPECT EMPENNAGE (B)						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3							
550101	INSPECT EMPENNAGE (A)						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
540126U	INSPECT NO. 2 ENGINE NACELLE/PYLON (B)						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3							
540121U	INSPECT NO. 2 ENGINE NACELLE/PYLON (A)						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
540106U	INSPECT NO. 1 ENGINE NACELLE/PYLON (B)						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3							
540101U	INSPECT NO. 1 ENGINE NACELLE/PYLON (A)						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							



AIRCRAFT Updates Report

Serial #: 368 Reg. #: N368MD
 Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
530166	INSPECT REAR COMPARTMENT (B)							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --						MOS
HRS	6912	TECH:						HRS
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
530161	INSPECT REAR COMPARTMENT (A)							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --						MOS
HRS	6912	TECH:						HRS
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
530146	INSPECT CABIN (A)							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --						MOS
HRS	6912	TECH:						HRS
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
530136	INSPECT COCKPIT (B)							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --						MOS
HRS	6912	TECH:						HRS
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
530131	INSPECT COCKPIT (A)							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --						MOS
HRS	6912	TECH:						HRS
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
530121	INSPECT NOSE COMPARTMENT (B)							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --						MOS
HRS	6912	TECH:						HRS
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
530116	INSPECT NOSE COMPARTMENT (A)							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --						MOS
HRS	6912	TECH:						HRS
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
530101	INSPECT FUSELAGE (A)							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --						MOS
HRS	6912	TECH:						HRS
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
520116	OPERATIONAL CHECK CABIN ENTRANCE DOOR						
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
520106	INSPECT/LUBRICATE CABIN ENTRANCE DOOR						
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
350169U	CHECK COPILOT OXYGEN MASK						
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
350166U	CHECK PILOT OXYGEN MASK						
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
344616	INSPECT EMERGENCY GYRO POWER SUPPLY BATTERY		EMERGENCY POWER SUPPLY				
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: PS 823 ONLY							
340121	DRAIN PITOT/STATIC SYSTEM						
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
330228	CHARGE EMERGENCY LIGHT BATTERY						
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
322206	FUNCTIONAL TEST EMERGENCY GEAR EXTENSION CONTROL CABLE						
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
322201	FUNCTIONAL TEST LANDING GEAR FREE FALL							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
322191	FUNCTIONAL TEST LANDING GEAR (NORMAL)							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
322176	FUNCTIONAL CHECK ANTI-SKID DETECTOR SYSTEM							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
322174	OPERATIONAL CHECK ANTI-SKID LIGHTS							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
321136	SERVICE RIGHT MAIN GEAR ASSEMBLY RIGHT MAIN GEAR SHOCK STRUT							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
321107	LUBRICATE RIGHT ACTUATOR BOLTS							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
321106	LUBRICATE RIGHT MAIN GEAR ASSEMBLY RIGHT MAIN GEAR							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
320691	INSPECT LEFT MAIN GEAR/WELL (A)							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								

03-BUS-50

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model : 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
320680	INSPECT/LUBRICATE LEFT MAIN GEAR OUTBOARD WHEEL HALF WHEEL BEARINGS		LEFT MAIN GEAR OUTBOARD		Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
	C/W WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --				MOS	
HRS	6912	TECH:				HRS	
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3							
320678	DYE PENETRANT CHECK LEFT WHEEL AXLE				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
	C/W WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --				MOS	
HRS	6912	TECH:				HRS	
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 2,3							
320676	INSPECT/LUBRICATE LEFT MAIN GEAR INBOARD WHEEL HALF BEARINGS		LEFT MAIN GEAR INBOARD WHEEL		Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
	C/W WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --				MOS	
HRS	6912	TECH:				HRS	
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3							
320636	SERVICE LEFT MAIN GEAR ASSEMBLY LEFT MAIN GEAR SHOCK STRUT				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
	C/W WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --				MOS	
HRS	6912	TECH:				HRS	
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 2,3							
300150	INSPECT COPILOT WINDSHIELD CYCLING CONTACTOR				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
	C/W WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --				MOS	
HRS	6912	TECH:				HRS	
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3							
300147	INSPECT PILOT WINDSHIELD CYCLING CONTACTOR				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
	C/W WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --				MOS	
HRS	6912	TECH:				HRS	
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3 - 7264-4654							
300104	INSPECT RIGHT DE-ICER CHECK VALVE				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
	C/W WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --				MOS	
HRS	6912	TECH:				HRS	
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 2,3							



AIRCRAFT Updates Report

Serial #: 368 Reg. #: N368MD
 Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
300102	INSPECT LEFT DE-ICER CHECK VALVE							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
290178	INSPECT/LUBRICATE NO. 2 HYDRAULIC PUMP NO.2 ENGINE HYDRAULIC PUMP SPLINES							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
290143	INSPECT/LUBRICATE NO. 1 HYDRAULIC PUMP NO.1 ENGINE HYDRAULIC PUMP SPLINES							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
290118	CLEAN/CHECK RESERVOIR AIR PRESSURE REGULATOR HYDRAULIC RESERVOIR AIR PRESSURE CHECK VALVE							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
281150	CHECK OPERATION OF FUEL BOOST PUMPS							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
100310	CHECK AIRWORTHY DIRECTIVES							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
270214	LUBRICATE AFT HINGE FITTING BEARINGS							
	C/W	WARR	TRANSACTION DATE: 25-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - PRE 55-021								
270215	LUBRICATE FORWARD SCISSOR ASSEMBLY							
	C/W	WARR	TRANSACTION DATE: 25-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - POST 55-021								

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
270224	CHANGE HORIZONTAL STABILIZER ACTUATOR NO.1 JACKSCREW				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 25-OCT-1999 12:00:00	Off: 21164-360	SN-UNKNOWN			
MOS	06-APR-1998	REASON: A - TIME	On:		MOS		
HRS	6346	TECH:			HRS	0	
AFL	4787	INSP:	LABOR HRS: 0	COST: \$0.00	AFL	0	
550656	CHECK HORIZONTAL STABILIZER AFT SPAR SPLICE-HINGE FITTING OUTBOARD LUGS FOR CRACKS				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 25-OCT-1999 12:00:00					
MOS	06-APR-1998	REASON: - -			MOS		
HRS	6346	TECH:			HRS		
AFL	4787	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
990131	ACCOMPLISH AD89-12-08 AIRWORTHINESS DIRECTIVE				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 25-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: - -			MOS		
HRS	6912	TECH:			HRS		
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: EFFECTIVE 07-10-89 - REF:550656							
1998-20-35 PART 2	TO PREVENT FAILURE OF THE TRIM ACTUATOR OF THE HORIZONTAL STABILIZER DUE TO FAILURE OF THE JACKSCREWS, WHICH COULD RESULT IN REDUCED CONTROLLABILITY OF THE AIRPLANE AIRWORTHINESS DIRECTIVE						
CW	WARR	TRANSACTION DATE: 25-OCT-1999 12:00:00					
MOS		REASON: - -			MOS		
HRS		TECH:			HRS		
AFL		INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
1999-18-80	TO PREVENT LOSS OF THE HYDRAULIC LOW PRESSURE WARNING LIGHTS WHICH COULD RESULT IN UNKNOWN LOW PRESSURE IN THE HYDRAULIC SYSTEM AND CONSEQUENT REDUCED CONTROLLABILITY OF THE AIRPLANE AIRWORTHINESS DIRECTIVE						
CW	WARR	TRANSACTION DATE: 25-OCT-1999 12:00:00					
MOS		REASON: - -			MOS		
MSC		TECH:			MSC		
AFL		INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
991634	ACCOMPLISH AD98-20-35 PART 1 AIRWORTHINESS DIRECTIVE				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 25-OCT-1999 12:00:00					
MOS	06-APR-1998	REASON: NA - NOT APPLICABLE			MOS		
HRS	6346	TECH:			HRS		
AFL	4787	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: EFFECTIVE 11-03-98 - RPL JACKSCRW							
910200	ACCOMPLISH SB 1124-55-020 REV 2 BULLETIN				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 25-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: - -			MOS		
HRS	6912	TECH:			HRS		
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 2,3							

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR	
550656	CHECK HORIZONTAL STABILIZER AFT SPAR SPLICE-HINGE FITTING OUTBOARD LUGS FOR CRACKS						
	TRANSACTION DATE: 25-OCT-1999 12:00:00						
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Done By: CAMP SYSTEMS INTERNATIONAL, LLC						
	C/W WARR						
MOS	04-OCT-1999						
HRS	6912						
AFL	5124						
	Note: OP 1,2,3						
270225	CHANGE HORIZONTAL STABILIZER ACTUATOR NO.2 JACKSCREW						
	TRANSACTION DATE: 25-OCT-1999 12:00:00						
	REASON: A - TIME						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Done By: CAMP SYSTEMS INTERNATIONAL, LLC						
	C/W WARR						
MOS	06-APR-1998						
HRS	6346						
AFL	4787						
	Note: OP 1,2,3						
120160	CHECK NO.1 ENGINE PREFLIGHT COMPLETE						
	TRANSACTION DATE: 26-OCT-1999 12:00:00						
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Done By: CAMP SYSTEMS INTERNATIONAL, LLC						
	C/W WARR						
MOS	26-OCT-1999						
HRS	6961						
AFL	5135						
	Note: OP 4,6						
240123	INSPECT NO. 1 STARTER GENERATOR SPLINE						
	TRANSACTION DATE: 26-OCT-1999 12:00:00						
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Done By: CAMP SYSTEMS INTERNATIONAL, LLC						
	C/W WARR						
MOS	26-OCT-1999						
HRS	6961						
AFL	5135						
	Note: OP 4,6						
240133	INSPECT NO. 2 STARTER GENERATOR SPLINE						
	TRANSACTION DATE: 26-OCT-1999 12:00:00						
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Done By: CAMP SYSTEMS INTERNATIONAL, LLC						
	C/W WARR						
MOS	26-OCT-1999						
HRS	6961						
AFL	5135						
	Note: OP 5,7						
780163	HYDROSTATIC TEST THRUST REVERSER GAS STORAGE BOTTLE						
	TRANSACTION DATE: 26-OCT-1999 12:00:00						
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Done By: CAMP SYSTEMS INTERNATIONAL, LLC						
	C/W WARR						
MOS	26-OCT-1999						
HRS	6961						
AFL	5135						
321613	HYDROSTATIC TEST EMERGENCY STORAGE BOTTLE						
	TRANSACTION DATE: 26-OCT-1999 12:00:00						
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Done By: CAMP SYSTEMS INTERNATIONAL, LLC						
	C/W WARR						
MOS	26-OCT-1999						
HRS	6961						
AFL	5135						
990821U	ACCOMPLISH AIRWORTHINESS DIRECTIVE AD82-23-03 R1 #1 ENGINE						
	TRANSACTION DATE: 26-OCT-1999 12:00:00						
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Done By: CAMP SYSTEMS INTERNATIONAL, LLC						
	C/W WARR						
MOS	26-OCT-1999						
HRS	6961						
AFL	5135						
	Note: EFFECTIVE 12-09-83						

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR	
972B39U	ACCOMPLISH BULLETIN GSBA72-3569 L/E FAN ROTOR						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR						
MOS	26-OCT-1999	TRANSACTION DATE: 26-OCT-1999 12:00:00					MOS
HRS	6961	REASON: --					HRS
AFL	5135	TECH:					AFL
		INSP:	LABOR HRS: 0	COST: \$0.00			
Note: ALERT							
971279U	ACCOMPLISH BULLETIN TFE731-72-3640 R3 ENG #1						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR						
MOS	26-OCT-1999	TRANSACTION DATE: 26-OCT-1999 12:00:00					MOS
HRS	6961	REASON: --					HRS
AFL	5135	TECH:					AFL
		INSP:	LABOR HRS: 0	COST: \$0.00			
Note: MOBIL 254 OIL, SVCE							
780120	CHECK #2 THRUST REVERSER SECONDARY LATCH SOLENOID SWITCH						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR						
MOS	26-OCT-1999	TRANSACTION DATE: 26-OCT-1999 12:00:00					MOS
HRS	6961	REASON: --					HRS
AFL	5135	TECH:					AFL
		INSP:	LABOR HRS: 0	COST: \$0.00			
780119	CHECK #1 THRUST REVERSER SECONDARY LATCH SOLENOID SWITCH						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR						
MOS	26-OCT-1999	TRANSACTION DATE: 26-OCT-1999 12:00:00					MOS
HRS	6961	REASON: --					HRS
AFL	5135	TECH:					AFL
		INSP:	LABOR HRS: 0	COST: \$0.00			
260169	VISUAL INSPECTION COCKPIT PORTABLE EXTINGUISHER COCKPIT FIRE EXTINGUISHER						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR						
MOS	26-OCT-1999	TRANSACTION DATE: 26-OCT-1999 12:00:00					MOS
HRS	6961	REASON: --					HRS
AFL	5135	TECH:					AFL
		INSP:	LABOR HRS: 0	COST: \$0.00			
260180	VISUAL INSPECTION CABIN PORTABLE EXTINGUISHER CABIN FIRE EXTINGUISHER						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR						
MOS	26-OCT-1999	TRANSACTION DATE: 26-OCT-1999 12:00:00					MOS
HRS	6961	REASON: --					HRS
AFL	5135	TECH:					AFL
		INSP:	LABOR HRS: 0	COST: \$0.00			
971280U	SERVICE BULLETIN TFE731-72-3640 R3 ENG #2						
C/W	WARR						
MOS	26-OCT-1999	TRANSACTION DATE: 26-OCT-1999 12:00:00					MOS
MSC		REASON: --					MSC
AFL	5135	TECH:					AFL
		INSP:	LABOR HRS: 0	COST: \$0.00			
911230U	SERVICE BULLETIN SB1124-53-123 DRAIN/CABIN						
C/W	WARR						
MOS	26-OCT-1999	TRANSACTION DATE: 26-OCT-1999 12:00:00					MOS
MSC		REASON: --					MSC
AFL	5135	TECH:					AFL
		INSP:	LABOR HRS: 0	COST: \$0.00			



AIRCRAFT Updates Report

Serial #: 368 Reg. #: N368MD
 Model: 1124A WESTWIND

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR	
1998-20-35 PART 1							
	TO PREVENT FAILURE OF THE TRIM ACTUATOR OF THE HORIZONTAL STABILIZER DUE TO FAILURE OF THE JACKSCREWS, WHICH COULD RESULT IN REDUCED CONTROLLABILITY OF THE AIRPLANE AIRWORTHINESS DIRECTIVE						
	CW WARR						
	TRANSACTION DATE: 26-OCT-1999 12:00:00						
MOS	REASON: --					MOS	
HRS	TECH:					HRS	
AFL	INSP:					AFL	
		LABOR HRS: 0	COST: \$0.00				
911360							
	SB1124-27-136 HORZ TRIM SERVICE BULLETIN						
	CW WARR						
	TRANSACTION DATE: 26-OCT-1999 12:00:00						
MOS	REASON: --					MOS	
HRS	TECH:					HRS	
AFL	INSP:					AFL	
		LABOR HRS: 0	COST: \$0.00				
1124-78A-134							
	THRUST REVERSER ALERT SERVICE BULLETIN						
	CW WARR						
	TRANSACTION DATE: 26-OCT-1999 12:00:00						
MOS	REASON: --					MOS	
MSC	TECH:					MSC	
AFL	INSP:					AFL	
		LABOR HRS: 0	COST: \$0.00				
240131							
	CHECK NO. 2 STARTER GENERATOR BRUSH WEAR/TENSION					Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
	CW WARR						
	TRANSACTION DATE: 26-OCT-1999 12:00:00						
MOS	REASON: --					MOS	
HRS	TECH:					HRS	
AFL	INSP:					AFL	
		LABOR HRS: 0	COST: \$0.00				
Note: OP 5,7							
240121							
	CHECK NO. 1 STARTER GENERATOR BRUSH WEAR/TENSION					Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
	CW WARR						
	TRANSACTION DATE: 26-OCT-1999 12:00:00						
MOS	REASON: --					MOS	
HRS	TECH:					HRS	
AFL	INSP:					AFL	
		LABOR HRS: 0	COST: \$0.00				
Note: OP 4,6							
120161							
	CHECK NO.2 ENGINE PREFLIGHT COMPLETE					Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
	CW WARR						
	TRANSACTION DATE: 26-OCT-1999 12:00:00						
MOS	REASON: --					MOS	
HRS	TECH:					HRS	
AFL	INSP:					AFL	
		LABOR HRS: 0	COST: \$0.00				
Note: OP 5,7							
230166							
	RENEW FCC RADIO/TELEPHONE LICENSE						
	CW WARR						
	TRANSACTION DATE: 27-OCT-1999 12:00:00						
MOS	REASON: --					MOS	
HRS	TECH:					HRS	
AFL	INSP:					AFL	
		LABOR HRS: 0	COST: \$0.00				
991755U							
	AIRWORTHINESS DIRECTIVE AD99-08-21						
	CW WARR						
	TRANSACTION DATE: 27-OCT-1999 12:00:00						
MOS	REASON: --					MOS	
HRS	TECH:					HRS	
AFL	INSP:					AFL	
		LABOR HRS: 0	COST: \$0.00				

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
260169	VISUAL INSPECTION COCKPIT PORTABLE EXTINGUISHER		COCKPIT FIRE EXTINGUISHER		Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 29-NOV-1999 12:00:00					
MOS	29-NOV-1999	REASON: --					MOS
HRS	6991	TECH:					HRS
AFL	5163	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
260180	VISUAL INSPECTION CABIN PORTABLE EXTINGUISHER		CABIN FIRE EXTINGUISHER		Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 29-NOV-1999 12:00:00					
MOS	29-NOV-1999	REASON: --					MOS
HRS	6991	TECH:					HRS
AFL	5163	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
290215	FUNCTIONAL TEST EMERGENCY HYDRAULIC PUMP		EMERGENCY HYDRAULIC FUSE				
CW	WARR	TRANSACTION DATE: 01-DEC-1999 12:00:00					
MOS	30-NOV-1999	REASON: --					MOS
HRS	6991	TECH:					HRS
AFL	5163	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
971279U	SERVICE BULLETIN TFE731-72-3640 R3 ENG #1						
CW	WARR	TRANSACTION DATE: 07-DEC-1999 12:00:00					
MOS	13-NOV-1999	REASON: --					MOS
HRS	6961	TECH:					HRS
AFL	5135	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
990821U	AIRWORTHINESS DIRECTIVE AD82-23-03 R1 #1 ENGINE						
CW	WARR	TRANSACTION DATE: 07-DEC-1999 12:00:00					
MOS	13-NOV-1999	REASON: --					MOS
MSC		TECH:					MSC
AFL	5135	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
972B39U	SERVICE BULLETIN GSBA72-3569 L/E FAN ROTOR						
CW	WARR	TRANSACTION DATE: 07-DEC-1999 12:00:00					
MOS	13-NOV-1999	REASON: --					MOS
HRS	6961	TECH:					HRS
AFL	5135	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
050150U	200 HOUR INSPECTION				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3							
270158	INSPECT RUDDER TRIM TAB FREEPLAY				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
260184	INSPECT CABIN PORTABLE EXTINGUISHER		CABIN FIRE EXTINGUISHER		Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
260181	WEIGHT CHECK CABIN PORTABLE EXTINGUISHER CABIN FIRE EXTINGUISHER					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --				MOS		
HRS	7107	TECH:				HRS		
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
260180	VISUAL INSPECTION CABIN PORTABLE EXTINGUISHER CABIN FIRE EXTINGUISHER					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --				MOS		
HRS	7107	TECH:				HRS		
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
260174	INSPECT COCKPIT PORTABLE EXTINGUISHER COCKPIT FIRE EXTINGUISHER					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --				MOS		
HRS	7107	TECH:				HRS		
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3								
260171	WEIGHT CHECK COCKPIT PORTABLE EXTINGUISHER COCKPIT FIRE EXTINGUISHER					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --				MOS		
HRS	7107	TECH:				HRS		
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
260169	VISUAL INSPECTION COCKPIT PORTABLE EXTINGUISHER COCKPIT FIRE EXTINGUISHER					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --				MOS		
HRS	7107	TECH:				HRS		
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
250162	INSPECT FIRST AID KIT					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --				MOS		
HRS	7107	TECH:				HRS		
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
250156	INSPECT LIFE PRESERVERS					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --				MOS		
HRS	7107	TECH:				HRS		
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
240203	FUNCTIONALLY CHECK EXTERNAL POWER RECEPTACLE BATTERY TEMPERATURE AND WARNING SYSTEM					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --				MOS		
HRS	7107	TECH:				HRS		
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3								

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
240181	DEEP CYCLE RIGHT BATTERY						
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
240176	CHECK RIGHT BATTERY ELECTROLYTE LEVEL						
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
240166	DEEP CYCLELEFT BATTERY						
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
240161	CHECK LEFT BATTERY ELECTROLYTE LEVEL						
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
240131	CHECK NO. 2 STARTER GENERATOR BRUSH WEAR/TENSION						
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 5,7							
240128	INSPECT NO. 2 STARTER GENERATOR						
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 5,7							
240123	INSPECT NO. 1 STARTER GENERATOR SPLINE						
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 4,6							
240118	INSPECT NO. 1 STARTER GENERATOR						
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 4,6							



AIRCRAFT Updates Report

Serial #: 368 Reg. #: N368MD
 Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
230400	CLEAN/TEST COCKPIT VOICE RECORDER BEACON							
	C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
210681	CHANGE COOLING TURBINE OIL							
	C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
210671	CLEAN/REPLACE WATER SEPARATOR CONDENSER/FILTER							
	C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
210622	INSPECT 35 DEGREE TEMPERATURE SENSOR 35 DEGREE DUCT SENSOR							
	C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
120161	CHECK NO.2 ENGINE PREFLIGHT COMPLETE							
	C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 5,7								
120160	CHECK NO.1 ENGINE PREFLIGHT COMPLETE							
	C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 4,6								
120150	CHECK PRE-FLIGHT							
	C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
1998-25-10 R1	TO PREVENT FAILURE OF THE SEAT RESTRAINT SYSTEM DUE TO THE BUCKLE ASSEMBLY (BUCKLE) LOCKING MECHANISM NOT ENGAGING PROPERLY, WHICH COULD RESULT IN THE SEAT RESTRAINT SYSTEM FAILING TO PROPERLY SECURE THE OCCUPANT DURING TURBULENCE OR LANDING AIRWORTHINESS DIRECTIVE							
	C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS			REASON: --					MOS
HRS	0		TECH:					HRS
AFL	0		INSP:	LABOR HRS: 0	COST: \$0.00			AFL

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
1999-23-22 R2	RESCISSION AIRWORTHINESS DIRECTIVE							
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS		REASON: --						MOS
MSC		TECH:						MSC
AFL	0	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
950911	SL WW-2491 REV 1 NLG BRGS SERVICE BULLETIN							
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS		REASON: --						MOS
MSC		TECH:						MSC
AFL	0	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
900280	SB WW 24-28A SERVICE BULLETIN							
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --						MOS
HRS	7107	TECH:						HRS
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
322169	CLEAN RIGHT ANTI-SKID CONTROL VALVE FILTERS							
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --						MOS
HRS	7107	TECH:						HRS
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
322149	CLEAN LEFT ANTI-SKID CONTROL VALVE FILTERS							
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --						MOS
HRS	7107	TECH:						HRS
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
320238	INSPECT NOSE GEAR LOWER STEERING BRACKET							
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --						MOS
HRS	7107	TECH:						HRS
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
320237	INSPECT NOSE GEAR UPPER STEERING BRACKET							
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --						MOS
HRS	7107	TECH:						HRS
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
320120	INSPECT NOSE GEAR ASSEMBLY OUTER STRUT BODY FORGING							
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --						MOS
HRS	7107	TECH:						HRS
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
320118	INSPECT/LUBRICATE NOSE GEAR ASSEMBLY UPPER/LOWER STRUT BEARINGS BODY							
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --						MOS
HRS	7107	TECH:						HRS
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00			AFL

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
281603	FUNCTIONAL CHECK FUEL DUMP SYSTEM							
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --						MOS
HRS	7107	TECH:						HRS
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
991561	ACCOMPLISH AD96-24-11 RIGHT AILERON AIRWORTHINESS DIRECTIVE							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --						MOS
HRS	7107	TECH:						HRS
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: EFFECTIVE 01-06-97								
991560	ACCOMPLISH AD96-24-11 LEFT AILERON AIRWORTHINESS DIRECTIVE							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --						MOS
HRS	7107	TECH:						HRS
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: EFFECTIVE 01-06-97								
990131	ACCOMPLISH AD89-12-08 AIRWORTHINESS DIRECTIVE							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --						MOS
HRS	7107	TECH:						HRS
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: EFFECTIVE 07-10-89 - REF:550656								
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --						MOS
HRS	7107	TECH:						HRS
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
911390	ACCOMPLISH SB1124-32-139 UPR STRG BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --						MOS
HRS	7107	TECH:						HRS
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 3 - RPT C CHECK								
911291	ACCOMPLISH SB1124-27-129 R AILERON BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --						MOS
HRS	7107	TECH:						HRS
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: RPT								
911290	ACCOMPLISH SB1124-27-129 L AILERON BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --						MOS
HRS	7107	TECH:						HRS
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: RPT								

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN						
	C/W WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
713650U	-- INSP #2 ENG INLET NACELLE						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
710650U	-- INSP #1 ENG INLET NACELLE						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
570120	INSPECT RIGHT AILERON BELLCRANK						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
570116	INSPECT RIGHT WING (A)						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
570106	INSPECT LEFT AILERON BELLCRANK						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
570101	INSPECT LEFT WING (A)						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
560101	CHANGE PILOT OUTER WINDSHIELD						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00	Off: 5-343026-501	84-H-1-2-096			
MOS	22-FEB-2000	REASON: B - FAIL	On:				MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00		0	AFL
						0	

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR	
550656	CHECK HORIZONTAL STABILIZER AFT SPAR SPLICE-HINGE FITTING OUTBOARD LUGS FOR CRACKS						
	C/W WARR						
MOS	22-FEB-2000	TRANSACTION DATE: 28-FEB-2000 12:00:00					
HRS	7107	REASON: --				MOS	
AFL	5232	TECH:				HRS	
		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
	Note: OP 1,2,3						
550101	INSPECT EMPENNAGE (A)						
	C/W WARR						
MOS	22-FEB-2000	TRANSACTION DATE: 28-FEB-2000 12:00:00					
HRS	7107	REASON: --				MOS	
AFL	5232	TECH:	LABOR HRS: 0	COST: \$0.00		HRS	
		INSP:				AFL	
	Note: OP 1,2,3						
540121U	INSPECT NO. 2 ENGINE NACELLE/PYLON (A)						
	C/W WARR						
MOS	22-FEB-2000	TRANSACTION DATE: 28-FEB-2000 12:00:00					
HRS	7107	REASON: --				MOS	
AFL	5232	TECH:	LABOR HRS: 0	COST: \$0.00		HRS	
		INSP:				AFL	
	Note: OP 1,2,3						
540101U	INSPECT NO. 1 ENGINE NACELLE/PYLON (A)						
	C/W WARR						
MOS	22-FEB-2000	TRANSACTION DATE: 28-FEB-2000 12:00:00					
HRS	7107	REASON: --				MOS	
AFL	5232	TECH:	LABOR HRS: 0	COST: \$0.00		HRS	
		INSP:				AFL	
	Note: OP 1,2,3						
530161	INSPECT REAR COMPARTMENT (A)						
	C/W WARR						
MOS	22-FEB-2000	TRANSACTION DATE: 28-FEB-2000 12:00:00					
HRS	7107	REASON: --				MOS	
AFL	5232	TECH:	LABOR HRS: 0	COST: \$0.00		HRS	
		INSP:				AFL	
	Note: OP 1,2,3						
530146	INSPECT CABIN (A)						
	C/W WARR						
MOS	22-FEB-2000	TRANSACTION DATE: 28-FEB-2000 12:00:00					
HRS	7107	REASON: --				MOS	
AFL	5232	TECH:	LABOR HRS: 0	COST: \$0.00		HRS	
		INSP:				AFL	
	Note: OP 1,2,3						
530131	INSPECT COCKPIT (A)						
	C/W WARR						
MOS	22-FEB-2000	TRANSACTION DATE: 28-FEB-2000 12:00:00					
HRS	7107	REASON: --				MOS	
AFL	5232	TECH:	LABOR HRS: 0	COST: \$0.00		HRS	
		INSP:				AFL	
	Note: OP 1,2,3						
530116	INSPECT NOSE COMPARTMENT (A)						
	C/W WARR						
MOS	22-FEB-2000	TRANSACTION DATE: 28-FEB-2000 12:00:00					
HRS	7107	REASON: --				MOS	
AFL	5232	TECH:	LABOR HRS: 0	COST: \$0.00		HRS	
		INSP:				AFL	
	Note: OP 1,2,3						

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
530101	INSPECT FUSELAGE (A)						
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
520116	OPERATIONAL CHECK CABIN ENTRANCE DOOR						
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
520106	INSPECT/LUBRICATE CABIN ENTRANCE DOOR						
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
344616	INSPECT EMERGENCY GYRO POWER SUPPLY BATTERY	EMERGENCY POWER SUPPLY					
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: PS 823 ONLY							
340121	DRAIN PITOT/STATIC SYSTEM						
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
330228	CHARGE EMERGENCY LIGHT BATTERY						
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000	REASON: ---					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
322206	FUNCTIONAL TEST EMERGENCY GEAR EXTENSION CONTROL CABLE						
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
322174	OPERATIONAL CHECK ANTI-SKID LIGHTS						
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							



AIRCRAFT Updates Report

Serial #: 368 Reg. #: N368MD
 Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
322171	INSPECT/CLEAN RIGHT ANTI-SKID DETECTOR							
	CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
322156	INSPECT/CLEAN LEFT ANTI-SKID DETECTOR							
	CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
322131	INSPECT/CHECK RIGHT MAIN GEAR BRAKE RIGHT BRAKE LININGS							
	CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
322116	INSPECT/CHECK LEFT MAIN GEAR BRAKE LEFT BRAKE LININGS							
	CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
321191	INSPECT RIGHT MAIN GEAR OUTBOARD WHEEL HALF RIGHT MAIN GEAR/WELL (A)							
	CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
321180	INSPECT/LUBRICATE RIGHT MAIN GEAR OUTBOARD WHEEL HALF RIGHT MAIN GEAR OUTBOARD WHEEL BEARINGS							
	CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
321176	INSPECT/LUBRICATE RIGHT MAIN GEAR INBOARD WHEEL HALF RIGHT MAIN GEAR INBOARD WHEEL BEARINGS							
	CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR	
321106	LUBRICATE RIGHT MAIN GEAR ASSEMBLY	RIGHT MAIN GEAR					
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	22-FEB-2000	REASON: --		MOS			
HRS	7107	TECH:		HRS			
AFL	5232	INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3							
320691	INSPECT LEFT MAIN GEAR/WELL (A)						
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	22-FEB-2000	REASON: --		MOS			
HRS	7107	TECH:		HRS			
AFL	5232	INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3							
320680	INSPECT/LUBRICATE LEFT MAIN GEAR OUTBOARD WHEEL HALF	LEFT MAIN GEAR OUTBOARD WHEEL BEARINGS					
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	22-FEB-2000	REASON: --		MOS			
HRS	7107	TECH:		HRS			
AFL	5232	INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3							
320676	INSPECT/LUBRICATE LEFT MAIN GEAR INBOARD WHEEL HALF	LEFT MAIN GEAR INBOARD WHEEL BEARINGS					
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	22-FEB-2000	REASON: --		MOS			
HRS	7107	TECH:		HRS			
AFL	5232	INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3							
320606	LUBRICATE LEFT MAIN GEAR ASSEMBLY	LEFT MAIN GEAR					
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	22-FEB-2000	REASON: --		MOS			
HRS	7107	TECH:		HRS			
AFL	5232	INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3							
320232	CHANGE NOSE GEAR LOWER STEERING BRACKET						
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00	Off: 22360300-001	SN-UNKNOWN			
MOS	22-FEB-2000	REASON: G - MOD	On:			MOS	
HRS	7107	TECH:				HRS	
AFL	5232	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00		0		
Note: OP 1,2,3							
320231	CHANGE NOSE GEAR UPPER STEERING BRACKET						
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00	Off: 22360300-001	SN-UNKNOWN			
MOS	22-FEB-2000	REASON: G - MOD	On:			MOS	
HRS	7107	TECH:				HRS	
AFL	5232	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00		0	0	
Note: OP 1,2,3							
320201	INSPECT NOSE GEAR (A)						
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	22-FEB-2000	REASON: --		MOS			
HRS	7107	TECH:		HRS			
AFL	5232	INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3							

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
320158	INSPECT/CLEAN/LUBRICATE NOSE GEAR RIGHT WHEEL BEARINGS					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --				MOS		
HRS	7107	TECH:				HRS		
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3								
320156	INSPECT/CLEAN/LUBRICATE NOSE GEAR LEFT WHEEL BEARINGS					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --				MOS		
HRS	7107	TECH:				HRS		
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3								
320106	LUBRICATE NOSE GEAR ASSEMBLY NOSE GEAR/DOORS					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --				MOS		
HRS	7107	TECH:				HRS		
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3								
300170	OPERATIONAL TEST P2T2 SENSOR HEATER					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --				MOS		
HRS	7107	TECH:				HRS		
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3								
300150	INSPECT COPILOT WINDSHIELD CYCLING CONTACTOR					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --				MOS		
HRS	7107	TECH:				HRS		
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3								
300147	INSPECT PILOT WINDSHIELD CYCLING CONTACTOR					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --				MOS		
HRS	7107	TECH:				HRS		
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3 - 7264-4654								
300146	CHANGE LEFT WINDSHIELD TEMPERATURE CONTROLLER					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00		Off. 833034-1	SN-UNKNOWN			
MOS	22-FEB-2000	REASON: B - FAIL		On:		MOS		
HRS	7107	TECH:				HRS 0		
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
290178	INSPECT/LUBRICATE NO. 2 HYDRAULIC PUMP NO.2 ENGINE HYDRAULIC PUMP SPLINES					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --				MOS		
HRS	7107	TECH:				HRS		
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3								

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
290143	INSPECT/LUBRICATE NO. 1 HYDRAULIC PUMP NO.1 ENGINE HYDRAULIC PUMP SPLINES				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --			MOS		
HRS	7107	TECH:			HRS		
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
281150	CHECK OPERATION OF FUEL BOOST PUMPS				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --			MOS		
HRS	7107	TECH:			HRS		
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
270335	OPERATIONAL CHECK SPEED BRAKES AND LIFT DUMPERS				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --			MOS		
HRS	7107	TECH:			HRS		
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
270247	INSPECT RIGHT FLAP/VANE				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --			MOS		
HRS	7107	TECH:			HRS		
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
270242	INSPECT RIGHT FLAP/VANE RIGHT FLAP HINGE AND BEARING 200 HOURS				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --			MOS		
HRS	7107	TECH:			HRS		
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
270240	INSPECT LEFT FLAP/VANE LEFT FLAP HINGE AND BEARING 200 HOURS				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --			MOS		
HRS	7107	TECH:			HRS		
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
270237	INSPECT LEFT FLAP/VANE LEFT FLAP VANE				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --			MOS		
HRS	7107	TECH:			HRS		
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
270215	LUBRICATE FORWARD SCISSOR ASSEMBLY				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --			MOS		
HRS	7107	TECH:			HRS		
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3 - POST 55-021							

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
270214	LUBRICATE AFT HINGE FITTING BEARINGS							
	C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - PRE 55-021								
270213	LUBRICATE ELEVATOR ATTACH POINTS							
	C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
270203	INSPECT RIGHT ELEVATOR SKIN SEPARATION							
	C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
270193	INSPECT LEFT ELEVATOR SKIN SEPARATION							
	C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
240133	INSPECT NO. 2 STARTER GENERATOR SPLINE							
	C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 5,7								
240121	CHECK NO. 1 STARTER GENERATOR BRUSH WEAR/TENSION							
	C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 4,6								
100330	CHECK SERVICE LETTERS							
	C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
100320	CHECK SERVICE BULLETINS							
	C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
100310	CHECK AIRWORTHY DIRECTIVES				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --			MOS		
HRS	7107	TECH:			HRS		
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
120160	CHECK NO.1 ENGINE PREFLIGHT COMPLETE				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 07-JUN-2000 12:00:00					
MOS	01-MAY-2000	REASON: --			MOS		
HRS	7246	TECH:			HRS		
AFL	5308	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 4,6							
240128	INSPECT NO. 2 STARTER GENERATOR				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 07-JUN-2000 12:00:00					
MOS	01-MAY-2000	REASON: --			MOS		
HRS	7246	TECH:			HRS		
AFL	5308	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 5,7							
240133	INSPECT NO. 2 STARTER GENERATOR SPLINE				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 07-JUN-2000 12:00:00					
MOS	01-MAY-2000	REASON: --			MOS		
HRS	7246	TECH:			HRS		
AFL	5308	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 5,7							
240131	CHECK NO. 2 STARTER GENERATOR BRUSH WEAR/TENSION				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 07-JUN-2000 12:00:00					
MOS	01-MAY-2000	REASON: --			MOS		
HRS	7246	TECH:			HRS		
AFL	5308	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 5,7							
240123	INSPECT NO. 1 STARTER GENERATOR SPLINE				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 07-JUN-2000 12:00:00					
MOS	01-MAY-2000	REASON: --			MOS		
HRS	7246	TECH:			HRS		
AFL	5308	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 4,6							
240121	CHECK NO. 1 STARTER GENERATOR BRUSH WEAR/TENSION				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 07-JUN-2000 12:00:00					
MOS	01-MAY-2000	REASON: --			MOS		
HRS	7246	TECH:			HRS		
AFL	5308	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 4,6							
240118	INSPECT NO. 1 STARTER GENERATOR				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 07-JUN-2000 12:00:00					
MOS	01-MAY-2000	REASON: --			MOS		
HRS	7246	TECH:			HRS		
AFL	5308	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 4,6							

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
120161	CHECK NO.2 ENGINE PREFLIGHT COMPLETE					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 07-JUN-2000 12:00:00						
MOS	01-MAY-2000	REASON: --				MOS		
HRS	7246	TECH:				HRS		
AFL	5308	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 5,7								
972847U	SERVICE BULLETIN GSB TFE 731-A72-3432 L/H							
C/W	WARR	TRANSACTION DATE: 10-JUL-2000 12:00:00						
MOS	05-JUL-2000	REASON: --				MOS		
HRS	7324	TECH:				HRS		
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
050150U	200 HOUR INSPECTION					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	17-JAN-2001	REASON: --				MOS		
HRS	7494	TECH:				HRS		
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 2,3								
100330	CHECK SERVICE LETTERS					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --				MOS		
HRS	7325	TECH:				HRS		
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3								
270158	INSPECT RUDDER TRIM TAB FREEPLAY					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --				MOS		
HRS	7325	TECH:				HRS		
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3								
270158	INSPECT RUDDER TRIM TAB FREEPLAY					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	17-JAN-2001	REASON: --				MOS		
HRS	7494	TECH:				HRS		
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3								
260186	OPERATIONAL CHECK FIRE PROTECTION SYSTEM					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --				MOS		
HRS	7325	TECH:				HRS		
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 2,3								
260184	INSPECT CABIN PORTABLE EXTINGUISHER CABIN FIRE EXTINGUISHER					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --				MOS		
HRS	7325	TECH:				HRS		
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3								

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR	
260184	INSPECT CABIN PORTABLE EXTINGUISHER CABIN FIRE EXTINGUISHER						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS 17-JAN-2001		REASON: --		MOS			
HRS 7494		TECH:		HRS			
AFL 5466		INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3							
260174	INSPECT COCKPIT PORTABLE EXTINGUISHER COCKPIT FIRE EXTINGUISHER						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS 26-JUL-2000		REASON: --		MOS			
HRS 7325		TECH:		HRS			
AFL 5360		INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3							
260174	INSPECT COCKPIT PORTABLE EXTINGUISHER COCKPIT FIRE EXTINGUISHER						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS 17-JAN-2001		REASON: --		MOS			
HRS 7494		TECH:		HRS			
AFL 5466		INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3							
260131	WEIGHT CHECK RIGHT FIRE EXTINGUISHER						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS 26-JUL-2000		REASON: --		MOS			
HRS 7325		TECH:		HRS			
AFL 5360		INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
260116	WEIGHT CHECK LEFT FIRE EXTINGUISHER						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS 26-JUL-2000		REASON: --		MOS			
HRS 7325		TECH:		HRS			
AFL 5360		INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
240176	CHECK RIGHT BATTERY ELECTROLYTE LEVEL						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS 26-JUL-2000		REASON: --		MOS			
HRS 7325		TECH:		HRS			
AFL 5360		INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3							
240176	CHECK RIGHT BATTERY ELECTROLYTE LEVEL						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS 17-JAN-2001		REASON: --		MOS			
HRS 7494		TECH:		HRS			
AFL 5466		INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3							
240166	DEEP CYCLELEFT BATTERY						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS 26-JUL-2000		REASON: --		MOS			
HRS 7325		TECH:		HRS			
AFL 5360		INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3							

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
240166	DEEP CYCLE LEFT BATTERY							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001		REASON: --					MOS
HRS	7494		TECH:					HRS
AFL	5466		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
240161	CHECK LEFT BATTERY ELECTROLYTE LEVEL							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
240161	CHECK LEFT BATTERY ELECTROLYTE LEVEL							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001		REASON: --					MOS
HRS	7494		TECH:					HRS
AFL	5466		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
240131	CHECK NO. 2 STARTER GENERATOR BRUSH WEAR/TENSION							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 5,7								
240128	INSPECT NO. 2 STARTER GENERATOR							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 5,7								
240123	INSPECT NO. 1 STARTER GENERATOR SPLINE							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001		REASON: --					MOS
HRS	7494		TECH:					HRS
AFL	5466		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 4,6								
240203	FUNCTIONALLY CHECK EXTERNAL POWER RECEPTACLE BATTERY TEMPERATURE AND WARNING SYSTEM							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR	
240203	FUNCTIONALLY CHECK EXTERNAL POWER RECEPTACLE BATTERY TEMPERATURE AND WARNING SYSTEM						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	17-JAN-2001	REASON: --		MOS			
HRS	7494	TECH:		HRS			
AFL	5466	INSP:		AFL			
Note: OP 1,2,3		LABOR HRS: 0	COST: \$0.00				
240181	DEEP CYCLE RIGHT BATTERY						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	26-JUL-2000	REASON: --		MOS			
HRS	7325	TECH:		HRS			
AFL	5360	INSP:		AFL			
Note: OP 1,2,3		LABOR HRS: 0	COST: \$0.00				
240181	DEEP CYCLE RIGHT BATTERY						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	17-JAN-2001	REASON: --		MOS			
HRS	7494	TECH:		HRS			
AFL	5466	INSP:		AFL			
Note: OP 1,2,3		LABOR HRS: 0	COST: \$0.00				
240121	CHECK NO. 1 STARTER GENERATOR BRUSH WEAR/TENSION						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	17-JAN-2001	REASON: --		MOS			
HRS	7494	TECH:		HRS			
AFL	5466	INSP:		AFL			
Note: OP 4,6		LABOR HRS: 0	COST: \$0.00				
240116	CHANGE NO. 1 STARTER GENERATOR						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	17-JAN-2001	Off. 23065-018-1	2258	MOS	0		
HRS	7494	On:		HRS	0		
AFL	5466	LABOR HRS: 0	COST: \$0.00	AFL	0		
230218	INSPECT/CHECK STATIC DISCHARGE WICK RESISTANCE						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	26-JUL-2000	REASON: --		MOS			
HRS	7325	TECH:		HRS			
AFL	5360	INSP:		AFL			
Note: OP 2,3		LABOR HRS: 0	COST: \$0.00				
210681	CHANGE COOLING TURBINE OIL						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	26-JUL-2000	REASON: --		MOS			
HRS	7325	TECH:		HRS			
AFL	5360	INSP:		AFL			
Note: OP 1,2,3		LABOR HRS: 0	COST: \$0.00				
210681	CHANGE COOLING TURBINE OIL						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	17-JAN-2001	REASON: --		MOS			
HRS	7494	TECH:		HRS			
AFL	5466	INSP:		AFL			
Note: OP 1,2,3		LABOR HRS: 0	COST: \$0.00				



AIRCRAFT Updates Report

Serial #: 368 Reg. #: N368MD
 Model: 1124A WESTWIND

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
210671	CLEAN/REPLACE WATER SEPARATOR CONDENSER/FILTER							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
210671	CLEAN/REPLACE WATER SEPARATOR CONDENSER/FILTER							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001		REASON: --					MOS
HRS	7494		TECH:					HRS
AFL	5466		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
210622	INSPECT 35 DEGREE TEMPERATURE SENSOR 35 DEGREE DUCT SENSOR							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
270240	INSPECT LEFT FLAP/VANE LEFT FLAP HINGE AND BEARING 200 HOURS							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001		REASON: --					MOS
HRS	7494		TECH:					HRS
AFL	5466		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
270238	TAP TEST LEFT FLAP/VANE LEFT FLAP							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
270237	INSPECT LEFT FLAP/VANE LEFT FLAP VANE							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
270237	INSPECT LEFT FLAP/VANE LEFT FLAP VANE							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001		REASON: --					MOS
HRS	7494		TECH:					HRS
AFL	5466		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
270217	INSPECT HORIZONTAL STABILIZER TRIM ACTUATOR							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
270215	LUBRICATE FORWARD SCISSOR ASSEMBLY						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - POST 55-021							
270215	LUBRICATE FORWARD SCISSOR ASSEMBLY						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001	REASON: --					MOS
HRS	7494	TECH:					HRS
AFL	5466	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - POST 55-021							
270214	LUBRICATE AFT HINGE FITTING BEARINGS						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - PRE 55-021							
270214	LUBRICATE AFT HINGE FITTING BEARINGS						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001	REASON: --					MOS
HRS	7494	TECH:					HRS
AFL	5466	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - PRE 55-021							
300104	INSPECT RIGHT DE-ICER CHECK VALVE						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3							
300102	INSPECT LEFT DE-ICER CHECK VALVE						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3							
290178	INSPECT/LUBRICATE NO. 2 HYDRAULIC PUMP NO.2 ENGINE HYDRAULIC PUMP SPLINES						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
290178	INSPECT/LUBRICATE NO. 2 HYDRAULIC PUMP NO.2 ENGINE HYDRAULIC PUMP SPLINES						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001	REASON: --					MOS
HRS	7494	TECH:					HRS
AFL	5466	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							



AIRCRAFT Updates Report

Serial #: 368 Reg. #: N368MD
 Model : 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
290143	INSPECT/LUBRICATE NO. 1 HYDRAULIC PUMP NO.1 ENGINE HYDRAULIC PUMP SPLINES							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --					MOS	
HRS	7325	TECH:					HRS	
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3								
290143	INSPECT/LUBRICATE NO. 1 HYDRAULIC PUMP NO.1 ENGINE HYDRAULIC PUMP SPLINES							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	17-JAN-2001	REASON: --					MOS	
HRS	7494	TECH:					HRS	
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3								
290118	CLEAN/CHECK RESERVOIR AIR PRESSURE REGULATOR HYDRAULIC RESERVOIR AIR PRESSURE CHECK VALVE							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --					MOS	
HRS	7325	TECH:					HRS	
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 2,3								
281150	CHECK OPERATION OF FUEL BOOST PUMPS							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	24-APR-2000	REASON: --					MOS	
HRS	7233	TECH:					HRS	
AFL	5301	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3								
281150	CHECK OPERATION OF FUEL BOOST PUMPS							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --					MOS	
HRS	7325	TECH:					HRS	
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3								
050600U	800/400/200 HOUR INSPECT							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --					MOS	
HRS	7325	TECH:					HRS	
AFL	5360	INSP:		LABOR HRS: 45.5	COST: \$0.00		AFL	
2000-23-13	TO PREVENT JAMMING OR DISCONNECTION OF THE HORIZONTAL STABILIZER TRIM ACTUATOR, WHICH COULD RESULT IN REDUCED PITCH CONTROL OF THE AIRPLANE AIRWORTHINESS DIRECTIVE							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS		REASON: --					MOS	
HRS	0	TECH:					HRS	
AFL	0	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR	
1996-24-11	RIGHT AILERON TO PREVENT EXCESSIVE WEAR OF THE AILERON PUSH-PULL TUBE, WHICH COULD RESULT IN UNEVEN MOVEMENT OF THE CONTROL WHEEL, PERFORATION OF THE AILERON PUSH-PULL TUBE, AND CONSEQUENT REDUCED ROLL CONTROL OF THE AIRPLANE AIRWORTHINESS DIRECTIVE						
CW	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --				MOS	
HRS	7325	TECH:				HRS	
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00	AFL	
1996-24-11	LEFT AILERON TO PREVENT EXCESSIVE WEAR OF THE AILERON PUSH-PULL TUBE, WHICH COULD RESULT IN UNEVEN MOVEMENT OF THE CONTROL WHEEL, PERFORATION OF THE AILERON PUSH-PULL TUBE, AND CONSEQUENT REDUCED ROLL CONTROL OF THE AIRPLANE AIRWORTHINESS DIRECTIVE						
CW	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --				MOS	
HRS	7325	TECH:				HRS	
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00	AFL	
1995-22-01	TO PREVENT SMOKE, FIRE, ELECTRICAL SHOCK, AND POSSIBLE ELECTROMAGNETIC INTERFERENCE CAUSED BY HIGH VOLTAGE ARCING IN THE CABIN WHICH, IF UNDETECTED, COULD RESULT IN PERSONAL HAZARD OR LOSS OF THE AIRCRAFT AIRWORTHINESS DIRECTIVE						
CW	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS		REASON: --				MOS	
HRS	0	TECH:				HRS	
AFL	0	INSP:		LABOR HRS: 0	COST: \$0.00	AFL	
1989-12-08	TO DETECT CRACKS IN THE HINGE LUGS OF THE HORIZONTAL STABILIZER AFT SPAR SPLICE FITTING (HINGE ASSEMBLY) AIRWORTHINESS DIRECTIVE						
CW	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	17-JAN-2001	REASON: --				MOS	
HRS	7494	TECH:				HRS	
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00	AFL	
1974-08-09 R2	TO PREVENT POSSIBLE FIRES THAT COULD RESULT FROM SMOKING MATERIALS BEING DROPPED INTO LAVATORY PAPER OR LINEN WASTE RECEPTACLES AIRWORTHINESS DIRECTIVE						
CW	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	17-JAN-2001	REASON: --				MOS	
HRS	7494	TECH:				HRS	
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00	AFL	
911470	ASB1124-27A-147 SERVICE BULLETIN						
CW	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS		REASON: --				MOS	
MSC		TECH:				MSC	
AFL	0	INSP:		LABOR HRS: 0	COST: \$0.00	AFL	
911390	SB1124-32-139 UPR STRG SERVICE BULLETIN						
CW	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --				MOS	
HRS	7325	TECH:				HRS	
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00	AFL	
1124-27-129	RIGHT AILERON FLIGHT CONTROLS SERVICE BULLETIN						
CW	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --				MOS	
HRS	7325	TECH:				HRS	
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00	AFL	

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR		
1124-27-129 LEFT AILERON FLIGHT CONTROLS SERVICE BULLETIN								
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --					MOS	
HRS	7325	TECH:					HRS	
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
780643 LUBRICATE NO. 2 THRUST REVERSER ASSEMBLY								
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --					MOS	
HRS	7325	TECH:					HRS	
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
780616 OPERATIONAL CHECK NO.2 THRUST REVERSER								
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --					MOS	
HRS	7325	TECH:					HRS	
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
780143 LUBRICATE NO. 1 THRUST REVERSER ASSEMBLY								
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --					MOS	
HRS	7325	TECH:					HRS	
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
780120 CHECK #2 THRUST REVERSER SECONDARY LATCH SOLENOID SWITCH								
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --					MOS	
HRS	7325	TECH:					HRS	
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
780119 CHECK #1 THRUST REVERSER SECONDARY LATCH SOLENOID SWITCH								
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --					MOS	
HRS	7325	TECH:					HRS	
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
780116 OPERATIONAL CHECK NO.1 THRUST REVERSER								
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --					MOS	
HRS	7325	TECH:					HRS	
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
560118 INSPECT COPILOT SIDE WINDOW								
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --					MOS	
HRS	7325	TECH:					HRS	
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
560112 INSPECT PILOT SIDE WINDOW								
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --					MOS	
HRS	7325	TECH:					HRS	
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	

3/19/2002 11:41:19 PM

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
DATE								
550658	CHECK HORIZONTAL STABILIZER ASSEMBLY RADIAL/AXIAL PLAY							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
540131U	INSPECT NO. 2 ENGINE NACELLE/PYLON (C)							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
540111U	INSPECT NO. 1 ENGINE NACELLE/PYLON (C)							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	17-JAN-2001	REASON: --						MOS
HRS	7494	TECH:						HRS
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
910200	ACCOMPLISH SB 1124-55-020 REV 2 BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
713650U	-- INSP #2 ENG INLET NACELLE							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
713650U	-- INSP #2 ENG INLET NACELLE							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	17-JAN-2001	REASON: --						MOS
HRS	7494	TECH:						HRS
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								



AIRCRAFT Updates Report

Serial #: 368 Reg. #: N368MD
 Model: 1124A WESTWIND

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
710650U	-- INSP #1 ENG INLET NACELLE							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
710650U	-- INSP #1 ENG INLET NACELLE							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					MOS
MOS	17-JAN-2001		REASON: --					HRS
HRS	7494		TECH:	LABOR HRS: 0	COST: \$0.00			AFL
AFL	5466		INSP:					
Note: OP 1,2,3								
570120	INSPECT RIGHT AILERON BELLCRANK							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					MOS
MOS	26-JUL-2000		REASON: --					HRS
HRS	7325		TECH:	LABOR HRS: 0	COST: \$0.00			AFL
AFL	5360		INSP:					
Note: OP 1,2,3								
570120	INSPECT RIGHT AILERON BELLCRANK							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					MOS
MOS	17-JAN-2001		REASON: --					HRS
HRS	7494		TECH:	LABOR HRS: 0	COST: \$0.00			AFL
AFL	5466		INSP:					
Note: OP 1,2,3								
570119	INSPECT RIGHT WING (B)							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					MOS
MOS	26-JUL-2000		REASON: --					HRS
HRS	7325		TECH:	LABOR HRS: 0	COST: \$0.00			AFL
AFL	5360		INSP:					
Note: OP 2,3								
570116	INSPECT RIGHT WING (A)							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					MOS
MOS	26-JUL-2000		REASON: --					HRS
HRS	7325		TECH:	LABOR HRS: 0	COST: \$0.00			AFL
AFL	5360		INSP:					
Note: OP 1,2,3								
570116	INSPECT RIGHT WING (A)							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					MOS
MOS	17-JAN-2001		REASON: --					HRS
HRS	7494		TECH:	LABOR HRS: 0	COST: \$0.00			AFL
AFL	5466		INSP:					
Note: OP 1,2,3								
570106	INSPECT LEFT AILERON BELLCRANK							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					MOS
MOS	26-JUL-2000		REASON: --					HRS
HRS	7325		TECH:	LABOR HRS: 0	COST: \$0.00			AFL
AFL	5360		INSP:					
Note: OP 1,2,3								

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
570106	INSPECT LEFT AILERON BELLCRANK				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	17-JAN-2001	REASON: --			MOS		
HRS	7494	TECH:			HRS		
AFL	5466	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
570104	INSPECT LEFT WING (B)				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --			MOS		
HRS	7325	TECH:			HRS		
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 2,3							
570101	INSPECT LEFT WING (A)				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --			MOS		
HRS	7325	TECH:			HRS		
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
570101	INSPECT LEFT WING (A)				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	17-JAN-2001	REASON: --			MOS		
HRS	7494	TECH:			HRS		
AFL	5466	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
560106	CHANGE COPILOT OUTER WINDSHIELD				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00	Off. PPG 343030-2	99158H0464			
MOS	26-AUG-2000	REASON: B - FAIL	On:		MOS		
HRS	7352	TECH:			HRS		
AFL	5381	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
560106	CHANGE COPILOT OUTER WINDSHIELD				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00	Off. PPG 343030-2	84-H-1-2-096			
MOS		REASON: --	On:		MOS	0	
HRS		TECH:			HRS	0	
AFL		INSP:	LABOR HRS: 0	COST: \$0.00	AFL	0	
560106	CHANGE COPILOT OUTER WINDSHIELD				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00	Off. 5-343026-501	SN-UNKNOWN			
MOS	26-JUL-2000	REASON: B - FAIL	On:		MOS		
HRS	7325	TECH:			HRS	0	
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00	AFL	0	
550656	CHECK HORIZONTAL STABILIZER AFT SPAR SPLICE-HINGE FITTING OUTBOARD LUGS FOR CRACKS				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --			MOS		
HRS	7325	TECH:			HRS		
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
550656	CHECK HORIZONTAL STABILIZER AFT SPAR SPLICE-HINGE FITTING OUTBOARD LUGS FOR CRACKS						
	C/W	WARR					
MOS	17-JAN-2001						MOS
HRS	7494						HRS
AFL	5466						AFL
Note: OP 1,2,3			LABOR HRS: 0	COST: \$0.00			
Done By: CAMP SYSTEMS INTERNATIONAL, LLC							
550106	INSPECT EMPENNAGE (B)						
	C/W	WARR					
MOS	26-JUL-2000						MOS
HRS	7325						HRS
AFL	5360						AFL
Note: OP 2,3			LABOR HRS: 0	COST: \$0.00			
Done By: CAMP SYSTEMS INTERNATIONAL, LLC							
550101	INSPECT EMPENNAGE (A)						
	C/W	WARR					
MOS	26-JUL-2000						MOS
HRS	7325						HRS
AFL	5360						AFL
Note: OP 1,2,3			LABOR HRS: 0	COST: \$0.00			
Done By: CAMP SYSTEMS INTERNATIONAL, LLC							
550101	INSPECT EMPENNAGE (A)						
	C/W	WARR					
MOS	17-JAN-2001						MOS
HRS	7494						HRS
AFL	5466						AFL
Note: OP 1,2,3			LABOR HRS: 0	COST: \$0.00			
Done By: CAMP SYSTEMS INTERNATIONAL, LLC							
540126U	INSPECT NO. 2 ENGINE NACELLE/PYLON (B)						
	C/W	WARR					
MOS	26-JUL-2000						MOS
HRS	7325						HRS
AFL	5360						AFL
Note: OP 2,3			LABOR HRS: 0	COST: \$0.00			
Done By: CAMP SYSTEMS INTERNATIONAL, LLC							
540121U	INSPECT NO. 2 ENGINE NACELLE/PYLON (A)						
	C/W	WARR					
MOS	26-JUL-2000						MOS
HRS	7325						HRS
AFL	5360						AFL
Note: OP 1,2,3			LABOR HRS: 0	COST: \$0.00			
Done By: CAMP SYSTEMS INTERNATIONAL, LLC							
540121U	INSPECT NO. 2 ENGINE NACELLE/PYLON (A)						
	C/W	WARR					
MOS	17-JAN-2001						MOS
HRS	7494						HRS
AFL	5466						AFL
Note: OP 1,2,3			LABOR HRS: 0	COST: \$0.00			
Done By: CAMP SYSTEMS INTERNATIONAL, LLC							
540106U	INSPECT NO. 1 ENGINE NACELLE/PYLON (B)						
	C/W	WARR					
MOS	26-JUL-2000						MOS
HRS	7325						HRS
AFL	5360						AFL
Note: OP 2,3			LABOR HRS: 0	COST: \$0.00			
Done By: CAMP SYSTEMS INTERNATIONAL, LLC							

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model : 1124A WESTWIND

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
540101U	INSPECT NO. 1 ENGINE NACELLE/PYLON (A)							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
540101U	INSPECT NO. 1 ENGINE NACELLE/PYLON (A)							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001	REASON: --						MOS
HRS	7494	TECH:						HRS
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
530166	INSPECT REAR COMPARTMENT (B)							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
530161	INSPECT REAR COMPARTMENT (A)							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
530161	INSPECT REAR COMPARTMENT (A)							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001	REASON: --						MOS
HRS	7494	TECH:						HRS
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
530146	INSPECT CABIN (A)							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
530146	INSPECT CABIN (A)							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001	REASON: --						MOS
HRS	7494	TECH:						HRS
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
530136	INSPECT COCKPIT (B)							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								



AIRCRAFT Updates Report

Serial #: 368 Reg. #: N368MD
 Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
530131	INSPECT COCKPIT (A)							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
530131	INSPECT COCKPIT (A)							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001		REASON: --					MOS
HRS	7494		TECH:					HRS
AFL	5466		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
530121	INSPECT NOSE COMPARTMENT (B)							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
530116	INSPECT NOSE COMPARTMENT (A)							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
530116	INSPECT NOSE COMPARTMENT (A)							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001		REASON: --					MOS
HRS	7494		TECH:					HRS
AFL	5466		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
530101	INSPECT FUSELAGE (A)							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
530101	INSPECT FUSELAGE (A)							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001		REASON: --					MOS
HRS	7494		TECH:					HRS
AFL	5466		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
520116	OPERATIONAL CHECK CABIN ENTRANCE DOOR							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
520116	OPERATIONAL CHECK CABIN ENTRANCE DOOR						
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
MOS	17-JAN-2001		REASON: --		MOS		
HRS	7494		TECH:		HRS		
AFL	5466		INSP:		AFL		
LABOR HRS: 0 COST: \$0.00							
Note: OP 1,2,3							
520106	INSPECT/LUBRICATE CABIN ENTRANCE DOOR						
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
MOS	26-JUL-2000		REASON: --		MOS		
HRS	7325		TECH:		HRS		
AFL	5360		INSP:		AFL		
LABOR HRS: 0 COST: \$0.00							
Note: OP 1,2,3							
520106	INSPECT/LUBRICATE CABIN ENTRANCE DOOR						
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
MOS	17-JAN-2001		REASON: --		MOS		
HRS	7494		TECH:		HRS		
AFL	5466		INSP:		AFL		
LABOR HRS: 0 COST: \$0.00							
Note: OP 1,2,3							
344616	INSPECT EMERGENCY GYRO POWER SUPPLY BATTERY		EMERGENCY POWER SUPPLY				
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
MOS	17-JAN-2001		REASON: --		MOS		
HRS	7494		TECH:		HRS		
AFL	5466		INSP:		AFL		
LABOR HRS: 0 COST: \$0.00							
Note: PS 823 ONLY							
340121	DRAIN PITOT/STATIC SYSTEM						
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
MOS	26-JUL-2000		REASON: --		MOS		
HRS	7325		TECH:		HRS		
AFL	5360		INSP:		AFL		
LABOR HRS: 0 COST: \$0.00							
Note: OP 1,2,3							
340121	DRAIN PITOT/STATIC SYSTEM						
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
MOS	17-JAN-2001		REASON: --		MOS		
HRS	7494		TECH:		HRS		
AFL	5466		INSP:		AFL		
LABOR HRS: 0 COST: \$0.00							
Note: OP 1,2,3							
330228	CHARGE EMERGENCY LIGHT BATTERY						
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
MOS	17-JAN-2001		REASON: --		MOS		
HRS	7494		TECH:		HRS		
AFL	5466		INSP:		AFL		
LABOR HRS: 0 COST: \$0.00							
330156	CHANGE UPPER ANTI-COLLISION LIGHT						
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
MOS	26-JUL-2000		REASON: B - FAIL		MOS		
HRS	7325		TECH:		HRS		
AFL	5360		INSP:		AFL		
LABOR HRS: 0				Off: G9950-31	11303		
				On:		0	
COST: \$0.00						0	

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
322206	FUNCTIONAL TEST EMERGENCY GEAR EXTENSION CONTROL CABLE							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
322206	FUNCTIONAL TEST EMERGENCY GEAR EXTENSION CONTROL CABLE							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001		REASON: --					MOS
HRS	7494		TECH:					HRS
AFL	5466		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
322201	FUNCTIONAL TEST LANDING GEAR FREE FALL							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
322191	FUNCTIONAL TEST LANDING GEAR (NORMAL)							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
322176	FUNCTIONAL CHECK ANTI-SKID DETECTOR SYSTEM							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
322174	OPERATIONAL CHECK ANTI-SKID LIGHTS							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
322174	OPERATIONAL CHECK ANTI-SKID LIGHTS							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001		REASON: --					MOS
HRS	7494		TECH:					HRS
AFL	5466		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
322171	INSPECT/CLEAN RIGHT ANTI-SKID DETECTOR							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
322171	INSPECT/CLEAN RIGHT ANTI-SKID DETECTOR						
CW	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001	REASON: --					MOS
HRS	7494	TECH:					HRS
AFL	5466	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
322156	INSPECT/CLEAN LEFT ANTI-SKID DETECTOR						
CW	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
322156	INSPECT/CLEAN LEFT ANTI-SKID DETECTOR						
CW	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001	REASON: --					MOS
HRS	7494	TECH:					HRS
AFL	5466	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
322131	INSPECT/CHECK RIGHT MAIN GEAR BRAKE RIGHT BRAKE LININGS						
CW	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
322131	INSPECT/CHECK RIGHT MAIN GEAR BRAKE RIGHT BRAKE LININGS						
CW	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001	REASON: --					MOS
HRS	7494	TECH:					HRS
AFL	5466	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
322116	INSPECT/CHECK LEFT MAIN GEAR BRAKE LEFT BRAKE LININGS						
CW	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
322116	INSPECT/CHECK LEFT MAIN GEAR BRAKE LEFT BRAKE LININGS						
CW	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001	REASON: --					MOS
HRS	7494	TECH:					HRS
AFL	5466	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
322128	CHANGE RIGHT MAIN GEAR BRAKE						
CW	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00	Off: 5002805-3	1140			Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001	REASON: C - WORN	On:				MOS
HRS	7494	TECH:					HRS
AFL	5466	INSP:	LABOR HRS: 0	COST: \$0.00			AFL

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002** From Date : To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
322128	CHANGE RIGHT MAIN GEAR BRAKE							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Off 5002805-3	MAY82-328			Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS		REASON: --		On:				MOS
HRS		TECH:						HRS
AFL		INSP:		LABOR HRS: 0	COST: \$0.00			AFL
321616	CHECK EMERGENCY STORAGE BOTTLE LANDING GEAR EMERGENCY SYSTEM PRESSURE							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
322113	CHANGE LEFT MAIN GEAR BRAKE							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Off 5002805-3	12153-6			Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001	REASON: C - WORN		On:				MOS
HRS	7494	TECH:						HRS
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
322113	CHANGE LEFT MAIN GEAR BRAKE							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Off 5002805-3	M104			Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS		REASON: --		On:				MOS
HRS		TECH:						HRS
AFL		INSP:		LABOR HRS: 0	COST: \$0.00			AFL
321191	INSPECT RIGHT MAIN GEAR OUTBOARD WHEEL HALF RIGHT MAIN GEAR/WELL (A)							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
321191	INSPECT RIGHT MAIN GEAR OUTBOARD WHEEL HALF RIGHT MAIN GEAR/WELL (A)							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001	REASON: --						MOS
HRS	7494	TECH:						HRS
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
321180	INSPECT/LUBRICATE RIGHT MAIN GEAR OUTBOARD WHEEL HALF RIGHT MAIN GEAR OUTBOARD WHEEL BEARINGS							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
321180	INSPECT/LUBRICATE RIGHT MAIN GEAR OUTBOARD WHEEL HALF RIGHT MAIN GEAR OUTBOARD WHEEL BEARINGS							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001	REASON: --						MOS
HRS	7494	TECH:						HRS
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
321178	DYE PENETRANT CHECK RIGHT WHEEL AXLE						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3							
321176	INSPECT/LUBRICATE RIGHT MAIN GEAR INBOARD WHEEL HALF RIGHT MAIN GEAR INBOARD WHEEL BEARINGS						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
321175	INSPECT/LUBRICATE RIGHT MAIN GEAR INBOARD WHEEL HALF RIGHT MAIN GEAR INBOARD WHEEL BEARINGS						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001	REASON: --					MOS
HRS	7494	TECH:					HRS
AFL	5466	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
321136	SERVICE RIGHT MAIN GEAR ASSEMBLY RIGHT MAIN GEAR SHOCK STRUT						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3							
321107	LUBRICATE RIGHT ACTUATOR BOLTS						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3							
321106	LUBRICATE RIGHT MAIN GEAR ASSEMBLY RIGHT MAIN GEAR						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
321106	LUBRICATE RIGHT MAIN GEAR ASSEMBLY RIGHT MAIN GEAR						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001	REASON: --					MOS
HRS	7494	TECH:					HRS
AFL	5466	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							



AIRCRAFT Updates Report

Serial #: 368 Reg. #: N368MD
 Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
320691	INSPECT LEFT MAIN GEAR/WELL (A)							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
320691	INSPECT LEFT MAIN GEAR/WELL (A)							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001		REASON: --					MOS
HRS	7494		TECH:					HRS
AFL	5466		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
320680	INSPECT/LUBRICATE LEFT MAIN GEAR OUTBOARD WHEEL HALF LEFT MAIN GEAR OUTBOARD WHEEL BEARINGS							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
320680	INSPECT/LUBRICATE LEFT MAIN GEAR OUTBOARD WHEEL HALF LEFT MAIN GEAR OUTBOARD WHEEL BEARINGS							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001		REASON: --					MOS
HRS	7494		TECH:					HRS
AFL	5466		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
320678	DYE PENETRANT CHECK LEFT WHEEL AXLE							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
320676	INSPECT/LUBRICATE LEFT MAIN GEAR INBOARD WHEEL HALF LEFT MAIN GEAR INBOARD WHEEL BEARINGS							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
320676	INSPECT/LUBRICATE LEFT MAIN GEAR INBOARD WHEEL HALF LEFT MAIN GEAR INBOARD WHEEL BEARINGS							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001		REASON: --					MOS
HRS	7494		TECH:					HRS
AFL	5466		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR	
320636	SERVICE LEFT MAIN GEAR ASSEMBLY LEFT MAIN GEAR SHOCK STRUT						
C/W	WARR						
MOS	26-JUL-2000	TRANSACTION DATE: 23-MAY-2001 12:00:00					
HRS	7325	REASON: --				MOS	
AFL	5360	TECH:				HRS	
		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 2,3							
320607	LUBRICATE LEFT ACTUATOR BOLTS						
C/W	WARR						
MOS	26-JUL-2000	TRANSACTION DATE: 23-MAY-2001 12:00:00					
HRS	7325	REASON: --				MOS	
AFL	5360	TECH:	LABOR HRS: 0	COST: \$0.00		HRS	
		INSP:				AFL	
Note: OP 2,3							
320606	LUBRICATE LEFT MAIN GEAR ASSEMBLY LEFT MAIN GEAR						
C/W	WARR						
MOS	26-JUL-2000	TRANSACTION DATE: 23-MAY-2001 12:00:00					
HRS	7325	REASON: --				MOS	
AFL	5360	TECH:	LABOR HRS: 0	COST: \$0.00		HRS	
		INSP:				AFL	
Note: OP 1,2,3							
320606	LUBRICATE LEFT MAIN GEAR ASSEMBLY LEFT MAIN GEAR						
C/W	WARR						
MOS	17-JAN-2001	TRANSACTION DATE: 23-MAY-2001 12:00:00					
HRS	7494	REASON: --				MOS	
AFL	5466	TECH:	LABOR HRS: 0	COST: \$0.00		HRS	
		INSP:				AFL	
Note: OP 1,2,3							
320206	INSPECT NOSE GEAR (B)						
C/W	WARR						
MOS	26-JUL-2000	TRANSACTION DATE: 23-MAY-2001 12:00:00					
HRS	7325	REASON: --				MOS	
AFL	5360	TECH:	LABOR HRS: 0	COST: \$0.00		HRS	
		INSP:				AFL	
Note: OP 2,3							
320201	INSPECT NOSE GEAR (A)						
C/W	WARR						
MOS	26-JUL-2000	TRANSACTION DATE: 23-MAY-2001 12:00:00					
HRS	7325	REASON: --				MOS	
AFL	5360	TECH:	LABOR HRS: 0	COST: \$0.00		HRS	
		INSP:				AFL	
Note: OP 1,2,3							
320201	INSPECT NOSE GEAR (A)						
C/W	WARR						
MOS	17-JAN-2001	TRANSACTION DATE: 23-MAY-2001 12:00:00					
HRS	7494	REASON: --				MOS	
AFL	5466	TECH:	LABOR HRS: 0	COST: \$0.00		HRS	
		INSP:				AFL	
Note: OP 1,2,3							
320158	INSPECT/CLEAN/LUBRICATE NOSE GEAR RIGHT WHEEL BEARINGS						
C/W	WARR						
MOS	26-JUL-2000	TRANSACTION DATE: 23-MAY-2001 12:00:00					
HRS	7325	REASON: --				MOS	
AFL	5360	TECH:	LABOR HRS: 0	COST: \$0.00		HRS	
		INSP:				AFL	
Note: OP 1,2,3							



AIRCRAFT Updates Report

Serial #: 368 Reg. #: N368MD
 Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
320158	INSPECT/CLEAN/LUBRICATE NOSE GEAR RIGHT WHEEL BEARINGS							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001		REASON: --					MOS
HRS	7494		TECH:					HRS
AFL	5466		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
320156	INSPECT/CLEAN/LUBRICATE NOSE GEAR LEFT WHEEL BEARINGS							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
320156	INSPECT/CLEAN/LUBRICATE NOSE GEAR LEFT WHEEL BEARINGS							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001		REASON: --					MOS
HRS	7494		TECH:					HRS
AFL	5466		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
320116	SERVICE NOSE GEAR ASSEMBLY SHOCK STRUT							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
320106	LUBRICATE NOSE GEAR ASSEMBLY NOSE GEAR/DOORS							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
320106	LUBRICATE NOSE GEAR ASSEMBLY NOSE GEAR/DOORS							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001		REASON: --					MOS
HRS	7494		TECH:					HRS
AFL	5466		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
300170	OPERATIONAL TEST P2T2 SENSOR HEATER							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
530205	INSPECT FORWARD TO AFT MAIN FRAME							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
530200	INSPECT FORWARD TO AFT PRESSURE BULKHEAD-FUSELAGE						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
530176	INSPECT AUXILIARY FUEL TANK STRUCTURE.						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
530156	INSPECT CABIN (C)						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
530141	INSPECT COCKPIT (C)						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
520151	INSPECT/LUBRICATE RIGHT EMERGENCY EXIT HATCH SEAL						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
520141	INSPECT/LUBRICATE LEFT EMERGENCY EXIT HATCH SEAL						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
350243	TEST PASSENGER OXYGEN SUPPLY SYSTEM						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
350106	HYDROSTATIC TEST OXYGEN CYLINDER						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
322211	FUNCTIONAL TEST EMERGENCY GEAR EXTENSION						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR	
322136	BLEED BRAKE SYSTEM						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS 17-JAN-2001		REASON: --				MOS	
MSC		TECH:				MSC	
AFL 5466		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
320180	LUBRICATE NOSE GEAR ASSEMBLY NOSE STEERING CONTROL CABLES						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS 26-JUL-2000		REASON: --				MOS	
HRS 7325		TECH:				HRS	
AFL 5360		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
320179	INSPECT NOSE GEAR ASSEMBLY NOSE STEERING CABLES						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS 26-JUL-2000		REASON: --				MOS	
HRS 7325		TECH:				HRS	
AFL 5360		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
320172	TEST NOSE GEAR ASSEMBLY DRAG BRACE DOWNLOCK TENSION						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS 26-JUL-2000		REASON: --				MOS	
HRS 7325		TECH:				HRS	
AFL 5360		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
300133	FUNCTIONAL CHECK PNEUMATIC DE-ICER BOOTS.						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS 26-JUL-2000		REASON: --				MOS	
HRS 7325		TECH:				HRS	
AFL 5360		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
290206	REPLACE RESERVOIR AIR PRESSURE REGULATOR NO.2 ENGINE HIGH PRESSURE HYDRAULIC FILTER ELEMENT						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS 26-JUL-2000		REASON: --				MOS	
HRS 7325		TECH:				HRS	
AFL 5360		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
290171	REPLACE RESERVOIR AIR PRESSURE REGULATOR NO.1 ENGINE HIGH PRESSURE HYDRAULIC FILTER ELEMENT						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS 26-JUL-2000		REASON: --				MOS	
HRS 7325		TECH:				HRS	
AFL 5360		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
290131	INSPECT/REPLACE RESERVOIR AIR PRESSURE REGULATOR RESERVOIR AIR PRESSURE FILTER						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS 26-JUL-2000		REASON: --				MOS	
HRS 7325		TECH:				HRS	
AFL 5360		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
290116	INSPECT/REPLACE RESERVOIR AIR PRESSURE REGULATOR RESERVOIR AIR VENT FILTER						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS 26-JUL-2000		REASON: --				MOS	
HRS 7325		TECH:				HRS	
AFL 5360		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
290106	REPLACE HYDRAULIC RESERVOIR FILTER							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
281602	OPERATIONAL CHECK FUEL DUMP SYSTEM							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
280123	CHECK LEFT MAIN BOOST PUMP BRUSH WEAR							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	24-APR-2000		REASON: --					MOS
HRS	7233		TECH:					HRS
AFL	5301		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
270356	LUBRICATE GUST LOCK							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
270351	INSPECT/LUBRICATE PRESSURE SEALS							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
270346	LUBRICATE FLIGHT CONTROL FORWARD/AFT BELLCRANKS							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
270340	CHECK CABLE TENSION FLIGHT/PASSENGER COMPARTMENT							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
270271	ADJUST/TEST FLAP COMPARATOR							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
270245	INSPECT RIGHT FLAP/VANE RIGHT FLAP HINGE AND BEARING 800 HOURS							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
270244	INSPECT LEFT FLAP/VANE LEFT FLAP HINGE AND BEARING 800 HOURS							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
270179	LUBRICATE CONTROL COLUMNS							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
270176	LUBRICATE RUDDER PEDAL ARMS							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
270145	STATIC FRICTION TEST AILERON AND RUDDER							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
270140	CHECK AILERON CONTROL SYSTEM FREEPLAY							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
260146	RECORD DATE LEFT FIRE EXTINGUISHER STAMPED ON NEW CARTRIDGE (SERVICE LIFE)							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	17-JAN-2001	REASON: --						MOS
HRS		TECH:						HRS
AFL		INSP:		LABOR HRS: 0	COST: \$0.00			AFL
260131	WEIGHT CHECK RIGHT FIRE EXTINGUISHER							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	17-JAN-2001	REASON: --						MOS
HRS	7494	TECH:						HRS
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
260116	WEIGHT CHECK LEFT FIRE EXTINGUISHER							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	17-JAN-2001	REASON: --						MOS
MSC		TECH:						MSC
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
241657	INSPECT TEST PRIORITY BUS DIODES							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
241655	INSPECT DISTRIBUTION BUS CIRCUIT BREAKER							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
241653	CHECK CIRCUIT BREAKER RESISTANCE/INSPECT BUS							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
210280	CHECK BLEED AIR DUCT OVERPRESSURE SWITCH							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
210221	REPLACE LOWER ABSOLUTE AIR PRESSURE REGULATOR LOWER INLET AIR FILTER ELEMENT							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
210211	REPLACE GROUND BY-PASS VALVE UPPER INLET AIR FILTER ELEMENT							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
210178	CLEAN CABIN AIR PRESSURE CONTROLLER FILTER							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
990131	ACCOMPLISH AD89-12-08 AIRWORTHINESS DIRECTIVE							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: EFFECTIVE 07-10-89 - REF:550656								
950942	ACCOMPLISH SLWW-2494 REV 3 RMG BOLTS BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: RPT 300 HRS								
950941	ACCOMPLISH SLWW-2494 REV 3 LMG BOLTS BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: RPT 300 HRS								

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001	REASON: --						MOS
HRS	7494	TECH:						HRS
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
300170	OPERATIONAL TEST P2T2 SENSOR HEATER							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001	REASON: --						MOS
HRS	7494	TECH:						HRS
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
300163	INSPECT WINDSHIELD WIPER ASSEMBLY							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
300163	INSPECT WINDSHIELD WIPER ASSEMBLY							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001	REASON: --						MOS
HRS	7494	TECH:						HRS
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
300150	INSPECT COPILOT WINDSHIELD CYCLING CONTACTOR							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
300150	INSPECT COPILOT WINDSHIELD CYCLING CONTACTOR							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001	REASON: --						MOS
HRS	7494	TECH:						HRS
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
300156	CHANGE LEFT WINDSHIELD WIPER MOTOR							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Off: 5-823099-401	29626			Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: B - FAIL		On:				MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00		0	AFL

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
300147	INSPECT PILOT WINDSHIELD CYCLING CONTACTOR				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --				MOS	
HRS	7325	TECH:				HRS	
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3 - 7264-4654							
300147	INSPECT PILOT WINDSHIELD CYCLING CONTACTOR				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	17-JAN-2001	REASON: --				MOS	
HRS	7494	TECH:				HRS	
AFL	5466	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3 - 7264-4654							
281150	CHECK OPERATION OF FUEL BOOST PUMPS				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	17-JAN-2001	REASON: --				MOS	
HRS	7494	TECH:				HRS	
AFL	5466	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3							
280121	CHANGE LEFT MAIN BOOST PUMP				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00	Off: 2070C01T3	157			
MOS	24-APR-2000	REASON: B - FAIL	On:			MOS	
HRS	7233	TECH:				HRS	
AFL	5301	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
270341	CHECK CABLE TENSION AFT FUSELAGE				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --				MOS	
HRS	7325	TECH:				HRS	
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 2,3							
270335	OPERATIONAL CHECK SPEED BRAKES AND LIFT DUMPERS				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --				MOS	
HRS	7325	TECH:				HRS	
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3							
270335	OPERATIONAL CHECK SPEED BRAKES AND LIFT DUMPERS				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	17-JAN-2001	REASON: --				MOS	
HRS	7494	TECH:				HRS	
AFL	5466	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3							
270265	CLEAN/CHECK RIGHT AILERON RIGHT GUIDE ROLLERS				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --				MOS	
HRS	7325	TECH:				HRS	
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 2,3							

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
270264	CLEAN/CHECK LEFT AILERON LEFT GUIDE ROLLERS							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
270263	INSPECT RIGHT AILERON RIGHT EXTERNAL PUSH-PULL TUBE							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
270262	INSPECT LEFT AILERON LEFT EXTERNAL PUSH-PULL TUBE							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
270248	FUNCTIONAL CHECK FLAP TIME EXCEED RELAY							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
270247	INSPECT RIGHT FLAP/VANE							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
270247	INSPECT RIGHT FLAP/VANE							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001		REASON: --					MOS
HRS	7494		TECH:					HRS
AFL	5466		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
270243	TAP TEST RIGHT FLAP/VANE							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
270242	INSPECT RIGHT FLAP/VANE RIGHT FLAP HINGE AND BEARING 200 HOURS							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR	
270242	INSPECT RIGHT FLAP/VANE RIGHT FLAP HINGE AND BEARING 200 HOURS						
C/W	WARR						
MOS	17-JAN-2001	TRANSACTION DATE: 23-MAY-2001 12:00:00				Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
HRS	7494	REASON: --				MOS	
AFL	5466	TECH:				HRS	
		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3							
270240	INSPECT LEFT FLAP/VANE LEFT FLAP HINGE AND BEARING 200 HOURS						
C/W	WARR						
MOS	26-JUL-2000	TRANSACTION DATE: 23-MAY-2001 12:00:00				Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
HRS	7325	REASON: --				MOS	
AFL	5360	TECH:				HRS	
		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3							
270213	LUBRICATE ELEVATOR ATTACH POINTS						
C/W	WARR						
MOS	26-JUL-2000	TRANSACTION DATE: 23-MAY-2001 12:00:00				Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
HRS	7325	REASON: --				MOS	
AFL	5360	TECH:				HRS	
		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3							
270213	LUBRICATE ELEVATOR ATTACH POINTS						
C/W	WARR						
MOS	17-JAN-2001	TRANSACTION DATE: 23-MAY-2001 12:00:00				Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
HRS	7494	REASON: --				MOS	
AFL	5466	TECH:				HRS	
		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3							
270211	INSPECT SCISSORS ASSEMBLY						
C/W	WARR						
MOS	26-JUL-2000	TRANSACTION DATE: 23-MAY-2001 12:00:00				Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
HRS	7325	REASON: --				MOS	
AFL	5360	TECH:				HRS	
		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 2,3							
270203	INSPECT RIGHT ELEVATOR SKIN SEPARATION						
C/W	WARR						
MOS	26-JUL-2000	TRANSACTION DATE: 23-MAY-2001 12:00:00				Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
HRS	7325	REASON: --				MOS	
AFL	5360	TECH:				HRS	
		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3							
270203	INSPECT RIGHT ELEVATOR SKIN SEPARATION						
C/W	WARR						
MOS	17-JAN-2001	TRANSACTION DATE: 23-MAY-2001 12:00:00				Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
HRS	7494	REASON: --				MOS	
AFL	5466	TECH:				HRS	
		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3							
270193	INSPECT LEFT ELEVATOR SKIN SEPARATION						
C/W	WARR						
MOS	26-JUL-2000	TRANSACTION DATE: 23-MAY-2001 12:00:00				Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
HRS	7325	REASON: --				MOS	
AFL	5360	TECH:				HRS	
		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3							



AIRCRAFT Updates Report

Serial #: 368 Reg. #: N368MD
 Model: 1124A WESTWIND

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
270193	INSPECT LEFT ELEVATOR SKIN SEPARATION							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001		REASON: --					MOS
HRS	7494		TECH:					HRS
AFL	5466		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
240133	INSPECT NO. 2 STARTER GENERATOR SPLINE							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 5,7								
210622	INSPECT 35 DEGREE TEMPERATURE SENSOR 35 DEGREE DUCT SENSOR							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001		REASON: --					MOS
HRS	7494		TECH:					HRS
AFL	5466		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
210276	OPERATIONAL CHECK PRESSURIZATION SWITCHES AND VALVES							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
210112	VISUALLY INSPECT RIGHT BLEED AIR SWITCHING VALVE							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
210102	VISUALLY INSPECT LEFT BLEED AIR SWITCHING VALVE							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
120150	CHECK PRE-FLIGHT							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
120150	CHECK PRE-FLIGHT							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001		REASON: --					MOS
HRS	7494		TECH:					HRS
AFL	5466		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model : 1124A WESTWIND

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
100330	CHECK SERVICE LETTERS					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	17-JAN-2001	REASON: --				MOS		
HRS	7494	TECH:				HRS		
AFL	5466	INSP:		LABOR HRS: 0		COST: \$0.00		AFL
Note: OP 1,2,3								
100320	CHECK SERVICE BULLETINS					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --				MOS		
HRS	7325	TECH:				HRS		
AFL	5360	INSP:		LABOR HRS: 0		COST: \$0.00		AFL
Note: OP 1,2,3								
240126	CHANGE NO. 2 STARTER GENERATOR					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Off. 23065-018-1	2562			
MOS	26-JUL-2000	REASON: A - TIME		On:		MOS	0	
HRS	7325	TECH:				HRS	0	
AFL	5360	INSP:				AFL	0	
LABOR HRS: 0 COST: \$0.00								
100320	CHECK SERVICE BULLETINS					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	17-JAN-2001	REASON: --				MOS		
HRS	7494	TECH:				HRS		
AFL	5466	INSP:		LABOR HRS: 0		COST: \$0.00		AFL
Note: OP 1,2,3								
100310	CHECK AIRWORTHY DIRECTIVES					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --				MOS		
HRS	7325	TECH:				HRS		
AFL	5360	INSP:		LABOR HRS: 0		COST: \$0.00		AFL
Note: OP 1,2,3								
100310	CHECK AIRWORTHY DIRECTIVES					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	17-JAN-2001	REASON: --				MOS		
HRS	7494	TECH:				HRS		
AFL	5466	INSP:		LABOR HRS: 0		COST: \$0.00		AFL
Note: OP 1,2,3								
050300U	400/200 HOUR INSPECTION					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --				MOS		
HRS	7325	TECH:				HRS		
AFL	5360	INSP:		LABOR HRS: 0		COST: \$0.00		AFL
Note: OP 3								
050150U	200 HOUR INSPECTION					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --				MOS		
HRS	7325	TECH:				HRS		
AFL	5360	INSP:		LABOR HRS: 0		COST: \$0.00		AFL
Note: OP 2,3								

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
120160	CHECK NO.1 ENGINE PREFLIGHT COMPLETE						
	C/W	WARR					
	16-FEB-2001						
MOS							MOS
HRS	7551						HRS
AFL	5515						AFL
Note: OP 4,6							
240121	CHECK NO. 1 STARTER GENERATOR BRUSH WEAR/TENSION						
	C/W	WARR					
	16-FEB-2001						
MOS							MOS
HRS	7551						HRS
AFL	5515						AFL
Note: OP 4,6							
346126	TEST NO.2 ATC TRANSPONDER FAR 91.413						
	C/W	WARR					
	18-JAN-2001						
MOS							MOS
HRS	7494						HRS
AFL	5466						AFL
346111	TEST NO.1 ATC TRANSPONDER FAR 91.413						
	C/W	WARR					
	18-JAN-2001						
MOS							MOS
HRS	7494						HRS
AFL	5466						AFL
343672	CALIBRATE NO.1 AIR DATA COMPUTER FAR 91.411						
	C/W	WARR					
	18-JAN-2001						
MOS							MOS
HRS	7494						HRS
AFL	5466						AFL
341116	TEST COPILOT ALTIMETER FAR 91.411						
	C/W	WARR					
	18-JAN-2001						
MOS							MOS
HRS	7494						HRS
AFL	5466						AFL
341106	TEST PILOT ALTIMETER FAR 91.411						
	C/W	WARR					
	18-JAN-2001						
MOS							MOS
HRS	7494						HRS
AFL	5466						AFL
340151	LEAK CHECK RIGHT STATIC SYSTEM						
	C/W	WARR					
	18-JAN-2001						
MOS							MOS
HRS	7494						HRS
AFL	5466						AFL
340146	LEAK CHECK LEFT STATIC SYSTEM						
	C/W	WARR					
	18-JAN-2001						
MOS							MOS
HRS	7494						HRS
AFL	5466						AFL

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR	
270285	CLEAN/INSPECT/LUBRICATE RIGHT INBOARD/OUTBOARD FLEXIBLE SHAFT						
CW	WARR	TRANSACTION DATE: 29-MAY-2001 12:00:00					
MOS	16-FEB-2001	REASON: --				MOS	
HRS	7551	TECH:				HRS	
AFL	5515	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00				
270280	CLEAN/INSPECT/LUBRICATE LEFT INBOARD/OUTBOARD FLEXIBLE SHAFT						
CW	WARR	TRANSACTION DATE: 29-MAY-2001 12:00:00					
MOS	16-FEB-2001	REASON: --				MOS	
HRS	7551	TECH:				HRS	
AFL	5515	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00				
240133	INSPECT NO. 2 STARTER GENERATOR SPLINE					Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
CW	WARR	TRANSACTION DATE: 29-MAY-2001 12:00:00					
MOS	16-FEB-2001	REASON: --				MOS	
HRS	7551	TECH:				HRS	
AFL	5515	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00				
Note: OP 5,7							
240131	CHECK NO. 2 STARTER GENERATOR BRUSH WEAR/TENSION					Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
CW	WARR	TRANSACTION DATE: 29-MAY-2001 12:00:00					
MOS	16-FEB-2001	REASON: --				MOS	
HRS	7551	TECH:				HRS	
AFL	5515	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00				
Note: OP 5,7							
240128	INSPECT NO. 2 STARTER GENERATOR					Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
CW	WARR	TRANSACTION DATE: 29-MAY-2001 12:00:00					
MOS	17-JAN-2001	REASON: --				MOS	
HRS	7494	TECH:				HRS	
AFL	5466	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00				
Note: OP 5,7							
240128	INSPECT NO. 2 STARTER GENERATOR					Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
CW	WARR	TRANSACTION DATE: 29-MAY-2001 12:00:00					
MOS	16-FEB-2001	REASON: --				MOS	
HRS	7551	TECH:				HRS	
AFL	5515	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00				
Note: OP 5,7							
240123	INSPECT NO. 1 STARTER GENERATOR SPLINE					Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
CW	WARR	TRANSACTION DATE: 29-MAY-2001 12:00:00					
MOS	16-FEB-2001	REASON: --				MOS	
HRS	7551	TECH:				HRS	
AFL	5515	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00				
Note: OP 4,6							
120161	CHECK NO.2 ENGINE PREFLIGHT COMPLETE					Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
CW	WARR	TRANSACTION DATE: 29-MAY-2001 12:00:00					
MOS	16-FEB-2001	REASON: --				MOS	
HRS	7551	TECH:				HRS	
AFL	5515	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00				
Note: OP 5,7							

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
240118	INSPECT NO. 1 STARTER GENERATOR					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 29-MAY-2001 12:00:00						
MOS	16-FEB-2001	REASON: --				MOS		
HRS	7551	TECH:				HRS		
AFL	5515	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 4,6								
240118	INSPECT NO. 1 STARTER GENERATOR					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 29-MAY-2001 12:00:00						
MOS	17-JAN-2001	REASON: --				MOS		
HRS	7494	TECH:				HRS		
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 4,6								
260161	RECORD DATE RIGHT FIRE EXTINGUISHER STAMPED ON NEW CARTRIDGE (SERVICE LIFE)							
C/W	WARR	TRANSACTION DATE: 29-MAY-2001 12:00:00						
MOS	17-JAN-2001	REASON: --				MOS		
HRS		TECH:				HRS		
AFL		INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
260156	RECORD DATE RIGHT FIRE EXTINGUISHER STAMPED ON NEW CARTRIDGE (SERVICE LIFE)							
C/W	WARR	TRANSACTION DATE: 29-MAY-2001 12:00:00						
MOS	17-JAN-2001	REASON: --				MOS		
HRS		TECH:				HRS		
AFL		INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
260153	REPLACE LEFT FIRE EXTINGUISHER NO.2 CARTRIDGE							
C/W	WARR	TRANSACTION DATE: 29-MAY-2001 12:00:00						
MOS	17-JAN-2001	REASON: --				MOS		
HRS		TECH:				HRS		
AFL		INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
240166	DEEP CYCLELEFT BATTERY					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --				MOS		
HRS	7687	TECH:				HRS		
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3								
260180	VISUAL INSPECTION CABIN PORTABLE EXTINGUISHER CABIN FIRE EXTINGUISHER					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --				MOS		
HRS	7687	TECH:				HRS		
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
330228	CHARGE EMERGENCY LIGHT BATTERY					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --				MOS		
HRS	7687	TECH:				HRS		
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
100310	CHECK AIRWORTHY DIRECTIVES							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --				MOS		
HRS	7687	TECH:				HRS		
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
100330	CHECK SERVICE LETTERS							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:						AFL
			LABOR HRS: 0		COST: \$0.00			
210102	VISUALLY INSPECT LEFT BLEED AIR SWITCHING VALVE							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:						AFL
			LABOR HRS: 0		COST: \$0.00			
210276	OPERATIONAL CHECK PRESSURIZATION SWITCHES AND VALVES							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:						AFL
			LABOR HRS: 0		COST: \$0.00			
210671	CLEAN/REPLACE WATER SEPARATOR CONDENSER/FILTER							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:						AFL
			LABOR HRS: 1		COST: \$0.00			
270215	LUBRICATE FORWARD SCISSOR ASSEMBLY							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:						AFL
			LABOR HRS: 0		COST: \$0.00			
270214	LUBRICATE AFT HINGE FITTING BEARINGS							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:						AFL
			LABOR HRS: 0		COST: \$0.00			
270213	LUBRICATE ELEVATOR ATTACH POINTS							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:						AFL
			LABOR HRS: 0		COST: \$0.00			
270211	INSPECT SCISSORS ASSEMBLY							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:						AFL
			LABOR HRS: 0		COST: \$0.00			
270203	INSPECT RIGHT ELEVATOR SKIN SEPARATION							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:						AFL
			LABOR HRS: 0		COST: \$0.00			

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
270193	INSPECT LEFT ELEVATOR SKIN SEPARATION							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
270158	INSPECT RUDDER TRIM TAB FREEPLAY							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
260186	OPERATIONAL CHECK FIRE PROTECTION SYSTEM							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
260184	INSPECT CABIN PORTABLE EXTINGUISHER CABIN FIRE EXTINGUISHER							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
260181	WEIGHT CHECK CABIN PORTABLE EXTINGUISHER CABIN FIRE EXTINGUISHER							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
260174	INSPECT COCKPIT PORTABLE EXTINGUISHER COCKPIT FIRE EXTINGUISHER							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
260171	WEIGHT CHECK COCKPIT PORTABLE EXTINGUISHER COCKPIT FIRE EXTINGUISHER							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
240203	FUNCTIONALLY CHECK EXTERNAL POWER RECEPTACLE BATTERY TEMPERATURE AND WARNING SYSTEM							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
240176	CHECK RIGHT BATTERY ELECTROLYTE LEVEL							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 1	COST: \$0.00			AFL

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
240161	CHECK LEFT BATTERY ELECTROLYTE LEVEL						
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001	REASON: --					MOS
HRS	7687	TECH:					HRS
AFL	5594	INSP:	LABOR HRS: 1	COST: \$0.00			AFL
230218	INSPECT/CHECK STATIC DISCHARGE WICK RESISTANCE						
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001	REASON: --					MOS
HRS	7687	TECH:					HRS
AFL	5594	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
210681	CHANGE COOLING TURBINE OIL						
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001	REASON: --					MOS
HRS	7687	TECH:					HRS
AFL	5594	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
270262	INSPECT LEFT AILERON LEFT EXTERNAL PUSH-PULL TUBE						
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001	REASON: --					MOS
HRS	7687	TECH:					HRS
AFL	5594	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
270248	FUNCTIONAL CHECK FLAP TIME EXCEED RELAY						
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001	REASON: --					MOS
HRS	7687	TECH:					HRS
AFL	5594	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
270247	INSPECT RIGHT FLAP/VANE						
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001	REASON: --					MOS
HRS	7687	TECH:					HRS
AFL	5594	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
270243	TAP TEST RIGHT FLAP/VANE						
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001	REASON: --					MOS
HRS	7687	TECH:					HRS
AFL	5594	INSP:	LABOR HRS: .5	COST: \$0.00			AFL
270242	INSPECT RIGHT FLAP/VANE RIGHT FLAP HINGE AND BEARING 200 HOURS						
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001	REASON: --					MOS
HRS	7687	TECH:					HRS
AFL	5594	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
270240	INSPECT LEFT FLAP/VANE LEFT FLAP HINGE AND BEARING 200 HOURS						
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001	REASON: --					MOS
HRS	7687	TECH:					HRS
AFL	5594	INSP:	LABOR HRS: 0	COST: \$0.00			AFL

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
270238	TAP TEST LEFT FLAP/VANE LEFT FLAP							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: .5	COST: \$0.00			AFL
270237	INSPECT LEFT FLAP/VANE LEFT FLAP VANE							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
270217	INSPECT HORIZONTAL STABILIZER TRIM ACTUATOR							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
320116	SERVICE NOSE GEAR ASSEMBLY SHOCK STRUT							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 2.5	COST: \$0.00			AFL
320106	LUBRICATE NOSE GEAR ASSEMBLY NOSE GEAR/DOORS							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: .5	COST: \$0.00			AFL
300170	OPERATIONAL TEST P2T2 SENSOR HEATER							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
300163	INSPECT WINDSHIELD WIPER ASSEMBLY							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
300150	INSPECT COPILOT WINDSHIELD CYCLING CONTACTOR							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
300147	INSPECT PILOT WINDSHIELD CYCLING CONTACTOR							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
300104	INSPECT RIGHT DE-ICER CHECK VALVE							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
300102	INSPECT LEFT DE-ICER CHECK VALVE							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
290178	INSPECT/LUBRICATE NO. 2 HYDRAULIC PUMP NO.2 ENGINE HYDRAULIC PUMP SPLINES							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 1	COST: \$0.00			AFL
321180	INSPECT/LUBRICATE RIGHT MAIN GEAR OUTBOARD WHEEL HALF RIGHT MAIN GEAR OUTBOARD WHEEL BEARINGS							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 1	COST: \$0.00			AFL
321178	DYE PENETRANT CHECK RIGHT WHEEL AXLE							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
321176	INSPECT/LUBRICATE RIGHT MAIN GEAR INBOARD WHEEL HALF RIGHT MAIN GEAR INBOARD WHEEL BEARINGS							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 1	COST: \$0.00			AFL
321136	SERVICE RIGHT MAIN GEAR ASSEMBLY RIGHT MAIN GEAR SHOCK STRUT							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 2	COST: \$0.00			AFL
321107	LUBRICATE RIGHT ACTUATOR BOLTS							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
321106	LUBRICATE RIGHT MAIN GEAR ASSEMBLY RIGHT MAIN GEAR							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: .5	COST: \$0.00			AFL

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
320691	INSPECT LEFT MAIN GEAR/WELL (A)							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 1.5	COST: \$0.00			AFL
320680	INSPECT/LUBRICATE LEFT MAIN GEAR OUTBOARD WHEEL HALF LEFT MAIN GEAR OUTBOARD WHEEL BEARINGS							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
320678	DYE PENETRANT CHECK LEFT WHEEL AXLE							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
713650U	-- INSP #2 ENG INLET NACELLE							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
710650U	-- INSP #1 ENG INLET NACELLE							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
050300U	400/200 HOUR INSPECTION							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 45.5	COST: \$0.00			AFL
050150U	200 HOUR INSPECTION							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 31	COST: \$0.00			AFL
950942	SLWW-2494 REV 3 RMG BOLTS SERVICE BULLETIN							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
950941	SLWW-2494 REV 3 LMG BOLTS SERVICE BULLETIN							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
950920	SL WW-2492 HYD HOSE INSP SERVICE BULLETIN							
	CW	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
1124-30-036 PART II	ICE AND RAIN PROTECTION SERVICE BULLETIN							
	CW	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
1124-55-020 R2	STABILIZERS SERVICE BULLETIN							
	CW	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
570120	INSPECT RIGHT AILERON BELLCRANK							
	CW	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
570119	INSPECT RIGHT WING (B)							
	CW	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
570116	INSPECT RIGHT WING (A)							
	CW	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 1.5	COST: \$0.00			AFL
570106	INSPECT LEFT AILERON BELLCRANK							
	CW	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
570104	INSPECT LEFT WING (B)							
	CW	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
570101	INSPECT LEFT WING (A)							
	CW	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 1.5	COST: \$0.00			AFL

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR	
550656	CHECK HORIZONTAL STABILIZER AFT SPAR SPLICE-HINGE FITTING OUTBOARD LUGS FOR CRACKS						
	C/W WARR						
	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --				MOS	
HRS	7687	TECH:				HRS	
AFL	5594	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
550106	INSPECT EMPENNAGE (B)						
	C/W WARR						
	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --				MOS	
HRS	7687	TECH:				HRS	
AFL	5594	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
550101	INSPECT EMPENNAGE (A)						
	C/W WARR						
	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --				MOS	
HRS	7687	TECH:				HRS	
AFL	5594	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
540126U	INSPECT NO. 2 ENGINE NACELLE/PYLON (B)						
	C/W WARR						
	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --				MOS	
HRS	7687	TECH:				HRS	
AFL	5594	INSP:	LABOR HRS: 3	COST: \$0.00		AFL	
540121U	INSPECT NO. 2 ENGINE NACELLE/PYLON (A)						
	C/W WARR						
	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --				MOS	
HRS	7687	TECH:				HRS	
AFL	5594	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
540106U	INSPECT NO. 1 ENGINE NACELLE/PYLON (B)						
	C/W WARR						
	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --				MOS	
HRS	7687	TECH:				HRS	
AFL	5594	INSP:	LABOR HRS: 3	COST: \$0.00		AFL	
540101U	INSPECT NO. 1 ENGINE NACELLE/PYLON (A)						
	C/W WARR						
	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --				MOS	
HRS	7687	TECH:				HRS	
AFL	5594	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
530166	INSPECT REAR COMPARTMENT (B)						
	C/W WARR						
	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --				MOS	
HRS	7687	TECH:				HRS	
AFL	5594	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
530161	INSPECT REAR COMPARTMENT (A)						
	C/W WARR						
	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --				MOS	
HRS	7687	TECH:				HRS	
AFL	5594	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model : 1124A WESTWIND

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
530146	INSPECT CABIN (A)							
CW	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
530136	INSPECT COCKPIT (B)							
CW	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
530131	INSPECT COCKPIT (A)							
CW	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
530121	INSPECT NOSE COMPARTMENT (B)							
CW	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
530116	INSPECT NOSE COMPARTMENT (A)							
CW	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
530101	INSPECT FUSELAGE (A)							
CW	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
520116	OPERATIONAL CHECK CABIN ENTRANCE DOOR							
CW	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
520106	INSPECT/LUBRICATE CABIN ENTRANCE DOOR							
CW	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
350169U	CHECK COPILOT OXYGEN MASK							
CW	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00			AFL

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
350166U	CHECK PILOT OXYGEN MASK							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
340121	DRAIN PITOT/STATIC SYSTEM							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 1.5	COST: \$0.00			AFL
322206	FUNCTIONAL TEST EMERGENCY GEAR EXTENSION CONTROL CABLE							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 1	COST: \$0.00			AFL
322201	FUNCTIONAL TEST LANDING GEAR FREE FALL							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
322191	FUNCTIONAL TEST LANDING GEAR (NORMAL)							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
322176	FUNCTIONAL CHECK ANTI-SKID DETECTOR SYSTEM							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 1	COST: \$0.00			AFL
322174	OPERATIONAL CHECK ANTI-SKID LIGHTS							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: .5	COST: \$0.00			AFL
322171	INSPECT/CLEAN RIGHT ANTI-SKID DETECTOR							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 1	COST: \$0.00			AFL
322156	INSPECT/CLEAN LEFT ANTI-SKID DETECTOR							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 1	COST: \$0.00			AFL

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR	
322131	INSPECT/CHECK RIGHT MAIN GEAR BRAKE RIGHT BRAKE LININGS						
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001	REASON: --				MOS	
HRS	7687	TECH:				HRS	
AFL	5594	INSP:				AFL	
		LABOR HRS: 1	COST: \$0.00				
322116	INSPECT/CHECK LEFT MAIN GEAR BRAKE LEFT BRAKE LININGS						
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001	REASON: --				MOS	
HRS	7687	TECH:				HRS	
AFL	5594	INSP:				AFL	
		LABOR HRS: 1	COST: \$0.00				
321616	CHECK EMERGENCY STORAGE BOTTLE LANDING GEAR EMERGENCY SYSTEM PRESSURE						
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001	REASON: --				MOS	
HRS	7687	TECH:				HRS	
AFL	5594	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00				
321191	INSPECT RIGHT MAIN GEAR OUTBOARD WHEEL HALF RIGHT MAIN GEAR/WELL (A)						
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001	REASON: --				MOS	
HRS	7687	TECH:				HRS	
AFL	5594	INSP:				AFL	
		LABOR HRS: 1.5	COST: \$0.00				
320676	INSPECT/LUBRICATE LEFT MAIN GEAR INBOARD WHEEL HALF LEFT MAIN GEAR INBOARD WHEEL BEARINGS						
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001	REASON: --				MOS	
HRS	7687	TECH:				HRS	
AFL	5594	INSP:				AFL	
		LABOR HRS: 1	COST: \$0.00				
320636	SERVICE LEFT MAIN GEAR ASSEMBLY LEFT MAIN GEAR SHOCK STRUT						
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001	REASON: --				MOS	
HRS	7687	TECH:				HRS	
AFL	5594	INSP:				AFL	
		LABOR HRS: 2	COST: \$0.00				
320607	LUBRICATE LEFT ACTUATOR BOLTS						
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001	REASON: --				MOS	
HRS	7687	TECH:				HRS	
AFL	5594	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00				
320606	LUBRICATE LEFT MAIN GEAR ASSEMBLY LEFT MAIN GEAR						
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001	REASON: --				MOS	
HRS	7687	TECH:				HRS	
AFL	5594	INSP:				AFL	
		LABOR HRS: .5	COST: \$0.00				
320206	INSPECT NOSE GEAR (B)						
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001	REASON: --				MOS	
HRS	7687	TECH:				HRS	
AFL	5594	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00				

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002** From Date : To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
320201	INSPECT NOSE GEAR (A)							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --				MOS	
HRS	7687		TECH:				HRS	
AFL	5594		INSP:	LABOR HRS: 1.5	COST: \$0.00		AFL	
320158	INSPECT/CLEAN/LUBRICATE NOSE GEAR RIGHT WHEEL BEARINGS							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --				MOS	
HRS	7687		TECH:				HRS	
AFL	5594		INSP:	LABOR HRS: 1.5	COST: \$0.00		AFL	
320156	INSPECT/CLEAN/LUBRICATE NOSE GEAR LEFT WHEEL BEARINGS							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --				MOS	
HRS	7687		TECH:				HRS	
AFL	5594		INSP:	LABOR HRS: 1.5	COST: \$0.00		AFL	
290143	INSPECT/LUBRICATE NO. 1 HYDRAULIC PUMP NO.1 ENGINE HYDRAULIC PUMP SPLINES							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --				MOS	
HRS	7687		TECH:				HRS	
AFL	5594		INSP:	LABOR HRS: 1	COST: \$0.00		AFL	
290118	CLEAN/CHECK RESERVOIR AIR PRESSURE REGULATOR HYDRAULIC RESERVOIR AIR PRESSURE CHECK VALVE							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --				MOS	
HRS	7687		TECH:				HRS	
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
281150	CHECK OPERATION OF FUEL BOOST PUMPS							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --				MOS	
HRS	7687		TECH:				HRS	
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
270341	CHECK CABLE TENSION AFT FUSELAGE							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --				MOS	
HRS	7687		TECH:				HRS	
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
270335	OPERATIONAL CHECK SPEED BRAKES AND LIFT DUMPERS							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --				MOS	
HRS	7687		TECH:				HRS	
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
270265	CLEAN/CHECK RIGHT AILERON RIGHT GUIDE ROLLERS							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --				MOS	
HRS	7687		TECH:				HRS	
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
270264	CLEAN/CHECK LEFT AILERON LEFT GUIDE ROLLERS							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
270263	INSPECT RIGHT AILERON RIGHT EXTERNAL PUSH-PULL TUBE							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
210622	INSPECT 35 DEGREE TEMPERATURE SENSOR 35 DEGREE DUCT SENSOR							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
210112	VISUALLY INSPECT RIGHT BLEED AIR SWITCHING VALVE							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
120150	CHECK PRE-FLIGHT							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
100320	CHECK SERVICE BULLETINS							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
344616	INSPECT EMERGENCY GYRO POWER SUPPLY BATTERY EMERGENCY POWER SUPPLY							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: PS 823 ONLY								
240181	DEEP CYCLE RIGHT BATTERY							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
260169	VISUAL INSPECTION COCKPIT PORTABLE EXTINGUISHER COCKPIT FIRE EXTINGUISHER							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL



AIRCRAFT Updates Report

Serial #: 368 Reg. #: N368MD
 Model: 1124A WESTWIND

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
240116	CHANGE NO. 1 STARTER GENERATOR					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00		Off. 23065-018-1	3684			
MOS	06-NOV-2001	REASON: C - WORN		On:		MOS	0	
HRS	7774	TECH:				HRS	0	
AFL	5641	INSP:		LABOR HRS: 0	COST: \$0.00	AFL	0	
344616	INSPECT EMERGENCY GYRO POWER SUPPLY BATTERY BATTERY/STAND-BY ATTITUDE GYRO			EMERGENCY POWER SUPPLY				
C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00						
MOS	06-NOV-2001	REASON: - -				MOS		
HRS	7774	TECH:				HRS		
AFL	5641	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
330228	CHARGE EMERGENCY LIGHT BATTERY							
C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00						
MOS	06-NOV-2001	REASON: - -				MOS		
HRS	7774	TECH:				HRS		
AFL	5641	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
240133	INSPECT NO. 2 STARTER GENERATOR SPLINE							
C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00						
MOS	06-NOV-2001	REASON: - -				MOS		
HRS	7774	TECH:				HRS		
AFL	5641	INSP:		LABOR HRS: 1	COST: \$0.00	AFL		
240131	CHECK NO. 2 STARTER GENERATOR BRUSH WEAR/TENSION							
C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00						
MOS	06-NOV-2001	REASON: - -				MOS		
HRS	7774	TECH:				HRS		
AFL	5641	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
240128	INSPECT NO. 2 STARTER GENERATOR							
C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00						
MOS	06-NOV-2001	REASON: - -				MOS		
HRS	7774	TECH:				HRS		
AFL	5641	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
240123	INSPECT NO. 1 STARTER GENERATOR SPLINE							
C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00						
MOS	06-NOV-2001	REASON: - -				MOS		
HRS	7774	TECH:				HRS		
AFL	5641	INSP:		LABOR HRS: 1	COST: \$0.00	AFL		
240121	CHECK NO. 1 STARTER GENERATOR BRUSH WEAR/TENSION							
C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00						
MOS	06-NOV-2001	REASON: - -				MOS		
HRS	7774	TECH:				HRS		
AFL	5641	INSP:		LABOR HRS: .5	COST: \$0.00	AFL		
240118	INSPECT NO. 1 STARTER GENERATOR							
C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00						
MOS	06-NOV-2001	REASON: - -				MOS		
HRS	7774	TECH:				HRS		
AFL	5641	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
230400	CLEANTEST COCKPIT VOICE RECORDER BEACON						
	C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00				
MOS	06-NOV-2001		REASON: --				MOS
HRS	7774		TECH:				HRS
AFL	5641		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
120161	CHECK NO.2 ENGINE PREFLIGHT COMPLETE						
	C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00				
MOS	26-JUN-2001		REASON: --				MOS
HRS	7687		TECH:				HRS
AFL	5594		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
120160	CHECK NO.1 ENGINE PREFLIGHT COMPLETE						
	C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00				
MOS	26-JUN-2001		REASON: --				MOS
HRS	7687		TECH:				HRS
AFL	5594		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
991855U	AIRWORTHINESS DIRECTIVE AD2001-15-17						
	C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00				
MOS	06-NOV-2001		REASON: --				MOS
HRS	7774		TECH:				HRS
AFL	5641		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
2001-03-01	TO PREVENT THE MAIN ENTRY DOOR FROM JAMMING, WHICH COULD IMPEDE THE SAFE EVACUATION OF PASSENGERS AND CREW DURING AN EMERGENCY AIRWORTHINESS DIRECTIVE						
	C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00				
MOS			REASON: --				MOS
MSC			TECH:				MSC
AFL			INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
1998-06-10	TO PREVENT FAILURE OF THE HYDRAULIC FUSE TO OPERATE PROPERLY IN THE EVENT OF AN EXTERNAL LEAK DOWNSTREAM OF THE FUSE, WHICH COULD RESULT IN LOSS OF HYDRAULIC SYSTEMS AIRWORTHINESS DIRECTIVE						
	C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00				
MOS	06-NOV-2001		REASON: --				MOS
HRS	7774		TECH:				HRS
AFL	5641		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
911380	ASB1124-54A-138 SERVICE BULLETIN						
	C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00				
MOS			REASON: --				MOS
MSC			TECH:				MSC
AFL	0		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
780636	CLEAN/LUBRICATE NO. 2 THROTTLE RETARDER FEEDBACK CONTROL ASSEMBLY NO.2 THROTTLE RETARDER CABLE AND CASING						
	C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00				
MOS	06-NOV-2001		REASON: --				MOS
HRS	7774		TECH:				HRS
AFL	5641		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR	
780136	CLEAN/LUBRICATE NO. 1 THROTTLE RETARDER FEEDBACK CONTROL ASSEMBLY NO.1 THROTTLE RETARDER CABLE AND CASING						
	C/W WARR						
	TRANSACTION DATE: 15-NOV-2001 12:00:00						
MOS	06-NOV-2001	REASON: --				MOS	
HRS	7774	TECH:				HRS	
AFL	5641	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
300165	REPLACE WIPER BLADE ELEMENT NOTE: IT IS RECOMMENDED TO REPLACE WIPER BLADE ELEMENT EVERY 6 MONTHS OR 250 HOURS.						
	C/W WARR						
	TRANSACTION DATE: 15-NOV-2001 12:00:00						
MOS	06-NOV-2001	REASON: --				MOS	
HRS	7774	TECH:				HRS	
AFL	5641	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
260182	DISCHARGE CABIN PORTABLE EXTINGUISHER /VALVE OVERHAUL AND REFILL CABIN FIRE EXTINGUISHER						
	C/W WARR						
	TRANSACTION DATE: 15-NOV-2001 12:00:00						
MOS	06-NOV-2001	REASON: --				MOS	
HRS	7774	TECH:				HRS	
AFL	5641	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
260180	VISUAL INSPECTION CABIN PORTABLE EXTINGUISHER CABIN FIRE EXTINGUISHER						
	C/W WARR						
	TRANSACTION DATE: 15-NOV-2001 12:00:00						
DAYS	06-NOV-2001	REASON: --				DAYS	
HRS	7774	TECH:				HRS	
AFL	5641	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
260172	DISCHARGE COCKPIT PORTABLE EXTINGUISHER /VALVE OVERHAUL AND REFILL COCKPIT FIRE EXTINGUISHER						
	C/W WARR						
	TRANSACTION DATE: 15-NOV-2001 12:00:00						
MOS	06-NOV-2001	REASON: --				MOS	
HRS	7774	TECH:				HRS	
AFL	5641	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
260169	VISUAL INSPECTION COCKPIT PORTABLE EXTINGUISHER COCKPIT FIRE EXTINGUISHER						
	C/W WARR						
	TRANSACTION DATE: 15-NOV-2001 12:00:00						
DAYS	06-NOV-2001	REASON: --				DAYS	
HRS	7774	TECH:				HRS	
AFL	5641	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
260121	HYDROSTATIC TEST LEFT FIRE EXTINGUISHER						
	C/W WARR						
	TRANSACTION DATE: 15-NOV-2001 12:00:00						
MOS	06-NOV-2001	REASON: --				MOS	
HRS	7774	TECH:				HRS	
AFL	5641	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
250162	INSPECT FIRST AID KIT						
	C/W WARR						
	TRANSACTION DATE: 15-NOV-2001 12:00:00						
MOS	06-NOV-2001	REASON: --				MOS	
HRS	7774	TECH:				HRS	
AFL	5641	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
250156	INSPECT LIFE PRESERVERS							
C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00						
MOS	06-NOV-2001	REASON: --						MOS
HRS	7774	TECH:						HRS
AFL	5641	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
240181	DEEP CYCLE RIGHT BATTERY							
C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00						
MOS	06-NOV-2001	REASON: --						MOS
HRS	7774	TECH:						HRS
AFL	5641	INSP:		LABOR HRS: 2	COST: \$0.00			AFL
240166	DEEP CYCLELEFT BATTERY							
C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00						
MOS	06-NOV-2001	REASON: --						MOS
HRS	7774	TECH:						HRS
AFL	5641	INSP:		LABOR HRS: 2	COST: \$0.00			AFL
240128	INSPECT NO. 2 STARTER GENERATOR							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 5,7								
240123	INSPECT NO. 1 STARTER GENERATOR SPLINE							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 4,6								
240118	INSPECT NO. 1 STARTER GENERATOR							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 4,6								
240133	INSPECT NO. 2 STARTER GENERATOR SPLINE							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 5,7								
240131	CHECK NO. 2 STARTER GENERATOR BRUSH WEAR/TENSION							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 5,7								



AIRCRAFT Updates Report

Serial #: 368 Reg. #: N368MD
 Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
240126	CHANGE NO. 2 STARTER GENERATOR				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00	Off: 23065-018-1	2562			
MOS	06-NOV-2001	REASON: C - WORN	On:		MOS	0	
HRS	7774	TECH:			HRS	0	
AFL	5641	INSP:	LABOR HRS: 0	COST: \$0.00	AFL	0	
240121	CHECK NO. 1 STARTER GENERATOR BRUSH WEAR/TENSION				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00					
MOS	26-JUN-2001	REASON: --			MOS		
HRS	7687	TECH:			HRS		
AFL	5594	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 4,6							