




CAMP SYSTEMS INTERNATIONAL, LLC
LONG ISLAND MAC ARTHUR AIRPORT
999 MARCONI AVE.
RONKONKOMA, NY 11779

POSTAL

R&S AIRCRAFT INVESTMENTS, LLC
ATTN: YANDELL ROGERS III
P.O. BOX 43
HOUSTON, TX 77001-0043

ModelName: 1124A WESTWIND 368
RegNo: N368MD

1124 WESTWIND



WORK COMPLIANCE FORMS

CAMP

Aviation from the ground up™

OWNER: R&S AIRCRAFT INVESTMENTS, LLC
ADDRESS: P.O. BOX 43 HOUSTON TX 77001-0043

OPERATOR: R&S AIRCRAFT INVESTMENTS, LLC
ADDRESS: P.O. BOX 43 HOUSTON TX 77001-0043

PHONE: 713-830-9584
FAX: 713-918-5925

PHONE: 713-830-9584
FAX: 713-918-5925

PROJECTED : 2 MOS. to 14-MAY-2002

AIRCRAFT

S/N: 368 **REG NO:** N368MD **MODEL:** 1124A WESTWIND **MANUFACTURER:** GULFSTREAM AEROSPACE CORPORATION

NOTE:
INSPECTION PROGRAM: 3
CERTIFICATE DATE: 11-FEB-1982

UOM	LAST ACTUAL	LAST ACTUAL DATE	PROJECTED
HRS	7806	28-FEB-2002	7895.2
AFL	5706	28-FEB-2002	5795

ENGINE NO. 1

S/N: P-77482 **PART NO:** 3072500-2 **MODEL:** TFE731-3 **MANUFACTURER:** HONEYWELL

INSTALLED DATE: 4/3/1989
A/C HRS: 4215
ENGINE HRS: 3972
ENGINE CYCLES: 2456

UOM	LAST ACTUAL	LAST ACTUAL DATE	PROJECTED
HRS	7806	28-FEB-2002	7895.2
ENC	0		0
(AFL)	5706	28-FEB-2002	5795

ENGINE NO. 2

S/N: P77488 **PART NO:** 3072500-2 **MODEL:** TFE731-3 **MANUFACTURER:** HONEYWELL

INSTALLED DATE: 5/31/1993
A/C HRS: 5278
ENGINE HRS: 5227
ENGINE CYCLES: 3867

UOM	LAST ACTUAL	LAST ACTUAL DATE	PROJECTED
HRS	7806	28-FEB-2002	7895.2
ENC	0		0
(AFL)	5706	28-FEB-2002	5795



Maintenance Due List/Time Remaining - AIRCRAFT(CALENDAR)

Aircraft Model - 1124A WESTWIND

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORK CARD WORK ORDER	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL TIME-----AT-----INSTALLATION COMPLIANCE				DISPOSITION NEXT DUE (ENH) AFH (xEXT)	TIME REMAINING OVD = Overdue	AREA PRICE LABOR
			TSN	TSO	TSR	WARR EXP			
AD 2000-15-09	NO. 1 ENGINE - HPC IMPELLER AIRWORTHINESS DIRECTIVE						10-OCT-2000	New Reqmt	
	REF:	DUE NEXT	MOS HRS/MSC ENC	4200					
AD 2000-15-09	NO. 2 ENGINE - HPC IMPELLER AIRWORTHINESS DIRECTIVE						10-OCT-2000	New Reqmt	
	REF:	DUE NEXT	MOS HRS/MSC ENC	4200					
260169 26.060	VISUAL INSPECTION COCKPIT PORTABLE EXTINGUISHER COCKPIT FIRE EXTINGUISHER		DAYS HRS/MSC AFL	30		06-NOV-2001 7774 5641	06-DEC-2001	OVD	F3
	REF: NO REF								
260180 26.060	VISUAL INSPECTION CABIN PORTABLE EXTINGUISHER CABIN FIRE EXTINGUISHER		DAYS HRS/MSC AFL	30		06-NOV-2001 7774 5641	06-DEC-2001	OVD	F3
	REF: NO REF								
330228 33.100	CHARGE EMERGENCY LIGHT BATTERY		MOS HRS/MSC AFL	3 200		06-NOV-2001 7774 5641	06-FEB-2002 7974	OVD 168	F4
	REF: AMM 12-10-06								
344616 34.370	INSPECT EMERGENCY GYRO POWER SUPPLY BATTERY EMERGENCY POWER SUPPLY BATTERY/STAND-BY ATTITUDE GYRO		MOS HRS/MSC AFL	3 200		06-NOV-2001 7774 5641	06-FEB-2002 7974	OVD 168	F5
	REF: AMM NO REF								
320118 32.540	INSPECT/LUBRICATE NOSE GEAR ASSEMBLY UPPER/LOWER STRUT BEARINGS BODY		MOS HRS/MSC AFL	24 1200		22-FEB-2000 7107 5232	22-FEB-2002 8307	OVD 501	L3
	REF: AMM 32-20-01								
230400 23.130	CLEAN/TEST COCKPIT VOICE RECORDER BEACON		MOS HRS/MSC AFL	6		06-NOV-2001 7774 5641	06-MAY-2002	1.57	T1
	REF: NO REF								

Total Labor Hours
Total Price :

R - Task was due on previous due lists
(xEXT) - Extension incorporated in the next due calculation

Aircraft Model - 1124A WESTWIND

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORK CARD WORK ORDER	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL TIME-----AT-----INSTALLATION COMPLIANCE				DISPOSITION NEXT DUE (ENH) AFH (xEXT)	TIME REMAINING OVD = Overdue	AREA PRICE LABOR
			TSN	TSO	TSR	WARR EXP			
AD 2002-01-26	TO PREVENT FAILURE OF ATTACHMENT BOLTS DUE TO FATIGUE, WHICH COULD RESULT IN SEPARATION OF THE ENGINE INLET COWL AND AFT NACELLE, AND CONSEQUENT DAMAGE TO THE HORIZONTAL OR VERTICAL STABILIZER AIRWORTHINESS DIRECTIVE						MANDATORY		
	REF:	MOS HRS/MSC AFL	DUE				50	New Reqmt	
AD 1989-12-08	TO DETECT CRACKS IN THE HINGE LUGS OF THE HORIZONTAL STABILIZER AFT SPAR SPLICE FITTING (HINGE ASSEMBLY) AIRWORTHINESS DIRECTIVE								
	REF: See Workcard	MOS HRS/MSC AFL	300			17-JAN-2001 7494 5466	7794	OVD	
SB 1124-30-036 PART II	ICE AND RAIN PROTECTION SERVICE BULLETIN								F3
	REF: See Workcard	MOS HRS/MSC AFL	150			26-JUN-2001 7687 5594	7837	31	
057110U	NO. 1 ENGINE - 150HR #1 ENGINE INSP								
	REF:	MOS HRS/MSC ENC (AFL)	150			26-JUN-2001 7687 5594	7837	31	1
057110U	NO. 2 ENGINE - 150HR #2 ENGINE INSP								
	REF:	MOS HRS/MSC ENC (AFL)	150			26-JUN-2001 7687 5594	7837	31	1
R 057120U	NO. 1 ENGINE - 300HR #1 ENGINE INSP								
	REF:	MOS HRS/MSC ENC (AFL)	300			16-FEB-2001 7551 5515	7851	45	1.5
R 057120U	NO. 2 ENGINE - 300HR #2 ENGINE INSP								
	REF:	MOS HRS/MSC ENC (AFL)	300			16-FEB-2001 7551 5515	7851	45	1.5
R 050150U	200 HOUR INSPECTION								
	REF:	MOS HRS/MSC AFL	200			26-JUN-2001 7687 5594	7887	81	31
SB 950920	SL WW-2492 HYD HOSE INSP SERVICE BULLETIN								
	REF:	MOS HRS/MSC AFL	200			26-JUN-2001 7687 5594	7887	81	
Total Labor Hours 36:0									
Total Price :									

R - Task was due on previous due lists
(xEXT) - Extension incorporated in the next due calculation



Maintenance Due List/Time Remaining - AIRCRAFT(AFL)

Aircraft Model - 1124A WESTWIND

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO	TASK DESCRIPTION	UNIT	INTERVAL TIME-----AT-----INSTALLATION COMPLIANCE				DISPOSITION	TIME	AREA
			WORK CARD	PART NUMBER/PKG	TSN	TSO			
WORK ORDER	SERIAL NUMBER						(ENH) AFH (xEXT)	OVD = Overdue	LABOR

SB 972B40U SERVICE BULLETIN GSBA72-3569 R/E FAN ROTOR

REF:

MOS
HRS/MSC A/R
AFL

5722

16

Total Labor Hours
Total Price :

R - Task was due on previous due lists
(xEXT) - Extension incorporated in the next due calculation

Aircraft Model - 1124A WESTWIND

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO	TASK DESCRIPTION	UNIT	INTERVAL TIME-----AT-----INSTALLATION COMPLIANCE				DISPOSITION	TIME	AREA
			WORK CARD	PART NUMBER/PKG	TSN	TSO			
WORK ORDER	SERIAL NUMBER								LABOR
R 725050	NO. 2 ENGINE - CHANGE FAN ROTOR DISC						LIFE LIMIT		
72.090	3073539-2 0-18040-4768 REF: NO REF	MOS HRS/MSC ENC (AFL)	4100	2660		20-MAY-1993 5278 3928	5368	OVD	
R 725030	NO. 2 ENGINE - CHANGE STAGE 3 LOW PRESSURE TURBINE DISC						LIFE LIMIT		
72.060	3072544-2 6-18040-4905 REF: NO REF	MOS HRS/MSC ENC (AFL)	3000	0		31-MAY-1989 4265 2793	5793	87	

Total Labor Hours
Total Price :

R - Task was due on previous due lists
(xEXT) - Extension incorporated in the next due calculation

OWNER: R&S AIRCRAFT INVESTMENTS, LLC
ADDRESS: P.O. BOX 43 HOUSTON TX 77001-0043
PHONE: 713-830-9584
FAX: 713-918-5925

OPERATOR: R&S AIRCRAFT INVESTMENTS, LLC
ADDRESS: P.O. BOX 43 HOUSTON TX 77001-0043
PHONE: 713-830-9584
FAX: 713-918-5925

PROJECTED : 2 MOS. to 14-JUL-2002

EXTENDED DUE LIST - FOR PLANNING PURPOSES ONLY - Scheduled Work Cards were not issued with this Report.

AIRCRAFT

S/N: 368 **REG NO:** N368MD **MODEL:** 1124A WESTWIND **MANUFACTURER:** GULFSTREAM AEROSPACE CORPORATION

NOTE:
INSPECTION PROGRAM: 3
CERTIFICATE DATE: 11-FEB-1982

UOM	LAST ACTUAL	LAST ACTUAL DATE	PROJECTED
HRS	7806	28-FEB-2002	7965.2
AFL	5706	28-FEB-2002	5865

ENGINE NO. 1

S/N: P-77482 **PART NO:** 3072500-2 **MODEL:** TFE731-3 **MANUFACTURER:** HONEYWELL

INSTALLED DATE: 4/3/1989
A/C HRS: 4215
ENGINE HRS: 3972
ENGINE CYCLES: 2456

UOM	LAST ACTUAL	LAST ACTUAL DATE	PROJECTED
HRS	7806	28-FEB-2002	7965.2
ENC	0		0
(AFL)	5706	28-FEB-2002	5865

ENGINE NO. 2

S/N: P77488 **PART NO:** 3072500-2 **MODEL:** TFE731-3 **MANUFACTURER:** HONEYWELL

INSTALLED DATE: 5/31/1993
A/C HRS: 5278
ENGINE HRS: 5227
ENGINE CYCLES: 3867

UOM	LAST ACTUAL	LAST ACTUAL DATE	PROJECTED
HRS	7806	28-FEB-2002	7965.2
ENC	0		0
(AFL)	5706	28-FEB-2002	5865



Extended Due List - AIRCRAFT(CALENDAR)

Aircraft Model - 1124A WESTWIND

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

EXTENDED DUE LIST - FOR PLANNING PURPOSE ONLY - Scheduled Work Cards were not issued with this Report.

ITEM NO WORK CARD WORK ORDER	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL TIME-----AT-----INSTALLATION				COMPLIANCE	DISPOSITION		AREA PRICE LABOR
			TSN	TSO	TSR	WARR EXP		NEXT DUE (ENH)	AFH (xEXT)	
270080	X-RAY INSPECT LEFT AILERON CONTROL ROD	LEFT AILERON CONTROL ROD ASSEMBLIES								W1
27.530	513506-503 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	60 5000				16-JUN-1997 6135 4707	16-JUN-2002 11135		
270081	X-RAY INSPECT RIGHT AILERON CONTROL ROD	ASSEMBLY								W2
27.535	513506-503 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	60 5000				16-JUN-1997 6135 4707	16-JUN-2002 11135		
270150	X-RAY INSPECT RUDDER CONTROL ROD	ASSEMBLY								T1
27.560	REF: NO REF	MOS HRS/MSC AFL	60 5000				16-JUN-1997 6135 4707	16-JUN-2002 11135		
270210	VISUAL INSPECT ELEVATOR CONTROL	BELLCRANK ASSEMBLY								
27.570	REF: AMM 5-10-00	MOS HRS/MSC AFL	60 5000				16-JUN-1997 6135 4707	16-JUN-2002 11135		
320110	X-RAY INSPECT NOSE GEAR ASSEMBLY	NOSE GEAR SHAFT AND DOOR ASSEMBLIES								L3
32.560	REF: AMM 5-10-00	MOS HRS/MSC AFL	60 5000				16-JUN-1997 6135 4707	16-JUN-2002 11135		
260171	WEIGHT CHECK COCKPIT PORTABLE	EXTINGUISHER COCKPIT FIRE EXTINGUISHER								F3
26.030	REF: AMM 5-10-00	MOS HRS/MSC AFL	12				26-JUN-2001 7687 5594	26-JUN-2002		
260181	WEIGHT CHECK CABIN PORTABLE	EXTINGUISHER CABIN FIRE EXTINGUISHER								F4
26.030	REF: AMM 5-10-00	MOS HRS/MSC AFL	12				26-JUN-2001 7687 5594	26-JUN-2002		
350166U	CHECK PILOT OXYGEN MASK									F3
35.070	REF: AMM 35-00-00	MOS HRS/MSC AFL	12 600				26-JUN-2001 7687 5594	26-JUN-2002 8287		
350169U	CHECK COPILOT OXYGEN MASK									F3
35.070	REF: AMM 35-00-00	MOS HRS/MSC AFL	12 600				26-JUN-2001 7687 5594	26-JUN-2002 8287		

Total Labor Hours
Total Price :

R - Task was due on previous due lists
(xEXT) - Extension incorporated in the next due calculation

Aircraft Model - 1124A WESTWIND

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

EXTENDED DUE LIST - FOR PLANNING PURPOSE ONLY - Scheduled Work Cards were not issued with this Report.

ITEM NO WORK CARD WORK ORDER	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL TIME-----AT-----INSTALLATION COMPLIANCE				DISPOSITION		AREA PRICE LABOR
			TSN	TSO	TSR	WARR EXP	NEXT DUE (ENH)	AFH (xEXT)	
710120 71.010	NO. 2 ENGINE - MAJOR PERIODIC INSPECTION	MOS HRS/MSC ENC (AFL)	1400				17-OCT-1998 6520	7920	
	REF: EMM 72-00-00						4889		
724120 72.030	NO. 2 ENGINE - INSPECT COMBUSTION PLENUM CASE	MOS HRS/MSC ENC (AFL)	1400				17-SEP-1998 6520	7920	
	REF: EMM 72-40-04						4889		
790120 79.020	NO. 2 ENGINE - CHANGE OIL	MOS HRS/MSC ENC (AFL)	1400				17-OCT-1998 6520	7920	
	REF: See Workcard						4889		
AD 1996-24-11 LEFT AILERON	TO PREVENT EXCESSIVE WEAR OF THE AILERON PUSH-PULL TUBE, WHICH COULD RESULT IN UNEVEN MOVEMENT OF THE CONTROL WHEEL, PERFORATION OF THE AILERON PUSH-PULL TUBE, AND CONSEQUENT REDUCED ROLL CONTROL OF THE AIRPLANE AIRWORTHINESS DIRECTIVE	MOS HRS/MSC AFL	600				26-JUL-2000 7325 5360	7925	W1
	REF: AD								
AD 1996-24-11 RIGHT AILERON	TO PREVENT EXCESSIVE WEAR OF THE AILERON PUSH-PULL TUBE, WHICH COULD RESULT IN UNEVEN MOVEMENT OF THE CONTROL WHEEL, PERFORATION OF THE AILERON PUSH-PULL TUBE, AND CONSEQUENT REDUCED ROLL CONTROL OF THE AIRPLANE AIRWORTHINESS DIRECTIVE	MOS HRS/MSC AFL	600				26-JUL-2000 7325 5360	7925	W2
	REF: AD								
SB 1124-27-129 LEFT AILERON	FLIGHT CONTROLS SERVICE BULLETIN	MOS HRS/MSC AFL	600				26-JUL-2000 7325 5360	7925	W1
	REF: BULLETINS								
SB 1124-27-129 RIGHT AILERON	FLIGHT CONTROLS SERVICE BULLETIN	MOS HRS/MSC AFL	600				26-JUL-2000 7325 5360	7925	W2
	REF: BULLETINS								

Total Labor Hours
Total Price :

R - Task was due on previous due lists
(xEXT) - Extension incorporated in the next due calculation

MODEL NAME : 1124A WESTWIND

SERIAL : 368

REG NO : N368MD

Each item on the Insufficient Information report has missing information needed to properly update the items(s). Missing information will be one or more of the following:

*TSN and/or

*Airframe Hours, Landings, Engine Cycles,

*Apu Hours or Starts

*Date of Manufacture

*Date of Expiration

For each item (code number) in the left hand column, please supply the missing information indicated by the question mark under the appropriate column heading, sign the authorization area



Insufficient Information Report

Aircraft Model - 1124A WESTWIND

Report Date 14-MAR-2002

Serial #: 368 Reg. #: N368MD

ITEM NO WORK CARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL TIME		AT	INSTALLATION TSR/TAC Warr Exp	COMPLIANCE	NEXT DUE	TIME REMAINING	AREA PRICE LABOR
			TSN	TSO						
230450U	-- REPLACE BEACON BATTERY	MOS					17-OCT-1998	?		
	REF: _____	HRS/MSC					6520			
	ENTER MISSING MANUAL NEXTDUE: _____	AFL					4889			
270251	CHANGE LEFT INBOARD FLAP ACTUATOR	MOS					16-JUN-1997			W1
27.210	1390T100-5	HRS/MSC	10000	?	?		6135	8329		\$1006.00
	610A REF: AMM 27-50-00	AFL					4707			8
	ENTER MISSING TSN HOURS, TSO HOURS: _____									
240116	CHANGE NO. 1 STARTER GENERATOR	MOS					06-NOV-2001			E1
24.010	23065-018-1	HRS/MSC	1000	?	?		7774	968		\$813.00
	3684 REF: AMM 80-10-00	AFL					5641			1
	ENTER MISSING TSN HOURS, TSO HOURS: _____									
240126	CHANGE NO. 2 STARTER GENERATOR	MOS					06-NOV-2001			E2
24.010	23065-018-1	HRS/MSC	1000	?	?		7774	968		\$813.00
	2562 REF: AMM 80-10-00	AFL					5641			1
	ENTER MISSING TSN HOURS, TSO HOURS: _____									
230207	REPLACE COCKPIT VOICE RECORDER BATTERY	MOS					17-OCT-1998	?		T1
23.130		HRS/MSC					6520			
	REF: NO REF	AFL					4889			
	ENTER MISSING MANUAL NEXTDUE: _____									

AUTHORIZED BY _____

CERT.# _____

DATE _____

OWNER: R&S AIRCRAFT INVESTMENTS, LLC
ADDRESS: P.O. BOX 43 HOUSTON TX 77001-0043

OPERATOR: R&S AIRCRAFT INVESTMENTS, LLC
ADDRESS: P.O. BOX 43 HOUSTON TX 77001-0043

PHONE: 713-830-9584
FAX: 713-918-5925

PHONE: 713-830-9584
FAX: 713-918-5925

AIRCRAFT

S/N: 368 **REG NO:** N368MD **MODEL:** 1124A WESTWIND **MANUFACTURER:** GULFSTREAM AEROSPACE CORPORATION

NOTE:
INSPECTION PROGRAM: 3
CERTIFICATE DATE: 11-FEB-1982

UOM	LAST ACTUAL	LAST ACTUAL DATE
HRS	7806	28-FEB-2002
AFL	5706	28-FEB-2002

ENGINE NO. 1

S/N: P-77482 **PART NO:** 3072500-2 **MODEL:** TFE731-3 **MANUFACTURER:** HONEYWELL

INSTALLED DATE: 4/3/1989
A/C HRS: 4215
ENGINE HRS: 3972
ENGINE CYCLES: 2456

UOM	LAST ACTUAL	LAST ACTUAL DATE
HRS	7806	28-FEB-2002
ENC	0	
(AFL)	5706	28-FEB-2002

ENGINE NO. 2

S/N: P77488 **PART NO:** 3072500-2 **MODEL:** TFE731-3 **MANUFACTURER:** HONEYWELL

INSTALLED DATE: 5/31/1993
A/C HRS: 5278
ENGINE HRS: 5227
ENGINE CYCLES: 3867

UOM	LAST ACTUAL	LAST ACTUAL DATE
HRS	7806	28-FEB-2002
ENC	0	
(AFL)	5706	28-FEB-2002



AIRCRAFT Status Report (Work Packages)

Aircraft Model - 1124 WESTWIND
 Owner Name R&S AIRCRAFT INVESTMENTS, LLC
 A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PKG NUMBER	UNT	ACT	INTERVAL TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
AIRCRAFT												
CHAPTER 05												
TIME LIMITS/MAINTENANCE CHECKS												
+ 050150U	200 HOUR INSPECTION PKG 1 in PKG 2, 3	MOS	R							26-JUN-2001		
	REF:	HRS/MSC		200						7687	7887 31	
		AFL								5594		
+ 050300U	400/200 HOUR INSPECTION PKG 2 in PKG 3	MOS	R							26-JUN-2001		
	REF:	HRS/MSC		400						7687	8087 45.5	
		AFL								5594		
+ 050600U	800/400/200 HOUR INSPECT PKG 3	MOS	R							26-JUL-2000		
	REF:	HRS/MSC		800				-38		7325	8087 45.5	
		AFL								5360		
+ 057110U	150HR #1 ENGINE INSP NO. 1 PKG 4	MOS								26-JUN-2001	E1	
	REF:	HRS/MSC		150						7687	1.5	
		AFL								5594		
+ 057110U	150HR #2 ENGINE INSP NO. 2 PKG 5	MOS								26-JUN-2001	E2	
	REF:	HRS/MSC		150						7687	1	
		AFL								5594		
+ 057120U	300HR #1 ENGINE INSP NO. 1 PKG 6	MOS								16-FEB-2001	E1	
	REF:	HRS/MSC		300						7551		
		AFL								5515		
+ 057120U	300HR #2 ENGINE INSP NO. 2 PKG 7	MOS								16-FEB-2001	E2	
	REF:	HRS/MSC		300						7551		
		AFL								5515		

Engine Model - TFE731-3
Owner Name R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PKG NUMBER	UNT	INTERVAL TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
			ACT	TSN	TSO	TSR	TSI				
ENGINE NO. 1											
CHAPTER 05											
TIME LIMITS/MAINTENANCE CHECKS											
+ 057110U	NO. 1 ENGINE - 150HR #1 ENGINE INSP PKG 4 in PKG 4,6, 6	MOS							26-JUN-2001		
	REF:	HRS/MSC	150					7687	7837	1	
		ENC (AFL)						5594			
+ 057120U	NO. 1 ENGINE - 300HR #1 ENGINE INSP PKG 6 in PKG 6	MOS							16-FEB-2001		
	REF:	HRS/MSC	300					7551	7851	1.5	
		ENC (AFL)						5515			

Engine Model - TFE731-3

Report Date **14-MAR-2002**

Owner Name **R&S AIRCRAFT INVESTMENTS, LLC**

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PKG NUMBER	UNT	ACT INTERVAL TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
			TSN	TSO	TSR	TSI	ADJ				
ENGINE NO. 2											
CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS											
+ 057110U	NO. 2 ENGINE - 150 HR #2 ENGINE INSP PKG 5 in PKG 5, 7	MOS						26-JUN-2001			
	REF:	HRS/MS ENC (AFL)	150					7687	7837	1	
								5594			
+ 057120U	NO. 2 ENGINE - 300 HR #2 ENGINE INSP PKG 7 in PKG 7	MOS						16-FEB-2001			
	REF:	HRS/MS ENC (AFL)	300					7551	7851	1.5	
								5515			

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNT	INTERVAL	TIME-----AT----- TSN TSO TSR TSI ADJ	INSTALLATION	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
AIRCRAFT									
CHAPTER 00 INFORMATION									
000004U	-- ICON HEALTH AND FITNESS							11-FEB-1982	
	REF:	MOS							
		HRS/MSC	N/R						
		AFL							
CHAPTER 10 PARKING, MOORING, STORE AND RET TO SERV									
+ 100310	CHECK AIRWORTHY DIRECTIVES								
10.010	PKG 1, 2, 3	MOS						26-JUN-2001	
	REF: NO REF	HRS/MSC	200					7687	
		AFL						5594	
+ 100320	CHECK SERVICE BULLETINS								
10.020	PKG 1, 2, 3	MOS						26-JUN-2001	
	REF: NO REF	HRS/MSC	200					7687	
		AFL						5594	
+ 100330	CHECK SERVICE LETTERS								
10.030	PKG 1, 2, 3	MOS						26-JUN-2001	
	REF: NO REF	HRS/MSC	200					7687	
		AFL						5594	
CHAPTER 12 SERVICING									
+ 120160	CHECK NO.1 ENGINE PREFLIGHT COMPLETE								E1
12.020	PKG 4	MOS						26-JUN-2001	
	REF: AMM 5-21-00	HRS/MSC	150					7687	
		AFL						5594	
+ 120161	CHECK NO.2 ENGINE PREFLIGHT COMPLETE								E2
12.020	PKG 5	MOS						26-JUN-2001	
	REF: AMM 5-21-00	HRS/MSC	150					7687	
		AFL						5594	
+ 120150	CHECK PRE-FLIGHT								
12.010	PKG 1, 2, 3	MOS						26-JUN-2001	
	REF: AMM 5-30-00	HRS/MSC	200					7687	
		AFL						5594	
CHAPTER 21 AIR CONDITIONING									
210280	CHECK BLEED AIR DUCT OVERPRESSURE SWITCH								F3
21.270	PKG 3	MOS						26-JUL-2000	
	REF: AMM 21-00-00	HRS/MSC	800					7325	
		AFL						5360	
+ 210276	OPERATIONAL CHECK PRESSURIZATION SWITCHES AND VALVES								F3
21.030	PKG 2, 3	MOS						26-JUN-2001	
	REF: AMM 21-00-00	HRS/MSC	400					7687	
		AFL						5594	
210641	ANTICIPATOR, TEMPERATURE SENSOR								F4
21.310	548486-1	MOS						11-FEB-1982	
	SN-UNKNOWN	HRS/MSC	O/C	0					
	REF: AMM 21-60-00	AFL							

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
210673 21.430	ASPIRATOR, ENVIRONMENTAL CONTROL SYSTEM PN SN-UNKNOWN REF: AMM 21-50-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5	
210661 21.350	BULB, CABIN TEMPERATURE INDICATOR SENSOR PN SN-UNKNOWN REF: AMM 21-60-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F4	
210626 21.450	CONTROL BOX, CABIN TEMPERATURE 548482-5 030C154 REF: AMM 21-60-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F4	
210118 21.360	CONTROL UNIT, BLEED AIR CONTROL RIGHT 3213894-4-1 P402C REF: NO REF	MOS HRS/MSC AFL					0 0 0			06-NOV-1990 4731 3324	F5	
210108 21.360	CONTROL UNIT, BLEED AIR LEFT 32131894-4-1 P336C REF: NO REF	MOS HRS/MSC AFL	O/C							06-NOV-1990 4731 3324	F5	
210176 21.180	CONTROLLER, CABIN AIR PRESSURE 130398-3 31340 REF: AMM 21-30-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3 \$1455. 3	
210178 21.480	CLEAN FILTER PKG 3 REF: AMM 21-30-00	MOS HRS/MSC AFL	800							26-JUL-2000 7325 5360	F3	
210606 21.240	EXCHANGER, REFRIGERATION UNIT HEAT PN SN-UNKNOWN REF: AMM 21-50-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5 20	
210636 21.300	FAN, CABIN TEMPERATURE 5783661-5 120713 REF: AMM 21-60-00	MOS HRS/MSC AFL	O/C							04-APR-1996 5747 4430	F4 \$302.	
210208 21.390	INDICATOR, CABIN ALTITUDE/PRESSURE 4883747-1 495 REF: AMM 21-31-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3	
210208 21.400	INDICATOR, CABIN RATE-OF-CLIMB 4883788 SN-UNKNOWN REF: AMM 21-31-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3	

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
210633 21.410	INDICATOR, CABIN TEMPERATURE 883767-501 197 REF: AMM 21-60-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982	F3	
210156 21.160	PLENUM, MIXING 5-783584-1 SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL	O/C	0						11-FEB-1982	F4	
210241 21.200	REGULATOR, ABSOLUTE AIR PRESSURE LOWER 102466-1 1203419 REF: AMM 21-30-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982	F3 4	
210221 21.080	REPLACE LOWER INLET AIR FILTER ELEMENT PKG 3 1203419 REF: AMM 21-30-00	MOS HRSMSC AFL	800							26-JUL-2000 7325 5360	F3	
210236 21.200	REGULATOR, ABSOLUTE AIR PRESSURE UPPER 102466-1 313613 REF: AMM 21-30-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982	F3 4	
210621 21.280	REGULATOR, PNEUMATIC PRESSURE PN SN-UNKNOWN REF: AMM 21-50-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982	F5	
210246 21.210	RELAY, PNEUMATIC 107312-2 11-9440 REF: AMM 21-30-00	MOS HRSMSC AFL	O/C	0						22-OCT-1982 482	F3 \$383. 4	
210619 21.420	SENSOR, 35 DEGREE TEMPERATURE 783649-1 071C730 REF: AMM 21-50-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982	F5	
+ 210622 21.420	INSPECT 35 DEGREE DUCT SENSOR PKG 1, 2, 3 REF: AMM 21-50-00	MOS HRSMSC AFL	200							26-JUN-2001 7687 5594	F5	
210631 21.460	SENSOR, CABIN TEMPERATURE 548484-1 070C482 REF: AMM 21-60-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982	F4	
210646 21.320	SENSOR, HIGH TEMPERATURE 627962-2 011C955 REF: AMM 21-60-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982	F4	

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION			COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR TSI ADJ			
210665	SENSOR, REFRIGERATION TEMPERATURE CONTROL								F3
21.440	3783649-1	MOS					03-NOV-1984		
	11166	HRS/MSC	O/C	0			2044		
	REF: NO REF	AFL							
210666	SEPARATOR, WATER								F5
21.050	179510-1	MOS					11-FEB-1982		
	31535	HRS/MSC	O/C	0					
	REF: AMM 21-70-00	AFL							
+ 210671	CLEAN/REPLACE CONDENSER/FILTER								F5
21.050	PKG 1, 2, 3	MOS					26-JUN-2001		
		HRS/MSC	200				7687	1	
	REF: AMM 21-70-00	AFL					5594		
210286	SWITCH, CABIN AIR SELECTOR								F3
21.380	823073-501	MOS					11-FEB-1982		
	8128133	HRS/MSC	O/C	0					
	REF: NO REF	AFL		0					
210656	SWITCH, OVERPRESSURE								F5
21.340	3-783646-2	MOS					11-FEB-1982		
	194	HRS/MSC	O/C	0					
	REF: AMM 21-60-00	AFL							
210651	SWITCH, OVERTEMPERATURE								F4
21.330	3-783645-1	MOS					11-FEB-1982		
	211	HRS/MSC	O/C	0					
	REF: AMM 21-60-00	AFL							
210623	TANK, AUXILIARY ENVIRONMENTAL CONTROL SYSTEM VOLUME								F2
21.440	131358-1	MOS					11-FEB-1982		
	311533	HRS/MSC	O/C	0					
	REF: NO REF	AFL							
210677	TURBINE, COOLING								F5
21.290	572375-2	MOS					15-MAR-1995		
	56-133	HRS/MSC	O/C	0			5585		
	REF: AMM 21-50-00	AFL					4260		
210681	CHANGE OIL								F5
21.290	PKG 1, 2, 3	MOS					26-JUN-2001		
		HRS/MSC	200				7687		
	REF: AMM 21-50-00	AFL					5594		
210601	UNIT, REFRIGERATION								F5
21.230	3783648-1	MOS					21-AUG-1983		
	120-333	HRS/MSC	O/C	0			1200		
	REF: AMM 21-50-00	AFL					667		
210616	VALVE, 35 DEGREE TEMPERATURE CONTROL								F5
21.260	898730-1	MOS					11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C	0					
	REF: AMM 21-50-00	AFL							

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
210121 21.060	VALVE, AIR CONDITIONING PRESSURE RELIEF 3-783644-1 162 REF: AMM 21-11-00	MOS HRS/MSC AFL							11-FEB-1982	F5	
210101 21.010	VALVE, BLEED AIR SWITCHING LEFT 3783647-3 P511 REF: AMM 21-11-00	MOS HRS/MSC AFL							11-FEB-1982	F5 \$1698.	
+ 210102 21.500	VISUALLY INSPECT PKG 2, 3 REF: AMM WCF 21.500	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594	F5	
210111 21.010	VALVE, BLEED AIR SWITCHING RIGHT 3783647-3 P506 REF: AMM 21-11-00	MOS HRS/MSC AFL							11-FEB-1982	F5 \$1698.	
+ 210112 21.500	VISUALLY INSPECT PKG 2, 3 REF: AMM WCF 21.500	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594	F5	
210146 21.130	VALVE, CABIN AIR CHECK LEFT PN SN-UNKNOWN REF: AMM 21-20-00	MOS HRS/MSC AFL							11-FEB-1982	F4	
210151 21.130	VALVE, CABIN AIR CHECK RIGHT PN SN-UNKNOWN REF: AMM 21-20-00	MOS HRS/MSC AFL							11-FEB-1982	F4	
210153 21.370	VALVE, COLD AIR CHECK PN SN-UNKNOWN REF: AMM 21-20-00	MOS HRS/MSC AFL							11-FEB-1982	F5	
210166 21.150	VALVE, CONDITION AIR PILOT PN SN-UNKNOWN REF: AMM 21-20-00	MOS HRS/MSC AFL							11-FEB-1982	F3	
210143 21.470	VALVE, EMERGENCY AIR CHECK PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL							11-FEB-1982	F5	
210141 21.120	VALVE, EMERGENCY AIR SHUTOFF 321760-2-1 P1222 REF: AMM 21-14-00	MOS HRS/MSC AFL							11-FEB-1982	F5 \$1099.	

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
210161 21.140	VALVE, FLOOD DUCT PN SN-UNKNOWN REF: AMM 21-20-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F4	
210136 21.110	VALVE, GROUND BY-PASS 4-783622-1 P4380 REF: AMM 21-13-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5 \$1099.	
210211 21.080	REPLACE UPPER INLET AIR FILTER ELEMENT PKG 3 REF: AMM 21-30-00	MOS HRS/MSC AFL	800							26-JUL-2000 7325 5360	F3	
210611 21.250	VALVE, HOT AIR 321760-2-1 P1108 REF: AMM 21-60-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5 \$1099.	
210158 21.380	VALVE, HOT AIR CHECK PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F4	
210226 21.070	VALVE, ISOBARIC SHUTOFF 3-783105 SN-UNKNOWN REF: AMM 21-30-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3	
210171 21.170	VALVE, MANUAL DEFOG PN SN-UNKNOWN REF: AMM 21-20-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3	
210181 21.190	VALVE, MANUAL DUMP 5-723018-401 21563 REF: AMM 21-30-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3	
210186 21.040	VALVE, NORMAL OUTFLOW 130374-6 110870 REF: AMM 21-30-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F4	
210256 21.220	VALVE, PRESSURE SOLENOID LOWER 3783686 175 REF: AMM 21-30-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3	
210251 21.220	VALVE, PRESSURE SOLENOID UPPER 3783686 214 REF: AMM 21-30-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3	

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
210131 21.100	VALVE, RAM AIR SHUTOFF 398712-1-1 P222 REF: AMM 21-12-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5	
210196 21.040	VALVE, SAFETY OUTFLOW 103278-8 11905 REF: AMM 21-30-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F4	
210261 21.160	VENTURI, AIRFLOW 131052-1 703075 REF: NO REF	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3	
210266 21.090	INSPECT/CLEAN SCREEN REF: NO REF	MOS HRS/MSC AFL	O/C						11-FEB-1982	F3	
CHAPTER 22 AUTO FLIGHT											
220166 22.020	AMPLIFIER, NO.1 AUTOPILOT SERVO 622-3108-016 2120LNR REF: AMM 22-10-03	MOS HRS/MSC AFL	O/C						27-AUG-1996	F3 1	
220156 22.050	COMPUTER, AUTO PILOT 522-2901-016 2198 REF: AMM 22-13-13	MOS HRS/MSC AFL	O/C		4165 3382			15-FEB-1995 5554 4242		F3	
220163 22.040	COMPUTER, AUTOPILOT YAW DAMPER 622-3167-028 4078 REF: AMM 22-10-05	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3	
221021 22.030	CONTROLLER, AIR DATA NO. 1 590A-3J SN-UNKNOWN REF: AMM 22-10-04	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3	
+ 340146 34.050 ASSOCIATED	LEAK CHECK LEFT STATIC SYSTEM REF: AMM 34-10-01	MOS HRS/MSC AFL	24						18-JAN-2001 7494 5466	MANDATORY F1 18-JAN-2003	
+ 340151 34.050 ASSOCIATED	LEAK CHECK RIGHT STATIC SYSTEM REF: AMM 34-10-01	MOS HRS/MSC AFL	24						18-JAN-2001 7494 5466	MANDATORY F1 18-JAN-2003	
221031 22.030	CONTROLLER, AIR DATA NO. 2 590A-3J1 SN-UNKNOWN REF: AMM 22-10-04	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3	

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----	INSTALLATION	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
					TSN	TSO	TSR	TSI	ADJ	
+ 340146		LEAK CHECK LEFT STATIC SYSTEM								MANDATORY F1
	34.050		MOS	24						18-JAN-2001 18-JAN-2003
	ASSOCIATED		HRS/MSC							7494
		REF: AMM 34-10-01	AFL							5466
+ 340151		LEAK CHECK RIGHT STATIC SYSTEM								MANDATORY F1
	34.050		MOS	24						18-JAN-2001 18-JAN-2003
	ASSOCIATED		HRS/MSC							7494
		REF: AMM 34-10-01	AFL							5466
222001		CONTROLLER, ALTITUDE PRESELECT								F3
	22.090	622-2923-066	MOS							11-FEB-1982
		SN-UNKNOWN	HRS/MSC	O/C	0					
		REF: NO REF	AFL		0					
220161		CONTROLLER, AUTOPILOT								F3
	22.010	792-6348-002	MOS							11-FEB-1982
		2759	HRS/MSC	O/C	0					1
		REF: AMM 22-10-02	AFL							
220181		MOUNT, AUTOPILOT AILERON SERVO								F5
	22.080	792-6783-001	MOS							11-FEB-1982
		1191	HRS/MSC	O/C	0					
		REF: AMM WCF 22.080	AFL							
220191		MOUNT, AUTOPILOT ELEVATOR SERVO								F5
	22.080	792-6783-001	MOS							11-FEB-1982
		1160	HRS/MSC	O/C	0					
		REF: AMM WCF 22.080	AFL							
220201		MOUNT, AUTOPILOT RUDDER SERVO								F5
	22.080	792-6783-001	MOS							11-FEB-1982
		1166	HRS/MSC	O/C	0					
		REF: AMM WCF 22.070	AFL							
220150		PANEL, AUTOPILOT								F3
	22.060	622-0141-023	MOS							11-FEB-1982
		SN-UNKNOWN	HRS/MSC	O/C						
		REF: AMM 22-11-02	AFL							
220176		SERVO, AUTOPILOT AILERON								F5
	22.070	792-6781-001	MOS							15-FEB-1995
		726	HRS/MSC	O/C	5554					5554
		REF: AMM WCF 22.070	AFL		4242					4242
220186		SERVO, AUTOPILOT ELEVATOR								F5
	22.070	792-6781-001	MOS							15-FEB-1995
		791	HRS/MSC	O/C	5554					5554
		REF: AMM WCF 22.070	AFL		4242					4242
220196		SERVO, AUTOPILOT RUDDER								F5
	22.070	792-6781-001	MOS							11-FEB-1982
		3915	HRS/MSC	O/C	0					
		REF: AMM WCF 22.070	AFL							

CHAPTER 23 COMMUNICATIONS

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L



AIRCRAFT Status Report

Aircraft Model - 1124 WESTWIND
 Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
 A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
230450U	-- REPLACE BEACON BATTERY	MOS								17-OCT-1998 ?		
	REF:	HRS/MSC								6520		
		AFL								4889		
+ 230218	INSPECT/CHECK STATIC DISCHARGE WICK RESISTANCE	MOS									F1	
23.120	PKG 2, 3	MOS								26-JUN-2001		
	REF: AMM 23-60-00	HRS/MSC	400							7687		
		AFL								5594		
230166	RENEW FCC RADIO/TELEPHONE LICENSE	MOS	60							27-OCT-1999 27-OCT-2004	F3	
23.100		HRS/MSC								6961		
	REF: See Workcard	AFL								5135		
238004U	-- INTERCOM, COPILOTS NAT LTD	MOS								15-APR-1993		
	AA80-020	MOS										
	9688	HRS/MSC	O/C							5252		
	REF:	AFL								3907		
238006U	-- INTERCOM, PILOTS NAT LTD.	MOS								15-APR-1993		
	AA80020	MOS										
	9689	HRS/MSC	O/C	0						5252		
	REF:	AFL								3907		
230111	AMPLIFIER, HF POWER	MOS								26-SEP-1995	F3	
23.030	622-2883-001	MOS										
	1033	HRS/MSC	O/C							5707		
	REF: AMM WCF 23.030	AFL								4380		
230156	ANTENNA, RADIO/TELEPHONE	MOS								11-FEB-1982	F1	
23.110	121-0011-000	MOS										
	3272	HRS/MSC	O/C	0								
	REF: AMM 23-21-00	AFL										
230136	ANTENNA, VHF BLADE	MOS								11-FEB-1982	F1	
23.070	DMC-81-1	MOS										
	387	HRS/MSC	O/C	0								
	REF: AMM 23-20-00	AFL										
230131	ANTENNA, VHF FIN CAP	MOS								11-FEB-1982	F1	
23.060	VFS-10-90-2	MOS										
	866	HRS/MSC	O/C	0							5	
	REF: AMM 23-20-00	AFL										
230399	BEACON, VOICE RECORDER	MOS								09-NOV-1996	T1	
23.130	DK-100	MOS										
	DL4928	HRS/MSC	O/C							5951		
	REF: NO REF	AFL								4589		
230171	CONTROL, COMMUNICATION 1	MOS								09-JAN-1986	F3	
23.140	622-4523-011	MOS										
	SN-UNKNOWN	HRS/MSC	O/C	0						2812		
	REF: NO REF	AFL								1743		

? - Insufficient Information
 + Task exists in FAA Manual
 3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
230181 23.140	CONTROL, COMMUNICATION 2 622-4523-003 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0						09-JAN-1986 2812 1743	F3	
230196 23.150	CONTROL, NO.1 AUDIO CENTER 522-3763-001 3747 REF: AMM 23-50-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3	
230201 23.150	CONTROL, NO.2 AUDIO CENTER 522-3763-001 3749 REF: AMM 23-50-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3	
230116 23.040	COUPLER, HF ANTENNA 622-2884-001 2427 REF: AMM WCF 23.040	MOS HRS/MSC AFL	O/C	5702 4372						16-AUG-1995 5702 4372	F3	
230101 23.010	PANEL, HF CONTROL 622-4545-001 SN-UNKNOWN REF: AMM WCF 23.010	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3	
230106 23.020	RECEIVER/EXCITER, HF 622-5337-001 1554 REF: AMM WCF 23.020	MOS HRS/MSC AFL	O/C							26-SEP-1995 5707 4380	F3	
230151 23.100	RECEIVER/TRANSMITTER, RADIO/TELEPHONE 400-0033-000 603 REF: AMM 23-21-00	MOS HRS/MSC AFL	O/C							29-JUL-1994 5472 4150	F3	
230206 23.130	RECORDER, COCKPIT VOICE 89094-003111 A01001 REF: NO REF	MOS HRS/MSC AFL	O/C							16-AUG-1995 5702 4372	T1	
230400 23.130	CLEAN/TEST BEACON REF: NO REF	MOS HRS/MSC AFL	6							06-NOV-2001 7774 5641	06-MAY-2002 T1	
230207 23.130	REPLACE BATTERY REF: NO REF	MOS HRS/MSC AFL								17-OCT-1998 6520 4889	? T1	
230121 23.050	TRANSCIVER, VHF NO. 1 622-1334-002 4589 REF: AMM 23-20-00	MOS HRS/MSC AFL	O/C	0						24-JUN-1991 4880 3495	F3	

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
230126	TRANSCIVER, VHF NO. 2									F3	
23.050	622-1879-002	MOS							28-MAY-1991		
	16718	HRS/MSC	O/C						4877		
	REF: AMM 23-20-00	AFL							3493		
230146	UNIT, RADIO/TELEPHONE CABIN									F4	
23.090	400-0030-004	MOS							06-FEB-1989		
	77790	HRS/MSC	O/C		0				4149		
	REF: AMM 23-21-00	AFL							2658		
230141	UNIT, RADIO/TELEPHONE COCKPIT									F3	
23.080	400-0032-002	MOS							11-FEB-1982		
	2506	HRS/MSC	O/C		0						
	REF: AMM 23-21-00	AFL									
230191	UNIT, UHF COMMUNICATION REMOTE DISPLAY									F3	
23.140	622-1945-011	MOS							11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C		0						
	REF: NO REF	AFL			0						
CHAPTER 24	ELECTRICAL POWER										
+ 241653	CHECK CIRCUIT BREAKER RESISTANCE/INSPECT BUS									F3	
24.140	PKG 3	MOS							26-JUL-2000		
		HRS/MSC	800						7325		
	REF: AMM 24-50-00	AFL							5360		
+ 241655	INSPECT DISTRIBUTION BUS CIRCUIT BREAKER									F3	
24.150	PKG 3	MOS							26-JUL-2000		
		HRS/MSC	800						7325		
	REF: AMM 24-50-00	AFL							5360		
+ 241657	INSPECT TEST PRIORITY BUS DIODES									F3	
24.160	PKG 3	MOS							26-JUL-2000		
		HRS/MSC	800						7325		
	REF: AMM 24-50-00	AFL							5360		
240156	BATTERY, LEFT									F2	
24.030	4833517-1	MOS							09-NOV-1996	\$2100.	
	8812674	HRS/MSC	O/C						5951	1	
	REF: AMM 24-30-00	AFL							4589		
240168	ANALYZE									F2	
24.030		MOS							09-NOV-1996		
		HRS/MSC	C/C						5951		
	REF: NO REF	AFL							4589		
+ 240161	CHECK ELECTROLYTE LEVEL									F2	
24.030	PKG 1, 2, 3	MOS							26-JUN-2001		
		HRS/MSC	200						7687	1	
	REF: AMM 12-10-06	AFL							5594		
240166	DEEP CYCLE									F2	
24.030	PKG 1, 2, 3	MOS							06-NOV-2001		
		HRS/MSC	200						7774	2	
	REF: AMM 12-10-06	AFL							5641		

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
240171	BATTERY, RIGHT										F2	
24.020	4833517-1	MOS							09-NOV-1996		\$2100.	
	8506152	HRS/MSC	O/C						5951		1	
	REF: AMM 24-30-00	AFL							4589			
240184	ANALYZE										F2	
24.020		MOS							09-NOV-1996			
		HRS/MSC							5951			
	REF: NO REF	AFL	C/C						4589			
+ 240176	CHECK ELECTROLYTE LEVEL										F2	
24.020	PKG 1, 2, 3	MOS							26-JUN-2001			
		HRS/MSC	200						7687		1	
	REF: AMM 12-10-06	AFL							5594			
240181	DEEP CYCLE										F2	
24.020	PKG 1, 2, 3	MOS							06-NOV-2001			
		HRS/MSC	200						7774		2	
	REF: AMM 12-10-06	AFL							5641			
240111	BLOWER, INVERTER COOLING										F2	
24.100	M125J-9A1	MOS							11-FEB-1982			
	200	HRS/MSC	O/C				0					
	REF: AMM 24-20-00	AFL										
240136	BOX, D.C. CONTACTOR LEFT										F5	
24.050	PN	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C				0					
	REF: NO REF	AFL										
240141	BOX, D.C. CONTACTOR RIGHT										F5	
24.050	PN	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C				0					
	REF: NO REF	AFL										
240146	CONTROL UNIT, GENERATOR NO. 1										F5	
24.040	5833515-1	MOS							30-NOV-1989			
	6681927M1	HRS/MSC	O/C						4430		1	
	REF: AMM 24-30-00	AFL							2987			
240151	CONTROL UNIT, GENERATOR NO. 2										F5	
24.040	5833515-1	MOS							01-MAY-1990			
	663958M1	HRS/MSC	O/C						4578		1	
	REF: AMM 24-30-00	AFL							3154			
240116	GENERATOR, STARTER NO. 1									OVERHAUL	E1	
24.010	23065-018-1	MOS							06-NOV-2001		\$813.	
	3684	HRS/MSC	1000						7774	?	1	
	REF: AMM 80-10-00	AFL							5641			
+ 240121	CHECK BRUSH WEAR/TENSION										E1	
24.010	PKG 4	MOS							06-NOV-2001			
		HRS/MSC	150						7774		.5	
	REF: See Workcard	AFL							5641			

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
+ 240118 24.170	INSPECT PKG 4	MOS HRS/MSC AFL	150						06-NOV-2001 7774 5641	E1	
	REF: AMM 5-21-00										
+ 240123 24.010	INSPECT SPLINE PKG 4	MOS HRS/MSC AFL	150						06-NOV-2001 7774 5641	E1 1	
	REF: AMM										
240128 24.010	GENERATOR, STARTER NO. 2 23065-018-1 2562	MOS HRS/MSC AFL	1000						06-NOV-2001 7774 5641	OVERHAUL E2 \$813. 1 ?	
	REF: AMM 80-10-00										
+ 240131 24.010	CHECK BRUSH WEAR/TENSION PKG 5	MOS HRS/MSC AFL	150						06-NOV-2001 7774 5641	E2	
	REF: See Workcard										
+ 240128 24.170	INSPECT PKG 5	MOS HRS/MSC AFL	150						06-NOV-2001 7774 5641	E2	
	REF: AMM 5-21-00										
+ 240133 24.010	INSPECT SPLINE PKG 5	MOS HRS/MSC AFL	150						06-NOV-2001 7774 5641	E2 1	
	REF: AMM 80-10-00										
240196 24.050	INDICATOR, BATTERY TEMPERATURE 4883754-501 1955	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3	
	REF: NO REF										
240101 24.080	INVERTER, NO. 1 6833508-501 C0253094	MOS HRS/MSC AFL	O/C	0					12-JUL-1989 4305 2845	F2 \$1150. 1	
	REF: AMM 24-20-00										
240106 24.080	INVERTER, NO. 2 6833508-501 1135	MOS HRS/MSC AFL	O/C	0					09-DEC-1985 2762 1713	F2 \$1150. 1	
	REF: AMM 24-20-00										
241651 24.120	METER, VOLT/AMP 6883091-513	MOS HRS/MSC AFL	O/C						11-FEB-1982		
	SN-UNKNOWN REF: NO REF										
241601 24.130	POWER SUPPLY, VHF EMERGENCY COMMUNICATION 501-1015-02	MOS HRS/MSC AFL	O/C	0					11-FEB-1982		
	SN-UNKNOWN REF: NO REF										

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
241606	INSPECT BATTERY										
24.130		MOS							11-OCT-1990		
		HRS/MSC	O/C						4718		
	REF: NO REF	AFL							3309		
240211	RECEPTACLE, EXTERNAL POWER									F1	
24.060	PN	MOS							11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C	0							
	REF: AMM 24-40-00	AFL									
+ 240203	FUNCTIONALLY CHECK BATTERY TEMPERATURE AND WARNING SYSTEM									F3	
24.070	PKG 1, 2, 3	MOS							26-JUN-2001		
	SN-UNKNOWN	HRS/MSC	200						7687		
	REF: AMM 24-30-01	AFL							5594		
240186	THERMISTOR, BATTERY LEFT									F2	
24.030	PN	MOS							11-JAN-1989		
	SN-UNKNOWN	HRS/MSC	O/C	0					4127		
	REF: See Workcard	AFL							2632		
240191	THERMISTOR, BATTERY RIGHT									F2	
24.020	PN	MOS							11-JAN-1989		
	SN-UNKNOWN	HRS/MSC	O/C	0					4127		
	REF: NO REF	AFL							2632		
240103	VOLTMETER, AC LEFT									F3	
	3883035-501	MOS							11-FEB-1982		
	HH9400	HRS/MSC	O/C	0							
	REF: NO REF	AFL									
240108	VOLTMETER, AC RIGHT									F3	
24.090	3883035-501	MOS							11-FEB-1982		
	JC1215	HRS/MSC	O/C	0							
	REF: NO REF	AFL									
240143	VOLTMETER, DC LEFT									F3	
24.110	6883091-505	MOS							11-FEB-1982		
	H69513	HRS/MSC	O/C	0							
	REF: NO REF	AFL									
240148	VOLTMETER, DC RIGHT									F3	
24.110	6883091-505	MOS							25-FEB-1994		
	JD1421	HRS/MSC	O/C		0				5408		
	REF: NO REF	AFL							4066		
CHAPTER 25	EQUIPMENT/FURNISHINGS										
+ 250162	INSPECT FIRST AID KIT									F4	
25.050		MOS	12						06-NOV-2001	06-NOV-2002	
		HRS/MSC							7774		
	REF: NO REF	AFL							5641		
+ 250156	INSPECT LIFE PRESERVERS									F4	
25.050		MOS	12						06-NOV-2001	06-NOV-2002	
		HRS/MSC							7774		
	REF: NO REF	AFL							5641		

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
250141 25.040	DISPLAY, CABIN INFORMATION 32940-004 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F4	
250146 25.040	OPERATIONAL CHECK REF: NO REF	MOS HRS/MSC AFL	O/C						11-FEB-1982	F4	
250116 25.020	INERTIA REEL, COPILOT PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3	
250111 25.020	INERTIA REEL, PILOT PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3	
250106 25.010	SEAT, COPILOT 1024-0 SN-UNKNOWN REF: AMM 25-10-01	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3	
250101 25.010	SEAT, PILOT 1025-0 SN-UNKNOWN REF: AMM 25-10-01	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3	
250131 25.030	SEATBELT, COPILOT PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3	
250121 25.030	SEATBELT, PILOT PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3	
250186 25.060	TRANSMITTER, EMERGENCY LOCATOR 607690-2 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F4	
CHAPTER 26	FIRE PROTECTION										
+ 260186 26.020	OPERATIONAL CHECK FIRE PROTECTION SYSTEM PKG 2, 3 REF: AMM 26-00-00	MOS HRS/MSC AFL		400					26-JUN-2001 7687 5594	F3	
+ 260148 26.010	REPLACE LEFT FIRE EXTINGUISHER NO.1 CARTRIDGE REF: AMM 26-20-00	MOS HRS/MSC AFL		48					17-JAN-2001 17-JAN-2005	SCRAP F5	

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
+ 260153 26.010	REPLACE LEFT FIRE EXTINGUISHER NO.2 CARTRIDGE	MOS HRS/MSC AFL	48							17-JAN-2001	SCRAP 17-JAN-2005	F5
	REF: AMM 26-20-00											
+ 260158 26.015	REPLACE RIGHT FIRE EXTINGUISHER NO.1 CARTRIDGE	MOS HRS/MSC AFL	48							17-JAN-2001	SCRAP 17-JAN-2005	F5
	REF: AMM 26-20-00											
+ 260163 26.015	REPLACE RIGHT FIRE EXTINGUISHER NO.2 CARTRIDGE	MOS HRS/MSC AFL	48							17-JAN-2001	SCRAP 17-JAN-2005	F5
	REF: AMM 26-20-00											
260176 26.030	EXTINGUISHER, CABIN PORTABLE MODEL 2-10	MOS HRS/MSC AFL				13				21-JAN-1989		F4
	U-329516		O/C			0				4131		
	REF: AMM 5-10-00									2636		
260182 26.030	DISCHARGE /VALVE OVERHAUL AND REFILL CABIN FIRE EXINGUISHER	MOS HRS/MSC AFL	72							06-NOV-2001	06-NOV-2007	F3
	REF: MSC SIL 1124-25-059R1									7774		
										5641		
260183 26.030	HYDROSTATIC TEST CABIN FIRE EXTINGUISHER	MOS HRS/MSC AFL	144							01-JAN-1995	01-JAN-2007	F4
	REF: See Workcard											
+ 260184 26.030	INSPECT CABIN FIRE EXTINGUISHER PKG 1, 2, 3	MOS HRS/MSC AFL	200							26-JUN-2001		F4
	REF: AMM 26-20-00									7687		
										5594		
+ 260180 26.060	VISUAL INSPECTION CABIN FIRE EXTINGUISHER	DAYS HRS/MSC AFL	30							06-NOV-2001	06-DEC-2001	F3
	REF: NO REF									7774		
										5641		
260181 26.030	WEIGHT CHECK CABIN FIRE EXTINGUISHER	MOS HRS/MSC AFL	12							26-JUN-2001	26-JUN-2002	F4
	REF: AMM 5-10-00									7687		
										5594		
260166 26.030	EXTINGUISHER, COCKPIT PORTABLE MODEL 2-10	MOS HRS/MSC AFL				13				21-JAN-1989		F3
	U-329659		O/C			0				4131		
	REF: AMM 5-10-00									2636		
260172 26.030	DISCHARGE /VALVE OVERHAUL AND REFILL COCKPIT FIRE EXTINGUISHER	MOS HRS/MSC AFL	72							06-NOV-2001	06-NOV-2007	F3
	REF: MSC SIL 1124-25-059R1									7774		
										5641		

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
260173 26.030	HYDROSTATIC TEST COCKPIT FIRE EXTINGUISHER	MOS HRS/MSC AFL	144						01-JAN-1995	01-JAN-2007	F3
	REF: MSC SIL 1124-25-059R1										
+ 260174 26.030	INSPECT COCKPIT FIRE EXTINGUISHER PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001		F3
	REF: AMM 26-20-00								7687 5594		
+ 260169 26.060	VISUAL INSPECTION COCKPIT FIRE EXTINGUISHER	DAYS HRS/MSC AFL	30						06-NOV-2001	06-DEC-2001	F3
	REF: NO REF								7774 5641		
260171 26.030	WEIGHT CHECK COCKPIT FIRE EXTINGUISHER	MOS HRS/MSC AFL	12						26-JUN-2001	26-JUN-2002	F3
	REF: AMM 5-10-00								7687 5594		
260111 26.010	EXTINGUISHER, FIRE LEFT 3643507-1 02447C1	MOS HRS/MSC AFL	O/C	0					11-FEB-1982		F5 \$795.
	REF: AMM 26-20-00										
260121 26.010	HYDROSTATIC TEST	MOS HRS/MSC AFL	60						06-NOV-2001	06-NOV-2006	MANDATORY F5
	REF: AMM 5-10-00								7774 5641		
+ 260146 26.010	RECORD DATE STAMPED ON NEW CARTRIDGE (SERVICE LIFE)	MOS HRS/MSC AFL	72						17-JAN-2001	17-JAN-2007	LIFE LIMIT F5
	REF: AMM 26-20-00										
+ 260151 26.010	RECORD DATE STAMPED ON NEW CARTRIDGE (SERVICE LIFE)	MOS HRS/MSC AFL	72						17-JAN-2001	17-JAN-2007	LIFE LIMIT F5
	REF: AMM 26-20-00										
+ 260148 26.010 ASSOCIATED	REPLACE LEFT FIRE EXTINGUISHER NO.1 CARTRIDGE	MOS HRS/MSC AFL	48						17-JAN-2001	17-JAN-2005	SCRAP F5
	REF: AMM 26-20-00										
+ 260153 26.010 ASSOCIATED	REPLACE LEFT FIRE EXTINGUISHER NO.2 CARTRIDGE	MOS HRS/MSC AFL	48						17-JAN-2001	17-JAN-2005	SCRAP F5
	REF: AMM 26-20-00										
260116 26.010	WEIGHT CHECK	MOS HRS/MSC AFL	O/C						17-JAN-2001		F5
	REF: See Workcard								7494 5466		

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
260126	EXTINGUISHER, FIRE RIGHT									F5	
26.015	23700004	MOS						10-JAN-1994		\$795.	
	02429C1	HRS/MSC	O/C		0			5382			
	REF: AMM 26-20-00	AFL						4036			
260136	HYDROSTATIC TEST								MANDATORY	F5	
26.015		MOS	60					07-APR-1999	07-APR-2004		
		HRS/MSC						6727			
	REF: AMM 5-10-00	AFL						4999			
+ 260156	RECORD DATE STAMPED ON NEW CARTRIDGE (SERVICE LIFE)								LIFE LIMIT	F5	
26.015		MOS	72					17-JAN-2001	17-JAN-2007		
		HRS/MSC									
	REF: AMM 26-20-00	AFL									
+ 260161	RECORD DATE STAMPED ON NEW CARTRIDGE (SERVICE LIFE)								LIFE LIMIT	F5	
26.015		MOS	72					17-JAN-2001	17-JAN-2007		
		HRS/MSC									
	REF: AMM 26-20-00	AFL									
+ 260158	REPLACE RIGHT FIRE EXTINGUISHER NO.1 CARTRIDGE								SCRAP	F5	
26.015		MOS	48					17-JAN-2001	17-JAN-2005		
	ASSOCIATED	HRS/MSC									
	REF: AMM 26-20-00	AFL									
+ 260163	REPLACE RIGHT FIRE EXTINGUISHER NO.2 CARTRIDGE								SCRAP	F5	
26.015		MOS	48					17-JAN-2001	17-JAN-2005		
	ASSOCIATED	HRS/MSC									
	REF: AMM 26-20-00	AFL									
260131	WEIGHT CHECK									F5	
26.015		MOS						17-JAN-2001			
		HRS/MSC	O/C					7494			
	REF: See Workcard	AFL						5466			
260101	FIRE DETECTOR, LEFT									E1	
26.040	4643506-3	MOS						11-FEB-1982			
	19491	HRS/MSC	O/C		0						
	REF: AMM 26-10-00	AFL									
260106	FIRE DETECTOR, RIGHT									E2	
26.040	4643506-3	MOS						11-FEB-1982			
	19503	HRS/MSC	O/C		0						
	REF: AMM 26-10-00	AFL									
260141	INDICATOR, EXTINGUISHER DISCHARGE									F5	
26.050	PN	MOS						11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C		0						
	REF: NO REF	AFL									
CHAPTER 27	FLIGHT CONTROLS										
+ 270271	ADJUST/TEST FLAP COMPARATOR									F3	
27.430	PKG 3	MOS						26-JUL-2000			
		HRS/MSC	800					7325			
	REF: AMM 27-50-00	AFL						5360			

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
+ 270140 27.070	CHECK AILERON CONTROL SYSTEM FREEPLAY PKG 3	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360	F5	
	REF: AMM 27-10-00										
+ 270341 27.440	CHECK CABLE TENSION AFT FUSELAGE PKG 2, 3	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594	F5	
	REF: AMM 27-00-00										
+ 270340 27.440	CHECK CABLE TENSION FLIGHT/PASSENGER COMPARTMENT PKG 3	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360	F3	
	REF: AMM 27-00-00										
+ 270280 27.230	CLEAN/INSPECT/LUBRICATE LEFT INBOARD/OUTBOARD FLEXIBLE SHAFT PKG 3	MOS HRS/MSC AFL	1200						16-FEB-2001 7551 5515	8751 W1	
	REF: AMM 27-50-00										
+ 270285 27.230	CLEAN/INSPECT/LUBRICATE RIGHT INBOARD/OUTBOARD FLEXIBLE SHAFT PKG 3	MOS HRS/MSC AFL	1200						16-FEB-2001 7551 5515	8751 W2	
	REF: AMM 27-50-00										
+ 270248 27.200	FUNCTIONAL CHECK FLAP TIME EXCEED RELAY PKG 2, 3	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594	F3	
	REF: AMM 27-50-00										
+ 270211 27.500	INSPECT SCISSORS ASSEMBLY PKG 2, 3	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594	T1	
	REF: See Workcard										
+ 270351 27.380	INSPECT/LUBRICATE PRESSURE SEALS PKG 3	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360	F4	
	REF: AMM WCF 27.380										
270214 27.195	LUBRICATE AFT HINGE FITTING BEARINGS PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594	T1	
	REF: NO REF										
270179 27.350	LUBRICATE CONTROL COLUMNS PKG 3	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360	F3	
	REF: AMM 12-20-00										
270213 27.190	LUBRICATE ELEVATOR ATTACH POINTS PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594	T1	
	REF: AMM 12-20-00										

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
270346 27.360	LUBRICATE FLIGHT CONTROL FORWARD/AFT BELLCRANKS PKG 3	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360		F4	
	REF: AMM 12-20-00	AFL										
270215 27.195	LUBRICATE FORWARD SCISSOR ASSEMBLY PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594		T1	
	REF: NO REF	AFL										
270356 27.370	LUBRICATE GUST LOCK PKG 3	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360		F3	
	REF: AMM 12-20-00	AFL										
270176 27.340	LUBRICATE RUDDER PEDAL ARMS PKG 3	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360		F3	
	REF: AMM 12-20-00	AFL										
+ 270335 27.280	OPERATIONAL CHECK SPEED BRAKES AND LIFT DUMPERS PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594		F2	
	REF: AMM 27-60-00	AFL										
270145 27.045	STATIC FRICTION TEST AILERON AND RUDDER PKG 3	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360			
	REF: AMM 27-00-00	AFL										
270210 27.570	VISUAL INSPECT ELEVATOR CONTROL BELLCRANK ASSEMBLY PKG 3	MOS HRS/MSC AFL	60 5000						16-JUN-1997 6135 4707	16-JUN-2002 11135		
	REF: AMM 5-10-00	AFL										
270331 27.320	ACCUMULATOR, LIFT DUMPER RIGHT WING 3-713515-501	INBOARD MOS HRS/MSC AFL	O/C	0					11-FEB-1982		W2	
	REF: AMM 27-60-00	AFL										
270116 27.060	ACTUATOR, AILERON TRIM TAB 5793500-1 1010	MOS HRS/MSC AFL	O/C						09-NOV-1996 5951 4589		W1	
	REF: AMM 27-10-00	AFL										
270251 27.210	ACTUATOR, FLAP LEFT INBOARD 1390T100-5 610A	MOS HRS/MSC AFL	10000						16-JUN-1997 6135 4707	LIFE LIMIT ?	W1 \$1006. 8	
	REF: AMM 27-50-00	AFL										
270256 27.220	ACTUATOR, FLAP LEFT OUTBOARD 1391T100-7 519A	MOS HRS/MSC AFL	10000			0			06-APR-1998 6346 4787	OVERHAUL 16346	W1 \$1046.	
	REF: AMM 27-50-00	AFL										

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
270261 27.210	ACTUATOR, FLAP RIGHT INBOARD 193544-1 749A REF: AMM 27-50-00	MOS HRS/MSC AFL	10000	0					15-JUL-1986 3201 1972	OVERHAUL 13201 8	W2 \$1006.
270266 27.220	ACTUATOR, FLAP RIGHT OUTBOARD 193544-502 120 REF: AMM 27-50-00	MOS HRS/MSC AFL	10000	0				22-OCT-1982 482	10482	LIFE LIMIT	W2 \$1046.
270216 27.170	ACTUATOR, HORIZONTAL STABILIZER TRIM 21164-005 0481-11AA REF: AMM 27-40-00	MOS HRS/MSC AFL	2500	0				06-APR-1998 6346 4787	7287	OVERHAUL	T1 \$4158.
+ 270217 27.170	INSPECT PKG 2, 3 REF: See Workcard	MOS HRS/MSC AFL	400					26-JUN-2001 7687 5594			T1
270328 27.310	ACTUATOR, LIFT DUMPER LEFT WING INBOARD 3-713515-501 SN-UNKNOWN REF: AMM 27-60-00	MOS HRS/MSC AFL	O/C	0				11-FEB-1982			W1
270326 27.310	ACTUATOR, LIFT DUMPER LEFT WING OUTBOARD 3-713515-501 SN-UNKNOWN REF: AMM 27-60-00	MOS HRS/MSC AFL	O/C	0				11-FEB-1982			W1
270333 27.320	ACTUATOR, LIFT DUMPER RIGHT WING OUTBOARD 3-713515-501 SN-UNKNOWN REF: AMM 27-60-00	MOS HRS/MSC AFL	O/C	0				11-FEB-1982			W2
270166 27.090	ACTUATOR, LOWER RUDDER TRIM 5793500-501 3219 REF: AMM 27-20-00	MOS HRS/MSC AFL	O/C	0				11-FEB-1982			T1 \$1000. 16
270301 27.260	ACTUATOR, SPEED BRAKE LEFT 3713515-503 1L-466P REF: AMM 27-60-00	MOS HRS/MSC AFL	O/C	0				11-FEB-1982			W1
270306 27.260	ACTUATOR, SPEED BRAKE RIGHT 3713515-503 1L-470P REF: AMM 27-60-00	MOS HRS/MSC AFL	O/C	0				11-FEB-1982			W2
270161 27.090	ACTUATOR, UPPER RUDDER TRIM 5793500-503 5220 REF: AMM 27-20-00	MOS HRS/MSC AFL	O/C	0				11-FEB-1982			T1 \$1000. 16

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
270101		AILERON, LEFT							W1
	27.010	5183003-407-2	MOS				11-FEB-1982		
		4376	HRS/MSC	O/C	0				
		REF: AMM 27-10-00	AFL						
+ 270140		CHECK AILERON CONTROL SYSTEM FREEPLAY							F5
	27.070	PKG 3	MOS				26-JUL-2000		
	ASSOCIATED		HRS/MSC	800			7325		
		REF: AMM 27-10-00	AFL				5360		
+ 270264		CLEAN/CHECK LEFT GUIDE ROLLERS							W1
	27.550	PKG 2, 3	MOS				26-JUN-2001		
			HRS/MSC	400			7687		
		REF: AMM 5-20-03	AFL				5594		
SB 1124-27-100 R2 L/H RODS		FLIGHT CONTROLS SERVICE BULLETIN							W1
	ASSOCIATED		MOS						
			HRS/MSC	A/R					
		REF: BULLETINS	AFL						
		Method of Compliance: OPEN							
SB 1124-27-129 LEFT AILERON		FLIGHT CONTROLS SERVICE BULLETIN							W1
	ASSOCIATED		MOS				26-JUL-2000		
			HRS/MSC	600			7325	7925	
		REF: BULLETINS	AFL				5360		
		Method of Compliance: OPEN							
+ 570106		INSPECT BELLCRANK							W1
	57.020	PKG 1, 2, 3	MOS				26-JUN-2001		
			HRS/MSC	200			7687		
		REF: AMM 5-20-03	AFL				5594		
+ 270262		INSPECT LEFT EXTERNAL PUSH-PULL TUBE							W1
	27.540	PKG 2, 3	MOS				26-JUN-2001		
			HRS/MSC	400			7687		
		REF: AMM 5-20-03	AFL				5594		
AD 1996-24-11 LEFT AILERON		TO PREVENT EXCESSIVE WEAR OF THE AILERON PUSH-PULL TUBE, WHICH COULD RESULT IN UNEVEN MOVEMENT OF THE CONTROL WHEEL, PERFORATION OF THE AILERON PUSH-PULL TUBE, AND CONSEQUENT REDUCED ROLL CONTROL OF THE AIRPLANE AIRWORTHINESS DIRECTIVE							W1
	ASSOCIATED		MOS				26-JUL-2000		
			HRS/MSC	600			7325	7925	
		REF: AD	AFL				5360		
		Method of Compliance: OPEN							
AD 1992-12-02 LEFT AILERON		TO PREVENT REDUCED CONTROLLABILITY OF THE AIRPLANE AIRWORTHINESS DIRECTIVE							W1
	ASSOCIATED		MOS						
			HRS/MSC	150					
		REF: AD	AFL						
		Method of Compliance: OPEN							
270106		AILERON, RIGHT							W2
	27.010	5183003-406-2	MOS				11-FEB-1982		
		4376	HRS/MSC	O/C	0				
		REF: AMM 27-10-00	AFL						

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
					TSN	TSO	TSR	TSI	ADJ			
+ 270140		CHECK AILERON CONTROL SYSTEM FREEPLAY										F5
	27.070	PKG 3	MOS							26-JUL-2000		
	ASSOCIATED		HRS/MSC	800						7325		
		REF: AMM 27-10-00	AFL							5360		
+ 270265		CLEAN/CHECK RIGHT GUIDE ROLLERS										W2
	27.550	PKG 2, 3	MOS							26-JUN-2001		
		REF: AMM 5-20-03	HRS/MSC	400						7687		
			AFL							5594		
SB 1124-27-100 R2 R/H		FLIGHT CONTROLS SERVICE BULLETIN										W2
	RODS		MOS									
	ASSOCIATED		HRS/MSC	A/R								
		REF: BULLETINS	AFL									
		Method of Compliance: OPEN										
SB 1124-27-129 RIGHT		FLIGHT CONTROLS SERVICE BULLETIN										W2
	AILERON		MOS							26-JUL-2000		
	ASSOCIATED		HRS/MSC	600						7325	7925	
		REF: BULLETINS	AFL							5360		
		Method of Compliance: OPEN										
+ 270263		INSPECT RIGHT EXTERNAL PUSH-PULL TUBE										W2
	27.540	PKG 2, 3	MOS							26-JUN-2001		
		REF: AMM 5-20-03	HRS/MSC	400						7687		
			AFL							5594		
AD 1996-24-11 RIGHT		TO PREVENT EXCESSIVE WEAR OF THE AILERON PUSH-PULL TUBE, WHICH COULD RESULT IN UNEVEN MOVEMENT OF THE CONTROL WHEEL,										W2
	AILERON	PERFORATION OF THE AILERON PUSH-PULL TUBE, AND CONSEQUENT REDUCED ROLL CONTROL OF THE AIRPLANE AIRWORTHINESS DIRECTIVE	MOS							26-JUL-2000		
	ASSOCIATED		HRS/MSC	600						7325	7925	
		REF: AD	AFL							5360		
		Method of Compliance: OPEN										
AD 1992-12-02 RIGHT		TO PREVENT REDUCED CONTROLLABILITY OF THE AIRPLANE AIRWORTHINESS DIRECTIVE										W2
	AILERON		MOS									
	ASSOCIATED		HRS/MSC	150								
		REF: AD	AFL									
		Method of Compliance: OPEN										
270291		BRAKE, SPEED LEFT										W1
	27.250	5-203007-507	MOS							11-FEB-1982		
		SN-UNKNOWN	HRS/MSC	O/C	0							
		REF: AMM 27-60-00	AFL									
+ 270335		OPERATIONAL CHECK SPEED BRAKES AND LIFT DUMPERS										F2
	27.280	PKG 1, 2, 3	MOS							26-JUN-2001		
	ASSOCIATED		HRS/MSC	200						7687		
		REF: AMM 27-60-00	AFL							5594		
270296		BRAKE, SPEED RIGHT										W2
	27.250	5-203007-506	MOS							11-FEB-1982		
		SN-UNKNOWN	HRS/MSC	O/C	0							
		REF: AMM 27-60-00	AFL									

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
+ 270335	OPERATIONAL CHECK SPEED BRAKES AND LIFT DUMPERS										F2	
27.280	PKG 1, 2, 3	MOS							26-JUN-2001			
	ASSOCIATED	HRS/MSC	200						7687			
	REF: AMM 27-60-00	AFL							5594			
270138	CHAIN, AILERON LEFT										F3	
27.080	3533516-1	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C	0								
	REF: AMM 27-30-00	AFL										
270139	CHAIN, AILERON RIGHT										F3	
27.080	3533516-1	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C	0								
	REF: AMM 27-30-00	AFL										
270186	COLUMN, CONTROL COPILOT										F3	
27.140	PN	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C	0								
	REF: AMM 27-30-00	AFL										
270181	COLUMN, CONTROL PILOT										F3	
27.140	PN	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C	0								
	REF: AMM 27-30-00	AFL										
270191	ELEVATOR, LEFT										T1	
27.150	5463012-401-1	MOS							11-FEB-1982			
	4381	HRS/MSC	O/C	0								
	REF: AMM 27-30-00	AFL										
+ 270193	INSPECT SKIN SEPARATION										T1	
27.150	PKG 1, 2, 3	MOS							26-JUN-2001			
		HRS/MSC	200						7687			
	REF: AMM 27-30-00	AFL							5594			
270213	LUBRICATE ELEVATOR ATTACH POINTS										T1	
27.190	PKG 1, 2, 3	MOS							26-JUN-2001			
	ASSOCIATED	HRS/MSC	200						7687			
	REF: AMM 12-20-00	AFL							5594			
270210	VISUAL INSPECT ELEVATOR CONTROL BELL CRANK ASSEMBLY											
27.570		MOS	60						16-JUN-1997	16-JUN-2002		
	ASSOCIATED	HRS/MSC	5000						6135	11135		
	REF: AMM 5-10-00	AFL							4707			
270201	ELEVATOR, RIGHT										T1	
27.150	5463012-402-1	MOS							11-FEB-1982			
	4381	HRS/MSC	O/C	0								
	REF: AMM 27-30-00	AFL										
+ 270203	INSPECT SKIN SEPARATION										T1	
27.150	PKG 1, 2, 3	MOS							26-JUN-2001			
		HRS/MSC	200						7687			
	REF: AMM 27-30-00	AFL							5594			

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
270213	LUBRICATE ELEVATOR ATTACH POINTS										
27.190	PKG 1, 2, 3	MOS						26-JUN-2001		T1	
	ASSOCIATED	HRS/MSC	200					7687			
	REF: AMM 12-20-00	AFL						5594			
270210	VISUAL INSPECT ELEVATOR CONTROL BELLCRANK ASSEMBLY										
27.570		MOS	60					16-JUN-1997	16-JUN-2002		
	ASSOCIATED	HRS/MSC	5000					6135	11135		
	REF: AMM 5-10-00	AFL						4707			
270233	FLAP ASSEMBLY, CONTROL BOX										
27.490	2813521-	MOS						11-FEB-1982		F3	
	286	HRS/MSC	O/C	0							
	REF: NO REF	AFL		0							
270236	FLAP/VANE, LEFT										
27.200	5193502-401	MOS						11-FEB-1982		W1	
	4369	HRS/MSC	O/C	0							
	REF: AMM 27-50-00	AFL									
+ 270248	FUNCTIONAL CHECK FLAP TIME EXCEED RELAY										
27.200	PKG 2, 3	MOS						26-JUN-2001		F3	
	ASSOCIATED	HRS/MSC	400					7687			
	REF: AMM 27-50-00	AFL						5594			
+ 270240	INSPECT LEFT FLAP HINGE AND BEARING 200 HOURS										
27.200	PKG 1, 2, 3	MOS						26-JUN-2001		W1	
		HRS/MSC	200					7687			
	REF: AMM 27-50-00	AFL						5594			
+ 270244	INSPECT LEFT FLAP HINGE AND BEARING 800 HOURS										
27.200	PKG 3	MOS						26-JUL-2000		W1	
		HRS/MSC	800					7325			
	REF: AMM 27-50-00	AFL						5360			
+ 270237	INSPECT LEFT FLAP VANE										
27.200	PKG 1, 2, 3	MOS						26-JUN-2001		W1	
		HRS/MSC	200					7687			
	REF: AMM 27-50-00	AFL						5594			
+ 270238	TAP TEST LEFT FLAP										
27.200	PKG 2, 3	MOS						26-JUN-2001		W1	
		HRS/MSC	400					7687		.5	
	REF: AMM 27-50-00	AFL						5594			
270241	FLAP/VANE, RIGHT										
27.200	5193502-402	MOS						11-FEB-1982		W2	
	4370	HRS/MSC	O/C	0							
	REF: AMM 27-50-00	AFL									
+ 270248	FUNCTIONAL CHECK FLAP TIME EXCEED RELAY										
27.200	PKG 2, 3	MOS						26-JUN-2001		F3	
	ASSOCIATED	HRS/MSC	400					7687			
	REF: AMM 27-50-00	AFL						5594			

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
+ 270247 27.200	INSPECT PKG 1, 2, 3	MOS HRS/MSC AFL	200							26-JUN-2001 7687 5594	W1	
	REF: AMM 27-50-00											
+ 270242 27.200	INSPECT RIGHT FLAP HINGE AND BEARING PKG 1, 2, 3	MOS HRS/MSC AFL	200							26-JUN-2001 7687 5594	W2	
	REF: AMM 27-50-00											
+ 270245 27.200	INSPECT RIGHT FLAP HINGE AND BEARING PKG 3	MOS HRS/MSC AFL	800							26-JUL-2000 7325 5360	W2	
	REF: AMM 27-50-00											
+ 270243 27.200	TAP TEST PKG 2, 3	MOS HRS/MSC AFL	400							26-JUN-2001 7687 5594	W2 .5	
	REF: AMM 27-50-00											
270276 27.400	GEARBOX, COMPARATOR LEFT 5-703541-501	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	W1 \$1570.	
	SN-UNKNOWN REF: AMM 27-50-00											
+ 270271 27.430 ASSOCIATED	ADJUST/TEST FLAP COMPARATOR PKG 3	MOS HRS/MSC AFL	800							26-JUL-2000 7325 5360	F3	
	REF: AMM 27-50-00											
270281 27.400	GEARBOX, COMPARATOR RIGHT 5-703541-502	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	W2	
	SN-UNKNOWN REF: AMM 27-50-00											
+ 270271 27.430 ASSOCIATED	ADJUST/TEST FLAP COMPARATOR PKG 3	MOS HRS/MSC AFL	800							26-JUL-2000 7325 5360	F3	
	REF: AMM 27-50-00											
270121 27.030	INDICATOR, AILERON TRIM TAB 3883026-515	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3	
	S0451 REF: AMM 27-10-00											
271101 27.470	INDICATOR, ANGLE-OF-ATTACK LEFT 3883765-501	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3	
	JN1066 REF: AMM 34-10-05											
271106 27.470	INDICATOR, ANGLE-OF-ATTACK RIGHT 3883765-501	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3	
	SN-UNKNOWN REF: AMM 34-10-05											

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
270288 27.420	INDICATOR, FLAP POSITION COPILOT 6883739-1 SN-UNKNOWN REF: AMM 27-50-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3	
270286 27.420	INDICATOR, FLAP POSITION PILOT 6883789-1 81090110 REF: AMM 27-50-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3 \$338.	
270226 27.160	INDICATOR, HORIZONTAL STABILIZER TRIM 3883026-525 T0119 REF: AMM 27-40-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3 \$306.	
270171 27.120	INDICATOR, RUDDER TRIM 3883026-517 T0163 REF: AMM 27-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3	
270224 27.185	JACKSCREW, HORIZONTAL STABILIZER ACTUATOR NO.1 21164-005 (ACT.ASSY) 0481-11A REF: NO REF	MOS HRS/MSC AFL		0	10000	0			06-APR-1998 6346 4787	LIFE LIMIT T1 14787	
270225 27.185	JACKSCREW, HORIZONTAL STABILIZER ACTUATOR NO.2 21164-005 (ACT.ASSY) 0481-11AA REF: NO REF	MOS HRS/MSC AFL		0	10000	0			06-APR-1998 6346 4787	LIFE LIMIT T1 14787	
270318 27.290	LIFT DUMPER, LEFT WING INBOARD 3713515-501 1L-900 REF: AMM 27-60-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	W1	
270316 27.290	LIFT DUMPER, LEFT WING OUTBOARD 3713515-501 1L887P REF: AMM 27-60-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	W1	
270321 27.300	LIFT DUMPER, RIGHT WING INBOARD 3713515-501 1L862P REF: AMM 27-60-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	W2	
270323 27.300	LIFT DUMPER, RIGHT WING OUTBOARD 5-203007-510 1L881P REF: AMM 27-60-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	W2	
270119 27.450	MOTOR, AILERON TRIM PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	W1	

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
270246 27.180	MOTOR, FLAP PRIME 193543-1 160 REF: AMM 27-50-00	MOS HRS/MSC AFL	10000		0				06/01/1993	01-DEC-1992 5188 3829	OVERHAUL 15188	F5 \$4235. 1
270221 27.460	MOTOR, PRIMARY HORIZONTAL STABILIZER PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C		0					11-FEB-1982		T1
270169 27.450	MOTOR, RUDDER TRIM PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C		0					11-FEB-1982		T1
270223 27.460	MOTOR, SECONDARY HORIZONTAL STABILIZER PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C		0					11-FEB-1982		T1
270274 27.410	POTENTIOMETER, LINEAR LEFT 833523-501 SN-UNKNOWN REF: AMM 27-50-00	MOS HRS/MSC AFL	O/C							10-AUG-1986 3515		W1
270282 27.410	POTENTIOMETER, LINEAR RIGHT 833523-501 589 REF: AMM 27-50-00	MOS HRS/MSC AFL	O/C							10-AUG-1986 3515		W2
270128 27.530	ROD, CONTROL LEFT AILERON 513506-503 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C							11-FEB-1982		W1
+ 270080 27.530	X-RAY INSPECT LEFT AILERON CONTROL ROD ASSEMBLIES SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	60 5000							16-JUN-1997 6135 4707	16-JUN-2002 11135	W1
270129 27.535	ROD, CONTROL RIGHT AILERON 513506-503 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C							11-FEB-1982		W2
+ 270081 27.535	X-RAY INSPECT ASSEMBLY SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	60 5000							16-JUN-1997 6135 4707	16-JUN-2002 11135	W2
270141 27.100	RUDDER, 5423026-402-2 4370 REF: AMM 27-20-00	MOS HRS/MSC AFL	O/C		0					11-FEB-1982		T1

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEMNO	WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
+ 270150	27.560	X-RAY INSPECT CONTROL ROD ASSEMBLY	MOS	60			16-JUN-1997	16-JUN-2002	T1
		REF: NO REF	HRS/MSC	5000			6135	11135	
			AFL				4707		
270279	27.230	SHAFT, FLEXIBLE INBOARD LEFT 193545-501	MOS					LIFE LIMIT	W1
		1200269	HRS/MSC	10000	0		11-FEB-1982	10000	
		REF: AMM 27-50-00	AFL						
+ 270280	27.230	CLEAN/INSPECT/LUBRICATE LEFT INBOARD/OUTBOARD FLEXIBLE SHAFT	MOS				16-FEB-2001		W1
	ASSOCIATED		HRS/MSC	1200			7551	8751	
		REF: AMM 27-50-00	AFL				5515		
270284	27.240	SHAFT, FLEXIBLE INBOARD RIGHT 193545-505	MOS					LIFE LIMIT	W2
		1200241	HRS/MSC	10000	0		11-FEB-1982	10000	
		REF: AMM 27-50-00	AFL						
+ 270285	27.230	CLEAN/INSPECT/LUBRICATE RIGHT INBOARD/OUTBOARD FLEXIBLE SHAFT	MOS				16-FEB-2001		W2
	ASSOCIATED		HRS/MSC	1200			7551	8751	
		REF: AMM 27-50-00	AFL				5515		
270278	27.230	SHAFT, FLEXIBLE OUTBOARD LEFT 193545-501	MOS					LIFE LIMIT	W1
		1200446	HRS/MSC	10000	0		11-FEB-1982	10000	
		REF: AMM 27-50-00	AFL						
+ 270280	27.230	CLEAN/INSPECT/LUBRICATE LEFT INBOARD/OUTBOARD FLEXIBLE SHAFT	MOS				16-FEB-2001		W1
	ASSOCIATED		HRS/MSC	1200			7551	8751	
		REF: AMM 27-50-00	AFL				5515		
270283	27.240	SHAFT, FLEXIBLE OUTBOARD RIGHT 193545-501	MOS					LIFE LIMIT	W2
		1200514	HRS/MSC	10000	0		11-FEB-1982	10000	
		REF: AMM 27-50-00	AFL						
+ 270285	27.230	CLEAN/INSPECT/LUBRICATE RIGHT INBOARD/OUTBOARD FLEXIBLE SHAFT	MOS				16-FEB-2001		W2
	ASSOCIATED		HRS/MSC	1200			7551	8751	
		REF: AMM 27-50-00	AFL				5515		
270126	27.040	TAB, AILERON SERVO 5-183005-505	MOS					LIFE LIMIT	W2
		SN-UNKNOWN	HRS/MSC	O/C	0		11-FEB-1982		
		REF: AMM 27-10-00	AFL						
270111	27.020	TAB, AILERON TRIM 5-183005-503	MOS					LIFE LIMIT	W1
		SN-UNKNOWN	HRS/MSC	O/C	0		11-FEB-1982		
		REF: AMM 27-10-00	AFL						

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----	INSTALLATION	COMPLIANCE	DISPOSITION	AREA
					TSN TSO TSR TSI ADJ	Warr Exp		NEXT DUE	PRICE LABOR HRS
270156		TAB, RUDDER TRIM							T1
	27.110	PN	MOS				11-FEB-1982		
		SN-UNKNOWN	HRS/MSC	O/C	0				
		REF: AMM 27-20-00	AFL						
+	270158	INSPECT FREEPLAY							T1
	27.130	PKG 1, 2, 3	MOS				26-JUN-2001		
			HRS/MSC	200			7687		
		REF: AMM 27-20-00	AFL				5594		
271111		TRANSMITTER, ANGLE-OF-ATTACK LEFT							W1
	27.480	SLZ7259	MOS				06-APR-1998		
		KE1141	HRS/MSC	O/C			6346		
		REF: AMM 34-10-05	AFL				4787		
271116		TRANSMITTER, ANGLE-OF-ATTACK RIGHT							W2
	27.480	SLZ-9280	MOS				11-FEB-1982		
		SN-UNKNOWN	HRS/MSC	O/C	0				
		REF: AMM 34-10-05	AFL		0				
270231		TRANSMITTER, TRIM POSITION INDICATOR							T1
	27.390	8TJ39-BAR-2	MOS				11-FEB-1982		\$543.
		T1353	HRS/MSC	O/C	0				
		REF: AMM 27-40-00	AFL						
270336		VALVE, LIFT DUMPER CONTROL							F5
	27.330	723573-1	MOS				11-FEB-1982		\$362.
		698	HRS/MSC	O/C	0				
		REF: AMM 27-60-00	AFL						
270311		VALVE, SPEED BRAKE CONTROL							F5
	27.270	723573-1	MOS				11-FEB-1982		\$362.
		845	HRS/MSC	O/C	0				
		REF: AMM 27-60-00	AFL						
270136		WHEEL, CONTROL COPILOT							F3
	27.050	5-533060-35	MOS				11-FEB-1982		
		SN-UNKNOWN	HRS/MSC	O/C	0				
		REF: AMM 27-10-00	AFL						
270131		WHEEL, CONTROL PILOT							F3
	27.050	5-533060-37	MOS				11-FEB-1982		
		SN-UNKNOWN	HRS/MSC	O/C	0				
		REF: AMM 27-10-00	AFL						
CHAPTER 28		FUEL							
+	281150	CHECK OPERATION OF FUEL BOOST PUMPS							F5
	28.010	PKG 1, 2, 3	MOS				26-JUN-2001		
			HRS/MSC	200			7687		
		REF: AMM 28-00-00	AFL				5594		
+	281603	FUNCTIONAL CHECK FUEL DUMP SYSTEM							F5
	28.090		MOS				22-FEB-2000		
			HRS/MSC	1200			7107	8307	
		REF: AMM 28-00-00	AFL				5232		

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
+ 281602 28.090	OPERATIONAL CHECK FUEL DUMP SYSTEM PKG 3	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360	F5	
281101 28.200	INDICATOR, FUEL QUANTITY LEFT 6883707-1	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3 \$444. 1	
281106 28.200	INDICATOR, FUEL QUANTITY RIGHT 6883707-1	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3 \$444. 1	
281108 28.210	INDICATOR, FUEL STATUS 6883710-501	MOS HRS/MSC AFL	O/C						11-FEB-1982	F3	
280626 28.160	PROBE, LEFT TIP TANK 6653505-519	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	W1	
280616 28.140	PROBE, LEFT WING INBOARD 5653505-507	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	W1	
280621 28.140	PROBE, LEFT WING OUTBOARD 5653505-505	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	W1	
280646 28.160	PROBE, RIGHT TIP TANK 6653505-519	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	W2	
280636 28.150	PROBE, RIGHT WING INBOARD 5653505-507	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	W2	
280641 28.150	PROBE, RIGHT WING OUTBOARD 5653505-505	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	W2	
280611 28.130	PROBE, FUSELAGE LEFT 3653505-509	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5	

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
280631 28.130	PROBE, FUSELAGE RIGHT 6653505-509 291 REF: AMM 28-40-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5	
280126 28.020	PUMP, ALTERNATE BOOST LEFT 5653744-505 T514 REF: AMM 28-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	W1	
280128 28.020	CHECK BRUSH WEAR REF: See Workcard	MOS HRS/MSC AFL	O/C						11-FEB-1982	W1	
+ 281150 28.010 ASSOCIATED	CHECK OPERATION OF FUEL BOOST PUMPS PKG 1, 2, 3 REF: AMM 28-00-00	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594	F5	
280136 28.020	PUMP, ALTERNATE BOOST RIGHT 5653744 853 REF: AMM 28-20-00	MOS HRS/MSC AFL	O/C						30-OCT-1989 4401 2956	W2	
280138 28.020	CHECK BRUSH WEAR REF: See Workcard	MOS HRS/MSC AFL	O/C						11-FEB-1982	W2	
+ 281150 28.010 ASSOCIATED	CHECK OPERATION OF FUEL BOOST PUMPS PKG 1, 2, 3 REF: AMM 28-00-00	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594	F5	
280161 28.110	PUMP, FUSELAGE JET LEFT 3-653015 1095 REF: AMM 28-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5	
280166 28.110	PUMP, FUSELAGE JET RIGHT 3-653015 1099 REF: AMM 28-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5	
280181 28.100	PUMP, JET LEFT TIP TANK 3-653015 1309 REF: AMM 28-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	W1	
280186 28.100	PUMP, JET RIGHT TIP TANK 3-653015 1311 REF: AMM 28-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	W2	

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
280167 28.230	PUMP, LONG RANGE BOOST 653009-513 SN-UNKNOWN REF: AMM 28-50-00	MOS HRS/MSC AFL							11-FEB-1982	F4	
280121 28.010	PUMP, MAIN BOOST LEFT 2070C01T3 T-330 REF: AMM 28-20-00	MOS HRS/MSC AFL				0			24-APR-2000 7233 5301	W1	
280123 28.010	CHECK BRUSH WEAR REF: NO REF	MOS HRS/MSC AFL							24-APR-2000 7233 5301	W1	
+ 281150 28.010 ASSOCIATED	CHECK OPERATION OF FUEL BOOST PUMPS PKG 1, 2, 3 REF: AMM 28-00-00	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594	F5	
280131 28.010	PUMP, MAIN BOOST RIGHT 2070C01T3 T1222 REF: AMM 28-20-00	MOS HRS/MSC AFL				0			26-AUG-1992 5151 3777	W2	
280133 28.010	CHECK BRUSH WEAR REF: See Workcard	MOS HRS/MSC AFL							26-AUG-1992 5151 3777	W2	
+ 281150 28.010 ASSOCIATED	CHECK OPERATION OF FUEL BOOST PUMPS PKG 1, 2, 3 REF: AMM 28-00-00	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594	F5	
281121 28.210	SIGNAL CONDITIONER, FUEL 883711-501 157 REF: NO REF	MOS HRS/MSC AFL				0			11-FEB-1982	F2	
280281 28.190	SWITCH, FUEL FLOAT LEFT 833006 A966 REF: NO REF	MOS HRS/MSC AFL				0			11-FEB-1982	F5	
280286 28.190	SWITCH, FUEL FLOAT RIGHT 833006 A920 REF: NO REF	MOS HRS/MSC AFL				0			11-FEB-1982	F5	
281141 28.170	SWITCH, LOW-LEVEL WARNING LEFT 3833006 SN-UNKNOWN REF: AMM 28-40-00	MOS HRS/MSC AFL				0			11-FEB-1982	F5	

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
281146 28.170	SWITCH, LOW-LEVEL WARNING RIGHT 3833006 SN-UNKNOWN REF: AMM 28-40-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5	
281139 28.240	SWITCH, PRESSURE(LONG RANGE) 833010-518 A-149 REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F4	
280250 28.220	TANK, FUEL (LONG RANGE) CMA61032-501 NSN REF: AMM 28-50-00	MOS HRS/MSC AFL	O/C		0					07-DEC-1989 4437 2994	F5	
281110 28.240	TRANSMITTER, QUANTITY (LONG RANGE) DA515A050 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F4	
280191 28.090	VALVE, DUMP LEFT 3653014 168 REF: AMM 28-30-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	W1 \$725.	
+ 281603 28.090 ASSOCIATED	FUNCTIONAL CHECK FUEL DUMP SYSTEM REF: AMM 28-00-00	MOS HRS/MSC AFL		1200						22-FEB-2000 7107 5232	8307 F5	
+ 281602 28.090 ASSOCIATED	OPERATIONAL CHECK FUEL DUMP SYSTEM PKG 3 REF: AMM 28-00-00	MOS HRS/MSC AFL		800						26-JUL-2000 7325 5360	F5	
280196 28.090	VALVE, DUMP RIGHT 3653014 31360 REF: AMM 28-30-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	W2 \$725.	
+ 281603 28.090 ASSOCIATED	FUNCTIONAL CHECK FUEL DUMP SYSTEM REF: AMM 28-00-00	MOS HRS/MSC AFL		1200						22-FEB-2000 7107 5232	8307 F5	
+ 281602 28.090 ASSOCIATED	OPERATIONAL CHECK FUEL DUMP SYSTEM PKG 3 REF: AMM 28-00-00	MOS HRS/MSC AFL		800						26-JUL-2000 7325 5360	F5	
280141 28.040	VALVE, FIREWALL SHUTOFF LEFT 3653012 L38199 REF: AMM 28-20-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	E1	

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
280151 28.040	VALVE, FIREWALL SHUTOFF RIGHT 3-653012 L35008 REF: AMM 28-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	E2 \$725.	
280251 28.050	VALVE, FUEL AUTO SHUTOFF LEFT 3653669 0114 REF: AMM 28-10-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5	
280256 28.050	VALVE, FUEL AUTO SHUTOFF RIGHT 3653669 0087 REF: AMM 28-10-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5	
280106 28.030	VALVE, FUEL INTERCONNECT AFT 3653014 31395 REF: AMM 28-10-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5 \$725.	
280101 28.030	VALVE, FUEL INTERCONNECT FORWARD AV16B1683 L18181 REF: AMM 28-10-00	MOS HRS/MSC AFL	O/C						16-JUN-1997 6135 4707	F5 \$725.	
280261 28.060	VALVE, FUEL PILOT LEFT 3653671 7732 REF: AMM 28-10-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5	
280266 28.060	VALVE, FUEL PILOT RIGHT 3653671 7728 REF: AMM 28-10-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5	
280194 28.070	VALVE, FUEL PRECHECK LEFT PN SN-UNKNOWN REF: AMM 28-10-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5	
280203 28.070	VALVE, FUEL PRECHECK RIGHT PN SN-UNKNOWN REF: AMM 28-10-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5	
280206 28.180	VALVE, FUEL SOLENOID LEFT MS-29527-1 744 REF: NO REF	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5	
280211 28.180	VALVE, FUEL SOLENOID RIGHT MS-29527-1 752 REF: NO REF	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5	

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
280171 28.120	VALVE, FUEL TRANSFER LEFT 4653572	MOS								11-FEB-1982	F5 \$805.	
	101 REF: AMM 28-20-00	HRS/MSC AFL	O/C	0								
280176 28.120	VALVE, FUEL TRANSFER RIGHT 4653572	MOS								11-FEB-1982	F5 \$805.	
	126 REF: AMM 28-20-00	HRS/MSC AFL	O/C	0								
280290 28.250	VALVE, SINGLE POINT REFUEL ADAPTER 3653670	MOS								11-FEB-1982	F5	
	205 REF: NO REF	HRS/MSC AFL	O/C									
280271 28.080	VALVE, SINGLE POINT REFUEL VENT LEFT 3653672	MOS								11-FEB-1982	F5	
	SN-UNKNOWN REF: AMM 28-10-00	HRS/MSC AFL	O/C	0	0							
280276 28.080	VALVE, SINGLE POINT REFUEL VENT RIGHT 3653672	MOS								11-FEB-1982	F5	
	SN-UNKNOWN REF: AMM 28-10-00	HRS/MSC AFL	O/C	0	0							
CHAPTER 29	HYDRAULIC POWER											
290221 29.080	ACCUMULATOR, EMERGENCY 3713008	MOS								11-FEB-1982	F5 \$472.	
	601 REF: AMM 29-20-00	HRS/MSC AFL	O/C	0								
290151 29.130	ACCUMULATOR, LEFT HYDRAULIC 4-71 3569-1	MOS								11-FEB-1982	F5	
	SN-UNKNOWN REF: NO REF	HRS/MSC AFL	O/C	0								
290186 29.130	ACCUMULATOR, RIGHT HYDRAULIC 4-71 3569-1	MOS								11-FEB-1982	F5	
	SN-UNKNOWN REF: NO REF	HRS/MSC AFL	O/C	0								
290261 29.040	ATTENUATOR, NO.1 ENG HYDRAULIC 3713562-1	MOS								11-FEB-1982	F5	
	0601 REF: AMM 29-10-00	HRS/MSC AFL	O/C	0								
290266 29.040	ATTENUATOR, NO.2 ENG HYDRAULIC 3713562-1	MOS								11-FEB-1982	F5	
	0591 REF: AMM 29-10-00	HRS/MSC AFL	O/C	0								
290119 29.180	CHECK VALVE, RESERVOIR BLEED AIR PN	MOS								11-FEB-1982	F5	
	SN-UNKNOWN REF: NO REF	HRS/MSC AFL	O/C	0								

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
290248 29.110	FUSE, EMERGENCY HYDRAULIC 3713047 3383 REF: AMM 29-30-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F2	
290246 29.100	GAUGE, EMERGENCY HYDRAULIC PRESSURE 4883746-1 SN-UNKNOWN REF: AMM 29-30-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3	
290148 29.140	GAUGE, LEFT ACCUMULATOR PRESSURE 7253014-501 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5	
290183 29.140	GAUGE, RIGHT ACCUMULATOR PRESSURE 7253014-501 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5	
290236 29.160	INDICATOR, HYDRAULIC PRESSURE 4883746-1 8007104 REF: AMM 29-30-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3	
290211 29.060	PUMP, EMERGENCY HYDRAULIC 3713010-505 13747 REF: AMM 29-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5 \$805.	
290215 29.110	FUNCTIONAL TEST EMERGENCY HYDRAULIC FUSE REF: AMM 29-30-06	MOS HRS/MSC AFL	36 1200					30-NOV-1999 6991 5163	30-NOV-2002 8191		
290141 29.120	PUMP, HYDRAULIC NO. 1 5713524-507 B1-58 REF: AMM 29-10-00	MOS HRS/MSC AFL	O/C		0 0 0			09-OCT-1990 4718 3309		E1	
+ 290143 29.120	INSPECT/LUBRICATE NO.1 ENGINE HYDRAULIC PUMP SPLINES PKG 1, 2, 3 REF: AMM 29-10-00	MOS HRS/MSC AFL	200					26-JUN-2001 7687 5594		E1 1	
290176 29.120	PUMP, HYDRAULIC NO. 2 5713524-507 A2-84 REF: AMM 29-10-00	MOS HRS/MSC AFL	O/C		0			04-FEB-1994 5390 4040		E2 1	
+ 290178 29.120	INSPECT/LUBRICATE NO.2 ENGINE HYDRAULIC PUMP SPLINES PKG 1, 2, 3 REF: AMM 29-10-00	MOS HRS/MSC AFL	200					26-JUN-2001 7687 5594		E2 1	

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
290121 29.050	REGULATOR, RESERVOIR AIR PRESSURE 3713015	MOS							11-FEB-1982	F5 \$1046.	
	509 REF: AMM 29-10-00	HRS/MSC AFL	O/C	0							
290118 29.050	CLEAN/CHECK HYDRAULIC RESERVOIR AIR PRESSURE CHECK VALVE PKG 2, 3	MOS							26-JUN-2001	F5	
	509 REF: AMM 5-20-00	HRS/MSC AFL	400					7687 5594			
+ 290131 29.050	INSPECT/REPLACE RESERVOIR AIR PRESSURE FILTER PKG 3	MOS							26-JUL-2000	F5	
	REF: AMM 29-10-00	HRS/MSC AFL	800					7325 5360			
+ 290116 29.050	INSPECT/REPLACE RESERVOIR AIR VENT FILTER PKG 3	MOS							26-JUL-2000	F5	
	509 REF: AMM 29-10-10	HRS/MSC AFL	800					7325 5360			
290171 29.050	REPLACE NO.1 ENGINE HIGH PRESSURE HYDRAULIC FILTER ELEMENT PKG 3	MOS							26-JUL-2000	F5	
	REF: AMM 29-10-10	HRS/MSC AFL	800					7325 5360			
290206 29.050	REPLACE NO.2 ENGINE HIGH PRESSURE HYDRAULIC FILTER ELEMENT PKG 3	MOS							26-JUL-2000	F5	
	REF: AMM 29-10-10	HRS/MSC AFL	800					7325 5360			
290101 29.010	RESERVOIR, HYDRAULIC 5713014-505	MOS							11-FEB-1982	F5	
	SN-UNKNOWN REF: AMM 29-10-00	HRS/MSC AFL	O/C	0							
290106 29.010	REPLACE FILTER PKG 3	MOS							26-JUL-2000	F5	
	REF: AMM 29-10-00	HRS/MSC AFL	800					7325 5360			
290226 29.090	SWITCH, EMERGENCY HYDRAULIC PRESSURE 4833010-515	MOS							11-FEB-1982	F5	
	872 REF: AMM 29-20-00	HRS/MSC AFL	O/C	0							
290241 29.170	SWITCH, NO.1 LOW HYDRAULIC PRESSURE WARNING 4713533-1	MOS							11-FEB-1982	F5	
	798 REF: AMM 29-30-00	HRS/MSC AFL	O/C	0						1	
290243 29.170	SWITCH, NO.2 LOW HYDRAULIC PRESSURE WARNING 4713533-1	MOS							11-FEB-1982	F5	
	788 REF: AMM 29-30-00	HRS/MSC AFL	O/C	0							

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
290231 29.150	TRANSMITTER, HYDRAULIC PRESSURE 3883028 8005119 REF: AMM 29-30-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5 \$507.	
290133 29.180	VALVE, BLEED RETURN PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5	
290216 29.070	VALVE, EMERGENCY THERMAL RELIEF 4713011-1 1L82 REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5	
290138 29.190	VALVE, HYDRAULIC PRESSURE RELIEF 373596-501 158 REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5	
290146 29.020	VALVE, LEFT HYDRAULIC SHUTOFF 713020- 080 REF: AMM 29-10-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	E1 \$322.	
290136 29.030	VALVE, MANUAL HIGH-PRESSURE RELIEF 3723628 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5	
290181 29.020	VALVE, RIGHT HYDRAULIC SHUTOFF 713020- 074 REF: AMM 29-10-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	E2 \$322.	
290271 29.190	VALVE, THERMAL HYDRAULIC RELIEF 3713554 0168 REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5	
CHAPTER 30 ICE AND RAIN PROTECTION												
+ 300133 30.100	FUNCTIONAL CHECK PNEUMATIC DE-ICER BOOTS. PKG 3 REF: AMM 30-10-00	MOS HRS/MSC AFL		800						26-JUL-2000 7325 5360	F3	
+ 300150 30.140	INSPECT COPILOT WINDSHIELD CYCLING CONTACTOR PKG 1, 2, 3 REF: AMM 30-40-00	MOS HRS/MSC AFL		200						26-JUN-2001 7687 5594	F3	
+ 300147 30.140	INSPECT PILOT WINDSHIELD CYCLING CONTACTOR PKG 1, 2, 3 REF: AMM 30-40-00	MOS HRS/MSC AFL		200						26-JUN-2001 7687 5594	F3	

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
+ 300163 30.160	INSPECT WINDSHIELD WIPER ASSEMBLY PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594			
300170 30.150	OPERATIONAL TEST P2T2 SENSOR HEATER PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594			
300165 30.170	REPLACE WIPER BLADE ELEMENT NOTE: IT IS RECOMMENDED TO REPLACE WIPER BLADE ELEMENT EVERY 6 MONTHS OR 250 HOURS.	MOS HRS/MSC AFL							06-NOV-2001 7774 5641			
300101 30.010	CHECK VALVE, DE-ICER LEFT PN SN-UNKNOWN REF: AMM 30-10-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982		F4	
+ 300102 30.010	INSPECT PKG 2, 3	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594		F4	
300103 30.010	CHECK VALVE, DE-ICER RIGHT PN SN-UNKNOWN REF: AMM 30-10-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982		F4	
+ 300104 30.010	INSPECT PKG 2, 3	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594		F4	
300146 30.110	CONTROLLER, WINDSHIELD TEMPERATURE LEFT HYLZ9661 982B REF: AMM 30-40-00	MOS HRS/MSC AFL	O/C	0					22-FEB-2000 7107 5232		F3	
300148 30.110	CONTROLLER, WINDSHIELD TEMPERATURE RIGHT 833034-1 SN-UNKNOWN REF: AMM 30-40-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982		F3	
300111 30.030	EJECTOR, AIR 850278-1 RF3295 REF: AMM 30-10-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982		F4	
300156 30.130	MOTOR, WINDSHIELD WIPER LEFT XW21126-315-R32 2-22826 REF: AMM 30-40-00	MOS HRS/MSC AFL	O/C	0					26-JUL-2000 7325 5360		F3 \$354. 7	

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
300161 30.130	MOTOR, WINDSHIELD WIPER RIGHT 5823099-402 213743 REF: AMM 30-40-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3	
300106 30.020	REGULATOR, PRESSURE 4753042-501 3300U REF: AMM 30-10-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F4 \$403.	
300116 30.040	SWITCH, PRESSURE 3753045-507 287 REF: AMM 30-10-00	MOS HRS/MSC AFL	O/C	0					31-OCT-1992 5170 3802	F4	
300141 30.090	SWITCH, PRESSURE INDICATOR NO. 1 ENGINE 12299 SN-UNKNOWN REF: AMM 30-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	E1	
300144 30.090	SWITCH, PRESSURE INDICATOR NO. 2 ENGINE 12299 1246 REF: AMM 30-20-00	MOS HRS/MSC AFL	O/C	0				06/29/1993	29-DEC-1992 5203 4938	E2	
300121 30.050	SWITCH, VACUUM 3-753064-501 277 REF: AMM 30-10-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F4	
300151 30.120	SWITCH, WINDSHIELD THERMOSTAT LEFT PN SN-UNKNOWN REF: AMM 30-40-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3	
300153 30.120	SWITCH, WINDSHIELD THERMOSTAT RIGHT PN SN-UNKNOWN REF: AMM 30-40-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3	
300131 30.070	TIMER, DE-ICER 3-753046-1 G426 REF: AMM 30-10-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F4	
300126 30.060	VALVE, DISTRIBUTOR 753511-1 41359U REF: AMM 30-10-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F4	
300136 30.080	VALVE, NO.1 NACELLE ANTI-ICE F10A-5-SCP-102-5 193RW REF: AMM 30-20-00	MOS HRS/MSC AFL	O/C	0					30-JAN-1984 1468 908	E1	

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
300138 30.080	VALVE, NO.2 NACELLE ANTI-ICE F10A-5-SCP-102-5	MOS							12-OCT-1983	E2	
	8100435	HRS/MSC	O/C	0					1321		
	REF: AMM 30-20-00	AFL							810		
CHAPTER 31	INDICATING/RECORDING SYSTEMS										
310101 31.010	CLOCK, COCKPIT DIGITAL 811-B	MOS							11-FEB-1982	F3	
	15324	HRS/MSC	O/C	0							
	REF: NO REF	AFL									
CHAPTER 32	LANDING GEAR										
321189U	- REPL SPARE MAIN WHEEL BLT	MOS							26-NOV-1989		
		HRS/MSC	O/C						4427		
	REF:	AFL							2984		
322136 32.400	BLEED BRAKE SYSTEM	MOS							17-JAN-2001	L2	
		HRS/MSC	O/C						7494		
	REF: AMM 32-43-00	AFL							5466		
320678 32.550	DYE PENETRANT CHECK LEFT WHEEL AXLE PKG 2, 3	MOS							26-JUN-2001	L1	
		HRS/MSC	400						7687		
	REF: AMM 5-20-04	AFL							5594		
321178 32.550	DYE PENETRANT CHECK RIGHT WHEEL AXLE PKG 2, 3	MOS							26-JUN-2001	L2	
		HRS/MSC	400						7687		
	REF: AMM 5-20-04	AFL							5594		
+ 322176 32.420	FUNCTIONAL CHECK ANTI-SKID DETECTOR SYSTEM PKG 2, 3	MOS							26-JUN-2001	F3	
		HRS/MSC	400						7687	1	
	REF: AMM 32-44-00	AFL							5594		
+ 322211 32.450	FUNCTIONAL TEST EMERGENCY GEAR EXTENSION PKG 3	MOS							26-JUL-2000	F3	
		HRS/MSC	800						7325		
	REF: AMM 32-30-00	AFL							5360		
+ 322206 32.440	FUNCTIONAL TEST EMERGENCY GEAR EXTENSION CONTROL CABLE PKG 1, 2, 3	MOS							26-JUN-2001	F3	
		HRS/MSC	200						7687	1	
	REF: AMM 32-30-00	AFL							5594		
+ 322191 32.430	FUNCTIONAL TEST LANDING GEAR (NORMAL) PKG 2, 3	MOS							26-JUN-2001	F3	
		HRS/MSC	400						7687		
	REF: AMM 32-30-00	AFL							5594		
+ 322201 32.430	FUNCTIONAL TEST LANDING GEAR FREE FALL PKG 2, 3	MOS							26-JUN-2001	F3	
		HRS/MSC	400						7687		
	REF: See Workcard	AFL							5594		

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
+ 320691 32.020	INSPECT LEFT MAIN GEAR/WELL (A) PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594	L1 1.5	
	REF: AMM WCF 32.020										
+ 320201 32.0101	INSPECT NOSE GEAR (A) PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594	L3 1.5	
	REF: AMM WCF 32.0101										
+ 320206 32.0102	INSPECT NOSE GEAR (B) PKG 2, 3	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594	L3	
	REF: AMM WCF 32.0202										
+ 322156 32.410	INSPECT/CLEAN LEFT ANTI-SKID DETECTOR PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594	L1 1	
	REF: AMM 5-20-04										
+ 322171 32.410	INSPECT/CLEAN RIGHT ANTI-SKID DETECTOR PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594	L2 1	
	REF: AMM 5-20-04										
320607 32.570	LUBRICATE LEFT ACTUATOR BOLTS PKG 2, 3	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594	L1	
	REF: AMM WCF 32.570										
321107 32.570	LUBRICATE RIGHT ACTUATOR BOLTS PKG 2, 3	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594	L2	
	REF: AMM WCF 32.570										
+ 322174 32.425	OPERATIONAL CHECK ANTI-SKID LIGHTS PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594	F3 .5	
	REF: AMM 32-44-00										
320686 32.180	REPLACE LEFT MAIN WHEEL BOLTS	MOS HRS/MSC AFL	O/C						09-NOV-1996 5951 4589	L1	
	REF: NO REF										
321186 32.180	REPLACE RIGHT MAIN WHEEL BOLTS	MOS HRS/MSC AFL	O/C						09-NOV-1996 5951 4589	L2	
	REF: NO REF										
320186 32.150	RIG STEERING SYSTEM	MOS HRS/MSC AFL	C/C						11-FEB-1982	L3	
	REF: AMM 32-50-00										

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
320621 32.220	AXLE, PISTON ROD FORK/ LEFT ES12908-503 SN-UNKNOWN REF: AMM 32-20-01	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	L1	
321121 32.220	AXLE, PISTON ROD FORK/ RIGHT ES12908-504 SN-UNKNOWN REF: AMM 32-20-01	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	L2	
321611 32.350	BOTTLE, EMERGENCY STORAGE 3753015-501 07510A1 REF: AMM 32-30-12	MOS HRS/MSC AFL	288	0						11-FEB-1982	LIFE LIMIT 11-FEB-2006 F5 1	
+ 321616 32.350	CHECK LANDING GEAR EMERGENCY SYSTEM PRESSURE PKG 2, 3 REF: AMM 12-10-04	MOS HRS/MSC AFL	400							26-JUN-2001 7687 5594	F5	
+ 321613 32.350	HYDROSTATIC TEST REF: AMM 32-30-12	MOS HRS/MSC AFL	36							26-OCT-1999 6961 5135	26-OCT-2002 F5	
320171 32.240	BRACE ASSEMBLY, DRAG NOSE GEAR PN SN-UNKNOWN REF: AMM 32-20-02	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	L3	
320173 32.240	ADJUST PRELOAD REF: AMM 32-20-02	MOS HRS/MSC AFL	C/C							11-FEB-1982	L3	
320611 32.230	BRACE ASSEMBLY, SIDE/JURY LEFT MAIN GEAR EA1681-503 SN-UNKNOWN REF: AMM 32-10-02	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	L1	
320616 32.230	ADJUST LEFT JURY BRACE PRELOAD REF: AMM 32-10-02	MOS HRS/MSC AFL	C/C							11-FEB-1982	L1	
321111 32.230	BRACE ASSEMBLY, SIDE/JURY RIGHT MAIN GEAR EA1681-503 SN-UNKNOWN REF: AMM 32-10-02	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	L2	
321116 32.230	ADJUST RIGHT JURY BRACE PRELOAD REF: AMM 32-10-02	MOS HRS/MSC AFL	C/C							11-FEB-1982	L2	

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
320232 32.600	BRACKET, LOWER STEERING NOSE GEAR A0122360300-001 SN-UNKNOWN REF: AMM 32-50-08	MOS HRS/MSC AFL	O/C						22-FEB-2000 7107 5232		L3	
+ 320238 32.600	INSPECT REF: AMM 32-50-08	MOS HRS/MSC AFL	1600						22-FEB-2000 7107 5232	8707	L3	
SB 911391	SB1124-32-139 LWR STRG SERVICE BULLETIN ASSOCIATED	MOS HRS/MSC AFL	A/R									
320231 32.600	BRACKET, UPPER STEERING NOSE GEAR A01223603000-001 SN-UNKNOWN REF: AMM 32-50-08	MOS HRS/MSC AFL	O/C						22-FEB-2000 7107 5232		L3	
+ 320237 32.600	INSPECT REF: AMM 32-50-08	MOS HRS/MSC AFL	1600						22-FEB-2000 7107 5232	8707	L3	
SB 911390	SB1124-32-139 UPR STRG SERVICE BULLETIN PKG 3 ASSOCIATED	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360	8125		
322113 32.390	BRAKE, LEFT MAIN GEAR 5002805-3 21139-1 REF: AMM 32-43-01	MOS HRS/MSC AFL	O/C	0	0	0			17-JAN-2001 7494 5466		L1 2	
322136 32.400	BLEED BRAKE SYSTEM ASSOCIATED	MOS HRS/MSC AFL	O/C						17-JAN-2001 7494 5466		L2	
+ 322116 32.390	INSPECT/CHECK LEFT BRAKE LININGS PKG 1, 2, 3 REF: AMM 32-43-01	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594		L1 1	
322128 32.390	BRAKE, RIGHT MAIN GEAR 5002805-3 JAN86-531 REF: AMM 32-43-01	MOS HRS/MSC AFL	O/C	0	0	0			17-JAN-2001 7494 5466		L2 2	
322136 32.400	BLEED BRAKE SYSTEM ASSOCIATED	MOS HRS/MSC AFL	O/C						17-JAN-2001 7494 5466		L2	

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
+ 322131 32.390	INSPECT/CHECK RIGHT BRAKE LININGS PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594	L2 1		
322141 32.490	CONTROL BOX, ANTI-SKID 5-823519-503 299 REF: AMM 32-44-01	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5 2		
+ 322176 32.420 ASSOCIATED	FUNCTIONAL CHECK ANTI-SKID DETECTOR SYSTEM PKG 2, 3	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594	F3 1		
320121 32.060	CYLINDER, ACTUATOR NOSE GEAR 5713059-505 0484 REF: AMM 32-30-06	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	L3 \$483. 3		
320646 32.310	CYLINDER, AFT ACTUATING LEFT MAIN GEAR 5713061-505 SN-UNKNOWN REF: AMM 32-30-03	MOS HRS/MSC AFL	O/C						09-JUN-1989 4274 2800	L1 \$443.		
321146 32.310	CYLINDER, AFT ACTUATING RIGHT MAIN GEAR 5713061-505 0704 REF: AMM 32-30-03	MOS HRS/MSC AFL	O/C	0					13-NOV-1995 5718 4397	L2 \$443.		
320641 32.300	CYLINDER, FORWARD ACTUATING LEFT MAIN GEAR 5713061-505 0878 REF: AMM 32-30-03	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	L1 \$443.		
321141 32.300	CYLINDER, FORWARD ACTUATING RIGHT MAIN GEAR 5713061-505 0856 REF: AMM 32-30-03	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	L2 \$443.		
320181 32.140	CYLINDER, STEERING ACTUATING LEFT 4713096-509 1L31 REF: AMM 32-50-02	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	L3 5		
320184 32.140	CYLINDER, STEERING ACTUATING RIGHT 4713096-509 1L27 REF: AMM 32-50-02	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	L3 5		
320651 32.260	CYLINDER, UNLOCK LEFT MAIN GEAR 4713058-505 1057 REF: AMM 32-30-05	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	L1		

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L



AIRCRAFT Status Report

Aircraft Model - 1124 WESTWIND
 Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
 A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
321151 32.260	CYLINDER, UNLOCK RIGHT MAIN GEAR 4713058-505 1091 REF: AMM 32-30-05	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	L2	
320126 32.070	CYLINDER, UPLOCK NOSE GEAR 4713005-501 0567 REF: AMM 32-30-08	MOS HRS/MSC AFL	O/C		0			06/08/1995	08-DEC-1994 5526 4218	L3	
322151 32.410	DETECTOR, ANTI-SKID LEFT MAIN GEAR 5-713513-503 200 REF: AMM 32-44-06	MOS HRS/MSC AFL	O/C	0					13-JUL-1988 3978 2511	L1 \$1064. 1	
+ 322176 32.420 ASSOCIATED	FUNCTIONAL CHECK ANTI-SKID DETECTOR SYSTEM PKG 2, 3 REF: AMM 32-44-00	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594	F3 1	
+ 322156 32.410 ASSOCIATED	INSPECT/CLEAN LEFT ANTI-SKID DETECTOR PKG 1, 2, 3 REF: AMM 5-20-04	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594	L1 1	
+ 322174 32.425 ASSOCIATED	OPERATIONAL CHECK ANTI-SKID LIGHTS PKG 1, 2, 3 REF: AMM 32-44-00	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594	F3 .5	
322166 32.410	DETECTOR, ANTI-SKID RIGHT MAIN GEAR 5-713513-504 553 REF: AMM 32-44-06	MOS HRS/MSC AFL	O/C	0					17-DEC-1983 1454 878	L2 \$1064. 1	
+ 322176 32.420 ASSOCIATED	FUNCTIONAL CHECK ANTI-SKID DETECTOR SYSTEM PKG 2, 3 REF: AMM 32-44-00	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594	F3 1	
+ 322171 32.410 ASSOCIATED	INSPECT/CLEAN RIGHT ANTI-SKID DETECTOR PKG 1, 2, 3 REF: AMM 5-20-04	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594	L2 1	
+ 322174 32.425 ASSOCIATED	OPERATIONAL CHECK ANTI-SKID LIGHTS PKG 1, 2, 3 REF: AMM 32-44-00	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594	F3 .5	
322111 32.380	FUSE, BRAKE HYDRAULIC LEFT 3-713047 1797 REF: AMM 32-43-04	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	W1	

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
322126		FUSE, BRAKE HYDRAULIC RIGHT							W2
	32.380	3-71 3047	MOS					11-FEB-1982	
		3371	HRS/MSC	O/C	0				
		REF: AMM 32-43-04	AFL						
320601		GEAR ASSEMBLY, MAIN LEFT							L1
	32.210	400-144-511	MOS					11-FEB-1982	
		1L195	HRS/MSC	O/C	0				
		REF: AMM 32-10-01	AFL						
320631		CHECK MAIN GEAR PARALLELISM							L1
	32.470		MOS					11-FEB-1982	
			HRS/MSC	C/C					
		REF: AMM 32-10-01	AFL						
320634		CHECK LEFT MAIN GEAR CLEARANCE							L1
	32.480		MOS					11-FEB-1982	
			HRS/MSC	C/C					
		REF: AMM 32-10-01	AFL						
+ 322211		FUNCTIONAL TEST EMERGENCY GEAR EXTENSION							F3
	32.450	PKG 3	MOS					26-JUL-2000	
	ASSOCIATED		HRS/MSC	800				7325	
		REF: AMM 32-30-00	AFL					5360	
+ 322206		FUNCTIONAL TEST EMERGENCY GEAR EXTENSION CONTROL CABLE							F3
	32.440	PKG 1, 2, 3	MOS					26-JUN-2001	
	ASSOCIATED		HRS/MSC	200				7687	1
		REF: AMM 32-30-00	AFL					5594	
+ 322191		FUNCTIONAL TEST LANDING GEAR (NORMAL)							F3
	32.430	PKG 2, 3	MOS					26-JUN-2001	
	ASSOCIATED		HRS/MSC	400				7687	
		REF: AMM 32-30-00	AFL					5594	
+ 322201		FUNCTIONAL TEST LANDING GEAR FREE FALL							F3
	32.430	PKG 2, 3	MOS					26-JUN-2001	
	ASSOCIATED		HRS/MSC	400				7687	
		REF: See Workcard	AFL					5594	
320606		LUBRICATE LEFT MAIN GEAR							L1
	32.030	PKG 1, 2, 3	MOS					26-JUN-2001	
			HRS/MSC	200				7687	.5
		REF: AMM 12-20-00	AFL					5594	
320636		SERVICE LEFT MAIN GEAR SHOCK STRUT							L1
	32.040	PKG 2, 3	MOS					26-JUN-2001	
			HRS/MSC	400				7687	2
		REF: AMM 12-10-04	AFL					5594	
SB 951030		SL WW-24103 L/H SERVICE BULLETIN							L1
	ASSOCIATED		MOS						
			HRS/MSC	A/R					
		REF:	AFL						
		Method of Compliance: OPEN							

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
SB	950941	SLWW-2494 REV 3 LMG BOLTS SERVICE BULLETIN	MOS				26-JUN-2001	L1	
	ASSOCIATED		HRS/MSC	300			7687	7987	
		REF: See Workcard	AFL				5594		
		Method of Compliance: OPEN							
321101		GEAR ASSEMBLY, MAIN RIGHT						L2	
	32.210	400-144-512	MOS				11-FEB-1982		
		1L195	HRS/MSC	O/C	0				
		REF: AMM 32-10-01	AFL						
321134		CHECK RIGHT MAIN GEAR CLEARANCE						L2	
	32.480		MOS				11-FEB-1982		
			HRS/MSC	C/C					
		REF: AMM 32-10-01	AFL						
+ 322211		FUNCTIONAL TEST EMERGENCY GEAR EXTENSION						F3	
	32.450	PKG 3	MOS				26-JUL-2000		
	ASSOCIATED		HRS/MSC	800			7325		
		REF: AMM 32-30-00	AFL				5360		
+ 322206		FUNCTIONAL TEST EMERGENCY GEAR EXTENSION CONTROL CABLE						F3	
	32.440	PKG 1, 2, 3	MOS				26-JUN-2001		
	ASSOCIATED		HRS/MSC	200			7687	1	
		REF: AMM 32-30-00	AFL				5594		
+ 322191		FUNCTIONAL TEST LANDING GEAR (NORMAL)						F3	
	32.430	PKG 2, 3	MOS				26-JUN-2001		
	ASSOCIATED		HRS/MSC	400			7687		
		REF: AMM 32-30-00	AFL				5594		
+ 322201		FUNCTIONAL TEST LANDING GEAR FREE FALL						F3	
	32.430	PKG 2, 3	MOS				26-JUN-2001		
	ASSOCIATED		HRS/MSC	400			7687		
		REF: See Workcard	AFL				5594		
321106		LUBRICATE RIGHT MAIN GEAR						L2	
	32.030	PKG 1, 2, 3	MOS				26-JUN-2001		
			HRS/MSC	200			7687	.5	
		REF: AMM 12-20-00	AFL				5594		
321136		SERVICE RIGHT MAIN GEAR SHOCK STRUT						L2	
	32.040	PKG 2, 3	MOS				26-JUN-2001		
			HRS/MSC	400			7687	2	
		REF: AMM 12-10-04	AFL				5594		
SB	951031	SL WW-24103 R/H SERVICE BULLETIN						L2	
	ASSOCIATED		MOS						
			HRS/MSC	A/R					
		REF:	AFL						
		Method of Compliance: OPEN							
SB	950942	SLWW-2494 REV 3 RMG BOLTS SERVICE BULLETIN						L2	
	ASSOCIATED		MOS				26-JUN-2001		
			HRS/MSC	300			7687	7987	
		REF: See Workcard	AFL				5594		
		Method of Compliance: OPEN							

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
320101 32.050	NOSE GEAR ASSEMBLY, 400-143-511 1L184 REF: AMM 32-20-01	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	L3	
320179 32.580	INSPECT NOSE STEERING CABLES PKG 3 REF: AMM 32-50-07	MOS HRS/MSC AFL		800					26-JUL-2000 7325 5360	L1	
320120 32.520	INSPECT OUTER STRUT BODY FORGING REF: AMM 32-20-01	MOS HRS/MSC AFL		1200					22-FEB-2000 7107 5232	L3	
320118 32.540	INSPECT/LUBRICATE UPPER/LOWER STRUT BEARINGS BODY REF: AMM 32-20-01	MOS HRS/MSC AFL		24 1200					22-FEB-2000 7107 5232	L3	
320106 32.030	LUBRICATE NOSE GEAR/DOORS PKG 1, 2, 3 REF: AMM 12-20-00	MOS HRS/MSC AFL		200					26-JUN-2001 7687 5594	L3	
320180 32.590	LUBRICATE NOSE STEERING CONTROL CABLES PKG 3 REF: AMM 12-20-00	MOS HRS/MSC AFL		800					26-JUL-2000 7325 5360	L1	
SB 900280 ASSOCIATED	SB WW 24-28A SERVICE BULLETIN REF: See Workcard Method of Compliance: OPEN	MOS HRS/MSC AFL		1200					22-FEB-2000 7107 5232	L3	
320116 32.040	SERVICE SHOCK STRUT PKG 2, 3 REF: AMM 12-10-04	MOS HRS/MSC AFL		400					26-JUN-2001 7687 5594	L3	
320172 32.240	TEST DRAG BRACE DOWNLOCK TENSION PKG 3 REF: AMM 32-20-02	MOS HRS/MSC AFL		800					26-JUL-2000 7325 5360	L3	
+ 320110 32.560	X-RAY INSPECT NOSE GEAR SHAFT AND DOOR ASSEMBLIES REF: AMM 5-10-00	MOS HRS/MSC AFL		60 5000					16-JUN-1997 6135 4707	L3	
321603 32.200	SELECTOR, GEAR VALVE 713025-501 IL-41 REF: NO REF	MOS HRS/MSC AFL	O/C		0			06/09/1995	09-DEC-1994 5526 4218	F3	

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
320661	SWITCH, DOWNLOCK LEFT MAIN GEAR										L1	
32.280	4-823051	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C	0								
	REF: NO REF	AFL										
320663	ADJUST										L1	
32.280		MOS								11-FEB-1982		
		HRS/MSC	C/C									
	REF: AMM 32-60-00	AFL										
320131	SWITCH, DOWNLOCK NOSE GEAR										L3	
32.080	4-823012-501	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C	0								
	REF: AMM 32-60-00	AFL										
320133	ADJUST										L3	
32.080		MOS								11-FEB-1982		
		HRS/MSC	C/C									
	REF: AMM 32-60-00	AFL										
321161	SWITCH, DOWNLOCK RIGHT MAIN GEAR										L2	
32.280	4-823051	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C	0								
	REF: NO REF	AFL										
321163	ADJUST										L2	
32.280		MOS								11-FEB-1982		
		HRS/MSC	C/C									
	REF: AMM 32-60-00	AFL										
320666	SWITCH, GROUND CONTACT LEFT MAIN GEAR										L1	
32.290	4-823051	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C	0								
	REF: NO REF	AFL										
320668	ADJUST										L1	
32.290		MOS								11-FEB-1982		
		HRS/MSC	C/C									
	REF: AMM 32-60-00	AFL										
320141	SWITCH, GROUND CONTACT NOSE GEAR										L3	
32.100	4-823053-501	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C	0								
	REF: See Workcard	AFL										
320143	ADJUST										L3	
32.100		MOS								11-FEB-1982		
		HRS/MSC	C/C									
	REF: AMM 32-60-00	AFL										
321166	SWITCH, GROUND CONTACT RIGHT MAIN GEAR										L2	
32.290	4-823024-505	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C	0								
	REF: See Workcard	AFL										

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
321168 32.290	ADJUST	MOS HRS/MSC AFL	C/C						11-FEB-1982	L2	
	REF: AMM 32-60-00										
320656 32.270	SWITCH, UPLOCK LEFT MAIN GEAR 3-823003	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	L1	
	SN-UNKNOWN REF: NO REF										
320658 32.270	ADJUST	MOS HRS/MSC AFL	C/C						11-FEB-1982	L1	
	REF: AMM 32-60-00										
320136 32.090	SWITCH, UPLOCK NOSE GEAR 3-823003	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	L3	
	SN-UNKNOWN REF: AMM 32-60-00										
320138 32.090	ADJUST	MOS HRS/MSC AFL	C/C						11-FEB-1982	L3	
	REF: AMM 32-60-00										
321156 32.270	SWITCH, UPLOCK RIGHT MAIN GEAR 3-823003	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	L2	
	SN-UNKNOWN REF: NO REF										
321158 32.270	ADJUST	MOS HRS/MSC AFL	C/C						11-FEB-1982	L2	
	REF: AMM 32-60-00										
320681 32.180	TIRE, LEFT MAIN GEAR 249K83-3	MOS HRS/MSC AFL	O/C	0					09-NOV-1996 5951 4589	L1 2	
	SN-UNKNOWN REF: AMM 32-41-00										
321181 32.190	TIRE, RIGHT MAIN GEAR 249K83-3	MOS HRS/MSC AFL	O/C	0					09-NOV-1996 5951 4589	L2 2	
	SN-UNKNOWN REF: AMM 32-41-00										
320161 32.110	TIRE, LEFT NOSE GEAR 164F43-2	MOS HRS/MSC AFL	O/C	0					22-NOV-1995 5720 4401	L3	
	31162139 REF: AMM 32-42-00										
320166 32.120	TIRE, RIGHT NOSE GEAR 164F43-2	MOS HRS/MSC AFL	O/C	0					29-NOV-1995 5720 4401	L3	
	22051064 REF: AMM 32-42-00										

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
320626 32.250	UPLOCK, LEFT MAIN GEAR 5-173057-501 SN-UNKNOWN REF: AMM 32-32-04	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	L1	
321126 32.250	UPLOCK, RIGHT MAIN GEAR 5-173057-502 SN-UNKNOWN REF: AMM 32-30-04	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	L2	
320176 32.130	VALVE ASSEMBLY, STEERING BA1801-2 1L185 REF: AMM 32-50-01	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	L3	
322146 32.500	VALVE, ANTI-SKID CONTROL LEFT 5723578-1 313A REF: AMM 32-44-02	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5	
322149 32.500	CLEAN FILTERS REF: AMM 32-41-00	MOS HRS/MSC AFL	1200						22-FEB-2000 7107 5232	8307	F5	
+ 322176 32.420 ASSOCIATED	FUNCTIONAL CHECK ANTI-SKID DETECTOR SYSTEM PKG 2, 3 REF: AMM 32-44-00	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594		F3 1	
322161 32.500	VALVE, ANTI-SKID CONTROL RIGHT 5723578-1 503A REF: AMM 32-44-02	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5	
322169 32.500	CLEAN FILTERS REF: AMM 32-41-00	MOS HRS/MSC AFL	1200						22-FEB-2000 7107 5232	8307	F5	
+ 322176 32.420 ASSOCIATED	FUNCTIONAL CHECK ANTI-SKID DETECTOR SYSTEM PKG 2, 3 REF: AMM 32-44-00	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594		F3 1	
322106 32.370	VALVE, BRAKE SHUTTLE LEFT 4-713066 2752 REF: AMM 32-43-03	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	W1	
322121 32.370	VALVE, BRAKE SHUTTLE RIGHT 4-713066 2775 REF: AMM 32-43-03	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	W2	

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
321606 32.340	VALVE, EMERGENCY GEAR EXTENSION 874521B SN-UNKNOWN REF: AMM 32-30-11	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5	
321601 32.320	VALVE, LANDING GEAR CONTROL 4753036 372 REF: AMM 32-30-01	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F2 \$644. 25	
320177 32.170	VALVE, NOSE STEERING SOLENOID 713557-501 SN-UNKNOWN REF: AMM 32-50-00	MOS HRS/MSC AFL	O/C							11-FEB-1982	L3	
320191 32.160	OPERATIONAL CHECK NOSE STEERING REF: AMM 32-50-00	MOS HRS/MSC AFL	C/C							11-FEB-1982	L3	
322181 32.510	VALVE, PARKING MOTOR 3-713551 L34900 REF: AMM 32-44-03	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5	
+ 322176 32.420 ASSOCIATED	FUNCTIONAL CHECK ANTI-SKID DETECTOR SYSTEM PKG 2, 3 REF: AMM 32-44-00	MOS HRS/MSC AFL		400						26-JUN-2001 7687 5594	F3 1	
322101 32.360	VALVE, POWER BRAKE 5713001-501 617AB REF: AMM 32-43-02	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F2 \$1932. 5	
320221 32.330	VALVE, SHUTTLE NOSE GEAR 4713066 SN-UNKNOWN REF: AMM 32-30-07	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	L3	
320671 32.180	WHEEL HALF, INBOARD LEFT MAIN GEAR 5002806-2 JUN89-537 REF: AMM 32-41-00	MOS HRS/MSC AFL	O/C							09-NOV-1996 5951 4589	L1 1	
320681 32.180 ASSOCIATED	CHANGE LEFT MAIN GEAR TIRE 249K83-3 SN-UNKNOWN REF: AMM 32-41-00	MOS HRS/MSC AFL	O/C	0 0 0						09-NOV-1996 5951 4589	L1 2	
320672 32.180 ASSOCIATED	CHANGE LEFT MAIN GEAR OUTBOARD WHEEL HALF 5002806-2 JUN89-537 REF: AMM 32-41-00	MOS HRS/MSC AFL	O/C							09-NOV-1996 5951 4589	L1 1	

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
320678	DYE PENETRANT CHECK LEFT WHEEL AXLE									L1	
32.550	PKG 2, 3	MOS						26-JUN-2001			
	ASSOCIATED	HRS/MSC	400					7687			
	REF: AMM 5-20-04	AFL						5594			
+ 320691	INSPECT LEFT MAIN GEAR/WELL (A)									L1	
32.020	PKG 1, 2, 3	MOS						26-JUN-2001			
	ASSOCIATED	HRS/MSC	200					7687	1.5		
	REF: AMM WCF 32.020	AFL						5594			
+ 322156	INSPECT/CLEAN LEFT ANTI-SKID DETECTOR									L1	
32.410	PKG 1, 2, 3	MOS						26-JUN-2001			
	ASSOCIATED	HRS/MSC	200					7687	1		
	REF: AMM 5-20-04	AFL						5594			
+ 320676	INSPECT/LUBRICATE LEFT MAIN GEAR INBOARD WHEEL BEARINGS									L1	
32.180	PKG 1, 2, 3	MOS						26-JUN-2001			
	ASSOCIATED	HRS/MSC	200					7687	1		
	REF: AMM 32-41-00	AFL						5594			
+ 322174	OPERATIONAL CHECK ANTI-SKID LIGHTS									F3	
32.425	PKG 1, 2, 3	MOS						26-JUN-2001			
	ASSOCIATED	HRS/MSC	200					7687	.5		
	REF: AMM 32-44-00	AFL						5594			
320686	REPLACE LEFT MAIN WHEEL BOLTS									L1	
32.180		MOS						09-NOV-1996			
	ASSOCIATED	HRS/MSC	O/C					5951			
	REF: NO REF	AFL						4589			
321171	WHEEL HALF, INBOARD RIGHT MAIN GEAR									L2	
32.190	5002806-2	MOS						09-NOV-1996			
	MAR84-662	HRS/MSC	O/C					5951	1		
	REF: AMM 32-41-00	AFL						4589			
321181	CHANGE RIGHT MAIN GEAR TIRE									L2	
32.190	249K83-3	MOS			0			09-NOV-1996			
	ASSOCIATED	HRS/MSC	O/C		0			5951	2		
	REF: AMM 32-41-00	AFL			0			4589			
321172	CHANGE RIGHT MAIN GEAR OUTBOARD WHEEL HALF									L2	
32.190	5002806-2	MOS						09-NOV-1996			
	ASSOCIATED	HRS/MSC	O/C					5951	1		
	MAR84-662	HRS/MSC	O/C					5951	1		
	REF: AMM 32-41-00	AFL						4589			
321178	DYE PENETRANT CHECK RIGHT WHEEL AXLE									L2	
32.550	PKG 2, 3	MOS						26-JUN-2001			
	ASSOCIATED	HRS/MSC	400					7687			
	REF: AMM 5-20-04	AFL						5594			
+ 322171	INSPECT/CLEAN RIGHT ANTI-SKID DETECTOR									L2	
32.410	PKG 1, 2, 3	MOS						26-JUN-2001			
	ASSOCIATED	HRS/MSC	200					7687	1		
	REF: AMM 5-20-04	AFL						5594			

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
					TSN	TSO	TSR	TSI	ADJ				
+ 321176		INSPECT/LUBRICATE RIGHT MAIN GEAR INBOARD WHEEL BEARINGS										L2	
	32.180	PKG 1, 2, 3	MOS							26-JUN-2001			
		REF: AMM 32-41-00	HRS/MSC	200						7687		1	
			AFL							5594			
+ 322174		OPERATIONAL CHECK ANTI-SKID LIGHTS										F3	
	32.425	PKG 1, 2, 3	MOS							26-JUN-2001			
	ASSOCIATED		HRS/MSC	200						7687		.5	
		REF: AMM 32-44-00	AFL							5594			
321186		REPLACE RIGHT MAIN WHEEL BOLTS										L2	
	32.180		MOS							09-NOV-1996			
	ASSOCIATED		HRS/MSC	O/C						5951			
		REF: NO REF	AFL							4589			
320672		WHEEL HALF, OUTBOARD LEFT MAIN GEAR										L1	
	32.180	5002806-2	MOS							09-NOV-1996			
		JUN89-537	HRS/MSC	O/C						5951		1	
		REF: AMM 32-41-00	AFL							4589			
320681		CHANGE LEFT MAIN GEAR TIRE										L1	
	32.180	249K83-3	MOS			0				09-NOV-1996			
	ASSOCIATED	SN-UNKNOWN	HRS/MSC	O/C		0				5951		2	
		REF: AMM 32-41-00	AFL			0				4589			
320678		DYE PENETRANT CHECK LEFT WHEEL AXLE										L1	
	32.550	PKG 2, 3	MOS							26-JUN-2001			
	ASSOCIATED		HRS/MSC	400						7687			
		REF: AMM 5-20-04	AFL							5594			
+ 320691		INSPECT LEFT MAIN GEAR/WELL (A)										L1	
	32.020	PKG 1, 2, 3	MOS							26-JUN-2001			
	ASSOCIATED		HRS/MSC	200						7687		1.5	
		REF: AMM WCF 32.020	AFL							5594			
+ 322156		INSPECT/CLEAN LEFT ANTI-SKID DETECTOR										L1	
	32.410	PKG 1, 2, 3	MOS							26-JUN-2001			
	ASSOCIATED		HRS/MSC	200						7687		1	
		REF: AMM 5-20-04	AFL							5594			
+ 320680		INSPECT/LUBRICATE LEFT MAIN GEAR OUTBOARD WHEEL BEARINGS										L1	
	32.180	PKG 1, 2, 3	MOS							26-JUN-2001			
			HRS/MSC	200						7687			
		REF: AMM 32-41-00	AFL							5594			
+ 322174		OPERATIONAL CHECK ANTI-SKID LIGHTS										F3	
	32.425	PKG 1, 2, 3	MOS							26-JUN-2001			
	ASSOCIATED		HRS/MSC	200						7687		.5	
		REF: AMM 32-44-00	AFL							5594			
320686		REPLACE LEFT MAIN WHEEL BOLTS										L1	
	32.180		MOS							09-NOV-1996			
	ASSOCIATED		HRS/MSC	O/C						5951			
		REF: NO REF	AFL							4589			

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
321172	WHEEL HALF, OUTBOARD RIGHT MAIN GEAR									L2	
32.190	5002806-2	MOS						09-NOV-1996			
	MAR84-662	HRS/MSC	O/C					5951		1	
	REF: AMM 32-41-00	AFL						4589			
321181	CHANGE RIGHT MAIN GEAR TIRE									L2	
32.190	249K83-3	MOS						09-NOV-1996			
ASSOCIATED	SN-UNKNOWN	HRS/MSC	O/C					5951		2	
	REF: AMM 32-41-00	AFL						4589			
321178	DYE PENETRANT CHECK RIGHT WHEEL AXLE									L2	
32.550	PKG 2, 3	MOS						26-JUN-2001			
ASSOCIATED		HRS/MSC	400					7687			
	REF: AMM 5-20-04	AFL						5594			
+ 321191	INSPECT RIGHT MAIN GEAR/WELL (A)									L2	
32.020	PKG 1, 2, 3	MOS						26-JUN-2001			
		HRS/MSC	200					7687		1.5	
	REF: AMM WCF 32.020	AFL						5594			
+ 322171	INSPECT/CLEAN RIGHT ANTI-SKID DETECTOR									L2	
32.410	PKG 1, 2, 3	MOS						26-JUN-2001			
ASSOCIATED		HRS/MSC	200					7687		1	
	REF: AMM 5-20-04	AFL						5594			
321180	INSPECT/LUBRICATE RIGHT MAIN GEAR OUTBOARD WHEEL BEARINGS									L2	
32.180	PKG 1, 2, 3	MOS						26-JUN-2001			
		HRS/MSC	200					7687		1	
	REF: AMM 32-41-00	AFL						5594			
+ 322174	OPERATIONAL CHECK ANTI-SKID LIGHTS									F3	
32.425	PKG 1, 2, 3	MOS						26-JUN-2001			
ASSOCIATED		HRS/MSC	200					7687		.5	
	REF: AMM 32-44-00	AFL						5594			
321186	REPLACE RIGHT MAIN WHEEL BOLTS									L2	
32.180		MOS						09-NOV-1996			
ASSOCIATED		HRS/MSC	O/C					5951			
	REF: NO REF	AFL						4589			
320146	WHEEL, LEFT NOSE GEAR									L3	
32.110	41874	MOS						22-NOV-1995			
	APR66-109	HRS/MSC	O/C			0		5720		4	
	REF: AMM 32-42-00	AFL						4401			
320161	CHANGE NOSE GEAR LEFT TIRE									L3	
32.110	164F43-2	MOS						22-NOV-1995			
ASSOCIATED	31162139	HRS/MSC	O/C			0		5720			
	REF: AMM 32-42-00	AFL						4401			
+ 320156	INSPECT/CLEAN/LUBRICATE BEARINGS									L3	
32.110	PKG 1, 2, 3	MOS						26-JUN-2001			
		HRS/MSC	200					7687		1.5	
	REF: AMM 5-20-01	AFL						5594			

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
320151	WHEEL, RIGHT NOSE GEAR										L3	
32.120	9541874	MOS								29-NOV-1995		
	OCT75-64 1	HRS/MSC	O/C			0				5720	4	
	REF: AMM 32-42-00	AFL								4401		
320166	CHANGE NOSE GEAR RIGHT TIRE										L3	
32.120	164F43-2	MOS								29-NOV-1995		
ASSOCIATED	22051064	HRS/MSC	O/C			0				5720		
	REF: AMM 32-42-00	AFL								4401		
+ 320158	INSPECT/CLEAN/LUBRICATE BEARINGS										L3	
32.120	PKG 1, 2, 3	MOS								26-JUN-2001		
	REF: AMM 5-20-01	HRS/MSC	200							7687	1.5	
		AFL								5594		
CHAPTER 33	LIGHTS											
330226	BATTERY, EMERGENCY LIGHT										F4	
33.100	AD-2058	MOS				0				06-OCT-1998		
	SN-UNKNOWN	HRS/MSC	O/C			0				6520		
	REF: AMM 33-50-00	AFL				0				4889		
330320	INVERTER, LIGHT POWER (CF-38-3)										F2	
33.070	CF-38-3	MOS								11-FEB-1982		
	291	HRS/MSC	O/C			0						
	REF: NO REF	AFL										
330111	LIGHT, TAIL CONE										F1	
33.020	4-823006-501	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C			0						
	REF: AMM 33-40-00	AFL										
330161	LIGHT, ANTI-COLLISION LOWER										F1	
33.030	G-9950-11	MOS						10/28/1989		28-APR-1989	\$635.	
	11709	HRS/MSC	O/C							4240		
	REF: AMM 33-40-00	AFL								2767		
330156	LIGHT, ANTI-COLLISION UPPER										T1	
33.030	G9950-11	MOS				0				26-JUL-2000	\$635.	
	11709	HRS/MSC	O/C			0				7325		
	REF: AMM 33-40-00	AFL				0				5360		
330221	LIGHT, EMERGENCY										F4	
33.090	3-823551-503	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C			0						
	REF: AMM 33-50-00	AFL										
330226	CHANGE EMERGENCY LIGHT BATTERY										F4	
33.100	AD-2058	MOS				0				06-OCT-1998		
ASSOCIATED	SN-UNKNOWN	HRS/MSC	O/C			0				6520		
	REF: AMM 33-50-00	AFL				0				4889		
330228	CHARGE BATTERY										F4	
33.100		MOS	3							06-NOV-2001	06-FEB-2002	
		HRS/MSC	200							7774	7974	
	REF: AMM 12-10-06	AFL								5641		

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
330136 33.060	LIGHT, LANDING LEFT 5-213004-1 SN-UNKNOWN REF: AMM 33-40-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	W1	
330146 33.060	LIGHT, LANDING RIGHT 5-213004-2 SN-UNKNOWN REF: AMM 33-40-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	W2	
330101 33.010	LIGHT, POSITION LEFT WING 301085-1 4224 REF: AMM 33-40-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	W1	
330106 33.010	LIGHT, POSITION RIGHT WING 301085-2 5772 REF: AMM 33-40-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	W2	
330166 33.040	LIGHT, STROBE LEFT WING 31-3172-11 SN-UNKNOWN REF: AMM 33-40-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	W1	
330171 33.040	LIGHT, STROBE RIGHT WING 31-3172-11 SN-UNKNOWN REF: AMM 33-40-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	W2	
330116 33.050	LIGHT, TAXI LEFT 5-823521-1 GE-4587 REF: AMM 33-40-00	MOS HRS/MSC AFL	O/C						30-AUG-1989 4350 2898	L1	
330126 33.050	LIGHT, TAXI RIGHT 5-823521-2 GE-4587 REF: AMM 33-40-00	MOS HRS/MSC AFL	O/C						30-AUG-1989 4350 2898	L2	
330505 33.085	POWER SUPPLY, 60-2799-1 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C						11-FEB-1982	W1	
330241 33.080	POWER SUPPLY, NO. 1 60-2799-1 6701 REF: NO REF	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	W1	
330246 33.080	POWER SUPPLY, NO. 2 60-2799-1 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0					25-APR-1984 1641 1010	W2	

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
330522 33.085	POWER SUPPLY, NO.4 60-2799-1	MOS								11-FEB-1982	W2	
	SN-UNKNOWN REF: NO REF	HRS/MSC AFL	O/C									
330325 33.070	UNIT, LIGHT POWER (CV-38) CV-38	MOS								11-FEB-1982	F2	
	6125 REF: NO REF	HRS/MSC AFL	O/C									
CHAPTER 34 NAVIGATION												
340121 34.060	DRAIN PITOT/STATIC SYSTEM PKG 1, 2, 3	MOS								26-JUN-2001	F2	
	REF: AMM 34-10-00	HRS/MSC AFL	200							7687 5594	1.5	
340111 34.040	LEAK CHECK LEFT PITOT SYSTEM	MOS								26-MAR-1996	F1	
	REF: AMM 34-10-01	HRS/MSC AFL	O/C									
+ 340146 34.050	LEAK CHECK LEFT STATIC SYSTEM	MOS	24							18-JAN-2001	MANDATORY 18-JAN-2003	F1
	REF: AMM 34-10-01	HRS/MSC AFL								7494 5466		
340116 34.040	LEAK CHECK RIGHT PITOT SYSTEM	MOS								11-FEB-1982	F1	
	REF: AMM 34-10-01	HRS/MSC AFL	O/C									
+ 340151 34.050	LEAK CHECK RIGHT STATIC SYSTEM	MOS	24							18-JAN-2001	MANDATORY 18-JAN-2003	F1
	REF: AMM 34-10-01	HRS/MSC AFL								7494 5466		
343141 34.390	SWING CHECK NO.1 COMPASS	MOS								11-FEB-1982	F3	
	REF: AMM 34-20-08	HRS/MSC AFL	O/C									
343186 34.390	SWING CHECK NO.2 COMPASS	MOS								11-FEB-1982	F3	
	REF: AMM 34-20-08	HRS/MSC AFL	O/C									
345101 34.490	ADVISORY, FLIGHT PROFILE 622-4569-001	MOS								11-FEB-1982	F3	
	SN-UNKNOWN REF: NO REF	HRS/MSC AFL	O/C	0								
345629 34.310	ALERTER, AL TITUDE 540-25100-004	MOS								11-FEB-1982	F3	
	SN-UNKNOWN REF: AMM 34-10-03	HRS/MSC AFL	O/C	0								

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
341111 34.071	ALTIMETER, COPILOT 4883778-501 3008 REF: NO REF	MOS HRS/MSC AFL								11-FEB-1982	F3	
+ 340151 34.050 ASSOCIATED	LEAK CHECK RIGHT STATIC SYSTEM REF: AMM 34-10-01	MOS HRS/MSC AFL	24							18-JAN-2001 7494 5466	MANDATORY 18-JAN-2003 F1	
+ 341116 34.071	TEST FAR 91.411 REF:	MOS HRS/MSC AFL	24							18-JAN-2001 7494 5466	MANDATORY 18-JAN-2003 F3	
341101 34.070	ALTIMETER, PILOT 622-3975-003 1323 REF: AMM 34-10-03	MOS HRS/MSC AFL								11-FEB-1982	F3	
+ 340146 34.050 ASSOCIATED	LEAK CHECK LEFT STATIC SYSTEM REF: AMM 34-10-01	MOS HRS/MSC AFL	24							18-JAN-2001 7494 5466	MANDATORY 18-JAN-2003 F1	
+ 341106 34.070	TEST FAR 91.411 REF:	MOS HRS/MSC AFL	24							18-JAN-2001 7494 5466	MANDATORY 18-JAN-2003 F3	
341121 34.075	ALTIMETER, STAND-BY 622-3975-003 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL								11-FEB-1982	F3	
+ 340146 34.050 ASSOCIATED	LEAK CHECK LEFT STATIC SYSTEM REF: AMM 34-10-01	MOS HRS/MSC AFL	24							18-JAN-2001 7494 5466	MANDATORY 18-JAN-2003 F1	
+ 340151 34.050 ASSOCIATED	LEAK CHECK RIGHT STATIC SYSTEM REF: AMM 34-10-01	MOS HRS/MSC AFL	24							18-JAN-2001 7494 5466	MANDATORY 18-JAN-2003 F1	
343176 34.170	ANNUNCIATOR, COMPASS COPILOT PN SN-UNKNOWN REF: AMM 34-20-08	MOS HRS/MSC AFL								11-FEB-1982	F3	
343131 34.170	ANNUNCIATOR, COMPASS PILOT PN SN-UNKNOWN REF: AMM 34-20-08	MOS HRS/MSC AFL								11-FEB-1982	F3	

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
346681 34.640	ANTENNA, #1 VLF 10085-2 6025 REF: AMM 34-60-02	MOS HRS/MSC AFL	O/C	0						03-APR-1989 4215 2745	F5	
347681 34.570	ANTENNA, GLIDESLOPE DMN-25-1 1896 REF: AMM 34-50-01	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F2	
346611 34.350	ANTENNA, NO.1 ADF LOOP 522-3761-001 4428 REF: AMM 34-50-03/04	MOS HRS/MSC AFL	O/C	0						31-JAN-1986 2855 1770	F1	
346131 34.330	ANTENNA, NO.1 ATC TRANSPONDER DMNI-50-6 323 REF: AMM 34-50-06	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F1	
347121 34.360	ANTENNA, NO.1 DME 4-87 3127-501 3234 REF: AMM 34-50-02	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F1 2	
348111 34.660	ANTENNA, NO.1 LRN 42804-000 100-00 1346 REF: AMM 34-60-04	MOS HRS/MSC AFL	O/C	0						11-FEB-1982		
346206 34.550	ANTENNA, NO.1 MARKER BEACON DMN-27-1/A 1919 REF: AMM 34-50-01	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5	
346546 34.580	ANTENNA, NO.1 VOR DMN-4-15-3/D 10987 REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5	
346636 34.350	ANTENNA, NO.2 ADF LOOP 522-3761-001 SN-UNKNOWN REF: AMM 34-50-03/04	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F1	
346136 34.330	ANTENNA, NO.2 ATC TRANSPONDER DMNI-50-6 3259 REF: AMM 34-50-06	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F1	
347621 34.360	ANTENNA, NO.2 DME 4-87 3127-503 3242 REF: AMM 34-50-02	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F1 2	

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
348114 34.700	ANTENNA, NO.2 LRN 42804-000 100-00 SN-UNKNOWN REF: AMM 34-60-04	MOS HRS/MSC AFL							11-FEB-1982		
346216 34.550	ANTENNA, NO.2 MARKER BEACON PN SN-UNKNOWN REF: AMM 34-50-01	MOS HRS/MSC AFL							11-FEB-1982	F5	
346576 34.600	ANTENNA, NO.2 VOR DMN-4-15-3A 10993 REF: NO REF	MOS HRS/MSC AFL							11-FEB-1982	F3	
345626 34.340	ANTENNA, RADIO ALTIMETER RECEIVER 522-4140-001 509 REF: AMM 34-10-04	MOS HRS/MSC AFL							11-FEB-1982	F1	
345621 34.340	ANTENNA, RADIO ALTIMETER TRANSMIT 622-4550-001 459 REF: AMM 34-10-04	MOS HRS/MSC AFL							11-FEB-1982	F1	
345831 34.520	ANTENNA, WEATHER RADAR 622-2504-001 270 REF: AMM WCF 34.520	MOS HRS/MSC AFL						04/19/1993	19-FEB-1993 5222 3870	F2	
344611 34.370	BATTERY, EMERGENCY GYRO POWER SUPPLY 501-1075-05PS823A/T 1186 REF: AMM 34-20-09	MOS HRS/MSC AFL							06-APR-1998 6346 4787	F5 1	
344621 34.370	DEEP CYCLE POWER SUPPLY GNS-500 NAV SYSTEM REF: AMM WCF 34.370	MOS HRS/MSC AFL							06-APR-1998 6346 4787	F5	
+ 344616 34.370	INSPECT EMERGENCY POWER SUPPLY BATTERY/STAND-BY ATTITUDE GYRO REF: AMM NO REF	MOS HRS/MSC AFL		3 200					06-NOV-2001 7774 5641	06-FEB-2002 7974	F5
347626 34.150	BOX, DME DUAL CONTROL PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL							11-FEB-1982	F2 1	
347641 34.580	BOX, HORIZONTAL SITUATION INDICATOR CONTROL 622-4569-001 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL							11-FEB-1982	F4	

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
346551 34.590	BOX, NO.1 VOR CONTROL 622-2899-012 SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL	O/C	0						11-FEB-1982	F3	
346581 34.590	BOX, NO.2 VOR CONTROL DMN-4-15-3/D SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL	O/C	0						11-FEB-1982	F3	
342601 34.100	COMPASS, STAND-BY MAGNETIC 2-883023-501 1A234 REF: NO REF	MOS HRSMSC AFL	O/C	0						11-FEB-1982	F3	
342611 34.100	SWING CHECK REF: CMM	MOS HRSMSC AFL	O/C							11-FEB-1982	F3	
343113 34.440	COMPENSATOR, NO.1 656767 81082033 REF: NO REF	MOS HRSMSC AFL	O/C	0 0						11-FEB-1982		
343158 34.440	COMPENSATOR, NO.2 656767 81092117 REF: NO REF	MOS HRSMSC AFL	O/C	0 0						11-FEB-1982		
344131 34.220	COMPUTER, FLIGHT COPILOT 622-5224-005 SN-UNKNOWN REF: AMM 4-20-04/21-04	MOS HRSMSC AFL	O/C	0						11-FEB-1982	F2	
343631 34.220	COMPUTER, FLIGHT PILOT 622-5224-004 5128 REF: AMM 4-20-04/21-04	MOS HRSMSC AFL	O/C	0						11-FEB-1982	F2 1	
340201 34.460	COMPUTER, NAVIGATION 622-5107-001 SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL	O/C	0 0						11-FEB-1982	F3	
343671 34.480	COMPUTER, NO.1 AIR DATA 622-5465-214 1080 REF: AMM 22-20-00	MOS HRSMSC AFL	O/C							26-MAR-1996	F3	
+ 343672 34.480	CALIBRATE FAR 91.411 REF: See Workcard	MOS HRSMSC AFL	24							18-JAN-2001 7494 18-JAN-2003 5466	F3	

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
341604 34.410	COMPUTER, SAT TAS 630-30980-135 1589 REF: NO REF	MOS HRS/MSC AFL	O/C	0 0					11-FEB-1982	F3	
346616 34.260	CONTROL, NO.1 ADF 622-4526-003 10601 REF: NO REF	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3	
346641 34.260	CONTROL, NO.2 ADF PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3	
346251 34.470	CONTROLLER, NO.1 NAVIGATION 622-4524-079 7898 REF: NO REF	MOS HRS/MSC AFL	O/C	5012 3648				14-JAN-1992 5012 3648		F3	
346261 34.470	CONTROLLER, NO.2 NAVIGATION 622-4524-079 7863 REF: NO REF	MOS HRS/MSC AFL	O/C	0 0 0			07/15/1992	15-JAN-1992 5012 3648		F3	
346141 34.540	CONTROLLER, TRANSPONDER 622-4527-011 6475 REF: NO REF	MOS HRS/MSC AFL	O/C	0 0				11-FEB-1982		F4	
346306 34.460	CONVERTER, NAV RECEIVER/VHF POWER 622-2093-001 17233 REF: NO REF	MOS HRS/MSC AFL	O/C	0 0				11-FEB-1982		F3	
347201 34.650	CONVERTER, NO.1 DME SYNCHRO 622-1920-001 SN-UNKNOWN REF: AMM 34-50-02	MOS HRS/MSC AFL	O/C	0 0				11-FEB-1982		F3	
347211 34.650	CONVERTER, NO.2 DME SYNCHRO 622-1920-001 SN-UNKNOWN REF: AMM 34-50-02	MOS HRS/MSC AFL	O/C	0 0				11-FEB-1982		F3	
341096 34.420	CONVERTER, RADIO ALTIMETER 995-29400-112 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0 0				11-FEB-1982		F3	
343641 34.230	COUPLER, NO.1 FLIGHT DIRECTOR MODE 161E-2A SN-UNKNOWN REF: AMM 22-03-06	MOS HRS/MSC AFL	O/C	0				11-FEB-1982		F2	

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
348146 34.740	COUPLER, NO.1 LRN 42807-001 100-001 1585 REF: NO REF	MOS HRS/MSC AFL	O/C	0					11-FEB-1982		
344141 34.230	COUPLER, NO.2 FLIGHT DIRECTOR MODE 161E-2A SN-UNKNOWN REF: AMM 22-03-06	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F2	
348151 34.740	COUPLER, NO.2 LRN 42807-001 100-001 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0					11-FEB-1982		
345833 34.530	DISH, WEATHER RADAR FLAT ANT-318 270 REF: AMM 34-40-01	MOS HRS/MSC AFL	O/C	5222 3870				04/19/1993 5222 3870	19-FEB-1993	F2	
348116 34.670	DISPLAY, NO.1 LRN CONTROL 622-5493-001 040 REF: AMM 34-60-04	MOS HRS/MSC AFL	O/C	0					11-FEB-1982		
348121 34.670	DISPLAY, NO.2 LRN CONTROL 622-5493-001 SN-UNKNOWN REF: AMM 34-60-04	MOS HRS/MSC AFL	O/C	0					11-FEB-1982		
345631 34.300	GENERATOR, TONE (ALERTER) 540-25100-004 SN-UNKNOWN REF: AMM 34-10-03	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3	
343101 34.110	GYRO, NO.1 DIRECTIONAL 622-4176-004 871 REF: AMM 34-20-08	MOS HRS/MSC AFL	O/C		0			04/02/1992 02-OCT-1991 4931 3454		F4	
343106 34.110	BENCH CHECK REF: CMM	MOS HRS/MSC AFL	O/C						11-FEB-1982	F4	
343651 34.200	GYRO, NO.1 VERTICAL 792-6694-001 6381 REF: AMM WCF 34.200	MOS HRS/MSC AFL	O/C	0					06-JAN-1986 2808 1739	F3 2	
343146 34.110	GYRO, NO.2 DIRECTIONAL 2587193-43 81095980 REF: AMM 34-20-08	MOS HRS/MSC AFL	O/C	0					24-SEP-1987 3737 2345	F4	

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
343151 34.110	BENCH CHECK	MOS HRSMSC AFL	O/C							11-FEB-1982	F4	
	REF: CMM											
344151 34.200	GYRO, NO.2 VERTICAL 792-6694-001	MOS HRSMSC AFL	O/C	0						11-FEB-1982	F3	
	SN-UNKNOWN REF: AMM WCF 34.200											
347611 34.140	INDICATOR, DME COPILOT PN	MOS HRSMSC AFL	O/C	0						11-FEB-1982	F3	
	SN-UNKNOWN REF: NO REF											
347111 34.140	INDICATOR, DME PILOT PN	MOS HRSMSC AFL	O/C	0						11-FEB-1982	F3	
	SN-UNKNOWN REF: NO REF											
344101 34.280	INDICATOR, FLIGHT DIRECTOR COPILOT 622-4808-004	MOS HRSMSC AFL	O/C	0						11-FEB-1982	F3	
	SN-UNKNOWN REF: AMM 4-20-01/21-02											
343601 34.280	INDICATOR, FLIGHT DIRECTOR PILOT 622-4808-004	MOS HRSMSC AFL	O/C	0						11-FEB-1982	F3	
	823 REF: AMM 4-20-01/21-02											
341601 34.080	INDICATOR, LEFT MACH/AIRSPEED 622-4382-013	MOS HRSMSC AFL	O/C	0						07-APR-1987 3676 2288	F3	
	1302 REF: NO REF											
341606 34.080	CALIBRATE	MOS HRSMSC AFL	O/C							10-APR-1990 4560 3132	F3	
	REF: CMM											
340111 34.040	LEAKCHECK LEFT PITOT SYSTEM	MOS HRSMSC AFL	O/C							26-MAR-1996	F1	
	REF: AMM 34-10-01											
+ 340146 34.050	LEAKCHECK LEFT STATIC SYSTEM	MOS HRSMSC AFL	24							18-JAN-2001 7494 5466	MANDATORY F1 18-JAN-2003	
	ASSOCIATED											
	REF: AMM 34-10-01											
342090 34.380	INDICATOR, LEFT VERTICAL NAV/SPEED 622-4782-003/VNI-80	MOS HRSMSC AFL	O/C	0						22-OCT-1982 482	F3	
	SN-UNKNOWN REF: NO REF											

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
342101		INDICATOR, LEFT VERTICAL SPEED							F3
	34.090	4883748-1	MOS				11-FEB-1982		\$486.
		640	HRS/MSC	O/C	0				
		REF: AMM 34-10-03	AFL						
342106		BENCH CHECK							F3
	34.090		MOS				11-FEB-1982		
			HRS/MSC	O/C					
		REF: See Workcard	AFL						
+ 340146		LEAK CHECK LEFT STATIC SYSTEM						MANDATORY	F1
	34.050		MOS	24			18-JAN-2001	18-JAN-2003	
		ASSOCIATED	HRS/MSC				7494		
		REF: AMM 34-10-01	AFL				5466		
342801		INDICATOR, NO.1 GYRO ATTITUDE							F3
	34.430	4020531-170	MOS				25-MAR-1991		
		80110830	HRS/MSC	O/C	0		4830		
		REF: NO REF	AFL		0		3441		
347651		INDICATOR, NO.1 HORIZONTAL SITUATION							F3
	34.560	622-4176-004	MOS				10-MAR-1987		
		871	HRS/MSC	O/C	0		3623		
		REF: AMM 4-20-02/21-02	AFL		0		2255		
342811		INDICATOR, NO.2 GYRO ATTITUDE							F3
	34.430	4020531-170	MOS				19-MAR-1991		
		6020225	HRS/MSC	O/C			4827		
		REF: NO REF	AFL				3439		
347655		INDICATOR, NO.2 HORIZONTAL SITUATION							F3
	34.560	622-4176-004	MOS				11-FEB-1982		
		1854	HRS/MSC	O/C	0				
		REF: AMM 4-20-02/21-02	AFL						
340601		INDICATOR, OUTSIDE AIR TEMPERATURE							F3
	34.380	4883753-3	MOS				14-APR-1984		
		64128-13	HRS/MSC	O/C	0		1645		
		REF: NO REF	AFL						
345611		INDICATOR, RADIO ALTIMETER							F3
	34.250	521-29007-203	MOS				11-FEB-1982		
		SN-UNKNOWN	HRS/MSC	O/C	0				
		REF: NO REF	AFL						
343166		INDICATOR, RADIO MAGNETIC COPILOT							F3
	34.160	622-2506-002	MOS				14-DEC-1986		
		1546	HRS/MSC	O/C	0		3484		1
		REF: AMM 34-50-05	AFL				2157		
343121		INDICATOR, RADIO MAGNETIC PILOT							F3
	34.160	622-2506-002	MOS				05-NOV-1986		
		1213	HRS/MSC	O/C	0		3385		1
		REF: AMM 34-50-05	AFL				2098		

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
341056 34.400	INDICATOR, RATE OF CLIMB COPILOT 229-0324-010 SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL			0 0					11-FEB-1982	F3	
341046 34.400	INDICATOR, RATE OF CLIMB PILOT 622-7689-003 166 REF: NO REF	MOS HRSMSC AFL			0					31-MAY-1993 5278 3928	F3	
341611 34.080	INDICATOR, RIGHT MACH/AIRSPEED 883615-513 149 REF: NO REF	MOS HRSMSC AFL			0					11-FEB-1982	F3	
341616 34.080	CALIBRATE REF: CMM VENDOR	MOS HRSMSC AFL								11-FEB-1982	F3	
340116 34.040 ASSOCIATED	LEAK CHECK RIGHT PITOT SYSTEM REF: AMM 34-10-01	MOS HRSMSC AFL								11-FEB-1982	F1	
+ 340151 34.050 ASSOCIATED	LEAK CHECK RIGHT STATIC SYSTEM REF: AMM 34-10-01	MOS HRSMSC AFL	24							18-JAN-2001 7494 5466	MANDATORY 18-JAN-2003 F1	
342111 34.090	INDICATOR, RIGHT VERTICAL SPEED RCS-60-IL-10 MD12158 REF: AMM 34-10-03	MOS HRSMSC AFL			0					11-FEB-1982	F3 \$486.	
342116 34.090	BENCH CHECK REF: See Workcard	MOS HRSMSC AFL								11-FEB-1982	F3	
+ 340151 34.050 ASSOCIATED	LEAK CHECK RIGHT STATIC SYSTEM REF: AMM 34-10-01	MOS HRSMSC AFL	24							18-JAN-2001 7494 5466	MANDATORY 18-JAN-2003 F1	
341605 34.410	INDICATOR, SAT TAS 622-2294-002 SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL			0 0					11-FEB-1982	F3	
344601 34.290	INDICATOR, STAND-BY HORIZON 501-1105-03 6010212 REF: AMM 34-20-09	MOS HRSMSC AFL			0					18-NOV-1984 2085 1284	F3	

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
345801 34.500	INDICATOR, WEATHER RADAR 622-4331-001 176 REF: AMM WCF 34.500	MOS HRS/MSC AFL	O/C		0				09/18/1993 18-MAR-1993 5231 3880	F3	
347101 34.270	INTERROGATOR, NO.1 DME 622-1233-001 13710 REF: AMM 34-50-02	MOS HRS/MSC AFL	O/C		0				11-FEB-1982	F2	
347601 34.270	INTERROGATOR, NO.2 DME 622-1233-001 15123 REF: AMM 34-50-02	MOS HRS/MSC AFL	O/C		0				11-FEB-1982	F2	
343663 34.190	PANEL, NO.1 FLIGHT GUIDANCE 622-2313-029 2661 REF: AMM 34-21-03	MOS HRS/MSC AFL	O/C		0 0				11-FEB-1982	F3	
343665 34.190	PANEL, NO.2 FLIGHT GUIDANCE 622-2265-030 SN-UNKNOWN REF: AMM 34-21-03	MOS HRS/MSC AFL	O/C		0 0				11-FEB-1982	F3	
345811 34.540	PANEL, WEATHER RADAR CONTROL DCP-320 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C		0 0				11-FEB-1982	F3	
340126 34.020	PORT, LEFT HEATED STATIC 3-883053-501 SN-UNKNOWN REF: AMM 34-10-01	MOS HRS/MSC AFL	O/C		0				11-FEB-1982	F1	
340121 34.060 ASSOCIATED	DRAIN PITOT/STATIC SYSTEM PKG 1, 2, 3 REF: AMM 34-10-00	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594	F2 1.5	
+ 340146 34.050 ASSOCIATED	LEAK CHECK LEFT STATIC SYSTEM REF: AMM 34-10-01	MOS HRS/MSC AFL	24						18-JAN-2001 7494 5466	MANDATORY F1 18-JAN-2003	
340131 34.030	PORT, LEFT UNHEATED STATIC 4-883050 SN-UNKNOWN REF: AMM 34-10-01	MOS HRS/MSC AFL	O/C		0				11-FEB-1982	F1	
340121 34.060 ASSOCIATED	DRAIN PITOT/STATIC SYSTEM PKG 1, 2, 3 REF: AMM 34-10-00	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594	F2 1.5	

COPYRIGHT 2001 CAMP SYSTEMS INT'L

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
+ 340 146	LEAK CHECK LEFT STATIC SYSTEM									MANDATORY	F1
34.050		MOS	24					18-JAN-2001	18-JAN-2003		
	ASSOCIATED	HRS/MSC						7494			
	REF: AMM 34-10-01	AFL						5466			
340 136	PORT, RIGHT HEATED STATIC										F1
34.020	3-883053-502	MOS						11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C	0							
	REF: AMM 34-10-01	AFL									
340 121	DRAIN PITOT/STATIC SYSTEM										F2
34.060	PKG 1, 2, 3	MOS						26-JUN-2001			
	ASSOCIATED	HRS/MSC	200					7687		1.5	
	REF: AMM 34-10-00	AFL						5594			
+ 340 151	LEAK CHECK RIGHT STATIC SYSTEM									MANDATORY	F1
34.050		MOS	24					18-JAN-2001	18-JAN-2003		
	ASSOCIATED	HRS/MSC						7494			
	REF: AMM 34-10-01	AFL						5466			
340 141	PORT, RIGHT UNHEATED STATIC										F1
34.030	4-883050	MOS						11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C	0							
	REF: AMM 34-10-01	AFL									
340 121	DRAIN PITOT/STATIC SYSTEM										F2
34.060	PKG 1, 2, 3	MOS						26-JUN-2001			
	ASSOCIATED	HRS/MSC	200					7687		1.5	
	REF: AMM 34-10-00	AFL						5594			
+ 340 151	LEAK CHECK RIGHT STATIC SYSTEM									MANDATORY	F1
34.050		MOS	24					18-JAN-2001	18-JAN-2003		
	ASSOCIATED	HRS/MSC						7494			
	REF: AMM 34-10-01	AFL						5466			
340 606	PROBE, OUTSIDE AIR TEMPERATURE										F1
34.380	MS28038-1	MOS						11-FEB-1982			
	9223	HRS/MSC	O/C	0							
	REF: NO REF	AFL									
347 659	PROGRAMMER, RNS										F1
34.740	622-5110-001	MOS						11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C	0							
	REF: NO REF	AFL		0							
346 601	RECEIVER, NO.1 ADF										F4
34.130	622-2362-001	MOS						11-FEB-1982			
	8945	HRS/MSC	O/C	0						1	
	REF: AMM 34-50-03/04	AFL									
346 301	RECEIVER, NO.1 VHF NAVIGATION										F3
34.450	622-0876-001	MOS						11-FEB-1982			
	16803	HRS/MSC	O/C	0							
	REF: AMM 34-50-01	AFL		0							

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
346536 34.580	RECEIVER, NO.1 VOR PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3	
346626 34.130	RECEIVER, NO.2 ADF 622-2362-001 8946 REF: AMM 34-50-03/04	MOS HRS/MSC AFL	O/C	0						06-APR-1985 2317 1423	F4	
346311 34.450	RECEIVER, NO.2 VHF NAVIGATION 622-0876-001 SN-UNKNOWN REF: AMM 34-50-01	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3	
346566 34.600	RECEIVER, NO.2 VOR PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3	
345608 34.420	RECEIVER, RADIO ALTIMETER 622-3201-001 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3	
346201 34.540	RECEIVER/TRANSMITTER, MARKER BEACON PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3	
345601 34.240	RECEIVER/TRANSMITTER, RADIO ALTIMETER 622-3201-001 3652 REF: AMM 34-10-04	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F2	
345821 34.510	RECEIVER/TRANSMITTER, WEATHER RADAR 622-4022-001 2126 REF: AMM WCF 34.510	MOS HRS/MSC AFL	O/C							12-APR-1995 5613 4281	F3	
344161 34.210	SELECTOR, MODE COPILOT 614E-23R SN-UNKNOWN REF: AMM 34-20-03	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3	
343661 34.210	SELECTOR, MODE PILOT 614E-20R SN-UNKNOWN REF: AMM 34-20-03	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3 1	
343677 34.490	SELECTOR, NO.1 REMOTE 622-4178-003 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3	

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
344177 34.490	SELECTOR, NO.2 REMOTE 622-4178-003	MOS								11-FEB-1982		
	SN-UNKNOWN REF: NO REF	HRS/MSC AFL	O/C	0								
344121 34.180	SENSOR, RATE-OF-TURN COPILOT 622-0181-001	MOS								11-FEB-1982	F3	
	SN-UNKNOWN REF: AMM WCF 34.180	HRS/MSC AFL	O/C	0								
343621 34.180	SENSOR, RATE-OF-TURN PILOT 772-5140-001	MOS								05-OCT-1983	F3	
	3984 REF: AMM WCF 34.180	HRS/MSC AFL	O/C	0						1300 794		
346101 34.320	TRANSPONDER, NO.1 ATC 622-1270-001	MOS							06/11/1996	11-DEC-1995	F3	
	9608 REF: AMM 34-50-06	HRS/MSC AFL	O/C							5726 4410	1	
346106 34.320	BENCH CHECK	MOS								25-SEP-1991	F3	
	REF: See Workcard	HRS/MSC AFL	O/C									
+ 346111 34.320	TEST FAR 91.413	MOS	24							18-JAN-2001	MANDATORY 18-JAN-2003	F3
	REF: CMM FAR 91.413	HRS/MSC AFL								7494 5466		
346116 34.320	TRANSPONDER, NO.2 ATC 622-1270-001	MOS								11-FEB-1982	F3	
	13112 REF: AMM 34-50-06	HRS/MSC AFL	O/C	0							3	
346121 34.320	BENCH CHECK	MOS								25-SEP-1991	F3	
	REF: CMM VENDOR MM	HRS/MSC AFL	O/C								4	
+ 346126 34.320	TEST FAR 91.413	MOS	24							18-JAN-2001	MANDATORY 18-JAN-2003	F3
	REF: CMM FAR 91.413	HRS/MSC AFL								7494 5466		
340101 34.010	TUBE, LEFT PITOT 4883049-1	MOS								11-FEB-1982	F1	
	59912 REF: AMM 34-10-01	HRS/MSC AFL	O/C	0								
340121 34.060	DRAIN PITOT/STATIC SYSTEM PKG 1, 2, 3	MOS								26-JUN-2001	F2	
ASSOCIATED	REF: AMM 34-10-00	HRS/MSC AFL	200							7687 5594	1.5	

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
340111	LEAK CHECK LEFT PITOT SYSTEM										F1	
34.040		MOS							26-MAR-1996			
	ASSOCIATED	HRS/MSC	O/C									
	REF: AMM 34-10-01	AFL										
340106	TUBE, RIGHT PITOT										F1	
34.010	4883049-1	MOS							11-FEB-1982			
	58348	HRS/MSC	O/C	0								
	REF: AMM 34-10-01	AFL										
340121	DRAIN PITOT/STATIC SYSTEM										F2	
34.060	PKG 1, 2, 3	MOS							26-JUN-2001			
	ASSOCIATED	HRS/MSC	200						7687		1.5	
	REF: AMM 34-10-00	AFL							5594			
340116	LEAK CHECK RIGHT PITOT SYSTEM										F1	
34.040		MOS							11-FEB-1982			
	ASSOCIATED	HRS/MSC	O/C									
	REF: AMM 34-10-01	AFL										
346648	UNIT, CONTROL DISPLAY PROCESS										F3	
34.460	622-2899-016	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C	0								
	REF: NO REF	AFL		0								
348165	UNIT, FMS AUXILIARY EQUIPMENT										F3	
34.770	622-5615-001/AEU-90	MOS						10/27/1989	27-JUL-1989			
	92	HRS/MSC	O/C						4311			
	REF: AMM 34-60-03	AFL							2856			
348160	UNIT, FMS COMPUTER RECEIVER										F3	
34.760	622-5614-020/CRU-90	MOS							12-FEB-1990			
	52	HRS/MSC	O/C						4504			
	REF: AMM 34-60-03	AFL							3073			
348170	UNIT, FMS CONTROL DISPLAY										F3	
34.790	622-5611-001/CDU-90	MOS							11-FEB-1982			
	040	HRS/MSC	O/C	0								
	REF: AMM 34-60-03	AFL										
348175	UNIT, FMS DATA ENTRY										F3	
34.780	622-5613-001/DEU-90	MOS							16-AUG-1984			
	183	HRS/MSC	O/C	0					1890			
	REF: NO REF	AFL										
348155	UNIT, FMS RADIO TUNING										F3	
34.750	622-5612-007/RTU-90	MOS							10-MAR-1987			
	50	HRS/MSC	O/C	0					3623			
	REF: AMM 34-60-03	AFL							2255			
348136	UNIT, NO. 1 LRN EQUIPMENT										F3	
34.690	622-5494-001	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C	0								
	REF: AMM 34-60-04	AFL		0								

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
348126 34.680	UNIT, NO.1 LRN RECEIVER COMP 622-5492-001 SN-UNKNOWN REF: AMM 34-60-04	MOS HRS/MSC AFL		O/C	0				11-FEB-1982		
348141 34.690	UNIT, NO.2 LRN EQUIPMENT 622-5494-001 SN-UNKNOWN REF: AMM 34-60-04	MOS HRS/MSC AFL		O/C	0				11-FEB-1982		
348131 34.720	UNIT, NO.2 LRN RECEIVER COMP 622-5494-001 SN-UNKNOWN REF: AMM 34-60-04	MOS HRS/MSC AFL		O/C	0				11-FEB-1982		
346651 34.610	UNIT, VLF CONTROL DISPLAY 10060-6 2579 REF: AMM 34-10-06	MOS HRS/MSC AFL		O/C	0			24-SEP-1987 3737 2345		F3	
346671 34.630	UNIT, VLF OPTIONAL EQUIPMENT 10600-2-210 2695 REF: AMM 34-60-02	MOS HRS/MSC AFL		O/C	0			05-SEP-1989 4355 2904		F3	
346661 34.620	UNIT, VLF RECEIVER COMPUTER 10050-4-4A-3140 1937 REF: AMM 34-60-02	MOS HRS/MSC AFL		O/C	0			05-SEP-1989 4355 2904		F5	
343111 34.120	VALVE, NO.1 FLUX 2594484 81096488 REF: AMM 34-20-01	MOS HRS/MSC AFL		O/C	0			11-FEB-1982		W1	
343156 34.120	VALVE, NO.2 FLUX 2594484 81096489 REF: AMM 34-20-08	MOS HRS/MSC AFL		O/C	0			11-FEB-1982		W2	
CHAPTER 35	OXYGEN										
350101 35.010	CYLINDER, OXYGEN 6350A25-EE-Z 49928W REF: AMM 35-00-00	MOS HRS/MSC AFL	288		0			04-FEB-1982	LIFE LIMIT 04-FEB-2006	F2	
350106 35.010	HYDROSTATIC TEST REF: AMM 35-00-00	MOS HRS/MSC AFL	36 3000					26-JUL-2000 7325 5360	26-JUL-2003 10325	F2	
350141 35.040	GAUGE, OXYGEN PRESSURE PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL		O/C	0			11-FEB-1982		F3	

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
350126 35.040	INDICATOR, OXYGEN DISCHARGE 118082	MOS									F1
	SN-UNKNOWN REF: NO REF	HRS/MSC AFL	O/C	0					11-FEB-1982		
350181 35.080	MASK, PASSENGER OXYGEN L1 PN	MOS									F4
	SN-UNKNOWN REF: NO REF	HRS/MSC AFL	O/C	0					11-FEB-1982		
350191 35.080	MASK, PASSENGER OXYGEN L2 PN	MOS									F4
	SN-UNKNOWN REF: NO REF	HRS/MSC AFL	O/C	0					11-FEB-1982		
350201 35.090	MASK, PASSENGER OXYGEN R1 PN	MOS									F4
	SN-UNKNOWN REF: NO REF	HRS/MSC AFL	O/C	0					11-FEB-1982		
350211 35.090	MASK, PASSENGER OXYGEN R2 PN	MOS									F4
	SN-UNKNOWN REF: NO REF	HRS/MSC AFL	O/C	0					11-FEB-1982		
350221 35.090	MASK, PASSENGER OXYGEN R3 PN	MOS									F4
	SN-UNKNOWN REF: NO REF	HRS/MSC AFL	O/C	0					11-FEB-1982		
350246 35.120	OUTLET, THERAPEUTIC OXYGEN 23599-11	MOS									F4
	SN-UNKNOWN REF: NO REF	HRS/MSC AFL	O/C	0					11-FEB-1982		
350158 35.120	REGULATOR, MASK COPILOT MC-1013-02	MOS	72	0							OVERHAUL F3
	8161 REF: NO REF	HRS/MSC AFL							09-NOV-1996 5951 4589	09-NOV-2002	
+ 350169U 35.070	CHECK	MOS	12								F3
	REF: AMM 35-00-00	HRS/MSC AFL	600						26-JUN-2001 7687 5594	26-JUN-2002 8287	
350148 35.120	REGULATOR, MASK PILOT MC-1013-02	MOS	72	0							OVERHAUL F3
	7750 REF: NO REF	HRS/MSC AFL		0					09-NOV-1996 5951 4589	09-NOV-2002	
+ 350166U 35.070	CHECK	MOS	12								F3
	REF: AMM 35-00-00	HRS/MSC AFL	600						26-JUN-2001 7687 5594	26-JUN-2002 8287	

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
350241 35.110	REGULATOR, OXYGEN DEMAND CONTROL PANEL (PURITAN) COPILOT 101202-11 SN-UNKNOWN REF: AMM 35-10-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3	
350236 35.110	REGULATOR, OXYGEN DEMAND CONTROL PANEL (PURITAN) PILOT 101202-11 SN-UNKNOWN REF: AMM 35-10-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3	
350116 35.030	REGULATOR, PRESSURE REDUCER 112031-06 670A REF: AMM 35-00-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3 \$970. 8	
350136 35.060	SWITCH, ALTITUDE PRESSURE 101800 8024154 REF: AMM 35-00-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3	
350231 35.100	SYSTEM, PASSENGER OXYGEN SUPPLY 5753004-400 189 REF: AMM 35-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3 \$950. 6	
350163 35.140	INSPECT/SERVICE OXYGEN SYSTEM 189 REF: AMM 35-00-00	MOS HRS/MSC AFL	O/C						13-NOV-1995 5718 4397	F3	
+ 350243 35.130	TEST PKG 3 REF: AMM 35-00-00	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360	F4	
350103 35.150	VALVE, OXYGEN CYLINDER 6350-A25-DDC SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C						11-DEC-1984 2119 1302	F2	
350111 35.020	VALVE, OXYGEN FILLER 26875-48 SN-UNKNOWN REF: AMM 35-00-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F1	
350131 35.050	VALVE, OXYGEN SHUTOFF 110115 SN-UNKNOWN REF: AMM 35-00-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F2	
350108 35.150	VALVE, TOGGLE 170001 8894 REF: NO REF	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F2	
CHAPTER 49 AIRBORNE AUXILIARY POWER											

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
49APU1	APU, PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	E/C									
CHAPTER 52	DOORS											
520181 52.020	LUBRICATE CABIN ENTRANCE STEP REF: AMM 12-20-00	MOS HRS/MSC AFL	O/C						11-FEB-1982		F4	
520161 52.040	DOOR, COMPARTMENT CMA21212-002 SN-UNKNOWN REF: AMM 52-30-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982		F5	
520171 52.050	DOOR, COMPARTMENT REAR BAGGAGE CMA22211-001 SN-UNKNOWN REF: AMM 52-30-01	MOS HRS/MSC AFL	O/C	0					11-FEB-1982		F5	
520101 52.010	DOOR, ENTRANCE CABIN 333045-505 SN-UNKNOWN REF: AMM 52-10-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982		F4	
+ 520106 52.010	INSPECT/LUBRICATE PKG 1, 2, 3 REF: AMM 52-10-00	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594		F4	
+ 520116 52.010	OPERATIONAL CHECK PKG 1, 2, 3 REF: AMM 52-10-00	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594		F4	
520136 52.030	HATCH, EMERGENCY EXIT LEFT 5-333031-501 SN-UNKNOWN REF: AMM 52-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982		F4	
+ 520141 52.030	INSPECT/LUBRICATE SEAL PKG 3 REF: See Workcard	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360		F4	
520146 52.030	HATCH, EMERGENCY EXIT RIGHT 5-333031-501 SN-UNKNOWN REF: AMM 52-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982		F4	
+ 520151 52.030	INSPECT/LUBRICATE SEAL PKG 3 REF: See Workcard	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360		F4	

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
520166 52.060	SEAL, COMPARTMENT DOOR CMA21212-057 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5	
520173 52.060	SEAL, COMPARTMENT DOOR REAR BAGGAGE CMA22211-006 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5	
520126 52.010	SEAL, ENTRANCE DOOR CABIN 333045-181 SN-UNKNOWN REF: AMM 52-10-00	MOS HRS/MSC AFL	O/C	0						01-DEC-1995 5727 4410	F4	
520176 52.020	STEP, ENTRANCE CABIN 5-123580-1 SN-UNKNOWN REF: AMM 52-60-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F4	
CHAPTER 53 FUSELAGE												
+ 530121 53.0202	INSPECT NOSE COMPARTMENT (B) PKG 2, 3 REF: AMM WCF 53.0302	MOS HRS/MSC AFL		400						26-JUN-2001 7687 5594	F2	
+ 530300 53.170	INSPECT AFT FUSELAGE STRUCTURE REF: AMM 5-40-02	MOS HRS/MSC AFL		4800						24-AUG-1993 5326 3975	MANDATORY F5 10126	
+ 530235 53.120	INSPECT AFT PRESSURE BULKHEAD AFT WEBS REF: AMM 5-40-01	MOS HRS/MSC AFL		15000							MANDATORY F5 15000	
+ 530230 53.110	INSPECT AFT PRESSURE BULKHEAD FORWARD WEBS. REF: AMM 5-40-01	MOS HRS/MSC AFL		9600							MANDATORY F5 9600	
+ 530250 53.150	INSPECT AFT PRESSURE BULKHEAD J-BEAM SPLICE FROM CABIN SIDE REF: AMM 5-40-01	MOS HRS/MSC AFL		9600							MANDATORY F5 9600	
+ 530255 53.160	INSPECT AFT PRESSURE BULKHEAD J-BEAM SPLICE FROM FUEL COMPARTMENT REF: AMM 5-40-01	MOS HRS/MSC AFL		15000							MANDATORY F5 15000	
+ 530240 53.130	INSPECT AFT PRESSURE BULKHEAD PERIPHERAL SECTION FROM CABIN SIDE. REF: AMM 5-40-01	MOS HRS/MSC AFL		9600							MANDATORY F5 9600	

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
+ 530245 53.140	INSPECT AFT PRESSURE BULKHEAD PERIPHERAL SECTION FROM FUEL COMPARTMENT	MOS HRS/MSC AFL	15000							MANDATORY 15000	F5
	REF: AMM 5-40-01	AFL									
+ 530176 53.060	INSPECT AUXILIARY FUEL TANK STRUCTURE	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360		F5
	REF: AMM 5-20-09	AFL									
+ 530146 53.0401	INSPECT CABIN (A)	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594		F4
	REF: AMM WCF 53.0401	AFL									
+ 530156 53.0402	INSPECT CABIN (C)	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360		F4
	REF: AMM WCF 53.0402	AFL									
+ 530131 53.0301	INSPECT COCKPIT (A)	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594		F3
	REF: AMM WCF 53.0301	AFL									
+ 530136 53.0302	INSPECT COCKPIT (B)	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594		F3
	REF: AMM WCF 53.0302	AFL									
+ 530141 53.0303	INSPECT COCKPIT (C)	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360		F3
	REF: AMM WCF 53.0303	AFL									
+ 530220 53.100	INSPECT ENTRY DOOR STOPS	MOS HRS/MSC AFL	5400						24-AUG-1993 5326 3975	MANDATORY 10726	F4
	REF: AMM 5-40-01	AFL									
+ 530205 53.180	INSPECT FORWARD TO AFT MAIN FRAME	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360	8125	F4
	REF: AMM 5-40-01	AFL									
+ 530200 53.080	INSPECT FORWARD TO AFT PRESSURE BULKHEAD-FUSELAGE	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360	MANDATORY 8125	F4
	REF: AMM 5-40-01	AFL									
+ 530101 53.010	INSPECT FUSELAGE (A)	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594		F1
	REF: AMM 5-20-02	AFL									

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
+ 530210 53.090	INSPECT FUSELAGE SKINS FLIGHT COMPARTMENT SIDE WINDOW	MOS HRS/MSC AFL	4800						24-AUG-1993 5326 3975	MANDATORY 10126	F4	
	REF: AMM 5-40-01											
+ 530116 53.0201	INSPECT NOSE COMPARTMENT (A) PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594		F2	
	REF: AMM WCF 53.0201											
+ 530161 53.0501	INSPECT REAR COMPARTMENT (A) PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594		F5	
	REF: AMM WCF 53.0501											
+ 530166 53.0502	INSPECT REAR COMPARTMENT (B) PKG 2, 3	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594		F5	
	REF: AMM WCF 53.0502											
531101 53.070	CONE, NOSE F10A-5-RD5-20000-7 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0					11-FEB-1982		F2	
				0								
CHAPTER 54 NACELLES/PYLONS												
+ 540200 54.020	INSPECT ENGINE SUPPORT INSTALLATION	MOS HRS/MSC AFL	4800						24-AUG-1993 5326 3975	MANDATORY 10126		
	REF: AMM 5-40-04											
+ 540101U 54.0101	INSPECT NO. 1 ENGINE NACELLE/PYLON (A) PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594		E1	
	REF: AMM WCF 54.0101											
+ 540106U 54.0102	INSPECT NO. 1 ENGINE NACELLE/PYLON (B) PKG 2, 3	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594		E1 3	
	REF: AMM WCF 54.0102											
+ 540111U 54.0103	INSPECT NO. 1 ENGINE NACELLE/PYLON (C) PKG 3	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360		E1	
	REF: AMM WCF 54.0103											
+ 540121U 54.0101	INSPECT NO. 2 ENGINE NACELLE/PYLON (A) PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594		E2	
	REF: AMM WCF 54.0101											
+ 540126U 54.0102	INSPECT NO. 2 ENGINE NACELLE/PYLON (B) PKG 2, 3	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594		E2 3	
	REF: AMM WCF 54.0102											

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT----- TSN TSO TSR TSI ADJ	INSTALLATION	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
+ 540131U 54.0103	INSPECT NO. 2 ENGINE NACELLE/PYLON (C) PKG 3	MOS HRS/MSC AFL	800				26-JUL-2000 7325 5360		E2
REF: AMM WCF 54.0103									
CHAPTER 55 STABILIZERS									
+ 550101 55.0101	INSPECT EMPENNAGE (A) PKG 1, 2, 3	MOS HRS/MSC AFL	200				26-JUN-2001 7687 5594		T1
REF: AMM WCF 55.0101									
+ 550106 55.0102	INSPECT EMPENNAGE (B) PKG 2, 3	MOS HRS/MSC AFL	400				26-JUN-2001 7687 5594		T1
REF: AMM WCF 55.0102									
+ 550200 55.060	INSPECT EMPENNAGE (MAJOR)	MOS HRS/MSC AFL	4800				24-AUG-1993 5326 3975	MANDATORY	T1
REF: AMM 5-40-03								10126	
550651 55.030	STABILIZER, HORIZONTAL 5453015-413-1 SN-UNKNOWN REF: AMM 55-10-00	MOS HRS/MSC AFL	O/C	0			11-FEB-1982		T1
550656 55.040	CHECK AFT SPAR SPLICE-HINGE FITTING OUTBOARD LUGS FOR CRACKS PKG 1, 2, 3	MOS HRS/MSC AFL	200				26-JUN-2001 7687 5594		T1
REF: AMM 55-10-00									
550658 55.050	CHECK ASSEMBLY RADIAL/AXIAL PLAY PKG 3	MOS HRS/MSC AFL	800				26-JUL-2000 7325 5360		T1
REF: See Workcard									
270214 27.195 ASSOCIATED	LUBRICATE AFT HINGE FITTING BEARINGS PKG 1, 2, 3	MOS HRS/MSC AFL	200				26-JUN-2001 7687 5594		T1
REF: NO REF									
270215 27.195 ASSOCIATED	LUBRICATE FORWARD SCISSOR ASSEMBLY PKG 1, 2, 3	MOS HRS/MSC AFL	200				26-JUN-2001 7687 5594		T1
REF: NO REF									
SB 1124-55-097 ASSOCIATED	STABILIZER SCISSR SERVICE BULLETIN	MOS HRS/MSC AFL	A/R						T1
REF: See Workcard									
Method of Compliance: OPEN									
550601 55.020	STABILIZER, VERTICAL 5413027-411 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	0			11-FEB-1982		T1

CHAPTER 56 WINDOWS

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
561601 56.075	WINDOW, EMERGENCY EXIT NO.L3 LEFT PN SN-UNKNOWN REF: AMM 56-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F4	
561606 56.075	WINDOW, EMERGENCY EXIT NO.R4 RIGHT PN SN-UNKNOWN REF: AMM 56-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F4	
560601 56.050	WINDOW, NO.L1 LEFT 5-343016-501 SN-UNKNOWN REF: AMM 56-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F4	
560606 56.060	WINDOW, NO.L2 LEFT 5-343016-501 SN-UNKNOWN REF: AMM 56-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F4	
560611 56.070	WINDOW, NO.L4 LEFT 5-343016-501 SN-UNKNOWN REF: AMM 56-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F4	
560616 56.080	WINDOW, NO.L5 LEFT 5-343016-501 SN-UNKNOWN REF: AMM 56-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F4	
561101 56.050	WINDOW, NO.R1 RIGHT 5-343016-501 SN-UNKNOWN REF: AMM 56-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F4	
561106 56.060	WINDOW, NO.R2 RIGHT 5-343016-501 SN-UNKNOWN REF: AMM 56-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F4	
561111 56.070	WINDOW, NO.R3 RIGHT 5-343016-501 SN-UNKNOWN REF: AMM 56-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F4	
561116 56.080	WINDOW, NO.R5 RIGHT 5-343016-501 SN-UNKNOWN REF: AMM 56-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F4	
561121 56.080	WINDOW, NO.R6 RIGHT 5-343016-501 SN-UNKNOWN REF: AMM 56-20-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F4	

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT----- TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
560121 56.040	WINDOW, OVERHEAD 5-343021-1 SN-UNKNOWN REF: AMM 56-10-02	MOS HRS/MSC AFL	O/C	0 0		11-FEB-1982		F3
560126 56.040	WINDOW, OVERHEAD 5-343021-2 SN-UNKNOWN REF: AMM 56-10-02	MOS HRS/MSC AFL	O/C	0 0		11-FEB-1982		F3
560116 56.030	WINDOW, SIDE COPILOT 5-343003-501 SN-UNKNOWN REF: AMM 56-10-04	MOS HRS/MSC AFL	O/C	0 0		11-FEB-1982		F3
+ 560118 56.030	INSPECT PKG 3 REF: See Workcard	MOS HRS/MSC AFL	800			26-JUL-2000 7325 5360		F3
560111 56.030	WINDOW, SIDE PILOT 5-343017-505 SN-UNKNOWN REF: AMM 56-10-03	MOS HRS/MSC AFL	O/C	0 0		11-FEB-1982		F3
+ 560112 56.030	INSPECT PKG 3 REF: AMM 56-10-03	MOS HRS/MSC AFL	800			26-JUL-2000 7325 5360		F3
560107 56.020	WINDSHIELD, INNER COPILOT 5343035 SN-UNKNOWN REF: AMM 56-10-01	MOS HRS/MSC AFL	O/C	0		11-FEB-1982		F3
560102 56.020	WINDSHIELD, INNER PILOT 5343035 SN-UNKNOWN REF: AMM 56-10-01	MOS HRS/MSC AFL	O/C	0		11-FEB-1982		F3
560106 56.010	WINDSHIELD, OUTER COPILOT PPG 343030-2 99064H0109 REF: AMM 56-10-01	MOS HRS/MSC AFL	O/C	0 0 0		26-AUG-2000 7352 5381		F3
560101 56.010	WINDSHIELD, OUTER PILOT 343030-1 98342H0422 REF: AMM 56-10-01	MOS HRS/MSC AFL	O/C	0 0 0		22-FEB-2000 7107 5232		F3
CHAPTER 57	WINGS							
+ 570220 57.050	INSPECT LEFT OUTER WING PANELS REF: AMM 5-40-05	MOS HRS/MSC AFL	4800			24-AUG-1993 5326 3975	MANDATORY 10126	W1

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND

Report Date **14-MAR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
+ 570101 57.0101	INSPECT LEFT WING (A) PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594		W1 1.5	
	REF: AMM WCF 57.0101											
+ 570104 57.0102	INSPECT LEFT WING (B) PKG 2, 3	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594		W1	
	REF: AMM WCF 57.0102											
+ 570200 57.040	INSPECT LEFT WING STRUCTURE	MOS HRS/MSC AFL	15000							MANDATORY 15000	W1	
	REF: AMM 5-40-05											
+ 570120 57.020	INSPECT RIGHT AILERON BELL CRANK PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594		W2	
	REF: AMM 5-20-03											
+ 570221 57.050	INSPECT RIGHT OUTER WING PANELS	MOS HRS/MSC AFL	4800						24-AUG-1993 5326 3975	10126	MANDATORY W2	
	REF: AMM 5-40-05											
+ 570116 57.0101	INSPECT RIGHT WING (A) PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594		W2 1.5	
	REF: AMM WCF 57.0101											
+ 570119 57.0102	INSPECT RIGHT WING (B) PKG 2, 3	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594		W2	
	REF: AMM WCF 57.0102											
+ 570201 57.040	INSPECT RIGHT WING STRUCTURE	MOS HRS/MSC AFL	15000							MANDATORY 15000	W2	
	REF: AMM 5-40-05											
570031 57.030	TANK, TIP LEFT 5213003-405 SN-UNKNOWN REF: AMM 57-20-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	W1	
570041 57.030	TANK, TIP RIGHT 5213003-406 SN-UNKNOWN REF: AMM 57-20-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	W2	
CHAPTER 71	POWER PLANT											
+ 710650U	- INSP #1 ENG INLET NACELLE PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594		E1	
	REF:											

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT----- TSN TSO TSR TSI ADJ	INSTALLATION	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
+ 713650U	INSP #2 ENG INLET NACELLE PKG 1, 2, 3	MOS HRS/MSC AFL	200				26-JUN-2001 7687 5594		E2
71EN1	ENGINE, NO. 1 3072500-2 P-77482	MOS HRS/MSC AFL	E/C						
71EN2	ENGINE, NO. 2 3072500-2 P77488	MOS HRS/MSC AFL	E/C						
CHAPTER 73 ENGINE FUEL AND CONTROL									
731101U	COMPUTER, FUEL CONT ENG #1 2101144-1	MOS HRS/MSC AFL	O/C	3972 2456			03-APR-1989 4215 2745		F5 \$4400. 3
733601U	COMPUTER, FUEL CONT ENG #2 2101144-1	MOS HRS/MSC AFL	O/C	4215 2745			31-MAY-1989 4265 2793		F5 \$4400. 3
732106U	INDICATOR, FUEL FLO ENG #1 6-883708-1	MOS HRS/MSC AFL	O/C	3209 1976			30-JUL-1986 3209 1976		F3 \$372.
734606U	INDICATOR, FUEL FLO ENG #2 6-883708-1	MOS HRS/MSC AFL	O/C	3017 1772			30-JUL-1986 3209 1976		F3 \$372.
CHAPTER 75 AIR									
750116 75.030	SENSOR, TEMPERATURE INLET 3070816-2	MOS HRS/MSC AFL	O/C	3972 2456			03-APR-1989 4215 2745		E1
750616 75.030	SENSOR, TEMPERATURE INLET 3070816-2	MOS HRS/MSC AFL	O/C	1592			31-MAY-1989 4265 2793		E2
CHAPTER 77 ENGINE INDICATING									
771606 77.020	INDICATOR, (N1) LOW-PRESSURE NO. 2 ENGINE 6-883619-1	MOS HRS/MSC AFL	O/C	0			11-FEB-1982		F3 \$1100.

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
770106 77.020	INDICATOR, (N1) LOW-PRESSURE NO. 1 ENGINE 6883619-1 SN-UNKNOWN REF: AMM 77-00-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3 \$1100.	
770608 77.040	INDICATOR, (N2) HIGH-PRESSURE NO. 1 ENGINE 6883620-1 SN-UNKNOWN REF: AMM 77-00-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3	
772106 77.040	INDICATOR, (N2) HIGH-PRESSURE NO. 2 ENGINE 6-883620-1 SN-UNKNOWN REF: AMM 77-00-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F3	
771106 77.060	INDICATOR, ITT NO. 1 ENGINE 6883621-503 R0097 REF: AMM 77-00-00	MOS HRS/MSC AFL	O/C		0				31-MAY-1993 5278 3928	F3 \$507.	
772606 77.060	INDICATOR, ITT NO. 2 ENGINE 6883621-503 R0031R REF: AMM 77-00-00	MOS HRS/MSC AFL	O/C		0				31-MAY-1993 5278 3928	F3 \$507.	
CHAPTER 78	EXHAUST										
+ 780119 78.140	CHECK #1 THRUST REVERSER SECONDARY LATCH SOLENOID SWITCH PKG 3 REF: AMM 78-30-00	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360	E1	
+ 780120 78.140	CHECK #2 THRUST REVERSER SECONDARY LATCH SOLENOID SWITCH PKG 3 REF: AMM 78-30-00	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360	E2	
+ 780116 78.110	OPERATIONAL CHECK NO.1 THRUST REVERSER PKG 3 REF: AMM 78-30-00	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360	E1	
+ 780616 78.110	OPERATIONAL CHECK NO.2 THRUST REVERSER PKG 3 REF: AMM 78-30-00	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360	E2	
780156 78.040	ACCUMULATOR, THRUST REVERSER 4723565-1 SN-UNKNOWN REF: AMM 78-34-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982	F5	
780146 78.020	ACTUATOR, THRUST REVERSER NO. 1 F10A-5-SCH203-1 0419 REF: AMM 78-34-00	MOS HRS/MSC AFL	O/C	0					02-JAN-1987 3504 2168	E1	

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
780646	ACTUATOR, THRUST REVERSER NO. 2										E2	
78.020	F10A-5-SCH203-1	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C	0								
	REF: AMM 78-34-00	AFL										
780161	BOTTLE, THRUST REVERSER GAS STORAGE									LIFE LIMIT	F5	
78.050	3753015-501	MOS	288	0					11-FEB-1982	11-FEB-2006		
	07511A1	HRS/MSC										
	REF: AMM 78-34-00	AFL										
+ 780163	HYDROSTATIC TEST										F5	
78.050		MOS	36						26-OCT-1999	26-OCT-2002		
		HRS/MSC							6961			
	REF: See Workcard	AFL							5135			
780131	CONTROL ASSEMBLY, THROTTLE RETARDER FEEDBACK NO. 1									LIFE LIMIT	E1	
78.090	F10A-5SCP203-1	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	10000	0						10000		
	REF: AMM 78-32-00	AFL										
780136	CLEAN/LUBRICATE NO.1 THROTTLE RETARDER CABLE AND CASING										E1	
78.090		MOS	36						06-NOV-2001	06-NOV-2004		
		HRS/MSC							7774			
	REF: AMM 12-20-00	AFL							5641			
780631	CONTROL ASSEMBLY, THROTTLE RETARDER FEEDBACK NO. 2									LIFE LIMIT	E2	
78.090	F10A-5SCP203-2	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	10000	0						10000		
	REF: AMM 78-32-00	AFL										
780636	CLEAN/LUBRICATE NO.2 THROTTLE RETARDER CABLE AND CASING										E2	
78.090		MOS	36						06-NOV-2001	06-NOV-2004		
		HRS/MSC							7774			
	REF: AMM 78-32-00	AFL							5641			
780171	RELEASE VALVE, THRUST REVERSER										F5	
78.070	3723581-1	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C	0								
	REF: AMM 78-34-00	AFL										
780158	SWITCH, THRUST REVERSER LOW-PRESSURE										F5	
78.080	4713533-1	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C	0								
	REF: AMM 78-34-00	AFL										
780141	THRUST REVERSER ASSEMBLY, NO. 1										E1	
78.010	F10A-5-B20202-1	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C	0								
	REF: NO REF	AFL										
+ 780148	INSPECT									INSPECT	E1	
78.130		MOS							20-AUG-1991			
		HRS/MSC	5000						4906	9906		
	REF: See Workcard	AFL										

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
780143 78.100	LUBRICATE PKG 3	MOS HRS/MSC AFL	800							26-JUL-2000 7325 5360	E1	
	REF: AMM 12-20-00											
780641 78.011	THRUST REVERSER ASSEMBLY, NO. 2 F10A-5-B20202-2 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	E2	
+ 780648 78.130	INSPECT	MOS HRS/MSC AFL	5000							INSPECT 20-AUG-1991 4906 9906	E2	
	REF: See Workcard											
780643 78.100	LUBRICATE PKG 3	MOS HRS/MSC AFL	800							26-JUL-2000 7325 5360	E2	
	REF: AMM 12-20-00											
780166 78.060	VALVE, RELIEF PN SN-UNKNOWN REF: AMM 78-34-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5	
780151 78.030	VALVE, THRUST REVERSER CONTROL NO. 1 723573 525 REF: AMM 78-34-00	MOS HRS/MSC AFL	O/C	0						08-APR-1987 3684 2293	F5 \$588. 2	
780651 78.030	VALVE, THRUST REVERSER CONTROL NO. 2 723573 SN-UNKNOWN REF: AMM 78-34-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F5 \$588. 2	
CHAPTER 79	OIL											
791121U	IND, PRESS/TEMP ENG #1 6-883706-1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3 \$805.	
792621U	IND, PRESS/TEMP ENG #2 6-883706-1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	0						11-FEB-1982	F3 \$805.	
790616U	VALVE, OIL TEMP ENG #1 157025-2 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	3972 2456						03-APR-1989 4215 2745	E1	
792116U	VALVE, OIL TEMP ENG #2 157025-2 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	4215						31-MAY-1989 4265 2793	E2	

Engine Model - TFE731-3

Report Date **14-MAR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
ENGINE NO. 1								
CHAPTER 71								
POWER PLANT								
710140U	NO. 1 ENGINE - -- RUN ADJ/TEST #1 ENG	MOS					13-NOV-1999	
	REF:	HRS/MSC	C/C			6961		
		ENC						5135
		(AFL)						
+ 714010	NO. 1 ENGINE - CHECK ELECTRICAL WIRES AND CONNECTIONS	MOS					26-JUL-2000	
71.040		HRS/MSC	800			7325	8125	
	REF: EMM 72-00-00 TR 72-61	ENC						5360
		(AFL)						
+ 715010	NO. 1 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS	MOS					26-JUL-2000	
71.050		HRS/MSC	800			7325	8125	
	REF: EMM 72-00-00 TR 72-61	ENC						5360
		(AFL)						
+ 710130	NO. 1 ENGINE - INSPECT FAN ROTOR ASSEMBLY BLADES	MOS					16-FEB-2001	
71.020	PKG 6, 6	HRS/MSC	300			7551		.5
	REF: EMM 72-00-00 TR 72-61	ENC						5515
		(AFL)						
+ 710120	NO. 1 ENGINE - MAJOR PERIODIC INSPECTION	MOS					13-NOV-1999	
71.010		HRS/MSC	1400			6961	8361	
	REF: EMM 72-00-00	ENC						5135
		(AFL)						
710110U	NO. 1 ENGINE - ENGINE, #1	MOS					03-APR-1989	
	3072500-2	HRS/MSC	O/C	3972		4215		
	P-77482	ENC						2745
	REF:	(AFL)		2456				
CHAPTER 72								
ENGINE								
+ 724120	NO. 1 ENGINE - INSPECT COMBUSTION PLENUM CASE	MOS					13-NOV-1999	
72.030		HRS/MSC	1400			6961	8361	
	REF: EMM 72-40-04	ENC						5135
		(AFL)						
+ 723110	NO. 1 ENGINE - INSPECT COMPRESSOR CORE	MOS					26-APR-1994	
72.010		HRS/MSC	4200			5442	9642	
	REF: NO REF	ENC						4106
		(AFL)						

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Engine Model - TFE731-3

Report Date **14-MAR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
+ 727110 72.300	NO. 1 ENGINE - PERIODIC INSPECT FAN SUPPORT ASSEMBLY	MOS							26-APR-1994		
	REF: EMM 72-70-06	HRS/MSC ENC (AFL)	4200					5442	9642		
724110 72.020	NO. 1 ENGINE - CASE, COMBUSTION PLENUM 3072443-4	MOS							03-APR-1989		
	IP8088	HRS/MSC	O/C	3972				4215			
	REF: NO REF	ENC (AFL)		2456				2745			
+ 724120 72.030 ASSOCIATED	NO. 1 ENGINE - INSPECT COMBUSTION PLENUM CASE	MOS							13-NOV-1999		
	REF: EMM 72-40-04	HRS/MSC ENC (AFL)	1400					6961	8361		
725050 72.090	NO. 1 ENGINE - DISC, FAN ROTOR 3073563-2	MOS							13-NOV-1999	LIFE LIMIT	
	970322902451	HRS/MSC		0				6961			
	REF: NO REF	ENC (AFL)	10000	0				5135	15135		
725060 72.100	NO. 1 ENGINE - DISC, STAGE 1 LOW PRESSURE COMPRESSOR 3072395	MOS							03-APR-1989	LIFE LIMIT	
	1-12112-1531	HRS/MSC		3972				4215			
	REF: NO REF	ENC (AFL)	10000	2456				2745	10289		
725010 72.040	NO. 1 ENGINE - DISC, STAGE 1 LOW PRESSURE TURBINE 3072352-4	MOS							12-JUL-1991	LIFE LIMIT	
	0-03229-1212	HRS/MSC		0				4879			
	REF: NO REF	ENC (AFL)	3000	0				3494	6494		
725070 72.110	NO. 1 ENGINE - DISC, STAGE 2 LOW PRESSURE COMPRESSOR 3072396	MOS							03-APR-1989	LIFE LIMIT	
	1-12112-429	HRS/MSC		3972				4215			
	REF: NO REF	ENC (AFL)	10000	2456				2745	10289		
725020 72.050	NO. 1 ENGINE - DISC, STAGE 2 LOW PRESSURE TURBINE 3072351-5	MOS							20-MAY-1993	LIFE LIMIT	
	1-03226-1486	HRS/MSC		0				5278			
	REF: NO REF	ENC (AFL)	3000	0				3928	6928		
725080 72.120	NO. 1 ENGINE - DISC, STAGE 3 LOW PRESSURE COMPRESSOR 3072397	MOS							03-APR-1989	LIFE LIMIT	
	0-12112-4057	HRS/MSC		3972				4215			
	REF: NO REF	ENC (AFL)	10000	2456				2745	10289		

Engine Model - TFE731-3

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
725030 72.060	NO. 1 ENGINE - DISC, STAGE 3 LOW PRESSURE TURBINE 3074097-1 975332202025 REF: NO REF	MOS HRS/MSC ENC (AFL)	7000	0						13-NOV-1999 6961	LIFE LIMIT	
725090 72.130	NO. 1 ENGINE - DISC, STAGE 4 LOW PRESSURE COMPRESSOR 3072398 0-03160-3697 REF: NO REF	MOS HRS/MSC ENC (AFL)		3972						5135 4215	LIFE LIMIT	
725160 72.200	NO. 1 ENGINE - DUCT, TURBINE INTERSTAGE TRANSITION 3072318 SN-UNKNOWN REF: EMM 72-50-05	MOS HRS/MSC ENC (AFL)	O/C							2456 4215	10289	
726110 72.250	NO. 1 ENGINE - GEARBOX, ACCESSORY 3070003-5 SN-UNKNOWN REF: EMM 72-60-01	MOS HRS/MSC ENC (AFL)	O/C	3972						2456 4215	03-APR-1989	
+ 726120 72.260	NO. 1 ENGINE - INSPECT REF: EMM 72-60-02	MOS HRS/MSC ENC (AFL)	4200							2745 5442	26-APR-1994 9642	
726130 72.270	NO. 1 ENGINE - GEARBOX, TRANSFER 3070093-3 P-2768 REF: EMM 72-60-01	MOS HRS/MSC ENC (AFL)	O/C	0						2745 4215	03-APR-1989	
725110 72.150	NO. 1 ENGINE - IMPELLER, HIGH PRESSURE 3073398-1 4-23365-1094 REF: NO REF	MOS HRS/MSC ENC (AFL)	10000	3972						2456 4215	LIFE LIMIT	
725180 72.220	NO. 1 ENGINE - NOZZLE, STAGE 1 LOW PRESSURE TURBINE 3072319-11 990134506659 REF: NO REF	MOS HRS/MSC ENC (AFL)	O/C	0						0 5135	13-NOV-1999 6961	
725140 72.180	NO. 1 ENGINE - PLATE, HIGH PRESSURE ROTOR SEAL 3072411-1 7-18040-2569 REF: NO REF	MOS HRS/MSC ENC (AFL)	10000	3816						2507 5135	LIFE LIMIT 12628	

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Engine Model - TFE731-3

Report Date **14-MAR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
725040 72.070	NO. 1 ENGINE - ROTOR, HIGH PRESSURE TURBINE 3072316 1-18040-598 REF: EMM 72-50-06	MOS HRS/MSC ENC (AFL)	7000		3972				03-APR-1989 4215	LIFE LIMIT	
					2456			2745	7289		
725170 72.210	NO. 1 ENGINE - SEAL PLATE, STAGE 1 LOW PRESSURE TURBINE 3073552 SN-UNKNOWN REF: NO REF	MOS HRS/MSC ENC (AFL)	O/C					11-FEB-1982			
725190 72.230	NO. 1 ENGINE - SEAL, LOW PRESSURE TURBINE ROTATING AIR 3073355 SN-UNKNOWN REF: NO REF	MOS HRS/MSC ENC (AFL)	O/C		0						
725120 72.160	NO. 1 ENGINE - SEAL, ROTATING 3072729-1 0-23151-343 REF: NO REF	MOS HRS/MSC ENC (AFL)	O/C		0			12-JUL-1991 4879			
					0			3494			
725150 72.190	NO. 1 ENGINE - SHAFT, FAN DRIVE 3071955-3 1P-39726 REF: NO REF	MOS HRS/MSC ENC (AFL)	O/C		3972			03-APR-1989 4215			
					2456			2745			
725130 72.170	NO. 1 ENGINE - SHAFT, HIGH PRESSURE SHOULDERED 3072545-1 1P-39446 REF: NO REF	MOS HRS/MSC ENC (AFL)	12000		3456			03-APR-1989 4215		LIFE LIMIT	
								2745	11289		
725191 72.240	NO. 1 ENGINE - SUPPORT, LOW PRESSURE TURBINE ROTATING AIR SEAL 3073764 SN-UNKNOWN REF: NO REF	MOS HRS/MSC ENC (AFL)	O/C								
725091 72.140	NO. 1 ENGINE - TIE ROD, LOW PRESSURE 3073049-1 1P-15433 REF: EMM 72-30-10	MOS HRS/MSC ENC (AFL)	O/C		3972			03-APR-1989 4215			
					2456			2745			
CHAPTER 73	ENGINE FUEL AND CONTROL										
+ 731120 73.020	NO. 1 ENGINE - REMOVE AND REPLACE FILTER ELEMENT PKG 6, 6 REF: See Workcard	MOS HRS/MSC ENC (AFL)	300					16-FEB-2001 7551			
								5515			

Engine Model - TFE731-3

Report Date **14-MAR-2002**

Owner Name - **R&S AIRCRAFT INVESTMENTS, LLC**
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
732110 73.060	NO. 1 ENGINE - CONTROL UNIT, FUEL 3070800-8 SN-UNKNOWN REF: EMM 73-20-01	MOS HRSMSC ENC (AFL)	O/C	3972						18-MAY-1989 4215		
				2456						2745		
732120 73.070 ASSOCIATED	NO. 1 ENGINE - CHANGE PRESSURE LIMITER VALVE 3070685-4 SN-UNKNOWN REF: NO REF	MOS HRSMSC ENC (AFL)	O/C	3972						03-APR-1989 4215		
				2456						2745		
731150 73.050	NO. 1 ENGINE - COOLER, FUEL/OIL 158610-5 SN-UNKNOWN REF: EMM 79-20-07	MOS HRSMSC ENC (AFL)	O/C	3972						03-APR-1989 4215		
				2456						2745		
731140 73.040	NO. 1 ENGINE - HEATER, FUEL 158670-3 SN-UNKNOWN REF: EMM 73-10-04	MOS HRSMSC ENC (AFL)	O/C	3972						03-APR-1989 4215		
				2456						2745		
731110 73.010	NO. 1 ENGINE - PUMP, ENGINE FUEL 3070850-8 SN-UNKNOWN REF: EMM 73-20-01	MOS HRSMSC ENC (AFL)	O/C	3972						03-APR-1989 4215		
				2456						2745		
+ 731120 73.020 ASSOCIATED	NO. 1 ENGINE - REMOVE AND REPLACE FILTER ELEMENT PKG 6, 6 REF: See Workcard	MOS HRSMSC ENC (AFL)	300							16-FEB-2001 7551		
										5515		
732160 73.110	NO. 1 ENGINE - TRANSMITTER, FUEL FLOW 6883709-1 564 REF: NO REF	MOS HRSMSC ENC (AFL)		0						06-MAY-1992 5105		
				0						3725		
731130 73.030	NO. 1 ENGINE - VALVE, FLOW DIVIDER/DRAIN 394366-4 SN-UNKNOWN REF: NO REF	MOS HRSMSC ENC (AFL)	O/C	3972						03-APR-1989 4215		
				2456						2745		
732110 73.060 ASSOCIATED	NO. 1 ENGINE - CHANGE FUEL CONTROL UNIT 3070800-8 SN-UNKNOWN REF: EMM 73-20-01	MOS HRSMSC ENC (AFL)	O/C	3972						18-MAY-1989 4215		
				2456						2745		

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Engine Model - TFE731-3

Report Date **14-MAR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
732120	NO. 1 ENGINE - CHANGE PRESSURE LIMITER VALVE											
73.070	3070685-4	MOS								03-APR-1989		
ASSOCIATED	SN-UNKNOWN	HRS/MSC	O/C	3972						4215		
	REF: NO REF	ENC										
		(AFL)		2456						2745		
732120	NO. 1 ENGINE - VALVE, PRESSURE LIMITER											
73.070	3070685-4	MOS								03-APR-1989		
	SN-UNKNOWN	HRS/MSC	O/C	3972						4215		
	REF: NO REF	ENC										
		(AFL)		2456						2745		
732140	NO. 1 ENGINE - VALVE, SOLENOID CONTROL											
73.090	109696-3-1	MOS								03-APR-1989		
	SN-UNKNOWN	HRS/MSC	O/C	3972						4215		
	REF: EMM 76-10-01	ENC										
		(AFL)		2456						2745		
732130	NO. 1 ENGINE - VALVE, SURGE BLEED											
73.080	978812-4-1	MOS								03-APR-1989		
	SN-UNKNOWN	HRS/MSC	O/C	3972						4215		
	REF: EMM 76-10-01	ENC										
		(AFL)		2456						2745		
CHAPTER 74	IGNITION											
+ 742120	NO. 1 ENGINE - INSPECT 6 O'CLOCK IGNITER PLUG											
74.040		MOS								26-JUL-2000		
	REF: See Workcard	HRS/MSC	800							7325	8125	
		ENC										
		(AFL)								5360		
+ 742140	NO. 1 ENGINE - INSPECT 7 O'CLOCK IGNITER PLUG											
74.060		MOS								26-JUL-2000		
	REF: See Workcard	HRS/MSC	800							7325	8125	
		ENC										
		(AFL)								5360		
+ 741120	NO. 1 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM											
74.020		MOS								26-JUL-2000		
	REF: EMM 74-00-01	HRS/MSC	800							7325	8125	
		ENC									1	
		(AFL)								5360		
742110	NO. 1 ENGINE - IGNITER PLUG, 6 O'CLOCK											
74.030	3071589-2	MOS								03-APR-1989		
	SN-UNKNOWN	HRS/MSC	O/C	3972						4215		
	REF: EMM 74-00-01	ENC										
		(AFL)		2456						2745		
+ 742120	NO. 1 ENGINE - INSPECT 6 O'CLOCK IGNITER PLUG											
74.040		MOS								26-JUL-2000		
ASSOCIATED	REF: See Workcard	HRS/MSC	800							7325	8125	
		ENC										
		(AFL)								5360		

Engine Model - TFE731-3

Report Date **14-MAR-2002**

Owner Name - **R&S AIRCRAFT INVESTMENTS, LLC**

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
742130	NO. 1 ENGINE - IGNITER PLUG, 7 O'CLOCK											
74.050	3071589-2	MOS							03-APR-1989			
	SN-UNKNOWN	HRS/MSC	O/C	3972					4215			
	REF: EMM 74-00-01	ENC										
		(AFL)		2456					2745			
+ 742140	NO. 1 ENGINE - INSPECT 7 O'CLOCK IGNITER PLUG											
74.060		MOS							26-JUL-2000			
ASSOCIATED		HRS/MSC	800						7325	8125		
	REF: See Workcard	ENC										
		(AFL)							5360			
741110	NO. 1 ENGINE - UNIT, IGNITION											
74.010	3070378-2	MOS							03-APR-1989			
	SN-UNKNOWN	HRS/MSC	O/C	3972					4215			
	REF: EMM 74-00-01	ENC										
		(AFL)		2456					2745			
+ 741120	NO. 1 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM											
74.020		MOS							26-JUL-2000			
ASSOCIATED		HRS/MSC	800						7325	8125	1	
	REF: EMM 74-00-01	ENC										
		(AFL)							5360			
CHAPTER 75	AIR											
751010	NO. 1 ENGINE - VALVE, ANTI-ICE SHUTOFF											
75.010	978944-1-1	MOS							03-APR-1989			
	SN-UNKNOWN	HRS/MSC	O/C	3972					4215			
	REF: EMM 75-10-01	ENC										
		(AFL)		2456					2745			
CHAPTER 77	ENGINE INDICATING											
772110	NO. 1 ENGINE - HARNESS, ITT THERMOCOUPLE											
77.030	3073595-1	MOS							12-JUL-1991			
	1-20219-407	HRS/MSC	O/C	0					4879			
	REF: EMM 77-20-01	ENC										
		(AFL)							3494			
771120	NO. 1 ENGINE - TRANSDUCER, HIGH PRESSURE (N2)											
77.020	3070722-2	MOS							03-APR-1989			
	SN-UNKNOWN	HRS/MSC	O/C	3972					4215			
	REF: EMM 77-10-05	ENC										
		(AFL)		2456					2745			
771110	NO. 1 ENGINE - TRANSDUCER, LOW PRESSURE (N1)											
77.010	3071928-5	MOS							03-APR-1989			
	SN-UNKNOWN	HRS/MSC	O/C	3972					4215			
	REF: EMM 77-10-03	ENC										
		(AFL)		2456					2745			
CHAPTER 79	OIL											

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Engine Model - TFE731-3

Report Date **14-MAR-2002**

Owner Name - **R&S AIRCRAFT INVESTMENTS, LLC**
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
+ 790110 79.010	NO. 1 ENGINE - ANALYZE ENGINE OIL PKG 4, 4,6, 6	MOS HRS/MSC ENC (AFL)	150							26-JUN-2001 7687	1	
	REF: EMM 72-00-00 TR 72-61									5594		
790120 79.020	NO. 1 ENGINE - CHANGE OIL	MOS HRS/MSC ENC (AFL)	1400							13-NOV-1999 6961	8361	
	REF: See Workcard									5135		
+ 790130 79.030	NO. 1 ENGINE - INSPECT CHIP DETECTOR PKG 4, 4,6, 6	MOS HRS/MSC ENC (AFL)	150							26-JUN-2001 7687		
	REF: EMM 72-00-00 TR 72-61									5594		
792150 79.080	NO. 1 ENGINE - COOLER, OIL LOWER LEFT 159900-1 SN-UNKNOWN REF: EMM 79-20-09	MOS HRS/MSC ENC (AFL)	O/C	3972						03-APR-1989 4215		
				2456						2745		
792160 79.090	NO. 1 ENGINE - COOLER, OIL LOWER RIGHT 159910-1 SN-UNKNOWN REF: EMM 79-20-09	MOS HRS/MSC ENC (AFL)	O/C	3972						03-APR-1989 4215		
				2456						2745		
792140 79.070	NO. 1 ENGINE - COOLER, OIL UPPER 158600-4 SN-UNKNOWN REF: EMM 79-20-09	MOS HRS/MSC ENC (AFL)	O/C	3972						03-APR-1989 4215		
				2456						2745		
792110 79.040	NO. 1 ENGINE - PUMP, OIL 3071949-7 SN-UNKNOWN REF: EMM 79-20-03	MOS HRS/MSC ENC (AFL)	O/C	3972						03-APR-1989 4215		
				2456						2745		
790120 79.020 ASSOCIATED	NO. 1 ENGINE - CHANGE OIL	MOS HRS/MSC ENC (AFL)	1400							13-NOV-1999 6961	8361	
	REF: See Workcard									5135		
793120 79.120	NO. 1 ENGINE - SWITCH, OIL PRESSURE 3833518 SN-UNKNOWN REF: NO REF	MOS HRS/MSC ENC (AFL)	O/C	3972						03-APR-1989 4215		
				2456						2745		

Engine Model - TFE731-3

Report Date **14-MAR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
793110 79.110	NO. 1 ENGINE - TRANSMITTER, OIL PRESSURE 101-412-80-13 SN-UNKNOWN REF: NO REF	MOS HRS/MSC ENC (AFL)	O/C	3972						03-APR-1989 4215		
792120 79.050	NO. 1 ENGINE - VALVE, OIL FILTER BYPASS 3070000NP69 SN-UNKNOWN REF: EMM 79-30-01	MOS HRS/MSC ENC (AFL)	O/C	3972						03-APR-1989 4215		
792130 79.060	NO. 1 ENGINE - VALVE, PRESSURE BREATHER 3071564-8 SN-UNKNOWN REF: EMM 79-20-02	MOS HRS/MSC ENC (AFL)	O/C	2456						18-MAY-1989 4215		
				2456						2745		
										2745		

Engine Model - TFE731-3

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT----- TSN TSO TSR TSI ADJ	INSTALLATION	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
ENGINE NO. 2									
CHAPTER 71 POWER PLANT									
710140U	NO. 2 ENGINE - --- RUN ADJ/TEST #2 ENG	MOS						31-MAY-1993	
	REF:	HRSMSC	C/C					5278	
		ENC							3928
		(AFL)							
+ 714010	NO. 2 ENGINE - CHECK ELECTRICAL WIRES AND CONNECTIONS	MOS						26-JUL-2000	
71.040		HRSMSC	800					7325	8125
	REF: EMM 72-00-00 TR 72-61	ENC							
		(AFL)							5360
+ 715010	NO. 2 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS	MOS						26-JUL-2000	
71.050		HRSMSC	800					7325	8125
	REF: EMM 72-00-00 TR 72-61	ENC							
		(AFL)							5360
+ 710130	NO. 2 ENGINE - INSPECT FAN ROTOR ASSEMBLY BLADES	MOS						16-FEB-2001	
71.020	PKG 7, 7	HRSMSC	300					7551	.5
	REF: EMM 72-00-00 TR 72-61	ENC							
		(AFL)							5515
+ 710120	NO. 2 ENGINE - MAJOR PERIODIC INSPECTION	MOS						17-OCT-1998	
71.010		HRSMSC	1400					6520	7920
	REF: EMM 72-00-00	ENC							
		(AFL)							4889
710110U	NO. 2 ENGINE - ENGINE, #2	MOS						31-MAY-1993	
	3072500-2	HRSMSC	O/C	5227				5278	
	P77488	ENC							
	REF:	(AFL)		3867					3928
CHAPTER 72 ENGINE									
+ 724120	NO. 2 ENGINE - INSPECT COMBUSTION PLENUM CASE	MOS						17-SEP-1998	
72.030		HRSMSC	1400					6520	7920
	REF: EMM 72-40-04	ENC							
		(AFL)							4889
+ 723110	NO. 2 ENGINE - INSPECT COMPRESSOR CORE	MOS						17-OCT-1998	
72.010		HRSMSC	4200					6520	10720
	REF: NO REF	ENC							
		(AFL)							4889

Engine Model - TFE731-3

Report Date **14-MAR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION			Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR				
+ 727110 72.300	NO. 2 ENGINE - PERIODIC INSPECT FAN SUPPORT ASSEMBLY	MOS						17-MAY-1989		
	REF: EMM 72-70-06	HRS/MSC ENC (AFL)	4200					4265 8465 2793		
724110 72.020	NO. 2 ENGINE - CASE, COMBUSTION PLENUM 3072443-4	MOS						31-MAY-1989		
	OP-52337	HRS/MSC	O/C	4215				4265		
	REF: NO REF	ENC (AFL)			2745			2793		
+ 724120 72.030 ASSOCIATED	NO. 2 ENGINE - INSPECT COMBUSTION PLENUM CASE	MOS						17-SEP-1998		
	REF: EMM 72-40-04	HRS/MSC ENC (AFL)	1400					6520 7920 4889		
725050 72.090	NO. 2 ENGINE - DISC, FAN ROTOR 3073539-2	MOS						20-MAY-1993	LIFE LIMIT	
	0-18040-4768	HRS/MSC		4087				5278		
	REF: NO REF	ENC (AFL)	4100	2660				3928 5368		
725060 72.100	NO. 2 ENGINE - DISC, STAGE 1 LOW PRESSURE COMPRESSOR 3072395	MOS						31-MAY-1989	LIFE LIMIT	
	1-12112-1647	HRS/MSC		4215				4265		
	REF: NO REF	ENC (AFL)	10000	2745				2793 10048		
725010 72.040	NO. 2 ENGINE - DISC, STAGE 1 LOW PRESSURE TURBINE 3072351-5	MOS						20-MAY-1993	LIFE LIMIT	
	1-03229-1486	HRS/MSC		0				5278		
	REF: NO REF	ENC (AFL)	3000	0				3928 6928		
725070 72.110	NO. 2 ENGINE - DISC, STAGE 2 LOW PRESSURE COMPRESSOR 3072396	MOS						31-MAY-1989	LIFE LIMIT	
	1-12112-581	HRS/MSC		4215				4265		
	REF: NO REF	ENC (AFL)	10000	2745				2793 10048		
725020 72.050	NO. 2 ENGINE - DISC, STAGE 2 LOW PRESSURE TURBINE 3072542-5	MOS						20-MAY-1993	LIFE LIMIT	
	1-03229-1277	HRS/MSC		0				5278		
	REF: NO REF	ENC (AFL)	3000	0				3928 6928		
725080 72.120	NO. 2 ENGINE - DISC, STAGE 3 LOW PRESSURE COMPRESSOR 3072397	MOS						31-MAY-1989	LIFE LIMIT	
	0-12112-1718	HRS/MSC		4215				4265		
	REF: NO REF	ENC (AFL)	10000	2745				2793 10048		

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Engine Model - TFE731-3

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
725030 72.060	NO. 2 ENGINE - DISC, STAGE 3 LOW PRESSURE TURBINE 3072544-2 6-18040-4905 REF: NO REF	MOS HRS/MSC ENC (AFL)			0				31-MAY-1989 4265	LIFE LIMIT	
			3000		0				2793	5793	
725090 72.130	NO. 2 ENGINE - DISC, STAGE 4 LOW PRESSURE COMPRESSOR 3072398 0-12112-3229 REF: NO REF	MOS HRS/MSC ENC (AFL)			4215				31-MAY-1989 4265	LIFE LIMIT	
			10000		2745				2793	10048	
725160 72.200	NO. 2 ENGINE - DUCT, TURBINE INTERSTAGE TRANSITION 3072318 SN-UNKNOWN REF: EMM 72-50-05	MOS HRS/MSC ENC (AFL)		O/C					31-MAY-1989 4265		
									2793		
726110 72.250	NO. 2 ENGINE - GEARBOX, ACCESSORY 3070003-5 P-948 REF: EMM 72-60-01	MOS HRS/MSC ENC (AFL)		O/C	4215				31-MAY-1989 4265		
					2745				2793		
+ 726120 72.260	NO. 2 ENGINE - INSPECT REF: EMM 72-60-02	MOS HRS/MSC ENC (AFL)		4200					17-MAY-1989 4265	8465	
									2793		
726130 72.270	NO. 2 ENGINE - GEARBOX, TRANSFER 3070093-3 P-3691 REF: EMM 72-60-01	MOS HRS/MSC ENC (AFL)		O/C	4215				31-MAY-1989 4265		
					2745				2793		
725110 72.150	NO. 2 ENGINE - IMPELLER, HIGH PRESSURE 3073394-1 0-23369-4190 REF: NO REF	MOS HRS/MSC ENC (AFL)			0				31-MAY-1989 4265	LIFE LIMIT	
			10000		0				2793	12793	
725180 72.220	NO. 2 ENGINE - NOZZLE, STAGE 1 LOW PRESSURE TURBINE 3072319 SN-UNKNOWN REF: NO REF	MOS HRS/MSC ENC (AFL)		O/C					31-MAY-1989 4265		
									2793		
725140 72.180	NO. 2 ENGINE - PLATE, HIGH PRESSURE ROTOR SEAL 3072411-1 1-18040-5077 REF: NO REF	MOS HRS/MSC ENC (AFL)			4215				31-MAY-1989 4265	LIFE LIMIT	
			10000		2745				2793	10048	

Engine Model - TFE731-3

Report Date **14-MAR-2002**

Owner Name - **R&S AIRCRAFT INVESTMENTS, LLC**

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
725040 72.070	NO. 2 ENGINE - ROTOR, HIGH PRESSURE TURBINE 307 2316 1-18040-451 REF: EMM 72-50-06	MOS HRS/MSC ENC (AFL)	7000		4215 2745					31-MAY-1989 4265 2793	LIFE LIMIT 7048	
725170 72.210	NO. 2 ENGINE - SEAL PLATE, STAGE 1 LOW PRESSURE TURBINE 307 3552 SN-UNKNOWN REF: NO REF	MOS HRS/MSC ENC (AFL)	O/C							11-FEB-1982		
725190 72.230	NO. 2 ENGINE - SEAL, LOW PRESSURE TURBINE ROTATING AIR 307 3355 SN-UNKNOWN REF: NO REF	MOS HRS/MSC ENC (AFL)	O/C		0 0 0							
725120 72.160	NO. 2 ENGINE - SEAL, ROTATING 307 2729-1 7-23 151-1814 REF: NO REF	MOS HRS/MSC ENC (AFL)	O/C		0 0 0					31-MAY-1989 4265 2793		
725150 72.190	NO. 2 ENGINE - SHAFT, FAN DRIVE 307 1955-3 IP-41464 REF: NO REF	MOS HRS/MSC ENC (AFL)	O/C		4215 2745					31-MAY-1989 4265 2793		
725130 72.170	NO. 2 ENGINE - SHAFT, HIGH PRESSURE SHOULDERED 307 2545-1 1P-39469 REF: NO REF	MOS HRS/MSC ENC (AFL)	12000		4215 2745					31-MAY-1989 4265 2793	LIFE LIMIT 12048	
725191 72.240	NO. 2 ENGINE - SUPPORT, LOW PRESSURE TURBINE ROTATING AIR SEAL 307 3764 SN-UNKNOWN REF: NO REF	MOS HRS/MSC ENC (AFL)	O/C									
725091 72.140	NO. 2 ENGINE - TIE ROD, LOW PRESSURE 307 3049-1 1P-15412 REF: EMM 72-30-10	MOS HRS/MSC ENC (AFL)	O/C		4215 2745					31-MAY-1989 4265 2793		
CHAPTER 73	ENGINE FUEL AND CONTROL											
+ 731120 73.020	NO. 2 ENGINE - REMOVE AND REPLACE FILTER ELEMENT PKG 7, 7 REF: See Workcard	MOS HRS/MSC ENC (AFL)	300							16-FEB-2001 7551 5515		

COPYRIGHT 2001 CAMP SYSTEMS INT'L

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

Engine Model - TFE731-3

Report Date **14-MAR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
732110	NO. 2 ENGINE - CONTROL UNIT, FUEL											
73.060	3070800-2	MOS								31-MAY-1989		
	A3593PT	HRS/MSC	O/C							4265		
	REF: EMM 73-20-01	ENC									2793	
	(AFL)											
732120	NO. 2 ENGINE - CHANGE PRESSURE LIMITER VALVE											
73.070	3070685-4	MOS								31-MAY-1989		
ASSOCIATED	A6760	HRS/MSC	O/C	4215						4265		
	REF: NO REF	ENC									2793	
	(AFL)			2745								
731150	NO. 2 ENGINE - COOLER, FUEL/OIL											
73.050	158610-7	MOS								31-MAY-1989		
	21-3736	HRS/MSC	O/C	4215						4265		
	REF: EMM 79-20-07	ENC									2793	
	(AFL)			2745								
731140	NO. 2 ENGINE - HEATER, FUEL											
73.040	158670-3	MOS								31-MAY-1989		
	71-2903	HRS/MSC	O/C	4215						4265		
	REF: EMM 73-10-04	ENC									2793	
	(AFL)			2745								
731110	NO. 2 ENGINE - PUMP, ENGINE FUEL											
73.010	3070850-8	MOS								31-MAY-1989		
	MX364112	HRS/MSC	O/C	4215						4265		
	REF: EMM 73-20-01	ENC									2793	
	(AFL)			2745								
+ 731120	NO. 2 ENGINE - REMOVE AND REPLACE FILTER ELEMENT											
73.020	PKG 7, 7	MOS								16-FEB-2001		
ASSOCIATED		HRS/MSC	300							7551		
	REF: See Workcard	ENC									5515	
	(AFL)											
732160	NO. 2 ENGINE - TRANSMITTER, FUEL FLOW											
73.110	883709-1	MOS								31-MAY-1989		
	SN-UNKNOWN	HRS/MSC	O/C	4215						4265		
	REF: NO REF	ENC									2793	
	(AFL)			2745								
731130	NO. 2 ENGINE - VALVE, FLOW DIVIDER/DRAIN											
73.030	394366-4	MOS								31-MAY-1989		
	SN-UNKNOWN	HRS/MSC	O/C	4215						4265		
	REF: NO REF	ENC									2793	
	(AFL)			2745								
732110	NO. 2 ENGINE - CHANGE FUEL CONTROL UNIT											
73.060	3070800-2	MOS								31-MAY-1989		
ASSOCIATED	A3593PT	HRS/MSC	O/C							4265		
	REF: EMM 73-20-01	ENC									2793	
	(AFL)											

Engine Model - TFE731-3

Report Date **14-MAR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
732120	NO. 2 ENGINE - CHANGE PRESSURE LIMITER VALVE										
73.070	3070685-4	MOS							31-MAY-1989		
ASSOCIATED	A6760	HRS/MSC	O/C	4215					4265		
	REF: NO REF	ENC (AFL)		2745					2793		
732120	NO. 2 ENGINE - VALVE, PRESSURE LIMITER										
73.070	3070685-4	MOS							31-MAY-1989		
	A6760	HRS/MSC	O/C	4215					4265		
	REF: NO REF	ENC (AFL)		2745					2793		
732140	NO. 2 ENGINE - VALVE, SOLENOID CONTROL										
73.090	109696-3-1	MOS							31-MAY-1989		
	P-3683	HRS/MSC	O/C	4215					4265		
	REF: EMM 76-10-01	ENC (AFL)		2745					2793		
732130	NO. 2 ENGINE - VALVE, SURGE BLEED										
73.080	978812-4-1	MOS							31-MAY-1989		
	P-3683	HRS/MSC	O/C	4215					4265		
	REF: EMM 76-10-01	ENC (AFL)		2745					2793		
CHAPTER 74	IGNITION										
+ 742120	NO. 2 ENGINE - INSPECT 6 O'CLOCK IGNITER PLUG										
74.040		MOS							26-JUL-2000		
	REF: See Workcard	HRS/MSC	800						7325	8125	
		ENC (AFL)							5360		
+ 742140	NO. 2 ENGINE - INSPECT 7 O'CLOCK IGNITER PLUG										
74.060		MOS							26-JUL-2000		
	REF: See Workcard	HRS/MSC	800						7325	8125	
		ENC (AFL)							5360		
+ 741120	NO. 2 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM										
74.020		MOS							26-JUL-2000		
	REF: EMM 74-00-01	HRS/MSC	800						7325	8125	
		ENC (AFL)							5360	1	
742110	NO. 2 ENGINE - IGNITER PLUG, 6 O'CLOCK										
74.030	3071589-2	MOS							17-OCT-1998		
	SN-UNKNOWN	HRS/MSC	O/C						6520		
	REF: EMM 74-00-01	ENC (AFL)							4889		
+ 742120	NO. 2 ENGINE - INSPECT 6 O'CLOCK IGNITER PLUG										
74.040		MOS							26-JUL-2000		
ASSOCIATED		HRS/MSC	800						7325	8125	
	REF: See Workcard	ENC (AFL)							5360		

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Engine Model - TFE731-3

Report Date **14-MAR-2002**

Owner Name - **R&S AIRCRAFT INVESTMENTS, LLC**
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
742130	NO. 2 ENGINE - IGNITER PLUG, 7 O'CLOCK											
74.050	3071589-2	MOS							09-NOV-1996			
	SN-UNKNOWN	HRS/MSC	O/C						5951			
	REF: EMM 74-00-01	ENC										
		(AFL)							4589			
+ 742140	NO. 2 ENGINE - INSPECT 7 O'CLOCK IGNITER PLUG											
74.060		MOS							26-JUL-2000			
ASSOCIATED		HRS/MSC	800						7325	8125		
	REF: See Workcard	ENC										
		(AFL)							5360			
741110	NO. 2 ENGINE - UNIT, IGNITION											
74.010	3070378-2	MOS							31-MAY-1989			
	SN-UNKNOWN	HRS/MSC	O/C	1142					4265			
	REF: EMM 74-00-01	ENC										
		(AFL)							2793			
+ 741120	NO. 2 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM											
74.020		MOS							26-JUL-2000			
ASSOCIATED		HRS/MSC	800						7325	8125	1	
	REF: EMM 74-00-01	ENC										
		(AFL)							5360			
CHAPTER 75	AIR											
751010	NO. 2 ENGINE - VALVE, ANTI-ICE SHUTOFF											
75.010	978944-1-1	MOS							31-MAY-1989			
	SN-UNKNOWN	HRS/MSC	O/C	4215					4265			
	REF: EMM 75-10-01	ENC										
		(AFL)							2793			
CHAPTER 77	ENGINE INDICATING											
772110	NO. 2 ENGINE - HARNESS, ITT THERMOCOUPLE											
77.030	3071849-3	MOS							31-MAY-1989			
	9-20219-358	HRS/MSC	O/C						4265			
	REF: EMM 77-20-01	ENC										
		(AFL)							2793			
771120	NO. 2 ENGINE - TRANSDUCER, HIGH PRESSURE (N2)											
77.020	3070722-2	MOS							31-MAY-1989			
	SN-UNKNOWN	HRS/MSC	O/C	4215					4265			
	REF: EMM 77-10-05	ENC										
		(AFL)							2793			
771110	NO. 2 ENGINE - TRANSDUCER, LOW PRESSURE (N1)											
77.010	3071928-5	MOS							31-MAY-1989			
	SN-UNKNOWN	HRS/MSC	O/C	4215					4265			
	REF: EMM 77-10-03	ENC										
		(AFL)							2793			
CHAPTER 79	OIL											

Report Date **14-MAR-2002**

Engine Model - **TFE731-3**

Owner Name - **R&S AIRCRAFT INVESTMENTS, LLC**

A/C Serial #: **368** A/C Reg. #: **N368MD**

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
+ 790110 79.010	NO. 2 ENGINE - ANALYZE ENGINE OIL PKG 5, 5,7, 7	MOS HRS/MSC ENC (AFL)	150							26-JUN-2001 7687	1 5594	
	REF: EMM 72-00-00 TR 72-61											
790120 79.020	NO. 2 ENGINE - CHANGE OIL	MOS HRS/MSC ENC (AFL)	1400							17-OCT-1998 6520 7920	4889	
	REF: See Workcard											
+ 790130 79.030	NO. 2 ENGINE - INSPECT CHIP DETECTOR PKG 5, 5,7, 7	MOS HRS/MSC ENC (AFL)	150							26-JUN-2001 7687	5594	
	REF: EMM 72-00-00 TR 72-61											
792150 79.080	NO. 2 ENGINE - COOLER, OIL LOWER LEFT 159900-1 SN-UNKNOWN REF: EMM 79-20-09	MOS HRS/MSC ENC (AFL)	O/C							31-MAY-1989 4265	2793	
792160 79.090	NO. 2 ENGINE - COOLER, OIL LOWER RIGHT 159910-1 SN-UNKNOWN REF: EMM 79-20-09	MOS HRS/MSC ENC (AFL)	O/C	4215						31-MAY-1989 4265	2793	
792140 79.070	NO. 2 ENGINE - COOLER, OIL UPPER 158600-4 SN-UNKNOWN REF: EMM 79-20-09	MOS HRS/MSC ENC (AFL)	O/C	4215						31-MAY-1989 4265	2793	
792110 79.040	NO. 2 ENGINE - PUMP, OIL 3071949-7 0683 REF: EMM 79-20-03	MOS HRS/MSC ENC (AFL)	O/C							31-MAY-1989 4265	2793	
790120 79.020 ASSOCIATED	NO. 2 ENGINE - CHANGE OIL	MOS HRS/MSC ENC (AFL)	1400							17-OCT-1998 6520 7920	4889	
	REF: See Workcard											
793120 79.120	NO. 2 ENGINE - SWITCH, OIL PRESSURE 3-833518 1041 REF: NO REF	MOS HRS/MSC ENC (AFL)	O/C	482						31-MAY-1989 4265	2793	

COPYRIGHT 2001 CAMP SYSTEMS INT'L

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:40:05 PM

Engine Model - TFE731-3

Report Date **14-MAR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
793110	NO. 2 ENGINE - TRANSMITTER, OIL PRESSURE											
79.110	101-412-80-13	MOS								31-MAY-1989		
	SN-UNKNOWN	HRS/MSC	O/C	4215						4265		
	REF: NO REF	ENC (AFL)								2793		
792120	NO. 2 ENGINE - VALVE, OIL FILTER BYPASS											
79.050	3070000NP69	MOS								31-MAY-1989		
	SN-UNKNOWN	HRS/MSC	O/C	4215						4265		
	REF: EMM 79-30-01	ENC (AFL)								2793		
792130	NO. 2 ENGINE - VALVE, PRESSURE BREATHER											
79.060	3075323-1	MOS								04-FEB-1994		
	6376	HRS/MSC	O/C		0					5390		
	REF: EMM 79-20-02	ENC (AFL)								4040		



AIRCRAFT Status Report (AD/SI)

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
AIRCRAFT											
AD 1974-08-09 R2	AIRWORTHINESS DIRECTIVE TO PREVENT POSSIBLE FIRES THAT COULD RESULT FROM SMOKING MATERIALS BEING DROPPED INTO LAVATORY PAPER OR LINEN WASTE RECEPTACLES									F4	
		MOS						17-JAN-2001			
		HRS/MSC	1000					7494	8494		
	REF:	AFL						5466			
	Method of Compliance: OPEN										
AD 1989-12-08	AIRWORTHINESS DIRECTIVE TO DETECT CRACKS IN THE HINGE LUGS OF THE HORIZONTAL STABILIZER AFT SPAR SPLICE FITTING (HINGE ASSEMBLY)										
		MOS						17-JAN-2001			
		HRS/MSC	300					7494	7794		
	REF: See Workcard	AFL						5466			
	Method of Compliance: OPEN										
AD 1996-24-11 LEFT AILERON	AIRWORTHINESS DIRECTIVE TO PREVENT EXCESSIVE WEAR OF THE AILERON PUSH-PULL TUBE, WHICH COULD RESULT IN UNEVEN MOVEMENT OF THE CONTROL WHEEL, PERFORATION OF THE AILERON PUSH-PULL TUBE, AND CONSEQUENT REDUCED ROLL CONTROL OF THE AIRPLANE									W1	
		MOS						26-JUL-2000			
		HRS/MSC	600					7325	7925		
	REF: AD	AFL						5360			
	Method of Compliance: OPEN										
SB 1124-27-129 LEFT AILERON	FLIGHT CONTROLS SERVICE BULLETIN									W1	
		MOS						26-JUL-2000			
ASSOCIATED		HRS/MSC	600					7325	7925		
	REF: BULLETINS	AFL						5360			
	Method of Compliance: OPEN										
AD 1996-24-11 RIGHT AILERON	AIRWORTHINESS DIRECTIVE TO PREVENT EXCESSIVE WEAR OF THE AILERON PUSH-PULL TUBE, WHICH COULD RESULT IN UNEVEN MOVEMENT OF THE CONTROL WHEEL, PERFORATION OF THE AILERON PUSH-PULL TUBE, AND CONSEQUENT REDUCED ROLL CONTROL OF THE AIRPLANE									W2	
		MOS						26-JUL-2000			
		HRS/MSC	600					7325	7925		
	REF: AD	AFL						5360			
	Method of Compliance: OPEN										
SB 1124-27-129 RIGHT AILERON	FLIGHT CONTROLS SERVICE BULLETIN									W2	
		MOS						26-JUL-2000			
ASSOCIATED		HRS/MSC	600					7325	7925		
	REF: BULLETINS	AFL						5360			
	Method of Compliance: OPEN										
AD 1998-06-10	AIRWORTHINESS DIRECTIVE TO PREVENT FAILURE OF THE HYDRAULIC FUSE TO OPERATE PROPERLY IN THE EVENT OF AN EXTERNAL LEAK DOWNSTREAM OF THE FUSE, WHICH COULD RESULT IN LOSS OF HYDRAULIC SYSTEMS										
		MOS	36					06-NOV-2001	06-NOV-2004		
		HRS/MSC	1200					7774	8974		
	REF: AD	AFL						5641			
	Method of Compliance: OPEN										

Aircraft Model - 1124 WESTWIND

Report Date 14-MAR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
					TSN	TSO	TSR	TSI	ADJ			
AD	2002-01-26	AIRWORTHINESS DIRECTIVE TO PREVENT FAILURE OF ATTACHMENT BOLTS DUE TO FATIGUE, WHICH COULD RESULT IN SEPARATION OF THE ENGINE INLET COWL AND AFT NACELLE, AND CONSEQUENT DAMAGE TO THE HORIZONTAL OR VERTICAL STABILIZER	MOS								MANDATORY	
		REF:	HRS/MS	DUE							50	
		Method of Compliance: OPEN	AFL									
SB	ASB1124-54A-138	SERVICE BULLETIN	MOS								MANDATORY	
	ASSOCIATED	REF:	HRS/MS	A/R								
		Method of Compliance: OPEN	AFL									
SB	1124-27-129 LEFT AILERON	SERVICE BULLETIN FLIGHT CONTROLS	MOS									W1
		REF: BULLETINS	HRS/MS	600					26-JUL-2000			
		Method of Compliance: OPEN	AFL						7325	7925		
									5360			
SB	1124-27-129 RIGHT AILERON	SERVICE BULLETIN FLIGHT CONTROLS	MOS									W2
		REF: BULLETINS	HRS/MS	600					26-JUL-2000			
		Method of Compliance: OPEN	AFL						7325	7925		
									5360			
SB	1124-30-036 PART II	SERVICE BULLETIN ICE AND RAIN PROTECTION	MOS									F3
		PKG 1, 2, 3	HRS/MS	150					26-JUN-2001			
		REF: See Workcard	AFL						7687	7837		
		Method of Compliance: OPEN							5594			
SB	1124-55-020 R2	SERVICE BULLETIN STABILIZERS	MOS									T1
		PKG 2, 3	HRS/MS	300					26-JUN-2001			
		REF: See Workcard	AFL						7687	7987		
		Method of Compliance: OPEN							5594			
SB	900280	SERVICE BULLETIN SB WW-24-28A	MOS									L3
		REF: See Workcard	HRS/MS	1200					22-FEB-2000			
		Method of Compliance: OPEN	AFL						7107			
									5232			
SB	911390	SERVICE BULLETIN SB1124-32-139 UPR STRG	MOS									
		PKG 3	HRS/MS	800					26-JUL-2000			
		REF:	AFL						7325	8125		
		Method of Compliance: OPEN							5360			
SB	950920	SERVICE BULLETIN SL WW-2492 HYD HOSE INSP	MOS									
		PKG 1, 2, 3	HRS/MS	200					26-JUN-2001			
		REF:	AFL						7687	7887		
		Method of Compliance: OPEN							5594			

? - Insufficient Information
+ Task exists in FAA Manual
3/19/2002 11:41:14 PM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
SB 950941	SERVICE BULLETIN SLWW-2494 REV 3 LMG BOLTS	MOS									L1	
	REF: See Workcard	HRS/MS	300						26-JUN-2001			
	Method of Compliance: OPEN	AFL							7687	7987		
									5594			
SB 950942	SERVICE BULLETIN SLWW-2494 REV 3 RMG BOLTS	MOS									L2	
	REF: See Workcard	HRS/MS	300						26-JUN-2001			
	Method of Compliance: OPEN	AFL							7687	7987		
									5594			
SB 972850U	SERVICE BULLETIN SB 731-A72-3668 #1 ENG	MOS									RECOMMENDED	
	REF:	HRS/MS	A/R								31-DEC-2002	
		AFL										
SB 972851U	SERVICE BULLETIN SB 731-A72-3668 #2 ENG	MOS									RECOMMENDED	
	REF:	HRS/MS	A/R								31-DEC-2002	
		AFL										
SB 972B40U	SERVICE BULLETIN GSBA72-3569 R/E FAN ROTOR	MOS										
	REF:	HRS/MS	A/R									
	Method of Compliance: OPEN	AFL								5722		

Engine Model - TFE731-3

Report Date **14-MAR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
ENGINE NO. 1											
AD 2000-15-09	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE HPC IMPELLER										
		MOS							10-OCT-2000		
		HRS/MS	4200								
	REF:	ENC									
	Method of Compliance: OPEN										
AD 2001-23-09	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE TO PREVENT FAILURE OF THE FAN ROTOR DISC DUE TO FATIGUE CRACKING IN THE DOVETAIL SLOTS								MANDATORY		
		MOS							31-DEC-2002		
		HRS/MS	DUE								
	REF:	ENC									
	Method of Compliance: OPEN										
SB TFE731-A72-3668	NO. 1 ENGINE - REMOVE FAN ROTOR DISC FROM SERVICE SERVICE BULLETIN								MANDATORY		
		MOS							31-DEC-2002		
	ASSOCIATED	HRS/MS	A/R								
	REF: BULLETINS	ENC									
	Method of Compliance: OPEN										

Engine Model - TFE731-3

Report Date **14-MAR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
ENGINE NO. 2												
AD 2000-15-09	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE HPC IMPELLER											
		MOS										10-OCT-2000
		HRS/MSC	4200									
	REF:	ENC										
	Method of Compliance: OPEN											
AD 2001-23-09	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE TO PREVENT FAILURE OF THE FAN ROTOR DISC DUE TO FATIGUE CRACKING IN THE DOVETAIL SLOTS											MANDATORY 31-DEC-2002
		MOS										
		HRS/MSC	DUE									
	REF:	ENC										
	Method of Compliance: OPEN											
SB TFE731-A72-3668	NO. 2 ENGINE - REMOVE FAN ROTOR DISC FROM SERVICE SERVICE BULLETIN											MANDATORY 31-DEC-2002
		MOS										
ASSOCIATED		HRS/MSC	A/R									
	REF: BULLETINS	ENC										
	Method of Compliance: OPEN											

A/C Serial No.: 368 A/C Regn No.: N368MD Model:1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

Report Date **14-MAR-2002**

Compliance

From 01/01/2001

To 3/14/2002

ITEM NO PART NO.	DESCRIPTION SERIAL NO.	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED				COMPONENT TIMES AFTER REMOVAL			
		C/W	TSN	TSO	TSR	C/W	TSN	TSO	TSR
CHAPTER --GENERAL									
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN								
		MOS	1/17/2001			TECH :		INSP :	
		HRS	7494					LABOR HRS :	
		AFL	5466					SERVICE REMARKS	--
CHAPTER 05-TIME LIMITS/MAINTENANCE CHECKS									
050150U	200 HOUR INSPECTION								
		MOS	1/17/2001			TECH :		INSP :	
		HRS	7494					LABOR HRS :	
		AFL	5466					SERVICE REMARKS	--
CHAPTER 10-PARKING, MOORING, STORE AND RET TO SERV									
100310	CHECK AIRWORTHY DIRECTIVES								
		MOS	1/17/2001			TECH :		INSP :	
		HRS	7494					LABOR HRS :	
		AFL	5466					SERVICE REMARKS	--
100320	CHECK SERVICE BULLETINS								
		MOS	1/17/2001			TECH :		INSP :	
		HRS	7494					LABOR HRS :	
		AFL	5466					SERVICE REMARKS	--
100330	CHECK SERVICE LETTERS								
		MOS	1/17/2001			TECH :		INSP :	
		HRS	7494					LABOR HRS :	
		AFL	5466					SERVICE REMARKS	--
CHAPTER 12-SERVICING									
120150	CHECK PRE-FLIGHT								
		MOS	1/17/2001			TECH :		INSP :	
		HRS	7494					LABOR HRS :	
		AFL	5466					SERVICE REMARKS	--
120160	CHECK NO.1 ENGINE PREFLIGHT COMPLETE								
		MOS	2/16/2001			TECH :		INSP :	
		HRS	7551					LABOR HRS :	
		AFL	5515					SERVICE REMARKS	--
120161	CHECK NO.2 ENGINE PREFLIGHT COMPLETE								
		MOS	2/16/2001			TECH :		INSP :	
		HRS	7551					LABOR HRS :	
		AFL	5515					SERVICE REMARKS	--
CHAPTER 21-AIR CONDITIONING									
210622	INSPECT 35 DEGREE TEMPERATURE SENSOR 35 DEGREE DUCT SENSOR								
		MOS	1/17/2001			TECH :		INSP :	
		HRS	7494					LABOR HRS :	
		AFL	5466					SERVICE REMARKS	--
210671	CLEAN/REPLACE WATER SEPARATOR CONDENSER/FILTER								
		MOS	1/17/2001			TECH :		INSP :	
		HRS	7494					LABOR HRS :	
		AFL	5466					SERVICE REMARKS	--
210681	CHANGE COOLING TURBINE OIL								
		MOS	1/17/2001			TECH :		INSP :	
		HRS	7494					LABOR HRS :	
		AFL	5466					SERVICE REMARKS	--
CHAPTER 24-ELECTRICAL POWER									

A/C Serial No.: 368 A/C Regn No.: N368MD Model:1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

Report Date 14-MAR-2002

Compliance

From 01/01/2001

To 3/14/2002

ITEM NO PART NO.	DESCRIPTION SERIAL NO.	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED				COMPONENT TIMES AFTER REMOVAL				TECH :	INSP :
		C/W	TSN	TSO	TSR	C/W	TSN	TSO	TSR		
240116 23065-018-1	CHANGE NO. 1 STARTER GENERATOR 3684	MOS	1/17/2001	0		11/6/2001	10			REASON : WORN	LABOR HRS :
		HRS	7494	0		7774	280			PRICE : 0	
		AFL	5466	0		5641	175				
240118	INSPECT NO. 1 STARTER GENERATOR	MOS	6/26/2001								
		HRS	7687								
		AFL	5594							SERVICE REMARKS	--
240121	CHECK NO. 1 STARTER GENERATOR BRUSH WEAR/TENSION	MOS	6/26/2001								
		HRS	7687								
		AFL	5594							SERVICE REMARKS	--
240123	INSPECT NO. 1 STARTER GENERATOR SPLINE	MOS	6/26/2001								
		HRS	7687								
		AFL	5594							SERVICE REMARKS	--
240128	INSPECT NO. 2 STARTER GENERATOR	MOS	6/26/2001								
		HRS	7687								
		AFL	5594							SERVICE REMARKS	--
240131	CHECK NO. 2 STARTER GENERATOR BRUSH WEAR/TENSION	MOS	6/26/2001								
		HRS	7687								
		AFL	5594							SERVICE REMARKS	--
240133	INSPECT NO. 2 STARTER GENERATOR SPLINE	MOS	6/26/2001								
		HRS	7687								
		AFL	5594							SERVICE REMARKS	--
240161	CHECK LEFT BATTERY ELECTROLYTE LEVEL	MOS	1/17/2001								
		HRS	7494								
		AFL	5466							SERVICE REMARKS	--
240166	DEEP CYCLE LEFT BATTERY	MOS	6/26/2001								
		HRS	7687								
		AFL	5594							SERVICE REMARKS	--
240176	CHECK RIGHT BATTERY ELECTROLYTE LEVEL	MOS	1/17/2001								
		HRS	7494								
		AFL	5466							SERVICE REMARKS	--
240181	DEEP CYCLE RIGHT BATTERY	MOS	6/26/2001								
		HRS	7687								
		AFL	5594							SERVICE REMARKS	--
240203	FUNCTIONALLY CHECK EXTERNAL POWER RECEPTACLE BATTERY TEMPERATURE AND WARNING SYSTEM	MOS	1/17/2001								
		HRS	7494								
		AFL	5466							SERVICE REMARKS	--

CHAPTER 26-FIRE PROTECTION

260169 VISUAL INSPECTION COCKPIT PORTABLE EXTINGUISHER COCKPIT FIRE EXTINGUISHER

A/C Serial No.: 368 A/C Regn No.: N368MD Model:1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

Report Date 14-MAR-2002

Compliance From 01/01/2001 To 3/14/2002

ITEM NO PART NO.	DESCRIPTION SERIAL NO.	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED				COMPONENT TIMES AFTER REMOVAL				TECH :	INSP :	LABOR HRS :	SERVICE REMARKS
		C/W	TSN	TSO	TSR	C/W	TSN	TSO	TSR				
		MOS	6/26/2001										
		HRS	7687										
		AFL	5594										
260174	INSPECT COCKPIT PORTABLE EXTINGUISHER COCKPIT FIRE EXTINGUISHER	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
260180	VISUAL INSPECTION CABIN PORTABLE EXTINGUISHER CABIN FIRE EXTINGUISHER	MOS	6/26/2001										
		HRS	7687										
		AFL	5594										
260184	INSPECT CABIN PORTABLE EXTINGUISHER CABIN FIRE EXTINGUISHER	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
CHAPTER 27-FLIGHT CONTROLS													
270158	INSPECT RUDDER TRIM TAB FREEPLAY	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
270193	INSPECT LEFT ELEVATOR SKIN SEPARATION	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
270203	INSPECT RIGHT ELEVATOR SKIN SEPARATION	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
270213	LUBRICATE ELEVATOR ATTACH POINTS	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
270214	LUBRICATE AFT HINGE FITTING BEARINGS	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
270215	LUBRICATE FORWARD SCISSOR ASSEMBLY	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
270237	INSPECT LEFT FLAP/VANE LEFT FLAP VANE	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
270240	INSPECT LEFT FLAP/VANE LEFT FLAP HINGE AND BEARING 200 HOURS	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
270242	INSPECT RIGHT FLAP/VANE RIGHT FLAP HINGE AND BEARING 200 HOURS	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										

A/C Serial No.: 368 A/C Regn No.: N368MD Model:1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

Report Date 14-MAR-2002

Compliance

From 01/01/2001

To 3/14/2002

ITEM NO PART NO.	DESCRIPTION SERIAL NO.	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED				COMPONENT TIMES AFTER REMOVAL			
		C/W	TSN	TSO	TSR	C/W	TSN	TSO	TSR
270247	INSPECT RIGHT FLAP/VANE								
		MOS	1/17/2001						
		HRS	7494						
		AFL	5466						
						TECH :		INSP :	
								LABOR HRS :	
								SERVICE REMARKS	--
270335	OPERATIONAL CHECK SPEED BRAKES AND LIFT DUMPERS								
		MOS	1/17/2001						
		HRS	7494						
		AFL	5466						
						TECH :		INSP :	
								LABOR HRS :	
								SERVICE REMARKS	--
CHAPTER 28-FUEL									
281150	CHECK OPERATION OF FUEL BOOST PUMPS								
		MOS	1/17/2001						
		HRS	7494						
		AFL	5466						
						TECH :		INSP :	
								LABOR HRS :	
								SERVICE REMARKS	--
CHAPTER 29-HYDRAULIC POWER									
290143	INSPECT/LUBRICATE NO. 1 HYDRAULIC PUMP NO.1 ENGINE HYDRAULIC PUMP SPLINES								
		MOS	1/17/2001						
		HRS	7494						
		AFL	5466						
						TECH :		INSP :	
								LABOR HRS :	
								SERVICE REMARKS	--
290178	INSPECT/LUBRICATE NO. 2 HYDRAULIC PUMP NO.2 ENGINE HYDRAULIC PUMP SPLINES								
		MOS	1/17/2001						
		HRS	7494						
		AFL	5466						
						TECH :		INSP :	
								LABOR HRS :	
								SERVICE REMARKS	--
CHAPTER 30-ICE AND RAIN PROTECTION									
300147	INSPECT PILOT WINDSHIELD CYCLING CONTACTOR								
		MOS	1/17/2001						
		HRS	7494						
		AFL	5466						
						TECH :		INSP :	
								LABOR HRS :	
								SERVICE REMARKS	--
300150	INSPECT COPILOT WINDSHIELD CYCLING CONTACTOR								
		MOS	1/17/2001						
		HRS	7494						
		AFL	5466						
						TECH :		INSP :	
								LABOR HRS :	
								SERVICE REMARKS	--
300163	INSPECT WINDSHIELD WIPER ASSEMBLY								
		MOS	1/17/2001						
		HRS	7494						
		AFL	5466						
						TECH :		INSP :	
								LABOR HRS :	
								SERVICE REMARKS	--
300170	OPERATIONAL TEST P2T2 SENSOR HEATER								
		MOS	1/17/2001						
		HRS	7494						
		AFL	5466						
						TECH :		INSP :	
								LABOR HRS :	
								SERVICE REMARKS	--
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN								
		MOS	1/17/2001						
		HRS	7494						
		AFL	5466						
						TECH :		INSP :	
								LABOR HRS :	
								SERVICE REMARKS	--
CHAPTER 32-LANDING GEAR									
320106	LUBRICATE NOSE GEAR ASSEMBLY NOSE GEAR/DOORS								
		MOS	1/17/2001						
		HRS	7494						
		AFL	5466						
						TECH :		INSP :	
								LABOR HRS :	
								SERVICE REMARKS	--
320156	INSPECT/CLEAN/LUBRICATE NOSE GEAR LEFT WHEEL BEARINGS								

A/C Serial No.: 368 A/C Regn No.: N368MD Model:1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

Report Date **14-MAR-2002**

Compliance From 01/01/2001 To 3/14/2002

ITEM NO PART NO.	DESCRIPTION SERIAL NO.	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED				COMPONENT TIMES AFTER REMOVAL				TECH :	INSP :
		C/W	TSN	TSO	TSR	C/W	TSN	TSO	TSR		
		MOS	1/17/2001								LABOR HRS :
		HRS	7494								SERVICE REMARKS --
		AFL	5466								
320158	INSPECT/CLEAN/LUBRICATE NOSE GEAR RIGHT WHEEL BEARINGS	MOS	1/17/2001								LABOR HRS :
		HRS	7494								SERVICE REMARKS --
		AFL	5466								
320201	INSPECT NOSE GEAR (A)	MOS	1/17/2001								LABOR HRS :
		HRS	7494								SERVICE REMARKS --
		AFL	5466								
320606	LUBRICATE LEFT MAIN GEAR ASSEMBLY LEFT MAIN GEAR	MOS	1/17/2001								LABOR HRS :
		HRS	7494								SERVICE REMARKS --
		AFL	5466								
320676	INSPECT/LUBRICATE LEFT MAIN GEAR INBOARD WHEEL HALF LEFT MAIN GEAR INBOARD WHEEL BEARINGS	MOS	1/17/2001								LABOR HRS :
		HRS	7494								SERVICE REMARKS --
		AFL	5466								
320680	INSPECT/LUBRICATE LEFT MAIN GEAR OUTBOARD WHEEL HALF LEFT MAIN GEAR OUTBOARD WHEEL BEARINGS	MOS	1/17/2001								LABOR HRS :
		HRS	7494								SERVICE REMARKS --
		AFL	5466								
320691	INSPECT LEFT MAIN GEAR/WELL (A)	MOS	1/17/2001								LABOR HRS :
		HRS	7494								SERVICE REMARKS --
		AFL	5466								
321106	LUBRICATE RIGHT MAIN GEAR ASSEMBLY RIGHT MAIN GEAR	MOS	1/17/2001								LABOR HRS :
		HRS	7494								SERVICE REMARKS --
		AFL	5466								
321176	INSPECT/LUBRICATE RIGHT MAIN GEAR INBOARD WHEEL HALF RIGHT MAIN GEAR INBOARD WHEEL BEARINGS	MOS	1/17/2001								LABOR HRS :
		HRS	7494								SERVICE REMARKS --
		AFL	5466								
321180	INSPECT/LUBRICATE RIGHT MAIN GEAR OUTBOARD WHEEL HALF RIGHT MAIN GEAR OUTBOARD WHEEL BEARINGS	MOS	1/17/2001								LABOR HRS :
		HRS	7494								SERVICE REMARKS --
		AFL	5466								
321191	INSPECT RIGHT MAIN GEAR OUTBOARD WHEEL HALF RIGHT MAIN GEAR/WELL (A)	MOS	1/17/2001								LABOR HRS :
		HRS	7494								SERVICE REMARKS --
		AFL	5466								
322113	CHANGE LEFT MAIN GEAR BRAKE	MOS				1/17/2001					LABOR HRS :
5002805-3	12153-6	HRS				7494					REASON : WORN
		AFL				5466					PRICE : 0
322116	INSPECT/CHECK LEFT MAIN GEAR BRAKE LEFT BRAKE LININGS	MOS	1/17/2001								LABOR HRS :
		HRS	7494								SERVICE REMARKS --
		AFL	5466								
322128	CHANGE RIGHT MAIN GEAR BRAKE										

A/C Serial No.: 368 A/C Regn No.: N368MD Model:1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

Report Date 14-MAR-2002

Compliance

From 01/01/2001

To 3/14/2002

ITEM NO PART NO.	DESCRIPTION SERIAL NO.	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED				COMPONENT TIMES AFTER REMOVAL				TECH :	REASON :	INSP :
		C/W	TSN	TSO	TSR	C/W	TSN	TSO	TSR			
5002805-3	1140	MOS				1/17/2001						INSP :
		HRS				7494					WORN	LABOR HRS :
		AFL				5466					0	
322131	INSPECT/CHECK RIGHT MAIN GEAR BRAKE RIGHT BRAKE LININGS	MOS	1/17/2001							TECH :		INSP :
		HRS	7494									LABOR HRS :
		AFL	5466									SERVICE REMARKS --
322156	INSPECT/CLEAN LEFT ANTI-SKID DETECTOR	MOS	1/17/2001							TECH :		INSP :
		HRS	7494									LABOR HRS :
		AFL	5466									SERVICE REMARKS --
322171	INSPECT/CLEAN RIGHT ANTI-SKID DETECTOR	MOS	1/17/2001							TECH :		INSP :
		HRS	7494									LABOR HRS :
		AFL	5466									SERVICE REMARKS --
322174	OPERATIONAL CHECK ANTI-SKID LIGHTS	MOS	1/17/2001							TECH :		INSP :
		HRS	7494									LABOR HRS :
		AFL	5466									SERVICE REMARKS --
322206	FUNCTIONAL TEST EMERGENCY GEAR EXTENSION CONTROL CABLE	MOS	1/17/2001							TECH :		INSP :
		HRS	7494									LABOR HRS :
		AFL	5466									SERVICE REMARKS --
CHAPTER 33-LIGHTS												
330228	CHARGE EMERGENCY LIGHT BATTERY	MOS	6/26/2001							TECH :		INSP :
		HRS	7687									LABOR HRS :
		AFL	5594									SERVICE REMARKS --
CHAPTER 34-NAVIGATION												
340121	DRAIN PITOT/STATIC SYSTEM	MOS	1/17/2001							TECH :		INSP :
		HRS	7494									LABOR HRS :
		AFL	5466									SERVICE REMARKS --
344616	INSPECT EMERGENCY GYRO POWER SUPPLY BATTERY EMERGENCY POWER SUPPLY BATTERY/STAND-BY ATTITUDE GYRO	MOS	6/26/2001							TECH :		INSP :
		HRS	7687									LABOR HRS :
		AFL	5594									SERVICE REMARKS --
CHAPTER 52-DOORS												
520106	INSPECT/LUBRICATE CABIN ENTRANCE DOOR	MOS	1/17/2001							TECH :		INSP :
		HRS	7494									LABOR HRS :
		AFL	5466									SERVICE REMARKS --
520116	OPERATIONAL CHECK CABIN ENTRANCE DOOR	MOS	1/17/2001							TECH :		INSP :
		HRS	7494									LABOR HRS :
		AFL	5466									SERVICE REMARKS --
CHAPTER 53-FUSELAGE												
530101	INSPECT FUSELAGE (A)	MOS	1/17/2001							TECH :		INSP :
		HRS	7494									LABOR HRS :
		AFL	5466									SERVICE REMARKS --

A/C Serial No.: 368 A/C Regn No.: N368MD Model:1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

Report Date **14-MAR-2002**

Compliance From 01/01/2001 To 3/14/2002

ITEM NO PART NO.	DESCRIPTION SERIAL NO.	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED				COMPONENT TIMES AFTER REMOVAL				TECH :	INSP :	LABOR HRS :	SERVICE REMARKS
		C/W	TSN	TSO	TSR	C/W	TSN	TSO	TSR				
530116	INSPECT NOSE COMPARTMENT (A)	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
530131	INSPECT COCKPIT (A)	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
530146	INSPECT CABIN (A)	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
530161	INSPECT REAR COMPARTMENT (A)	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
CHAPTER 54-NACELLES/PYLONS													
540101U	INSPECT NO. 1 ENGINE NACELLE/PYLON (A)	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
540121U	INSPECT NO. 2 ENGINE NACELLE/PYLON (A)	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
CHAPTER 55-STABILIZERS													
550101	INSPECT EMPENNAGE (A)	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
550656	CHECK HORIZONTAL STABILIZER AFT SPAR SPLICE-HINGE FITTING OUTBOARD LUGS FOR CRACKS	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
CHAPTER 57-WINGS													
570101	INSPECT LEFT WING (A)	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
570106	INSPECT LEFT AILERON BELLCRANK	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
570116	INSPECT RIGHT WING (A)	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
570120	INSPECT RIGHT AILERON BELLCRANK	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										

Aircraft Model - 1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

MASTER & C/W
THE FOLLOWING INFORMATION IS ACCURATE AND CURRENT TO THE BEST KNOWLEDGE AND ABILITY OF CSI
HOWEVER, CAMP SHALL NOT BE RESPONSIBLE OR LIABLE FOR ANY ERRORS CONTAINED IN THIS REPORT.

ITEM NO	EFFECTIVE DATE	TASK DESCRIPTION	C/W Date	DISPOSITION
		METHOD OF COMPLIANCE		
AIRCRAFT				
AD	1972-19-04	AIRWORTHINESS DIRECTIVE TO PREVENT A POSSIBLE BATTERY FIRE THAT MAY RESULT FROM OVERHEATING CAUSED BY AN UNDETECTED BATTERY FAILURE	No Data	
		OPEN		
AD	1974-08-09 R2	AIRWORTHINESS DIRECTIVE TO PREVENT POSSIBLE FIRES THAT COULD RESULT FROM SMOKING MATERIALS BEING DROPPED INTO LAVATORY PAPER OR LINEN WASTE RECEPTACLES	01/17/2001	
		REPEAT OPEN		
AD	1980-01-05 R1	AIRWORTHINESS DIRECTIVE TO PREVENT FAILURE TO OPEN OF THE FLIGHT CREW AND ATTENDANTS' SEAT BELTS	No Data	
		OPEN		
AD	1980-18-08	AIRWORTHINESS DIRECTIVE TO PREVENT LOSS OF EMERGENCY ELECTRICAL POWER AND POSSIBLE CORROSIVE OR THERMAL DAMAGE TO THE AIRCRAFT	No Data	
		OPEN		
AD	1980-19-15	AIRWORTHINESS DIRECTIVE TO PREVENT THE UPPER HOT LIQUID CONTAINER IN THE GALLEY FROM RUBBING AGAINST THE ELECTRICAL WIRE BUNDLE AND CAUSING A FIRE WHICH COULD RESULT IN THE LOSS OF THRUST REVERSERS, FLAPS, SPOILERS, AND SOME AIRPLANE LIGHTS	No Data	
		OPEN		
AD	1980-19-19	AIRWORTHINESS DIRECTIVE TO PREVENT POSSIBLE CONFLICT WITH OTHER IFR TRAFFIC	No Data	
		OPEN		
AD	1981-01-08	AIRWORTHINESS DIRECTIVE TO PRECLUDE THE POSSIBILITY OF STRUCTURAL FAILURE OF THE 25 PERCENT WING SPAR	No Data	
		OPEN		
AD	1981-07-07 PARA A	AIRWORTHINESS DIRECTIVE TO PREVENT FIRE DUE TO OVERHEATING OF THE INTERCOM SYSTEM	No Data	
		OPEN		
AD	1981-07-07 PARA B	AIRWORTHINESS DIRECTIVE TO PREVENT FIRE DUE TO OVERHEATING OF THE INTERCOM SYSTEM	No Data	
		OPEN		
AD	1981-21-05	AIRWORTHINESS DIRECTIVE APPLIES TO ARTEX REPLACEMENT BATTERY PACKS, P/N 00-21-006, WHICH ARE DESIGNED FOR USE IN THE EMERGENCY BEACON CORPORATION EMERGENCY LOCATOR TRANSMITTER.	No Data	
		OPEN		
AD	1984-02-08	AIRWORTHINESS DIRECTIVE TO PREVENT POSSIBLE USE OF IMPROPERLY CHARGED OXYGEN CYLINDERS, BLEED DOWN (DISCHARGE) THE CYLINDERS, AND RECHARGE WITH AVIATOR'S BREATHING OXYGEN	No Data	
		OPEN		
AD	1984-18-07	AIRWORTHINESS DIRECTIVE TO PREVENT HAZARDS IN FLIGHT ASSOCIATED WITH THE NON-OPERATION OF THE FIRE EXTINGUISHER CAUSED BY NON-FIRING OF THE DISCHARGE CARTRIDGE(S)	No Data	
		OPEN		
AD	1985-26-03	AIRWORTHINESS DIRECTIVE TO PREVENT THE BLOCKAGE OF OXYGEN FLOW DUE TO INCOMPLETELY DRILLED OXYGEN CONNECTORS	No Data	
		OPEN		
AD	1986-14-02	AIRWORTHINESS DIRECTIVE SUPERSEDED BY AD1989-12-08	No Data	
		OPEN		
AD	1986-22-10	AIRWORTHINESS DIRECTIVE TO PREVENT DISPLAY OF ERRONEOUS DME-42 INFORMATION	No Data	
		OPEN		
AD	1986-25-01	AIRWORTHINESS DIRECTIVE TO PREVENT DEVIATION OUTPUT SIGNAL OSCILLATION THAT MAY CAUSE UNDETECTED ERRONEOUS VOR AND ILS LOCALIZER DEVIATION DISPLAY, FLIGHT DIRECTOR COMMANDS, AND/OR AUTOPILOT TRACKING	No Data	
		OPEN		

Aircraft Model - 1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

MASTER & C/W
THE FOLLOWING INFORMATION IS ACCURATE AND CURRENT TO THE BEST KNOWLEDGE AND ABILITY OF CSI
HOWEVER, CAMP SHALL NOT BE RESPONSIBLE OR LIABLE FOR ANY ERRORS CONTAINED IN THIS REPORT.

ITEM NO	EFFECTIVE DATE	METHOD OF COMPLIANCE	TASK DESCRIPTION	C/W Date	DISPOSITION
AD	1987-06-09		AIRWORTHINESS DIRECTIVE TO PREVENT POSSIBLE LOSS OF ESSENTIAL EQUIPMENT, ELECTRICAL FIRE, OR ELECTRICAL SHOCK HAZARD ON AIRCRAFT	No Data	
		OPEN			
AD	1987-16-07		AIRWORTHINESS DIRECTIVE TO ELIMINATE ERRONEOUS DISPLAY OF THE ANGLE OF ATTACK FAST/SLOW PRESENTATION	No Data	
		OPEN			
AD	1987-17-06		AIRWORTHINESS DIRECTIVE TO ELIMINATE RESTRAINT SYSTEM CONNECTORS WITH THE INCORRECT DIMENSIONS, WHICH COULD ALLOW INADVERTENT OPENING OF OCCUPANT RESTRAINT SYSTEM ASSEMBLIES	No Data	
		OPEN			
AD	1987-20-05		AIRWORTHINESS DIRECTIVE TO ELIMINATE LAP BELT ASSEMBLIES WITH BELT RETRACTOR SHAFTS WHICH DO NOT PROVIDE ADEQUATE STRENGTH	No Data	
		OPEN			
AD	1989-02-10 R1		AIRWORTHINESS DIRECTIVE TO PREVENT FMS POSITION JUMPS WHILE CROSSING THE 180 DEGREE MERIDIAN	No Data	
		OPEN			
AD	1989-09-02		AIRWORTHINESS DIRECTIVE TO PREVENT THE POSSIBILITY OF THE APPLICABLE SAFETY-BELTS FROM BECOMING DIFFICULT TO RELEASE OR BECOMING COMPLETELY JAMMED WHEN ACTUATED THROUGH 90 DEGREES	No Data	
		OPEN			
AD	1989-12-08		AIRWORTHINESS DIRECTIVE TO DETECT CRACKS IN THE HINGE LUGS OF THE HORIZONTAL STABILIZER AFT SPAR SPLICE FITTING (HINGE ASSEMBLY)	01/17/2001	
		REPEAT OPEN			
AD	1989-20-06		AIRWORTHINESS DIRECTIVE TO PREVENT FMS NAVIGATION ERRORS CAUSED BY AN ERRONEOUS OMEGA/VLF SENSOR	No Data	
		OPEN			
AD	1990-03-02		AIRWORTHINESS DIRECTIVE SUPERSEDED BY AD1990-06-13	No Data	
		OPEN			
AD	1990-07-08 R1		AIRWORTHINESS DIRECTIVE TO PREVENT SMOKE, FIRE, AND POSSIBLE ELECTRICAL SHOCK, OR ELECTROMAGNETIC INTERFERENCE TO FLIGHT CRITICAL OR ESSENTIAL SYSTEMS	No Data	
		OPEN			
AD	1990-10-04 LEFT AILERON		AIRWORTHINESS DIRECTIVE SUPERSEDED BY AD1992-12-02	No Data	
		OPEN			
AD	1990-10-04 RIGHT AILERON		AIRWORTHINESS DIRECTIVE SUPERSEDED BY AD1992-12-02	No Data	
		OPEN			
AD	1990-14-06		AIRWORTHINESS DIRECTIVE SUPERSEDED BY AD1995-22-01	No Data	
		OPEN			
AD	1991-13-08		AIRWORTHINESS DIRECTIVE TO PREVENT THE INABILITY TO EXTEND THE NOSE LANDING GEAR FOR LANDING	No Data	
		OPEN			
AD	1992-12-02 LEFT AILERON		AIRWORTHINESS DIRECTIVE TO PREVENT REDUCED CONTROLLABILITY OF THE AIRPLANE	No Data	
		OPEN			
AD	1992-12-02 RIGHT AILERON		AIRWORTHINESS DIRECTIVE TO PREVENT REDUCED CONTROLLABILITY OF THE AIRPLANE	No Data	
		OPEN			
AD	1993-04-02 PARA A		AIRWORTHINESS DIRECTIVE TO PREVENT A MID-AIR COLLISION OR A NEAR-MISS SITUATION CAUSED BY FAILURE OF THESE MODE S TRANSPONDERS	No Data	
		OPEN			
AD	1993-04-02 PARA B		AIRWORTHINESS DIRECTIVE TO PREVENT A MID-AIR COLLISION OR A NEAR-MISS SITUATION CAUSED BY FAILURE OF THESE MODE S TRANSPONDERS	No Data	
		OPEN			
AD	1994-21-06		AIRWORTHINESS DIRECTIVE TO PREVENT THE INABILITY OF PASSENGERS OR CREW TO EGRESS FROM THEIR SEATS DURING AN EMERGENCY SITUATION, DUE TO PROBLEMS ASSOCIATED WITH THE LAP BELT ASSEMBLY	No Data	
		OPEN			

Aircraft Model - 1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date **14-MAR-2002**

MASTER & C/W
THE FOLLOWING INFORMATION IS ACCURATE AND CURRENT TO THE BEST KNOWLEDGE AND ABILITY OF CSI
HOWEVER, CAMP SHALL NOT BE RESPONSIBLE OR LIABLE FOR ANY ERRORS CONTAINED IN THIS REPORT.

ITEM NO	EFFECTIVE DATE	TASK DESCRIPTION	C/W Date	DISPOSITION
		METHOD OF COMPLIANCE		
AD	1995-22-01	AIRWORTHINESS DIRECTIVE TO PREVENT SMOKE, FIRE, ELECTRICAL SHOCK, AND POSSIBLE ELECTROMAGNETIC INTERFERENCE CAUSED BY HIGH VOLTAGE ARCING IN THE CABIN WHICH, IF UNDETECTED, COULD RESULT IN PERSONAL HAZARD OR LOSS OF THE AIRCRAFT	No Data	
		OPEN		
AD	1996-24-11 LEFT AILERON	AIRWORTHINESS DIRECTIVE TO PREVENT EXCESSIVE WEAR OF THE AILERON PUSH-PULL TUBE, WHICH COULD RESULT IN UNEVEN MOVEMENT OF THE CONTROL WHEEL, PERFORATION OF THE AILERON PUSH-PULL TUBE, AND CONSEQUENT REDUCED ROLL CONTROL OF THE AIRPLANE	07/26/2000	
		REPEAT OPEN		
SB	1124-27-129 LEFT AILERON	FLIGHT CONTROLS SERVICE BULLETIN	07/26/2000	
		REPEAT OPEN		
AD	1996-24-11 RIGHT AILERON	AIRWORTHINESS DIRECTIVE TO PREVENT EXCESSIVE WEAR OF THE AILERON PUSH-PULL TUBE, WHICH COULD RESULT IN UNEVEN MOVEMENT OF THE CONTROL WHEEL, PERFORATION OF THE AILERON PUSH-PULL TUBE, AND CONSEQUENT REDUCED ROLL CONTROL OF THE AIRPLANE	07/26/2000	
		REPEAT OPEN		
SB	1124-27-129 RIGHT AILERON	FLIGHT CONTROLS SERVICE BULLETIN	07/26/2000	
		REPEAT OPEN		
AD	1997-05-03 R1	AIRWORTHINESS DIRECTIVE TO PREVENT DEVIATION FROM AN INTENDED FLIGHT PATH DURING A NON-PRECISION APPROACH TO AN AIRPORT CAUSED BY INACCURATE INFORMATION FROM THE GPS FLIGHT MANAGEMENT SYSTEM	No Data	MANDATORY
		OPEN		
AD	1997-11-10	AIRWORTHINESS DIRECTIVE TO PREVENT RESTRICTED OXYGEN FLOW, WHICH, IF NOT CORRECTED, COULD CAUSE SERIOUS INJURY TO A PASSENGER IN NEED OF EMERGENCY OR FIRST AID OXYGEN DURING FLIGHT	No Data	
		OPEN		
AD	1998-05-09	AIRWORTHINESS DIRECTIVE 98-20-35 ISRAEL AIRCRAFT INDUSTRIES (IAI), LTD.: AMENDMENT 39-10802. DOCKET 98-NM-108-AD. SUPERSEDES AD 98-05-09, AMENDMENT 39-10370.	No Data	SUPERSEDED
		OPEN		
AD	1998-06-10	AIRWORTHINESS DIRECTIVE TO PREVENT FAILURE OF THE HYDRAULIC FUSE TO OPERATE PROPERLY IN THE EVENT OF AN EXTERNAL LEAK DOWNSTREAM OF THE FUSE, WHICH COULD RESULT IN LOSS OF HYDRAULIC SYSTEMS	11/06/2001	
		REPEAT OPEN		
AD	1998-20-35 PART 1	AIRWORTHINESS DIRECTIVE TO PREVENT FAILURE OF THE TRIM ACTUATOR OF THE HORIZONTAL STABILIZER DUE TO FAILURE OF THE JACKSCREWS, WHICH COULD RESULT IN REDUCED CONTROLLABILITY OF THE AIRPLANE	No Data	MANDATORY
		OPEN		
AD	1998-20-35 PART 2	AIRWORTHINESS DIRECTIVE TO PREVENT FAILURE OF THE TRIM ACTUATOR OF THE HORIZONTAL STABILIZER DUE TO FAILURE OF THE JACKSCREWS, WHICH COULD RESULT IN REDUCED CONTROLLABILITY OF THE AIRPLANE	No Data	MANDATORY
		OPEN		
AD	1998-25-10 R1	AIRWORTHINESS DIRECTIVE TO PREVENT FAILURE OF THE SEAT RESTRAINT SYSTEM DUE TO THE BUCKLE ASSEMBLY (BUCKLE) LOCKING MECHANISM NOT ENGAGING PROPERLY, WHICH COULD RESULT IN THE SEAT RESTRAINT SYSTEM FAILING TO PROPERLY SECURE THE OCCUPANT DURING TURBULENCE OR LANDING	No Data	MANDATORY
		OPEN		
AD	1999-18-80	AIRWORTHINESS DIRECTIVE TO PREVENT LOSS OF THE HYDRAULIC LOW PRESSURE WARNING LIGHTS WHICH COULD RESULT IN UNKNOWN LOW PRESSURE IN THE HYDRAULIC SYSTEM AND CONSEQUENT REDUCED CONTROLLABILITY OF THE AIRPLANE	No Data	
		OPEN		
AD	1999-23-22 R2	AIRWORTHINESS DIRECTIVE RESCISSION	No Data	
		OPEN		

Aircraft Model - 1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

MASTER & C/W
THE FOLLOWING INFORMATION IS ACCURATE AND CURRENT TO THE BEST KNOWLEDGE AND ABILITY OF CSI
HOWEVER, CAMP SHALL NOT BE RESPONSIBLE OR LIABLE FOR ANY ERRORS CONTAINED IN THIS REPORT.

ITEM NO	EFFECTIVE DATE	METHOD OF COMPLIANCE	TASK DESCRIPTION	C/W Date	DISPOSITION
AD	2000-10-04		AIRWORTHINESS DIRECTIVE TO PREVENT CRACKING OF THE AILERON SKIN DUE TO MISSING RIVETS, WHICH COULD RESULT IN REDUCED STRUCTURAL INTEGRITY OF THE AILERON AND CONSEQUENT REDUCED CONTROLLABILITY OF THE AIRPLANE AIRWORTHINESS DIRECTIVE	No Data	MANDATORY
SB	911450	OPEN	ASB 1124-27A-145 SERVICE BULLETIN	No Data	MANDATORY
		OPEN			
AD	2000-10-04U		AIRWORTHINESS DIRECTIVE TO PREVENT CRACKING OF THE AILERON SKIN DUE TO MISSING RIVETS, WHICH COULD RESULT IN REDUCED STRUCTURAL INTEGRITY OF THE AILERON AND CONSEQUENT REDUCED CONTROLLABILITY OF THE AIRPLANE	No Data	MANDATORY
		OPEN			
AD	2000-15-09#1ENG		AIRWORTHINESS DIRECTIVE	No Data	MANDATORY
		OPEN			
AD	2000-15-09#2ENG		AIRWORTHINESS DIRECTIVE	No Data	MANDATORY
		OPEN			
AD	2000-21-03		AIRWORTHINESS DIRECTIVE TO PREVENT THE CONTROL LINK OF THE AILERON AUTOPILOT SERVO FROM BEING DRIVEN OVERCENTER, WHICH COULD RESULT IN ROLL OSCILLATIONS WHEN THE AUTOPILOT IS ENGAGED	No Data	MANDATORY
		OPEN			
AD	2000-23-13		AIRWORTHINESS DIRECTIVE TO PREVENT JAMMING OR DISCONNECTION OF THE HORIZONTAL STABILIZER TRIM ACTUATOR, WHICH COULD RESULT IN REDUCED PITCH CONTROL OF THE AIRPLANE	No Data	MANDATORY
		OPEN			
SB	911470	OPEN	ASB 1124-27A-147 SERVICE BULLETIN	No Data	MANDATORY
		OPEN			
AD	2000-23-13U		AIRWORTHINESS DIRECTIVE TO PREVENT JAMMING OR DISCONNECTION OF THE HORIZONTAL STABILIZER TRIM ACTUATOR, WHICH COULD RESULT IN REDUCED PITCH CONTROL OF THE AIRPLANE	No Data	MANDATORY
		OPEN			
AD	2001-03-01		AIRWORTHINESS DIRECTIVE TO PREVENT THE MAIN ENTRY DOOR FROM JAMMING, WHICH COULD IMPEDE THE SAFE EVACUATION OF PASSENGERS AND CREW DURING AN EMERGENCY	No Data	MANDATORY
		OPEN			
AD	2001-03-01U		AIRWORTHINESS DIRECTIVE TO PREVENT THE MAIN ENTRY DOOR FROM JAMMING, WHICH COULD IMPEDE THE SAFE EVACUATION OF PASSENGERS AND CREW DURING AN EMERGENCY	No Data	MANDATORY
		OPEN			
AD	2002-01-26		AIRWORTHINESS DIRECTIVE TO PREVENT FAILURE OF ATTACHMENT BOLTS DUE TO FATIGUE, WHICH COULD RESULT IN SEPARATION OF THE ENGINE INLET COWL AND AFT NACELLE, AND CONSEQUENT DAMAGE TO THE HORIZONTAL OR VERTICAL STABILIZER	No Data	MANDATORY
		OPEN			
07-MAR-02					
SB	ASB1124-54A-138	OPEN	SERVICE BULLETIN	No Data	MANDATORY
		OPEN			
AD	990010U		AIRWORTHINESS DIRECTIVE AD72-19-04	02/03/1982	
		OPEN			
AD	990025		AIRWORTHINESS DIRECTIVE AD75-07-10	No Data	
		OPEN			
AD	990027		AIRWORTHINESS DIRECTIVE AD78-22-10	No Data	
		OPEN			
AD	990040U		AIRWORTHINESS DIRECTIVE AD80-01-05R1	No Data	
		OPEN			
AD	990045		AIRWORTHINESS DIRECTIVE AD80-16-04	No Data	
		OPEN			
AD	990045U		AIRWORTHINESS DIRECTIVE AD80-16-04	08/07/1980	
		NOT APPLICABLE N/A			

Aircraft Model - 1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date **14-MAR-2002**

MASTER & C/W
THE FOLLOWING INFORMATION IS ACCURATE AND CURRENT TO THE BEST KNOWLEDGE AND ABILITY OF CSI
HOWEVER, CAMP SHALL NOT BE RESPONSIBLE OR LIABLE FOR ANY ERRORS CONTAINED IN THIS REPORT.

ITEM NO	EFFECTIVE DATE	TASK DESCRIPTION	METHOD OF COMPLIANCE	C/W Date	DISPOSITION
AD 990048U		AIRWORTHINESS DIRECTIVE AD80-18-08		02/05/1985	
			COMPLIED WITH C/W		
AD 990050U		AIRWORTHINESS DIRECTIVE AD80-19-15		09/11/1980	
			NOT APPLICABLE N/A		
AD 990060U		AIRWORTHINESS DIRECTIVE AD80-19-19		No Data	
AD 990065U		AIRWORTHINESS DIRECTIVE AD81-01-08		No Data	
AD 990070U		AIRWORTHINESS DIRECTIVE AD81-07-07 PARA A		01/03/1985	
			NOT APPLICABLE N/A		
AD 990075U		AIRWORTHINESS DIRECTIVE AD81-07-07 PARA B		01/03/1985	
			NOT APPLICABLE N/A		
AD 990080U		AIRWORTHINESS DIRECTIVE AD81-21-05		No Data	
AD 990085U		AIRWORTHINESS DIRECTIVE AD81-24-08 #1 ENGINE		07/12/1991	
			NOT APPLICABLE N/A		
AD 990090U		AIRWORTHINESS DIRECTIVE AD81-24-08 #2 ENGINE		01/06/1982	
			NOT APPLICABLE N/A		
AD 990095		AIRWORTHINESS DIRECTIVE TO PREVENT A FALSE INDICATION, THAT EMERGENCY POWER IS AVAILABLE		No Data	
			OPEN		
AD 990100U		AIRWORTHINESS DIRECTIVE AD84-02-08		04/10/1990	
			NOT APPLICABLE N/A		
AD 990105U		AIRWORTHINESS DIRECTIVE AD84-18-07		No Data	
AD 990120U		AIRWORTHINESS DIRECTIVE AD86-03-01 #1 ENGINE		07/28/1986	
			NOT APPLICABLE N/A		
AD 990121U		AIRWORTHINESS DIRECTIVE AD86-03-01 #2 ENGINE		No Data	
			OPEN		
AD 990130U		AIRWORTHINESS DIRECTIVE AD86-14-02		01/20/1989	
AD 990140U		AIRWORTHINESS DIRECTIVE AD86-22-10		No Data	
AD 990145U		AIRWORTHINESS DIRECTIVE AD86-25-01		No Data	
AD 990150U		AIRWORTHINESS DIRECTIVE AD87-16-07		No Data	
AD 990155U		AIRWORTHINESS DIRECTIVE AD87-17-06		No Data	
AD 990160U		AIRWORTHINESS DIRECTIVE AD87-20-05		No Data	
AD 990165U		AIRWORTHINESS DIRECTIVE AD88-18-03 #1 ENGINE		01/20/1989	
			COMPLIED WITH C/W		
AD 990166U		AIRWORTHINESS DIRECTIVE AD88-18-03 #2 ENGINE		01/20/1989	
			COMPLIED WITH C/W		
AD 990821U		AIRWORTHINESS DIRECTIVE AD82-23-03 R1 #1 ENGINE		11/13/1999	
			NOT APPLICABLE N/A		
AD 990822U		AIRWORTHINESS DIRECTIVE AD82-23-03 R1 #2 ENGINE		05/17/1989	
AD 990960U		AIRWORTHINESS DIRECTIVE AD89-02-10R1		No Data	
			NOT APPLICABLE N/A		

Aircraft Model - 1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

MASTER & C/W
THE FOLLOWING INFORMATION IS ACCURATE AND CURRENT TO THE BEST KNOWLEDGE AND ABILITY OF CSI
HOWEVER, CAMP SHALL NOT BE RESPONSIBLE OR LIABLE FOR ANY ERRORS CONTAINED IN THIS REPORT.

ITEM NO	EFFECTIVE DATE	TASK DESCRIPTION	C/W Date	DISPOSITION
		METHOD OF COMPLIANCE		
AD 990970U		AIRWORTHINESS DIRECTIVE AD89-20-06	No Data	
AD 990980U		AIRWORTHINESS DIRECTIVE AD90-03-02	03/21/1990	
AD 990982U		NOT APPLICABLE N/A		
AD 990983U		AIRWORTHINESS DIRECTIVE AD90-03-04 #1 ENGINE	03/21/1990	
AD 990983U		NOT APPLICABLE N/A		
AD 990983U		AIRWORTHINESS DIRECTIVE AD90-03-04 #2 ENGINE	03/21/1990	
AD 990985U		NOT APPLICABLE N/A		
AD 990985U		AIRWORTHINESS DIRECTIVE AD90-10-04 LEFT AILERON	11/01/1992	
AD 990986U		NOT APPLICABLE N/A		
AD 990986U		AIRWORTHINESS DIRECTIVE AD90-10-04 RIGHT AILERON	11/01/1992	
AD 990987U		NOT APPLICABLE N/A		
AD 990987U		AIRWORTHINESS DIRECTIVE AD90-14-06	06/19/1991	
AD 990988U		COMPLIED WITH C/W		
AD 990988U		AIRWORTHINESS DIRECTIVE AD90-07-08R1	07/11/1990	
AD 991020U		NOT APPLICABLE N/A		
AD 991020U		AIRWORTHINESS DIRECTIVE AD91-08-13 #1 ENGINE	04/26/1994	
AD 991030U		AIRWORTHINESS DIRECTIVE AD91-08-13 #2 ENGINE	05/31/1993	
AD 991040U		AIRWORTHINESS DIRECTIVE AD91-13-08	11/09/1996	
AD 991065U		COMPLIED WITH C/W		
AD 991065U		AIRWORTHINESS DIRECTIVE AD92-12-09 #1 ENGINE	06/23/1992	
AD 991070U		COMPLIED WITH C/W		
AD 991070U		AIRWORTHINESS DIRECTIVE AD92-12-02 LEFT AILERON	11/01/1992	
AD 991071U		COMPLIED WITH C/W		
AD 991071U		AIRWORTHINESS DIRECTIVE AD92-12-02 RIGHT AILERON	11/01/1992	
AD 991090U		COMPLIED WITH C/W		
AD 991090U		AIRWORTHINESS DIRECTIVE AD92-26-09 #1 ENGINE	09/30/1993	
AD 991091U		NOT APPLICABLE N/A		
AD 991091U		AIRWORTHINESS DIRECTIVE AD92-26-09 #2 ENGINE	04/26/1994	
AD 991100U		NOT APPLICABLE N/A		
AD 991100U		AIRWORTHINESS DIRECTIVE AD93-04-02 PARA A	04/19/1993	
AD 991105U		NOT APPLICABLE N/A		
AD 991105U		AIRWORTHINESS DIRECTIVE AD93-04-02 PARA B	04/19/1993	
AD 991115U		NOT APPLICABLE N/A		
AD 991115U		AIRWORTHINESS DIRECTIVE AD93-10-10 #1 ENGINE	09/29/1993	SUPERSEDED
AD 991120U		OPEN		
AD 991120U		AIRWORTHINESS DIRECTIVE AD93-10-10 #2 ENGINE	09/29/1993	SUPERSEDED
AD 991350U		OPEN		
AD 991350U		AIRWORTHINESS DIRECTIVE AD93-25-16 #1 ENGINE	04/26/1994	
AD 991351U		NOT APPLICABLE N/A		
AD 991351U		AIRWORTHINESS DIRECTIVE AD93-25-16 #2 ENGINE	03/07/1994	
AD 991370		NOT APPLICABLE N/A		
AD 991370		AIRWORTHINESS DIRECTIVE AD94-07-03 PARA A	No Data	
AD 991370U		OPEN		
AD 991370U		AIRWORTHINESS DIRECTIVE AD94-07-03 PARA A	07/27/1994	
AD 991400U		NOT APPLICABLE N/A		
AD 991400U		AIRWORTHINESS DIRECTIVE AD94-21-06	02/21/1995	
AD 991400U		NOT APPLICABLE N/A		

Aircraft Model - 1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date **14-MAR-2002**

MASTER & C/W
THE FOLLOWING INFORMATION IS ACCURATE AND CURRENT TO THE BEST KNOWLEDGE AND ABILITY OF CSI
HOWEVER, CAMP SHALL NOT BE RESPONSIBLE OR LIABLE FOR ANY ERRORS CONTAINED IN THIS REPORT.

ITEM NO	EFFECTIVE DATE	TASK DESCRIPTION	METHOD OF COMPLIANCE	C/W Date	DISPOSITION
AD 991510U		AIRWORTHINESS DIRECTIVE AD95-22-01		07/26/2000	
		COMPLIED WITH C/W			
AD 991570U		AIRWORTHINESS DIRECTIVE AD97-05-03R1		06/16/1997	
		NOT APPLICABLE N/A			
AD 991580U		AIRWORTHINESS DIRECTIVE AD97-04-03 #1 ENGINE		10/17/1998	
		NOT APPLICABLE N/A			
AD 991581U		AIRWORTHINESS DIRECTIVE AD97-04-03 #2 ENGINE		10/17/1998	
		NOT APPLICABLE N/A			
AD 991590U		AIRWORTHINESS DIRECTIVE AD97-11-10		10/17/1998	
		NOT APPLICABLE N/A			
AD 991610U		AIRWORTHINESS DIRECTIVE AD98-05-09		10/17/1998	SUPERSEDED
		OPEN			
AD 991620U		AIRWORTHINESS DIRECTIVE AD98-17-01 R1 L/E		10/06/1998	MANDATORY
		NOT APPLICABLE N/A			
AD 991625U		AIRWORTHINESS DIRECTIVE AD98-17-01 R1 R/E		10/06/1998	MANDATORY
		NOT APPLICABLE N/A			
AD 991634U		AIRWORTHINESS DIRECTIVE AD98-20-35 PART 1		04/07/1998	
		OPEN			
AD 991635U		AIRWORTHINESS DIRECTIVE AD98-20-35 PART 2		04/06/1998	MANDATORY
		COMPLIED WITH C/W			
AD 991640U		AIRWORTHINESS DIRECTIVE AD98-25-10		04/07/1999	MANDATORY
		OPEN			
AD 991645U		AIRWORTHINESS DIRECTIVE AD98-25-02		04/07/1999	MANDATORY
		OPEN			
AD 991755U		AIRWORTHINESS DIRECTIVE AD99-08-21		10/27/1999	MANDATORY
		OPEN			
AD 991765U		AIRWORTHINESS DIRECTIVE AD99-18-08		10/17/1998	
		OPEN			
AD 991770U		AIRWORTHINESS DIRECTIVE AD99-23-22 R2		02/22/2000	
		OPEN			
AD 991775U		AIRWORTHINESS DIRECTIVE AD98-25-10 R1		02/22/2000	MANDATORY
		OPEN			
AD 991845U		AIRWORTHINESS DIRECTIVE AD2000-23-13		01/17/2001	MANDATORY
		OPEN			
AD 991850U		AIRWORTHINESS DIRECTIVE AD2001-03-01		11/06/2001	MANDATORY
		OPEN			
AD 991855U		AIRWORTHINESS DIRECTIVE AD2001-15-17		11/06/2001	MANDATORY
		OPEN			
ASB 1124-78A-134		ALERT SERVICE BULLETIN THRUST REVERSER		No Data	MANDATORY
		OPEN			
SB 1124-27-100 R2 L/H RODS		SERVICE BULLETIN FLIGHT CONTROLS		No Data	
		OPEN			
SB 1124-27-100 R2 R/H RODS		SERVICE BULLETIN FLIGHT CONTROLS		No Data	
		OPEN			
SB 1124-27-129 LEFT AILERON		SERVICE BULLETIN FLIGHT CONTROLS		07/26/2000	
		REPEAT			
SB 1124-27-129 RIGHT AILERON		SERVICE BULLETIN FLIGHT CONTROLS		07/26/2000	
		REPEAT			
SB 1124-27-133 R1		SERVICE BULLETIN FLIGHT CONTROLS		No Data	MANDATORY
		OPEN			

Aircraft Model - 1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

MASTER & C/W
THE FOLLOWING INFORMATION IS ACCURATE AND CURRENT TO THE BEST KNOWLEDGE AND ABILITY OF CSI
HOWEVER, CAMP SHALL NOT BE RESPONSIBLE OR LIABLE FOR ANY ERRORS CONTAINED IN THIS REPORT.

ITEM NO	EFFECTIVE DATE	METHOD OF COMPLIANCE	TASK DESCRIPTION	C/W Date	DISPOSITION
SB 1124-30-036 PART II		REPEAT OPEN	SERVICE BULLETIN ICE AND RAIN PROTECTION	06/26/2001	
SB 1124-55-020 R2		REPEAT OPEN	SERVICE BULLETIN STABILIZERS	06/26/2001	
SB 1124-55-021 R3		OPEN	SERVICE BULLETIN STABILIZERS	No Data	
SB 1124-55-097		OPEN	SERVICE BULLETIN STABILIZER SCISSR	No Data	
SB 1124-71-091 R2 #1 ENG		OPEN	SERVICE BULLETIN INSPECT ENG MOUNT FASTENERS	No Data	
SB 1124-71-091 R2 #2 ENGINE		OPEN	SERVICE BULLETIN INSPECT ENG MOUNT FASTENERS	No Data	
SB 1124-79-093 PART A		OPEN	SERVICE BULLETIN OIL	No Data	
SB 900280 30-JAN-02		OPEN	SERVICE BULLETIN SB WW 24-28A	02/22/2000	
SB 910100U		NOT APPLICABLE N/A	SERVICE BULLETIN SB1124-27-100R2 L/H RODS	11/01/1992	
SB 910101U			SERVICE BULLETIN SB1124-27-100R2 R/H RODS	11/01/1992	
SB 910210U			SERVICE BULLETIN SB1124-55-021 REV 3	10/13/1985	
SB 910911U		COMPLIED WITH C/W	SERVICE BULLETIN SB 1124-71-091 PART II	04/12/1989	
SB 910912U		COMPLIED WITH C/W	SERVICE BULLETIN SB 1124-71-091 PART II	05/31/1989	
SB 910970U		COMPLIED WITH C/W	SERVICE BULLETIN SB 1124-55-097STAB SCISSR	04/30/1990	
SB 911160U		NOT APPLICABLE N/A	SERVICE BULLETIN SB1124-32-116 L/G NW STR	06/01/1995	
SB 911190U		COMPLIED WITH C/W	SERVICE BULLETIN SB1124-26-119 FIRE EXTGHR	09/29/1993	
SB 911230U		COMPLIED WITH C/W	SERVICE BULLETIN SB1124-53-123 DRAIN/CABIN	10/26/1999	
SB 911320U		OPEN	SERVICE BULLETIN SB1124-29-132 HYD FUS TST	No Data	MANDATORY
SB 911330U		COMPLIED WITH C/W	SERVICE BULLETIN SB1124-27-133R1 INSP HORZ	11/09/1996	MANDATORY
SB 911340U		COMPLIED WITH C/W	SERVICE BULLETIN ASB1124-78A-134	10/26/1999	MANDATORY
SB 911360		OPEN	SERVICE BULLETIN SB1124-27-136 HORZ TRIM	No Data	MANDATORY
SB 911360U		OPEN	SERVICE BULLETIN SB1124-27-136 HORZ TRIM	04/07/1998	
SB 911380		OPEN	SERVICE BULLETIN ASB1124-54A-138	No Data	MANDATORY
SB 911380U		OPEN	SERVICE BULLETIN ASB1124-54A-138	11/06/2001	MANDATORY

Aircraft Model - 1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

MASTER & C/W
THE FOLLOWING INFORMATION IS ACCURATE AND CURRENT TO THE BEST KNOWLEDGE AND ABILITY OF CSI
HOWEVER, CAMP SHALL NOT BE RESPONSIBLE OR LIABLE FOR ANY ERRORS CONTAINED IN THIS REPORT.

ITEM NO	EFFECTIVE DATE	METHOD OF COMPLIANCE	TASK DESCRIPTION	C/W Date	DISPOSITION
SB 911390		REPEAT OPEN	SERVICE BULLETIN SB1124-32-139 UPR STRG	07/26/2000	
SB 911391		OPEN	SERVICE BULLETIN SB1124-32-139 LWR STRG	No Data	
SB 911400U		COMPLIED WITH C/W	SERVICE BULLETIN ASB 1124-29A-140	10/06/1998	MANDATORY
SB 911420		OPEN	SERVICE BULLETIN ASB1124-30A-142	No Data	MANDATORY
SB 911450		OPEN	SERVICE BULLETIN ASB1124-27A-145	No Data	MANDATORY
SB 911470		OPEN	SERVICE BULLETIN ASB1124-27A-147	No Data	MANDATORY
SB 911470U		OPEN	SERVICE BULLETIN ASB1124-27A-147	01/17/2001	MANDATORY
SB 950035		OPEN	SERVICE BULLETIN SL-2406 R1 G.E. START GEN	No Data	
SB 950491		OPEN	SERVICE BULLETIN SL WW-2449R1 INSP ECU MT	No Data	
SB 950911		OPEN	SERVICE BULLETIN SL WW-2491 REV 1 NLG BRGS	No Data	
SB 950911U		OPEN	SERVICE BULLETIN SL WW-2491 REV 1 NLG BRGS	02/22/2000	
SB 950920		REPEAT OPEN	SERVICE BULLETIN SL WW-2492 HYD HOSE INSP	06/26/2001	
SB 950941		REPEAT OPEN	SERVICE BULLETIN SLWW-2494 REV 3 LMG BOLTS	06/26/2001	
SB 950942		REPEAT OPEN	SERVICE BULLETIN SLWW-2494 REV 3 RMG BOLTS	06/26/2001	
SB 951010		OPEN	SERVICE BULLETIN SLWW-24101 R1 LEFT SIDE	No Data	
SB 951011		OPEN	SERVICE BULLETIN SLWW-24101 R1 RIGHT SIDE	No Data	
SB 951030		OPEN	SERVICE BULLETIN SL WW-24103 L/H	No Data	
SB 951030U		OPEN	SERVICE BULLETIN SL WW-24103 L/H	08/15/1988	
SB 951031		OPEN	SERVICE BULLETIN SL WW-24103 R/H	No Data	
SB 951031U		OPEN	SERVICE BULLETIN SL WW-24103 R/H	08/15/1988	
SB 951060		OPEN	SERVICE BULLETIN SL WW-24106	No Data	
SB 951060U		OPEN	SERVICE BULLETIN SL WW-24106	No Data	
SB 960078		OPEN	SERVICE BULLETIN SIL1124-21-078 R2 35D SEN	No Data	
SB 960078U		OPEN	SERVICE BULLETIN SIL1124-21-078 R2 35D SEN	11/13/1995	

Aircraft Model - 1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

MASTER & C/W
THE FOLLOWING INFORMATION IS ACCURATE AND CURRENT TO THE BEST KNOWLEDGE AND ABILITY OF CSI
HOWEVER, CAMP SHALL NOT BE RESPONSIBLE OR LIABLE FOR ANY ERRORS CONTAINED IN THIS REPORT.

ITEM NO	EFFECTIVE DATE	TASK DESCRIPTION	C/W Date	DISPOSITION
		METHOD OF COMPLIANCE		
SB 971279U		SERVICE BULLETIN TFE731-72-3640 R3 ENG #1 NOT APPLICABLE N/A	11/13/1999	
SB 971280U		SERVICE BULLETIN TFE731-72-3640 R3 ENG #2	10/26/1999	RECOMMENDED
SB 972200U		SERVICE BULLETIN TFE731-A72-3388 LEFT ENG NOT APPLICABLE N/A	12/05/1989	
SB 972202U		SERVICE BULLETIN TFE731-A72-3388 RIGHT ENG NOT APPLICABLE N/A	12/05/1989	
SB 972655U		SERVICE BULLETIN GSBA72-3328 R5 LEFT ENG NOT APPLICABLE N/A	10/31/1995	
SB 972656U		SERVICE BULLETIN GSBA72-3328 R5 RIGHT ENG NOT APPLICABLE N/A	10/31/1995	
SB 972847U		SERVICE BULLETIN GSB TFE 731-A72-3432 L/H NOT APPLICABLE N/A	07/05/2000	
SB 972848U		SERVICE BULLETIN GSB TFE 731-A72-3432 R/H NOT APPLICABLE N/A	06/07/1991	
SB 972850U		SERVICE BULLETIN SB 731-A72-3668 #1 ENG	No Data	RECOMMENDED
SB 972851U		SERVICE BULLETIN SB 731-A72-3668 #2 ENG	No Data	RECOMMENDED
SB 972863U		SERVICE BULLETIN GSBA72-3432 R5 L/ENGINE	No Data	
SB 972864U		SERVICE BULLETIN GSBA72-3432 R5 R/ENGINE	No Data	
SB 972A03U		SERVICE BULLETIN G/SB72-3502 #1 ENGINE COMPLIED WITH C/W	05/31/1993	
SB 972A04U		SERVICE BULLETIN G/SB72-3502 #2 ENGINE COMPLIED WITH C/W	05/31/1993	
SB 972A07U		SERVICE BULLETIN G/SBA72-3504 L/ENG REV 1 NOT APPLICABLE N/A	02/25/1994	
SB 972A08U		SERVICE BULLETIN G/SBA72-3504 R/ENG REV 1 NOT APPLICABLE N/A	02/25/1994	
SB 972A87U		SERVICE BULLETIN SB TFE731-A72-3544 LH ENG NOT APPLICABLE N/A	02/17/1994	
SB 972A88U		SERVICE BULLETIN SB TFE731-A72-3544 RH ENG NOT APPLICABLE N/A	02/17/1994	
SB 972B07U		SERVICE BULLETIN G/SBA72-3504 L/ENG REV 1 NOT APPLICABLE N/A	09/30/1993	
SB 972B08U		SERVICE BULLETIN G/SBA72-3504 R/ENG REV 1 NOT APPLICABLE N/A	09/30/1993	
SB 972B13U		SERVICE BULLETIN REPL LE 1ST STG LP TURB NOT APPLICABLE N/A	07/27/1994	RECOMMENDED
SB 972B14U		SERVICE BULLETIN REPL LE 2ND STG LP TURB NOT APPLICABLE N/A	07/27/1994	RECOMMENDED
SB 972B15U		SERVICE BULLETIN REPL RE 1ST STG LP TURB NOT APPLICABLE N/A	07/27/1994	RECOMMENDED
SB 972B16U		SERVICE BULLETIN REPL RE 2ND STG LP TURB NOT APPLICABLE N/A	07/27/1994	RECOMMENDED
SB 972B39U		SERVICE BULLETIN GSBA72-3569 L/E FAN ROTOR NOT APPLICABLE N/A	11/13/1999	



Aircraft Model - 1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

MASTER & C/W
THE FOLLOWING INFORMATION IS ACCURATE AND CURRENT TO THE BEST KNOWLEDGE AND ABILITY OF CSI
HOWEVER, CAMP SHALL NOT BE RESPONSIBLE OR LIABLE FOR ANY ERRORS CONTAINED IN THIS REPORT.

ITEM NO	EFFECTIVE DATE	TASK DESCRIPTION	C/W Date	DISPOSITION
		METHOD OF COMPLIANCE		
SB 972B40U		SERVICE BULLETIN GSBA72-3569 R/E FAN ROTOR	No Data	
		OPEN		
SB 972B53U		SERVICE BULLETIN GSBA72-3578 LEFT ENGINE	10/31/1995	
		NOT APPLICABLE N/A		
SB 972B54U		SERVICE BULLETIN GSBA72-3578 RIGHT ENGINE	10/31/1995	
		NOT APPLICABLE N/A		
SB 973241U		SERVICE BULLETIN GSB 73-3121 L/E FUEL CONT	03/07/1994	
		NOT APPLICABLE N/A		
SB 973242U		SERVICE BULLETIN GSB 73-3121 R/E FUEL CONT	03/07/1994	
		NOT APPLICABLE N/A		
SB 973636U		SERVICE BULLETIN SB731-A72-3636R1 L/E	10/17/1998	
		OPEN		
SB 973665U		SERVICE BULLETIN SB731-A72-3636R1 R/E	10/17/1998	
		OPEN		
SB 977039U		SERVICE BULLETIN SBTFE731-A77-3020 L/H	06/11/1991	
		NOT APPLICABLE N/A		
SB 977040U		SERVICE BULLETIN SBTFE 731-A77-3020 R/H	06/11/1991	
		NOT APPLICABLE N/A		
SB ASB1124-27A-145		SERVICE BULLETIN	No Data	MANDATORY
		OPEN		
SB ASB1124-27A-147		SERVICE BULLETIN	No Data	MANDATORY
		OPEN		
SB ASB1124-30A-142		SERVICE BULLETIN	No Data	MANDATORY
		OPEN		
SB ASB1124-54A-138		SERVICE BULLETIN	No Data	MANDATORY
		OPEN		
SB SB731-A72-3636L/E		SERVICE BULLETIN	No Data	MANDATORY SCRAP
		OPEN		
SB SB731-A72-3636R/E		SERVICE BULLETIN	No Data	MANDATORY SCRAP
		OPEN		
SB SB731-A72-3636R1L/E		SERVICE BULLETIN	No Data	
		OPEN		
SB SB731-A72-3636R1R/E		SERVICE BULLETIN	No Data	
		OPEN		
SB SB731-A72-3668L/E		SERVICE BULLETIN	No Data	MANDATORY SCRAP
		OPEN		
SB SB731-A72-3668R/E		SERVICE BULLETIN	No Data	MANDATORY SCRAP
		OPEN		

Aircraft Model - 1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

MASTER & C/W
THE FOLLOWING INFORMATION IS ACCURATE AND CURRENT TO THE BEST KNOWLEDGE AND ABILITY OF CSI
HOWEVER, CAMP SHALL NOT BE RESPONSIBLE OR LIABLE FOR ANY ERRORS CONTAINED IN THIS REPORT.

ITEM NO	EFFECTIVE DATE	TASK DESCRIPTION	C/W Date	DISPOSITION
		METHOD OF COMPLIANCE		
ENGINE NO. 1				
AD	1978-22-10 22-SEP-78	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE LOW PRESSURE ROTOR THRUST BALL BEARINGS	No Data	
		OPEN		
AD	1980-16-04 07-AUG-80	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE TIE ROD	No Data	
		OPEN		
AD	1981-24-08 06-JAN-82	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE TURBINE INTERSTAGE TRANSITION DUCTS	No Data	
		OPEN		
AD	1982-23-03 09-DEC-83	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE HIGH PRESSURE COMPRESSOR IMPELLERS	No Data	
		OPEN		
AD	1986-03-01 24-FEB-86	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE TURBINE INTERSTAGE TRANSITION DUCTS	No Data	
		OPEN		
PRIORITY LETTER	1986-04-02 14-FEB-86	NO. 1 ENGINE - PRIORITY LETTER FAN ROTOR DISCS	No Data	SUPERSEDED
		OPEN		
AD	1986-11-05	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE FAN ROTOR DISCS	No Data	SUPERSEDED
		OPEN		
AD	1986-21-05	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE FORWARD ENGINE MOUNTS	No Data	
		OPEN		
AD	1988-18-03 30-AUG-88	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE HIGH PRESSURE TURBINE ROTOR DISC	No Data	
		OPEN		
AD	1990-03-04 22-FEB-90	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE HIGH PRESSURE TURBINE ROTOR DISCS	No Data	
		OPEN		
AD	1990-24-06 13-NOV-90	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE THERMOCOUPLE LEAD ASSEMBLIES	No Data	
		OPEN		
AD	1991-08-13 16-APR-91	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE FAN ROTOR DISK	No Data	SUPERSEDED
		OPEN		
AD	1992-21-06 27-NOV-92	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE LOW PRESSURE TURBINE (LPT) ROTOR DISKS	No Data	MANDATORY
		OPEN		
AD	1992-26-09 22-DEC-92	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE FAN ROTOR DISK	No Data	SUPERSEDED
		OPEN		
AD	1993-10-10 29-JUN-93	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE FUEL LINE CLAMP ASSEMBLY	No Data	SUPERSEDED
		OPEN		
AD	1993-25-16 02-JUN-93	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE FAN DISK	No Data	SUPERSEDED
		OPEN		
AD	1994-07-03 06-JUN-94	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE TURBINE NOZZLES	No Data	
		OPEN		
AD	1994-14-15 05-AUG-94	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE EXHAUST DUCT ATTACHMENT CLAMPS	No Data	
		OPEN		
AD	1995-07-02 19-JUN-95	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE LOW PRESSURE TURBINE DISKS	No Data	
		OPEN		
AD	1995-07-02 1ST STAGE 19-JUN-95	NO. 1 ENGINE - ACCOMPLISH	No Data	
		OPEN		
AD	1995-07-02 2ND STAGE 19-JUN-95	NO. 1 ENGINE - ACCOMPLISH	No Data	
		OPEN		

Aircraft Model - 1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

MASTER & C/W
THE FOLLOWING INFORMATION IS ACCURATE AND CURRENT TO THE BEST KNOWLEDGE AND ABILITY OF CSI
HOWEVER, CAMP SHALL NOT BE RESPONSIBLE OR LIABLE FOR ANY ERRORS CONTAINED IN THIS REPORT.

ITEM NO	EFFECTIVE DATE	METHOD OF COMPLIANCE	TASK DESCRIPTION	C/W Date	DISPOSITION
AD	1996-04-01 15-MAR-96	OPEN	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE FAN ROTOR ASSEMBLY	No Data	
AD	1996-05-03 02-APR-96	OPEN	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE FAN ROTOR DISKS	No Data	
AD	1996-18-13	OPEN	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE FAN ROTOR DISK	No Data	SUPERSEDED
AD	1998-17-01 13-OCT-98	OPEN	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE FLEX FUEL TUBE	No Data	
AD	1998-17-01 REV.1 29-NOV-99	OPEN	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE FLEX FUEL TUBE	No Data	MANDATORY
AD	2000-15-09 10-OCT-00	REPEAT OPEN	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE HPC IMPELLER	No Data	
AD	2001-23-09 21-DEC-01	OPEN	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE TO PREVENT FAILURE OF THE FAN ROTOR DISC DUE TO FATIGUE CRACKING IN THE DOVETAIL SLOTS	No Data	MANDATORY
SB	TFE731-A72-3668 25-OCT-00	OPEN	NO. 1 ENGINE - REMOVE FAN ROTOR DISC FROM SERVICE SERVICE BULLETIN	No Data	MANDATORY
AD	990100U	OPEN	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE AD86-11-05 #1 ENGINE	04/26/1994	
AD	990101U	NOT APPLICABLE N/A	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE AD90-24-06 #1 ENGINE	06/11/1991	
AD	990102U	NOT APPLICABLE N/A	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE AD92-21-06 #1 ENGINE	12/28/1992	
AD	990103U	NOT APPLICABLE N/A	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE AD94-07-03 #1 ENGINE	07/27/1994	
AD	990104U	NOT APPLICABLE N/A	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE AD95-07-02 #1E #1 LPT DSK	09/26/1995	
AD	990105U	NOT APPLICABLE N/A	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE AD95-07-02 #1E #2 LPT DSK	09/26/1995	
AD	990106U	NOT APPLICABLE N/A	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE AD96-04-01 #1 ENGINE	03/27/1996	
AD	990107U	NOT APPLICABLE N/A	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE AD96-05-03 #1 ENGINE	07/05/2000	
AD	990108U	NOT APPLICABLE N/A	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE AD96-18-13 #1 ENGINE	11/13/1999	
SB	TFE-731-A72-3504	OPEN	NO. 1 ENGINE - SERVICE BULLETIN INSPECT FAN ROTOR ASSEMBLY	No Data	
SB	TFE731-73-3137	OPEN	NO. 1 ENGINE - SERVICE BULLETIN REPLACE FUEL HEATER CHECK VALVES	No Data	
SB	TFE731-A72-3126	OPEN	NO. 1 ENGINE - SERVICE BULLETIN REPLACE/REWORK PLANET GEAR ASSEMBLY	No Data	
SB	TFE731-A72-3169	OPEN	NO. 1 ENGINE - SERVICE BULLETIN REPLACE IDENTIFIED HP ROTOR #5 THRUST BEARING	No Data	
SB	TFE731-A72-3306	OPEN	NO. 1 ENGINE - SERVICE BULLETIN IDENTIFY 1ST STAGE LOW PRESSURE DISC	No Data	

Aircraft Model - 1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

MASTER & C/W
THE FOLLOWING INFORMATION IS ACCURATE AND CURRENT TO THE BEST KNOWLEDGE AND ABILITY OF CSI
HOWEVER, CAMP SHALL NOT BE RESPONSIBLE OR LIABLE FOR ANY ERRORS CONTAINED IN THIS REPORT.

ITEM NO	EFFECTIVE DATE	METHOD OF COMPLIANCE	TASK DESCRIPTION	C/W Date	DISPOSITION
SB	TFE731-A72-3328	OPEN	NO. 1 ENGINE - SERVICE BULLETIN REPLACE ENGINE FAN ROTOR ASSEMBLY	No Data	
SB	TFE731-A72-3376	OPEN	NO. 1 ENGINE - SERVICE BULLETIN REPLACE ENGINE TURBINE ROTOR DISC	No Data	
SB	TFE731-A72-3388	OPEN	NO. 1 ENGINE - SERVICE BULLETIN REPLACE HIGH PRESSURE TURBINE ROTOR DISC	No Data	
SB	TFE731-A72-3424	OPEN	NO. 1 ENGINE - SERVICE BULLETIN REPLACE ENGINE FAN ROTOR ASSEMBLY	No Data	
SB	TFE731-A72-3432	OPEN	NO. 1 ENGINE - SERVICE BULLETIN INSPECT ENGINE FAN ROTOR DISC ASSEMBLY	No Data	
SB	TFE731-A72-3474	OPEN	NO. 1 ENGINE - SERVICE BULLETIN REPLACE LOW PRESSURE TURBINE STAGE #3 DISC	No Data	
SB	TFE731-A72-3502	OPEN	NO. 1 ENGINE - SERVICE BULLETIN INSTALL/REWORK LOW PRESSURE FIRST STAGE TURBINE NOZZLE ASSEMBLY	No Data	
SB	TFE731-A72-3544	OPEN	NO. 1 ENGINE - SERVICE BULLETIN REPLACE 1ST AND 2ND STAGE LOW PRESSURE TURBINE DISCS	No Data	
SB	TFE731-A72-3557	OPEN	NO. 1 ENGINE - SERVICE BULLETIN REPLACE 2ND STAGE LOW PRESSURE TURBINE	No Data	
SB	TFE731-A72-3569	OPEN	NO. 1 ENGINE - SERVICE BULLETIN REPLACE 1ST AND 2ND STAGE LOW PRESSURE TURBINE DISCS	No Data	
SB	TFE731-A72-3578	OPEN	NO. 1 ENGINE - SERVICE BULLETIN INSPECT FAN ROTOR DISCS	No Data	
SB	TFE731-A72-3636 R1	OPEN	NO. 1 ENGINE - SERVICE BULLETIN INSPECT HP COMPRESSOR IMPELLAR SEAL/RELIEF/BORE FOR FATIGUE CRACKING	No Data	
SB	TFE731-A72-3640 R3	OPEN	NO. 1 ENGINE - SERVICE BULLETIN CHANGE ENGINE OIL CHANGE INTERVAL TO 450 HOURS	No Data	
SB	TFE731-A72-3641 R3	OPEN	NO. 1 ENGINE - SERVICE BULLETIN PERFORM EDDY CURRENT INSPECTION ON HP COMPRESSOR IMPELLAR	No Data	
SB	TFE731-A72-3668 25-OCT-00	OPEN	NO. 1 ENGINE - SERVICE BULLETIN REMOVE FAN ROTOR DISC FROM SERVICE	No Data	MANDATORY
SB	TFE731-A73-3135 24-AUG-00	OPEN	NO. 1 ENGINE - SERVICE BULLETIN INSPECT/REPLACE FLEX TUBE ASSEMBLY	No Data	RECOMMENDED
SB	TFE731-A77-3020	OPEN	NO. 1 ENGINE - SERVICE BULLETIN REPLACE THERMOCOUPLE LEADS	No Data	

Aircraft Model - 1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

MASTER & C/W
THE FOLLOWING INFORMATION IS ACCURATE AND CURRENT TO THE BEST KNOWLEDGE AND ABILITY OF CSI
HOWEVER, CAMP SHALL NOT BE RESPONSIBLE OR LIABLE FOR ANY ERRORS CONTAINED IN THIS REPORT.

ITEM NO	EFFECTIVE DATE	TASK DESCRIPTION	C/W Date	DISPOSITION
		METHOD OF COMPLIANCE		
ENGINE NO. 2				
AD	1978-22-10 22-SEP-78	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE LOW PRESSURE ROTOR THRUST BALL BEARINGS	No Data	
		OPEN		
AD	1980-16-04 07-AUG-80	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE TIE ROD	No Data	
		OPEN		
AD	1981-24-08 06-JAN-82	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE TURBINE INTERSTAGE TRANSITION DUCTS	No Data	
		OPEN		
AD	1982-23-03 09-DEC-83	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE HIGH PRESSURE COMPRESSOR IMPELLERS	No Data	
		OPEN		
AD	1986-03-01 24-FEB-86	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE TURBINE INTERSTAGE TRANSITION DUCTS	No Data	
		OPEN		
PRIORITY LETTER	1986-04-02 14-FEB-86	NO. 2 ENGINE - PRIORITY LETTER FAN ROTOR DISCS	No Data	SUPERSEDED
		OPEN		
AD	1986-11-05	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE FAN ROTOR DISCS	No Data	SUPERSEDED
		OPEN		
AD	1986-21-05	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE FORWARD ENGINE MOUNTS	No Data	
		OPEN		
AD	1988-18-03 30-AUG-88	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE HIGH PRESSURE TURBINE ROTOR DISC	No Data	
		OPEN		
AD	1990-03-04 22-FEB-90	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE HIGH PRESSURE TURBINE ROTOR DISCS	No Data	
		OPEN		
AD	1990-24-06 13-NOV-90	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE THERMOCOUPLE LEAD ASSEMBLIES	No Data	
		OPEN		
AD	1991-08-13 16-APR-91	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE FAN ROTOR DISK	No Data	SUPERSEDED
		OPEN		
AD	1992-21-06 27-NOV-92	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE LOW PRESSURE TURBINE (LPT) ROTOR DISKS	No Data	MANDATORY
		OPEN		
AD	1992-26-09 22-DEC-92	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE FAN ROTOR DISK	No Data	SUPERSEDED
		OPEN		
AD	1993-10-10 29-JUN-93	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE FUEL LINE CLAMP ASSEMBLY	No Data	SUPERSEDED
		OPEN		
AD	1993-25-16 02-JUN-93	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE FAN DISK	No Data	SUPERSEDED
		OPEN		
AD	1994-07-03 06-JUN-94	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE TURBINE NOZZLES	No Data	
		OPEN		
AD	1994-14-15 05-AUG-94	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE EXHAUST DUCT ATTACHMENT CLAMPS	No Data	
		OPEN		
AD	1995-07-02 19-JUN-95	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE LOW PRESSURE TURBINE DISKS	No Data	
		OPEN		
AD	1995-07-02 1ST STAGE 19-JUN-95	NO. 2 ENGINE - ACCOMPLISH	No Data	
		OPEN		
AD	1995-07-02 2ND STAGE 19-JUN-95	NO. 2 ENGINE - ACCOMPLISH	No Data	
		OPEN		

Aircraft Model - 1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

MASTER & C/W
THE FOLLOWING INFORMATION IS ACCURATE AND CURRENT TO THE BEST KNOWLEDGE AND ABILITY OF CSI
HOWEVER, CAMP SHALL NOT BE RESPONSIBLE OR LIABLE FOR ANY ERRORS CONTAINED IN THIS REPORT.

ITEM NO	EFFECTIVE DATE	METHOD OF COMPLIANCE	TASK DESCRIPTION	C/W Date	DISPOSITION
AD	1996-04-01 15-MAR-96	OPEN	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE FAN ROTOR ASSEMBLY	No Data	
AD	1996-05-03		NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE FAN ROTOR DISKS	No Data	
	02-APR-96	OPEN			
AD	1996-18-13	OPEN	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE FAN ROTOR DISK	No Data	SUPERSEDED
AD	1998-17-01 13-OCT-98	OPEN	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE FLEX FUEL TUBE	No Data	
AD	1998-17-01 REV.1 29-NOV-99	OPEN	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE FLEX FUEL TUBE	No Data	MANDATORY
AD	2000-15-09		NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE HPC IMPELLER	No Data	
	10-OCT-00	REPEAT OPEN			
AD	2001-23-09		NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE TO PREVENT FAILURE OF THE FAN ROTOR DISC DUE TO FATIGUE CRACKING IN THE DOVETAIL SLOTS	No Data	MANDATORY
	21-DEC-01	OPEN			
SB	TFE731-A72-3668 25-OCT-00	OPEN	NO. 2 ENGINE - REMOVE FAN ROTOR DISC FROM SERVICE SERVICE BULLETIN	No Data	MANDATORY
AD	990100U		NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE AD86-11-05 #2 ENGINE	No Data	
		OPEN			
AD	990101U		NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE AD90-24-06 #2 ENGINE	06/11/1991	
		NOT APPLICABLE N/A			
AD	990102U		NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE AD92-21-06 #2 ENGINE	01/25/1993	
		COMPLIED WITH C/W			
AD	990103U		NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE AD94-07-03 #2 ENGINE	07/27/1994	
		NOT APPLICABLE N/A			
AD	990104U		NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE AD95-07-02 #2E #2 LPT DSK	09/26/1995	
		NOT APPLICABLE N/A			
AD	990105U		NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE AD95-07-02 #2E #1 LPT DSK	09/26/1995	
		NOT APPLICABLE N/A			
AD	990106U		NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE AD96-04-01 #2 ENGINE	10/06/1998	
		NOT APPLICABLE N/A			
AD	990107U		NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE AD96-05-03 #2 ENGINE	03/27/1996	
		NOT APPLICABLE N/A			
AD	990108U		NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE AD96-18-13 #2 ENGINE	10/06/1998	
		NOT APPLICABLE N/A			
SB	TFE-731-A72-3504		NO. 2 ENGINE - SERVICE BULLETIN INSPECT FAN ROTOR ASSEMBLY	No Data	
		OPEN			
SB	TFE731-73-3137		NO. 2 ENGINE - SERVICE BULLETIN REPLACE FUEL HEATER CHECK VALVES	No Data	
		OPEN			
SB	TFE731-A72-3126		NO. 2 ENGINE - SERVICE BULLETIN REPLACE/REWORK PLANET GEAR ASSEMBLY	No Data	
		OPEN			
SB	TFE731-A72-3169		NO. 2 ENGINE - SERVICE BULLETIN REPLACE IDENTIFIED HP ROTOR #5 THRUST BEARING	No Data	
		OPEN			
SB	TFE731-A72-3306		NO. 2 ENGINE - SERVICE BULLETIN IDENTIFY 1ST STAGE LOW PRESSURE DISC	No Data	
		OPEN			

Aircraft Model - 1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 14-MAR-2002

MASTER & C/W
THE FOLLOWING INFORMATION IS ACCURATE AND CURRENT TO THE BEST KNOWLEDGE AND ABILITY OF CSI
HOWEVER, CAMP SHALL NOT BE RESPONSIBLE OR LIABLE FOR ANY ERRORS CONTAINED IN THIS REPORT.

ITEM NO	EFFECTIVE DATE	METHOD OF COMPLIANCE	TASK DESCRIPTION	C/W Date	DISPOSITION
SB	TFE731-A72-3328	OPEN	NO. 2 ENGINE - SERVICE BULLETIN REPLACE ENGINE FAN ROTOR ASSEMBLY	No Data	
SB	TFE731-A72-3376	OPEN	NO. 2 ENGINE - SERVICE BULLETIN REPLACE ENGINE TURBINE ROTOR DISC	No Data	
SB	TFE731-A72-3388	OPEN	NO. 2 ENGINE - SERVICE BULLETIN REPLACE HIGH PRESSURE TURBINE ROTOR DISC	No Data	
SB	TFE731-A72-3424	OPEN	NO. 2 ENGINE - SERVICE BULLETIN REPLACE ENGINE FAN ROTOR ASSEMBLY	No Data	
SB	TFE731-A72-3432	OPEN	NO. 2 ENGINE - SERVICE BULLETIN INSPECT ENGINE FAN ROTOR DISC ASSEMBLY	No Data	
SB	TFE731-A72-3474	OPEN	NO. 2 ENGINE - SERVICE BULLETIN REPLACE LOW PRESSURE TURBINE STAGE #3 DISC	No Data	
SB	TFE731-A72-3502	OPEN	NO. 2 ENGINE - SERVICE BULLETIN INSTALL/REWORK LOW PRESSURE FIRST STAGE TURBINE NOZZLE ASSEMBLY	No Data	
SB	TFE731-A72-3544	OPEN	NO. 2 ENGINE - SERVICE BULLETIN REPLACE 1ST AND 2ND STAGE LOW PRESSURE TURBINE DISCS	No Data	
SB	TFE731-A72-3557	OPEN	NO. 2 ENGINE - SERVICE BULLETIN REPLACE 2ND STAGE LOW PRESSURE TURBINE	No Data	
SB	TFE731-A72-3569	OPEN	NO. 2 ENGINE - SERVICE BULLETIN REPLACE 1ST AND 2ND STAGE LOW PRESSURE TURBINE DISCS	No Data	
SB	TFE731-A72-3578	OPEN	NO. 2 ENGINE - SERVICE BULLETIN INSPECT FAN ROTOR DISCS	No Data	
SB	TFE731-A72-3636 R1	OPEN	NO. 2 ENGINE - SERVICE BULLETIN INSPECT HP COMPRESSOR IMPELLAR SEAL/RELIEF/BORE FOR FATIGUE CRACKING	No Data	
SB	TFE731-A72-3640 R3	OPEN	NO. 2 ENGINE - SERVICE BULLETIN CHANGE ENGINE OIL CHANGE INTERVAL TO 450 HOURS	No Data	
SB	TFE731-A72-3641 R3	OPEN	NO. 2 ENGINE - SERVICE BULLETIN PERFORM EDDY CURRENT INSPECTION ON HP COMPRESSOR IMPELLAR	No Data	
SB	TFE731-A72-3668 25-OCT-00	OPEN	NO. 2 ENGINE - SERVICE BULLETIN REMOVE FAN ROTOR DISC FROM SERVICE	No Data	MANDATORY
SB	TFE731-A73-3135 24-AUG-00	OPEN	NO. 2 ENGINE - SERVICE BULLETIN INSPECT/REPLACE FLEX TUBE ASSEMBLY	No Data	RECOMMENDED
SB	TFE731-A77-3020	OPEN	NO. 2 ENGINE - SERVICE BULLETIN REPLACE THERMOCOUPLE LEADS	No Data	



AIRCRAFT Updates Report

Serial #: 368 Reg. #: N368MD
 Model: 1124A WESTWIND

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
AIRCRAFT Serial #: 368 Reg #: N368MD								
910080	SB 1124-24-008							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 04-NOV-1987 12:00:00					
MOS	06-JUN-1986		REASON: --					MOS
HRS	3108		TECH:					HRS
AFL	1422		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: C/W								
910650	SB 1124-24-065							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 04-NOV-1987 12:00:00					
MOS	06-JUN-1986		REASON: --					MOS
HRS	3108		TECH:					HRS
AFL	1422		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: C/W								
910720	SB 1124-22-072 A/P							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 04-NOV-1987 12:00:00					
MOS	28-MAY-1986		REASON: --					MOS
HRS	3099		TECH:					HRS
AFL			INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: C/W								
910880	SB 1124-11-088A							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 04-NOV-1987 12:00:00					
MOS	18-SEP-1987		REASON: --					MOS
HRS	3734		TECH:					HRS
AFL			INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: C/W								
950930	SL WW-2493 FLAP POTENT							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 04-NOV-1987 12:00:00					
MOS	10-AUG-1986		REASON: --					MOS
HRS	3515		TECH:					HRS
AFL			INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: C/W								
950840	SL WW-2484							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 04-NOV-1987 12:00:00					
MOS	05-JAN-1987		REASON: --					MOS
HRS/MS			TECH:					HRS/MS
AFL			INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: C/W								
910100	ACCOMPLISH SB1124-27-100R2 L/H RODS BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 06-NOV-1987 12:00:00					
MOS	14-NOV-1985		REASON: --					MOS
HRS	2702		TECH:					HRS
AFL	1681		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: C/W								

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
910290	SB 1124-21-029				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 06-NOV-1987 12:00:00					
MOS	20-JAN-1986	REASON: --					MOS
HRS	2832	TECH:					HRS
AFL	1755	INSP:					AFL
Note: C/W			LABOR HRS: 0	COST: \$0.00			
910250	SB 1124-22-025				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 06-NOV-1987 12:00:00					
MOS	09-JAN-1986	REASON: --					MOS
HRS	2812	TECH:					HRS
AFL	1743	INSP:					AFL
Note: C/W			LABOR HRS: 0	COST: \$0.00			
910910	ACCOMPLISH INSP #2 ENG MT FASTENERS BULLETIN				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 06-NOV-1987 12:00:00					
MOS	18-SEP-1987	REASON: --					MOS
HRS	3734	TECH:					HRS
AFL		INSP:					AFL
Note: C/W			LABOR HRS: 0	COST: \$0.00			
910860	SB 1124-27-086				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 06-NOV-1987 12:00:00					
MOS	18-SEP-1987	REASON: --					MOS
HRS/MS		TECH:					HRS/MS
AFL		INSP:					AFL
Note: C/W			LABOR HRS: 0	COST: \$0.00			
910620	SB 1124-27-062				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 06-NOV-1987 12:00:00					
MOS	18-SEP-1987	REASON: --					MOS
HRS	3734	TECH:					HRS
AFL		INSP:					AFL
Note: C/W			LABOR HRS: 0	COST: \$0.00			
910450	SB 1124-32-045				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 06-NOV-1987 12:00:00					
MOS	06-DEC-1985	REASON: --					MOS
HRS	2758	TECH:					HRS
AFL	1709	INSP:					AFL
Note: C/W			LABOR HRS: 0	COST: \$0.00			
910400	SB 1124-57-004				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 06-NOV-1987 12:00:00					
MOS	25-AUG-1985	REASON: --					MOS
HRS	2564	TECH:					HRS
AFL	1584	INSP:					AFL
Note: C/W			LABOR HRS: 0	COST: \$0.00			
910300	SB 1124-32-030				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 06-NOV-1987 12:00:00					
MOS	06-DEC-1985	REASON: --					MOS
HRS	2758	TECH:					HRS
AFL	1709	INSP:					AFL
Note: C/W			LABOR HRS: 0	COST: \$0.00			

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
990085U	ACCOMPLISH AIRWORTHINESS DIRECTIVE AD81-24-08 #1 ENGINE			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
	C/W	WARR	TRANSACTION DATE: 24-NOV-1987 12:00:00					
MOS	06-JAN-1982		REASON: --					MOS
HRS/MS			TECH:					HRS/MS
AFL			INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: INSP L/E TURB DUCT - N/A BY S/N								
1981-07-07 PARA B	TO PREVENT FIRE DUE TO OVERHEATING OF THE INTERCOM SYSTEM AIRWORTHINESS DIRECTIVE							
	C/W	WARR	TRANSACTION DATE: 24-NOV-1987 12:00:00					
MOS			REASON: --					MOS
MSC			TECH:					MSC
AFL	0		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
990120U	AIRWORTHINESS DIRECTIVE AD86-03-01 #1 ENGINE							
	C/W	WARR	TRANSACTION DATE: 24-NOV-1987 12:00:00					
MOS	28-JUL-1986		REASON: --					MOS
HRS			TECH:					HRS
AFL			INSP:	LABOR HRS: 0	COST: \$0.00			AFL
990090U	AIRWORTHINESS DIRECTIVE AD81-24-08 #2 ENGINE							
	C/W	WARR	TRANSACTION DATE: 24-NOV-1987 12:00:00					
MOS	06-JAN-1982		REASON: --					MOS
MSC			TECH:					MSC
AFL			INSP:	LABOR HRS: 0	COST: \$0.00			AFL
1981-07-07 PARA A	TO PREVENT FIRE DUE TO OVERHEATING OF THE INTERCOM SYSTEM AIRWORTHINESS DIRECTIVE							
	C/W	WARR	TRANSACTION DATE: 24-NOV-1987 12:00:00					
MOS			REASON: --					MOS
MSC			TECH:					MSC
AFL	0		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
990130	ACCOMPLISH AD86-14-02 AIRWORTHINESS DIRECTIVE			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
	C/W	WARR	TRANSACTION DATE: 24-NOV-1987 12:00:00					
MOS	13-OCT-1985		REASON: --					MOS
HRS/MS			TECH:					HRS/MS
AFL			INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: REF CODE 550656								
990045	AD80-16-04 AIRWORTHINESS DIRECTIVE							
	C/W	WARR	TRANSACTION DATE: 24-NOV-1987 12:00:00					
MOS			REASON: --					MOS
MSC			TECH:					MSC
AFL	0		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
1980-18-08	TO PREVENT LOSS OF EMERGENCY ELECTRICAL POWER AND POSSIBLE CORROSIVE OR THERMAL DAMAGE TO THE AIRCRAFT AIRWORTHINESS DIRECTIVE							
	C/W	WARR	TRANSACTION DATE: 24-NOV-1987 12:00:00					
MOS			REASON: --					MOS
MSC			TECH:					MSC
AFL	0		INSP:	LABOR HRS: 0	COST: \$0.00			AFL

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR	
1980-19-15	TO PREVENT THE UPPER HOT LIQUID CONTAINER IN THE GALLEY FROM RUBBING AGAINST THE ELECTRICAL WIRE BUNDLE AND CAUSING A FIRE WHICH COULD RESULT IN THE LOSS OF THRUST REVERSERS, FLAPS, SPOILERS, AND SOME AIRPLANE LIGHTS AIRWORTHINESS DIRECTIVE						
CW	WARR	TRANSACTION DATE: 24-NOV-1987 12:00:00					
MOS		REASON: --				MOS	
MSC		TECH:				MSC	
AFL	0	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
1972-19-04	TO PREVENT A POSSIBLE BATTERY FIRE THAT MAY RESULT FROM OVERHEATING CAUSED BY AN UNDETECTED BATTERY FAILURE AIRWORTHINESS DIRECTIVE						
CW	WARR	TRANSACTION DATE: 24-NOV-1987 12:00:00					
MOS		REASON: --				MOS	
MSC		TECH:				MSC	
AFL	0	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
990095	ACCOMPLISH AD82-21-04 AIRWORTHINESS DIRECTIVE						
CW	WARR	TRANSACTION DATE: 24-NOV-1987 12:00:00				Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
MOS	22-JAN-1985	REASON: --				MOS	
HRS/MSQ		TECH:				HRS/MSQ	
AFL		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: PS823 INSTALLED							
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN						
CW	WARR	TRANSACTION DATE: 23-JUN-1988 12:00:00				Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
MOS	25-MAR-1988	REASON: --				MOS	
HRS	3883	TECH:				HRS	
AFL	2442	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3							
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN						
CW	WARR	TRANSACTION DATE: 23-JUN-1988 12:00:00				Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
MOS	25-MAR-1988	REASON: --				MOS	
HRS	3883	TECH:				HRS	
AFL	2442	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3							
950785	SL WW-2478 R HYD PUMP						
CW	WARR	TRANSACTION DATE: 23-JUN-1988 12:00:00				Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
MOS	25-MAR-1988	REASON: --				MOS	
HRS	3883	TECH:				HRS	
AFL	2442	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3							
950780	SL WW-2478 L HYD PUMP						
CW	WARR	TRANSACTION DATE: 23-JUN-1988 12:00:00				Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
MOS	25-MAR-1988	REASON: --				MOS	
HRS	3883	TECH:				HRS	
AFL	2442	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3							
950570	SL WW-2457 PART A,R/H						
CW	WARR	TRANSACTION DATE: 23-JUN-1988 12:00:00				Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
MOS	25-MAR-1988	REASON: --				MOS	
HRS	3883	TECH:				HRS	
AFL	2442	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3 - RPT 160 HRS							



AIRCRAFT Updates Report

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model : 1124A WESTWIND

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
950569	SL WW-2457 PART A,L/H							
	C/W	WARR	TRANSACTION DATE: 23-JUN-1988 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	25-MAR-1988		REASON: --					MOS
HRS	3883		TECH:					HRS
AFL	2442		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - RPT 150 HRS								
910170	SB 1124-27-017							
	C/W	WARR	TRANSACTION DATE: 02-SEP-1988 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	15-AUG-1988		REASON: --					MOS
HRS	3988		TECH:					HRS
AFL	2523		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: C/W								
910300	SB 1124-32-030							
	C/W	WARR	TRANSACTION DATE: 02-SEP-1988 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	15-AUG-1988		REASON: --					MOS
HRS	3988		TECH:					HRS
AFL	2523		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: C/W								
910920	SB 1124-57-092							
	C/W	WARR	TRANSACTION DATE: 02-SEP-1988 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	15-AUG-1988		REASON: --					MOS
HRS	3988		TECH:					HRS
AFL	2523		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: C/W								
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN							
	C/W	WARR	TRANSACTION DATE: 08-SEP-1988 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	16-AUG-1988		REASON: --					MOS
HRS	3988		TECH:					HRS
AFL	2523		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
910930	ACCOMPLISH SB 1124-79-093 PART A BULLETIN							
	C/W	WARR	TRANSACTION DATE: 08-SEP-1988 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	15-AUG-1988		REASON: --					MOS
HRS	3988		TECH:					HRS
AFL	2523		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: UNTIL PART B C/W - C/W PART II								
910940	SB1124-32-094 LG SELECTOR							
	C/W	WARR	TRANSACTION DATE: 08-SEP-1988 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	15-AUG-1988		REASON: --					MOS
HRS	3988		TECH:					HRS
AFL	2523		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: C/W								
910960	SB 1124-32-096							
	C/W	WARR	TRANSACTION DATE: 08-SEP-1988 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	15-AUG-1988		REASON: --					MOS
HRS	3988		TECH:					HRS
AFL	2523		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: C/W								

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model : 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
910950	SB 1124-27-095						
	C/W	WARR					
	TRANSACTION DATE: 08-SEP-1988 12:00:00						
	REASON: --						
MOS	15-AUG-1988						MOS
HRS	3988						HRS
AFL	2523						AFL
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Note: C/W						
951031	SL WW-24103 R/H SERVICE BULLETIN						
	C/W	WARR					
	TRANSACTION DATE: 08-SEP-1988 12:00:00						
	REASON: --						
MOS							MOS
MSC							MSC
AFL	0						AFL
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
951030	SL WW-24103 L/H SERVICE BULLETIN						
	C/W	WARR					
	TRANSACTION DATE: 08-SEP-1988 12:00:00						
	REASON: --						
MOS							MOS
MSC							MSC
AFL	0						AFL
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
990020	ACCOMPLISH AD74-08-09 R2 AIRWORTHINESS DIRECTIVE						
	C/W	WARR					
	TRANSACTION DATE: 08-SEP-1988 12:00:00						
	REASON: W - FREQUENCY OK AS IS						
MOS	15-AUG-1988						MOS
HRS	3989						HRS
AFL	2523						AFL
	TECH:						
	INSP:						
	LABOR HRS: .2						
	COST: \$0.00						
	Note: AD 74-08-09 - RPT 1000 HRS						
950942	ACCOMPLISH SLWW-2494 REV 3 RMG BOLTS BULLETIN						
	C/W	WARR					
	TRANSACTION DATE: 08-SEP-1988 12:00:00						
	REASON: --						
MOS	29-DEC-1987						MOS
HRS	3767						HRS
AFL	2367						AFL
	TECH:						
	INSP:						
	LABOR HRS: 3						
	COST: \$0.00						
	Note: OP 2,3						
950942	ACCOMPLISH SLWW-2494 REV 3 RMG BOLTS BULLETIN						
	C/W	WARR					
	TRANSACTION DATE: 08-SEP-1988 12:00:00						
	REASON: --						
MOS	06-AUG-1988						MOS
HRS	3988						HRS
AFL	2523						AFL
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Note: OP 2,3						
950941	ACCOMPLISH SLWW-2494 REV 3 LMG BOLTS BULLETIN						
	C/W	WARR					
	TRANSACTION DATE: 08-SEP-1988 12:00:00						
	REASON: --						
MOS	29-DEC-1987						MOS
HRS	3767						HRS
AFL	2367						AFL
	TECH:						
	INSP:						
	LABOR HRS: 3						
	COST: \$0.00						
	Note: OP 2,3						
950941	ACCOMPLISH SLWW-2494 REV 3 LMG BOLTS BULLETIN						
	C/W	WARR					
	TRANSACTION DATE: 08-SEP-1988 12:00:00						
	REASON: --						
MOS	06-AUG-1988						MOS
HRS	3988						HRS
AFL	2523						AFL
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Note: OP 2,3						

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN							
	C/W	WARR	TRANSACTION DATE: 08-SEP-1988 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	15-AUG-1988		REASON: --					MOS
HRS	3988		TECH:					HRS
AFL	2523		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
950911	ACCOMPLISH SL WW-2491 REV 1 NLG BRGS BULLETIN							
	C/W	WARR	TRANSACTION DATE: 08-SEP-1988 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	29-DEC-1987		REASON: --					MOS
HRS	3767		TECH:					HRS
AFL	2367		INSP:	LABOR HRS: 8	COST: \$0.00			AFL
Note: RPT 1200 HRS								
950910	SL WW-2491A							
	C/W	WARR	TRANSACTION DATE: 08-SEP-1988 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	15-AUG-1988		REASON: --					MOS
HRS	3988		TECH:					HRS
AFL	2523		INSP:	LABOR HRS: 2	COST: \$0.00			AFL
Note: C/W								
950785	SL WW-2478 R HYD PUMP							
	C/W	WARR	TRANSACTION DATE: 08-SEP-1988 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	06-AUG-1988		REASON: --					MOS
HRS	3988		TECH:					HRS
AFL	2523		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
950780	SL WW-2478 L HYD PUMP							
	C/W	WARR	TRANSACTION DATE: 08-SEP-1988 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	06-AUG-1988		REASON: --					MOS
HRS	3988		TECH:					HRS
AFL	2523		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
950570	SL WW-2457 PART A,R/H							
	C/W	WARR	TRANSACTION DATE: 08-SEP-1988 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	12-AUG-1988		REASON: --					MOS
HRS	3988		TECH:					HRS
AFL	2523		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - RPT 150 HRS								
950569	SL WW-2457 PART A,L/H							
	C/W	WARR	TRANSACTION DATE: 08-SEP-1988 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	12-AUG-1988		REASON: --					MOS
HRS	3988		TECH:					HRS
AFL	2523		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - RPT 150 HRS								
910931	SB1124-79-093 PART B							
	C/W	WARR	TRANSACTION DATE: 08-SEP-1988 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	15-AUG-1988		REASON: --					MOS
HRS	3988		TECH:					HRS
AFL	2523		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: C/W								

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model : 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
910200	ACCOMPLISH SB 1124-55-020 REV 2 BULLETIN						
CW	WARR	TRANSACTION DATE: 07-FEB-1989 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	20-JAN-1989	REASON: --					MOS
HRS	4130	TECH:					HRS
AFL	2635	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
950911	ACCOMPLISH SL WW-2491 REV 1 NLG BRGS BULLETIN						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
CW	WARR	TRANSACTION DATE: 07-FEB-1989 12:00:00					
MOS	29-DEC-1987	REASON: --					MOS
HRS	3797	TECH:					HRS
AFL	2386	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: REF TO CODE 320118 - RPT 1200 HRS							
990166U	AIRWORTHINESS DIRECTIVE AD88-18-03 #2 ENGINE						
CW	WARR	TRANSACTION DATE: 07-FEB-1989 12:00:00					
MOS	20-JAN-1989	REASON: --					MOS
MSC		TECH:					MSC
AFL	2635	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
990165U	AIRWORTHINESS DIRECTIVE AD88-18-03 #1 ENGINE						
CW	WARR	TRANSACTION DATE: 07-FEB-1989 12:00:00					
MOS	20-JAN-1989	REASON: --					MOS
HRS	4130	TECH:					HRS
AFL	2635	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
1986-14-02	SUPERSEDED BY AD1989-12-08 AIRWORTHINESS DIRECTIVE						
CW	WARR	TRANSACTION DATE: 07-FEB-1989 12:00:00					
MOS		REASON: --					MOS
MSC		TECH:					MSC
AFL	0	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
CW	WARR	TRANSACTION DATE: 07-FEB-1989 12:00:00					
MOS	20-JAN-1989	REASON: --					MOS
HRS	4130	TECH:					HRS
AFL	2635	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
950500	SL WW-2450B INSP NACL CWL						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
CW	WARR	TRANSACTION DATE: 07-FEB-1989 12:00:00					
MOS	20-JAN-1989	REASON: --					MOS
HRS	4130	TECH:					HRS
AFL	2635	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - RPT 150 HRS							
950785	SL WW-2478 R HYD PUMP						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
CW	WARR	TRANSACTION DATE: 07-FEB-1989 12:00:00					
MOS	20-JAN-1989	REASON: --					MOS
HRS	4130	TECH:					HRS
AFL	2635	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model : 1124A WESTWIND

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
950780	SL WW-2478 L HYD PUMP							
C/W	WARR	TRANSACTION DATE: 07-FEB-1989 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	20-JAN-1989	REASON: --						MOS
HRS	4130	TECH:						HRS
AFL	2635	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
950570	SL WW-2457 PART A,R/H							
C/W	WARR	TRANSACTION DATE: 07-FEB-1989 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	20-JAN-1989	REASON: --						MOS
HRS	4130	TECH:						HRS
AFL	2635	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - RPT 150 HRS								
950569	SL WW-2457 PART A,L/H							
C/W	WARR	TRANSACTION DATE: 07-FEB-1989 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	20-JAN-1989	REASON: --						MOS
HRS	4130	TECH:						HRS
AFL	2635	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - RPT 150 HRS								
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN							
C/W	WARR	TRANSACTION DATE: 07-FEB-1989 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	20-JAN-1989	REASON: --						MOS
HRS	4130	TECH:						HRS
AFL	2635	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
950940	SL WW-2494							
C/W	WARR	TRANSACTION DATE: 02-MAR-1989 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	20-JAN-1989	REASON: --						MOS
HRS	4130	TECH:						HRS
AFL	2635	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
950180	SL WW-2424D,L FLEX SHAFT							
C/W	WARR	TRANSACTION DATE: 09-MAY-1989 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	06-APR-1989	REASON: --						MOS
HRS	4215	TECH:						HRS
AFL	2745	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: REF: CODE 270280								
950185	SL WW-2424D,R FLEX SHAFT							
C/W	WARR	TRANSACTION DATE: 09-MAY-1989 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	06-APR-1989	REASON: --						MOS
HRS	4215	TECH:						HRS
AFL	2745	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: REF: CODE 270285								
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN							
C/W	WARR	TRANSACTION DATE: 13-JUN-1989 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	09-JUN-1989	REASON: --						MOS
HRS	4274	TECH:						HRS
AFL	2800	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
950500	SL WW-2450B INSP NACL CWL						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 13-JUN-1989 12:00:00					
MOS	09-JUN-1989	REASON: --					MOS
HRS	4274	TECH:					HRS
AFL	2800	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - RPT 150 HRS							
950571	SL WW-2457 PART B,L/H						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 13-JUN-1989 12:00:00					
MOS	09-JUN-1989	REASON: --					MOS
HRS	4274	TECH:					HRS
AFL	2800	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 3 - RPT 600 HRS							
950780	SL WW-2478 L HYD PUMP						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 13-JUN-1989 12:00:00					
MOS	09-JUN-1989	REASON: --					MOS
HRS	4274	TECH:					HRS
AFL	2800	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 13-JUN-1989 12:00:00					
MOS	09-JUN-1989	REASON: --					MOS
HRS	4274	TECH:					HRS
AFL	2800	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
950942	ACCOMPLISH SLWW-2494 REV 3 RMG BOLTS BULLETIN						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 13-JUN-1989 12:00:00					
MOS	09-JUN-1989	REASON: --					MOS
HRS	4274	TECH:					HRS
AFL	2800	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3							
910911U	SERVICE BULLETIN SB 1124-71-091 PART II						
C/W	WARR	TRANSACTION DATE: 13-JUN-1989 12:00:00					
MOS	12-APR-1989	REASON: --					MOS
HRS	4218	TECH:					HRS
AFL		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
950941	ACCOMPLISH SLWW-2494 REV 3 LMG BOLTS BULLETIN						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 13-JUN-1989 12:00:00					
MOS	09-JUN-1989	REASON: --					MOS
HRS	4274	TECH:					HRS
AFL	2800	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3							
950785	SL WW-2478 R HYD PUMP						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 13-JUN-1989 12:00:00					
MOS	09-JUN-1989	REASON: --					MOS
HRS	4274	TECH:					HRS
AFL	2800	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
950572	SL WW-2457 PART B,R/H							
	C/W	WARR	TRANSACTION DATE: 13-JUN-1989 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	09-JUN-1989		REASON: --					MOS
HRS	4274		TECH:					HRS
AFL	2800		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 3								
950570	SL WW-2457 PART A,R/H							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 13-JUN-1989 12:00:00					
MOS	09-JUN-1989		REASON: --					MOS
HRS	4274		TECH:					HRS
AFL	2800		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - RPT 150 HRS								
950569	SL WW-2457 PART A,L/H							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 13-JUN-1989 12:00:00					
MOS	09-JUN-1989		REASON: --					MOS
HRS	4274		TECH:					HRS
AFL	2800		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - RPT 150 HRS								
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 07-JUL-1989 12:00:00					
MOS	09-JUN-1989		REASON: --					MOS
HRS	4273		TECH:					HRS
AFL	2800		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
950942	ACCOMPLISH SLWW-2494 REV 3 RMG BOLTS BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 07-JUL-1989 12:00:00					
MOS	09-JUN-1989		REASON: --					MOS
HRS	4273		TECH:					HRS
AFL	2800		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
950941	ACCOMPLISH SLWW-2494 REV 3 LMG BOLTS BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 07-JUL-1989 12:00:00					
MOS	09-JUN-1989		REASON: --					MOS
HRS	4273		TECH:					HRS
AFL	2800		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 07-JUL-1989 12:00:00					
MOS	09-JUN-1989		REASON: --					MOS
HRS	4273		TECH:					HRS
AFL	2800		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
950500	SL WW-2450B INSP NACL CWL							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 07-JUL-1989 12:00:00					
MOS	09-JUN-1989		REASON: --					MOS
HRS	4273		TECH:					HRS
AFL	2800		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - RPT 150 HRS								

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model : 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
950570	SL WW-2457 PART A,R/H						
C/W	WARR	TRANSACTION DATE: 07-JUL-1989 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS 09-JUN-1989		REASON: --					MOS
HRS 4273		TECH:					HRS
AFL 2800		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - RPT 150 HRS							
950572	SL WW-2457 PART B,R/H						
C/W	WARR	TRANSACTION DATE: 07-JUL-1989 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS 09-JUN-1989		REASON: --					MOS
HRS 4273		TECH:					HRS
AFL 2800		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 3							
950785	SL WW-2478 R HYD PUMP						
C/W	WARR	TRANSACTION DATE: 07-JUL-1989 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS 09-JUN-1989		REASON: --					MOS
HRS 4273		TECH:					HRS
AFL 2800		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
950780	SL WW-2478 L HYD PUMP						
C/W	WARR	TRANSACTION DATE: 07-JUL-1989 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS 09-JUN-1989		REASON: --					MOS
HRS 4273		TECH:					HRS
AFL 2800		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
950571	SL WW-2457 PART B,L/H						
C/W	WARR	TRANSACTION DATE: 07-JUL-1989 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS 09-JUN-1989		REASON: --					MOS
HRS 4273		TECH:					HRS
AFL 2800		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 3 - RPT 600 HRS							
950569	SL WW-2457 PART A,L/H						
C/W	WARR	TRANSACTION DATE: 07-JUL-1989 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS 09-JUN-1989		REASON: --					MOS
HRS 4273		TECH:					HRS
AFL 2800		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - RPT 160 HRS							
910090	SB 1124-32-009						
C/W	WARR	TRANSACTION DATE: 12-JUL-1989 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS 06-SEP-1989		REASON: --					MOS
HRS 4272		TECH:					HRS
AFL 2800		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: C/W							
910912U	SERVICE BULLETIN SB 1124-71-091 PART II						
C/W	WARR	TRANSACTION DATE: 10-AUG-1989 12:00:00					
MOS 31-MAY-1989		REASON: --					MOS
MSC		TECH:					MSC
AFL 2793		INSP:	LABOR HRS: 0	COST: \$0.00			AFL



AIRCRAFT Updates Report

Serial #: 368 Reg. #: N368MD
 Model: 1124A WESTWIND

Report Date **14-MAR-2002** From Date : To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
990822U	AIRWORTHINESS DIRECTIVE AD82-23-03 R1 #2 ENGINE							
C/W	WARR	TRANSACTION DATE: 12-OCT-1989 12:00:00						
MOS	17-MAY-1989	REASON: --					MOS	
MSC		TECH:					MSC	
AFL	2793	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 07-DEC-1989 12:00:00						
MOS	30-NOV-1989	REASON: --					MOS	
HRS	4430	TECH:					HRS	
AFL	2987	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3								
950569	SL WW-2457 PART A,L/H							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 07-DEC-1989 12:00:00						
MOS	30-NOV-1989	REASON: --					MOS	
HRS	4430	TECH:					HRS	
AFL	2987	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3 - RPT 150 HRS								
950500	SL WW-2450B INSP NAACL CWL							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 07-DEC-1989 12:00:00						
MOS	30-NOV-1989	REASON: --					MOS	
HRS	4430	TECH:					HRS	
AFL	2987	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3 - RPT 150 HRS								
950570	SL WW-2457 PART A,R/H							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 07-DEC-1989 12:00:00						
MOS	30-NOV-1989	REASON: --					MOS	
HRS	4430	TECH:					HRS	
AFL	2987	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3 - RPT 150 HRS								
950785	SL WW-2478 R HYD PUMP							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 07-DEC-1989 12:00:00						
MOS	30-NOV-1989	REASON: --					MOS	
HRS	4430	TECH:					HRS	
AFL	2987	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3								
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 07-DEC-1989 12:00:00						
MOS	30-NOV-1989	REASON: --					MOS	
HRS	4430	TECH:					HRS	
AFL	2987	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3								
950911	ACCOMPLISH SL WW-2491 REV 1 NLG BRGS BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 07-DEC-1989 12:00:00						
MOS	30-NOV-1989	REASON: --					MOS	
HRS	4430	TECH:					HRS	
AFL	2987	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
Note: REF TO CODE 320118 - RPT								

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
950780	SL WW-2478 L HYD PUMP						
		Done By: CAMP SYSTEMS INTERNATIONAL, LLC					
C/W	WARR	TRANSACTION DATE: 07-DEC-1989 12:00:00					
MOS	30-NOV-1989	REASON: --					MOS
HRS	4430	TECH:					HRS
AFL	2987	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
972202U	SERVICE BULLETIN TFE731-A72-3388 RIGHT ENG						
C/W	WARR	TRANSACTION DATE: 07-DEC-1989 12:00:00					
MOS	05-DEC-1989	REASON: --					MOS
MSC		TECH:					MSC
AFL	2994	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
972200U	SERVICE BULLETIN TFE731-A72-3388 LEFT ENG						
C/W	WARR	TRANSACTION DATE: 07-DEC-1989 12:00:00					
MOS	05-DEC-1989	REASON: --					MOS
HRS	4436	TECH:					HRS
AFL	2994	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
990100	ACCOMPLISH AD84-02-08 AIRWORTHINESS DIRECTIVE						
C/W	WARR	TRANSACTION DATE: 11-APR-1990 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	20-JAN-1989	REASON: --					MOS
HRS	4130	TECH:					HRS
AFL	2635	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: SCOTT OXYGEN CYLIND - N/A							
1984-02-08	TO PREVENT POSSIBLE USE OF IMPROPERLY CHARGED OXYGEN CYLINDERS, BLEED DOWN (DISCHARGE) THE CYLINDERS, AND RECHARGE WITH AVIATOR'S BREATHING OXYGEN AIRWORTHINESS DIRECTIVE						
C/W	WARR	TRANSACTION DATE: 12-APR-1990 12:00:00					
MOS		REASON: --					MOS
MSC		TECH:					MSC
AFL	0	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
1990-03-02	SUPERSEDED BY AD1990-06-13 AIRWORTHINESS DIRECTIVE						
C/W	WARR	TRANSACTION DATE: 12-APR-1990 12:00:00					
MOS		REASON: --					MOS
MSC		TECH:					MSC
AFL	0	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
990982U	ACCOMPLISH AIRWORTHINESS DIRECTIVE AD90-03-04 #1 ENGINE						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 23-APR-1990 12:00:00					
MOS	05-DEC-1989	REASON: --					MOS
HRS	4436	TECH:					HRS
AFL	2994	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: C/W 731-A72-3388 - N/A							
990983U	ACCOMPLISH AIRWORTHINESS DIRECTIVE AD90-03-04 #2 ENGINE						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 23-APR-1990 12:00:00					
MOS	05-DEC-1989	REASON: --					MOS
HRS	4436	TECH:					HRS
AFL	2994	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: C/W731-A72-3388 - N/A							

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
990982U	AIRWORTHINESS DIRECTIVE AD90-03-04 #1 ENGINE							
	C/W	WARR	TRANSACTION DATE: 02-MAY-1990 12:00:00					
MOS	21-MAR-1990		REASON: --					MOS
MSC			TECH:					MSC
AFL			INSP:	LABOR HRS: 0	COST: \$0.00			AFL
990983U	AIRWORTHINESS DIRECTIVE AD90-03-04 #2 ENGINE							
	C/W	WARR	TRANSACTION DATE: 02-MAY-1990 12:00:00					
MOS	21-MAR-1990		REASON: --					MOS
MSC			TECH:					MSC
AFL			INSP:	LABOR HRS: 0	COST: \$0.00			AFL
910200	ACCOMPLISH SB 1124-55-020 REV 2 BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 24-MAY-1990 12:00:00					
MOS	30-APR-1990		REASON: --					MOS
HRS	4578		TECH:					HRS
AFL	3154		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
950500	SL WW-2450B INSP NACL CWL							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 24-MAY-1990 12:00:00					
MOS	30-APR-1990		REASON: --					MOS
HRS	4578		TECH:					HRS
AFL	3154		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - RPT 150 HRS								
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 24-MAY-1990 12:00:00					
MOS	30-APR-1990		REASON: --					MOS
HRS	4578		TECH:					HRS
AFL	3154		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
950780	SL WW-2478 L HYD PUMP							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 24-MAY-1990 12:00:00					
MOS	30-APR-1990		REASON: --					MOS
HRS	4578		TECH:					HRS
AFL	3154		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
950942	ACCOMPLISH SLWW-2494 REV 3 RMG BOLTS BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 24-MAY-1990 12:00:00					
MOS	30-APR-1990		REASON: --					MOS
HRS	4578		TECH:					HRS
AFL	3154		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
950941	ACCOMPLISH SLWW-2494 REV 3 LMG BOLTS BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 24-MAY-1990 12:00:00					
MOS	30-APR-1990		REASON: --					MOS
HRS	4578		TECH:					HRS
AFL	3154		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model : 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN						
CW	WARR	TRANSACTION DATE: 24-MAY-1990 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS 30-APR-1990		REASON: --					MOS
HRS 4578		TECH:					HRS
AFL 3154		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
950785	SL WW-2478 R HYD PUMP						
CW	WARR	TRANSACTION DATE: 24-MAY-1990 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS 30-APR-1990		REASON: --					MOS
HRS 4578		TECH:					HRS
AFL 3154		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
950570	SL WW-2457 PART A,R/H						
CW	WARR	TRANSACTION DATE: 24-MAY-1990 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS 30-APR-1990		REASON: --					MOS
HRS 4578		TECH:					HRS
AFL 3154		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - RPT 150 HRS							
950569	SL WW-2457 PART A,L/H						
CW	WARR	TRANSACTION DATE: 24-MAY-1990 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS 30-APR-1990		REASON: --					MOS
HRS 4578		TECH:					HRS
AFL 3154		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - RPT 150 HRS							
990131	ACCOMPLISH AD89-12-08 AIRWORTHINESS DIRECTIVE						
CW	WARR	TRANSACTION DATE: 11-JUN-1990 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS 30-APR-1990		REASON: --					MOS
HRS 4578		TECH:					HRS
AFL 3154		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: SUPS AD 86-14-02 - REF:550656							
910100	ACCOMPLISH SB1124-27-100R2 L/H RODS BULLETIN						
CW	WARR	TRANSACTION DATE: 06-JUL-1990 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS 20-JUN-1990		REASON: --					MOS
HRS 4621		TECH:					HRS
AFL 3211		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: SEE CODE 990985 - RPT 150 HRS							
1990-07-08 R1	TO PREVENT SMOKE, FIRE, AND POSSIBLE ELECTRICAL SHOCK, OR ELECTROMAGNETIC INTERFERENCE TO FLIGHT CRITICAL OR ESSENTIAL SYSTEMS AIRWORTHINESS DIRECTIVE						
CW	WARR	TRANSACTION DATE: 06-AUG-1990 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS		REASON: --					MOS
MSC		TECH:					MSC
AFL 0		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN						
CW	WARR	TRANSACTION DATE: 06-DEC-1990 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS 06-NOV-1990		REASON: --					MOS
HRS 4731		TECH:					HRS
AFL 3324		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							



AIRCRAFT Updates Report

Serial #: 368 Reg. #: N368MD
 Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR		
950500	SL WW-2450B INSP NACL CWL							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR							
MOS	06-NOV-1990							MOS
HRS	4731							HRS
AFL	3324							AFL
Note: OP 1,2,3 - RPT 150 HRS								
		LABOR HRS: 0		COST: \$0.00				
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR							
MOS	06-NOV-1990							MOS
HRS	4731							HRS
AFL	3324							AFL
Note: OP 1,2,3								
		LABOR HRS: 0		COST: \$0.00				
960078	ACCOMPLISH SIL1124-21-078 R2 35D SEN BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR							
MOS	06-NOV-1990							MOS
HRS	4731							HRS
AFL	3324							AFL
Note: REPEAT								
		LABOR HRS: 0		COST: \$0.00				
1124-55-021 R3	STABILIZERS SERVICE BULLETIN							
C/W	WARR							
MOS								MOS
HRS	0							HRS
AFL	0							AFL
		LABOR HRS: 0		COST: \$0.00				
900280	ACCOMPLISH SB WW 24-28A BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR							
MOS	07-JUN-1991							MOS
HRS	4878							HRS
AFL	3494							AFL
Note: REF CODE 320120								
		LABOR HRS: 0		COST: \$0.00				
910101	ACCOMPLISH SB1124-27-100R2 R/H RODS BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR							
MOS	07-JUN-1991							MOS
HRS	4878							HRS
AFL	3494							AFL
Note: SEE CODE 990986 - RPT 150 HRS								
		LABOR HRS: 0		COST: \$0.00				
910100	ACCOMPLISH SB1124-27-100R2 L/H RODS BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR							
MOS	07-JUN-1991							MOS
HRS	4878							HRS
AFL	3494							AFL
Note: SEE CODE 990985 - RPT 150 HRS								
		LABOR HRS: 0		COST: \$0.00				
977040U	SERVICE BULLETIN SBTFE 731-A77-3020 R/H							
C/W	WARR							
MOS	11-JUN-1991							MOS
MSC								MSC
AFL	3494							AFL
		LABOR HRS: 0		COST: \$0.00				

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
977039U	SERVICE BULLETIN SBTFE731-A77-3020 L/H						
MOS	CW	WARR	TRANSACTION DATE: 09-JUL-1991 12:00:00				
MSC	11-JUN-1991		REASON: --				MOS
AFL	3494		TECH:				MSC
			INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
972848U	SERVICE BULLETIN GSB TFE 731-A72-3432 R/H						
MOS	CW	WARR	TRANSACTION DATE: 09-JUL-1991 12:00:00				
MSC	07-JUN-1991		REASON: --				MOS
AFL			TECH:				MSC
			INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
990986	ACCOMPLISH AD90-10-04 RIGHT AILERON AIRWORTHINESS DIRECTIVE				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
MOS	CW	WARR	TRANSACTION DATE: 09-JUL-1991 12:00:00				
HRS	07-JUN-1991		REASON: --				MOS
AFL	4878		TECH:				HRS
	3494		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
990985	ACCOMPLISH AD90-10-04 LEFT AILERON AIRWORTHINESS DIRECTIVE				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
MOS	CW	WARR	TRANSACTION DATE: 09-JUL-1991 12:00:00				
HRS	07-JUN-1991		REASON: --				MOS
AFL	4878		TECH:				HRS
	3494		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
Note: RPT							
990131	ACCOMPLISH AD89-12-08 AIRWORTHINESS DIRECTIVE				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
MOS	CW	WARR	TRANSACTION DATE: 09-JUL-1991 12:00:00				
HRS	07-JUN-1991		REASON: --				MOS
AFL	4878		TECH:				HRS
	3494		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
Note: SUPS AD 86-14-02 - REF:550656							
972847U	ACCOMPLISH BULLETIN GSB TFE 731-A72-3432 L/H				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
MOS	CW	WARR	TRANSACTION DATE: 09-JUL-1991 12:00:00				
HRS/MS	07-JUN-1991		REASON: --				MOS
AFL			TECH:				HRS/MS
			INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
Note: N/A BY S/N							
960078	ACCOMPLISH SIL1124-21-078 R2 35D SEN BULLETIN				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
MOS	CW	WARR	TRANSACTION DATE: 09-JUL-1991 12:00:00				
HRS	07-JUN-1991		REASON: --				MOS
AFL	4878		TECH:				HRS
	3494		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
Note: REPEAT							
950942	ACCOMPLISH SLWW-2494 REV 3 RMG BOLTS BULLETIN				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
MOS	CW	WARR	TRANSACTION DATE: 09-JUL-1991 12:00:00				
HRS	07-JUN-1991		REASON: --				MOS
AFL	4878		TECH:				HRS
	3494		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
Note: OP 2,3							

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
950941	ACCOMPLISH SLWW-2494 REV 3 LMG BOLTS BULLETIN			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
C/W	WARR	TRANSACTION DATE: 09-JUL-1991 12:00:00						
MOS	07-JUN-1991	REASON: --					MOS	
HRS	4878	TECH:					HRS	
AFL	3494	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 2,3								
950500	SL WW-2450B INSP NAEL CWL			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
C/W	WARR	TRANSACTION DATE: 09-JUL-1991 12:00:00						
MOS	11-JUN-1991	REASON: --					MOS	
HRS	4878	TECH:					HRS	
AFL	3494	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3 - RPT 150 HRS								
910200	ACCOMPLISH SB 1124-55-020 REV 2 BULLETIN			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
C/W	WARR	TRANSACTION DATE: 09-JUL-1991 12:00:00						
MOS	07-JUN-1991	REASON: --					MOS	
HRS	4878	TECH:					HRS	
AFL	3494	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
C/W	WARR	TRANSACTION DATE: 09-JUL-1991 12:00:00						
MOS	07-JUN-1991	REASON: --					MOS	
HRS	4878	TECH:					HRS	
AFL	3494	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3								
1124-55-097	STABILIZER SCISSR SERVICE BULLETIN			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
C/W	WARR	TRANSACTION DATE: 11-JUL-1991 12:00:00						
MOS		REASON: --					MOS	
MSC		TECH:					MSC	
AFL	0	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
990085U	AIRWORTHINESS DIRECTIVE AD81-24-08 #1 ENGINE			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
C/W	WARR	TRANSACTION DATE: 30-AUG-1991 12:00:00						
MOS	12-JUL-1991	REASON: --					MOS	
HRS	4879	TECH:					HRS	
AFL	3494	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
C/W	WARR	TRANSACTION DATE: 08-JAN-1992 12:00:00						
MOS	20-JUN-1991	REASON: --					MOS	
HRS	4878	TECH:					HRS	
AFL	3494	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3								
950942	ACCOMPLISH SLWW-2494 REV 3 RMG BOLTS BULLETIN			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
C/W	WARR	TRANSACTION DATE: 08-JAN-1992 12:00:00						
MOS	20-JUN-1991	REASON: --					MOS	
HRS	4878	TECH:					HRS	
AFL	3494	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 2,3								

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
950941	ACCOMPLISH SLWW-2494 REV 3 LMG BOLTS BULLETIN				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 08-JAN-1992 12:00:00					
MOS	20-JUN-1991	REASON: --			MOS		
HRS	4878	TECH:			HRS		
AFL	3494	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 2,3							
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 08-JAN-1992 12:00:00					
MOS	20-JUN-1991	REASON: --			MOS		
HRS	4878	TECH:			HRS		
AFL	3494	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
950500	SL WW-2450B INSP NACL CWL				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 08-JAN-1992 12:00:00					
MOS	20-JUN-1991	REASON: --			MOS		
HRS	4878	TECH:			HRS		
AFL	3494	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3 - RPT 160 HRS							
950911	ACCOMPLISH SL WW-2491 REV 1 NLG BRGS BULLETIN				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 09-JAN-1992 12:00:00					
MOS	19-JUN-1991	REASON: --			MOS		
HRS	4878	TECH:			HRS		
AFL	3478	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: REF TO CODE 320118 - RPT							
991040	ACCOMPLISH AD91-13-08 AIRWORTHINESS DIRECTIVE				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 09-JAN-1992 12:00:00					
MOS	24-DEC-1991	REASON: --			MOS		
HRS	5007	TECH:			HRS		
AFL	3641	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: AD 91-13-08 - CW							
1990-14-06	SUPERSEDED BY AD1995-22-01 AIRWORTHINESS DIRECTIVE						
CW	WARR	TRANSACTION DATE: 09-JAN-1992 12:00:00					
MOS		REASON: --			MOS		
MSC		TECH:			MSC		
AFL	0	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 05-FEB-1992 12:00:00					
MOS	23-JAN-1992	REASON: --			MOS		
HRS	5021	TECH:			HRS		
AFL	3654	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
950500	SL WW-2450B INSP NACL CWL				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 05-FEB-1992 12:00:00					
MOS	23-JAN-1992	REASON: --			MOS		
HRS	5021	TECH:			HRS		
AFL	3654	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3 - RPT 160 HRS							



AIRCRAFT Updates Report

Serial #: 368 Reg. #: N368MD
 Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR		
990986	ACCOMPLISH AD90-10-04 RIGHT AILERON AIRWORTHINESS DIRECTIVE						Done By:	CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 05-FEB-1992 12:00:00						
MOS	23-JAN-1992	REASON: --						MOS
HRS	5021	TECH:						HRS
AFL	3654	INSP:	LABOR HRS: 0		COST: \$0.00			AFL
Note: OP 1,2,3								
990985	ACCOMPLISH AD90-10-04 LEFT AILERON AIRWORTHINESS DIRECTIVE						Done By:	CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 05-FEB-1992 12:00:00						
MOS	23-JAN-1992	REASON: --						MOS
HRS	5021	TECH:						HRS
AFL	3654	INSP:	LABOR HRS: 0		COST: \$0.00			AFL
Note: OP 1,2,3 - RPT								
990020	ACCOMPLISH AD74-08-09 R2 AIRWORTHINESS DIRECTIVE						Done By:	CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 05-FEB-1992 12:00:00						
MOS	22-JAN-1992	REASON: --						MOS
HRS	5021	TECH:						HRS
AFL	3654	INSP:	LABOR HRS: 0		COST: \$0.00			AFL
Note: AD 74-08-09 - RPT 1000 HRS								
990078	ACCOMPLISH SIL1124-21-078 R2 35D SEN BULLETIN						Done By:	CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 05-FEB-1992 12:00:00						
MOS	22-JAN-1992	REASON: --						MOS
HRS	5021	TECH:						HRS
AFL	3654	INSP:	LABOR HRS: 0		COST: \$0.00			AFL
Note: OP 1,2,3 - REPEAT								
990920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN						Done By:	CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 05-FEB-1992 12:00:00						
MOS	23-JAN-1992	REASON: --						MOS
HRS	5021	TECH:						HRS
AFL	3654	INSP:	LABOR HRS: 0		COST: \$0.00			AFL
Note: OP 1,2,3								
990920	SIL1124-78-092						Done By:	CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 07-AUG-1992 12:00:00						
MOS	29-JUL-1992	REASON: --						MOS
HRS	5124	TECH:						HRS
AFL	3746	INSP:	LABOR HRS: 0		COST: \$0.00			AFL
Note: C/W								
991065U	AIRWORTHINESS DIRECTIVE AD92-12-09 #1 ENGINE							
C/W	WARR	TRANSACTION DATE: 07-AUG-1992 12:00:00						
MOS	23-JUN-1992	REASON: --						MOS
HRS	5122	TECH:						HRS
AFL	3742	INSP:	LABOR HRS: 0		COST: \$0.00			AFL
910200	ACCOMPLISH SB 1124-55-020 REV 2 BULLETIN						Done By:	CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 10-NOV-1992 12:00:00						
MOS	29-OCT-1992	REASON: --						MOS
HRS	5170	TECH:						HRS
AFL	3802	INSP:	LABOR HRS: 0		COST: \$0.00			AFL
Note: OP 2,3								

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR	
950500	SL WW-2450B INSP NAACL CWL						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR						
MOS	01-NOV-1992	TRANSACTION DATE:	10-NOV-1992 12:00:00				
HRS	5170	REASON:	--				MOS
AFL	3802	TECH:					HRS
		INSP:					AFL
		LABOR HRS:	0				
		COST:	\$0.00				
Note: OP 1,2,3 - RPT 150 HRS							
950942	ACCOMPLISH SLWW-2494 REV 3 RMG BOLTS BULLETIN						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR						
MOS	01-NOV-1992	TRANSACTION DATE:	10-NOV-1992 12:00:00				
HRS	5170	REASON:	--				MOS
AFL	3802	TECH:					HRS
		INSP:					AFL
		LABOR HRS:	0				
		COST:	\$0.00				
Note: OP 2,3							
960078	ACCOMPLISH SIL1124-21-078 R2 35D SEN BULLETIN						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR						
MOS	01-NOV-1992	TRANSACTION DATE:	10-NOV-1992 12:00:00				
HRS	5170	REASON:	--				MOS
AFL	3802	TECH:					HRS
		INSP:					AFL
		LABOR HRS:	0				
		COST:	\$0.00				
Note: OP 1,2,3 - REPEAT							
950941	ACCOMPLISH SLWW-2494 REV 3 LMG BOLTS BULLETIN						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR						
MOS	01-NOV-1992	TRANSACTION DATE:	10-NOV-1992 12:00:00				
HRS	5170	REASON:	--				MOS
AFL	3802	TECH:					HRS
		INSP:					AFL
		LABOR HRS:	0				
		COST:	\$0.00				
Note: OP 2,3							
1992-12-02 RIGHT AILERON	TO PREVENT REDUCED CONTROLLABILITY OF THE AIRPLANE AIRWORTHINESS DIRECTIVE						
C/W	WARR						
MOS		TRANSACTION DATE:	10-NOV-1992 12:00:00				
HRS	0	REASON:	--				MOS
AFL	0	TECH:					HRS
		INSP:					AFL
		LABOR HRS:	0				
		COST:	\$0.00				
1992-12-02 LEFT AILERON	TO PREVENT REDUCED CONTROLLABILITY OF THE AIRPLANE AIRWORTHINESS DIRECTIVE						
C/W	WARR						
MOS		TRANSACTION DATE:	10-NOV-1992 12:00:00				
HRS	0	REASON:	--				MOS
AFL	0	TECH:					HRS
		INSP:					AFL
		LABOR HRS:	0				
		COST:	\$0.00				
1990-10-04 RIGHT AILERON	SUPERSEDED BY AD1992-12-02 AIRWORTHINESS DIRECTIVE						
C/W	WARR						
MOS		TRANSACTION DATE:	10-NOV-1992 12:00:00				
HRS	0	REASON:	--				MOS
AFL	0	TECH:					HRS
		INSP:					AFL
		LABOR HRS:	0				
		COST:	\$0.00				
1990-10-04 LEFT AILERON	SUPERSEDED BY AD1992-12-02 AIRWORTHINESS DIRECTIVE						
C/W	WARR						
MOS		TRANSACTION DATE:	10-NOV-1992 12:00:00				
MSC		REASON:	--				MOS
AFL	0	TECH:					MSC
		INSP:					AFL
		LABOR HRS:	0				
		COST:	\$0.00				



AIRCRAFT Updates Report

Serial #: 368 Reg. #: N368MD
 Model: 1124A WESTWIND

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
990986	ACCOMPLISH AD90-10-04 RIGHT AILERON AIRWORTHINESS DIRECTIVE							
C/W	WARR	TRANSACTION DATE: 10-NOV-1992 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	29-OCT-1992	REASON: --						MOS
HRS/MS		TECH:						HRS/MS
AFL		INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: SUPSD BY AD92-12-02 - N/A								
990985	ACCOMPLISH AD90-10-04 LEFT AILERON AIRWORTHINESS DIRECTIVE							
C/W	WARR	TRANSACTION DATE: 10-NOV-1992 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	29-OCT-1992	REASON: --						MOS
HRS/MS		TECH:						HRS/MS
AFL		INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: SUPSD BY AD92-12-02 - N/A								
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN							
C/W	WARR	TRANSACTION DATE: 10-NOV-1992 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	01-NOV-1992	REASON: --						MOS
HRS	5170	TECH:						HRS
AFL	3802	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN							
C/W	WARR	TRANSACTION DATE: 10-NOV-1992 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	29-OCT-1992	REASON: --						MOS
HRS	5170	TECH:						HRS
AFL	3802	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
991070	ACCOMPLISH AD92-12-02 LEFT AILERON AIRWORTHINESS DIRECTIVE							
C/W	WARR	TRANSACTION DATE: 30-NOV-1992 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	20-JUN-1992	REASON: --						MOS
HRS	4878	TECH:						HRS
AFL	3494	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: REPLACED RODS - C/W								
991071	ACCOMPLISH AD92-12-02 RIGHT AILERON AIRWORTHINESS DIRECTIVE							
C/W	WARR	TRANSACTION DATE: 30-NOV-1992 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	20-JUN-1991	REASON: --						MOS
HRS	4878	TECH:						HRS
AFL	3494	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: REPLACED RODS - C/W								
972A07U	ACCOMPLISH BULLETIN G/SBA72-3504 L/ENG REV 1							
C/W	WARR	TRANSACTION DATE: 07-JAN-1993 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	28-DEC-1992	REASON: --						MOS
HRS	5201	TECH:						HRS
AFL	3842	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: N/A								
1124-27-100 R2 L/H RODS	FLIGHT CONTROLS SERVICE BULLETIN							
C/W	WARR	TRANSACTION DATE: 07-JAN-1993 12:00:00						
MOS		REASON: --						MOS
MSC		TECH:						MSC
AFL	0	INSP:		LABOR HRS: 0	COST: \$0.00			AFL

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
1124-27-100 R2	R/H RODS	FLIGHT CONTROLS SERVICE BULLETIN					
	C/W	WARR	TRANSACTION DATE: 07-JAN-1993 12:00:00				
MOS			REASON: --				MOS
HRS	0		TECH:				HRS
AFL	0		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
972547		731-A72-3474 RTR DISC L/H			Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
	C/W	WARR	TRANSACTION DATE: 07-JAN-1993 12:00:00				
MOS	28-DEC-1992		REASON: --				MOS
HRS	5201		TECH:				HRS
AFL	3842		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
Note: N/A BY S/N							
972548		731-A72-3474 RTR DISC R/H			Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
	C/W	WARR	TRANSACTION DATE: 07-JAN-1993 12:00:00				
MOS	28-DEC-1992		REASON: --				MOS
HRS	5201		TECH:				HRS
AFL	3842		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
Note: N/A BY S/N							
972220		G/SB73-3110 RIGHT ENGINE			Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
	C/W	WARR	TRANSACTION DATE: 07-JAN-1993 12:00:00				
MOS	28-DEC-1992		REASON: --				MOS
HRS	5201		TECH:				HRS
AFL	3842		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
Note: N/A							
972A08U		ACCOMPLISH BULLETIN G/SBA72-3504 R/ENG REV 1			Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
	C/W	WARR	TRANSACTION DATE: 07-JAN-1993 12:00:00				
MOS	28-DEC-1992		REASON: --				MOS
HRS	5201		TECH:				HRS
AFL	3842		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
Note: N/A							
972219		G/SB73-3110 LEFT ENGINE			Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
	C/W	WARR	TRANSACTION DATE: 07-JAN-1993 12:00:00				
MOS	28-DEC-1992		REASON: --				MOS
HRS	5201		TECH:				HRS
AFL	3842		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
Note: N/A							
991090U		ACCOMPLISH AIRWORTHINESS DIRECTIVE AD92-26-09 #1 ENGINE			Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
	C/W	WARR	TRANSACTION DATE: 08-FEB-1993 12:00:00				
MOS	25-JAN-1993		REASON: --				MOS
HRS	5209		TECH:				HRS
AFL	3855		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
Note: N/A							
991091U		ACCOMPLISH AIRWORTHINESS DIRECTIVE AD92-26-09 #2 ENGINE			Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
	C/W	WARR	TRANSACTION DATE: 08-FEB-1993 12:00:00				
MOS	25-JAN-1993		REASON: --				MOS
HRS	5209		TECH:				HRS
AFL	3855		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
Note: N/A							

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
C/W	WARR	TRANSACTION DATE: 01-MAR-1993 12:00:00						
MOS	08-FEB-1993	REASON: --					MOS	
HRS	5216	TECH:					HRS	
AFL	3864	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1 THRU 12								
1993-04-02 PARA A	TO PREVENT A MID-AIR COLLISION OR A NEAR-MISS SITUATION CAUSED BY FAILURE OF THESE MODE S TRANSPONDERS AIR WORTHINESS DIRECTIVE							
C/W	WARR	TRANSACTION DATE: 03-MAY-1993 12:00:00						
MOS		REASON: --					MOS	
MSC		TECH:					MSC	
AFL	0	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
1993-04-02 PARA B	TO PREVENT A MID-AIR COLLISION OR A NEAR-MISS SITUATION CAUSED BY FAILURE OF THESE MODE S TRANSPONDERS AIR WORTHINESS DIRECTIVE							
C/W	WARR	TRANSACTION DATE: 03-MAY-1993 12:00:00						
MOS		REASON: --					MOS	
MSC		TECH:					MSC	
AFL	0	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
C/W	WARR	TRANSACTION DATE: 04-MAY-1993 12:00:00						
MOS	30-APR-1993	REASON: --					MOS	
HRS	5270	TECH:					HRS	
AFL	3920	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 2,5,8,11								
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
C/W	WARR	TRANSACTION DATE: 04-MAY-1993 12:00:00						
MOS	30-APR-1993	REASON: --					MOS	
HRS	5270	TECH:					HRS	
AFL	3920	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1 THRU 12								
960078	ACCOMPLISH SIL1124-21-078 R2 35D SEN BULLETIN			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
C/W	WARR	TRANSACTION DATE: 04-MAY-1993 12:00:00						
MOS	30-APR-1993	REASON: --					MOS	
HRS	5270	TECH:					HRS	
AFL	3920	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 2,5,8,11 - REPEAT								
972A03U	SERVICE BULLETIN G/SB72-3502 #1 ENGINE							
C/W	WARR	TRANSACTION DATE: 08-JUN-1993 12:00:00						
MOS	31-MAY-1993	REASON: --					MOS	
MSC		TECH:					MSC	
AFL	3928	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
991030U	AIR WORTHINESS DIRECTIVE AD91-08-13 #2 ENGINE							
C/W	WARR	TRANSACTION DATE: 08-JUN-1993 12:00:00						
MOS	31-MAY-1993	REASON: --					MOS	
MSC		TECH:					MSC	
AFL	3928	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model : 1124A WESTWIND

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
972A04U	SERVICE BULLETIN G/SB72-3502 #2 ENGINE							
CW	WARR	TRANSACTION DATE: 08-JUN-1993 12:00:00						
MOS	31-MAY-1993	REASON: --				MOS		
HRS	5278	TECH:				HRS		
AFL	3928	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
950911	ACCOMPLISH SL WW-2491 REV 1 NLG BRGS BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
CW	WARR	TRANSACTION DATE: 09-JUL-1993 12:00:00						
MOS	24-JUN-1993	REASON: --				MOS		
HRS	5288	TECH:				HRS		
AFL	3947	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: REF TO CODE 320118 - RPT								
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
CW	WARR	TRANSACTION DATE: 08-OCT-1993 12:00:00						
MOS	03-AUG-1993	REASON: --				MOS		
HRS	5318	TECH:				HRS		
AFL	3973	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1 THRU 12								
991091U	ACCOMPLISH AIRWORTHINESS DIRECTIVE AD92-26-09 #2 ENGINE							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
CW	WARR	TRANSACTION DATE: 08-OCT-1993 12:00:00						
MOS	30-SEP-1993	REASON: --				MOS		
HRS	5343	TECH:				HRS		
AFL	3997	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: N/A								
972B07U	SERVICE BULLETIN G/SBA72-3504 L/ENG REV 1							
CW	WARR	TRANSACTION DATE: 08-OCT-1993 12:00:00						
MOS	30-SEP-1993	REASON: --				MOS		
HRS	5343	TECH:				HRS		
AFL	3997	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
991115U	AIRWORTHINESS DIRECTIVE AD93-10-10 #1 ENGINE							
CW	WARR	TRANSACTION DATE: 08-OCT-1993 12:00:00						
MOS	29-SEP-1993	REASON: --				MOS		
MSC		TECH:				MSC		
AFL	3997	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
991090U	AIRWORTHINESS DIRECTIVE AD92-26-09 #1 ENGINE							
CW	WARR	TRANSACTION DATE: 08-OCT-1993 12:00:00						
MOS	30-SEP-1993	REASON: --				MOS		
MSC		TECH:				MSC		
AFL		INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
972B08U	SERVICE BULLETIN G/SBA72-3504 R/ENG REV 1							
CW	WARR	TRANSACTION DATE: 08-OCT-1993 12:00:00						
MOS	30-SEP-1993	REASON: --				MOS		
HRS	5343	TECH:				HRS		
AFL	3997	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
911190U	SERVICE BULLETIN SB1124-26-119 FIRE EXTGHR							
CW	WARR	TRANSACTION DATE: 08-OCT-1993 12:00:00						
MOS	29-SEP-1993	REASON: --				MOS		
MSC		TECH:				MSC		
AFL	3997	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
991120U	AIRWORTHINESS DIRECTIVE AD93-10-10 #2 ENGINE							
	C/W	WARR	TRANSACTION DATE: 08-OCT-1993 12:00:00					
MOS	29-SEP-1993		REASON: --				MOS	
HRS	5343		TECH:				HRS	
AFL	3997		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
950180	SL WW-2424D,L FLEX SHAFT							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 04-NOV-1993 12:00:00					
MOS	01-DEC-1992		REASON: --				MOS	
HRS	5188		TECH:				HRS	
AFL	3829		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: REF: CODE 270280								
950185	SL WW-2424D,R FLEX SHAFT							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 04-NOV-1993 12:00:00					
MOS	01-DEC-1992		REASON: --				MOS	
HRS	5188		TECH:				HRS	
AFL	3829		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: REF: CODE 270285								
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 25-JAN-1994 12:00:00					
MOS	24-NOV-1993		REASON: --				MOS	
HRS	5367		TECH:				HRS	
AFL	4023		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1 THRU 12								
972A07U	SERVICE BULLETIN G/SBA72-3504 L/ENG REV 1							
	C/W	WARR	TRANSACTION DATE: 08-MAR-1994 12:00:00					
MOS	25-FEB-1994		REASON: --				MOS	
HRS	5408		TECH:				HRS	
AFL	4066		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
972A87U	SERVICE BULLETIN SB TFE731-A72-3544 LH ENG							
	C/W	WARR	TRANSACTION DATE: 08-MAR-1994 12:00:00					
MOS	17-FEB-1994		REASON: --				MOS	
HRS	5404		TECH:				HRS	
AFL	4062		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
972A88U	SERVICE BULLETIN SB TFE731-A72-3544 RH ENG							
	C/W	WARR	TRANSACTION DATE: 08-MAR-1994 12:00:00					
MOS	17-FEB-1994		REASON: --				MOS	
HRS	5404		TECH:				HRS	
AFL	4062		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
972A08U	SERVICE BULLETIN G/SBA72-3504 R/ENG REV 1							
	C/W	WARR	TRANSACTION DATE: 08-MAR-1994 12:00:00					
MOS	25-FEB-1994		REASON: --				MOS	
HRS	5408		TECH:				HRS	
AFL	4066		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model : 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR	
910200	ACCOMPLISH SB 1124-55-020 REV 2 BULLETIN						
CW	WARR					Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
MOS	24-MAR-1994	TRANSACTION DATE: 07-APR-1994 12:00:00					
HRS	5417	REASON: --				MOS	
AFL	4076	TECH:				HRS	
		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
	Note: OP 5,11						
991351U	AIRWORTHINESS DIRECTIVE AD93-25-16 #2 ENGINE						
CW	WARR						
MOS	07-MAR-1994	TRANSACTION DATE: 07-APR-1994 12:00:00				MOS	
HRS	5411	REASON: --				HRS	
AFL	4070	TECH:	LABOR HRS: 0	COST: \$0.00		AFL	
		INSP:					
973242U	SERVICE BULLETIN GSB 73-3121 R/E FUEL CONT						
CW	WARR						
MOS	07-MAR-1994	TRANSACTION DATE: 07-APR-1994 12:00:00				MOS	
HRS	5411	REASON: --				HRS	
AFL	4070	TECH:	LABOR HRS: 0	COST: \$0.00		AFL	
		INSP:					
973241U	SERVICE BULLETIN GSB 73-3121 L/E FUEL CONT						
CW	WARR						
MOS	07-MAR-1994	TRANSACTION DATE: 07-APR-1994 12:00:00				MOS	
MSC		REASON: --				MSC	
AFL	4070	TECH:	LABOR HRS: 0	COST: \$0.00		AFL	
		INSP:					
991350U	ACCOMPLISH AIRWORTHINESS DIRECTIVE AD93-25-16 #1 ENGINE						
CW	WARR					Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
MOS	07-MAR-1994	TRANSACTION DATE: 07-APR-1994 12:00:00					
HRS	5411	REASON: --				MOS	
AFL	4070	TECH:	LABOR HRS: 0	COST: \$0.00		HRS	
		INSP:				AFL	
	Note: SUPSDS AD92-26-09 - N/A						
960078	ACCOMPLISH SIL1124-21-078 R2 35D SEN BULLETIN						
CW	WARR					Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
MOS	24-MAR-1994	TRANSACTION DATE: 07-APR-1994 12:00:00					
HRS	5417	REASON: --				MOS	
AFL	4076	TECH:	LABOR HRS: 0	COST: \$0.00		HRS	
		INSP:				AFL	
	Note: OP 2,5,8,11 - REPEAT						
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN						
CW	WARR					Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
MOS	24-MAR-1994	TRANSACTION DATE: 07-APR-1994 12:00:00					
HRS	5417	REASON: --				MOS	
AFL	4076	TECH:	LABOR HRS: 0	COST: \$0.00		HRS	
		INSP:				AFL	
	Note: OP 1 THRU 12						
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN						
CW	WARR					Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
MOS	24-MAR-1994	TRANSACTION DATE: 07-APR-1994 12:00:00					
HRS	5417	REASON: --				MOS	
AFL	4076	TECH:	LABOR HRS: 0	COST: \$0.00		HRS	
		INSP:				AFL	
	Note: OP 2,5,8,11						

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
C/W	WARR	TRANSACTION DATE: 12-JUL-1994 12:00:00						
MOS	02-JUL-1994	REASON: --				MOS		
HRS	5463	TECH:				HRS		
AFL	4135	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1 THRU 12								
972B13U	SERVICE BULLETIN REPL LE 1ST STG LP TURB							
C/W	WARR	TRANSACTION DATE: 08-AUG-1994 12:00:00						
MOS	27-JUL-1994	REASON: --				MOS		
HRS	5472	TECH:				HRS		
AFL	4150	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
972B14U	SERVICE BULLETIN REPL LE 2ND STG LP TURB							
C/W	WARR	TRANSACTION DATE: 08-AUG-1994 12:00:00						
MOS	27-JUL-1994	REASON: --				MOS		
HRS	5472	TECH:				HRS		
AFL	4150	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
972B15U	SERVICE BULLETIN REPL RE 1ST STG LP TURB							
C/W	WARR	TRANSACTION DATE: 08-AUG-1994 12:00:00						
MOS	27-JUL-1994	REASON: --				MOS		
MSC		TECH:				MSC		
AFL	4150	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
972B16U	SERVICE BULLETIN REPL RE 2ND STG LP TURB							
C/W	WARR	TRANSACTION DATE: 08-AUG-1994 12:00:00						
MOS	27-JUL-1994	REASON: --				MOS		
HRS	5472	TECH:				HRS		
AFL	4150	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
991370	AD94-07-03 PARA A AIRWORTHINESS DIRECTIVE							
C/W	WARR	TRANSACTION DATE: 10-AUG-1994 12:00:00						
MOS		REASON: --				MOS		
HRS	0	TECH:				HRS		
AFL	0	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
950911	ACCOMPLISH SL WW-2491 REV 1 NLG BRGS BULLETIN			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
C/W	WARR	TRANSACTION DATE: 09-SEP-1994 12:00:00						
MOS	10-AUG-1994	REASON: --				MOS		
HRS	5476	TECH:				HRS		
AFL	4158	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: REF TO CODE 320118 - RPT								
950942	ACCOMPLISH SLWW-2494 REV 3 RMG BOLTS BULLETIN			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
C/W	WARR	TRANSACTION DATE: 09-SEP-1994 12:00:00						
MOS	10-AUG-1994	REASON: --				MOS		
HRS	5476	TECH:				HRS		
AFL	4158	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: RPT 300 HRS								

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
950941	ACCOMPLISH SLWW-2494 REV 3 LMG BOLTS BULLETIN				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 09-SEP-1994 12:00:00					
MOS	10-AUG-1994	REASON: --			MOS		
HRS	5476	TECH:			HRS		
AFL	4158	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: RPT 300 HRS							
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 11-JAN-1995 12:00:00					
MOS	24-NOV-1994	REASON: --			MOS		
HRS	5516	TECH:			HRS		
AFL	4206	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1 THRU 12							
1994-21-06	TO PREVENT THE INABILITY OF PASSENGERS OR CREW TO EGRESS FROM THEIR SEATS DURING AN EMERGENCY SITUATION, DUE TO PROBLEMS ASSOCIATED WITH THE LAP BELT ASSEMBLY AIRWORTHINESS DIRECTIVE						
CW	WARR	TRANSACTION DATE: 07-MAR-1995 12:00:00					
MOS		REASON: --			MOS		
MSC		TECH:			MSC		
AFL	0	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
991020U	AIRWORTHINESS DIRECTIVE AD91-08-13 #1 ENGINE						
CW	WARR	TRANSACTION DATE: 22-MAR-1995 12:00:00					
MOS	26-APR-1994	REASON: --			MOS		
MSC		TECH:			MSC		
AFL	4106	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
991350U	AIRWORTHINESS DIRECTIVE AD93-25-16 #1 ENGINE						
CW	WARR	TRANSACTION DATE: 22-MAR-1995 12:00:00					
MOS	26-APR-1994	REASON: --			MOS		
HRS	5442	TECH:			HRS		
AFL	4106	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
991091U	AIRWORTHINESS DIRECTIVE AD92-26-09 #2 ENGINE						
CW	WARR	TRANSACTION DATE: 22-MAR-1995 12:00:00					
MOS	26-APR-1994	REASON: --			MOS		
MSC		TECH:			MSC		
AFL	4106	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 12-APR-1995 12:00:00					
MOS	02-MAR-1995	REASON: --			MOS		
HRS	5570	TECH:			HRS		
AFL	4251	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 2,5,8,11							
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 12-APR-1995 12:00:00					
MOS	02-MAR-1995	REASON: --			MOS		
HRS	5570	TECH:			HRS		
AFL	4251	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1 THRU 12							

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
960078	ACCOMPLISH SIL1124-21-078 R2 35D SEN BULLETIN					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 12-APR-1995 12:00:00						
MOS	02-MAR-1995	REASON: --				MOS		
HRS	5570	TECH:				HRS		
AFL	4251	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 2,5,8,11 - REPEAT								
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 06-JUN-1995 12:00:00						
MOS	14-APR-1995	REASON: --				MOS		
HRS	5618	TECH:				HRS		
AFL	4287	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1 THRU 12								
911160U	SERVICE BULLETIN SB1124-32-116 L/G N/W STR							
C/W	WARR	TRANSACTION DATE: 08-JUN-1995 12:00:00						
MOS	01-JUN-1995	REASON: --				MOS		
MSC		TECH:				MSC		
AFL	4310	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 28-JUL-1995 12:00:00						
MOS	23-JUN-1995	REASON: --				MOS		
HRS	5666	TECH:				HRS		
AFL	4331	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1 THRU 12								
911290	ACCOMPLISH SB1124-27-129 L AILERON BULLETIN					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 09-NOV-1995 12:00:00						
MOS	16-AUG-1995	REASON: --				MOS		
HRS	5702	TECH:				HRS		
AFL	4372	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 6 - RPT								
911291	ACCOMPLISH SB1124-27-129 R AILERON BULLETIN					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 09-NOV-1995 12:00:00						
MOS	16-AUG-1995	REASON: --				MOS		
HRS	5702	TECH:				HRS		
AFL	4372	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 6 - RPT								
972B53U	SERVICE BULLETIN GSBA72-3578 LEFT ENGINE							
C/W	WARR	TRANSACTION DATE: 10-NOV-1995 12:00:00						
MOS	31-OCT-1995	REASON: --				MOS		
MSC		TECH:				MSC		
AFL	4390	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
972656U	SERVICE BULLETIN GSBA72-3328 R5 RIGHT ENG							
C/W	WARR	TRANSACTION DATE: 10-NOV-1995 12:00:00						
MOS	31-OCT-1995	REASON: --				MOS		
HRS	5714	TECH:				HRS		
AFL	4390	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
972B54U	SERVICE BULLETIN GSBA72-3578 RIGHT ENGINE						
C/W	WARR	TRANSACTION DATE: 10-NOV-1995 12:00:00					
MOS	31-OCT-1995	REASON: --					MOS
HRS	5714	TECH:					HRS
AFL	4390	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
972655U	SERVICE BULLETIN GSBA72-3328 R5 LEFT ENG						
C/W	WARR	TRANSACTION DATE: 10-NOV-1995 12:00:00					
MOS	31-OCT-1995	REASON: --					MOS
HRS	5714	TECH:					HRS
AFL	4390	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
910200	ACCOMPLISH SB 1124-55-020 REV 2 BULLETIN						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 08-DEC-1995 12:00:00					
MOS	13-NOV-1995	REASON: --					MOS
HRS	5718	TECH:					HRS
AFL	4397	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 5,11							
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 08-DEC-1995 12:00:00					
MOS	13-NOV-1995	REASON: --					MOS
HRS	5718	TECH:					HRS
AFL	4397	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1 THRU 12							
960078	SIL1124-21-078 R2 35D SEN SERVICE BULLETIN						
C/W	WARR	TRANSACTION DATE: 08-DEC-1995 12:00:00					
MOS		REASON: --					MOS
MSC		TECH:					MSC
AFL	0	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 08-DEC-1995 12:00:00					
MOS	13-NOV-1995	REASON: --					MOS
HRS	5718	TECH:					HRS
AFL	4397	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,5,8,11							
911140	SB1124-78-114						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 30-JAN-1996 12:00:00					
MOS	08-DEC-1995	REASON: --					MOS
HRS	5718	TECH:					HRS
AFL	4397	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: C/W							
991510	ACCOMPLISH AD95-22-01 AIRWORTHINESS DIRECTIVE						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 02-FEB-1996 12:00:00					
MOS	04-JAN-1996	REASON: --					MOS
HRS	5718	TECH:					HRS
AFL	4397	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: C/W							

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
900280	ACCOMPLISH SB WW 24-28A BULLETIN							
	C/W	WARR	TRANSACTION DATE: 13-NOV-1996 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	09-NOV-1996		REASON: --					MOS
HRS	5951		TECH:					HRS
AFL	4589		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: REF CODE 320120								
1124-27-133 R1	FLIGHT CONTROLS SERVICE BULLETIN							
	C/W	WARR	TRANSACTION DATE: 13-NOV-1996 12:00:00					
MOS			REASON: --					MOS
HRS	0		TECH:					HRS
AFL	0		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
950911	ACCOMPLISH SL WW-2491 REV 1 NLG BRGS BULLETIN							
	C/W	WARR	TRANSACTION DATE: 13-NOV-1996 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	09-NOV-1996		REASON: --					MOS
HRS	5951		TECH:					HRS
AFL	4589		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: REF TO CODE 320118 - RPT								
990020	ACCOMPLISH AD74-08-09 R2 AIRWORTHINESS DIRECTIVE							
	C/W	WARR	TRANSACTION DATE: 13-NOV-1996 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	09-NOV-1996		REASON: --					MOS
HRS	5951		TECH:					HRS
AFL	4589		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: EFFECTIVE 07-29-96 - RPT 1000 HRS								
1991-13-08	TO PREVENT THE INABILITY TO EXTEND THE NOSE LANDING GEAR FOR LANDING AIRWORTHINESS DIRECTIVE							
	C/W	WARR	TRANSACTION DATE: 13-NOV-1996 12:00:00					
MOS			REASON: --					MOS
MSC			TECH:					MSC
AFL	0		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
910200	ACCOMPLISH SB 1124-55-020 REV 2 BULLETIN							
	C/W	WARR	TRANSACTION DATE: 15-NOV-1996 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	09-NOV-1996		REASON: --					MOS
HRS	5951		TECH:					HRS
AFL	4589		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN							
	C/W	WARR	TRANSACTION DATE: 15-NOV-1996 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	09-NOV-1996		REASON: --					MOS
HRS	5951		TECH:					HRS
AFL	4589		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
911291	ACCOMPLISH SB1124-27-129 R AILERON BULLETIN							
	C/W	WARR	TRANSACTION DATE: 15-NOV-1996 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	09-NOV-1996		REASON: --					MOS
HRS	5951		TECH:					HRS
AFL	4589		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 3 - RPT								

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
911290	ACCOMPLISH SB1124-27-129 L AILERON BULLETIN				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 15-NOV-1996 12:00:00					
MOS	09-NOV-1996	REASON: --					MOS
HRS	5951	TECH:					HRS
AFL	4589	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 3 - RPT							
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 15-NOV-1996 12:00:00					
MOS	09-NOV-1996	REASON: --					MOS
HRS	5951	TECH:					HRS
AFL	4589	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
910200	ACCOMPLISH SB 1124-55-020 REV 2 BULLETIN				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 01-JUL-1997 12:00:00					
MOS	16-JUN-1997	REASON: --					MOS
HRS	6135	TECH:					HRS
AFL	4707	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3							
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 01-JUL-1997 12:00:00					
MOS	16-JUN-1997	REASON: --					MOS
HRS	6135	TECH:					HRS
AFL	4707	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 01-JUL-1997 12:00:00					
MOS	16-JUN-1997	REASON: --					MOS
HRS	6135	TECH:					HRS
AFL	4707	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
910860	SB 1124-27-086				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 01-JUL-1997 12:00:00					
MOS	09-NOV-1996	REASON: --					MOS
HRS	5951	TECH:					HRS
AFL	4589	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: C/W							
911290	ACCOMPLISH SB1124-27-129 L AILERON BULLETIN				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 07-JUL-1997 12:00:00					
MOS	16-JUN-1997	REASON: --					MOS
HRS	6135	TECH:					HRS
AFL	4707	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: RPT							
911291	ACCOMPLISH SB1124-27-129 R AILERON BULLETIN				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 07-JUL-1997 12:00:00					
MOS	16-JUN-1997	REASON: --					MOS
HRS	6135	TECH:					HRS
AFL	4707	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: RPT							



AIRCRAFT Updates Report

Serial #: 368 Reg. #: N368MD
 Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR		
990131	ACCOMPLISH AD89-12-08 AIRWORTHINESS DIRECTIVE							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR							
MOS	16-JUN-1997							MOS
HRS	6135							HRS
AFL	4707							AFL
Note: EFFECTIVE 07-10-89 - REF:550656								
991561	ACCOMPLISH AD96-24-11 RIGHT AILERON AIRWORTHINESS DIRECTIVE							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR							
MOS	16-JUN-1997							MOS
HRS	6135							HRS
AFL	4707							AFL
Note: EFFECTIVE 01-06-97								
1997-05-03 R1	TO PREVENT DEVIATION FROM AN INTENDED FLIGHT PATH DURING A NON-PRECISION APPROACH TO AN AIRPORT CAUSED BY INACCURATE INFORMATION FROM THE GPS FLIGHT MANAGEMENT SYSTEM AIRWORTHINESS DIRECTIVE							
C/W	WARR							
MOS								MOS
HRS	0							HRS
AFL	0							AFL
Note: EFFECTIVE 01-06-97								
991560	ACCOMPLISH AD96-24-11 LEFT AILERON AIRWORTHINESS DIRECTIVE							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR							
MOS	16-JUN-1997							MOS
HRS	6135							HRS
AFL	4707							AFL
Note: EFFECTIVE 01-06-97								
990280	ACCOMPLISH SB WW 24-28A BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR							
MOS	06-APR-1998							MOS
HRS	6346							HRS
AFL	4787							AFL
Note: REF CODE 320120								
990911	ACCOMPLISH SL WW-2491 REV 1 NLG BRGS BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR							
MOS	06-APR-1998							MOS
HRS	6346							HRS
AFL	4787							AFL
Note: REF TO CODE 320118 - RPT								
991510	ACCOMPLISH AD95-22-01 AIRWORTHINESS DIRECTIVE							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR							
MOS	06-APR-1998							MOS
HRS	6346							HRS
AFL	4787							AFL
Note: EFFECTIVE 12-04-95 - C/W								
990920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR							
MOS	06-APR-1998							MOS
HRS	6346							HRS
AFL	4787							AFL
Note: OP 1,2,3								

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN						
C/W	WARR	TRANSACTION DATE: 08-APR-1998 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	06-APR-1998	REASON: --					MOS
HRS	6346	TECH:					HRS
AFL	4787	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
911360	ACCOMPLISH SB1124-27-136 HORZ TRIM BULLETIN						
C/W	WARR	TRANSACTION DATE: 11-JUN-1998 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	06-APR-1998	REASON: --					MOS
HRS	6346	TECH:					HRS
AFL	4787	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
911390	ACCOMPLISH SB1124-32-139 UPR STRG BULLETIN						
C/W	WARR	TRANSACTION DATE: 11-JUN-1998 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	06-APR-1998	REASON: --					MOS
HRS	6346	TECH:					HRS
AFL	4787	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: RPT C CHECK							
910200	ACCOMPLISH SB 1124-55-020 REV 2 BULLETIN						
C/W	WARR	TRANSACTION DATE: 02-DEC-1998 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-OCT-1998	REASON: --					MOS
HRS	6520	TECH:					HRS
AFL	4889	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3							
911390	ACCOMPLISH SB1124-32-139 UPR STRG BULLETIN						
C/W	WARR	TRANSACTION DATE: 02-DEC-1998 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-OCT-1998	REASON: --					MOS
HRS	6520	TECH:					HRS
AFL	4889	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 3 - RPT C CHECK							
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN						
C/W	WARR	TRANSACTION DATE: 02-DEC-1998 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-OCT-1998	REASON: --					MOS
HRS	6520	TECH:					HRS
AFL	4889	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
973665U	SERVICE BULLETIN SB731-A72-3636R1 R/E						
C/W	WARR	TRANSACTION DATE: 02-DEC-1998 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-OCT-1998	REASON: --					MOS
HRS	6520	TECH:					HRS
AFL	4889	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
973636U	SERVICE BULLETIN SB731-A72-3636R1 L/E						
C/W	WARR	TRANSACTION DATE: 02-DEC-1998 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-OCT-1998	REASON: --					MOS
MSC		TECH:					MSC
AFL	4889	INSP:	LABOR HRS: 0	COST: \$0.00			AFL

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN							
	C/W	WARR	TRANSACTION DATE: 02-DEC-1998 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-OCT-1998		REASON: --					MOS
HRS	6520		TECH:					HRS
AFL	4889		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
911290	ACCOMPLISH SB1124-27-129 L AILERON BULLETIN							
	C/W	WARR	TRANSACTION DATE: 03-DEC-1998 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-OCT-1998		REASON: --					MOS
HRS	6520		TECH:					HRS
AFL	4889		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: RPT								
990020	ACCOMPLISH AD74-08-09 R2 AIRWORTHINESS DIRECTIVE							
	C/W	WARR	TRANSACTION DATE: 03-DEC-1998 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-OCT-1998		REASON: --					MOS
HRS	6520		TECH:					HRS
AFL	4889		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: EFFECTIVE 07-29-96 - RPT 1000 HRS								
991560	ACCOMPLISH AD96-24-11 LEFT AILERON AIRWORTHINESS DIRECTIVE							
	C/W	WARR	TRANSACTION DATE: 03-DEC-1998 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-OCT-1998		REASON: --					MOS
HRS	6520		TECH:					HRS
AFL	4889		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: EFFECTIVE 01-06-97								
991625U	AIRWORTHINESS DIRECTIVE AD98-17-01 R1 R/E							
	C/W	WARR	TRANSACTION DATE: 03-DEC-1998 12:00:00					
MOS	06-OCT-1998		REASON: --					MOS
MSC			TECH:					MSC
AFL	4889		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
991620U	AIRWORTHINESS DIRECTIVE AD98-17-01 R1 L/E							
	C/W	WARR	TRANSACTION DATE: 03-DEC-1998 12:00:00					
MOS	06-OCT-1998		REASON: --					MOS
MSC			TECH:					MSC
AFL	4889		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
991581U	AIRWORTHINESS DIRECTIVE AD97-04-03 #2 ENGINE							
	C/W	WARR	TRANSACTION DATE: 03-DEC-1998 12:00:00					
MOS	17-OCT-1998		REASON: --					MOS
MSC			TECH:					MSC
AFL	4889		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
991580U	AIRWORTHINESS DIRECTIVE AD97-04-03 #1 ENGINE							
	C/W	WARR	TRANSACTION DATE: 03-DEC-1998 12:00:00					
MOS	17-OCT-1998		REASON: --					MOS
HRS	6520		TECH:					HRS
AFL	4889		INSP:	LABOR HRS: 0	COST: \$0.00			AFL

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
911400U	SERVICE BULLETIN ASB 1124-29A-140						
C/W	WARR	TRANSACTION DATE: 03-DEC-1998 12:00:00					
06-OCT-1998		REASON: --					MOS
MSC		TECH:					MSC
AFL	4889	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
1998-05-09	98-20-35 ISRAEL AIRCRAFT INDUSTRIES (IAI), LTD.: AMENDMENT 39-10802. DOCKET 98-NM-108-AD. SUPERSEDES AD 98-05-09, AMENDMENT 39-10370.						
	AIRWORTHINESS DIRECTIVE						
C/W	WARR	TRANSACTION DATE: 03-DEC-1998 12:00:00					
MOS		REASON: --					MOS
MSC		TECH:					MSC
AFL	0	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
1997-11-10	TO PREVENT RESTRICTED OXYGEN FLOW, WHICH, IF NOT CORRECTED, COULD CAUSE SERIOUS INJURY TO A PASSENGER IN NEED OF EMERGENCY OR FIRST AID OXYGEN DURING FLIGHT						
	AIRWORTHINESS DIRECTIVE						
C/W	WARR	TRANSACTION DATE: 03-DEC-1998 12:00:00					
MOS		REASON: --					MOS
HRS	0	TECH:					HRS
AFL	0	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
991615	ACCOMPLISH AD98-06-10 AIRWORTHINESS DIRECTIVE						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 03-DEC-1998 12:00:00					
MOS	17-OCT-1998	REASON: --					MOS
HRS	6520	TECH:					HRS
AFL	4889	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: EFFECTIVE 04/17/98 - RPT							
991561	ACCOMPLISH AD96-24-11 RIGHT AILERON AIRWORTHINESS DIRECTIVE						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 03-DEC-1998 12:00:00					
MOS	17-OCT-1998	REASON: --					MOS
HRS	6520	TECH:					HRS
AFL	4889	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: EFFECTIVE 01-06-97							
990131	ACCOMPLISH AD89-12-08 AIRWORTHINESS DIRECTIVE						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 03-DEC-1998 12:00:00					
MOS	17-OCT-1998	REASON: --					MOS
HRS	6520	TECH:					HRS
AFL	4889	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: EFFECTIVE 07-10-89 - REF:550656							
973665U	ACCOMPLISH BULLETIN SB731-A72-3636R1 R/E						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 03-DEC-1998 12:00:00					
MOS	06-OCT-1998	REASON: --					MOS
HRS	6520	TECH:					HRS
AFL	4889	INSP:	LABOR HRS: 0	COST: \$0.00			AFL

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
911291	ACCOMPLISH SB1124-27-129 R AILERON BULLETIN					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 03-DEC-1998 12:00:00						
MOS	17-OCT-1998	REASON: --					MOS	
HRS	6520	TECH:					HRS	
AFL	4889	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
Note: RPT								
950941	ACCOMPLISH SLWW-2494 REV 3 LMG BOLTS BULLETIN					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 03-DEC-1998 12:00:00						
MOS	06-OCT-1998	REASON: --					MOS	
HRS	6520	TECH:					HRS	
AFL	4889	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
Note: RPT 300 HRS								
973636U	ACCOMPLISH BULLETIN SB731-A72-3636R1 L/E					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 03-DEC-1998 12:00:00						
MOS	06-OCT-1998	REASON: --					MOS	
HRS	6520	TECH:					HRS	
AFL	4889	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
950942	ACCOMPLISH SLWW-2494 REV 3 RMG BOLTS BULLETIN					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 03-DEC-1998 12:00:00						
MOS	06-OCT-1998	REASON: --					MOS	
HRS	6520	TECH:					HRS	
AFL	4889	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
Note: RPT 300 HRS								
320231	CHANGE NOSE GEAR UPPER STEERING BRACKET					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 06-JAN-1999 12:00:00		Off. ES12970-7	SN-UNKNOWN			
MOS	06-APR-1998	REASON: A - TIME		On:			MOS	0
HRS	6346	TECH:					HRS	0
AFL	4787	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	0
050150U	200 HOUR INSPECTION					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --					MOS	
HRS	6912	TECH:					HRS	
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 2,3								
260136	HYDROSTATIC TEST RIGHT FIRE EXTINGUISHER					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	07-APR-1999	REASON: --					MOS	
HRS	6727	TECH:					HRS	
AFL	4999	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
050300U	400/200 HOUR INSPECTION					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --					MOS	
HRS	6912	TECH:					HRS	
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 3								

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
100320	CHECK SERVICE BULLETINS				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --			MOS		
HRS	6912	TECH:			HRS		
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
120150	CHECK PRE-FLIGHT				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --			MOS		
HRS	6912	TECH:			HRS		
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
120160	CHECK NO.1 ENGINE PREFLIGHT COMPLETE				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	14-JUL-1999	REASON: --			MOS		
HRS	6828	TECH:			HRS		
AFL	5070	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 4,6							
120161	CHECK NO.2 ENGINE PREFLIGHT COMPLETE				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	14-JUL-1999	REASON: --			MOS		
HRS	6828	TECH:			HRS		
AFL	5070	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 5,7							
210112	VISUALLY INSPECT RIGHT BLEED AIR SWITCHING VALVE				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --			MOS		
HRS	6912	TECH:			HRS		
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 2,3							
210622	INSPECT 35 DEGREE TEMPERATURE SENSOR 35 DEGREE DUCT SENSOR				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --			MOS		
HRS	6912	TECH:			HRS		
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
210681	CHANGE COOLING TURBINE OIL				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --			MOS		
HRS	6912	TECH:			HRS		
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
240131	CHECK NO. 2 STARTER GENERATOR BRUSH WEAR/TENSION				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	14-JUL-1999	REASON: --			MOS		
HRS	6828	TECH:			HRS		
AFL	5070	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 5,7							



AIRCRAFT Updates Report

Serial #: 368 Reg. #: N368MD
 Model: 1124A WESTWIND

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
240123	INSPECT NO. 1 STARTER GENERATOR SPLINE							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	14-JUL-1999		REASON: --					MOS
HRS	6828		TECH:					HRS
AFL	5070		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 4,6								
240121	CHECK NO. 1 STARTER GENERATOR BRUSH WEAR/TENSION							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	14-JUL-1999		REASON: --					MOS
HRS	6828		TECH:					HRS
AFL	5070		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 4,6								
230400	CLEAN/TEST COCKPIT VOICE RECORDER BEACON							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
230218	INSPECT/CHECK STATIC DISCHARGE WICK RESISTANCE							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
210671	CLEAN/REPLACE WATER SEPARATOR CONDENSER/FILTER							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
210276	OPERATIONAL CHECK PRESSURIZATION SWITCHES AND VALVES							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
210102	VISUALLY INSPECT LEFT BLEED AIR SWITCHING VALVE							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
270158	INSPECT RUDDER TRIM TAB FREEPLAY							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR	
260186	OPERATIONAL CHECK FIRE PROTECTION SYSTEM						
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	04-OCT-1999	REASON: --		MOS			
HRS	6912	TECH:		HRS			
AFL	5124	INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
Note: OP 2,3							
260184	INSPECT CABIN PORTABLE EXTINGUISHER CABIN FIRE EXTINGUISHER						
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	04-OCT-1999	REASON: --		MOS			
HRS	6912	TECH:		HRS			
AFL	5124	INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3							
260181	WEIGHT CHECK CABIN PORTABLE EXTINGUISHER CABIN FIRE EXTINGUISHER						
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	07-APR-1999	REASON: --		MOS			
HRS	6727	TECH:		HRS			
AFL	4999	INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
260180	VISUAL INSPECTION CABIN PORTABLE EXTINGUISHER CABIN FIRE EXTINGUISHER						
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	04-OCT-1999	REASON: --		MOS			
HRS	6912	TECH:		HRS			
AFL	5124	INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
260174	INSPECT COCKPIT PORTABLE EXTINGUISHER COCKPIT FIRE EXTINGUISHER						
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	04-OCT-1999	REASON: --		MOS			
HRS	6912	TECH:		HRS			
AFL	5124	INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3							
260171	WEIGHT CHECK COCKPIT PORTABLE EXTINGUISHER COCKPIT FIRE EXTINGUISHER						
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	07-APR-1999	REASON: --		MOS			
HRS	6727	TECH:		HRS			
AFL	4999	INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
260169	VISUAL INSPECTION COCKPIT PORTABLE EXTINGUISHER COCKPIT FIRE EXTINGUISHER						
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	04-OCT-1999	REASON: --		MOS			
HRS	6912	TECH:		HRS			
AFL	5124	INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
250162	INSPECT FIRST AID KIT						
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	07-APR-1999	REASON: --		MOS			
HRS	6727	TECH:		HRS			
AFL	4999	INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
270262	INSPECT LEFT AILERON LEFT EXTERNAL PUSH-PULL TUBE							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
270248	FUNCTIONAL CHECK FLAP TIME EXCEED RELAY							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
270247	INSPECT RIGHT FLAP/VANE							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
270243	TAP TEST RIGHT FLAP/VANE							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
270242	INSPECT RIGHT FLAP/VANE RIGHT FLAP HINGE AND BEARING 200 HOURS							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
270240	INSPECT LEFT FLAP/VANE LEFT FLAP HINGE AND BEARING 200 HOURS							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
270238	TAP TEST LEFT FLAP/VANE LEFT FLAP							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
270237	INSPECT LEFT FLAP/VANE LEFT FLAP VANE							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
270217	INSPECT HORIZONTAL STABILIZER TRIM ACTUATOR						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3							
250156	INSPECT LIFE PRESERVERS						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	07-APR-1999	REASON: --					MOS
HRS	6727	TECH:					HRS
AFL	4999	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3							
240203	FUNCTIONALLY CHECK EXTERNAL POWER RECEPTACLE BATTERY TEMPERATURE AND WARNING SYSTEM						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
240181	DEEP CYCLE RIGHT BATTERY						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
240176	CHECK RIGHT BATTERY ELECTROLYTE LEVEL						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
240166	DEEP CYCLE LEFT BATTERY						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
240161	CHECK LEFT BATTERY ELECTROLYTE LEVEL						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
240133	INSPECT NO. 2 STARTER GENERATOR SPLINE						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	14-JUL-1999	REASON: --					MOS
HRS	6828	TECH:					HRS
AFL	5070	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 5,7							

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
100330	CHECK SERVICE LETTERS					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --				MOS		
HRS	6912	TECH:				HRS		
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3								
270341	CHECK CABLE TENSION AFT FUSELAGE					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --				MOS		
HRS	6912	TECH:				HRS		
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 2,3								
270335	OPERATIONAL CHECK SPEED BRAKES AND LIFT DUMPERS					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --				MOS		
HRS	6912	TECH:				HRS		
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3								
270265	CLEAN/CHECK RIGHT AILERON RIGHT GUIDE ROLLERS					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --				MOS		
HRS	6912	TECH:				HRS		
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 2,3								
270264	CLEAN/CHECK LEFT AILERON LEFT GUIDE ROLLERS					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --				MOS		
HRS	6912	TECH:				HRS		
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 2,3								
270263	INSPECT RIGHT AILERON RIGHT EXTERNAL PUSH-PULL TUBE					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --				MOS		
HRS	6912	TECH:				HRS		
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 2,3								
270213	LUBRICATE ELEVATOR ATTACH POINTS					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --				MOS		
HRS	6912	TECH:				HRS		
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3								
270211	INSPECT SCISSORS ASSEMBLY					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --				MOS		
HRS	6912	TECH:				HRS		
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 2,3								

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
270203	INSPECT RIGHT ELEVATOR SKIN SEPARATION				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --			MOS		
HRS	6912	TECH:			HRS		
AFL	5124	INSP:			AFL		
LABOR HRS: 0 COST: \$0.00							
Note: OP 1,2,3							
270193	INSPECT LEFT ELEVATOR SKIN SEPARATION				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --			MOS		
HRS	6912	TECH:			HRS		
AFL	5124	INSP:			AFL		
LABOR HRS: 0 COST: \$0.00							
Note: OP 1,2,3							
320607	LUBRICATE LEFT ACTUATOR BOLTS				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --			MOS		
HRS	6912	TECH:			HRS		
AFL	5124	INSP:			AFL		
LABOR HRS: 0 COST: \$0.00							
Note: OP 2,3							
320606	LUBRICATE LEFT MAIN GEAR ASSEMBLY LEFT MAIN GEAR				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --			MOS		
HRS	6912	TECH:			HRS		
AFL	5124	INSP:			AFL		
LABOR HRS: 0 COST: \$0.00							
Note: OP 1,2,3							
320206	INSPECT NOSE GEAR (B)				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --			MOS		
HRS	6912	TECH:			HRS		
AFL	5124	INSP:			AFL		
LABOR HRS: 0 COST: \$0.00							
Note: OP 2,3							
320201	INSPECT NOSE GEAR (A)				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --			MOS		
HRS	6912	TECH:			HRS		
AFL	5124	INSP:			AFL		
LABOR HRS: 0 COST: \$0.00							
Note: OP 1,2,3							
320158	INSPECT/CLEAN/LUBRICATE NOSE GEAR RIGHT WHEEL BEARINGS				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --			MOS		
HRS	6912	TECH:			HRS		
AFL	5124	INSP:			AFL		
LABOR HRS: 0 COST: \$0.00							
Note: OP 1,2,3							
320156	INSPECT/CLEAN/LUBRICATE NOSE GEAR LEFT WHEEL BEARINGS				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --			MOS		
HRS	6912	TECH:			HRS		
AFL	5124	INSP:			AFL		
LABOR HRS: 0 COST: \$0.00							
Note: OP 1,2,3							

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
320116	SERVICE NOSE GEAR ASSEMBLY SHOCK STRUT							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
320106	LUBRICATE NOSE GEAR ASSEMBLY NOSE GEAR/DOORS							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
300170	OPERATIONAL TEST P2T2 SENSOR HEATER							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
322171	INSPECT/CLEAN RIGHT ANTI-SKID DETECTOR							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
322156	INSPECT/CLEAN LEFT ANTI-SKID DETECTOR							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
322131	INSPECT/CHECK RIGHT MAIN GEAR BRAKE RIGHT BRAKE LININGS							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
322116	INSPECT/CHECK LEFT MAIN GEAR BRAKE LEFT BRAKE LININGS							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
321616	CHECK EMERGENCY STORAGE BOTTLE LANDING GEAR EMERGENCY SYSTEM PRESSURE							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model : 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
321191	INSPECT RIGHT MAIN GEAR OUTBOARD WHEEL HALF RIGHT MAIN GEAR/WELL (A)				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --			MOS		
HRS	6912	TECH:			HRS		
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
321180	INSPECT/LUBRICATE RIGHT MAIN GEAR OUTBOARD WHEEL HALF RIGHT MAIN GEAR OUTBOARD WHEEL BEARINGS				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --			MOS		
HRS	6912	TECH:			HRS		
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
321178	DYE PENETRANT CHECK RIGHT WHEEL AXLE				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --			MOS		
HRS	6912	TECH:			HRS		
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 2,3							
321176	INSPECT/LUBRICATE RIGHT MAIN GEAR INBOARD WHEEL HALF RIGHT MAIN GEAR INBOARD WHEEL BEARINGS				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --			MOS		
HRS	6912	TECH:			HRS		
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
991645U	AIRWORTHINESS DIRECTIVE AD98-25-02						
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	07-APR-1999	REASON: --			MOS		
HRS	6727	TECH:			HRS		
AFL	4999	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
991640U	AIRWORTHINESS DIRECTIVE AD98-25-10						
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	07-APR-1999	REASON: --			MOS		
HRS	6727	TECH:			HRS		
AFL	4999	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
950942	ACCOMPLISH SLWW-2494 REV 3 RMG BOLTS BULLETIN				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --			MOS		
HRS	6912	TECH:			HRS		
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: RPT 300 HRS							
950941	ACCOMPLISH SLWW-2494 REV 3 LMG BOLTS BULLETIN				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --			MOS		
HRS	6912	TECH:			HRS		
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: RPT 300 HRS							

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
713650U	-- INSP #2 ENG INLET NACELLE							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
710650U	-- INSP #1 ENG INLET NACELLE							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
570120	INSPECT RIGHT AILERON BELLCRANK							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
570119	INSPECT RIGHT WING (B)							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
570116	INSPECT RIGHT WING (A)							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
570106	INSPECT LEFT AILERON BELLCRANK							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
570104	INSPECT LEFT WING (B)							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
570101	INSPECT LEFT WING (A)							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
550106	INSPECT EMPENNAGE (B)							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
550101	INSPECT EMPENNAGE (A)							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
540126U	INSPECT NO. 2 ENGINE NACELLE/PYLON (B)							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
540121U	INSPECT NO. 2 ENGINE NACELLE/PYLON (A)							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
540106U	INSPECT NO. 1 ENGINE NACELLE/PYLON (B)							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
540101U	INSPECT NO. 1 ENGINE NACELLE/PYLON (A)							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								



AIRCRAFT Updates Report

Serial #: 368 Reg. #: N368MD
 Model: 1124A WESTWIND

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
530166	INSPECT REAR COMPARTMENT (B)			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --						
HRS	6912	TECH:						
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00	MOS	HRS	AFL
Note: OP 2,3								
530161	INSPECT REAR COMPARTMENT (A)			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --						
HRS	6912	TECH:						
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00	MOS	HRS	AFL
Note: OP 1,2,3								
530146	INSPECT CABIN (A)			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --						
HRS	6912	TECH:						
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00	MOS	HRS	AFL
Note: OP 1,2,3								
530136	INSPECT COCKPIT (B)			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --						
HRS	6912	TECH:						
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00	MOS	HRS	AFL
Note: OP 2,3								
530131	INSPECT COCKPIT (A)			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --						
HRS	6912	TECH:						
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00	MOS	HRS	AFL
Note: OP 1,2,3								
530121	INSPECT NOSE COMPARTMENT (B)			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --						
HRS	6912	TECH:						
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00	MOS	HRS	AFL
Note: OP 2,3								
530116	INSPECT NOSE COMPARTMENT (A)			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --						
HRS	6912	TECH:						
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00	MOS	HRS	AFL
Note: OP 1,2,3								
530101	INSPECT FUSELAGE (A)			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
CW	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00						
MOS	04-OCT-1999	REASON: --						
HRS	6912	TECH:						
AFL	5124	INSP:		LABOR HRS: 0	COST: \$0.00	MOS	HRS	AFL
Note: OP 1,2,3								

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
520116	OPERATIONAL CHECK CABIN ENTRANCE DOOR						
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
520106	INSPECT/LUBRICATE CABIN ENTRANCE DOOR						
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
350169U	CHECK COPILOT OXYGEN MASK						
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
350166U	CHECK PILOT OXYGEN MASK						
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
344616	INSPECT EMERGENCY GYRO POWER SUPPLY BATTERY		EMERGENCY POWER SUPPLY				
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: PS 823 ONLY							
340121	DRAIN PITOT/STATIC SYSTEM						
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
330228	CHARGE EMERGENCY LIGHT BATTERY						
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
322206	FUNCTIONAL TEST EMERGENCY GEAR EXTENSION CONTROL CABLE						
C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999	REASON: --					MOS
HRS	6912	TECH:					HRS
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
322201	FUNCTIONAL TEST LANDING GEAR FREE FALL							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
322191	FUNCTIONAL TEST LANDING GEAR (NORMAL)							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
322176	FUNCTIONAL CHECK ANTI-SKID DETECTOR SYSTEM							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
322174	OPERATIONAL CHECK ANTI-SKID LIGHTS							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
321136	SERVICE RIGHT MAIN GEAR ASSEMBLY RIGHT MAIN GEAR SHOCK STRUT							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
321107	LUBRICATE RIGHT ACTUATOR BOLTS							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
321106	LUBRICATE RIGHT MAIN GEAR ASSEMBLY RIGHT MAIN GEAR							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
320691	INSPECT LEFT MAIN GEAR/WELL (A)							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
300102	INSPECT LEFT DE-ICER CHECK VALVE							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
290178	INSPECT/LUBRICATE NO. 2 HYDRAULIC PUMP NO.2 ENGINE HYDRAULIC PUMP SPLINES							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
290143	INSPECT/LUBRICATE NO. 1 HYDRAULIC PUMP NO.1 ENGINE HYDRAULIC PUMP SPLINES							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
290118	CLEAN/CHECK RESERVOIR AIR PRESSURE REGULATOR CHECK VALVE							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
281150	CHECK OPERATION OF FUEL BOOST PUMPS							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
100310	CHECK AIRWORTHY DIRECTIVES							
	C/W	WARR	TRANSACTION DATE: 04-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
270214	LUBRICATE AFT HINGE FITTING BEARINGS							
	C/W	WARR	TRANSACTION DATE: 25-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - PRE 55-021								
270215	LUBRICATE FORWARD SCISSOR ASSEMBLY							
	C/W	WARR	TRANSACTION DATE: 25-OCT-1999 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	04-OCT-1999		REASON: --					MOS
HRS	6912		TECH:					HRS
AFL	5124		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - POST 55-021								

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
270224	CHANGE HORIZONTAL STABILIZER ACTUATOR NO.1 JACKSCREW				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 25-OCT-1999 12:00:00	Off: 21164-360	SN-UNKNOWN			
MOS	06-APR-1998	REASON: A - TIME	On:		MOS		
HRS	6346	TECH:			HRS	0	
AFL	4787	INSP:	LABOR HRS: 0	COST: \$0.00	AFL	0	
550656	CHECK HORIZONTAL STABILIZER AFT SPAR SPLICE-HINGE FITTING OUTBOARD LUGS FOR CRACKS				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 25-OCT-1999 12:00:00					
MOS	06-APR-1998	REASON: --			MOS		
HRS	6346	TECH:			HRS		
AFL	4787	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
990131	ACCOMPLISH AD89-12-08 AIRWORTHINESS DIRECTIVE				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 25-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --			MOS		
HRS	6912	TECH:			HRS		
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: EFFECTIVE 07-10-89 - REF:550656							
1998-20-35 PART 2	TO PREVENT FAILURE OF THE TRIM ACTUATOR OF THE HORIZONTAL STABILIZER DUE TO FAILURE OF THE JACKSCREWS, WHICH COULD RESULT IN REDUCED CONTROLLABILITY OF THE AIRPLANE AIRWORTHINESS DIRECTIVE						
CW	WARR	TRANSACTION DATE: 25-OCT-1999 12:00:00					
MOS		REASON: --			MOS		
HRS		TECH:			HRS		
AFL		INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
1999-18-80	TO PREVENT LOSS OF THE HYDRAULIC LOW PRESSURE WARNING LIGHTS WHICH COULD RESULT IN UNKNOWN LOW PRESSURE IN THE HYDRAULIC SYSTEM AND CONSEQUENT REDUCED CONTROLLABILITY OF THE AIRPLANE AIRWORTHINESS DIRECTIVE						
CW	WARR	TRANSACTION DATE: 25-OCT-1999 12:00:00					
MOS		REASON: --			MOS		
MSC		TECH:			MSC		
AFL		INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
991634	ACCOMPLISH AD98-20-35 PART 1 AIRWORTHINESS DIRECTIVE				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 25-OCT-1999 12:00:00					
MOS	06-APR-1998	REASON: NA - NOT APPLICABLE			MOS		
HRS	6346	TECH:			HRS		
AFL	4787	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: EFFECTIVE 11-03-98 - RPL JACKSCRW							
910200	ACCOMPLISH SB 1124-55-020 REV 2 BULLETIN				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 25-OCT-1999 12:00:00					
MOS	04-OCT-1999	REASON: --			MOS		
HRS	6912	TECH:			HRS		
AFL	5124	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 2,3							

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR	
550656	CHECK HORIZONTAL STABILIZER AFT SPAR SPLICE-HINGE FITTING OUTBOARD LUGS FOR CRACKS						
	TRANSACTION DATE: 25-OCT-1999 12:00:00						
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Done By: CAMP SYSTEMS INTERNATIONAL, LLC						
	C/W WARR						
MOS	04-OCT-1999						
HRS	6912						
AFL	5124						
	Note: OP 1,2,3						
270225	CHANGE HORIZONTAL STABILIZER ACTUATOR NO.2 JACKSCREW						
	TRANSACTION DATE: 25-OCT-1999 12:00:00						
	REASON: A - TIME						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Done By: CAMP SYSTEMS INTERNATIONAL, LLC						
	C/W WARR						
MOS	06-APR-1998						
HRS	6346						
AFL	4787						
	Note: OP 1,2,3						
120160	CHECK NO.1 ENGINE PREFLIGHT COMPLETE						
	TRANSACTION DATE: 26-OCT-1999 12:00:00						
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Done By: CAMP SYSTEMS INTERNATIONAL, LLC						
	C/W WARR						
MOS	26-OCT-1999						
HRS	6961						
AFL	5135						
	Note: OP 4,6						
240123	INSPECT NO. 1 STARTER GENERATOR SPLINE						
	TRANSACTION DATE: 26-OCT-1999 12:00:00						
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Done By: CAMP SYSTEMS INTERNATIONAL, LLC						
	C/W WARR						
MOS	26-OCT-1999						
HRS	6961						
AFL	5135						
	Note: OP 4,6						
240133	INSPECT NO. 2 STARTER GENERATOR SPLINE						
	TRANSACTION DATE: 26-OCT-1999 12:00:00						
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Done By: CAMP SYSTEMS INTERNATIONAL, LLC						
	C/W WARR						
MOS	26-OCT-1999						
HRS	6961						
AFL	5135						
	Note: OP 5,7						
780163	HYDROSTATIC TEST THRUST REVERSER GAS STORAGE BOTTLE						
	TRANSACTION DATE: 26-OCT-1999 12:00:00						
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Done By: CAMP SYSTEMS INTERNATIONAL, LLC						
	C/W WARR						
MOS	26-OCT-1999						
HRS	6961						
AFL	5135						
321613	HYDROSTATIC TEST EMERGENCY STORAGE BOTTLE						
	TRANSACTION DATE: 26-OCT-1999 12:00:00						
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Done By: CAMP SYSTEMS INTERNATIONAL, LLC						
	C/W WARR						
MOS	26-OCT-1999						
HRS	6961						
AFL	5135						
990821U	ACCOMPLISH AIRWORTHINESS DIRECTIVE AD82-23-03 R1 #1 ENGINE						
	TRANSACTION DATE: 26-OCT-1999 12:00:00						
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Done By: CAMP SYSTEMS INTERNATIONAL, LLC						
	C/W WARR						
MOS	26-OCT-1999						
HRS	6961						
AFL	5135						
	Note: EFFECTIVE 12-09-83						

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR	
972B39U	ACCOMPLISH BULLETIN GSBA72-3569 L/E FAN ROTOR						
C/W	WARR						
MOS	26-OCT-1999	TRANSACTION DATE: 26-OCT-1999 12:00:00					
HRS	6961	REASON: --				MOS	
AFL	5135	TECH:				HRS	
		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: ALERT							
971279U	ACCOMPLISH BULLETIN TFE731-72-3640 R3 ENG #1						
C/W	WARR						
MOS	26-OCT-1999	TRANSACTION DATE: 26-OCT-1999 12:00:00					
HRS	6961	REASON: --				MOS	
AFL	5135	TECH:				HRS	
		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: MOBIL 254 OIL, SVCE							
780120	CHECK #2 THRUST REVERSER SECONDARY LATCH SOLENOID SWITCH						
C/W	WARR						
MOS	26-OCT-1999	TRANSACTION DATE: 26-OCT-1999 12:00:00					
HRS	6961	REASON: --				MOS	
AFL	5135	TECH:				HRS	
		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
780119	CHECK #1 THRUST REVERSER SECONDARY LATCH SOLENOID SWITCH						
C/W	WARR						
MOS	26-OCT-1999	TRANSACTION DATE: 26-OCT-1999 12:00:00					
HRS	6961	REASON: --				MOS	
AFL	5135	TECH:				HRS	
		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
260169	VISUAL INSPECTION COCKPIT PORTABLE EXTINGUISHER COCKPIT FIRE EXTINGUISHER						
C/W	WARR						
MOS	26-OCT-1999	TRANSACTION DATE: 26-OCT-1999 12:00:00					
HRS	6961	REASON: --				MOS	
AFL	5135	TECH:				HRS	
		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
260180	VISUAL INSPECTION CABIN PORTABLE EXTINGUISHER CABIN FIRE EXTINGUISHER						
C/W	WARR						
MOS	26-OCT-1999	TRANSACTION DATE: 26-OCT-1999 12:00:00					
HRS	6961	REASON: --				MOS	
AFL	5135	TECH:				HRS	
		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
971280U	SERVICE BULLETIN TFE731-72-3640 R3 ENG #2						
C/W	WARR						
MOS	26-OCT-1999	TRANSACTION DATE: 26-OCT-1999 12:00:00					
MSC		REASON: --				MOS	
AFL	5135	TECH:				MSC	
		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
911230U	SERVICE BULLETIN SB1124-53-123 DRAIN/CABIN						
C/W	WARR						
MOS	26-OCT-1999	TRANSACTION DATE: 26-OCT-1999 12:00:00					
MSC		REASON: --				MOS	
AFL	5135	TECH:				MSC	
		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR	
1998-20-35 PART 1							
	TO PREVENT FAILURE OF THE TRIM ACTUATOR OF THE HORIZONTAL STABILIZER DUE TO FAILURE OF THE JACKSCREWS, WHICH COULD RESULT IN REDUCED CONTROLLABILITY OF THE AIRPLANE AIRWORTHINESS DIRECTIVE						
	CW WARR						
	TRANSACTION DATE: 26-OCT-1999 12:00:00						
MOS	REASON: --					MOS	
HRS	TECH:					HRS	
AFL	INSP:					AFL	
		LABOR HRS: 0	COST: \$0.00				
911360							
	SB1124-27-136 HORZ TRIM SERVICE BULLETIN						
	CW WARR						
	TRANSACTION DATE: 26-OCT-1999 12:00:00						
MOS	REASON: --					MOS	
HRS	TECH:					HRS	
AFL	INSP:					AFL	
		LABOR HRS: 0	COST: \$0.00				
1124-78A-134							
	THRUST REVERSER ALERT SERVICE BULLETIN						
	CW WARR						
	TRANSACTION DATE: 26-OCT-1999 12:00:00						
MOS	REASON: --					MOS	
MSC	TECH:					MSC	
AFL	INSP:					AFL	
		LABOR HRS: 0	COST: \$0.00				
240131							
	CHECK NO. 2 STARTER GENERATOR BRUSH WEAR/TENSION					Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
	CW WARR						
	TRANSACTION DATE: 26-OCT-1999 12:00:00						
MOS	REASON: --					MOS	
HRS	TECH:					HRS	
AFL	INSP:					AFL	
		LABOR HRS: 0	COST: \$0.00				
Note: OP 5,7							
240121							
	CHECK NO. 1 STARTER GENERATOR BRUSH WEAR/TENSION					Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
	CW WARR						
	TRANSACTION DATE: 26-OCT-1999 12:00:00						
MOS	REASON: --					MOS	
HRS	TECH:					HRS	
AFL	INSP:					AFL	
		LABOR HRS: 0	COST: \$0.00				
Note: OP 4,6							
120161							
	CHECK NO.2 ENGINE PREFLIGHT COMPLETE					Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
	CW WARR						
	TRANSACTION DATE: 26-OCT-1999 12:00:00						
MOS	REASON: --					MOS	
HRS	TECH:					HRS	
AFL	INSP:					AFL	
		LABOR HRS: 0	COST: \$0.00				
Note: OP 5,7							
230166							
	RENEW FCC RADIO/TELEPHONE LICENSE						
	CW WARR						
	TRANSACTION DATE: 27-OCT-1999 12:00:00						
MOS	REASON: --					MOS	
HRS	TECH:					HRS	
AFL	INSP:					AFL	
		LABOR HRS: 0	COST: \$0.00				
991755U							
	AIRWORTHINESS DIRECTIVE AD99-08-21						
	CW WARR						
	TRANSACTION DATE: 27-OCT-1999 12:00:00						
MOS	REASON: --					MOS	
HRS	TECH:					HRS	
AFL	INSP:					AFL	
		LABOR HRS: 0	COST: \$0.00				

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
260169	VISUAL INSPECTION COCKPIT PORTABLE EXTINGUISHER		COCKPIT FIRE EXTINGUISHER		Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 29-NOV-1999 12:00:00					
MOS	29-NOV-1999	REASON: --					MOS
HRS	6991	TECH:					HRS
AFL	5163	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
260180	VISUAL INSPECTION CABIN PORTABLE EXTINGUISHER		CABIN FIRE EXTINGUISHER		Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 29-NOV-1999 12:00:00					
MOS	29-NOV-1999	REASON: --					MOS
HRS	6991	TECH:					HRS
AFL	5163	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
290215	FUNCTIONAL TEST EMERGENCY HYDRAULIC PUMP		EMERGENCY HYDRAULIC FUSE				
CW	WARR	TRANSACTION DATE: 01-DEC-1999 12:00:00					
MOS	30-NOV-1999	REASON: --					MOS
HRS	6991	TECH:					HRS
AFL	5163	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
971279U	SERVICE BULLETIN TFE731-72-3640 R3 ENG #1						
CW	WARR	TRANSACTION DATE: 07-DEC-1999 12:00:00					
MOS	13-NOV-1999	REASON: --					MOS
HRS	6961	TECH:					HRS
AFL	5135	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
990821U	AIRWORTHINESS DIRECTIVE AD82-23-03 R1 #1 ENGINE						
CW	WARR	TRANSACTION DATE: 07-DEC-1999 12:00:00					
MOS	13-NOV-1999	REASON: --					MOS
MSC		TECH:					MSC
AFL	5135	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
972B39U	SERVICE BULLETIN GSBA72-3569 L/E FAN ROTOR						
CW	WARR	TRANSACTION DATE: 07-DEC-1999 12:00:00					
MOS	13-NOV-1999	REASON: --					MOS
HRS	6961	TECH:					HRS
AFL	5135	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
050150U	200 HOUR INSPECTION				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3							
270158	INSPECT RUDDER TRIM TAB FREEPLAY				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
260184	INSPECT CABIN PORTABLE EXTINGUISHER		CABIN FIRE EXTINGUISHER		Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
260181	WEIGHT CHECK CABIN PORTABLE EXTINGUISHER CABIN FIRE EXTINGUISHER					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --				MOS		
HRS	7107	TECH:				HRS		
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
260180	VISUAL INSPECTION CABIN PORTABLE EXTINGUISHER CABIN FIRE EXTINGUISHER					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --				MOS		
HRS	7107	TECH:				HRS		
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
260174	INSPECT COCKPIT PORTABLE EXTINGUISHER COCKPIT FIRE EXTINGUISHER					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --				MOS		
HRS	7107	TECH:				HRS		
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3								
260171	WEIGHT CHECK COCKPIT PORTABLE EXTINGUISHER COCKPIT FIRE EXTINGUISHER					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --				MOS		
HRS	7107	TECH:				HRS		
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
260169	VISUAL INSPECTION COCKPIT PORTABLE EXTINGUISHER COCKPIT FIRE EXTINGUISHER					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --				MOS		
HRS	7107	TECH:				HRS		
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
250162	INSPECT FIRST AID KIT					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --				MOS		
HRS	7107	TECH:				HRS		
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
250156	INSPECT LIFE PRESERVERS					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --				MOS		
HRS	7107	TECH:				HRS		
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
240203	FUNCTIONALLY CHECK EXTERNAL POWER RECEPTACLE BATTERY TEMPERATURE AND WARNING SYSTEM					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --				MOS		
HRS	7107	TECH:				HRS		
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3								

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
240181	DEEP CYCLE RIGHT BATTERY						
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS 22-FEB-2000		REASON: --					MOS
HRS 7107		TECH:					HRS
AFL 5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
240176	CHECK RIGHT BATTERY ELECTROLYTE LEVEL						
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS 22-FEB-2000		REASON: --					MOS
HRS 7107		TECH:					HRS
AFL 5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
240166	DEEP CYCLELEFT BATTERY						
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS 22-FEB-2000		REASON: --					MOS
HRS 7107		TECH:					HRS
AFL 5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
240161	CHECK LEFT BATTERY ELECTROLYTE LEVEL						
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS 22-FEB-2000		REASON: --					MOS
HRS 7107		TECH:					HRS
AFL 5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
240131	CHECK NO. 2 STARTER GENERATOR BRUSH WEAR/TENSION						
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS 22-FEB-2000		REASON: --					MOS
HRS 7107		TECH:					HRS
AFL 5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 5,7							
240128	INSPECT NO. 2 STARTER GENERATOR						
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS 22-FEB-2000		REASON: --					MOS
HRS 7107		TECH:					HRS
AFL 5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 5,7							
240123	INSPECT NO. 1 STARTER GENERATOR SPLINE						
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS 22-FEB-2000		REASON: --					MOS
HRS 7107		TECH:					HRS
AFL 5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 4,6							
240118	INSPECT NO. 1 STARTER GENERATOR						
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS 22-FEB-2000		REASON: --					MOS
HRS 7107		TECH:					HRS
AFL 5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 4,6							



AIRCRAFT Updates Report

Serial #: 368 Reg. #: N368MD
 Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
230400	CLEAN/TEST COCKPIT VOICE RECORDER BEACON							
	C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
210681	CHANGE COOLING TURBINE OIL							
	C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
210671	CLEAN/REPLACE WATER SEPARATOR CONDENSER/FILTER							
	C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
210622	INSPECT 35 DEGREE TEMPERATURE SENSOR 35 DEGREE DUCT SENSOR							
	C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
120161	CHECK NO.2 ENGINE PREFLIGHT COMPLETE							
	C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 5,7								
120160	CHECK NO.1 ENGINE PREFLIGHT COMPLETE							
	C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 4,6								
120150	CHECK PRE-FLIGHT							
	C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
1998-25-10 R1	TO PREVENT FAILURE OF THE SEAT RESTRAINT SYSTEM DUE TO THE BUCKLE ASSEMBLY (BUCKLE) LOCKING MECHANISM NOT ENGAGING PROPERLY, WHICH COULD RESULT IN THE SEAT RESTRAINT SYSTEM FAILING TO PROPERLY SECURE THE OCCUPANT DURING TURBULENCE OR LANDING AIRWORTHINESS DIRECTIVE							
	C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS			REASON: --					MOS
HRS	0		TECH:					HRS
AFL	0		INSP:	LABOR HRS: 0	COST: \$0.00			AFL

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model : 1124A WESTWIND

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
1999-23-22 R2	RESCISSION AIRWORTHINESS DIRECTIVE							
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS		REASON: --						MOS
MSC		TECH:						MSC
AFL	0	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
950911	SL WW-2491 REV 1 NLG BRGS SERVICE BULLETIN							
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS		REASON: --						MOS
MSC		TECH:						MSC
AFL	0	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
900280	SB WW 24-28A SERVICE BULLETIN							
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --						MOS
HRS	7107	TECH:						HRS
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
322169	CLEAN RIGHT ANTI-SKID CONTROL VALVE FILTERS							
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --						MOS
HRS	7107	TECH:						HRS
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
322149	CLEAN LEFT ANTI-SKID CONTROL VALVE FILTERS							
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --						MOS
HRS	7107	TECH:						HRS
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
320238	INSPECT NOSE GEAR LOWER STEERING BRACKET							
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --						MOS
HRS	7107	TECH:						HRS
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
320237	INSPECT NOSE GEAR UPPER STEERING BRACKET							
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --						MOS
HRS	7107	TECH:						HRS
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
320120	INSPECT NOSE GEAR ASSEMBLY OUTER STRUT BODY FORGING							
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --						MOS
HRS	7107	TECH:						HRS
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
320118	INSPECT/LUBRICATE NOSE GEAR ASSEMBLY UPPER/LOWER STRUT BEARINGS BODY							
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --						MOS
HRS	7107	TECH:						HRS
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00			AFL

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
281603	FUNCTIONAL CHECK FUEL DUMP SYSTEM							
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --						MOS
HRS	7107	TECH:						HRS
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
991561	ACCOMPLISH AD96-24-11 RIGHT AILERON AIRWORTHINESS DIRECTIVE							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --						MOS
HRS	7107	TECH:						HRS
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: EFFECTIVE 01-06-97								
991560	ACCOMPLISH AD96-24-11 LEFT AILERON AIRWORTHINESS DIRECTIVE							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --						MOS
HRS	7107	TECH:						HRS
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: EFFECTIVE 01-06-97								
990131	ACCOMPLISH AD89-12-08 AIRWORTHINESS DIRECTIVE							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --						MOS
HRS	7107	TECH:						HRS
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: EFFECTIVE 07-10-89 - REF:550656								
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --						MOS
HRS	7107	TECH:						HRS
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
911390	ACCOMPLISH SB1124-32-139 UPR STRG BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --						MOS
HRS	7107	TECH:						HRS
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 3 - RPT C CHECK								
911291	ACCOMPLISH SB1124-27-129 R AILERON BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --						MOS
HRS	7107	TECH:						HRS
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: RPT								
911290	ACCOMPLISH SB1124-27-129 L AILERON BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --						MOS
HRS	7107	TECH:						HRS
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: RPT								

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN						
	C/W WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
713650U	-- INSP #2 ENG INLET NACELLE						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
710650U	-- INSP #1 ENG INLET NACELLE						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
570120	INSPECT RIGHT AILERON BELLCRANK						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
570116	INSPECT RIGHT WING (A)						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
570106	INSPECT LEFT AILERON BELLCRANK						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
570101	INSPECT LEFT WING (A)						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
560101	CHANGE PILOT OUTER WINDSHIELD						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00	Off: 5-343026-501	84-H-1-2-096			
MOS	22-FEB-2000	REASON: B - FAIL	On:				MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00		0	AFL
						0	

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR	
550656	CHECK HORIZONTAL STABILIZER AFT SPAR SPLICE-HINGE FITTING OUTBOARD LUGS FOR CRACKS						
	TRANSACTION DATE: 28-FEB-2000 12:00:00						
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Done By: CAMP SYSTEMS INTERNATIONAL, LLC						
	C/W WARR						
MOS	22-FEB-2000						
HRS	7107						
AFL	5232						
	Note: OP 1,2,3						
550101	INSPECT EMPENNAGE (A)						
	TRANSACTION DATE: 28-FEB-2000 12:00:00						
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Done By: CAMP SYSTEMS INTERNATIONAL, LLC						
	C/W WARR						
MOS	22-FEB-2000						
HRS	7107						
AFL	5232						
	Note: OP 1,2,3						
540121U	INSPECT NO. 2 ENGINE NACELLE/PYLON (A)						
	TRANSACTION DATE: 28-FEB-2000 12:00:00						
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Done By: CAMP SYSTEMS INTERNATIONAL, LLC						
	C/W WARR						
MOS	22-FEB-2000						
HRS	7107						
AFL	5232						
	Note: OP 1,2,3						
540101U	INSPECT NO. 1 ENGINE NACELLE/PYLON (A)						
	TRANSACTION DATE: 28-FEB-2000 12:00:00						
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Done By: CAMP SYSTEMS INTERNATIONAL, LLC						
	C/W WARR						
MOS	22-FEB-2000						
HRS	7107						
AFL	5232						
	Note: OP 1,2,3						
530161	INSPECT REAR COMPARTMENT (A)						
	TRANSACTION DATE: 28-FEB-2000 12:00:00						
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Done By: CAMP SYSTEMS INTERNATIONAL, LLC						
	C/W WARR						
MOS	22-FEB-2000						
HRS	7107						
AFL	5232						
	Note: OP 1,2,3						
530146	INSPECT CABIN (A)						
	TRANSACTION DATE: 28-FEB-2000 12:00:00						
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Done By: CAMP SYSTEMS INTERNATIONAL, LLC						
	C/W WARR						
MOS	22-FEB-2000						
HRS	7107						
AFL	5232						
	Note: OP 1,2,3						
530131	INSPECT COCKPIT (A)						
	TRANSACTION DATE: 28-FEB-2000 12:00:00						
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Done By: CAMP SYSTEMS INTERNATIONAL, LLC						
	C/W WARR						
MOS	22-FEB-2000						
HRS	7107						
AFL	5232						
	Note: OP 1,2,3						
530116	INSPECT NOSE COMPARTMENT (A)						
	TRANSACTION DATE: 28-FEB-2000 12:00:00						
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Done By: CAMP SYSTEMS INTERNATIONAL, LLC						
	C/W WARR						
MOS	22-FEB-2000						
HRS	7107						
AFL	5232						
	Note: OP 1,2,3						

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
530101	INSPECT FUSELAGE (A)				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
520116	OPERATIONAL CHECK CABIN ENTRANCE DOOR				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
520106	INSPECT/LUBRICATE CABIN ENTRANCE DOOR				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
344616	INSPECT EMERGENCY GYRO POWER SUPPLY BATTERY		EMERGENCY POWER SUPPLY		Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: PS 823 ONLY							
340121	DRAIN PITOT/STATIC SYSTEM				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
330228	CHARGE EMERGENCY LIGHT BATTERY				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
322206	FUNCTIONAL TEST EMERGENCY GEAR EXTENSION CONTROL CABLE				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
322174	OPERATIONAL CHECK ANTI-SKID LIGHTS				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --					MOS
HRS	7107	TECH:					HRS
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
322171	INSPECT/CLEAN RIGHT ANTI-SKID DETECTOR							
	CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
322156	INSPECT/CLEAN LEFT ANTI-SKID DETECTOR							
	CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
322131	INSPECT/CHECK RIGHT MAIN GEAR BRAKE RIGHT BRAKE LININGS							
	CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
322116	INSPECT/CHECK LEFT MAIN GEAR BRAKE LEFT BRAKE LININGS							
	CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
321191	INSPECT RIGHT MAIN GEAR OUTBOARD WHEEL HALF RIGHT MAIN GEAR/WELL (A)							
	CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
321180	INSPECT/LUBRICATE RIGHT MAIN GEAR OUTBOARD WHEEL HALF RIGHT MAIN GEAR OUTBOARD WHEEL BEARINGS							
	CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
321176	INSPECT/LUBRICATE RIGHT MAIN GEAR INBOARD WHEEL HALF RIGHT MAIN GEAR INBOARD WHEEL BEARINGS							
	CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR	
321106	LUBRICATE RIGHT MAIN GEAR ASSEMBLY RIGHT MAIN GEAR						
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	22-FEB-2000	REASON: --		MOS			
HRS	7107	TECH:		HRS			
AFL	5232	INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3							
320691	INSPECT LEFT MAIN GEAR/WELL (A)						
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	22-FEB-2000	REASON: --		MOS			
HRS	7107	TECH:		HRS			
AFL	5232	INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3							
320680	INSPECT/LUBRICATE LEFT MAIN GEAR OUTBOARD WHEEL HALF LEFT MAIN GEAR OUTBOARD WHEEL BEARINGS						
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	22-FEB-2000	REASON: --		MOS			
HRS	7107	TECH:		HRS			
AFL	5232	INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3							
320676	INSPECT/LUBRICATE LEFT MAIN GEAR INBOARD WHEEL HALF LEFT MAIN GEAR INBOARD WHEEL BEARINGS						
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	22-FEB-2000	REASON: --		MOS			
HRS	7107	TECH:		HRS			
AFL	5232	INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3							
320606	LUBRICATE LEFT MAIN GEAR ASSEMBLY LEFT MAIN GEAR						
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	22-FEB-2000	REASON: --		MOS			
HRS	7107	TECH:		HRS			
AFL	5232	INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3							
320232	CHANGE NOSE GEAR LOWER STEERING BRACKET						
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00	Off: 22360300-001	SN-UNKNOWN			
MOS	22-FEB-2000	REASON: G - MOD	On:			MOS	
HRS	7107	TECH:				HRS 0	
AFL	5232	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00				
320231	CHANGE NOSE GEAR UPPER STEERING BRACKET						
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00	Off: 22360300-001	SN-UNKNOWN			
MOS	22-FEB-2000	REASON: G - MOD	On:			MOS 0	
HRS	7107	TECH:				HRS 0	
AFL	5232	INSP:				AFL 0	
		LABOR HRS: 0	COST: \$0.00				
320201	INSPECT NOSE GEAR (A)						
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	22-FEB-2000	REASON: --		MOS			
HRS	7107	TECH:		HRS			
AFL	5232	INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3							

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
320158	INSPECT/CLEAN/LUBRICATE NOSE GEAR RIGHT WHEEL BEARINGS					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --				MOS		
HRS	7107	TECH:				HRS		
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3								
320156	INSPECT/CLEAN/LUBRICATE NOSE GEAR LEFT WHEEL BEARINGS					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --				MOS		
HRS	7107	TECH:				HRS		
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3								
320106	LUBRICATE NOSE GEAR ASSEMBLY NOSE GEAR/DOORS					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --				MOS		
HRS	7107	TECH:				HRS		
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3								
300170	OPERATIONAL TEST P2T2 SENSOR HEATER					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --				MOS		
HRS	7107	TECH:				HRS		
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3								
300150	INSPECT COPILOT WINDSHIELD CYCLING CONTACTOR					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --				MOS		
HRS	7107	TECH:				HRS		
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3								
300147	INSPECT PILOT WINDSHIELD CYCLING CONTACTOR					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --				MOS		
HRS	7107	TECH:				HRS		
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3 - 7264-4654								
300146	CHANGE LEFT WINDSHIELD TEMPERATURE CONTROLLER					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00		Off. 833034-1	SN-UNKNOWN			
MOS	22-FEB-2000	REASON: B - FAIL		On:		MOS		
HRS	7107	TECH:				HRS	0	
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
290178	INSPECT/LUBRICATE NO. 2 HYDRAULIC PUMP NO.2 ENGINE HYDRAULIC PUMP SPLINES					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00						
MOS	22-FEB-2000	REASON: --				MOS		
HRS	7107	TECH:				HRS		
AFL	5232	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3								

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model : 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
290143	INSPECT/LUBRICATE NO. 1 HYDRAULIC PUMP NO.1 ENGINE HYDRAULIC PUMP SPLINES				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --			MOS		
HRS	7107	TECH:			HRS		
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
281150	CHECK OPERATION OF FUEL BOOST PUMPS				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --			MOS		
HRS	7107	TECH:			HRS		
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
270335	OPERATIONAL CHECK SPEED BRAKES AND LIFT DUMPERS				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --			MOS		
HRS	7107	TECH:			HRS		
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
270247	INSPECT RIGHT FLAP/VANE				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --			MOS		
HRS	7107	TECH:			HRS		
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
270242	INSPECT RIGHT FLAP/VANE RIGHT FLAP HINGE AND BEARING 200 HOURS				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --			MOS		
HRS	7107	TECH:			HRS		
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
270240	INSPECT LEFT FLAP/VANE LEFT FLAP HINGE AND BEARING 200 HOURS				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --			MOS		
HRS	7107	TECH:			HRS		
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
270237	INSPECT LEFT FLAP/VANE LEFT FLAP VANE				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --			MOS		
HRS	7107	TECH:			HRS		
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
270215	LUBRICATE FORWARD SCISSOR ASSEMBLY				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
CW	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --			MOS		
HRS	7107	TECH:			HRS		
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3 - POST 55-021							

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
270214	LUBRICATE AFT HINGE FITTING BEARINGS							
	C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - PRE 55-021								
270213	LUBRICATE ELEVATOR ATTACH POINTS							
	C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
270203	INSPECT RIGHT ELEVATOR SKIN SEPARATION							
	C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
270193	INSPECT LEFT ELEVATOR SKIN SEPARATION							
	C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
240133	INSPECT NO. 2 STARTER GENERATOR SPLINE							
	C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 5,7								
240121	CHECK NO. 1 STARTER GENERATOR BRUSH WEAR/TENSION							
	C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 4,6								
100330	CHECK SERVICE LETTERS							
	C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
100320	CHECK SERVICE BULLETINS							
	C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	22-FEB-2000		REASON: --					MOS
HRS	7107		TECH:					HRS
AFL	5232		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
100310	CHECK AIRWORTHY DIRECTIVES				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 28-FEB-2000 12:00:00					
MOS	22-FEB-2000	REASON: --			MOS		
HRS	7107	TECH:			HRS		
AFL	5232	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3							
120160	CHECK NO.1 ENGINE PREFLIGHT COMPLETE				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 07-JUN-2000 12:00:00					
MOS	01-MAY-2000	REASON: --			MOS		
HRS	7246	TECH:			HRS		
AFL	5308	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 4,6							
240128	INSPECT NO. 2 STARTER GENERATOR				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 07-JUN-2000 12:00:00					
MOS	01-MAY-2000	REASON: --			MOS		
HRS	7246	TECH:			HRS		
AFL	5308	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 5,7							
240133	INSPECT NO. 2 STARTER GENERATOR SPLINE				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 07-JUN-2000 12:00:00					
MOS	01-MAY-2000	REASON: --			MOS		
HRS	7246	TECH:			HRS		
AFL	5308	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 5,7							
240131	CHECK NO. 2 STARTER GENERATOR BRUSH WEAR/TENSION				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 07-JUN-2000 12:00:00					
MOS	01-MAY-2000	REASON: --			MOS		
HRS	7246	TECH:			HRS		
AFL	5308	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 5,7							
240123	INSPECT NO. 1 STARTER GENERATOR SPLINE				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 07-JUN-2000 12:00:00					
MOS	01-MAY-2000	REASON: --			MOS		
HRS	7246	TECH:			HRS		
AFL	5308	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 4,6							
240121	CHECK NO. 1 STARTER GENERATOR BRUSH WEAR/TENSION				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 07-JUN-2000 12:00:00					
MOS	01-MAY-2000	REASON: --			MOS		
HRS	7246	TECH:			HRS		
AFL	5308	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 4,6							
240118	INSPECT NO. 1 STARTER GENERATOR				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 07-JUN-2000 12:00:00					
MOS	01-MAY-2000	REASON: --			MOS		
HRS	7246	TECH:			HRS		
AFL	5308	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 4,6							

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
120161	CHECK NO.2 ENGINE PREFLIGHT COMPLETE						
	C/W	WARR					
	01-MAY-2000						
MOS							MOS
HRS	7246						HRS
AFL	5308						AFL
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Note: OP 5,7						
972847U	SERVICE BULLETIN GSB TFE 731-A72-3432 L/H						
	C/W	WARR					
	05-JUL-2000						
MOS							MOS
HRS	7324						HRS
AFL	5360						AFL
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Note: OP 5,7						
050150U	200 HOUR INSPECTION						
	C/W	WARR					
	17-JAN-2001						
MOS							MOS
HRS	7494						HRS
AFL	5466						AFL
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Note: OP 2,3						
100330	CHECK SERVICE LETTERS						
	C/W	WARR					
	26-JUL-2000						
MOS							MOS
HRS	7325						HRS
AFL	5360						AFL
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Note: OP 1,2,3						
270158	INSPECT RUDDER TRIM TAB FREEPLAY						
	C/W	WARR					
	26-JUL-2000						
MOS							MOS
HRS	7325						HRS
AFL	5360						AFL
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Note: OP 1,2,3						
270158	INSPECT RUDDER TRIM TAB FREEPLAY						
	C/W	WARR					
	17-JAN-2001						
MOS							MOS
HRS	7494						HRS
AFL	5466						AFL
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Note: OP 1,2,3						
260186	OPERATIONAL CHECK FIRE PROTECTION SYSTEM						
	C/W	WARR					
	26-JUL-2000						
MOS							MOS
HRS	7325						HRS
AFL	5360						AFL
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Note: OP 2,3						
260184	INSPECT CABIN PORTABLE EXTINGUISHER CABIN FIRE EXTINGUISHER						
	C/W	WARR					
	26-JUL-2000						
MOS							MOS
HRS	7325						HRS
AFL	5360						AFL
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Note: OP 1,2,3						

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR	
260184	INSPECT CABIN PORTABLE EXTINGUISHER CABIN FIRE EXTINGUISHER						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	17-JAN-2001	REASON: --		MOS			
HRS	7494	TECH:		HRS			
AFL	5466	INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3							
260174	INSPECT COCKPIT PORTABLE EXTINGUISHER COCKPIT FIRE EXTINGUISHER						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	26-JUL-2000	REASON: --		MOS			
HRS	7325	TECH:		HRS			
AFL	5360	INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3							
260174	INSPECT COCKPIT PORTABLE EXTINGUISHER COCKPIT FIRE EXTINGUISHER						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	17-JAN-2001	REASON: --		MOS			
HRS	7494	TECH:		HRS			
AFL	5466	INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3							
260131	WEIGHT CHECK RIGHT FIRE EXTINGUISHER						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	26-JUL-2000	REASON: --		MOS			
HRS	7325	TECH:		HRS			
AFL	5360	INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
260116	WEIGHT CHECK LEFT FIRE EXTINGUISHER						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	26-JUL-2000	REASON: --		MOS			
HRS	7325	TECH:		HRS			
AFL	5360	INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
240176	CHECK RIGHT BATTERY ELECTROLYTE LEVEL						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	26-JUL-2000	REASON: --		MOS			
HRS	7325	TECH:		HRS			
AFL	5360	INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3							
240176	CHECK RIGHT BATTERY ELECTROLYTE LEVEL						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	17-JAN-2001	REASON: --		MOS			
HRS	7494	TECH:		HRS			
AFL	5466	INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3							
240166	DEEP CYCLELEFT BATTERY						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	26-JUL-2000	REASON: --		MOS			
HRS	7325	TECH:		HRS			
AFL	5360	INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3							



AIRCRAFT Updates Report

Serial #: 368 Reg. #: N368MD
 Model: 1124A WESTWIND

Report Date **14-MAR-2002** From Date : To Date : 03/14/2002

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
240166	DEEP CYCLE LEFT BATTERY						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001	REASON: --					MOS
HRS	7494	TECH:					HRS
AFL	5466	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
240161	CHECK LEFT BATTERY ELECTROLYTE LEVEL						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
240161	CHECK LEFT BATTERY ELECTROLYTE LEVEL						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001	REASON: --					MOS
HRS	7494	TECH:					HRS
AFL	5466	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
240131	CHECK NO. 2 STARTER GENERATOR BRUSH WEAR/TENSION						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 5,7							
240128	INSPECT NO. 2 STARTER GENERATOR						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 5,7							
240123	INSPECT NO. 1 STARTER GENERATOR SPLINE						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001	REASON: --					MOS
HRS	7494	TECH:					HRS
AFL	5466	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 4,6							
240203	FUNCTIONALLY CHECK EXTERNAL POWER RECEPTACLE BATTERY TEMPERATURE AND WARNING SYSTEM						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR	
240203	FUNCTIONALLY CHECK EXTERNAL POWER RECEPTACLE BATTERY TEMPERATURE AND WARNING SYSTEM						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	17-JAN-2001	REASON: --		MOS			
HRS	7494	TECH:		HRS			
AFL	5466	INSP:		AFL			
Note: OP 1,2,3		LABOR HRS: 0	COST: \$0.00				
240181	DEEP CYCLE RIGHT BATTERY						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	26-JUL-2000	REASON: --		MOS			
HRS	7325	TECH:		HRS			
AFL	5360	INSP:		AFL			
Note: OP 1,2,3		LABOR HRS: 0	COST: \$0.00				
240181	DEEP CYCLE RIGHT BATTERY						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	17-JAN-2001	REASON: --		MOS			
HRS	7494	TECH:		HRS			
AFL	5466	INSP:		AFL			
Note: OP 1,2,3		LABOR HRS: 0	COST: \$0.00				
240121	CHECK NO. 1 STARTER GENERATOR BRUSH WEAR/TENSION						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	17-JAN-2001	REASON: --		MOS			
HRS	7494	TECH:		HRS			
AFL	5466	INSP:		AFL			
Note: OP 4,6		LABOR HRS: 0	COST: \$0.00				
240116	CHANGE NO. 1 STARTER GENERATOR						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	17-JAN-2001	Off. 23065-018-1	2258	MOS	0		
HRS	7494	On:		HRS	0		
AFL	5466	REASON: A - TIME		AFL	0		
		TECH:					
		INSP:					
Note: OP 1,2,3		LABOR HRS: 0	COST: \$0.00				
230218	INSPECT/CHECK STATIC DISCHARGE WICK RESISTANCE						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	26-JUL-2000	REASON: --		MOS			
HRS	7325	TECH:		HRS			
AFL	5360	INSP:		AFL			
Note: OP 2,3		LABOR HRS: 0	COST: \$0.00				
210681	CHANGE COOLING TURBINE OIL						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	26-JUL-2000	REASON: --		MOS			
HRS	7325	TECH:		HRS			
AFL	5360	INSP:		AFL			
Note: OP 1,2,3		LABOR HRS: 0	COST: \$0.00				
210681	CHANGE COOLING TURBINE OIL						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS	17-JAN-2001	REASON: --		MOS			
HRS	7494	TECH:		HRS			
AFL	5466	INSP:		AFL			
Note: OP 1,2,3		LABOR HRS: 0	COST: \$0.00				



AIRCRAFT Updates Report

Serial #: 368 Reg. #: N368MD
 Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
210671	CLEAN/REPLACE WATER SEPARATOR CONDENSER/FILTER							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
210671	CLEAN/REPLACE WATER SEPARATOR CONDENSER/FILTER							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001		REASON: --					MOS
HRS	7494		TECH:					HRS
AFL	5466		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
210622	INSPECT 35 DEGREE TEMPERATURE SENSOR 35 DEGREE DUCT SENSOR							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
270240	INSPECT LEFT FLAP/VANE LEFT FLAP HINGE AND BEARING 200 HOURS							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001		REASON: --					MOS
HRS	7494		TECH:					HRS
AFL	5466		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
270238	TAP TEST LEFT FLAP/VANE LEFT FLAP							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
270237	INSPECT LEFT FLAP/VANE LEFT FLAP VANE							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
270237	INSPECT LEFT FLAP/VANE LEFT FLAP VANE							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001		REASON: --					MOS
HRS	7494		TECH:					HRS
AFL	5466		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
270217	INSPECT HORIZONTAL STABILIZER TRIM ACTUATOR							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
270215	LUBRICATE FORWARD SCISSOR ASSEMBLY						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - POST 55-021							
270215	LUBRICATE FORWARD SCISSOR ASSEMBLY						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001	REASON: --					MOS
HRS	7494	TECH:					HRS
AFL	5466	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - POST 55-021							
270214	LUBRICATE AFT HINGE FITTING BEARINGS						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - PRE 55-021							
270214	LUBRICATE AFT HINGE FITTING BEARINGS						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001	REASON: --					MOS
HRS	7494	TECH:					HRS
AFL	5466	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3 - PRE 55-021							
300104	INSPECT RIGHT DE-ICER CHECK VALVE						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3							
300102	INSPECT LEFT DE-ICER CHECK VALVE						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3							
290178	INSPECT/LUBRICATE NO. 2 HYDRAULIC PUMP NO.2 ENGINE HYDRAULIC PUMP SPLINES						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
290178	INSPECT/LUBRICATE NO. 2 HYDRAULIC PUMP NO.2 ENGINE HYDRAULIC PUMP SPLINES						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001	REASON: --					MOS
HRS	7494	TECH:					HRS
AFL	5466	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR	
290143	INSPECT/LUBRICATE NO. 1 HYDRAULIC PUMP NO.1 ENGINE HYDRAULIC PUMP SPLINES						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00		AFL
Note: OP 1,2,3							
290143	INSPECT/LUBRICATE NO. 1 HYDRAULIC PUMP NO.1 ENGINE HYDRAULIC PUMP SPLINES						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	17-JAN-2001	REASON: --					MOS
HRS	7494	TECH:					HRS
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00		AFL
Note: OP 1,2,3							
290118	CLEAN/CHECK RESERVOIR AIR PRESSURE REGULATOR HYDRAULIC RESERVOIR AIR PRESSURE CHECK VALVE						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00		AFL
Note: OP 2,3							
281150	CHECK OPERATION OF FUEL BOOST PUMPS						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	24-APR-2000	REASON: --					MOS
HRS	7233	TECH:					HRS
AFL	5301	INSP:		LABOR HRS: 0	COST: \$0.00		AFL
Note: OP 1,2,3							
281150	CHECK OPERATION OF FUEL BOOST PUMPS						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00		AFL
Note: OP 1,2,3							
050600U	800/400/200 HOUR INSPECT						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:		LABOR HRS: 45.5	COST: \$0.00		AFL
2000-23-13	TO PREVENT JAMMING OR DISCONNECTION OF THE HORIZONTAL STABILIZER TRIM ACTUATOR, WHICH COULD RESULT IN REDUCED PITCH CONTROL OF THE AIRPLANE AIRWORTHINESS DIRECTIVE						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS		REASON: --					MOS
HRS	0	TECH:					HRS
AFL	0	INSP:		LABOR HRS: 0	COST: \$0.00		AFL

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR	
1996-24-11	RIGHT AILERON TO PREVENT EXCESSIVE WEAR OF THE AILERON PUSH-PULL TUBE, WHICH COULD RESULT IN UNEVEN MOVEMENT OF THE CONTROL WHEEL, PERFORATION OF THE AILERON PUSH-PULL TUBE, AND CONSEQUENT REDUCED ROLL CONTROL OF THE AIRPLANE AIRWORTHINESS DIRECTIVE						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --				MOS	
HRS	7325	TECH:				HRS	
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00	AFL	
1996-24-11	LEFT AILERON TO PREVENT EXCESSIVE WEAR OF THE AILERON PUSH-PULL TUBE, WHICH COULD RESULT IN UNEVEN MOVEMENT OF THE CONTROL WHEEL, PERFORATION OF THE AILERON PUSH-PULL TUBE, AND CONSEQUENT REDUCED ROLL CONTROL OF THE AIRPLANE AIRWORTHINESS DIRECTIVE						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --				MOS	
HRS	7325	TECH:				HRS	
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00	AFL	
1995-22-01	TO PREVENT SMOKE, FIRE, ELECTRICAL SHOCK, AND POSSIBLE ELECTROMAGNETIC INTERFERENCE CAUSED BY HIGH VOLTAGE ARCING IN THE CABIN WHICH, IF UNDETECTED, COULD RESULT IN PERSONAL HAZARD OR LOSS OF THE AIRCRAFT AIRWORTHINESS DIRECTIVE						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS		REASON: --				MOS	
HRS	0	TECH:				HRS	
AFL	0	INSP:		LABOR HRS: 0	COST: \$0.00	AFL	
1989-12-08	TO DETECT CRACKS IN THE HINGE LUGS OF THE HORIZONTAL STABILIZER AFT SPAR SPLICE FITTING (HINGE ASSEMBLY) AIRWORTHINESS DIRECTIVE						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	17-JAN-2001	REASON: --				MOS	
HRS	7494	TECH:				HRS	
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00	AFL	
1974-08-09 R2	TO PREVENT POSSIBLE FIRES THAT COULD RESULT FROM SMOKING MATERIALS BEING DROPPED INTO LAVATORY PAPER OR LINEN WASTE RECEPTACLES AIRWORTHINESS DIRECTIVE						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	17-JAN-2001	REASON: --				MOS	
HRS	7494	TECH:				HRS	
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00	AFL	
911470	ASB1124-27A-147 SERVICE BULLETIN						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS		REASON: --				MOS	
MSC		TECH:				MSC	
AFL	0	INSP:		LABOR HRS: 0	COST: \$0.00	AFL	
911390	SB1124-32-139 UPR STRG SERVICE BULLETIN						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --				MOS	
HRS	7325	TECH:				HRS	
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00	AFL	
1124-27-129	RIGHT AILERON FLIGHT CONTROLS SERVICE BULLETIN						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --				MOS	
HRS	7325	TECH:				HRS	
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00	AFL	

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR		
1124-27-129 LEFT AILERON FLIGHT CONTROLS SERVICE BULLETIN								
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --					MOS	
HRS	7325	TECH:					HRS	
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
780643 LUBRICATE NO. 2 THRUST REVERSER ASSEMBLY								
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --					MOS	
HRS	7325	TECH:					HRS	
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
780616 OPERATIONAL CHECK NO.2 THRUST REVERSER								
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --					MOS	
HRS	7325	TECH:					HRS	
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
780143 LUBRICATE NO. 1 THRUST REVERSER ASSEMBLY								
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --					MOS	
HRS	7325	TECH:					HRS	
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
780120 CHECK #2 THRUST REVERSER SECONDARY LATCH SOLENOID SWITCH								
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --					MOS	
HRS	7325	TECH:					HRS	
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
780119 CHECK #1 THRUST REVERSER SECONDARY LATCH SOLENOID SWITCH								
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --					MOS	
HRS	7325	TECH:					HRS	
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
780116 OPERATIONAL CHECK NO.1 THRUST REVERSER								
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --					MOS	
HRS	7325	TECH:					HRS	
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
560118 INSPECT COPILOT SIDE WINDOW								
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --					MOS	
HRS	7325	TECH:					HRS	
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	
560112 INSPECT PILOT SIDE WINDOW								
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --					MOS	
HRS	7325	TECH:					HRS	
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00		AFL	

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
550658	CHECK HORIZONTAL STABILIZER ASSEMBLY RADIAL/AXIAL PLAY						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
540131U	INSPECT NO. 2 ENGINE NACELLE/PYLON (C)						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
540111U	INSPECT NO. 1 ENGINE NACELLE/PYLON (C)						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	17-JAN-2001	REASON: --					MOS
HRS	7494	TECH:					HRS
AFL	5466	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
910200	ACCOMPLISH SB 1124-55-020 REV 2 BULLETIN						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3							
713650U	-- INSP #2 ENG INLET NACELLE						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
713650U	-- INSP #2 ENG INLET NACELLE						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	17-JAN-2001	REASON: --					MOS
HRS	7494	TECH:					HRS
AFL	5466	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
710650U	-- INSP #1 ENG INLET NACELLE							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
710650U	-- INSP #1 ENG INLET NACELLE							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					MOS
MOS	17-JAN-2001		REASON: --					HRS
HRS	7494		TECH:	LABOR HRS: 0	COST: \$0.00			AFL
AFL	5466		INSP:					
Note: OP 1,2,3								
570120	INSPECT RIGHT AILERON BELLCRANK							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					MOS
MOS	26-JUL-2000		REASON: --					HRS
HRS	7325		TECH:	LABOR HRS: 0	COST: \$0.00			AFL
AFL	5360		INSP:					
Note: OP 1,2,3								
570120	INSPECT RIGHT AILERON BELLCRANK							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					MOS
MOS	17-JAN-2001		REASON: --					HRS
HRS	7494		TECH:	LABOR HRS: 0	COST: \$0.00			AFL
AFL	5466		INSP:					
Note: OP 1,2,3								
570119	INSPECT RIGHT WING (B)							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					MOS
MOS	26-JUL-2000		REASON: --					HRS
HRS	7325		TECH:	LABOR HRS: 0	COST: \$0.00			AFL
AFL	5360		INSP:					
Note: OP 2,3								
570116	INSPECT RIGHT WING (A)							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					MOS
MOS	26-JUL-2000		REASON: --					HRS
HRS	7325		TECH:	LABOR HRS: 0	COST: \$0.00			AFL
AFL	5360		INSP:					
Note: OP 1,2,3								
570116	INSPECT RIGHT WING (A)							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					MOS
MOS	17-JAN-2001		REASON: --					HRS
HRS	7494		TECH:	LABOR HRS: 0	COST: \$0.00			AFL
AFL	5466		INSP:					
Note: OP 1,2,3								
570106	INSPECT LEFT AILERON BELLCRANK							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					MOS
MOS	26-JUL-2000		REASON: --					HRS
HRS	7325		TECH:	LABOR HRS: 0	COST: \$0.00			AFL
AFL	5360		INSP:					
Note: OP 1,2,3								

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
570106	INSPECT LEFT AILERON BELLCRANK						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	17-JAN-2001	REASON: - -					
HRS	7494	TECH:					MOS
AFL	5466	INSP:	LABOR HRS: 0	COST: \$0.00			HRS
							AFL
Note: OP 1,2,3							
570104	INSPECT LEFT WING (B)						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: - -					
HRS	7325	TECH:					MOS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			HRS
							AFL
Note: OP 2,3							
570101	INSPECT LEFT WING (A)						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: - -					
HRS	7325	TECH:					MOS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			HRS
							AFL
Note: OP 1,2,3							
570101	INSPECT LEFT WING (A)						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	17-JAN-2001	REASON: - -					
HRS	7494	TECH:					MOS
AFL	5466	INSP:	LABOR HRS: 0	COST: \$0.00			HRS
							AFL
Note: OP 1,2,3							
560106	CHANGE COPILOT OUTER WINDSHIELD						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00	Off. PPG 343030-2	99158H0464			
MOS	26-AUG-2000	REASON: B - FAIL	On:				MOS
HRS	7352	TECH:					HRS
AFL	5381	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Done By: CAMP SYSTEMS INTERNATIONAL, LLC							
560106	CHANGE COPILOT OUTER WINDSHIELD						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00	Off. PPG 343030-2	84-H-1-2-096			
MOS		REASON: - -	On:				MOS
HRS		TECH:					HRS
AFL		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
							0
Done By: CAMP SYSTEMS INTERNATIONAL, LLC							
560106	CHANGE COPILOT OUTER WINDSHIELD						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00	Off. 5-343026-501	SN-UNKNOWN			
MOS	26-JUL-2000	REASON: B - FAIL	On:				MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
							0
Done By: CAMP SYSTEMS INTERNATIONAL, LLC							
550656	CHECK HORIZONTAL STABILIZER AFT SPAR SPLICE-HINGE FITTING OUTBOARD LUGS FOR CRACKS						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: - -					
HRS	7325	TECH:					MOS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			HRS
							AFL
Note: OP 1,2,3							

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
550656	CHECK HORIZONTAL STABILIZER AFT SPAR SPLICE-HINGE FITTING OUTBOARD LUGS FOR CRACKS						
	TRANSACTION DATE: 23-MAY-2001 12:00:00						
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Done By: CAMP SYSTEMS INTERNATIONAL, LLC						
C/W	WARR						
MOS	17-JAN-2001						
HRS	7494						
AFL	5466						
	Note: OP 1,2,3						
550106	INSPECT EMPENNAGE (B)						
	TRANSACTION DATE: 23-MAY-2001 12:00:00						
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Done By: CAMP SYSTEMS INTERNATIONAL, LLC						
C/W	WARR						
MOS	26-JUL-2000						
HRS	7325						
AFL	5360						
	Note: OP 2,3						
550101	INSPECT EMPENNAGE (A)						
	TRANSACTION DATE: 23-MAY-2001 12:00:00						
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Done By: CAMP SYSTEMS INTERNATIONAL, LLC						
C/W	WARR						
MOS	26-JUL-2000						
HRS	7325						
AFL	5360						
	Note: OP 1,2,3						
550101	INSPECT EMPENNAGE (A)						
	TRANSACTION DATE: 23-MAY-2001 12:00:00						
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Done By: CAMP SYSTEMS INTERNATIONAL, LLC						
C/W	WARR						
MOS	17-JAN-2001						
HRS	7494						
AFL	5466						
	Note: OP 1,2,3						
540126U	INSPECT NO. 2 ENGINE NACELLE/PYLON (B)						
	TRANSACTION DATE: 23-MAY-2001 12:00:00						
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Done By: CAMP SYSTEMS INTERNATIONAL, LLC						
C/W	WARR						
MOS	26-JUL-2000						
HRS	7325						
AFL	5360						
	Note: OP 2,3						
540121U	INSPECT NO. 2 ENGINE NACELLE/PYLON (A)						
	TRANSACTION DATE: 23-MAY-2001 12:00:00						
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Done By: CAMP SYSTEMS INTERNATIONAL, LLC						
C/W	WARR						
MOS	26-JUL-2000						
HRS	7325						
AFL	5360						
	Note: OP 1,2,3						
540121U	INSPECT NO. 2 ENGINE NACELLE/PYLON (A)						
	TRANSACTION DATE: 23-MAY-2001 12:00:00						
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Done By: CAMP SYSTEMS INTERNATIONAL, LLC						
C/W	WARR						
MOS	17-JAN-2001						
HRS	7494						
AFL	5466						
	Note: OP 1,2,3						
540106U	INSPECT NO. 1 ENGINE NACELLE/PYLON (B)						
	TRANSACTION DATE: 23-MAY-2001 12:00:00						
	REASON: --						
	TECH:						
	INSP:						
	LABOR HRS: 0						
	COST: \$0.00						
	Done By: CAMP SYSTEMS INTERNATIONAL, LLC						
C/W	WARR						
MOS	26-JUL-2000						
HRS	7325						
AFL	5360						
	Note: OP 2,3						

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model : 1124A WESTWIND

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
540101U	INSPECT NO. 1 ENGINE NACELLE/PYLON (A)							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
540101U	INSPECT NO. 1 ENGINE NACELLE/PYLON (A)							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001	REASON: --						MOS
HRS	7494	TECH:						HRS
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
530166	INSPECT REAR COMPARTMENT (B)							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
530161	INSPECT REAR COMPARTMENT (A)							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
530161	INSPECT REAR COMPARTMENT (A)							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001	REASON: --						MOS
HRS	7494	TECH:						HRS
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
530146	INSPECT CABIN (A)							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
530146	INSPECT CABIN (A)							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001	REASON: --						MOS
HRS	7494	TECH:						HRS
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
530136	INSPECT COCKPIT (B)							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
530131	INSPECT COCKPIT (A)							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
530131	INSPECT COCKPIT (A)							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001	REASON: --						MOS
HRS	7494	TECH:						HRS
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
530121	INSPECT NOSE COMPARTMENT (B)							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
530116	INSPECT NOSE COMPARTMENT (A)							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
530116	INSPECT NOSE COMPARTMENT (A)							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001	REASON: --						MOS
HRS	7494	TECH:						HRS
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
530101	INSPECT FUSELAGE (A)							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
530101	INSPECT FUSELAGE (A)							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001	REASON: --						MOS
HRS	7494	TECH:						HRS
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
520116	OPERATIONAL CHECK CABIN ENTRANCE DOOR							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
520116	OPERATIONAL CHECK CABIN ENTRANCE DOOR				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	17-JAN-2001	REASON: --				MOS	
HRS	7494	TECH:				HRS	
AFL	5466	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3							
520106	INSPECT/LUBRICATE CABIN ENTRANCE DOOR				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --				MOS	
HRS	7325	TECH:				HRS	
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3							
520106	INSPECT/LUBRICATE CABIN ENTRANCE DOOR				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	17-JAN-2001	REASON: --				MOS	
HRS	7494	TECH:				HRS	
AFL	5466	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3							
344616	INSPECT EMERGENCY GYRO POWER SUPPLY BATTERY BATTERY/STAND-BY ATTITUDE GYRO		EMERGENCY POWER SUPPLY		Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	17-JAN-2001	REASON: --				MOS	
HRS	7494	TECH:				HRS	
AFL	5466	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: PS 823 ONLY							
340121	DRAIN PITOT/STATIC SYSTEM				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --				MOS	
HRS	7325	TECH:				HRS	
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3							
340121	DRAIN PITOT/STATIC SYSTEM				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	17-JAN-2001	REASON: --				MOS	
HRS	7494	TECH:				HRS	
AFL	5466	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
Note: OP 1,2,3							
330228	CHARGE EMERGENCY LIGHT BATTERY				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	17-JAN-2001	REASON: --				MOS	
HRS	7494	TECH:				HRS	
AFL	5466	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
330156	CHANGE UPPER ANTI-COLLISION LIGHT				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00	Off: G9950-31	11303			
MOS	26-JUL-2000	REASON: B - FAIL	On:			MOS	
HRS	7325	TECH:				HRS	0
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00		AFL	0

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
322206	FUNCTIONAL TEST EMERGENCY GEAR EXTENSION CONTROL CABLE							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
322206	FUNCTIONAL TEST EMERGENCY GEAR EXTENSION CONTROL CABLE							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001		REASON: --					MOS
HRS	7494		TECH:					HRS
AFL	5466		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
322201	FUNCTIONAL TEST LANDING GEAR FREE FALL							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
322191	FUNCTIONAL TEST LANDING GEAR (NORMAL)							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
322176	FUNCTIONAL CHECK ANTI-SKID DETECTOR SYSTEM							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
322174	OPERATIONAL CHECK ANTI-SKID LIGHTS							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
322174	OPERATIONAL CHECK ANTI-SKID LIGHTS							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001		REASON: --					MOS
HRS	7494		TECH:					HRS
AFL	5466		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
322171	INSPECT/CLEAN RIGHT ANTI-SKID DETECTOR							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
322171	INSPECT/CLEAN RIGHT ANTI-SKID DETECTOR							
CW	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001	REASON: --						MOS
HRS	7494	TECH:						HRS
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
322156	INSPECT/CLEAN LEFT ANTI-SKID DETECTOR							
CW	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
322156	INSPECT/CLEAN LEFT ANTI-SKID DETECTOR							
CW	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001	REASON: --						MOS
HRS	7494	TECH:						HRS
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
322131	INSPECT/CHECK RIGHT MAIN GEAR BRAKE RIGHT BRAKE LININGS							
CW	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
322131	INSPECT/CHECK RIGHT MAIN GEAR BRAKE RIGHT BRAKE LININGS							
CW	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001	REASON: --						MOS
HRS	7494	TECH:						HRS
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
322116	INSPECT/CHECK LEFT MAIN GEAR BRAKE LEFT BRAKE LININGS							
CW	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
322116	INSPECT/CHECK LEFT MAIN GEAR BRAKE LEFT BRAKE LININGS							
CW	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001	REASON: --						MOS
HRS	7494	TECH:						HRS
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
322128	CHANGE RIGHT MAIN GEAR BRAKE							
CW	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Off: 5002805-3	1140			Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001	REASON: C - WORN		On:				MOS
HRS	7494	TECH:						HRS
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00			AFL

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
322128	CHANGE RIGHT MAIN GEAR BRAKE							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Off 5002805-3	MAY82-328			Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS		REASON: --		On:				MOS
HRS		TECH:						HRS
AFL		INSP:		LABOR HRS: 0	COST: \$0.00			AFL
321616	CHECK EMERGENCY STORAGE BOTTLE LANDING GEAR EMERGENCY SYSTEM PRESSURE							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
322113	CHANGE LEFT MAIN GEAR BRAKE							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Off 5002805-3	12153-6			
MOS	17-JAN-2001	REASON: C - WORN		On:				MOS
HRS	7494	TECH:						HRS
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
322113	CHANGE LEFT MAIN GEAR BRAKE							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Off 5002805-3	M104			
MOS		REASON: --		On:				MOS
HRS		TECH:						HRS
AFL		INSP:		LABOR HRS: 0	COST: \$0.00			AFL
321191	INSPECT RIGHT MAIN GEAR OUTBOARD WHEEL HALF RIGHT MAIN GEAR/WELL (A)							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
321191	INSPECT RIGHT MAIN GEAR OUTBOARD WHEEL HALF RIGHT MAIN GEAR/WELL (A)							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	17-JAN-2001	REASON: --						MOS
HRS	7494	TECH:						HRS
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
321180	INSPECT/LUBRICATE RIGHT MAIN GEAR OUTBOARD WHEEL HALF RIGHT MAIN GEAR OUTBOARD WHEEL BEARINGS							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
321180	INSPECT/LUBRICATE RIGHT MAIN GEAR OUTBOARD WHEEL HALF RIGHT MAIN GEAR OUTBOARD WHEEL BEARINGS							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	17-JAN-2001	REASON: --						MOS
HRS	7494	TECH:						HRS
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
321178	DYE PENETRANT CHECK RIGHT WHEEL AXLE						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3							
321176	INSPECT/LUBRICATE RIGHT MAIN GEAR INBOARD WHEEL HALF RIGHT MAIN GEAR INBOARD WHEEL BEARINGS						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
321175	INSPECT/LUBRICATE RIGHT MAIN GEAR INBOARD WHEEL HALF RIGHT MAIN GEAR INBOARD WHEEL BEARINGS						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001	REASON: --					MOS
HRS	7494	TECH:					HRS
AFL	5466	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
321136	SERVICE RIGHT MAIN GEAR ASSEMBLY RIGHT MAIN GEAR SHOCK STRUT						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3							
321107	LUBRICATE RIGHT ACTUATOR BOLTS						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3							
321106	LUBRICATE RIGHT MAIN GEAR ASSEMBLY RIGHT MAIN GEAR						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
321106	LUBRICATE RIGHT MAIN GEAR ASSEMBLY RIGHT MAIN GEAR						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001	REASON: --					MOS
HRS	7494	TECH:					HRS
AFL	5466	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
320691	INSPECT LEFT MAIN GEAR/WELL (A)					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --				MOS		
HRS	7325	TECH:				HRS		
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3								
320691	INSPECT LEFT MAIN GEAR/WELL (A)					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	17-JAN-2001	REASON: --				MOS		
HRS	7494	TECH:				HRS		
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3								
320680	INSPECT/LUBRICATE LEFT MAIN GEAR OUTBOARD WHEEL HALF LEFT MAIN GEAR OUTBOARD WHEEL BEARINGS					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --				MOS		
HRS	7325	TECH:				HRS		
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3								
320680	INSPECT/LUBRICATE LEFT MAIN GEAR OUTBOARD WHEEL HALF LEFT MAIN GEAR OUTBOARD WHEEL BEARINGS					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	17-JAN-2001	REASON: --				MOS		
HRS	7494	TECH:				HRS		
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3								
320678	DYE PENETRANT CHECK LEFT WHEEL AXLE					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --				MOS		
HRS	7325	TECH:				HRS		
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 2,3								
320676	INSPECT/LUBRICATE LEFT MAIN GEAR INBOARD WHEEL HALF LEFT MAIN GEAR INBOARD WHEEL BEARINGS					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --				MOS		
HRS	7325	TECH:				HRS		
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3								
320676	INSPECT/LUBRICATE LEFT MAIN GEAR INBOARD WHEEL HALF LEFT MAIN GEAR INBOARD WHEEL BEARINGS					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	17-JAN-2001	REASON: --				MOS		
HRS	7494	TECH:				HRS		
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 1,2,3								

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
320636	SERVICE LEFT MAIN GEAR ASSEMBLY LEFT MAIN GEAR SHOCK STRUT				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3							
320607	LUBRICATE LEFT ACTUATOR BOLTS				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3							
320606	LUBRICATE LEFT MAIN GEAR ASSEMBLY LEFT MAIN GEAR				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
320606	LUBRICATE LEFT MAIN GEAR ASSEMBLY LEFT MAIN GEAR				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	17-JAN-2001	REASON: --					MOS
HRS	7494	TECH:					HRS
AFL	5466	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
320206	INSPECT NOSE GEAR (B)				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3							
320201	INSPECT NOSE GEAR (A)				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
320201	INSPECT NOSE GEAR (A)				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	17-JAN-2001	REASON: --					MOS
HRS	7494	TECH:					HRS
AFL	5466	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							
320158	INSPECT/CLEAN/LUBRICATE NOSE GEAR RIGHT WHEEL BEARINGS				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3							



AIRCRAFT Updates Report

Serial #: 368 Reg. #: N368MD
 Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR		
320158	INSPECT/CLEAN/LUBRICATE NOSE GEAR RIGHT WHEEL BEARINGS							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR							
MOS	17-JAN-2001	TRANSACTION DATE:	23-MAY-2001 12:00:00					MOS
HRS	7494	REASON:	--					HRS
AFL	5466	TECH:						AFL
		INSP:		LABOR HRS:	0	COST:	\$0.00	
Note: OP 1,2,3								
320156	INSPECT/CLEAN/LUBRICATE NOSE GEAR LEFT WHEEL BEARINGS							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR							
MOS	26-JUL-2000	TRANSACTION DATE:	23-MAY-2001 12:00:00					MOS
HRS	7325	REASON:	--					HRS
AFL	5360	TECH:						AFL
		INSP:		LABOR HRS:	0	COST:	\$0.00	
Note: OP 1,2,3								
320156	INSPECT/CLEAN/LUBRICATE NOSE GEAR LEFT WHEEL BEARINGS							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR							
MOS	17-JAN-2001	TRANSACTION DATE:	23-MAY-2001 12:00:00					MOS
HRS	7494	REASON:	--					HRS
AFL	5466	TECH:						AFL
		INSP:		LABOR HRS:	0	COST:	\$0.00	
Note: OP 1,2,3								
320116	SERVICE NOSE GEAR ASSEMBLY SHOCK STRUT							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR							
MOS	26-JUL-2000	TRANSACTION DATE:	23-MAY-2001 12:00:00					MOS
HRS	7325	REASON:	--					HRS
AFL	5360	TECH:						AFL
		INSP:		LABOR HRS:	0	COST:	\$0.00	
Note: OP 2,3								
320106	LUBRICATE NOSE GEAR ASSEMBLY NOSE GEAR/DOORS							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR							
MOS	26-JUL-2000	TRANSACTION DATE:	23-MAY-2001 12:00:00					MOS
HRS	7325	REASON:	--					HRS
AFL	5360	TECH:						AFL
		INSP:		LABOR HRS:	0	COST:	\$0.00	
Note: OP 1,2,3								
320106	LUBRICATE NOSE GEAR ASSEMBLY NOSE GEAR/DOORS							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR							
MOS	17-JAN-2001	TRANSACTION DATE:	23-MAY-2001 12:00:00					MOS
HRS	7494	REASON:	--					HRS
AFL	5466	TECH:						AFL
		INSP:		LABOR HRS:	0	COST:	\$0.00	
Note: OP 1,2,3								
300170	OPERATIONAL TEST P2T2 SENSOR HEATER							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR							
MOS	26-JUL-2000	TRANSACTION DATE:	23-MAY-2001 12:00:00					MOS
HRS	7325	REASON:	--					HRS
AFL	5360	TECH:						AFL
		INSP:		LABOR HRS:	0	COST:	\$0.00	
Note: OP 1,2,3								
530205	INSPECT FORWARD TO AFT MAIN FRAME							
C/W	WARR							
MOS	26-JUL-2000	TRANSACTION DATE:	23-MAY-2001 12:00:00					MOS
HRS	7325	REASON:	--					HRS
AFL	5360	TECH:						AFL
		INSP:		LABOR HRS:	0	COST:	\$0.00	

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR	
530200	INSPECT FORWARD TO AFT PRESSURE BULKHEAD-FUSELAGE						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --				MOS	
HRS	7325	TECH:				HRS	
AFL	5360	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00				
530176	INSPECT AUXILIARY FUEL TANK STRUCTURE.						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --				MOS	
HRS	7325	TECH:				HRS	
AFL	5360	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00				
530156	INSPECT CABIN (C)						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --				MOS	
HRS	7325	TECH:				HRS	
AFL	5360	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00				
530141	INSPECT COCKPIT (C)						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --				MOS	
HRS	7325	TECH:				HRS	
AFL	5360	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00				
520151	INSPECT/LUBRICATE RIGHT EMERGENCY EXIT HATCH SEAL						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --				MOS	
HRS	7325	TECH:				HRS	
AFL	5360	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00				
520141	INSPECT/LUBRICATE LEFT EMERGENCY EXIT HATCH SEAL						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --				MOS	
HRS	7325	TECH:				HRS	
AFL	5360	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00				
350243	TEST PASSENGER OXYGEN SUPPLY SYSTEM						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --				MOS	
HRS	7325	TECH:				HRS	
AFL	5360	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00				
350106	HYDROSTATIC TEST OXYGEN CYLINDER						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --				MOS	
HRS	7325	TECH:				HRS	
AFL	5360	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00				
322211	FUNCTIONAL TEST EMERGENCY GEAR EXTENSION						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --				MOS	
HRS	7325	TECH:				HRS	
AFL	5360	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00				

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
322136	BLEED BRAKE SYSTEM							
MOS	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
	17-JAN-2001		REASON: --					MOS
MSC			TECH:					MSC
AFL	5466		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
320180	LUBRICATE NOSE GEAR ASSEMBLY NOSE STEERING CONTROL CABLES							
MOS	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
320179	INSPECT NOSE GEAR ASSEMBLY NOSE STEERING CABLES							
MOS	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
320172	TEST NOSE GEAR ASSEMBLY DRAG BRACE DOWNLOCK TENSION							
MOS	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
300133	FUNCTIONAL CHECK PNEUMATIC DE-ICER BOOTS.							
MOS	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
290206	REPLACE RESERVOIR AIR PRESSURE REGULATOR NO.2 ENGINE HIGH PRESSURE HYDRAULIC FILTER ELEMENT							
MOS	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
290171	REPLACE RESERVOIR AIR PRESSURE REGULATOR NO.1 ENGINE HIGH PRESSURE HYDRAULIC FILTER ELEMENT							
MOS	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
290131	INSPECT/REPLACE RESERVOIR AIR PRESSURE REGULATOR RESERVOIR AIR PRESSURE FILTER							
MOS	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
290116	INSPECT/REPLACE RESERVOIR AIR PRESSURE REGULATOR RESERVOIR AIR VENT FILTER							
MOS	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
290106	REPLACE HYDRAULIC RESERVOIR FILTER						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
281602	OPERATIONAL CHECK FUEL DUMP SYSTEM						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
280123	CHECK LEFT MAIN BOOST PUMP BRUSH WEAR						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	24-APR-2000	REASON: --					MOS
HRS	7233	TECH:					HRS
AFL	5301	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
270356	LUBRICATE GUST LOCK						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
270351	INSPECT/LUBRICATE PRESSURE SEALS						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
270346	LUBRICATE FLIGHT CONTROL FORWARD/AFT BELLCRANKS						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
270340	CHECK CABLE TENSION FLIGHT/PASSENGER COMPARTMENT						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
270271	ADJUST/TEST FLAP COMPARATOR						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
270245	INSPECT RIGHT FLAP/VANE RIGHT FLAP HINGE AND BEARING 800 HOURS						
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --					MOS
HRS	7325	TECH:					HRS
AFL	5360	INSP:	LABOR HRS: 0	COST: \$0.00			AFL

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
270244	INSPECT LEFT FLAP/VANE LEFT FLAP HINGE AND BEARING 800 HOURS							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
270179	LUBRICATE CONTROL COLUMNS							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
270176	LUBRICATE RUDDER PEDAL ARMS							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
270145	STATIC FRICTION TEST AILERON AND RUDDER							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
270140	CHECK AILERON CONTROL SYSTEM FREEPLAY							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
260146	RECORD DATE LEFT FIRE EXTINGUISHER STAMPED ON NEW CARTRIDGE (SERVICE LIFE)							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	17-JAN-2001	REASON: --						MOS
HRS		TECH:						HRS
AFL		INSP:		LABOR HRS: 0	COST: \$0.00			AFL
260131	WEIGHT CHECK RIGHT FIRE EXTINGUISHER							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	17-JAN-2001	REASON: --						MOS
HRS	7494	TECH:						HRS
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
260116	WEIGHT CHECK LEFT FIRE EXTINGUISHER							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	17-JAN-2001	REASON: --						MOS
MSC		TECH:						MSC
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
241657	INSPECT TEST PRIORITY BUS DIODES							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
241655	INSPECT DISTRIBUTION BUS CIRCUIT BREAKER							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
241653	CHECK CIRCUIT BREAKER RESISTANCE/INSPECT BUS							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
210280	CHECK BLEED AIR DUCT OVERPRESSURE SWITCH							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
210221	REPLACE LOWER ABSOLUTE AIR PRESSURE REGULATOR LOWER INLET AIR FILTER ELEMENT							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
210211	REPLACE GROUND BY-PASS VALVE UPPER INLET AIR FILTER ELEMENT							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
210178	CLEAN CABIN AIR PRESSURE CONTROLLER FILTER							
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
990131	ACCOMPLISH AD89-12-08 AIRWORTHINESS DIRECTIVE							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: EFFECTIVE 07-10-89 - REF:550666								
950942	ACCOMPLISH SLWW-2494 REV 3 RMG BOLTS BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: RPT 300 HRS								
950941	ACCOMPLISH SLWW-2494 REV 3 LMG BOLTS BULLETIN							Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --						MOS
HRS	7325	TECH:						HRS
AFL	5360	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
Note: RPT 300 HRS								

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001		REASON: --					MOS
HRS	7494		TECH:					HRS
AFL	5466		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
300170	OPERATIONAL TEST P2T2 SENSOR HEATER							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001		REASON: --					MOS
HRS	7494		TECH:					HRS
AFL	5466		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
300163	INSPECT WINDSHIELD WIPER ASSEMBLY							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
300163	INSPECT WINDSHIELD WIPER ASSEMBLY							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001		REASON: --					MOS
HRS	7494		TECH:					HRS
AFL	5466		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
300150	INSPECT COPILOT WINDSHIELD CYCLING CONTACTOR							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
300150	INSPECT COPILOT WINDSHIELD CYCLING CONTACTOR							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001		REASON: --					MOS
HRS	7494		TECH:					HRS
AFL	5466		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
300156	CHANGE LEFT WINDSHIELD WIPER MOTOR							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00	Off: 5-823099-401	29626			Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: B - FAIL	On:				MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00		0	AFL

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR	
300147	INSPECT PILOT WINDSHIELD CYCLING CONTACTOR					Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --				MOS	
HRS	7325	TECH:				HRS	
AFL	5360	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3 - 7264-4654							
300147	INSPECT PILOT WINDSHIELD CYCLING CONTACTOR					Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	17-JAN-2001	REASON: --				MOS	
HRS	7494	TECH:				HRS	
AFL	5466	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3 - 7264-4654							
281150	CHECK OPERATION OF FUEL BOOST PUMPS					Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	17-JAN-2001	REASON: --				MOS	
HRS	7494	TECH:				HRS	
AFL	5466	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3							
280121	CHANGE LEFT MAIN BOOST PUMP					Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	24-APR-2000	REASON: B - FAIL		Off: 2070C01T3	157	MOS	
HRS	7233	TECH:		On:		HRS	
AFL	5301	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00				
270341	CHECK CABLE TENSION AFT FUSELAGE					Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --				MOS	
HRS	7325	TECH:				HRS	
AFL	5360	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00				
Note: OP 2,3							
270335	OPERATIONAL CHECK SPEED BRAKES AND LIFT DUMPERS					Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --				MOS	
HRS	7325	TECH:				HRS	
AFL	5360	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3							
270335	OPERATIONAL CHECK SPEED BRAKES AND LIFT DUMPERS					Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	17-JAN-2001	REASON: --				MOS	
HRS	7494	TECH:				HRS	
AFL	5466	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3							
270265	CLEAN/CHECK RIGHT AILERON RIGHT GUIDE ROLLERS					Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					
MOS	26-JUL-2000	REASON: --				MOS	
HRS	7325	TECH:				HRS	
AFL	5360	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00				
Note: OP 2,3							



AIRCRAFT Updates Report

Serial #: 368 Reg. #: N368MD
 Model: 1124A WESTWIND

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
270264	CLEAN/CHECK LEFT AILERON LEFT GUIDE ROLLERS							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
270263	INSPECT RIGHT AILERON RIGHT EXTERNAL PUSH-PULL TUBE							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
270262	INSPECT LEFT AILERON LEFT EXTERNAL PUSH-PULL TUBE							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
270248	FUNCTIONAL CHECK FLAP TIME EXCEED RELAY							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
270247	INSPECT RIGHT FLAP/VANE							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
270247	INSPECT RIGHT FLAP/VANE							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001		REASON: --					MOS
HRS	7494		TECH:					HRS
AFL	5466		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
270243	TAP TEST RIGHT FLAP/VANE							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
270242	INSPECT RIGHT FLAP/VANE RIGHT FLAP HINGE AND BEARING 200 HOURS							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR	
270242	INSPECT RIGHT FLAP/VANE RIGHT FLAP HINGE AND BEARING 200 HOURS						
CW	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS 17-JAN-2001		REASON: --		MOS			
HRS 7494		TECH:		HRS			
AFL 5466		INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3							
270240	INSPECT LEFT FLAP/VANE LEFT FLAP HINGE AND BEARING 200 HOURS						
CW	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS 26-JUL-2000		REASON: --		MOS			
HRS 7325		TECH:		HRS			
AFL 5360		INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3							
270213	LUBRICATE ELEVATOR ATTACH POINTS						
CW	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS 26-JUL-2000		REASON: --		MOS			
HRS 7325		TECH:		HRS			
AFL 5360		INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3							
270213	LUBRICATE ELEVATOR ATTACH POINTS						
CW	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS 17-JAN-2001		REASON: --		MOS			
HRS 7494		TECH:		HRS			
AFL 5466		INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3							
270211	INSPECT SCISSORS ASSEMBLY						
CW	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS 26-JUL-2000		REASON: --		MOS			
HRS 7325		TECH:		HRS			
AFL 5360		INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
Note: OP 2,3							
270203	INSPECT RIGHT ELEVATOR SKIN SEPARATION						
CW	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS 26-JUL-2000		REASON: --		MOS			
HRS 7325		TECH:		HRS			
AFL 5360		INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3							
270203	INSPECT RIGHT ELEVATOR SKIN SEPARATION						
CW	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS 17-JAN-2001		REASON: --		MOS			
HRS 7494		TECH:		HRS			
AFL 5466		INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3							
270193	INSPECT LEFT ELEVATOR SKIN SEPARATION						
CW	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Done By: CAMP SYSTEMS INTERNATIONAL, LLC			
MOS 26-JUL-2000		REASON: --		MOS			
HRS 7325		TECH:		HRS			
AFL 5360		INSP:		AFL			
		LABOR HRS: 0	COST: \$0.00				
Note: OP 1,2,3							

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
270193	INSPECT LEFT ELEVATOR SKIN SEPARATION							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001		REASON: --					MOS
HRS	7494		TECH:					HRS
AFL	5466		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
240133	INSPECT NO. 2 STARTER GENERATOR SPLINE							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 5,7								
210622	INSPECT 35 DEGREE TEMPERATURE SENSOR 35 DEGREE DUCT SENSOR							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001		REASON: --					MOS
HRS	7494		TECH:					HRS
AFL	5466		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
210276	OPERATIONAL CHECK PRESSURIZATION SWITCHES AND VALVES							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
210112	VISUALLY INSPECT RIGHT BLEED AIR SWITCHING VALVE							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
210102	VISUALLY INSPECT LEFT BLEED AIR SWITCHING VALVE							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 2,3								
120150	CHECK PRE-FLIGHT							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	26-JUL-2000		REASON: --					MOS
HRS	7325		TECH:					HRS
AFL	5360		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								
120150	CHECK PRE-FLIGHT							
	C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00					Done By: CAMP SYSTEMS INTERNATIONAL, LLC
MOS	17-JAN-2001		REASON: --					MOS
HRS	7494		TECH:					HRS
AFL	5466		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 1,2,3								

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model : 1124A WESTWIND

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
100330	CHECK SERVICE LETTERS					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	17-JAN-2001	REASON: --				MOS		
HRS	7494	TECH:				HRS		
AFL	5466	INSP:		LABOR HRS: 0		COST: \$0.00		AFL
Note: OP 1,2,3								
100320	CHECK SERVICE BULLETINS					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --				MOS		
HRS	7325	TECH:				HRS		
AFL	5360	INSP:		LABOR HRS: 0		COST: \$0.00		AFL
Note: OP 1,2,3								
240126	CHANGE NO. 2 STARTER GENERATOR					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00		Off. 23065-018-1	2562			
MOS	26-JUL-2000	REASON: A - TIME		On:		MOS		0
HRS	7325	TECH:				HRS		0
AFL	5360	INSP:				AFL		0
LABOR HRS: 0 COST: \$0.00								
100320	CHECK SERVICE BULLETINS					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	17-JAN-2001	REASON: --				MOS		
HRS	7494	TECH:				HRS		
AFL	5466	INSP:		LABOR HRS: 0		COST: \$0.00		AFL
Note: OP 1,2,3								
100310	CHECK AIRWORTHY DIRECTIVES					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --				MOS		
HRS	7325	TECH:				HRS		
AFL	5360	INSP:		LABOR HRS: 0		COST: \$0.00		AFL
Note: OP 1,2,3								
100310	CHECK AIRWORTHY DIRECTIVES					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	17-JAN-2001	REASON: --				MOS		
HRS	7494	TECH:				HRS		
AFL	5466	INSP:		LABOR HRS: 0		COST: \$0.00		AFL
Note: OP 1,2,3								
050300U	400/200 HOUR INSPECTION					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --				MOS		
HRS	7325	TECH:				HRS		
AFL	5360	INSP:		LABOR HRS: 0		COST: \$0.00		AFL
Note: OP 3								
050150U	200 HOUR INSPECTION					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 23-MAY-2001 12:00:00						
MOS	26-JUL-2000	REASON: --				MOS		
HRS	7325	TECH:				HRS		
AFL	5360	INSP:		LABOR HRS: 0		COST: \$0.00		AFL
Note: OP 2,3								

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
120160	CHECK NO.1 ENGINE PREFLIGHT COMPLETE					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 29-MAY-2001 12:00:00						
MOS	16-FEB-2001	REASON: --				MOS		
HRS	7551	TECH:				HRS		
AFL	5515	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 4,6								
240121	CHECK NO. 1 STARTER GENERATOR BRUSH WEAR/TENSION					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 29-MAY-2001 12:00:00						
MOS	16-FEB-2001	REASON: --				MOS		
HRS	7551	TECH:				HRS		
AFL	5515	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 4,6								
346126	TEST NO.2 ATC TRANSPONDER FAR 91.413							
C/W	WARR	TRANSACTION DATE: 29-MAY-2001 12:00:00						
MOS	18-JAN-2001	REASON: --				MOS		
HRS	7494	TECH:				HRS		
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
346111	TEST NO.1 ATC TRANSPONDER FAR 91.413							
C/W	WARR	TRANSACTION DATE: 29-MAY-2001 12:00:00						
MOS	18-JAN-2001	REASON: --				MOS		
HRS	7494	TECH:				HRS		
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
343672	CALIBRATE NO.1 AIR DATA COMPUTER FAR 91.411							
C/W	WARR	TRANSACTION DATE: 29-MAY-2001 12:00:00						
MOS	18-JAN-2001	REASON: --				MOS		
HRS	7494	TECH:				HRS		
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
341116	TEST COPILOT ALTIMETER FAR 91.411							
C/W	WARR	TRANSACTION DATE: 29-MAY-2001 12:00:00						
MOS	18-JAN-2001	REASON: --				MOS		
HRS	7494	TECH:				HRS		
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
341106	TEST PILOT ALTIMETER FAR 91.411							
C/W	WARR	TRANSACTION DATE: 29-MAY-2001 12:00:00						
MOS	18-JAN-2001	REASON: --				MOS		
HRS	7494	TECH:				HRS		
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
340151	LEAK CHECK RIGHT STATIC SYSTEM							
C/W	WARR	TRANSACTION DATE: 29-MAY-2001 12:00:00						
MOS	18-JAN-2001	REASON: --				MOS		
HRS	7494	TECH:				HRS		
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
340146	LEAK CHECK LEFT STATIC SYSTEM							
C/W	WARR	TRANSACTION DATE: 29-MAY-2001 12:00:00						
MOS	18-JAN-2001	REASON: --				MOS		
HRS	7494	TECH:				HRS		
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR	
270285	CLEAN/INSPECT/LUBRICATE RIGHT INBOARD/OUTBOARD FLEXIBLE SHAFT						
CW	WARR	TRANSACTION DATE: 29-MAY-2001 12:00:00					
MOS	16-FEB-2001	REASON: --				MOS	
HRS	7551	TECH:				HRS	
AFL	5515	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00				
270280	CLEAN/INSPECT/LUBRICATE LEFT INBOARD/OUTBOARD FLEXIBLE SHAFT						
CW	WARR	TRANSACTION DATE: 29-MAY-2001 12:00:00					
MOS	16-FEB-2001	REASON: --				MOS	
HRS	7551	TECH:				HRS	
AFL	5515	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00				
240133	INSPECT NO. 2 STARTER GENERATOR SPLINE					Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
CW	WARR	TRANSACTION DATE: 29-MAY-2001 12:00:00					
MOS	16-FEB-2001	REASON: --				MOS	
HRS	7551	TECH:				HRS	
AFL	5515	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00				
Note: OP 5,7							
240131	CHECK NO. 2 STARTER GENERATOR BRUSH WEAR/TENSION					Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
CW	WARR	TRANSACTION DATE: 29-MAY-2001 12:00:00					
MOS	16-FEB-2001	REASON: --				MOS	
HRS	7551	TECH:				HRS	
AFL	5515	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00				
Note: OP 5,7							
240128	INSPECT NO. 2 STARTER GENERATOR					Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
CW	WARR	TRANSACTION DATE: 29-MAY-2001 12:00:00					
MOS	17-JAN-2001	REASON: --				MOS	
HRS	7494	TECH:				HRS	
AFL	5466	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00				
Note: OP 5,7							
240128	INSPECT NO. 2 STARTER GENERATOR					Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
CW	WARR	TRANSACTION DATE: 29-MAY-2001 12:00:00					
MOS	16-FEB-2001	REASON: --				MOS	
HRS	7551	TECH:				HRS	
AFL	5515	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00				
Note: OP 5,7							
240123	INSPECT NO. 1 STARTER GENERATOR SPLINE					Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
CW	WARR	TRANSACTION DATE: 29-MAY-2001 12:00:00					
MOS	16-FEB-2001	REASON: --				MOS	
HRS	7551	TECH:				HRS	
AFL	5515	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00				
Note: OP 4,6							
120161	CHECK NO.2 ENGINE PREFLIGHT COMPLETE					Done By: CAMP SYSTEMS INTERNATIONAL, LLC	
CW	WARR	TRANSACTION DATE: 29-MAY-2001 12:00:00					
MOS	16-FEB-2001	REASON: --				MOS	
HRS	7551	TECH:				HRS	
AFL	5515	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00				
Note: OP 5,7							



AIRCRAFT Updates Report

Serial #: 368 Reg. #: N368MD
 Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
240118	INSPECT NO. 1 STARTER GENERATOR			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
C/W	WARR	TRANSACTION DATE: 29-MAY-2001 12:00:00						
MOS	16-FEB-2001	REASON: --						
HRS	7551	TECH:						
AFL	5515	INSP:		LABOR HRS: 0	COST: \$0.00	MOS	HRS	AFL
Note: OP 4,6								
240118	INSPECT NO. 1 STARTER GENERATOR			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
C/W	WARR	TRANSACTION DATE: 29-MAY-2001 12:00:00						
MOS	17-JAN-2001	REASON: --						
HRS	7494	TECH:						
AFL	5466	INSP:		LABOR HRS: 0	COST: \$0.00	MOS	HRS	AFL
Note: OP 4,6								
260161	RECORD DATE RIGHT FIRE EXTINGUISHER STAMPED ON NEW CARTRIDGE (SERVICE LIFE)							
C/W	WARR	TRANSACTION DATE: 29-MAY-2001 12:00:00						
MOS	17-JAN-2001	REASON: --						
HRS		TECH:						
AFL		INSP:		LABOR HRS: 0	COST: \$0.00	MOS	HRS	AFL
260156	RECORD DATE RIGHT FIRE EXTINGUISHER STAMPED ON NEW CARTRIDGE (SERVICE LIFE)							
C/W	WARR	TRANSACTION DATE: 29-MAY-2001 12:00:00						
MOS	17-JAN-2001	REASON: --						
HRS		TECH:						
AFL		INSP:		LABOR HRS: 0	COST: \$0.00	MOS	HRS	AFL
260153	REPLACE LEFT FIRE EXTINGUISHER NO.2 CARTRIDGE							
C/W	WARR	TRANSACTION DATE: 29-MAY-2001 12:00:00						
MOS	17-JAN-2001	REASON: --						
HRS		TECH:						
AFL		INSP:		LABOR HRS: 0	COST: \$0.00	MOS	HRS	AFL
240166	DEEP CYCLE LEFT BATTERY			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						
HRS	7687	TECH:						
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00	MOS	HRS	AFL
Note: OP 1,2,3								
260180	VISUAL INSPECTION CABIN PORTABLE EXTINGUISHER CABIN FIRE EXTINGUISHER			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						
HRS	7687	TECH:						
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00	MOS	HRS	AFL
330228	CHARGE EMERGENCY LIGHT BATTERY			Done By: CAMP SYSTEMS INTERNATIONAL, LLC				
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						
HRS	7687	TECH:						
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00	MOS	HRS	AFL
100310	CHECK AIRWORTHY DIRECTIVES							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						
HRS	7687	TECH:						
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00	MOS	HRS	AFL

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
100330	CHECK SERVICE LETTERS							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:						AFL
		LABOR HRS:	0	COST:	\$0.00			
210102	VISUALLY INSPECT LEFT BLEED AIR SWITCHING VALVE							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:						AFL
		LABOR HRS:	0	COST:	\$0.00			
210276	OPERATIONAL CHECK PRESSURIZATION SWITCHES AND VALVES							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:						AFL
		LABOR HRS:	0	COST:	\$0.00			
210671	CLEAN/REPLACE WATER SEPARATOR CONDENSER/FILTER							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:						AFL
		LABOR HRS:	1	COST:	\$0.00			
270215	LUBRICATE FORWARD SCISSOR ASSEMBLY							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:						AFL
		LABOR HRS:	0	COST:	\$0.00			
270214	LUBRICATE AFT HINGE FITTING BEARINGS							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:						AFL
		LABOR HRS:	0	COST:	\$0.00			
270213	LUBRICATE ELEVATOR ATTACH POINTS							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:						AFL
		LABOR HRS:	0	COST:	\$0.00			
270211	INSPECT SCISSORS ASSEMBLY							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:						AFL
		LABOR HRS:	0	COST:	\$0.00			
270203	INSPECT RIGHT ELEVATOR SKIN SEPARATION							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:						AFL
		LABOR HRS:	0	COST:	\$0.00			

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
270193	INSPECT LEFT ELEVATOR SKIN SEPARATION							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
270158	INSPECT RUDDER TRIM TAB FREEPLAY							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
260186	OPERATIONAL CHECK FIRE PROTECTION SYSTEM							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
260184	INSPECT CABIN PORTABLE EXTINGUISHER CABIN FIRE EXTINGUISHER							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
260181	WEIGHT CHECK CABIN PORTABLE EXTINGUISHER CABIN FIRE EXTINGUISHER							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
260174	INSPECT COCKPIT PORTABLE EXTINGUISHER COCKPIT FIRE EXTINGUISHER							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
260171	WEIGHT CHECK COCKPIT PORTABLE EXTINGUISHER COCKPIT FIRE EXTINGUISHER							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
240203	FUNCTIONALLY CHECK EXTERNAL POWER RECEPTACLE BATTERY TEMPERATURE AND WARNING SYSTEM							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
240176	CHECK RIGHT BATTERY ELECTROLYTE LEVEL							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 1	COST: \$0.00			AFL

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
240161	CHECK LEFT BATTERY ELECTROLYTE LEVEL							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 1	COST: \$0.00			AFL
230218	INSPECT/CHECK STATIC DISCHARGE WICK RESISTANCE							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
210681	CHANGE COOLING TURBINE OIL							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
270262	INSPECT LEFT AILERON LEFT EXTERNAL PUSH-PULL TUBE							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
270248	FUNCTIONAL CHECK FLAP TIME EXCEED RELAY							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
270247	INSPECT RIGHT FLAP/VANE							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
270243	TAP TEST RIGHT FLAP/VANE							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: .5	COST: \$0.00			AFL
270242	INSPECT RIGHT FLAP/VANE RIGHT FLAP HINGE AND BEARING 200 HOURS							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
270240	INSPECT LEFT FLAP/VANE LEFT FLAP HINGE AND BEARING 200 HOURS							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00			AFL

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
270238	TAP TEST LEFT FLAP/VANE LEFT FLAP							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: .5	COST: \$0.00			AFL
270237	INSPECT LEFT FLAP/VANE LEFT FLAP VANE							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:	LABOR HRS: 0	COST: \$0.00			HRS
AFL	5594		INSP:					AFL
270217	INSPECT HORIZONTAL STABILIZER TRIM ACTUATOR							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:	LABOR HRS: 0	COST: \$0.00			HRS
AFL	5594		INSP:					AFL
320116	SERVICE NOSE GEAR ASSEMBLY SHOCK STRUT							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:	LABOR HRS: 2.5	COST: \$0.00			HRS
AFL	5594		INSP:					AFL
320106	LUBRICATE NOSE GEAR ASSEMBLY NOSE GEAR/DOORS							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:	LABOR HRS: .5	COST: \$0.00			HRS
AFL	5594		INSP:					AFL
300170	OPERATIONAL TEST P2T2 SENSOR HEATER							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:	LABOR HRS: 0	COST: \$0.00			HRS
AFL	5594		INSP:					AFL
300163	INSPECT WINDSHIELD WIPER ASSEMBLY							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:	LABOR HRS: 0	COST: \$0.00			HRS
AFL	5594		INSP:					AFL
300150	INSPECT COPILOT WINDSHIELD CYCLING CONTACTOR							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:	LABOR HRS: 0	COST: \$0.00			HRS
AFL	5594		INSP:					AFL
300147	INSPECT PILOT WINDSHIELD CYCLING CONTACTOR							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:	LABOR HRS: 0	COST: \$0.00			HRS
AFL	5594		INSP:					AFL

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
300104	INSPECT RIGHT DE-ICER CHECK VALVE							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
300102	INSPECT LEFT DE-ICER CHECK VALVE							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
290178	INSPECT/LUBRICATE NO. 2 HYDRAULIC PUMP NO.2 ENGINE HYDRAULIC PUMP SPLINES							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 1	COST: \$0.00			AFL
321180	INSPECT/LUBRICATE RIGHT MAIN GEAR OUTBOARD WHEEL HALF RIGHT MAIN GEAR OUTBOARD WHEEL BEARINGS							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 1	COST: \$0.00			AFL
321178	DYE PENETRANT CHECK RIGHT WHEEL AXLE							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
321176	INSPECT/LUBRICATE RIGHT MAIN GEAR INBOARD WHEEL HALF RIGHT MAIN GEAR INBOARD WHEEL BEARINGS							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 1	COST: \$0.00			AFL
321136	SERVICE RIGHT MAIN GEAR ASSEMBLY RIGHT MAIN GEAR SHOCK STRUT							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 2	COST: \$0.00			AFL
321107	LUBRICATE RIGHT ACTUATOR BOLTS							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
321106	LUBRICATE RIGHT MAIN GEAR ASSEMBLY RIGHT MAIN GEAR							
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: .5	COST: \$0.00			AFL

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
320691	INSPECT LEFT MAIN GEAR/WELL (A)							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 1.5	COST: \$0.00			AFL
320680	INSPECT/LUBRICATE LEFT MAIN GEAR OUTBOARD WHEEL HALF LEFT MAIN GEAR OUTBOARD WHEEL BEARINGS							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
320678	DYE PENETRANT CHECK LEFT WHEEL AXLE							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
713650U	-- INSP #2 ENG INLET NACELLE							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
710650U	-- INSP #1 ENG INLET NACELLE							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
050300U	400/200 HOUR INSPECTION							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 45.5	COST: \$0.00			AFL
050150U	200 HOUR INSPECTION							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 31	COST: \$0.00			AFL
950942	SLWW-2494 REV 3 RMG BOLTS SERVICE BULLETIN							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
950941	SLWW-2494 REV 3 LMG BOLTS SERVICE BULLETIN							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
950920	SL WW-2492 HYD HOSE INSP SERVICE BULLETIN						
	CW	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00				
MOS	26-JUN-2001		REASON: --				MOS
HRS	7687		TECH:				HRS
AFL	5594		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
1124-30-036 PART II	ICE AND RAIN PROTECTION SERVICE BULLETIN						
	CW	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00				
MOS	26-JUN-2001		REASON: --				MOS
HRS	7687		TECH:				HRS
AFL	5594		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
1124-55-020 R2	STABILIZERS SERVICE BULLETIN						
	CW	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00				
MOS	26-JUN-2001		REASON: --				MOS
HRS	7687		TECH:				HRS
AFL	5594		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
570120	INSPECT RIGHT AILERON BELLCRANK						
	CW	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00				
MOS	26-JUN-2001		REASON: --				MOS
HRS	7687		TECH:				HRS
AFL	5594		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
570119	INSPECT RIGHT WING (B)						
	CW	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00				
MOS	26-JUN-2001		REASON: --				MOS
HRS	7687		TECH:				HRS
AFL	5594		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
570116	INSPECT RIGHT WING (A)						
	CW	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00				
MOS	26-JUN-2001		REASON: --				MOS
HRS	7687		TECH:				HRS
AFL	5594		INSP:				AFL
			LABOR HRS: 1.5	COST: \$0.00			
570106	INSPECT LEFT AILERON BELLCRANK						
	CW	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00				
MOS	26-JUN-2001		REASON: --				MOS
HRS	7687		TECH:				HRS
AFL	5594		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
570104	INSPECT LEFT WING (B)						
	CW	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00				
MOS	26-JUN-2001		REASON: --				MOS
HRS	7687		TECH:				HRS
AFL	5594		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
570101	INSPECT LEFT WING (A)						
	CW	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00				
MOS	26-JUN-2001		REASON: --				MOS
HRS	7687		TECH:				HRS
AFL	5594		INSP:				AFL
			LABOR HRS: 1.5	COST: \$0.00			

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
550656	CHECK HORIZONTAL STABILIZER AFT SPAR SPLICE-HINGE FITTING OUTBOARD LUGS FOR CRACKS						
	C/W	WARR					
MOS	26-JUN-2001						MOS
HRS	7687						HRS
AFL	5594						AFL
	TRANSACTION DATE: 09-JUL-2001 12:00:00						
	REASON: --						
	TECH:						
	INSP:						
			LABOR HRS: 0	COST: \$0.00			
550106	INSPECT EMPENNAGE (B)						
	C/W	WARR					
MOS	26-JUN-2001						MOS
HRS	7687						HRS
AFL	5594						AFL
	TRANSACTION DATE: 09-JUL-2001 12:00:00						
	REASON: --						
	TECH:						
	INSP:						
			LABOR HRS: 0	COST: \$0.00			
550101	INSPECT EMPENNAGE (A)						
	C/W	WARR					
MOS	26-JUN-2001						MOS
HRS	7687						HRS
AFL	5594						AFL
	TRANSACTION DATE: 09-JUL-2001 12:00:00						
	REASON: --						
	TECH:						
	INSP:						
			LABOR HRS: 0	COST: \$0.00			
540126U	INSPECT NO. 2 ENGINE NACELLE/PYLON (B)						
	C/W	WARR					
MOS	26-JUN-2001						MOS
HRS	7687						HRS
AFL	5594						AFL
	TRANSACTION DATE: 09-JUL-2001 12:00:00						
	REASON: --						
	TECH:						
	INSP:						
			LABOR HRS: 3	COST: \$0.00			
540121U	INSPECT NO. 2 ENGINE NACELLE/PYLON (A)						
	C/W	WARR					
MOS	26-JUN-2001						MOS
HRS	7687						HRS
AFL	5594						AFL
	TRANSACTION DATE: 09-JUL-2001 12:00:00						
	REASON: --						
	TECH:						
	INSP:						
			LABOR HRS: 0	COST: \$0.00			
540106U	INSPECT NO. 1 ENGINE NACELLE/PYLON (B)						
	C/W	WARR					
MOS	26-JUN-2001						MOS
HRS	7687						HRS
AFL	5594						AFL
	TRANSACTION DATE: 09-JUL-2001 12:00:00						
	REASON: --						
	TECH:						
	INSP:						
			LABOR HRS: 3	COST: \$0.00			
540101U	INSPECT NO. 1 ENGINE NACELLE/PYLON (A)						
	C/W	WARR					
MOS	26-JUN-2001						MOS
HRS	7687						HRS
AFL	5594						AFL
	TRANSACTION DATE: 09-JUL-2001 12:00:00						
	REASON: --						
	TECH:						
	INSP:						
			LABOR HRS: 0	COST: \$0.00			
530166	INSPECT REAR COMPARTMENT (B)						
	C/W	WARR					
MOS	26-JUN-2001						MOS
HRS	7687						HRS
AFL	5594						AFL
	TRANSACTION DATE: 09-JUL-2001 12:00:00						
	REASON: --						
	TECH:						
	INSP:						
			LABOR HRS: 0	COST: \$0.00			
530161	INSPECT REAR COMPARTMENT (A)						
	C/W	WARR					
MOS	26-JUN-2001						MOS
HRS	7687						HRS
AFL	5594						AFL
	TRANSACTION DATE: 09-JUL-2001 12:00:00						
	REASON: --						
	TECH:						
	INSP:						
			LABOR HRS: 0	COST: \$0.00			

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model : 1124A WESTWIND

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
530146	INSPECT CABIN (A)							
CW	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
530136	INSPECT COCKPIT (B)							
CW	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
530131	INSPECT COCKPIT (A)							
CW	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
530121	INSPECT NOSE COMPARTMENT (B)							
CW	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
530116	INSPECT NOSE COMPARTMENT (A)							
CW	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
530101	INSPECT FUSELAGE (A)							
CW	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
520116	OPERATIONAL CHECK CABIN ENTRANCE DOOR							
CW	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
520106	INSPECT/LUBRICATE CABIN ENTRANCE DOOR							
CW	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00			AFL
350169U	CHECK COPILOT OXYGEN MASK							
CW	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00						
MOS	26-JUN-2001	REASON: --						MOS
HRS	7687	TECH:						HRS
AFL	5594	INSP:		LABOR HRS: 0	COST: \$0.00			AFL

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
350166U	CHECK PILOT OXYGEN MASK							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
340121	DRAIN PITOT/STATIC SYSTEM							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 1.5	COST: \$0.00			AFL
322206	FUNCTIONAL TEST EMERGENCY GEAR EXTENSION CONTROL CABLE							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 1	COST: \$0.00			AFL
322201	FUNCTIONAL TEST LANDING GEAR FREE FALL							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
322191	FUNCTIONAL TEST LANDING GEAR (NORMAL)							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00			AFL
322176	FUNCTIONAL CHECK ANTI-SKID DETECTOR SYSTEM							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 1	COST: \$0.00			AFL
322174	OPERATIONAL CHECK ANTI-SKID LIGHTS							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: .5	COST: \$0.00			AFL
322171	INSPECT/CLEAN RIGHT ANTI-SKID DETECTOR							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 1	COST: \$0.00			AFL
322156	INSPECT/CLEAN LEFT ANTI-SKID DETECTOR							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --					MOS
HRS	7687		TECH:					HRS
AFL	5594		INSP:	LABOR HRS: 1	COST: \$0.00			AFL

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION	PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR	
322131	INSPECT/CHECK RIGHT MAIN GEAR BRAKE RIGHT BRAKE LININGS						
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001	REASON: --				MOS	
HRS	7687	TECH:				HRS	
AFL	5594	INSP:				AFL	
		LABOR HRS: 1	COST: \$0.00				
322116	INSPECT/CHECK LEFT MAIN GEAR BRAKE LEFT BRAKE LININGS						
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001	REASON: --				MOS	
HRS	7687	TECH:				HRS	
AFL	5594	INSP:				AFL	
		LABOR HRS: 1	COST: \$0.00				
321616	CHECK EMERGENCY STORAGE BOTTLE LANDING GEAR EMERGENCY SYSTEM PRESSURE						
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001	REASON: --				MOS	
HRS	7687	TECH:				HRS	
AFL	5594	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00				
321191	INSPECT RIGHT MAIN GEAR OUTBOARD WHEEL HALF RIGHT MAIN GEAR/WELL (A)						
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001	REASON: --				MOS	
HRS	7687	TECH:				HRS	
AFL	5594	INSP:				AFL	
		LABOR HRS: 1.5	COST: \$0.00				
320676	INSPECT/LUBRICATE LEFT MAIN GEAR INBOARD WHEEL HALF LEFT MAIN GEAR INBOARD WHEEL BEARINGS						
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001	REASON: --				MOS	
HRS	7687	TECH:				HRS	
AFL	5594	INSP:				AFL	
		LABOR HRS: 1	COST: \$0.00				
320636	SERVICE LEFT MAIN GEAR ASSEMBLY LEFT MAIN GEAR SHOCK STRUT						
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001	REASON: --				MOS	
HRS	7687	TECH:				HRS	
AFL	5594	INSP:				AFL	
		LABOR HRS: 2	COST: \$0.00				
320607	LUBRICATE LEFT ACTUATOR BOLTS						
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001	REASON: --				MOS	
HRS	7687	TECH:				HRS	
AFL	5594	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00				
320606	LUBRICATE LEFT MAIN GEAR ASSEMBLY LEFT MAIN GEAR						
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001	REASON: --				MOS	
HRS	7687	TECH:				HRS	
AFL	5594	INSP:				AFL	
		LABOR HRS: .5	COST: \$0.00				
320206	INSPECT NOSE GEAR (B)						
C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001	REASON: --				MOS	
HRS	7687	TECH:				HRS	
AFL	5594	INSP:				AFL	
		LABOR HRS: 0	COST: \$0.00				

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
320201	INSPECT NOSE GEAR (A)							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --				MOS	
HRS	7687		TECH:				HRS	
AFL	5594		INSP:	LABOR HRS: 1.5	COST: \$0.00		AFL	
320158	INSPECT/CLEAN/LUBRICATE NOSE GEAR RIGHT WHEEL BEARINGS							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --				MOS	
HRS	7687		TECH:				HRS	
AFL	5594		INSP:	LABOR HRS: 1.5	COST: \$0.00		AFL	
320156	INSPECT/CLEAN/LUBRICATE NOSE GEAR LEFT WHEEL BEARINGS							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --				MOS	
HRS	7687		TECH:				HRS	
AFL	5594		INSP:	LABOR HRS: 1.5	COST: \$0.00		AFL	
290143	INSPECT/LUBRICATE NO. 1 HYDRAULIC PUMP NO.1 ENGINE HYDRAULIC PUMP SPLINES							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --				MOS	
HRS	7687		TECH:				HRS	
AFL	5594		INSP:	LABOR HRS: 1	COST: \$0.00		AFL	
290118	CLEAN/CHECK RESERVOIR AIR PRESSURE REGULATOR HYDRAULIC RESERVOIR AIR PRESSURE CHECK VALVE							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --				MOS	
HRS	7687		TECH:				HRS	
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
281150	CHECK OPERATION OF FUEL BOOST PUMPS							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --				MOS	
HRS	7687		TECH:				HRS	
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
270341	CHECK CABLE TENSION AFT FUSELAGE							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --				MOS	
HRS	7687		TECH:				HRS	
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
270335	OPERATIONAL CHECK SPEED BRAKES AND LIFT DUMPERS							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --				MOS	
HRS	7687		TECH:				HRS	
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	
270265	CLEAN/CHECK RIGHT AILERON RIGHT GUIDE ROLLERS							
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00					
MOS	26-JUN-2001		REASON: --				MOS	
HRS	7687		TECH:				HRS	
AFL	5594		INSP:	LABOR HRS: 0	COST: \$0.00		AFL	

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
270264	CLEAN/CHECK LEFT AILERON LEFT GUIDE ROLLERS						
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00				
MOS	26-JUN-2001		REASON: --				MOS
HRS	7687		TECH:				HRS
AFL	5594		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
270263	INSPECT RIGHT AILERON RIGHT EXTERNAL PUSH-PULL TUBE						
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00				
MOS	26-JUN-2001		REASON: --				MOS
HRS	7687		TECH:				HRS
AFL	5594		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
210622	INSPECT 35 DEGREE TEMPERATURE SENSOR 35 DEGREE DUCT SENSOR						
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00				
MOS	26-JUN-2001		REASON: --				MOS
HRS	7687		TECH:				HRS
AFL	5594		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
210112	VISUALLY INSPECT RIGHT BLEED AIR SWITCHING VALVE						
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00				
MOS	26-JUN-2001		REASON: --				MOS
HRS	7687		TECH:				HRS
AFL	5594		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
120150	CHECK PRE-FLIGHT						
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00				
MOS	26-JUN-2001		REASON: --				MOS
HRS	7687		TECH:				HRS
AFL	5594		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
100320	CHECK SERVICE BULLETINS						
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00				
MOS	26-JUN-2001		REASON: --				MOS
HRS	7687		TECH:				HRS
AFL	5594		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
344616	INSPECT EMERGENCY GYRO POWER SUPPLY BATTERY EMERGENCY POWER SUPPLY						
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00				
MOS	26-JUN-2001		REASON: --				MOS
HRS	7687		TECH:				HRS
AFL	5594		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
	Note: PS 823 ONLY						
240181	DEEP CYCLE RIGHT BATTERY						
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00				
MOS	26-JUN-2001		REASON: --				MOS
HRS	7687		TECH:				HRS
AFL	5594		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
	Note: OP 1,2,3						
260169	VISUAL INSPECTION COCKPIT PORTABLE EXTINGUISHER COCKPIT FIRE EXTINGUISHER						
	C/W	WARR	TRANSACTION DATE: 09-JUL-2001 12:00:00				
MOS	26-JUN-2001		REASON: --				MOS
HRS	7687		TECH:				HRS
AFL	5594		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			

Done By: **CAMP SYSTEMS INTERNATIONAL, LLC**

Done By: **CAMP SYSTEMS INTERNATIONAL, LLC**

Done By: **CAMP SYSTEMS INTERNATIONAL, LLC**

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION				COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION			PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
240116	CHANGE NO. 1 STARTER GENERATOR					Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00		Off. 23065-018-1	3684			
MOS	06-NOV-2001	REASON: C - WORN		On:		MOS	0	
HRS	7774	TECH:				HRS	0	
AFL	5641	INSP:		LABOR HRS: 0	COST: \$0.00	AFL	0	
344616	INSPECT EMERGENCY GYRO POWER SUPPLY BATTERY BATTERY/STAND-BY ATTITUDE GYRO			EMERGENCY POWER SUPPLY				
C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00						
MOS	06-NOV-2001	REASON: --				MOS		
HRS	7774	TECH:				HRS		
AFL	5641	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
330228	CHARGE EMERGENCY LIGHT BATTERY							
C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00						
MOS	06-NOV-2001	REASON: --				MOS		
HRS	7774	TECH:				HRS		
AFL	5641	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
240133	INSPECT NO. 2 STARTER GENERATOR SPLINE							
C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00						
MOS	06-NOV-2001	REASON: --				MOS		
HRS	7774	TECH:				HRS		
AFL	5641	INSP:		LABOR HRS: 1	COST: \$0.00	AFL		
240131	CHECK NO. 2 STARTER GENERATOR BRUSH WEAR/TENSION							
C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00						
MOS	06-NOV-2001	REASON: --				MOS		
HRS	7774	TECH:				HRS		
AFL	5641	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
240128	INSPECT NO. 2 STARTER GENERATOR							
C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00						
MOS	06-NOV-2001	REASON: --				MOS		
HRS	7774	TECH:				HRS		
AFL	5641	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		
240123	INSPECT NO. 1 STARTER GENERATOR SPLINE							
C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00						
MOS	06-NOV-2001	REASON: --				MOS		
HRS	7774	TECH:				HRS		
AFL	5641	INSP:		LABOR HRS: 1	COST: \$0.00	AFL		
240121	CHECK NO. 1 STARTER GENERATOR BRUSH WEAR/TENSION							
C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00						
MOS	06-NOV-2001	REASON: --				MOS		
HRS	7774	TECH:				HRS		
AFL	5641	INSP:		LABOR HRS: .5	COST: \$0.00	AFL		
240118	INSPECT NO. 1 STARTER GENERATOR							
C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00						
MOS	06-NOV-2001	REASON: --				MOS		
HRS	7774	TECH:				HRS		
AFL	5641	INSP:		LABOR HRS: 0	COST: \$0.00	AFL		

Serial #: 368 Reg. #: N368MD

Report Date 14-MAR-2002

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
230400	CLEANTEST COCKPIT VOICE RECORDER BEACON						
MOS	CW	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00				
HRS	06-NOV-2001		REASON: --				MOS
AFL	7774		TECH:				HRS
	5641		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
120161	CHECK NO.2 ENGINE PREFLIGHT COMPLETE						
MOS	CW	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00				
HRS	26-JUN-2001		REASON: --				MOS
AFL	7687		TECH:				HRS
	5594		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
120160	CHECK NO.1 ENGINE PREFLIGHT COMPLETE						
MOS	CW	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00				
HRS	26-JUN-2001		REASON: --				MOS
AFL	7687		TECH:				HRS
	5594		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
991855U	AIRWORTHINESS DIRECTIVE AD2001-15-17						
MOS	CW	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00				
HRS	06-NOV-2001		REASON: --				MOS
AFL	7774		TECH:				HRS
	5641		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
2001-03-01	TO PREVENT THE MAIN ENTRY DOOR FROM JAMMING, WHICH COULD IMPEDE THE SAFE EVACUATION OF PASSENGERS AND CREW DURING AN EMERGENCY AIRWORTHINESS DIRECTIVE						
MOS	CW	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00				
MSC			REASON: --				MOS
AFL			TECH:				MSC
			INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
1998-06-10	TO PREVENT FAILURE OF THE HYDRAULIC FUSE TO OPERATE PROPERLY IN THE EVENT OF AN EXTERNAL LEAK DOWNSTREAM OF THE FUSE, WHICH COULD RESULT IN LOSS OF HYDRAULIC SYSTEMS AIRWORTHINESS DIRECTIVE						
MOS	CW	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00				
HRS	06-NOV-2001		REASON: --				MOS
AFL	7774		TECH:				HRS
	5641		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
911380	ASB1124-54A-138 SERVICE BULLETIN						
MOS	CW	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00				
MSC			REASON: --				MOS
AFL	0		TECH:				MSC
			INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			
780636	CLEAN/LUBRICATE NO. 2 THROTTLE RETARDER FEEDBACK CONTROL ASSEMBLY NO.2 THROTTLE RETARDER CABLE AND CASING						
MOS	CW	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00				
HRS	06-NOV-2001		REASON: --				MOS
AFL	7774		TECH:				HRS
	5641		INSP:				AFL
			LABOR HRS: 0	COST: \$0.00			

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
780136	CLEAN/LUBRICATE NO. 1 THROTTLE RETARDER FEEDBACK CONTROL ASSEMBLY NO.1 THROTTLE RETARDER CABLE AND CASING						
	C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00				
MOS	06-NOV-2001		REASON: --				MOS
HRS	7774		TECH:				HRS
AFL	5641		LABOR HRS: 0	COST: \$0.00			AFL
300165	REPLACE WIPER BLADE ELEMENT						
	NOTE: IT IS RECOMMENDED TO REPLACE WIPER BLADE ELEMENT EVERY 6 MONTHS OR 250 HOURS.						
	C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00				
MOS	06-NOV-2001		REASON: --				MOS
HRS	7774		TECH:				HRS
AFL	5641		LABOR HRS: 0	COST: \$0.00			AFL
260182	DISCHARGE CABIN PORTABLE EXTINGUISHER /VALVE OVERHAUL AND REFILL CABIN FIRE EXINGUISHER						
	C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00				
MOS	06-NOV-2001		REASON: --				MOS
HRS	7774		TECH:				HRS
AFL	5641		LABOR HRS: 0	COST: \$0.00			AFL
260180	VISUAL INSPECTION CABIN PORTABLE EXTINGUISHER CABIN FIRE EXTINGUISHER						
	C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00				
DAYS	06-NOV-2001		REASON: --				DAYS
HRS	7774		TECH:				HRS
AFL	5641		LABOR HRS: 0	COST: \$0.00			AFL
260172	DISCHARGE COCKPIT PORTABLE EXTINGUISHER /VALVE OVERHAUL AND REFILL COCKPIT FIRE EXTINGUISHER						
	C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00				
MOS	06-NOV-2001		REASON: --				MOS
HRS	7774		TECH:				HRS
AFL	5641		LABOR HRS: 0	COST: \$0.00			AFL
260169	VISUAL INSPECTION COCKPIT PORTABLE EXTINGUISHER COCKPIT FIRE EXTINGUISHER						
	C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00				
DAYS	06-NOV-2001		REASON: --				DAYS
HRS	7774		TECH:				HRS
AFL	5641		LABOR HRS: 0	COST: \$0.00			AFL
260121	HYDROSTATIC TEST LEFT FIRE EXTINGUISHER						
	C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00				
MOS	06-NOV-2001		REASON: --				MOS
HRS	7774		TECH:				HRS
AFL	5641		LABOR HRS: 0	COST: \$0.00			AFL
250162	INSPECT FIRST AID KIT						
	C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00				
MOS	06-NOV-2001		REASON: --				MOS
HRS	7774		TECH:				HRS
AFL	5641		LABOR HRS: 0	COST: \$0.00			AFL

Serial #: 368 Reg. #: N368MD

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

Model: 1124A WESTWIND

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
250156	INSPECT LIFE PRESERVERS						
C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00					
MOS	06-NOV-2001	REASON: --					MOS
HRS	7774	TECH:					HRS
AFL	5641	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
240181	DEEP CYCLE RIGHT BATTERY						
C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00					
MOS	06-NOV-2001	REASON: --					MOS
HRS	7774	TECH:					HRS
AFL	5641	INSP:	LABOR HRS: 2	COST: \$0.00			AFL
240166	DEEP CYCLELEFT BATTERY						
C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00					
MOS	06-NOV-2001	REASON: --					MOS
HRS	7774	TECH:					HRS
AFL	5641	INSP:	LABOR HRS: 2	COST: \$0.00			AFL
240128	INSPECT NO. 2 STARTER GENERATOR						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00					
MOS	26-JUN-2001	REASON: --					MOS
HRS	7687	TECH:					HRS
AFL	5594	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 5,7							
240123	INSPECT NO. 1 STARTER GENERATOR SPLINE						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00					
MOS	26-JUN-2001	REASON: --					MOS
HRS	7687	TECH:					HRS
AFL	5594	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 4,6							
240118	INSPECT NO. 1 STARTER GENERATOR						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00					
MOS	26-JUN-2001	REASON: --					MOS
HRS	7687	TECH:					HRS
AFL	5594	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 4,6							
240133	INSPECT NO. 2 STARTER GENERATOR SPLINE						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00					
MOS	26-JUN-2001	REASON: --					MOS
HRS	7687	TECH:					HRS
AFL	5594	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 5,7							
240131	CHECK NO. 2 STARTER GENERATOR BRUSH WEAR/TENSION						Done By: CAMP SYSTEMS INTERNATIONAL, LLC
C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00					
MOS	26-JUN-2001	REASON: --					MOS
HRS	7687	TECH:					HRS
AFL	5594	INSP:	LABOR HRS: 0	COST: \$0.00			AFL
Note: OP 5,7							



AIRCRAFT Updates Report

Serial #: 368 Reg. #: N368MD
Model: 1124A WESTWIND

Report Date **14-MAR-2002**

From Date :

To Date : 03/14/2002

UPDATE INFORMATION			COMPONENT INFORMATION		COMPONENT TIME AT INSTALLATION		
ITEM NO DATE	DESCRIPTION		PART NUMBER	SERIAL NUMBER	TSN	TSO	TSR
240126	CHANGE NO. 2 STARTER GENERATOR				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00	Off: 23065-018-1	2562			
MOS	06-NOV-2001	REASON: C - WORN	On:		MOS	0	
HRS	7774	TECH:			HRS	0	
AFL	5641	INSP:	LABOR HRS: 0	COST: \$0.00	AFL	0	
240121	CHECK NO. 1 STARTER GENERATOR BRUSH WEAR/TENSION				Done By: CAMP SYSTEMS INTERNATIONAL, LLC		
C/W	WARR	TRANSACTION DATE: 15-NOV-2001 12:00:00					
MOS	26-JUN-2001	REASON: --			MOS		
HRS	7687	TECH:			HRS		
AFL	5594	INSP:	LABOR HRS: 0	COST: \$0.00	AFL		
Note: OP 4,6							