



CAMP SYSTEMS INTERNATIONAL, LLC
LONG ISLAND MAC ARTHUR AIRPORT
999 MARCONI AVE.
RONKONKOMA, NY 11779

POSTAL

R&S AIRCRAFT INVESTMENTS, LLC
ATTN: YANDELL ROGERS III
P.O. BOX 43
HOUSTON, TX 77001-0043



PLEASE FILL IN THE INFORMATION REQUESTED BELOW AND RETURN CARD TO
CAMP SYSTEMS, INT'L.

1124 WESTWIND 368

AIRCRAFT MODEL _____

Y 05/02 UNITED STATES OF AMERICA _____

RECORD PRESENT:

AIRCRAFT HOURS _____

LANDINGS _____

NO. 1 ENG. HOURS _____

CYCLES _____

NO. 2 ENG. HOURS _____

CYCLES _____

NO. 3 ENG. HOURS _____

CYCLES _____

NO. 4 ENG. HOURS _____

CYCLES _____

APU HOURS _____

STARTS _____

DATE _____

OWNER: R&S AIRCRAFT INVESTMENTS, LLC
ADDRESS: P.O. BOX 43 HOUSTON TX 77001-0043

PHONE: 713-830-9584
FAX: 713-918-5925

OPERATOR: R&S AIRCRAFT INVESTMENTS, LLC
ADDRESS: P.O. BOX 43 HOUSTON TX 77001-0043

PHONE: 713-830-9584
FAX: 713-918-5925

AIRCRAFT

S/N: 368 **REG NO:** N368MD **MODEL:** 1124A WESTWIND **MANUFACTURER:** GULFSTREAM AEROSPACE CORPORATION

NOTE:
INSPECTION PROGRAM: 3
CERTIFICATE DATE: 11-FEB-1982

UOM	LAST ACTUAL	LAST ACTUAL DATE
HRS	7806	28-FEB-2002
AFL	5706	28-FEB-2002

ENGINE NO. 1

S/N: P-77482 **PART NO:** 3072500-2 **MODEL:** TFE731-3 **MANUFACTURER:** HONEYWELL

INSTALLED DATE: 4/3/1989
A/C HRS: 4215
ENGINE HRS: 3972
ENGINE CYCLES: 2456

UOM	LAST ACTUAL	LAST ACTUAL DATE
HRS	7806	28-FEB-2002
ENC	0	
(AFL)	5706	28-FEB-2002

ENGINE NO. 2

S/N: P77488 **PART NO:** 3072500-2 **MODEL:** TFE731-3 **MANUFACTURER:** HONEYWELL

INSTALLED DATE: 5/31/1993
A/C HRS: 5278
ENGINE HRS: 5227
ENGINE CYCLES: 3867

UOM	LAST ACTUAL	LAST ACTUAL DATE
HRS	7806	28-FEB-2002
ENC	0	
(AFL)	5706	28-FEB-2002

Aircraft Model - 1124 WESTWIND

Report Date **11-APR-2002**

Owner Name **R&S AIRCRAFT INVESTMENTS, LLC**
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PKG NUMBER	UNIT	ACT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
AIRCRAFT									
CHAPTER 05	TIME LIMITS/MAINTENANCE CHECKS								
+ 050150U	200 HOUR INSPECTION								
	PKG 1 in PKG 2, 3	MOS	R				26-JUN-2001		
		HRS/MSC		200			7687	7887	31
	REF:	AFL					5594		
+ 050300U	400/200 HOUR INSPECTION						26-JUN-2001		
	PKG 2 in PKG 3	MOS	R				26-JUN-2001		
		HRS/MSC		400			7687	8087	45.5
	REF:	AFL					5594		
+ 050600U	800/400/200 HOUR INSPECT						26-JUL-2000		
	PKG 3	MOS	R				26-JUL-2000		
		HRS/MSC		800		-38	7325	8087	45.5
	REF:	AFL					5360		
+ 057110U	150HR #1 ENGINE INSP NO. 1								E1
	PKG 4	MOS					26-JUN-2001		
		HRS/MSC		150			7687		1.5
	REF:	AFL					5594		
+ 057110U	150HR #2 ENGINE INSP NO. 2								E2
	PKG 5	MOS					26-JUN-2001		
		HRS/MSC		150			7687		1
	REF:	AFL					5594		
+ 057120U	300HR #1 ENGINE INSP NO. 1								E1
	PKG 6	MOS					16-FEB-2001		
		HRS/MSC		300			7551		
	REF:	AFL					5515		
+ 057120U	300HR #2 ENGINE INSP NO. 2								E2
	PKG 7	MOS					16-FEB-2001		
		HRS/MSC		300			7551		
	REF:	AFL					5515		

Engine Model- TFE731-3

Report Date **11-APR-2002**

Owner Name R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PKG NUMBER	UNIT	ACT	INTERVAL	TIME-----AT-----INSTALLATION	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
					TSN TSO TSR TSI ADJ	Warr Exp		
ENGINE NO. 1								
CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS								
+ 057110U	NO. 1 ENGINE - 150HR #1 ENGINE INSP							
	PKG 4 in PKG 4, 6, 6	MOS					26-JUN-2001	
	REF:	HRS/MS	150				7687	7837 1
		ENC					5594	
		(AFL)						
+ 057120U	NO. 1 ENGINE - 300HR #1 ENGINE INSP							
	PKG 6 in PKG 6	MOS					18-FEB-2001	
	REF:	HRS/MS	300				7551	7851 1.5
		ENC					5515	
		(AFL)						

Engine Model - TFE731-3

Report Date **11-APR-2002**

Owner Name **R&S AIRCRAFT INVESTMENTS, LLC**
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PKG NUMBER	UNIT	ACT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
ENGINE NO. 2									
CHAPTER 05	TIME LIMITS/MAINTENANCE CHECKS								
+ 057110U	NO. 2 ENGINE - 150 HR #2 ENGINE INSP PKG 5 in PKG 5, 7, 7	MOS HRS/MS ENC (AFL)		150			26-JUN-2001 7687	7837	1
	REF:						5594		
+ 057120U	NO. 2 ENGINE - 300 HR #2 ENGINE INSP PKG 7 in PKG 7	MOS HRS/MS ENC (AFL)		300			16-FEB-2001 7551	7851	1.5
	REF:						5515		

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
AIRCRAFT								
CHAPTER 00 INFORMATION								
000004U	-- ICON HEALTH AND FITNESS	MOS					11-FEB-1982	
		HRSMSC	N/R			0		
	REF:	AFL				0		
CHAPTER 10 PARKING, MOORING, STORE AND RET TO SERV								
+ 100310	CHECK AIRWORTHY DIRECTIVES	MOS					26-JUN-2001	
10.010	PKG 1, 2, 3	HRSMSC	200			7687		
	REF: NO REF	AFL				5594		
+ 100320	CHECK SERVICE BULLETINS	MOS					26-JUN-2001	
10.020	PKG 1, 2, 3	HRSMSC	200			7687		
	REF: NO REF	AFL				5594		
+ 100330	CHECK SERVICE LETTERS	MOS					26-JUN-2001	
10.030	PKG 1, 2, 3	HRSMSC	200			7687		
	REF: NO REF	AFL				5594		
CHAPTER 12 SERVICING								
+ 120160	CHECK NO.1 ENGINE PREFLIGHT COMPLETE							E1
12.020	PKG 4	MOS					26-JUN-2001	
	REF: AMM 5-21-00	HRSMSC	150			7687		
		AFL				5594		
+ 120161	CHECK NO.2 ENGINE PREFLIGHT COMPLETE							E2
12.020	PKG 5	MOS					26-JUN-2001	
	REF: AMM 5-21-00	HRSMSC	150			7687		
		AFL				5594		
+ 120150	CHECK PRE-FLIGHT							
12.010	PKG 1, 2, 3	MOS					26-JUN-2001	
	REF: AMM 5-30-00	HRSMSC	200			7687		
		AFL				5594		
CHAPTER 21 AIR CONDITIONING								
210280	CHECK BLEED AIR DUCT OVERPRESSURE SWITCH							F3
21.270	PKG 3	MOS					26-JUL-2000	
	REF: AMM 21-00-00	HRSMSC	800			7325		
		AFL				5360		
+ 210276	OPERATIONAL CHECK PRESSURIZATION SWITCHES AND VALVES							F3
21.030	PKG 2, 3	MOS					26-JUN-2001	
	REF: AMM 21-00-00	HRSMSC	400			7687		
		AFL				5594		
210641	ANTICIPATOR, TEMPERATURE SENSOR							F4
21.310	548486-1	MOS					11-FEB-1982	
	SN-UNKNOWN	HRSMSC	O/C	0		0		
	REF: AMM 21-60-00	AFL				0		

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
210673		ASPIRATOR, ENVIRONMENTAL CONTROL SYSTEM							F5
	21.430	PN	MOS					11-FEB-1982	
		SN-UNKNOWN	HRSMSC	O/C	0		0		
		REF: AMM 21-50-00	AFL				0		
210661		BULB, CABIN TEMPERATURE INDICATOR SENSOR							F4
	21.350	PN	MOS					11-FEB-1982	
		SN-UNKNOWN	HRSMSC	O/C	0		0		
		REF: AMM 21-60-00	AFL				0		
210626		CONTROL BOX, CABIN TEMPERATURE							F4
	21.450	548482-5	MOS					11-FEB-1982	
		030C154	HRSMSC	O/C	0		0		
		REF: AMM 21-60-00	AFL				0		
210118		CONTROL UNIT, BLEED AIR CONTROL RIGHT							F5
	21.360	3213894-4-1	MOS			0		06-NOV-1990	
		P402C	HRSMSC	O/C		0	4731		
		REF: NO REF	AFL			0	3324		
210108		CONTROL UNIT, BLEED AIR LEFT							F5
	21.360	32131894-4-1	MOS					06-NOV-1990	
		P336C	HRSMSC	O/C			4731		
		REF: NO REF	AFL				3324		
210176		CONTROLLER, CABIN AIR PRESSURE							F3
	21.180	130398-3	MOS					11-FEB-1982	\$1455.
		31340	HRSMSC	O/C	0		0		3
		REF: AMM 21-30-00	AFL				0		
210178		CLEAN FILTER							F3
	21.480	PKG 3	MOS					26-JUL-2000	
			HRSMSC	800			7325		
		REF: AMM 21-30-00	AFL				5360		
210606		EXCHANGER, REFRIGERATION UNIT HEAT							F5
	21.240	PN	MOS					11-FEB-1982	
		SN-UNKNOWN	HRSMSC	O/C	0		0		20
		REF: AMM 21-50-00	AFL				0		
210636		FAN, CABIN TEMPERATURE							F4
	21.300	5783661-5	MOS					04-APR-1996	\$302.
		120713	HRSMSC	O/C			5747		
		REF: AMM 21-60-00	AFL				4430		
210206		INDICATOR, CABIN ALTITUDE/PRESSURE							F3
	21.390	4883747-1	MOS					11-FEB-1982	
		495	HRSMSC	O/C	0		0		
		REF: AMM 21-31-00	AFL				0		
210208		INDICATOR, CABIN RATE-OF-CLIMB							F3
	21.400	4883788	MOS					11-FEB-1982	
		SN-UNKNOWN	HRSMSC	O/C	0		0		
		REF: AMM 21-31-00	AFL				0		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
210633	INDICATOR, CABIN TEMPERATURE							F3
21.410	883767-501	MOS					11-FEB-1982	
	197	HRS/MS	O/C	0		0		
	REF: AMM 21-60-00	AFL				0		
210156	PLENUM, MIXING							F4
21.160	5-783584-1	MOS					11-FEB-1982	
	SN-UNKNOWN	HRS/MS	O/C	0		0		
	REF: NO REF	AFL				0		
210241	REGULATOR, ABSOLUTE AIR PRESSURE LOWER							F3
21.200	102466-1	MOS					11-FEB-1982	
	1203419	HRS/MS	O/C	0		0		4
	REF: AMM 21-30-00	AFL				0		
210221	REPLACE LOWER INLET AIR FILTER ELEMENT							F3
21.080	PKG 3	MOS					26-JUL-2000	
	1203419	HRS/MS	800			7325		
	REF: AMM 21-30-00	AFL				5360		
210236	REGULATOR, ABSOLUTE AIR PRESSURE UPPER							F3
21.200	102466-1	MOS					11-FEB-1982	
	313613	HRS/MS	O/C	0		0		4
	REF: AMM 21-30-00	AFL				0		
210621	REGULATOR, PNEUMATIC PRESSURE							F5
21.280	PN	MOS					11-FEB-1982	
	SN-UNKNOWN	HRS/MS	O/C	0		0		
	REF: AMM 21-50-00	AFL				0		
210246	RELAY, PNEUMATIC							F3
21.210	107312-2	MOS					22-OCT-1982	\$383.
	11-9440	HRS/MS	O/C	0		482		4
	REF: AMM 21-30-00	AFL						
210619	SENSOR, 35 DEGREE TEMPERATURE							F5
21.420	783649-1	MOS					11-FEB-1982	
	071C730	HRS/MS	O/C	0		0		
	REF: AMM 21-50-00	AFL				0		
+ 210622	INSPECT 35 DEGREE DUCT SENSOR							F5
21.420	PKG 1, 2, 3	MOS					26-JUN-2001	
		HRS/MS	200			7687		
	REF: AMM 21-50-00	AFL				5594		
210631	SENSOR, CABIN TEMPERATURE							F4
21.460	548484-1	MOS					11-FEB-1982	
	070C482	HRS/MS	O/C	0		0		
	REF: AMM 21-60-00	AFL				0		
210646	SENSOR, HIGH TEMPERATURE							F4
21.320	627962-2	MOS					11-FEB-1982	
	011C955	HRS/MS	O/C	0		0		
	REF: AMM 21-60-00	AFL				0		

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
210665		SENSOR, REFRIGERATION TEMPERATURE CONTROL							F3
	21.440	3783649-1	MOS				03-NOV-1984		
		11166	HRSMSC	O/C	0		2044		
		REF: NO REF	AFL						
210666		SEPARATOR, WATER							F5
	21.050	179510-1	MOS				11-FEB-1982		
		31535	HRSMSC	O/C	0		0		
		REF: AMM 21-70-00	AFL				0		
+	210671	CLEAN/REPLACE CONDENSER/FILTER							F5
	21.050	PKG 1, 2, 3	MOS				26-JUN-2001		
			HRSMSC	200			7687	1	
		REF: AMM 21-70-00	AFL				5594		
210286		SWITCH, CABIN AIR SELECTOR							F3
	21.380	823073-501	MOS				11-FEB-1982		
		8128133	HRSMSC	O/C	0		0		
		REF: NO REF	AFL		0		0		
210656		SWITCH, OVERPRESSURE							F5
	21.340	3-783646-2	MOS				11-FEB-1982		
		194	HRSMSC	O/C	0		0		
		REF: AMM 21-60-00	AFL				0		
210651		SWITCH, OVERTEMPERATURE							F4
	21.330	3-783645-1	MOS				11-FEB-1982		
		211	HRSMSC	O/C	0		0		
		REF: AMM 21-60-00	AFL				0		
210623		TANK, AUXILIARY ENVIRONMENTAL CONTROL SYSTEM VOLUME							F2
	21.440	131358-1	MOS				11-FEB-1982		
		311533	HRSMSC	O/C	0		0		
		REF: NO REF	AFL				0		
210677		TURBINE, COOLING							F5
	21.290	572375-2	MOS				15-MAR-1995		
		56-133	HRSMSC	O/C	0		5585		
		REF: AMM 21-50-00	AFL				4260		
210681		CHANGE OIL							F5
	21.290	PKG 1, 2, 3	MOS				26-JUN-2001		
			HRSMSC	200			7687		
		REF: AMM 21-50-00	AFL				5594		
210601		UNIT, REFRIGERATION							F5
	21.230	3783648-1	MOS				21-AUG-1983		
		120-333	HRSMSC	O/C	0		1200		
		REF: AMM 21-50-00	AFL				667		
210616		VALVE, 35 DEGREE TEMPERATURE CONTROL							F5
	21.260	898730-1	MOS				11-FEB-1982		
		SN-UNKNOWN	HRSMSC	O/C	0		0		
		REF: AMM 21-50-00	AFL				0		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND
Report Date 11-APR-2002
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
210121	VALVE, AIR CONDITIONING PRESSURE RELIEF											F5
21.060	3-783644-1	MOS								11-FEB-1982		
	162	HRS/MS	O/C	0						0		
	REF: AMM 21-11-00	AFL								0		
210101	VALVE, BLEED AIR SWITCHING LEFT											F5
21.010	3783647-3	MOS								11-FEB-1982		\$1698.
	P511	HRS/MS	O/C	0						0		
	REF: AMM 21-11-00	AFL								0		
+ 210102	VISUALLY INSPECT											F5
21.500	PKG 2, 3	MOS								26-JUN-2001		
		HRS/MS	400							7687		
	REF: AMM 5-20-05	AFL								5594		
210111	VALVE, BLEED AIR SWITCHING RIGHT											F5
21.010	3783647-3	MOS								11-FEB-1982		\$1698.
	P506	HRS/MS	O/C	0						0		
	REF: AMM 21-11-00	AFL								0		
+ 210112	VISUALLY INSPECT											F5
21.500	PKG 2, 3	MOS								26-JUN-2001		
		HRS/MS	400							7687		
	REF: AMM 5-20-05	AFL								5594		
210146	VALVE, CABIN AIR CHECK LEFT											F4
21.130	PN	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0						0		
	REF: AMM 21-20-00	AFL								0		
210151	VALVE, CABIN AIR CHECK RIGHT											F4
21.130	PN	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0						0		
	REF: AMM 21-20-00	AFL								0		
210153	VALVE, COLD AIR CHECK											F5
21.370	PN	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0						0		
	REF: AMM 21-20-00	AFL								0		
210166	VALVE, CONDITION AIR PILOT											F3
21.150	PN	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0						0		
	REF: AMM 21-20-00	AFL								0		
210143	VALVE, EMERGENCY AIR CHECK											F5
21.470	PN	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0						0		
	REF: NO REF	AFL								0		
210141	VALVE, EMERGENCY AIR SHUTOFF											F5
21.120	321760-2-1	MOS								11-FEB-1982		\$1099.
	P1222	HRS/MS	O/C	0						0		
	REF: AMM 21-14-00	AFL								0		

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT----- TSN TSO TSR TSI ADJ	INSTALLATION	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
210161	VALVE, FLOOD DUCT								F4
21.140	PN	MOS					11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C	0			0		
	REF: AMM 21-20-00	AFL					0		
210136	VALVE, GROUND BY-PASS								F5
21.110	4-783622-1	MOS					11-FEB-1982		\$1099.
	P4380	HRS/MSC	O/C	0			0		
	REF: AMM 21-13-00	AFL					0		
210211	REPLACE UPPER INLET AIR FILTER ELEMENT								F3
21.080	PKG 3	MOS					26-JUL-2000		
		HRS/MSC	800				7325		
	REF: AMM 21-30-00	AFL					5360		
210611	VALVE, HOT AIR								F5
21.250	321760-2-1	MOS					11-FEB-1982		\$1099.
	P1108	HRS/MSC	O/C	0			0		
	REF: AMM 21-60-00	AFL					0		
210158	VALVE, HOT AIR CHECK								F4
21.380	PN	MOS					11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C	0			0		
	REF: NO REF	AFL					0		
210226	VALVE, ISOBARIC SHUTOFF								F3
21.070	3-783105	MOS					11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C	0			0		
	REF: AMM 21-30-00	AFL					0		
210171	VALVE, MANUAL DEFOG								F3
21.170	PN	MOS					11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C	0			0		
	REF: AMM 21-20-00	AFL					0		
210181	VALVE, MANUAL DUMP								F3
21.190	5-723018-401	MOS					11-FEB-1982		
	21563	HRS/MSC	O/C	0			0		
	REF: AMM 21-30-00	AFL					0		
210186	VALVE, NORMAL OUTFLOW								F4
21.040	130374-6	MOS					11-FEB-1982		
	110870	HRS/MSC	O/C	0			0		
	REF: AMM 21-30-00	AFL					0		
210256	VALVE, PRESSURE SOLENOID LOWER								F3
21.220	3783686	MOS					11-FEB-1982		
	175	HRS/MSC	O/C	0			0		
	REF: AMM 21-30-00	AFL					0		
210251	VALVE, PRESSURE SOLENOID UPPER								F3
21.220	3783686	MOS					11-FEB-1982		
	214	HRS/MSC	O/C	0			0		
	REF: AMM 21-30-00	AFL					0		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date **11-APR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
210131	VALVE, RAM AIR SHUTOFF											F5
21.100	398712-1-1	MOS								11-FEB-1982		
	P222	HRS/MS	O/C	0						0		
	REF: AMM 21-12-00	AFL								0		
210196	VALVE, SAFETY OUTFLOW											F4
21.040	103278-8	MOS								11-FEB-1982		
	11905	HRS/MS	O/C	0						0		
	REF: AMM 21-30-00	AFL								0		
210261	VENTURI, AIRFLOW											F3
21.160	131052-1	MOS								11-FEB-1982		
	703075	HRS/MS	O/C	0						0		
	REF: NO REF	AFL								0		
210266	INSPECT/CLEAN SCREEN											F3
21.090		MOS								11-FEB-1982		
		HRS/MS	O/C							0		
	REF: NO REF	AFL								0		
CHAPTER 22 AUTO FLIGHT												
220166	AMPLIFIER, NO.1 AUTOPILOT SERVO											F3
22.020	622-3108-016	MOS								27-AUG-1996		
	2120LNR	HRS/MS	O/C									1
	REF: AMM 22-10-03	AFL										F3
220156	COMPUTER, AUTO PILOT											F3
22.050	522-2901-016	MOS								15-FEB-1995		
	2198	HRS/MS	O/C			4165				5554		
	REF: AMM 22-13-13	AFL				3382				4242		
220163	COMPUTER, AUTOPILOT YAW DAMPER											F3
22.040	622-3167-028	MOS								11-FEB-1982		
	4078	HRS/MS	O/C	0						0		
	REF: AMM 22-10-05	AFL								0		
221021	CONTROLLER, AIR DATA NO. 1											F3
22.030	590A-3J	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0						0		
	REF: AMM 22-10-04	AFL								0		
+ 340146	LEAK CHECK LEFT STATIC SYSTEM										MANDATORY	F1
34.050		MOS	24							18-JAN-2001	18-JAN-2003	
ASSOCIATED		HRS/MS								7494		
	REF: AMM 34-10-01	AFL								5466		
+ 340151	LEAK CHECK RIGHT STATIC SYSTEM										MANDATORY	F1
34.050		MOS	24							18-JAN-2001	18-JAN-2003	
ASSOCIATED		HRS/MS								7494		
	REF: AMM 34-10-01	AFL								5466		
221031	CONTROLLER, AIR DATA NO. 2											F3
22.030	590A-3J1	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0						0		
	REF: AMM 22-10-04	AFL								0		

Aircraft Model - 1124 WESTWIND

Report Date **11-APR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT----- TSN TSO TSR TSI ADJ	INSTALLATION	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
+ 340146	LEAK CHECK LEFT STATIC SYSTEM							MANDATORY	F1
34.050		MOS	24				18-JAN-2001	18-JAN-2003	
ASSOCIATED		HRS/MS					7494		
	REF: AMM 34-10-01	AFL					5466		
+ 340151	LEAK CHECK RIGHT STATIC SYSTEM							MANDATORY	F1
34.050		MOS	24				18-JAN-2001	18-JAN-2003	
ASSOCIATED		HRS/MS					7494		
	REF: AMM 34-10-01	AFL					5466		
222001	CONTROLLER, ALTITUDE PRESELECT								F3
22.090	622-2923-066	MOS					11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0			0		
	REF: NO REF	AFL		0			0		
220161	CONTROLLER, AUTOPILOT								F3
22.010	792-6348-002	MOS					11-FEB-1982		
	2759	HRS/MS	O/C	0			0		1
	REF: AMM 22-10-02	AFL					0		
220181	MOUNT, AUTOPILOT AILERON SERVO								F5
22.080	792-6783-001	MOS					11-FEB-1982		
	1191	HRS/MS	O/C	0			0		
	REF:	AFL					0		
220191	MOUNT, AUTOPILOT ELEVATOR SERVO								F5
22.080	792-6783-001	MOS					11-FEB-1982		
	1160	HRS/MS	O/C	0			0		
	REF:	AFL					0		
220201	MOUNT, AUTOPILOT RUDDER SERVO								F5
22.080	792-6783-001	MOS					11-FEB-1982		
	1166	HRS/MS	O/C	0			0		
	REF:	AFL					0		
220150	PANEL, AUTOPILOT								F3
22.060	622-0141-023	MOS					11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C				0		
	REF: AMM 22-11-02	AFL					0		
220176	SERVO, AUTOPILOT AILERON								F5
22.070	792-6781-001	MOS					15-FEB-1995		
	726	HRS/MS	O/C		5554		5554		
	REF: AMM 22-10-06(1124),22-11-07(1124A)	AFL			4242		4242		
220186	SERVO, AUTOPILOT ELEVATOR								F5
22.070	792-6781-001	MOS					15-FEB-1995		
	791	HRS/MS	O/C		5554		5554		
	REF: AMM 22-10-06(1124),22-11-07(1124A)	AFL			4242		4242		
220196	SERVO, AUTOPILOT RUDDER								F5
22.070	792-6781-001	MOS					11-FEB-1982		
	3915	HRS/MS	O/C	0			0		
	REF: AMM 22-10-06(1124),22-11-07(1124A)	AFL					0		
CHAPTER 23 COMMUNICATIONS									

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
230450U	-- REPLACE BEACON BATTERY	MOS				17-OCT-1998	?	
		HRS/MS				6520		
		AFL				4889		
+ 230218	INSPECT/CHECK STATIC DISCHARGE WICK RESISTANCE							F1
23.120	PKG 2, 3	MOS				26-JUN-2001		
		HRS/MS	400			7687		
	REF: AMM 23-60-00	AFL				5594		
230166	RENEW FCC RADIO/TELEPHONE LICENSE							F3
23.100		MOS	60			27-OCT-1999	27-OCT-2004	
		HRS/MS				6961		
	REF: See Workcard	AFL				5135		
238004U	-- INTERCOM, COPILOTS NAT LTD							
	AA80-020	MOS				15-APR-1993		
	9688	HRS/MS	O/C			5252		
	REF:	AFL				3907		
238006U	-- INTERCOM, PILOTS NAT LTD.							
	AA80020	MOS				15-APR-1993		
	9689	HRS/MS	O/C	0		5252		
	REF:	AFL				3907		
230111	AMPLIFIER, HF POWER							F3
23.030	622-2883-001	MOS				26-SEP-1995		
	1033	HRS/MS	O/C			5707		
	REF: AMM REF BELOW	AFL				4380		
230156	ANTENNA, RADIO/TELEPHONE							F1
23.110	121-0011-000	MOS				11-FEB-1982		
	3272	HRS/MS	O/C	0		0		
	REF: AMM 23-21-00	AFL				0		
230136	ANTENNA, VHF BLADE							F1
23.070	DMC-81-1	MOS				11-FEB-1982		
	387	HRS/MS	O/C	0		0		
	REF: AMM 23-20-00	AFL				0		
230131	ANTENNA, VHF FIN CAP							F1
23.060	VFS-10-90-2	MOS				11-FEB-1982		
	866	HRS/MS	O/C	0		0		5
	REF: AMM 23-20-00	AFL				0		
230399	BEACON, VOICE RECORDER							T1
23.130	DK-100	MOS				09-NOV-1996		
	DL4928	HRS/MS	O/C			5951		
	REF: NO REF	AFL				4589		
230171	CONTROL, COMMUNICATION 1							F3
23.140	622-4523-011	MOS				09-JAN-1986		
	SN-UNKNOWN	HRS/MS	O/C	0		2812		
	REF: NO REF	AFL		0		1743		

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
230181	CONTROL, COMMUNICATION 2										F3
23.140	622-4523-003	MOS							09-JAN-1986		
	SN-UNKNOWN	HRS/MS	O/C	0					2812		
	REF: NO REF	AFL		0					1743		
230196	CONTROL, NO.1 AUDIO CENTER										F3
23.150	522-3763-001	MOS							11-FEB-1982		
	3747	HRS/MS	O/C	0					0		
	REF: AMM 23-50-00	AFL							0		
230201	CONTROL, NO.2 AUDIO CENTER										F3
23.150	522-3763-001	MOS							11-FEB-1982		
	3749	HRS/MS	O/C	0					0		
	REF: AMM 23-50-00	AFL							0		
230116	COUPLER, HF ANTENNA										F3
23.040	622-2884-001	MOS							16-AUG-1995		
	2427	HRS/MS	O/C	5702					5702		
	REF: AMM REF BELOW	AFL		4372					4372		
230101	PANEL, HF CONTROL										F3
23.010	622-4545-001	MOS							11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0					0		
	REF: AMM REF BELOW	AFL							0		
230106	RECEIVER/EXCITER, HF										F3
23.020	622-5337-001	MOS							26-SEP-1995		
	1554	HRS/MS	O/C						5707		
	REF: AMM REF BELOW	AFL							4380		
230151	RECEIVER/TRANSMITTER, RADIO/TELEPHONE										F3
23.100	400-0033-000	MOS							29-JUL-1994		
	603	HRS/MS	O/C						5472		
	REF: AMM 23-21-00	AFL							4150		
230206	RECORDER, COCKPIT VOICE										T1
23.130	89094-003111	MOS							16-AUG-1995		
	A01001	HRS/MS	O/C						5702		
	REF: NO REF	AFL							4372		
230400	CLEAN/TEST BEACON										T1
23.130		MOS	6						06-NOV-2001	06-MAY-2002	
		HRS/MS							7774		
	REF: NO REF	AFL							5641		
230207	REPLACE BATTERY										T1
23.130		MOS							17-OCT-1998	?	
		HRS/MS							6520		
	REF: NO REF	AFL							4889		
230121	TRANSCIVER, VHF NO. 1										F3
23.050	622-1334-002	MOS							24-JUN-1991		
	4589	HRS/MS	O/C					0	4880		
	REF: AMM 23-20-00	AFL							3495		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
230126	TRANSCIVER, VHF NO. 2							F3
23.050	622-1879-002	MOS		0		28-MAY-1991		
	16718	HRS/MS	O/C	0		4877		
	REF: AMM 23-20-00	AFL		0		3493		
230146	UNIT, RADIO/TELEPHONE CABIN							F4
23.090	400-0030-004	MOS				06-FEB-1989		
	77790	HRS/MS	O/C	0		4149		
	REF: AMM 23-21-00	AFL				2658		
230141	UNIT, RADIO/TELEPHONE COCKPIT							F3
23.080	400-0032-002	MOS				11-FEB-1982		
	2506	HRS/MS	O/C	0		0		
	REF: AMM 23-21-00	AFL				0		
230191	UNIT, UHF COMMUNICATION REMOTE DISPLAY							F3
23.140	622-1945-011	MOS				11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0		0		
	REF: NO REF	AFL		0		0		
CHAPTER 24 ELECTRICAL POWER								
+ 241653	CHECK CIRCUIT BREAKER RESISTANCE/INSPECT BUS							F3
24.140	PKG 3	MOS				26-JUL-2000		
		HRS/MS	800			7325		
	REF: AMM 24-50-00	AFL				5360		
+ 241655	INSPECT DISTRIBUTION BUS CIRCUIT BREAKER							F3
24.150	PKG 3	MOS				26-JUL-2000		
		HRS/MS	800			7325		
	REF: AMM 24-50-00	AFL				5360		
+ 241657	INSPECT TEST PRIORITY BUS DIODES							F3
24.160	PKG 3	MOS				26-JUL-2000		
		HRS/MS	800			7325		
	REF: AMM 24-50-00	AFL				5360		
240156	BATTERY, LEFT							F2
24.030	4833517-1	MOS				09-NOV-1996		\$2100.
	8812674	HRS/MS	O/C			5951		1
	REF: AMM 24-30-00	AFL				4589		
240168	ANALYZE							F2
24.030		MOS				09-NOV-1996		
		HRS/MS	C/C			5951		
	REF: NO REF	AFL				4589		
+ 240161	CHECK ELECTROLYTE LEVEL							F2
24.030	PKG 1, 2, 3	MOS				26-JUN-2001		
		HRS/MS	200			7687		1
	REF: AMM 12-10-06	AFL				5594		
240166	DEEP CYCLE							F2
24.030	PKG 1, 2, 3	MOS				06-NOV-2001		
		HRS/MS	200			7774		2
	REF: AMM 12-10-06	AFL				5641		

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
240171	BATTERY, RIGHT										F2
24.020	4833517-1	MOS							09-NOV-1996		\$2100.
	8506152	HRS/MS	O/C						5951		1
	REF: AMM 24-30-00	AFL							4589		
240184	ANALYZE										F2
24.020		MOS							09-NOV-1996		
		HRS/MS	C/C						5951		
		AFL							4589		
+ 240176	CHECK ELECTROLYTE LEVEL										F2
24.020	PKG 1, 2, 3	MOS							26-JUN-2001		
		HRS/MS	200						7687		1
		AFL							5594		
	REF: AMM 12-10-06										
240181	DEEP CYCLE										F2
24.020	PKG 1, 2, 3	MOS							06-NOV-2001		
		HRS/MS	200						7774		2
		AFL							5641		
	REF: AMM 12-10-06										
240111	BLOWER, INVERTER COOLING										F2
24.100	M125J-9A1	MOS							11-FEB-1982		
	200	HRS/MS	O/C						0		
	REF: AMM 24-20-00	AFL							0		
240136	BOX, D.C. CONTACTOR LEFT										F5
24.050	PN	MOS							11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C						0		
	REF: NO REF	AFL							0		
240141	BOX, D.C. CONTACTOR RIGHT										F5
24.050	PN	MOS							11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C						0		
	REF: NO REF	AFL							0		
240146	CONTROL UNIT, GENERATOR NO. 1										F5
24.040	5833515-1	MOS							30-NOV-1989		
	6681927M1	HRS/MS	O/C						4430		1
	REF: AMM 24-30-00	AFL							2987		
240151	CONTROL UNIT, GENERATOR NO. 2										F5
24.040	5833515-1	MOS							01-MAY-1990		
	663958M1	HRS/MS	O/C						4578		1
	REF: AMM 24-30-00	AFL							3154		
240116	GENERATOR, STARTER NO. 1									OVERHAUL	E1
24.010	23065-018-1	MOS							06-NOV-2001		\$813.
	3684	HRS/MS	1000						7774	?	1
	REF: AMM 80-10-00	AFL							5641		
+ 240121	CHECK BRUSH WEAR/TENSION										E1
24.010	PKG 4	MOS							06-NOV-2001		
		HRS/MS	150						7774		.5
	REF: See Workcard	AFL							5641		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
+ 240118 24.170	INSPECT PKG 4	MOS HRSMSC AFL	150			06-NOV-2001 7774 5641		E1
	REF: AMM 5-21-00							
+ 240123 24.010	INSPECT SPLINE PKG 4	MOS HRSMSC AFL	150			06-NOV-2001 7774 5641		E1
	REF: AMM							
240126 24.010	GENERATOR, STARTER NO. 2 23065-018-1	MOS HRSMSC AFL	1000			06-NOV-2001 7774 5641	OVERHAUL ?	E2 \$813. 1
	2562 REF: AMM 80-10-00							
+ 240131 24.010	CHECK BRUSH WEAR/TENSION PKG 5	MOS HRSMSC AFL	150			06-NOV-2001 7774 5641		E2
	REF: See Workcard							
+ 240128 24.170	INSPECT PKG 5	MOS HRSMSC AFL	150			06-NOV-2001 7774 5641		E2
	REF: AMM 5-21-00							
+ 240133 24.010	INSPECT SPLINE PKG 5	MOS HRSMSC AFL	150			06-NOV-2001 7774 5641		E2
	REF: AMM 80-10-00							
240196 24.050	INDICATOR, BATTERY TEMPERATURE 4883754-501	MOS HRSMSC AFL	O/C	0		11-FEB-1982 0 0		F3
	1955 REF: NO REF							
240101 24.080	INVERTER, NO. 1 6833508-501	MOS HRSMSC AFL	O/C	0		12-JUL-1989 4305 2845		F2 \$1150. 1
	C0253094 REF: AMM 24-20-00							
240108 24.080	INVERTER, NO. 2 6833508-501	MOS HRSMSC AFL	O/C	0		09-DEC-1985 2762 1713		F2 \$1150. 1
	1135 REF: AMM 24-20-00							
241651 24.120	METER, VOLT/AMP 6883091-513	MOS HRSMSC AFL	O/C			11-FEB-1982 0 0		
	SN-UNKNOWN REF: NO REF							
241601 24.130	POWER SUPPLY, VHF EMERGENCY COMMUNICATION 501-1015-02	MOS HRSMSC AFL	O/C	0		11-FEB-1982 0 0		
	SN-UNKNOWN REF: NO REF							

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT----- TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
241606 24.130	INSPECT BATTERY	MOS					11-OCT-1990	
	REF: NO REF	HRS/MSAFL	O/C			4718 3309		
240211 24.060	RECEPTACLE, EXTERNAL POWER	MOS					11-FEB-1982	F1
	PN	HRS/MSAFL	O/C	0		0 0		
+ 240203 24.070	FUNCTIONALLY CHECK BATTERY TEMPERATURE AND WARNING SYSTEM	MOS					26-JUN-2001	F3
	PKG 1, 2, 3	HRS/MSAFL	200			7687 5594		
240186 24.030	THERMISTOR, BATTERY LEFT	MOS					11-JAN-1989	F2
	PN	HRS/MSAFL	O/C	0		4127 2632		
240191 24.020	THERMISTOR, BATTERY RIGHT	MOS					11-JAN-1989	F2
	PN	HRS/MSAFL	O/C	0		4127 2632		
240103	VOLTMETER, AC LEFT	MOS					11-FEB-1982	F3
	3883035-501	HRS/MSAFL	O/C	0		0 0		
240108 24.090	VOLTMETER, AC RIGHT	MOS					11-FEB-1982	F3
	3883035-501	HRS/MSAFL	O/C	0		0 0		
240143 24.110	VOLTMETER, DC LEFT	MOS					11-FEB-1982	F3
	6883091-505	HRS/MSAFL	O/C	0		0 0		
240148 24.110	VOLTMETER, DC RIGHT	MOS					25-FEB-1994	F3
	6883091-505	HRS/MSAFL	O/C	0		5408 4066		
CHAPTER 25	EQUIPMENT/FURNISHINGS							
+ 250162 25.050	INSPECT FIRST AID KIT	MOS	12				06-NOV-2001 06-NOV-2002	F4
	REF: NO REF	HRS/MSAFL				7774 5641		
+ 250156 25.050	INSPECT LIFE PRESERVERS	MOS	12				06-NOV-2001 06-NOV-2002	F4
	REF: NO REF	HRS/MSAFL				7774 5641		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
250141	DISPLAY, CABIN INFORMATION											F4
25.040	32940-004	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0						0		
	REF: NO REF	AFL								0		
250146	OPERATIONAL CHECK											F4
25.040		MOS								11-FEB-1982		
		HRS/MS	O/C							0		
	REF: NO REF	AFL								0		
250116	INERTIA REEL, COPILOT											F3
25.020	PN	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0						0		
	REF: NO REF	AFL								0		
250111	INERTIA REEL, PILOT											F3
25.020	PN	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0						0		
	REF: NO REF	AFL								0		
250106	SEAT, COPILOT											F3
25.010	1024-0	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0						0		
	REF: AMM 25-10-01	AFL								0		
250101	SEAT, PILOT											F3
25.010	1025-0	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0						0		
	REF: AMM 25-10-01	AFL								0		
250131	SEATBELT, COPILOT											F3
25.030	PN	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0						0		
	REF: NO REF	AFL								0		
250121	SEATBELT, PILOT											F3
25.030	PN	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0						0		
	REF: NO REF	AFL								0		
250166	TRANSMITTER, EMERGENCY LOCATOR											F4
25.060	607690-2	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0						0		
	REF: NO REF	AFL								0		
CHAPTER 26 FIRE PROTECTION												
+ 260186	OPERATIONAL CHECK FIRE PROTECTION SYSTEM											F3
26.020	PKG 2, 3	MOS								26-JUN-2001		
		HRS/MS	400							7687		
	REF: AMM 26-00-00	AFL								5594		
+ 260148	REPLACE LEFT FIRE EXTINGUISHER NO.1 CARTRIDGE										SCRAP	F5
26.010		MOS	48							17-JAN-2001	17-JAN-2005	
		HRS/MS										
	REF: AMM 26-20-00	AFL										

Aircraft Model - 1124 WESTWIND

Report Date **11-APR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----	INSTALLATION	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
					TSN	TSO	TSR	TSI	ADJ	
+	260153	REPLACE LEFT FIRE EXTINGUISHER NO.2 CARTRIDGE								
	26.010		MOS	48						
			HRS/MS							
		REF: AMM 26-20-00	AFL							
+	260158	REPLACE RIGHT FIRE EXTINGUISHER NO.1 CARTRIDGE								
	26.015		MOS	48						
			HRS/MS							
		REF: AMM 26-20-00	AFL							
+	260163	REPLACE RIGHT FIRE EXTINGUISHER NO.2 CARTRIDGE								
	26.015		MOS	48						
			HRS/MS							
		REF: AMM 26-20-00	AFL							
260176		EXTINGUISHER, CABIN PORTABLE								
	26.030	MODEL 2-10	MOS		13					
		U-329516	HRS/MS	O/C	0					
		REF: AMM 5-10-00	AFL							
260182		DISCHARGE /VALVE OVERHAUL AND REFILL CABIN FIRE EXINGUISHER								
	26.030		MOS	72						
			HRS/MS							
		REF: MSC SIL 1124-25-059R1	AFL							
260183		HYDROSTATIC TEST CABIN FIRE EXTINGUISHER								
	26.030		MOS	144						
			HRS/MS							
		REF: See Workcard	AFL							
+	260184	INSPECT CABIN FIRE EXTINGUISHER								
	26.030	PKG 1, 2, 3	MOS							
			HRS/MS	200						
		REF: AMM 26-20-00	AFL							
+	260180	VISUAL INSPECTION CABIN FIRE EXTINGUISHER								
	26.060		DAYS	30						
			HRS/MS							
		REF: NO REF	AFL							
260181		WEIGHT CHECK CABIN FIRE EXTINGUISHER								
	26.030		MOS	12						
			HRS/MS							
		REF: AMM 5-10-00	AFL							
260166		EXTINGUISHER, COCKPIT PORTABLE								
	26.030	MODEL 2-10	MOS		13					
		U-329659	HRS/MS	O/C	0					
		REF: AMM 5-10-00	AFL							
260172		DISCHARGE /VALVE OVERHAUL AND REFILL COCKPIT FIRE EXTINGUISHER								
	26.030		MOS	72						
			HRS/MS							
		REF: MSC SIL 1124-25-059R1	AFL							

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
260173 26.030	HYDROSTATIC TEST COCKPIT FIRE EXTINGUISHER	MOS	144			01-JAN-1995	01-JAN-2007	F3
	REF: MSC SIL 1124-25-059R1	HRS/MS AFL						
+ 260174 26.030	INSPECT COCKPIT FIRE EXTINGUISHER PKG 1, 2, 3	MOS				26-JUN-2001		F3
	REF: AMM 26-20-00	HRS/MS AFL	200			7687 5594		
+ 260169 26.060	VISUAL INSPECTION COCKPIT FIRE EXTINGUISHER	MOS						F3
	REF: NO REF	HRS/MS AFL	30			06-NOV-2001 7774 5641	06-DEC-2001	
260171 26.030	WEIGHT CHECK COCKPIT FIRE EXTINGUISHER	MOS	12			26-JUN-2001	26-JUN-2002	F3
	REF: AMM 5-10-00	HRS/MS AFL				7687 5594		
260111 26.010	EXTINGUISHER, FIRE LEFT 3643507-1	MOS				11-FEB-1982		F5
	02447C1	HRS/MS AFL	O/C	0		0 0		\$795.
260121 26.010	HYDROSTATIC TEST	MOS	60				MANDATORY	F5
	REF: AMM 5-10-00	HRS/MS AFL				06-NOV-2001 7774 5641	06-NOV-2006	
+ 260146 26.010	RECORD DATE STAMPED ON NEW CARTRIDGE (SERVICE LIFE)	MOS	72				LIFE LIMIT	F5
	REF: AMM 26-20-00	HRS/MS AFL				17-JAN-2001	17-JAN-2007	
+ 260151 26.010	RECORD DATE STAMPED ON NEW CARTRIDGE (SERVICE LIFE)	MOS	72				LIFE LIMIT	F5
	REF: AMM 26-20-00	HRS/MS AFL				17-JAN-2001	17-JAN-2007	
+ 260148 26.010 ASSOCIATED	REPLACE LEFT FIRE EXTINGUISHER NO.1 CARTRIDGE	MOS	48				SCRAP	F5
	REF: AMM 26-20-00	HRS/MS AFL				17-JAN-2001	17-JAN-2005	
+ 260153 26.010 ASSOCIATED	REPLACE LEFT FIRE EXTINGUISHER NO.2 CARTRIDGE	MOS	48				SCRAP	F5
	REF: AMM 26-20-00	HRS/MS AFL				17-JAN-2001	17-JAN-2005	
260116 26.010	WEIGHT CHECK	MOS				17-JAN-2001		F5
	REF: See Workcard	HRS/MS AFL	O/C			7494 5466		

Aircraft Model - 1124 WESTWIND

Report Date **11-APR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT----- TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
260126	EXTINGUISHER, FIRE RIGHT							F5
26.015	23700004	MOS				10-JAN-1994		\$795.
	02429C1	HRS/MSC	O/C	0		5382		
	REF: AMM 26-20-00	AFL				4036		
260136	HYDROSTATIC TEST						MANDATORY	F5
26.015		MOS	60			07-APR-1999	07-APR-2004	
		HRS/MSC				6727		
	REF: AMM 5-10-00	AFL				4999		
+ 260156	RECORD DATE STAMPED ON NEW CARTRIDGE (SERVICE LIFE)						LIFE LIMIT	F5
26.015		MOS	72			17-JAN-2001	17-JAN-2007	
		HRS/MSC						
	REF: AMM 26-20-00	AFL						
+ 260161	RECORD DATE STAMPED ON NEW CARTRIDGE (SERVICE LIFE)						LIFE LIMIT	F5
26.015		MOS	72			17-JAN-2001	17-JAN-2007	
		HRS/MSC						
	REF: AMM 26-20-00	AFL						
+ 260158	REPLACE RIGHT FIRE EXTINGUISHER NO.1 CARTRIDGE						SCRAP	F5
26.015		MOS	48			17-JAN-2001	17-JAN-2005	
ASSOCIATED		HRS/MSC						
	REF: AMM 26-20-00	AFL						
+ 260163	REPLACE RIGHT FIRE EXTINGUISHER NO.2 CARTRIDGE						SCRAP	F5
26.015		MOS	48			17-JAN-2001	17-JAN-2005	
ASSOCIATED		HRS/MSC						
	REF: AMM 26-20-00	AFL						
260131	WEIGHT CHECK							F5
26.015		MOS				17-JAN-2001		
		HRS/MSC	O/C			7494		
	REF: See Workcard	AFL				5466		
260101	FIRE DETECTOR, LEFT							E1
26.040	4643506-3	MOS				11-FEB-1982		
	19491	HRS/MSC	O/C	0		0		
	REF: AMM 26-10-00	AFL				0		
260106	FIRE DETECTOR, RIGHT							E2
26.040	4643506-3	MOS				11-FEB-1982		
	19503	HRS/MSC	O/C	0		0		
	REF: AMM 26-10-00	AFL				0		
260141	INDICATOR, EXTINGUISHER DISCHARGE							F5
26.050	PN	MOS				11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C	0		0		
	REF: NO REF	AFL				0		
CHAPTER 27	FLIGHT CONTROLS							
+ 270271	ADJUST/TEST FLAP COMPARATOR							F3
27.430	PKG 3	MOS				26-JUL-2000		
		HRS/MSC	800			7325		
	REF: AMM 27-50-00	AFL				5360		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
+ 270140 27.070	CHECK AILERON CONTROL SYSTEM FREEPLAY PKG 3	MOS HRS/MSC AFL	800			26-JUL-2000 7325 5360		F5
	REF: AMM 27-10-00							
+ 270341 27.440	CHECK CABLE TENSION AFT FUSELAGE PKG 2, 3	MOS HRS/MSC AFL	400			26-JUN-2001 7687 5594		F5
	REF: AMM 27-00-00							
+ 270340 27.440	CHECK CABLE TENSION FLIGHT/PASSENGER COMPARTMENT PKG 3	MOS HRS/MSC AFL	800			26-JUL-2000 7325 5360		F3
	REF: AMM 27-00-00							
+ 270280 27.230	CLEAN/INSPECT/LUBRICATE LEFT INBOARD/OUTBOARD FLEXIBLE SHAFT PKG 3	MOS HRS/MSC AFL	1200			16-FEB-2001 7551 5515	8751	W1
	REF: AMM 27-50-00							
+ 270285 27.230	CLEAN/INSPECT/LUBRICATE RIGHT INBOARD/OUTBOARD FLEXIBLE SHAFT PKG 3	MOS HRS/MSC AFL	1200			16-FEB-2001 7551 5515	8751	W2
	REF: AMM 27-50-00							
+ 270248 27.200	FUNCTIONAL CHECK FLAP TIME EXCEED RELAY PKG 2, 3	MOS HRS/MSC AFL	400			26-JUN-2001 7687 5594		F3
	REF: AMM 27-50-00							
+ 270211 27.500	INSPECT SCISSORS/ASSEMBLY PKG 2, 3	MOS HRS/MSC AFL	400			26-JUN-2001 7687 5594		T1
	REF: See Workcard							
+ 270351 27.380	INSPECT/LUBRICATE PRESSURE SEALS PKG 3	MOS HRS/MSC AFL	800			26-JUL-2000 7325 5360		F4
	REF: AMM 12-20-00							
270214 27.195	LUBRICATE AFT HINGE FITTING BEARINGS PKG 1, 2, 3	MOS HRS/MSC AFL	200			26-JUN-2001 7687 5594		T1
	REF: NO REF							
270179 27.350	LUBRICATE CONTROL COLUMNS PKG 3	MOS HRS/MSC AFL	800			26-JUL-2000 7325 5360		F3
	REF: AMM 12-20-00							
270213 27.190	LUBRICATE ELEVATOR ATTACH POINTS PKG 1, 2, 3	MOS HRS/MSC AFL	200			26-JUN-2001 7687 5594		T1
	REF: AMM 12-20-00							

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
270346	27.360	LUBRICATE FLIGHT CONTROL FORWARD/AFT BELL CRANKS PKG 3	MOS HRS/MSA AFL	800			26-JUL-2000 7325 5360		F4
		REF: AMM 12-20-00							
270215	27.195	LUBRICATE FORWARD SCISSOR ASSEMBLY PKG 1, 2, 3	MOS HRS/MSA AFL	200			26-JUN-2001 7687 5594		T1
		REF: NO REF							
270356	27.370	LUBRICATE GUST LOCK PKG 3	MOS HRS/MSA AFL	800			26-JUL-2000 7325 5360		F3
		REF: AMM 12-20-00							
270176	27.340	LUBRICATE RUDDER PEDAL ARMS PKG 3	MOS HRS/MSA AFL	800			26-JUL-2000 7325 5360		F3
		REF: AMM 12-20-00							
+ 270335	27.280	OPERATIONAL CHECK SPEED BRAKES AND LIFT DUMPERS PKG 1, 2, 3	MOS HRS/MSA AFL	200			26-JUN-2001 7687 5594		F2
		REF: AMM 27-60-00							
270145	27.045	STATIC FRICTION TEST AILERON AND RUDDER PKG 3	MOS HRS/MSA AFL	800			26-JUL-2000 7325 5360		
		REF: AMM 27-00-00							
270210	27.570	VISUAL INSPECT ELEVATOR CONTROL BELLCRANK ASSEMBLY PKG 3	MOS HRS/MSA AFL	60 5000			16-JUN-1997 6135 4707	16-JUN-2002 11135	
		REF: AMM 5-10-00							
270331	27.320	ACCUMULATOR, LIFT DUMPER RIGHT WING INBOARD 3-713515-501 SN-UNKNOWN REF: AMM 27-60-00	MOS HRS/MSA AFL	O/C	0		11-FEB-1982 0 0		W2
		REF: AMM 27-60-00							
270116	27.060	ACTUATOR, AILERON TRIM TAB 5793500-1 1010 REF: AMM 27-10-00	MOS HRS/MSA AFL	O/C			09-NOV-1996 5951 4589		W1
		REF: AMM 27-10-00							
270251	27.210	ACTUATOR, FLAP LEFT INBOARD 1390T100-5 610A REF: AMM 27-50-00	MOS HRS/MSA AFL	10000			16-JUN-1997 6135 4707	LIFE LIMIT ?	W1 \$1006. 8
		REF: AMM 27-50-00							
270256	27.220	ACTUATOR, FLAP LEFT OUTBOARD 1391T100-7 519A REF: AMM 27-50-00	MOS HRS/MSA AFL	10000	0		06-APR-1998 6346 4787	OVERHAUL 16346	W1 \$1046.
		REF: AMM 27-50-00							

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT----- TSN TSO TSR TSI ADJ	INSTALLATION	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
270261	ACTUATOR, FLAP RIGHT INBOARD							OVERHAUL	W2
27.210	193544-1	MOS					15-JUL-1986		\$1006.
	749A	HRSMSC	10000	0			3201	13201	8
	REF: AMM 27-50-00	AFL					1972		
270266	ACTUATOR, FLAP RIGHT OUTBOARD							LIFE LIMIT	W2
27.220	193544-502	MOS					22-OCT-1982		\$1046.
	120	HRSMSC	10000	0			482	10482	
	REF: AMM 27-50-00	AFL							
270216	ACTUATOR, HORIZONTAL STABILIZER TRIM							OVERHAUL	T1
27.170	21164-005	MOS					06-APR-1998		\$4158.
	0481-11AA	HRSMSC					6346		
	REF: AMM 27-40-00	AFL	2500	0			4787	7287	
+ 270217	INSPECT								T1
27.170	PKG 2, 3	MOS					26-JUN-2001		
		HRSMSC	400				7687		
	REF: See Workcard	AFL					5594		
270328	ACTUATOR, LIFT DUMPER LEFT WING INBOARD								W1
27.310	3-713515-501	MOS					11-FEB-1982		
	SN-UNKNOWN	HRSMSC	O/C	0			0		
	REF: AMM 27-60-00	AFL					0		
270326	ACTUATOR, LIFT DUMPER LEFT WING OUTBOARD								W1
27.310	3-713515-501	MOS					11-FEB-1982		
	SN-UNKNOWN	HRSMSC	O/C	0			0		
	REF: AMM 27-60-00	AFL					0		
270333	ACTUATOR, LIFT DUMPER RIGHT WING OUTBOARD								W2
27.320	3-713515-501	MOS					11-FEB-1982		
	SN-UNKNOWN	HRSMSC	O/C	0			0		
	REF: AMM 27-60-00	AFL					0		
270166	ACTUATOR, LOWER RUDDER TRIM								T1
27.090	5793500-501	MOS					11-FEB-1982		\$1000.
	3219	HRSMSC	O/C	0			0		16
	REF: AMM 27-20-00	AFL					0		
270301	ACTUATOR, SPEED BRAKE LEFT								W1
27.260	3713515-503	MOS					11-FEB-1982		
	1L-466P	HRSMSC	O/C	0			0		
	REF: AMM 27-60-00	AFL					0		
270306	ACTUATOR, SPEED BRAKE RIGHT								W2
27.260	3713515-503	MOS					11-FEB-1982		
	1L-470P	HRSMSC	O/C	0			0		
	REF: AMM 27-60-00	AFL					0		
270161	ACTUATOR, UPPER RUDDER TRIM								T1
27.090	5793500-503	MOS					11-FEB-1982		\$1000.
	5220	HRSMSC	O/C	0			0		16
	REF: AMM 27-20-00	AFL					0		

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME-----AT-----INSTALLATION	COMPLIANCE	DISPOSITION	AREA
WORKCARD	PART NUMBER/PKG SERIAL NUMBER			TSN TSO TSR TSI ADJ	Warr Exp	NEXT DUE	PRICE LABOR HRS
270101	AILERON, LEFT						W1
27.010	5183003-407-2	MOS				11-FEB-1982	
	4376	HRS/MS	O/C	0		0	
	REF: AMM 27-10-00	AFL				0	
+ 270140	CHECK AILERON CONTROL SYSTEM FREEPLAY						F5
27.070	PKG 3	MOS				26-JUL-2000	
ASSOCIATED		HRS/MS	800			7325	
	REF: AMM 27-10-00	AFL				5360	
+ 270264	CLEAN/CHECK LEFT GUIDE ROLLERS						W1
27.550	PKG 2, 3	MOS				26-JUN-2001	
		HRS/MS	400			7687	
	REF: AMM 5-20-03	AFL				5594	
SB 1124-27-100 R2 L/H RODS	FLIGHT CONTROLS SERVICE BULLETIN						W1
		MOS					
ASSOCIATED		HRS/MS	A/R			0	
	REF: BULLETINS	AFL				0	
	Method of Compliance: OPEN						
SB 1124-27-129 LEFT AILERON	FLIGHT CONTROLS SERVICE BULLETIN						W1
		MOS				26-JUL-2000	
ASSOCIATED		HRS/MS	600			7325	7925
	REF: BULLETINS	AFL				5360	
	Method of Compliance: OPEN						
+ 570106	INSPECT BELLCRANK						W1
57.020	PKG 1, 2, 3	MOS				26-JUN-2001	
		HRS/MS	200			7687	
	REF: AMM 5-20-03	AFL				5594	
+ 270262	INSPECT LEFT EXTERNAL PUSH-PULL TUBE						W1
27.540	PKG 2, 3	MOS				26-JUN-2001	
		HRS/MS	400			7687	
	REF: AMM 5-20-03	AFL				5594	
AD 1996-24-11 LEFT AILERON	TO PREVENT EXCESSIVE WEAR OF THE AILERON PUSH-PULL TUBE, WHICH COULD RESULT IN UNEVEN MOVEMENT OF THE CONTROL WHEEL, PERFORATION OF THE AILERON PUSH-PULL TUBE, AND CONSEQUENT REDUCED ROLL CONTROL OF THE AIRPLANE AIRWORTHINESS DIRECTIVE						W1
		MOS				26-JUL-2000	
ASSOCIATED		HRS/MS	600			7325	7925
	REF: AD	AFL				5360	
	Method of Compliance: OPEN						
AD 1992-12-02 LEFT AILERON	TO PREVENT REDUCED CONTROLLABILITY OF THE AIRPLANE AIRWORTHINESS DIRECTIVE						W1
		MOS					
ASSOCIATED		HRS/MS	150			0	
	REF: AD	AFL				0	
	Method of Compliance: OPEN						
270106	AILERON, RIGHT						W2
27.010	5183003-406-2	MOS				11-FEB-1982	
	4376	HRS/MS	O/C	0		0	
	REF: AMM 27-10-00	AFL				0	

 ? - Insufficient Information
 + Task exists in FAA Manual
 4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
+ 270140	CHECK AILERON CONTROL SYSTEM FREEPLAY							F5
27.070	PKG 3	MOS				26-JUL-2000		
ASSOCIATED	REF: AMM 27-10-00	HRSMSC	800			7325		
		AFL				5360		
+ 270265	CLEAN/CHECK RIGHT GUIDE ROLLERS							W2
27.550	PKG 2, 3	MOS				26-JUN-2001		
	REF: AMM 5-20-03	HRSMSC	400			7687		
		AFL				5594		
SB 1124-27-100 R2 R/H RODS	FLIGHT CONTROLS SERVICE BULLETIN							W2
ASSOCIATED		MOS						
	REF: BULLETINS	HRSMSC	A/R			0		
	Method of Compliance: OPEN	AFL				0		
SB 1124-27-129 RIGHT AILERON	FLIGHT CONTROLS SERVICE BULLETIN							W2
ASSOCIATED		MOS				26-JUL-2000		
	REF: BULLETINS	HRSMSC	600			7325	7925	
	Method of Compliance: OPEN	AFL				5360		
+ 270263	INSPECT RIGHT EXTERNAL PUSH-PULL TUBE							W2
27.540	PKG 2, 3	MOS				26-JUN-2001		
	REF: AMM 5-20-03	HRSMSC	400			7687		
		AFL				5594		
AD 1996-24-11 RIGHT AILERON	TO PREVENT EXCESSIVE WEAR OF THE AILERON PUSH-PULL TUBE, WHICH COULD RESULT IN UNEVEN MOVEMENT OF THE CONTROL WHEEL, PERFORATION OF THE AILERON PUSH-PULL TUBE, AND CONSEQUENT REDUCED ROLL CONTROL OF THE AIRPLANE AIRWORTHINESS DIRECTIVE							W2
ASSOCIATED		MOS				26-JUL-2000		
	REF: AD	HRSMSC	600			7325	7925	
	Method of Compliance: OPEN	AFL				5360		
AD 1992-12-02 RIGHT AILERON	TO PREVENT REDUCED CONTROLLABILITY OF THE AIRPLANE AIRWORTHINESS DIRECTIVE							W2
ASSOCIATED		MOS						
	REF: AD	HRSMSC	150			0		
	Method of Compliance: OPEN	AFL				0		
270291	BRAKE, SPEED LEFT							W1
27.250	5-203007-507	MOS				11-FEB-1982		
	SN-UNKNOWN	HRSMSC	O/C	0		0		
	REF: AMM 27-60-00	AFL				0		
+ 270335	OPERATIONAL CHECK SPEED BRAKES AND LIFT DUMPERS							F2
27.280	PKG 1, 2, 3	MOS				26-JUN-2001		
ASSOCIATED	REF: AMM 27-60-00	HRSMSC	200			7687		
		AFL				5594		
270296	BRAKE, SPEED RIGHT							W2
27.250	5-203007-506	MOS				11-FEB-1982		
	SN-UNKNOWN	HRSMSC	O/C	0		0		
	REF: AMM 27-60-00	AFL				0		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
+ 270335	27.280	OPERATIONAL CHECK SPEED BRAKES AND LIFT DUMPERS	MOS						F2
	ASSOCIATED	PKG 1, 2, 3	HRSMSC	200			26-JUN-2001		
		REF: AMM 27-60-00	AFL				7687		
							5594		
270138	27.080	CHAIN, AILERON LEFT	MOS				11-FEB-1982		F3
		3533516-1	HRSMSC	O/C	0		0		
		SN-UNKNOWN	AFL				0		
		REF: AMM 27-30-00							
270139	27.080	CHAIN, AILERON RIGHT	MOS				11-FEB-1982		F3
		3533516-1	HRSMSC	O/C	0		0		
		SN-UNKNOWN	AFL				0		
		REF: AMM 27-30-00							
270186	27.140	COLUMN, CONTROL COPILOT	MOS				11-FEB-1982		F3
		PN	HRSMSC	O/C	0		0		
		SN-UNKNOWN	AFL				0		
		REF: AMM 27-30-00							
270181	27.140	COLUMN, CONTROL PILOT	MOS				11-FEB-1982		F3
		PN	HRSMSC	O/C	0		0		
		SN-UNKNOWN	AFL				0		
		REF: AMM 27-30-00							
270191	27.150	ELEVATOR, LEFT	MOS				11-FEB-1982		T1
		5463012-401-1	HRSMSC	O/C	0		0		
		4381	AFL				0		
		REF: AMM 27-30-00							
+ 270193	27.150	INSPECT SKIN SEPARATION	MOS						T1
		PKG 1, 2, 3	HRSMSC	200			26-JUN-2001		
		REF: AMM 27-30-00	AFL				7687		
							5594		
270213	27.190	LUBRICATE ELEVATOR ATTACH POINTS	MOS				26-JUN-2001		T1
	ASSOCIATED	PKG 1, 2, 3	HRSMSC	200			7687		
		REF: AMM 12-20-00	AFL				5594		
270210	27.570	VISUAL INSPECT ELEVATOR CONTROL BELLCRANK ASSEMBLY	MOS	60			16-JUN-1997	16-JUN-2002	
	ASSOCIATED		HRSMSC	5000			6135	11135	
		REF: AMM 5-10-00	AFL				4707		
270201	27.150	ELEVATOR, RIGHT	MOS				11-FEB-1982		T1
		5463012-402-1	HRSMSC	O/C	0		0		
		4381	AFL				0		
		REF: AMM 27-30-00							
+ 270203	27.150	INSPECT SKIN SEPARATION	MOS						T1
		PKG 1, 2, 3	HRSMSC	200			26-JUN-2001		
		REF: AMM 27-30-00	AFL				7687		
							5594		

 ? - Insufficient Information
 + Task exists in FAA Manual
 4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
270213	LUBRICATE ELEVATOR ATTACH POINTS							T1
27.190	PKG 1, 2, 3	MOS				26-JUN-2001		
ASSOCIATED	REF: AMM 12-20-00	HRS/MS	200			7687		
		AFL				5594		
270210	VISUAL INSPECT ELEVATOR CONTROL BELLCRANK ASSEMBLY							
27.570		MOS	60			16-JUN-1997	16-JUN-2002	
ASSOCIATED	REF: AMM 5-10-00	HRS/MS	5000			6135	11135	
		AFL				4707		
270233	FLAP ASSEMBLY, CONTROL BOX							F3
27.490	2813521-	MOS				11-FEB-1982		
	286	HRS/MS	O/C	0		0		
	REF: NO REF	AFL		0		0		
270236	FLAP/VANE, LEFT							W1
27.200	5193502-401	MOS				11-FEB-1982		
	4369	HRS/MS	O/C	0		0		
	REF: AMM 27-50-00	AFL				0		
+ 270248	FUNCTIONAL CHECK FLAP TIME EXCEED RELAY							F3
27.200	PKG 2, 3	MOS				26-JUN-2001		
ASSOCIATED	REF: AMM 27-50-00	HRS/MS	400			7687		
		AFL				5594		
+ 270240	INSPECT LEFT FLAP HINGE AND BEARING 200 HOURS							W1
27.200	PKG 1, 2, 3	MOS				26-JUN-2001		
	REF: AMM 27-50-00	HRS/MS	200			7687		
		AFL				5594		
+ 270244	INSPECT LEFT FLAP HINGE AND BEARING 800 HOURS							W1
27.200	PKG 3	MOS				26-JUL-2000		
	REF: AMM 27-50-00	HRS/MS	800			7325		
		AFL				5360		
+ 270237	INSPECT LEFT FLAP VANE							W1
27.200	PKG 1, 2, 3	MOS				26-JUN-2001		
	REF: AMM 27-50-00	HRS/MS	200			7687		
		AFL				5594		
+ 270238	TAP TEST LEFT FLAP							W1
27.200	PKG 2, 3	MOS				26-JUN-2001		
	REF: AMM 27-50-00	HRS/MS	400			7687	.5	
		AFL				5594		
270241	FLAP/VANE, RIGHT							W2
27.200	5193502-402	MOS				11-FEB-1982		
	4370	HRS/MS	O/C	0		0		
	REF: AMM 27-50-00	AFL				0		
+ 270248	FUNCTIONAL CHECK FLAP TIME EXCEED RELAY							F3
27.200	PKG 2, 3	MOS				26-JUN-2001		
ASSOCIATED	REF: AMM 27-50-00	HRS/MS	400			7687		
		AFL				5594		

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
+	270247	INSPECT							W1
	27.200	PKG 1, 2, 3	MOS				26-JUN-2001		
		REF: AMM 27-50-00	HRSMSC	200			7687		
			AFL				5594		
+	270242	INSPECT RIGHT FLAP HINGE AND BEARING	200 HOURS				26-JUN-2001		W2
	27.200	PKG 1, 2, 3	MOS				7687		
		REF: AMM 27-50-00	HRSMSC	200			5594		
			AFL						
+	270245	INSPECT RIGHT FLAP HINGE AND BEARING	800 HOURS				26-JUL-2000		W2
	27.200	PKG 3	MOS				7325		
		REF: AMM 27-50-00	HRSMSC	800			5360		
			AFL						
+	270243	TAP TEST					26-JUN-2001		W2
	27.200	PKG 2, 3	MOS				7687		.5
		REF: AMM 27-50-00	HRSMSC	400			5594		
			AFL						
	270276	GEARBOX, COMPARATOR LEFT					11-FEB-1982		W1
	27.400	5-703541-501	MOS				0		\$1570.
		SN-UNKNOWN	HRSMSC	O/C	0		0		
		REF: AMM 27-50-00	AFL				0		
+	270271	ADJUST/TEST FLAP COMPARATOR					26-JUL-2000		F3
	27.430	PKG 3	MOS				7325		
	ASSOCIATED	REF: AMM 27-50-00	HRSMSC	800			5360		
			AFL						
	270281	GEARBOX, COMPARATOR RIGHT					11-FEB-1982		W2
	27.400	5-703541-502	MOS				0		
		SN-UNKNOWN	HRSMSC	O/C	0		0		
		REF: AMM 27-50-00	AFL				0		
+	270271	ADJUST/TEST FLAP COMPARATOR					26-JUL-2000		F3
	27.430	PKG 3	MOS				7325		
	ASSOCIATED	REF: AMM 27-50-00	HRSMSC	800			5360		
			AFL						
	270121	INDICATOR, AILERON TRIM TAB					11-FEB-1982		F3
	27.030	3883026-515	MOS				0		
		S0451	HRSMSC	O/C	0		0		
		REF: AMM 27-10-00	AFL				0		
	271101	INDICATOR, ANGLE-OF-ATTACK LEFT					11-FEB-1982		F3
	27.470	3883765-501	MOS				0		
		JN1066	HRSMSC	O/C	0		0		
		REF: AMM 34-10-05	AFL		0		0		
	271106	INDICATOR, ANGLE-OF-ATTACK RIGHT					11-FEB-1982		F3
	27.470	3883765-501	MOS				0		
		SN-UNKNOWN	HRSMSC	O/C	0		0		
		REF: AMM 34-10-05	AFL		0		0		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Page 26 of 107

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
270288 27.420	INDICATOR, FLAP POSITION COPILOT 6883739-1 SN-UNKNOWN REF: AMM 27-50-00	MOS HRSMSC AFL	O/C	0		11-FEB-1982 0 0		F3
270286 27.420	INDICATOR, FLAP POSITION PILOT 6883789-1 81090110 REF: AMM 27-50-00	MOS HRSMSC AFL	O/C	0		11-FEB-1982 0 0		F3 \$338.
270226 27.160	INDICATOR, HORIZONTAL STABILIZER TRIM 3883026-525 T0119 REF: AMM 27-40-00	MOS HRSMSC AFL	O/C	0		11-FEB-1982 0 0		F3 \$306.
270171 27.120	INDICATOR, RUDDER TRIM 3883026-517 T0163 REF: AMM 27-20-00	MOS HRSMSC AFL	O/C	0		11-FEB-1982 0 0		F3
270224 27.185	JACKSCREW, HORIZONTAL STABILIZER ACTUATOR NO.1 21164-005 (ACT.ASSY) 0481-11A REF: NO REF	MOS HRSMSC AFL	10000	0		06-APR-1998 6346 4787	LIFE LIMIT 14787	T1
270225 27.185	JACKSCREW, HORIZONTAL STABILIZER ACTUATOR NO.2 21164-005 (ACT.ASSY) 0481-11AA REF: NO REF	MOS HRSMSC AFL	10000	0		06-APR-1998 6346 4787	LIFE LIMIT 14787	T1
270318 27.290	LIFT DUMPER, LEFT WING INBOARD 3713515-501 1L-900 REF: AMM 27-60-00	MOS HRSMSC AFL	O/C	0		11-FEB-1982 0 0		W1
270316 27.290	LIFT DUMPER, LEFT WING OUTBOARD 3713515-501 1L687P REF: AMM 27-60-00	MOS HRSMSC AFL	O/C	0		11-FEB-1982 0 0		W1
270321 27.300	LIFT DUMPER, RIGHT WING INBOARD 3713515-501 1L862P REF: AMM 27-60-00	MOS HRSMSC AFL	O/C	0		11-FEB-1982 0 0		W2
270323 27.300	LIFT DUMPER, RIGHT WING OUTBOARD 5-203007-510 1L881P REF: AMM 27-60-00	MOS HRSMSC AFL	O/C	0		11-FEB-1982 0 0		W2
270119 27.450	MOTOR, AILERON TRIM PN SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL	O/C	0		11-FEB-1982 0 0		W1

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT----- TSN TSO TSR TSI ADJ	INSTALLATION	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
270246		MOTOR, FLAP PRIME							OVERHAUL	F5
27.180		193543-1	MOS				06/01/1993	01-DEC-1992		\$4235.
		160	HRS/MS	10000	0			5188	15188	1
		REF: AMM 27-50-00	AFL					3829		
270221		MOTOR, PRIMARY HORIZONTAL STABILIZER								T1
27.460		PN	MOS					11-FEB-1982		
		SN-UNKNOWN	HRS/MS	O/C	0			0		
		REF: NO REF	AFL					0		
270169		MOTOR, RUDDER TRIM								T1
27.450		PN	MOS					11-FEB-1982		
		SN-UNKNOWN	HRS/MS	O/C	0			0		
		REF: NO REF	AFL					0		
270223		MOTOR, SECONDARY HORIZONTAL STABILIZER								T1
27.460		PN	MOS					11-FEB-1982		
		SN-UNKNOWN	HRS/MS	O/C	0			0		
		REF: NO REF	AFL					0		
270274		POTENTIOMETER, LINEAR LEFT								W1
27.410		833523-501	MOS					10-AUG-1986		
		SN-UNKNOWN	HRS/MS	O/C				3515		
		REF: AMM 27-50-00	AFL							
270282		POTENTIOMETER, LINEAR RIGHT								W2
27.410		833523-501	MOS					10-AUG-1986		
		589	HRS/MS	O/C				3515		
		REF: AMM 27-50-00	AFL							
270128		ROD, CONTROL LEFT AILERON								W1
27.530		513506-503	MOS					11-FEB-1982		
		SN-UNKNOWN	HRS/MS	O/C				0		
		REF: NO REF	AFL					0		
+ 270080		X-RAY INSPECT LEFT AILERON CONTROL ROD ASSEMBLIES								W1
27.530			MOS	60				16-JUN-1997	16-JUN-2002	
		SN-UNKNOWN	HRS/MS	5000				6135	11135	
		REF: NO REF	AFL					4707		
270129		ROD, CONTROL RIGHT AILERON								W2
27.535		513506-503	MOS					11-FEB-1982		
		SN-UNKNOWN	HRS/MS	O/C				0		
		REF: NO REF	AFL					0		
+ 270081		X-RAY INSPECT ASSEMBLY								W2
27.535			MOS	60				16-JUN-1997	16-JUN-2002	
		SN-UNKNOWN	HRS/MS	5000				6135	11135	
		REF: NO REF	AFL					4707		
270141		RUDDER,								T1
27.100		5423026-402-2	MOS					11-FEB-1982		
		4370	HRS/MS	O/C	0			0		
		REF: AMM 27-20-00	AFL					0		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
+ 270150 27.560	X-RAY INSPECT CONTROL ROD ASSEMBLY	MOS	60			16-JUN-1997	16-JUN-2002	T1
		HRSMSC	5000			6135	11135	
	REF: NO REF	AFL				4707		
270279 27.230	SHAFT, FLEXIBLE INBOARD LEFT	MOS				11-FEB-1982	LIFE LIMIT	W1
	193545-501	HRSMSC	10000	0		0	10000	
	1200269	AFL				0		
	REF: AMM 27-50-00							
+ 270280 27.230 ASSOCIATED	CLEAN/INSPECT/LUBRICATE LEFT INBOARD/OUTBOARD FLEXIBLE SHAFT	MOS				16-FEB-2001		W1
		HRSMSC	1200			7551	8751	
	REF: AMM 27-50-00	AFL				5515		
270284 27.240	SHAFT, FLEXIBLE INBOARD RIGHT	MOS				11-FEB-1982	LIFE LIMIT	W2
	193545-505	HRSMSC	10000	0		0	10000	
	1200241	AFL				0		
	REF: AMM 27-50-00							
+ 270285 27.230 ASSOCIATED	CLEAN/INSPECT/LUBRICATE RIGHT INBOARD/OUTBOARD FLEXIBLE SHAFT	MOS				16-FEB-2001		W2
		HRSMSC	1200			7551	8751	
	REF: AMM 27-50-00	AFL				5515		
270278 27.230	SHAFT, FLEXIBLE OUTBOARD LEFT	MOS				11-FEB-1982	LIFE LIMIT	W1
	193545-501	HRSMSC	10000	0		0	10000	
	1200446	AFL				0		
	REF: AMM 27-50-00							
+ 270280 27.230 ASSOCIATED	CLEAN/INSPECT/LUBRICATE LEFT INBOARD/OUTBOARD FLEXIBLE SHAFT	MOS				16-FEB-2001		W1
		HRSMSC	1200			7551	8751	
	REF: AMM 27-50-00	AFL				5515		
270283 27.240	SHAFT, FLEXIBLE OUTBOARD RIGHT	MOS				11-FEB-1982	LIFE LIMIT	W2
	193545-501	HRSMSC	10000	0		0	10000	
	1200514	AFL				0		
	REF: AMM 27-50-00							
+ 270285 27.230 ASSOCIATED	CLEAN/INSPECT/LUBRICATE RIGHT INBOARD/OUTBOARD FLEXIBLE SHAFT	MOS				16-FEB-2001		W2
		HRSMSC	1200			7551	8751	
	REF: AMM 27-50-00	AFL				5515		
270126 27.040	TAB, AILERON SERVO	MOS				11-FEB-1982		W2
	5-183005-505	HRSMSC	O/C	0		0		
	SN-UNKNOWN	AFL				0		
	REF: AMM 27-10-00							
270111 27.020	TAB, AILERON TRIM	MOS				11-FEB-1982		W1
	5-183005-503	HRSMSC	O/C	0		0		
	SN-UNKNOWN	AFL				0		
	REF: AMM 27-10-00							

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
270156	TAB, RUDDER TRIM							T1
27.110	PN	MOS					11-FEB-1982	
	SN-UNKNOWN	HRS/MSC	O/C	0		0		
	REF: AMM 27-20-00	AFL				0		
+ 270158	INSPECT FREEPLAY							T1
27.130	PKG 1, 2, 3	MOS					26-JUN-2001	
		HRS/MSC	200			7687		
	REF: AMM 27-20-00	AFL				5594		
271111	TRANSMITTER, ANGLE-OF-ATTACK LEFT							W1
27.480	SLZ7259	MOS					06-APR-1998	
	KE1141	HRS/MSC	O/C			6346		
	REF: AMM 34-10-05	AFL				4787		
271116	TRANSMITTER, ANGLE-OF-ATTACK RIGHT							W2
27.480	SLZ-9280	MOS					11-FEB-1982	
	SN-UNKNOWN	HRS/MSC	O/C	0		0		
	REF: AMM 34-10-05	AFL		0		0		
270231	TRANSMITTER, TRIM POSITION INDICATOR							T1
27.390	8TJ39-BAR-2	MOS					11-FEB-1982	\$543.
	T1353	HRS/MSC	O/C	0		0		
	REF: AMM 27-40-00	AFL				0		
270336	VALVE, LIFT DUMPER CONTROL							F5
27.330	723573-1	MOS					11-FEB-1982	\$362.
	698	HRS/MSC	O/C	0		0		
	REF: AMM 27-60-00	AFL				0		
270311	VALVE, SPEED BRAKE CONTROL							F5
27.270	723573-1	MOS					11-FEB-1982	\$362.
	845	HRS/MSC	O/C	0		0		
	REF: AMM 27-60-00	AFL				0		
270136	WHEEL, CONTROL COPILOT							F3
27.050	5-533060-35	MOS					11-FEB-1982	
	SN-UNKNOWN	HRS/MSC	O/C	0		0		
	REF: AMM 27-10-00	AFL				0		
270131	WHEEL, CONTROL PILOT							F3
27.050	5-533060-37	MOS					11-FEB-1982	
	SN-UNKNOWN	HRS/MSC	O/C	0		0		
	REF: AMM 27-10-00	AFL				0		
CHAPTER 28 FUEL								
+ 281150	CHECK OPERATION OF FUEL BOOST PUMPS							F5
28.010	PKG 1, 2, 3	MOS					26-JUN-2001	
		HRS/MSC	200			7687		
	REF: AMM 28-00-00	AFL				5594		
+ 281603	FUNCTIONAL CHECK FUEL DUMP SYSTEM							F5
28.090		MOS					22-FEB-2000	
		HRS/MSC	1200			7107	8307	
	REF: AMM 28-00-00	AFL				5232		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
+ 281602 28.090	OPERATIONAL CHECK FUEL DUMP SYSTEM PKG 3	MOS HRSMSC AFL	800			26-JUL-2000 7325 5360		F5
281101 28.200	INDICATOR, FUEL QUANTITY LEFT 6883707-1 359 REF: AMM 28-00-00	MOS HRSMSC AFL	O/C	0		11-FEB-1982 0 0		F3 \$444. 1
281106 28.200	INDICATOR, FUEL QUANTITY RIGHT 6883707-1 361 REF: AMM 28-40-00	MOS HRSMSC AFL	O/C	0		11-FEB-1982 0 0		F3 \$444. 1
281108 28.210	INDICATOR, FUEL STATUS 6883710-501 173 REF: NO REF	MOS HRSMSC AFL	O/C			11-FEB-1982		F3
280626 28.160	PROBE, LEFT TIP TANK 6653505-519 227 REF: AMM 28-40-00	MOS HRSMSC AFL	O/C	0		11-FEB-1982 0 0		W1
280616 28.140	PROBE, LEFT WING INBOARD 5653505-507 207 REF: AMM 28-40-00	MOS HRSMSC AFL	O/C	0		11-FEB-1982 0 0		W1
280621 28.140	PROBE, LEFT WING OUTBOARD 5653505-505 214 REF: AMM 28-40-00	MOS HRSMSC AFL	O/C	0		11-FEB-1982 0 0		W1
280646 28.160	PROBE, RIGHT TIP TANK 6653505-519 233 REF: AMM 28-40-00	MOS HRSMSC AFL	O/C	0		11-FEB-1982 0 0		W2
280636 28.150	PROBE, RIGHT WING INBOARD 5653505-507 266 REF: AMM 28-40-00	MOS HRSMSC AFL	O/C	0		11-FEB-1982 0 0		W2
280641 28.150	PROBE, RIGHT WING OUTBOARD 5653505-505 235 REF: AMM 28-40-00	MOS HRSMSC AFL	O/C	0		11-FEB-1982 0 0		W2
280611 28.130	PROBE, FUSELAGE LEFT 3653505-509 224 REF: AMM 28-40-00	MOS HRSMSC AFL	O/C	0		11-FEB-1982 0 0		F5

Aircraft Model - 1124 WESTWIND
Report Date 11-APR-2002
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
280631		PROBE, FUSELAGE RIGHT							F5
	28.130	6653505-509	MOS				11-FEB-1982		
		291	HRSMSC	O/C	0		0		
		REF: AMM 28-40-00	AFL				0		
280126		PUMP, ALTERNATE BOOST LEFT							W1
	28.020	5653744-505	MOS				11-FEB-1982		
		T514	HRSMSC	O/C	0		0		
		REF: AMM 28-20-00	AFL				0		
280128		CHECK BRUSH WEAR							W1
	28.020		MOS				11-FEB-1982		
			HRSMSC	O/C			0		
		REF: See Workcard	AFL				0		
+ 281150		CHECK OPERATION OF FUEL BOOST PUMPS							F5
	28.010	PKG 1, 2, 3	MOS				26-JUN-2001		
	ASSOCIATED		HRSMSC	200			7687		
		REF: AMM 28-00-00	AFL				5594		
280136		PUMP, ALTERNATE BOOST RIGHT							W2
	28.020	5653744	MOS				30-OCT-1989		
		853	HRSMSC	O/C			4401		
		REF: AMM 28-20-00	AFL				2956		
280138		CHECK BRUSH WEAR							W2
	28.020		MOS				11-FEB-1982		
			HRSMSC	O/C			0		
		REF: See Workcard	AFL				0		
+ 281150		CHECK OPERATION OF FUEL BOOST PUMPS							F5
	28.010	PKG 1, 2, 3	MOS				26-JUN-2001		
	ASSOCIATED		HRSMSC	200			7687		
		REF: AMM 28-00-00	AFL				5594		
280161		PUMP, FUSELAGE JET LEFT							F5
	28.110	3-653015	MOS				11-FEB-1982		
		1095	HRSMSC	O/C	0		0		
		REF: AMM 28-20-00	AFL				0		
280166		PUMP, FUSELAGE JET RIGHT							F5
	28.110	3-653015	MOS				11-FEB-1982		
		1099	HRSMSC	O/C	0		0		
		REF: AMM 28-20-00	AFL				0		
280181		PUMP, JET LEFT TIP TANK							W1
	28.100	3-653015	MOS				11-FEB-1982		
		1309	HRSMSC	O/C	0		0		
		REF: AMM 28-20-00	AFL				0		
280186		PUMP, JET RIGHT TIP TANK							W2
	28.100	3-653015	MOS				11-FEB-1982		
		1311	HRSMSC	O/C	0		0		
		REF: AMM 28-20-00	AFL				0		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Page 32 of 107

Aircraft Model - 1124 WESTWIND
Report Date 11-APR-2002
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT----- TSN TSO TSR TSI ADJ	INSTALLATION	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
280167 28.230	PUMP, LONG RANGE BOOST 653009-513 SN-UNKNOWN REF: AMM 28-50-00	MOS HRSMSC AFL	O/C				11-FEB-1982		F4
280121 28.010	PUMP, MAIN BOOST LEFT 2070C01T3 T-330 REF: AMM 28-20-00	MOS HRSMSC AFL	O/C	0			24-APR-2000 7233 5301		W1
280123 28.010	CHECK BRUSH WEAR REF: NO REF	MOS HRSMSC AFL	O/C				24-APR-2000 7233 5301		W1
+ 281150 28.010 ASSOCIATED	CHECK OPERATION OF FUEL BOOST PUMPS PKG 1, 2, 3 REF: AMM 28-00-00	MOS HRSMSC AFL	200				26-JUN-2001 7687 5594		F5
280131 28.010	PUMP, MAIN BOOST RIGHT 2070C01T3 T1222 REF: AMM 28-20-00	MOS HRSMSC AFL	O/C	0 0 0			26-AUG-1992 5151 3777		W2
280133 28.010	CHECK BRUSH WEAR REF: See Workcard	MOS HRSMSC AFL	O/C				26-AUG-1992 5151 3777		W2
+ 281150 28.010 ASSOCIATED	CHECK OPERATION OF FUEL BOOST PUMPS PKG 1, 2, 3 REF: AMM 28-00-00	MOS HRSMSC AFL	200				26-JUN-2001 7687 5594		F5
281121 28.210	SIGNAL CONDITIONER, FUEL 883711-501 157 REF: NO REF	MOS HRSMSC AFL	O/C	0			11-FEB-1982 0 0		F2
280281 28.190	SWITCH, FUEL FLOAT LEFT 833006 A966 REF: NO REF	MOS HRSMSC AFL	O/C	0			11-FEB-1982 0 0		F5
280286 28.190	SWITCH, FUEL FLOAT RIGHT 833006 A920 REF: NO REF	MOS HRSMSC AFL	O/C	0			11-FEB-1982 0 0		F5
281141 28.170	SWITCH, LOW-LEVEL WARNING LEFT 3833006 SN-UNKNOWN REF: AMM 28-40-00	MOS HRSMSC AFL	O/C	0			11-FEB-1982 0 0		F5

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT----- TSN TSO TSR TSI ADJ	INSTALLATION	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
281146 28.170	SWITCH, LOW-LEVEL WARNING RIGHT 3833006 SN-UNKNOWN REF: AMM 28-40-00	MOS HRS/MS AFL	O/C	0			11-FEB-1982 0 0		F5
281139 28.240	SWITCH, PRESSURE(LONG RANGE) 833010-518 A-149 REF: NO REF	MOS HRS/MS AFL	O/C	0			11-FEB-1982 0 0		F4
280250 28.220	TANK, FUEL (LONG RANGE) CMA61032-501 NSN REF: AMM 28-50-00	MOS HRS/MS AFL	O/C		0 0 0		07-DEC-1989 4437 2994		F5
281110 28.240	TRANSMITTER, QUANTITY (LONG RANGE) DA515A050 SN-UNKNOWN REF: NO REF	MOS HRS/MS AFL	O/C	0			11-FEB-1982 0 0		F4
280191 28.090	VALVE, DUMP LEFT 3653014 168 REF: AMM 28-30-00	MOS HRS/MS AFL	O/C	0			11-FEB-1982 0 0		W1 \$725.
+ 281603 28.090 ASSOCIATED	FUNCTIONAL CHECK FUEL DUMP SYSTEM REF: AMM 28-00-00	MOS HRS/MS AFL	1200				22-FEB-2000 7107 5232	8307	F5
+ 281602 28.090 ASSOCIATED	OPERATIONAL CHECK FUEL DUMP SYSTEM PKG 3 REF: AMM 28-00-00	MOS HRS/MS AFL	800				26-JUL-2000 7325 5360		F5
280196 28.090	VALVE, DUMP RIGHT 3653014 31360 REF: AMM 28-30-00	MOS HRS/MS AFL	O/C	0			11-FEB-1982 0 0		W2 \$725.
+ 281603 28.090 ASSOCIATED	FUNCTIONAL CHECK FUEL DUMP SYSTEM REF: AMM 28-00-00	MOS HRS/MS AFL	1200				22-FEB-2000 7107 5232	8307	F5
+ 281602 28.090 ASSOCIATED	OPERATIONAL CHECK FUEL DUMP SYSTEM PKG 3 REF: AMM 28-00-00	MOS HRS/MS AFL	800				26-JUL-2000 7325 5360		F5
280141 28.040	VALVE, FIREWALL SHUTOFF LEFT 3653012 L38199 REF: AMM 28-20-00	MOS HRS/MS AFL	O/C	0			11-FEB-1982 0 0		E1

 ? - Insufficient Information
 + Task exists in FAA Manual
 4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
280151	VALVE, FIREWALL SHUTOFF RIGHT											
28.040	3-653012	MOS								11-FEB-1982		E2
	L35008	HRS/MS	O/C	0						0		\$725.
	REF: AMM 28-20-00	AFL								0		
280251	VALVE, FUEL AUTO SHUTOFF LEFT											F5
28.050	3653669	MOS								11-FEB-1982		
	0114	HRS/MS	O/C	0						0		
	REF: AMM 28-10-00	AFL		0						0		
280256	VALVE, FUEL AUTO SHUTOFF RIGHT											F5
28.050	3653669	MOS								11-FEB-1982		
	0087	HRS/MS	O/C	0						0		
	REF: AMM 28-10-00	AFL		0						0		
280106	VALVE, FUEL INTERCONNECT AFT											F5
28.030	3653014	MOS								11-FEB-1982		\$725.
	31395	HRS/MS	O/C	0						0		
	REF: AMM 28-10-00	AFL								0		
280101	VALVE, FUEL INTERCONNECT FORWARD											F5
28.030	AV16B1683	MOS								16-JUN-1997		\$725.
	L18181	HRS/MS	O/C							6135		
	REF: AMM 28-10-00	AFL								4707		
280261	VALVE, FUEL PILOT LEFT											F5
28.060	3653671	MOS								11-FEB-1982		
	7732	HRS/MS	O/C	0						0		
	REF: AMM 28-10-00	AFL		0						0		
280266	VALVE, FUEL PILOT RIGHT											F5
28.060	3653671	MOS								11-FEB-1982		
	7728	HRS/MS	O/C	0						0		
	REF: AMM 28-10-00	AFL		0						0		
280194	VALVE, FUEL PRECHECK LEFT											F5
28.070	PN	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0						0		
	REF: AMM 28-10-00	AFL		0						0		
280203	VALVE, FUEL PRECHECK RIGHT											F5
28.070	PN	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0						0		
	REF: AMM 28-10-00	AFL		0						0		
280206	VALVE, FUEL SOLENOID LEFT											F5
28.180	MS-29527-1	MOS								11-FEB-1982		
	744	HRS/MS	O/C	0						0		
	REF: NO REF	AFL								0		
280211	VALVE, FUEL SOLENOID RIGHT											F5
28.180	MS-29527-1	MOS								11-FEB-1982		
	752	HRS/MS	O/C	0						0		
	REF: NO REF	AFL								0		

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
280171	VALVE, FUEL TRANSFER LEFT							F5
28.120	4653572	MOS					11-FEB-1982	\$805.
	101	HRS/MS	O/C	0		0		
	REF: AMM 28-20-00	AFL				0		
280176	VALVE, FUEL TRANSFER RIGHT							F5
28.120	4653572	MOS					11-FEB-1982	\$805.
	126	HRS/MS	O/C	0		0		
	REF: AMM 28-20-00	AFL				0		
280290	VALVE, SINGLE POINT REFUEL ADAPTER							F5
28.250	3653670	MOS					11-FEB-1982	
	205	HRS/MS	O/C			0		
	REF: NO REF	AFL				0		
280271	VALVE, SINGLE POINT REFUEL VENT LEFT							F5
28.080	3653672	MOS					11-FEB-1982	
	SN-UNKNOWN	HRS/MS	O/C	0		0		
	REF: AMM 28-10-00	AFL		0		0		
280276	VALVE, SINGLE POINT REFUEL VENT RIGHT							F5
28.080	3653672	MOS					11-FEB-1982	
	SN-UNKNOWN	HRS/MS	O/C	0		0		
	REF: AMM 28-10-00	AFL		0		0		
CHAPTER 29 HYDRAULIC POWER								
290221	ACCUMULATOR, EMERGENCY							F5
29.080	3713008	MOS					11-FEB-1982	\$472.
	601	HRS/MS	O/C	0		0		
	REF: AMM 29-20-00	AFL				0		
290151	ACCUMULATOR, LEFT HYDRAULIC							F5
29.130	4-713569-1	MOS					11-FEB-1982	
	SN-UNKNOWN	HRS/MS	O/C	0		0		
	REF: NO REF	AFL				0		
290186	ACCUMULATOR, RIGHT HYDRAULIC							F5
29.130	4-713569-1	MOS					11-FEB-1982	
	SN-UNKNOWN	HRS/MS	O/C	0		0		
	REF: NO REF	AFL				0		
290261	ATTENUATOR, NO.1 ENG HYDRAULIC							F5
29.040	3713562-1	MOS					11-FEB-1982	
	0601	HRS/MS	O/C	0		0		
	REF: AMM 29-10-00	AFL				0		
290266	ATTENUATOR, NO.2 ENG HYDRAULIC							F5
29.040	3713562-1	MOS					11-FEB-1982	
	0591	HRS/MS	O/C	0		0		
	REF: AMM 29-10-00	AFL				0		
290119	CHECK VALVE, RESERVOIR BLEED AIR							F5
29.180	PN	MOS					11-FEB-1982	
	SN-UNKNOWN	HRS/MS	O/C	0		0		
	REF: NO REF	AFL				0		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Page 36 of 107

Aircraft Model - 1124 WESTWIND

Report Date **11-APR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
290248	FUSE, EMERGENCY HYDRAULIC							F2
29.110	3713047	MOS					11-FEB-1982	
	3383	HRS/MS	O/C	0		0		
	REF: AMM 29-30-00	AFL				0		
290246	GAUGE, EMERGENCY HYDRAULIC PRESSURE							F3
29.100	4883746-1	MOS					11-FEB-1982	
	SN-UNKNOWN	HRS/MS	O/C	0		0		
	REF: AMM 29-30-00	AFL				0		
290148	GAUGE, LEFT ACCUMULATOR PRESSURE							F5
29.140	7253014-501	MOS					11-FEB-1982	
	SN-UNKNOWN	HRS/MS	O/C	0		0		
	REF: NO REF	AFL				0		
290183	GAUGE, RIGHT ACCUMULATOR PRESSURE							F5
29.140	7253014-501	MOS					11-FEB-1982	
	SN-UNKNOWN	HRS/MS	O/C	0		0		
	REF: NO REF	AFL				0		
290236	INDICATOR, HYDRAULIC PRESSURE							F3
29.160	4883746-1	MOS					11-FEB-1982	
	8007104	HRS/MS	O/C	0		0		
	REF: AMM 29-30-00	AFL				0		
290211	PUMP, EMERGENCY HYDRAULIC							F5
29.060	3713010-505	MOS					11-FEB-1982	\$805.
	13747	HRS/MS	O/C	0		0		
	REF: AMM 29-20-00	AFL				0		
290215	FUNCTIONAL TEST EMERGENCY HYDRAULIC FUSE							
29.110		MOS	36				30-NOV-1999	30-NOV-2002
		HRS/MS	1200			6991	8191	
	REF: AMM 29-30-06	AFL				5163		
290141	PUMP, HYDRAULIC NO. 1							E1
29.120	5713524-507	MOS			0		09-OCT-1990	
	B1-58	HRS/MS	O/C		0	4718		
	REF: AMM 29-10-00	AFL			0	3309		
+ 290143	INSPECT/LUBRICATE NO.1 ENGINE HYDRAULIC PUMP SPLINES							E1
29.120	PKG 1, 2, 3	MOS					26-JUN-2001	
		HRS/MS	200			7687		1
	REF: AMM 29-10-00	AFL				5594		
290176	PUMP, HYDRAULIC NO. 2							E2
29.120	5713524-507	MOS					04-FEB-1994	
	A2-84	HRS/MS	O/C		0	5390		1
	REF: AMM 29-10-00	AFL				4040		
+ 290178	INSPECT/LUBRICATE NO.2 ENGINE HYDRAULIC PUMP SPLINES							E2
29.120	PKG 1, 2, 3	MOS					26-JUN-2001	
		HRS/MS	200			7687		1
	REF: AMM 29-10-00	AFL				5594		

Aircraft Model - 1124 WESTWIND

Report Date **11-APR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
290121		REGULATOR, RESERVOIR AIR PRESSURE							F5
	29.050	3713015	MOS				11-FEB-1982		\$1046.
		509	HRSMSC	O/C	0		0		
		REF: AMM 29-10-00	AFL				0		
290118		CLEAN/CHECK HYDRAULIC RESERVOIR AIR PRESSURE CHECK VALVE							F5
	29.050	PKG 2, 3	MOS				26-JUN-2001		
		509	HRSMSC	400			7687		
		REF: AMM 5-20-00	AFL				5594		
+ 290131		INSPECT/REPLACE RESERVOIR AIR PRESSURE FILTER							F5
	29.050	PKG 3	MOS				26-JUL-2000		
			HRSMSC	800			7325		
		REF: AMM 29-10-00	AFL				5360		
+ 290116		INSPECT/REPLACE RESERVOIR AIR VENT FILTER							F5
	29.050	PKG 3	MOS				26-JUL-2000		
		509	HRSMSC	800			7325		
		REF: AMM 29-10-10	AFL				5360		
290171		REPLACE NO.1 ENGINE HIGH PRESSURE HYDRAULIC FILTER ELEMENT							F5
	29.050	PKG 3	MOS				26-JUL-2000		
			HRSMSC	800			7325		
		REF: AMM 29-10-10	AFL				5360		
290206		REPLACE NO.2 ENGINE HIGH PRESSURE HYDRAULIC FILTER ELEMENT							F5
	29.050	PKG 3	MOS				26-JUL-2000		
			HRSMSC	800			7325		
		REF: AMM 29-10-10	AFL				5360		
290101		RESERVOIR, HYDRAULIC							F5
	29.010	5713014-505	MOS				11-FEB-1982		
		SN-UNKNOWN	HRSMSC	O/C	0		0		
		REF: AMM 29-10-00	AFL				0		
290106		REPLACE FILTER							F5
	29.010	PKG 3	MOS				26-JUL-2000		
			HRSMSC	800			7325		
		REF: AMM 29-10-00	AFL				5360		
290226		SWITCH, EMERGENCY HYDRAULIC PRESSURE							F5
	29.090	4833010-515	MOS				11-FEB-1982		
		872	HRSMSC	O/C	0		0		
		REF: AMM 29-20-00	AFL				0		
290241		SWITCH, NO.1 LOW HYDRAULIC PRESSURE WARNING							F5
	29.170	4713533-1	MOS				11-FEB-1982		
		798	HRSMSC	O/C	0		0		1
		REF: AMM 29-30-00	AFL				0		
290243		SWITCH, NO.2 LOW HYDRAULIC PRESSURE WARNING							F5
	29.170	4713533-1	MOS				11-FEB-1982		
		788	HRSMSC	O/C	0		0		
		REF: AMM 29-30-00	AFL				0		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
290231	TRANSMITTER, HYDRAULIC PRESSURE							F5
29.150	3883028	MOS					11-FEB-1982	\$507.
	8005119	HRS/MS	O/C	0		0		
	REF: AMM 29-30-00	AFL				0		
290133	VALVE, BLEED RETURN							F5
29.180	PN	MOS					11-FEB-1982	
	SN-UNKNOWN	HRS/MS	O/C	0		0		
	REF: NO REF	AFL				0		
290216	VALVE, EMERGENCY THERMAL RELIEF							F5
29.070	4713011-1	MOS					11-FEB-1982	
	1L82	HRS/MS	O/C	0		0		
	REF: NO REF	AFL				0		
290138	VALVE, HYDRAULIC PRESSURE RELIEF							F5
29.190	373596-501	MOS					11-FEB-1982	
	158	HRS/MS	O/C	0		0		
	REF: NO REF	AFL				0		
290146	VALVE, LEFT HYDRAULIC SHUTOFF							E1
29.020	713020-	MOS					11-FEB-1982	\$322.
	080	HRS/MS	O/C	0		0		
	REF: AMM 29-10-00	AFL				0		
290136	VALVE, MANUAL HIGH-PRESSURE RELIEF							F5
29.030	3723628	MOS					11-FEB-1982	
	SN-UNKNOWN	HRS/MS	O/C	0		0		
	REF: NO REF	AFL				0		
290181	VALVE, RIGHT HYDRAULIC SHUTOFF							E2
29.020	713020-	MOS					11-FEB-1982	\$322.
	074	HRS/MS	O/C	0		0		
	REF: AMM 29-10-00	AFL				0		
290271	VALVE, THERMAL HYDRAULIC RELIEF							F5
29.190	3713554	MOS					11-FEB-1982	
	0168	HRS/MS	O/C	0		0		
	REF: NO REF	AFL				0		
CHAPTER 30	ICE AND RAIN PROTECTION							
+ 300133	FUNCTIONAL CHECK PNEUMATIC DE-ICER BOOTS.							F3
30.100	PKG 3	MOS					26-JUL-2000	
		HRS/MS	800			7325		
	REF: AMM 30-10-00	AFL				5360		
+ 300150	INSPECT COPILOT WINDSHIELD CYCLING CONTACTOR							F3
30.140	PKG 1, 2, 3	MOS					26-JUN-2001	
		HRS/MS	200			7687		
	REF: AMM 30-40-00	AFL				5594		
+ 300147	INSPECT PILOT WINDSHIELD CYCLING CONTACTOR							F3
30.140	PKG 1, 2, 3	MOS					26-JUN-2001	
		HRS/MS	200			7687		
	REF: AMM 30-40-00	AFL				5594		

Aircraft Model - 1124 WESTWIND

Report Date **11-APR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT----- TSN TSO TSR TSI ADJ	INSTALLATION	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
+	300163	INSPECT WINDSHIELD WIPER ASSEMBLY								
	30.160	PKG 1, 2, 3	MOS					26-JUN-2001		
		REF: AMM 30-40-00	HRS/MSA	200				7687		
			AFL					5594		
	300170	OPERATIONAL TEST P2T2 SENSOR HEATER								
	30.150	PKG 1, 2, 3	MOS					26-JUN-2001		
		REF: AMM 30-20-00	HRS/MSA	200				7687		
			AFL					5594		
	300165	REPLACE WIPER BLADE ELEMENT								
		NOTE: IT IS RECOMMENDED TO REPLACE WIPER BLADE ELEMENT EVERY 6 MONTHS OR 250 HOURS.								
	30.170		MOS					06-NOV-2001		
		REF: AMM 30-40-00	HRS/MSA					7774		
			AFL					5641		
	300101	CHECK VALVE, DE-ICER LEFT								F4
	30.010	PN	MOS					11-FEB-1982		
		SN-UNKNOWN	HRS/MSA	O/C	0			0		
		REF: AMM 30-10-00	AFL					0		
+	300102	INSPECT								F4
	30.010	PKG 2, 3	MOS					26-JUN-2001		
		REF: AMM 30-10-00	HRS/MSA	400				7687		
			AFL					5594		
	300103	CHECK VALVE, DE-ICER RIGHT								F4
	30.010	PN	MOS					11-FEB-1982		
		SN-UNKNOWN	HRS/MSA	O/C	0			0		
		REF: AMM 30-10-00	AFL					0		
+	300104	INSPECT								F4
	30.010	PKG 2, 3	MOS					26-JUN-2001		
		REF: AMM 30-10-00	HRS/MSA	400				7687		
			AFL					5594		
	300146	CONTROLLER, WINDSHIELD TEMPERATURE LEFT								F3
	30.110	HYLZ9661	MOS					22-FEB-2000		
		982B	HRS/MSA	O/C	0			7107		
		REF: AMM 30-40-00	AFL					5232		
	300148	CONTROLLER, WINDSHIELD TEMPERATURE RIGHT								F3
	30.110	833034-1	MOS					11-FEB-1982		
		SN-UNKNOWN	HRS/MSA	O/C	0			0		
		REF: AMM 30-40-00	AFL					0		
	300111	EJECTOR, AIR								F4
	30.030	850278-1	MOS					11-FEB-1982		
		RF3295	HRS/MSA	O/C	0			0		
		REF: AMM 30-10-00	AFL					0		
	300156	MOTOR, WINDSHIELD WIPER LEFT								F3
	30.130	XW21126-315-R32	MOS					26-JUL-2000		\$354.
		2-22826	HRS/MSA	O/C	0			7325		7
		REF: AMM 30-40-00	AFL					5360		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
300161		MOTOR, WINDSHIELD WIPER RIGHT							
	30.130	5823099-402	MOS					11-FEB-1982	F3
		213743	HRS/MS	O/C	0		0		
		REF: AMM 30-40-00	AFL				0		
300106		REGULATOR, PRESSURE							
	30.020	4753042-501	MOS					11-FEB-1982	F4
		3300U	HRS/MS	O/C	0		0		\$403.
		REF: AMM 30-10-00	AFL				0		
300116		SWITCH, PRESSURE							
	30.040	3753045-507	MOS					31-OCT-1992	F4
		287	HRS/MS	O/C	0		5170		
		REF: AMM 30-10-00	AFL				3802		
300141		SWITCH, PRESSURE INDICATOR NO. 1 ENGINE							
	30.090	12299	MOS					11-FEB-1982	E1
		SN-UNKNOWN	HRS/MS	O/C	0		0		
		REF: AMM 30-20-00	AFL				0		
300144		SWITCH, PRESSURE INDICATOR NO. 2 ENGINE							
	30.090	12299	MOS			06/29/1993		29-DEC-1992	E2
		1246	HRS/MS	O/C	0		5203		
		REF: AMM 30-20-00	AFL				4938		
300121		SWITCH, VACUUM							
	30.050	3-753064-501	MOS					11-FEB-1982	F4
		277	HRS/MS	O/C	0		0		
		REF: AMM 30-10-00	AFL				0		
300151		SWITCH, WINDSHIELD THERMOSTAT LEFT							
	30.120	PN	MOS					11-FEB-1982	F3
		SN-UNKNOWN	HRS/MS	O/C	0		0		
		REF: AMM 30-40-00	AFL				0		
300153		SWITCH, WINDSHIELD THERMOSTAT RIGHT							
	30.120	PN	MOS					11-FEB-1982	F3
		SN-UNKNOWN	HRS/MS	O/C	0		0		
		REF: AMM 30-40-00	AFL				0		
300131		TIMER, DE-ICER							
	30.070	3-753046-1	MOS					11-FEB-1982	F4
		G426	HRS/MS	O/C	0		0		
		REF: AMM 30-10-00	AFL				0		
300126		VALVE, DISTRIBUTOR							
	30.060	753511-1	MOS					11-FEB-1982	F4
		41359U	HRS/MS	O/C	0		0		
		REF: AMM 30-10-00	AFL				0		
300136		VALVE, NO. 1 NACELLE ANTI-ICE							
	30.080	F10A-5-SCP-102-5	MOS					30-JAN-1984	E1
		193RW	HRS/MS	O/C	0		1468		
		REF: AMM 30-20-00	AFL				908		

Aircraft Model - 1124 WESTWIND

Report Date **11-APR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT----- TSN TSO TSR TSI ADJ	INSTALLATION	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
300138	VALVE, NO.2 NACELLE ANTI-ICE								E2
30.080	F10A-5-SCP-102-5	MOS					12-OCT-1983		
	8100435	HRS/MSC	O/C	0			1321		
	REF: AMM 30-20-00	AFL					810		
CHAPTER 31	INDICATING/RECORDING SYSTEMS								
310101	CLOCK, COCKPIT DIGITAL								F3
31.010	811-B	MOS					11-FEB-1982		
	15324	HRS/MSC	O/C	0			0		
	REF: NO REF	AFL					0		
CHAPTER 32	LANDING GEAR								
321189U	-- REPL SPARE MAIN WHEEL BLT								
		MOS					26-NOV-1989		
		HRS/MSC	O/C				4427		
	REF:	AFL					2984		
322136	BLEED BRAKE SYSTEM								L2
32.400		MOS					17-JAN-2001		
		HRS/MSC	O/C				7494		
	REF: AMM 32-43-00	AFL					5466		
320678	DYE PENETRANT CHECK LEFT WHEEL AXLE								L1
32.550	PKG 2, 3	MOS					26-JUN-2001		
		HRS/MSC	400				7687		
	REF: AMM 5-20-04	AFL					5594		
321178	DYE PENETRANT CHECK RIGHT WHEEL AXLE								L2
32.550	PKG 2, 3	MOS					26-JUN-2001		
		HRS/MSC	400				7687		
	REF: AMM 5-20-04	AFL					5594		
+ 322176	FUNCTIONAL CHECK ANTI-SKID DETECTOR SYSTEM								F3
32.420	PKG 2, 3	MOS					26-JUN-2001		
		HRS/MSC	400				7687		1
	REF: AMM 32-44-00	AFL					5594		
+ 322211	FUNCTIONAL TEST EMERGENCY GEAR EXTENSION								F3
32.450	PKG 3	MOS					26-JUL-2000		
		HRS/MSC	800				7325		
	REF: AMM 32-30-00	AFL					5360		
+ 322206	FUNCTIONAL TEST EMERGENCY GEAR EXTENSION CONTROL CABLE								F3
32.440	PKG 1, 2, 3	MOS					26-JUN-2001		
		HRS/MSC	200				7687		1
	REF: AMM 32-30-00	AFL					5594		
+ 322191	FUNCTIONAL TEST LANDING GEAR (NORMAL)								F3
32.430	PKG 2, 3	MOS					26-JUN-2001		
		HRS/MSC	400				7687		
	REF: AMM 32-30-00	AFL					5594		
+ 322201	FUNCTIONAL TEST LANDING GEAR FREE FALL								F3
32.430	PKG 2, 3	MOS					26-JUN-2001		
		HRS/MSC	400				7687		
	REF: See Workcard	AFL					5594		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
+ 320691 32.020	INSPECT LEFT MAIN GEAR/WELL (A) PKG 1, 2, 3	MOS HRS/MSA AFL	200			26-JUN-2001 7687 5594		L1 1.5
	REF: AMM 5-20-04							
+ 320201 32.0101	INSPECT NOSE GEAR (A) PKG 1, 2, 3	MOS HRS/MSA AFL	200			26-JUN-2001 7687 5594		L3 1.5
	REF: AMM 5-20-01							
+ 320206 32.0102	INSPECT NOSE GEAR (B) PKG 2, 3	MOS HRS/MSA AFL	400			26-JUN-2001 7687 5594		L3
	REF: AMM 5-20-01							
+ 322156 32.410	INSPECT/CLEAN LEFT ANTI-SKID DETECTOR PKG 1, 2, 3	MOS HRS/MSA AFL	200			26-JUN-2001 7687 5594		L1 1
	REF: AMM 5-20-04							
+ 322171 32.410	INSPECT/CLEAN RIGHT ANTI-SKID DETECTOR PKG 1, 2, 3	MOS HRS/MSA AFL	200			26-JUN-2001 7687 5594		L2 1
	REF: AMM 5-20-04							
320607 32.570	LUBRICATE LEFT ACTUATOR BOLTS PKG 2, 3	MOS HRS/MSA AFL	400			26-JUN-2001 7687 5594		L1
	REF: AMM 5-20-04/SL WW-2494R3							
321107 32.570	LUBRICATE RIGHT ACTUATOR BOLTS PKG 2, 3	MOS HRS/MSA AFL	400			26-JUN-2001 7687 5594		L2
	REF: AMM 5-20-04/SL WW-2494R3							
+ 322174 32.425	OPERATIONAL CHECK ANTI-SKID LIGHTS PKG 1, 2, 3	MOS HRS/MSA AFL	200			26-JUN-2001 7687 5594		F3 .5
	REF: AMM 32-44-00							
320686 32.180	REPLACE LEFT MAIN WHEEL BOLTS	MOS HRS/MSA AFL	O/C			09-NOV-1996 5951 4589		L1
	REF: NO REF							
321186 32.180	REPLACE RIGHT MAIN WHEEL BOLTS	MOS HRS/MSA AFL	O/C			09-NOV-1996 5951 4589		L2
	REF: NO REF							
320186 32.150	RIG STEERING SYSTEM	MOS HRS/MSA AFL	C/C			11-FEB-1982 0 0		L3
	REF: AMM 32-50-00							

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEMNO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
320621	AXLE, PISTON ROD FORK/ LEFT							L1
32.220	ES12908-503	MOS				11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0		0		
	REF: AMM 32-20-01	AFL				0		
321121	AXLE, PISTON ROD FORK/ RIGHT							L2
32.220	ES12908-504	MOS				11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0		0		
	REF: AMM 32-20-01	AFL				0		
321611	BOTTLE, EMERGENCY STORAGE						LIFE LIMIT	F5
32.350	3753015-501	MOS	288	0		11-FEB-1982	11-FEB-2006	
	07510A1	HRS/MS		0		0		1
	REF: AMM 32-30-12	AFL		0		0		
+ 321616	CHECK LANDING GEAR EMERGENCY SYSTEM PRESSURE							F5
32.350	PKG 2, 3	MOS				26-JUN-2001		
		HRS/MS	400			7687		
	REF: AMM 12-10-04	AFL				5594		
+ 321613	HYDROSTATIC TEST							F5
32.350		MOS	36			26-OCT-1999	26-OCT-2002	
		HRS/MS				6961		
	REF: AMM 32-30-12	AFL				5135		
320171	BRACE ASSEMBLY, DRAG NOSE GEAR							L3
32.240	PN	MOS				11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0		0		
	REF: AMM 32-20-02	AFL				0		
320173	ADJUST PRELOAD							L3
32.240		MOS				11-FEB-1982		
		HRS/MS	C/C			0		
	REF: AMM 32-20-02	AFL				0		
320611	BRACE ASSEMBLY, SIDE/JURY LEFT MAIN GEAR							L1
32.230	EA1681-503	MOS				11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0		0		
	REF: AMM 32-10-02	AFL				0		
320616	ADJUST LEFT JURY BRACE PRELOAD							L1
32.230		MOS				11-FEB-1982		
		HRS/MS	C/C			0		
	REF: AMM 32-10-02	AFL				0		
321111	BRACE ASSEMBLY, SIDE/JURY RIGHT MAIN GEAR							L2
32.230	EA1681-503	MOS				11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0		0		
	REF: AMM 32-10-02	AFL				0		
321116	ADJUST RIGHT JURY BRACE PRELOAD							L2
32.230		MOS				11-FEB-1982		
		HRS/MS	C/C			0		
	REF: AMM 32-10-02	AFL				0		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Page 44 of 107

Aircraft Model - 1124 WESTWIND

Report Date **11-APR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEMNO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
320232	BRACKET, LOWER STEERING NOSE GEAR							L3
32.600	A0122360300-001	MOS				22-FEB-2000		
	SN-UNKNOWN	HRS/MS	O/C			7107		
	REF: AMM 32-50-08	AFL				5232		
+ 320238	INSPECT							L3
32.600		MOS				22-FEB-2000		
		HRS/MS	1600			7107	8707	
	REF: AMM 32-50-08	AFL				5232		
SB 1124-32-139 LOWER	LANDING GEAR SERVICE BULLETIN							
ASSOCIATED		MOS						
	REF:	HRS/MS	A/R			0		
	Method of Compliance: OPEN	AFL				0		
320231	BRACKET, UPPER STEERING NOSE GEAR							L3
32.600	A01223603000-001	MOS				22-FEB-2000		
	SN-UNKNOWN	HRS/MS	O/C			7107		
	REF: AMM 32-50-08	AFL				5232		
+ 320237	INSPECT							L3
32.600		MOS				22-FEB-2000		
		HRS/MS	1600			7107	8707	
	REF: AMM 32-50-08	AFL				5232		
SB 1124-32-139 UPPER	LANDING GEAR SERVICE BULLETIN							
ASSOCIATED	PKG 3	MOS				26-JUL-2000		
		HRS/MS	800			7325	8125	
	REF:	AFL				5360		
	Method of Compliance: OPEN							
322113	BRAKE, LEFT MAIN GEAR							L1
32.390	5002805-3	MOS			0	17-JAN-2001		\$1978.
	21139-1	HRS/MS	O/C		0	7494		2
	REF: AMM 32-43-01	AFL			0	5466		
322136	BLEED BRAKE SYSTEM							L2
32.400		MOS				17-JAN-2001		
ASSOCIATED		HRS/MS	O/C			7494		
	REF: AMM 32-43-00	AFL				5466		
+ 322116	INSPECT/CHECK LEFT BRAKE LININGS							L1
32.390	PKG 1, 2, 3	MOS				26-JUN-2001		
		HRS/MS	200			7687		1
	REF: AMM 32-43-01	AFL				5594		
322128	BRAKE, RIGHT MAIN GEAR							L2
32.390	5002805-3	MOS			0	17-JAN-2001		\$1978.
	JAN86-531	HRS/MS	O/C		0	7494		2
	REF: AMM 32-43-01	AFL			0	5466		
322136	BLEED BRAKE SYSTEM							L2
32.400		MOS				17-JAN-2001		
ASSOCIATED		HRS/MS	O/C			7494		
	REF: AMM 32-43-00	AFL				5466		

Aircraft Model - 1124 WESTWIND
Report Date 11-APR-2002
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
+ 322131	32.390	INSPECT/CHECK RIGHT BRAKE LININGS PKG 1, 2, 3	MOS HRS/MS AFL	200			26-JUN-2001 7687 5594	L2 1	
322141	32.490	CONTROL BOX, ANTI-SKID 5-823519-503 299 REF: AMM 32-44-01	MOS HRS/MS AFL	O/C	0		11-FEB-1982 0 0	F5 2	
+ 322176	32.420 ASSOCIATED	FUNCTIONAL CHECK ANTI-SKID DETECTOR SYSTEM PKG 2, 3 REF: AMM 32-44-00	MOS HRS/MS AFL	400			26-JUN-2001 7687 5594	F3 1	
320121	32.060	CYLINDER, ACTUATOR NOSE GEAR 5713059-505 0484 REF: AMM 32-30-06	MOS HRS/MS AFL	O/C	0		11-FEB-1982 0 0	L3 \$483. 3	
320646	32.310	CYLINDER, AFT ACTUATING LEFT MAIN GEAR 5713061-505 SN-UNKNOWN REF: AMM 32-30-03	MOS HRS/MS AFL	O/C			09-JUN-1989 4274 2800	L1 \$443.	
321146	32.310	CYLINDER, AFT ACTUATING RIGHT MAIN GEAR 5713061-505 0704 REF: AMM 32-30-03	MOS HRS/MS AFL	O/C	0		13-NOV-1995 5718 4397	L2 \$443.	
320641	32.300	CYLINDER, FORWARD ACTUATING LEFT MAIN GEAR 5713061-505 0878 REF: AMM 32-30-03	MOS HRS/MS AFL	O/C	0		11-FEB-1982 0 0	L1 \$443.	
321141	32.300	CYLINDER, FORWARD ACTUATING RIGHT MAIN GEAR 5713061-505 0856 REF: AMM 32-30-03	MOS HRS/MS AFL	O/C	0		11-FEB-1982 0 0	L2 \$443.	
320181	32.140	CYLINDER, STEERING ACTUATING LEFT 4713096-509 1L31 REF: AMM 32-50-02	MOS HRS/MS AFL	O/C	0		11-FEB-1982 0 0	L3 5	
320184	32.140	CYLINDER, STEERING ACTUATING RIGHT 4713096-509 1L27 REF: AMM 32-50-02	MOS HRS/MS AFL	O/C	0		11-FEB-1982 0 0	L3 5	
320651	32.260	CYLINDER, UNLOCK LEFT MAIN GEAR 4713058-505 1057 REF: AMM 32-30-05	MOS HRS/MS AFL	O/C	0		11-FEB-1982 0 0	L1	

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND
 Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
 A/C Serial #: 368 A/C Reg. #: N368MD

Report Date **11-APR-2002**

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
321151	CYLINDER, UNLOCK RIGHT MAIN GEAR							L2
32.260	4713058-505	MOS					11-FEB-1982	
	1091	HRSMSC	O/C	0		0		
	REF: AMM 32-30-05	AFL				0		
320126	CYLINDER, UNLOCK NOSE GEAR							L3
32.070	4713005-501	MOS				06/08/1995	08-DEC-1994	
	0567	HRSMSC	O/C	0		5526		
	REF: AMM 32-30-08	AFL				4218		
322151	DETECTOR, ANTI-SKID LEFT MAIN GEAR							L1
32.410	5-713513-503	MOS					13-JUL-1988	\$1064.
	200	HRSMSC	O/C	0		3978		1
	REF: AMM 32-44-06	AFL				2511		
+ 322176	FUNCTIONAL CHECK ANTI-SKID DETECTOR SYSTEM							F3
32.420	PKG 2, 3	MOS					26-JUN-2001	
ASSOCIATED		HRSMSC	400			7687		1
	REF: AMM 32-44-00	AFL				5594		
+ 322156	INSPECT/CLEAN LEFT ANTI-SKID DETECTOR							L1
32.410	PKG 1, 2, 3	MOS					26-JUN-2001	
ASSOCIATED		HRSMSC	200			7687		1
	REF: AMM 5-20-04	AFL				5594		
+ 322174	OPERATIONAL CHECK ANTI-SKID LIGHTS							F3
32.425	PKG 1, 2, 3	MOS					26-JUN-2001	
ASSOCIATED		HRSMSC	200			7687		.5
	REF: AMM 32-44-00	AFL				5594		
322166	DETECTOR, ANTI-SKID RIGHT MAIN GEAR							L2
32.410	5-713513-504	MOS					17-DEC-1983	\$1064.
	553	HRSMSC	O/C	0		1454		1
	REF: AMM 32-44-06	AFL				878		
+ 322176	FUNCTIONAL CHECK ANTI-SKID DETECTOR SYSTEM							F3
32.420	PKG 2, 3	MOS					26-JUN-2001	
ASSOCIATED		HRSMSC	400			7687		1
	REF: AMM 32-44-00	AFL				5594		
+ 322171	INSPECT/CLEAN RIGHT ANTI-SKID DETECTOR							L2
32.410	PKG 1, 2, 3	MOS					26-JUN-2001	
ASSOCIATED		HRSMSC	200			7687		1
	REF: AMM 5-20-04	AFL				5594		
+ 322174	OPERATIONAL CHECK ANTI-SKID LIGHTS							F3
32.425	PKG 1, 2, 3	MOS					26-JUN-2001	
ASSOCIATED		HRSMSC	200			7687		.5
	REF: AMM 32-44-00	AFL				5594		
322111	FUSE, BRAKE HYDRAULIC LEFT							W1
32.380	3-713047	MOS					11-FEB-1982	
	1797	HRSMSC	O/C	0		0		
	REF: AMM 32-43-04	AFL				0		

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
322126		FUSE, BRAKE HYDRAULIC RIGHT							W2
32.380		3-713047	MOS				11-FEB-1982		
		3371	HRS/MS	O/C	0		0		
		REF: AMM 32-43-04	AFL				0		
320601		GEAR ASSEMBLY, MAIN LEFT							L1
32.210		400-144-511	MOS				11-FEB-1982		
		1L195	HRS/MS	O/C	0		0		
		REF: AMM 32-10-01	AFL				0		
320631		CHECK MAIN GEAR PARALLELISM							L1
32.470			MOS				11-FEB-1982		
			HRS/MS	C/C			0		
		REF: AMM 32-10-01	AFL				0		
320634		CHECK LEFT MAIN GEAR CLEARANCE							L1
32.480			MOS				11-FEB-1982		
			HRS/MS	C/C			0		
		REF: AMM 32-10-01	AFL				0		
+ 322211		FUNCTIONAL TEST EMERGENCY GEAR EXTENSION							F3
32.450		PKG 3	MOS				26-JUL-2000		
ASSOCIATED			HRS/MS	800			7325		
		REF: AMM 32-30-00	AFL				5360		
+ 322208		FUNCTIONAL TEST EMERGENCY GEAR EXTENSION CONTROL CABLE							F3
32.440		PKG 1, 2, 3	MOS				26-JUN-2001		
ASSOCIATED			HRS/MS	200			7687		1
		REF: AMM 32-30-00	AFL				5594		
+ 322191		FUNCTIONAL TEST LANDING GEAR (NORMAL)							F3
32.430		PKG 2, 3	MOS				26-JUN-2001		
ASSOCIATED			HRS/MS	400			7687		
		REF: AMM 32-30-00	AFL				5594		
+ 322201		FUNCTIONAL TEST LANDING GEAR FREE FALL							F3
32.430		PKG 2, 3	MOS				26-JUN-2001		
ASSOCIATED			HRS/MS	400			7687		
		REF: See Workcard	AFL				5594		
SL WW-2494 R3 LEFT		LANDING GEAR SERVICE LETTER							L1
ASSOCIATED			MOS				26-JUN-2001		
			HRS/MS	300			7687	7987	
		REF: See Workcard	AFL				5594		
320606		LUBRICATE LEFT MAIN GEAR							L1
32.030		PKG 1, 2, 3	MOS				26-JUN-2001		
			HRS/MS	200			7687		.5
		REF: AMM 12-20-00	AFL				5594		
320636		SERVICE LEFT MAIN GEAR SHOCK STRUT							L1
32.040		PKG 2, 3	MOS				26-JUN-2001		
			HRS/MS	400			7687		2
		REF: AMM 12-10-04	AFL				5594		

 ? - Insufficient Information
 + Task exists in FAA Manual
 4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
SL	WW-24103 LEFT	SERVICE LETTER							L1
	ASSOCIATED		MOS						
		REF:	HRS/MS	A/R			0		
		Method of Compliance: OPEN	AFL				0		
321101		GEAR ASSEMBLY, MAIN RIGHT							L2
32.210		400-144-512	MOS				11-FEB-1982		
		1L195	HRS/MS	O/C	0		0		
		REF: AMM 32-10-01	AFL				0		
321134		CHECK RIGHT MAIN GEAR CLEARANCE							L2
32.480			MOS				11-FEB-1982		
			HRS/MS	C/C			0		
		REF: AMM 32-10-01	AFL				0		
+ 322211		FUNCTIONAL TEST EMERGENCY GEAR EXTENSION							F3
32.450		PKG 3	MOS				26-JUL-2000		
	ASSOCIATED		HRS/MS	800			7325		
		REF: AMM 32-30-00	AFL				5360		
+ 322206		FUNCTIONAL TEST EMERGENCY GEAR EXTENSION CONTROL CABLE							F3
32.440		PKG 1, 2, 3	MOS				26-JUN-2001		
	ASSOCIATED		HRS/MS	200			7687	1	
		REF: AMM 32-30-00	AFL				5594		
+ 322191		FUNCTIONAL TEST LANDING GEAR (NORMAL)							F3
32.430		PKG 2, 3	MOS				26-JUN-2001		
	ASSOCIATED		HRS/MS	400			7687		
		REF: AMM 32-30-00	AFL				5594		
+ 322201		FUNCTIONAL TEST LANDING GEAR FREE FALL							F3
32.430		PKG 2, 3	MOS				26-JUN-2001		
	ASSOCIATED		HRS/MS	400			7687		
		REF: See Workcard	AFL				5594		
SL	WW-2494 R3 RIGHT	LANDING GEAR SERVICE LETTER							L2
	ASSOCIATED		MOS				26-JUN-2001		
		REF: See Workcard	HRS/MS	300			7687	7987	
		Method of Compliance: OPEN	AFL				5594		
321106		LUBRICATE RIGHT MAIN GEAR							L2
32.030		PKG 1, 2, 3	MOS				26-JUN-2001		
			HRS/MS	200			7687	.5	
		REF: AMM 12-20-00	AFL				5594		
SL	WW-24103 RIGHT	SERVICE LETTER							L2
	ASSOCIATED		MOS						
		REF:	HRS/MS	A/R			0		
		Method of Compliance: OPEN	AFL				0		
321136		SERVICE RIGHT MAIN GEAR SHOCK STRUT							L2
32.040		PKG 2, 3	MOS				26-JUN-2001		
			HRS/MS	400			7687	2	
		REF: AMM 12-10-04	AFL				5594		

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
320101	32.050	NOSE GEAR ASSEMBLY, 400-143-511 1L184 REF: AMM 32-20-01	MOS HRS/MSC AFL	O/C	0		11-FEB-1982 0 0		L3
320179	32.580	INSPECT NOSE STEERING CABLES PKG 3 REF: AMM 32-50-07	MOS HRS/MSC AFL	800			26-JUL-2000 7325 5360		L1
320120	32.520	INSPECT OUTER STRUT BODY FORGING REF: AMM 32-20-01	MOS HRS/MSC AFL	1200			22-FEB-2000 7107 5232	8307	L3
320118	32.540	INSPECT/LUBRICATE UPPER/LOWER STRUT BEARINGS BODY REF: AMM 32-20-01	MOS HRS/MSC AFL	24 1200			22-FEB-2000 7107 5232	22-FEB-2002 8307	L3
320106	32.030	LUBRICATE NOSE GEAR/DOORS PKG 1, 2, 3 REF: AMM 12-20-00	MOS HRS/MSC AFL	200			26-JUN-2001 7687 5594		L3
320180	32.590	LUBRICATE NOSE STEERING CONTROL CABLES PKG 3 REF: AMM 12-20-00	MOS HRS/MSC AFL	800			26-JUL-2000 7325 5360		L1
SB 900280	ASSOCIATED	SB WW 24-28A SERVICE BULLETIN REF: See Workcard Method of Compliance: OPEN	MOS HRS/MSC AFL	1200			22-FEB-2000 7107 5232		L3
320116	32.040	SERVICE SHOCK STRUT PKG 2, 3 REF: AMM 12-10-04	MOS HRS/MSC AFL	400			26-JUN-2001 7687 5594		L3
320172	32.240	TEST DRAG BRACE DOWNLOCK TENSION PKG 3 REF: AMM 32-20-02	MOS HRS/MSC AFL	800			26-JUL-2000 7325 5360		L3
+ 320110	32.560	X-RAY INSPECT NOSE GEAR SHAFT AND DOOR ASSEMBLIES REF: AMM 5-10-00	MOS HRS/MSC AFL	60 5000			16-JUN-1997 6135 4707	16-JUN-2002 11135	L3
321603	32.200	SELECTOR, GEAR VALVE 713025-501 IL-41 REF: NO REF	MOS HRS/MSC AFL	O/C	0	06/09/1995	09-DEC-1994 5526 4218		F3

 ? - Insufficient Information
 + Task exists in FAA Manual
 4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND

Report Date **11-APR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
320661 32.280	SWITCH, DOWNLOCK LEFT MAIN GEAR 4-823051 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0		L1
320663 32.280	ADJUST REF: AMM 32-60-00	MOS HRS/MSC AFL	C/C							11-FEB-1982 0 0		L1
320131 32.080	SWITCH, DOWNLOCK NOSE GEAR 4-823012-501 SN-UNKNOWN REF: AMM 32-60-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0		L3
320133 32.080	ADJUST REF: AMM 32-60-00	MOS HRS/MSC AFL	C/C							11-FEB-1982 0 0		L3
321161 32.280	SWITCH, DOWNLOCK RIGHT MAIN GEAR 4-823051 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0		L2
321163 32.280	ADJUST REF: AMM 32-60-00	MOS HRS/MSC AFL	C/C							11-FEB-1982 0 0		L2
320666 32.290	SWITCH, GROUND CONTACT LEFT MAIN GEAR 4-823051 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0		L1
320668 32.290	ADJUST REF: AMM 32-60-00	MOS HRS/MSC AFL	C/C							11-FEB-1982 0 0		L1
320141 32.100	SWITCH, GROUND CONTACT NOSE GEAR 4-823053-501 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0		L3
320143 32.100	ADJUST REF: AMM 32-60-00	MOS HRS/MSC AFL	C/C							11-FEB-1982 0 0		L3
321166 32.290	SWITCH, GROUND CONTACT RIGHT MAIN GEAR 4-823024-505 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0		L2

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
321168	32.290	ADJUST	MOS						L2
		REF: AMM 32-60-00	HRSMSC	C/C			11-FEB-1982		
			AFL				0		
							0		
320656	32.270	SWITCH, UPLOCK LEFT MAIN GEAR	MOS						L1
		3-823003	HRSMSC	O/C	0		11-FEB-1982		
		SN-UNKNOWN	AFL				0		
		REF: NO REF					0		
320658	32.270	ADJUST	MOS						L1
		REF: AMM 32-60-00	HRSMSC	C/C			11-FEB-1982		
			AFL				0		
							0		
320136	32.090	SWITCH, UPLOCK NOSE GEAR	MOS						L3
		3-823003	HRSMSC	O/C	0		11-FEB-1982		
		SN-UNKNOWN	AFL				0		
		REF: AMM 32-60-00					0		
320138	32.090	ADJUST	MOS						L3
		REF: AMM 32-60-00	HRSMSC	C/C			11-FEB-1982		
			AFL				0		
							0		
321156	32.270	SWITCH, UPLOCK RIGHT MAIN GEAR	MOS						L2
		3-823003	HRSMSC	O/C	0		11-FEB-1982		
		SN-UNKNOWN	AFL				0		
		REF: NO REF					0		
321158	32.270	ADJUST	MOS						L2
		REF: AMM 32-60-00	HRSMSC	C/C			11-FEB-1982		
			AFL				0		
							0		
320681	32.180	TIRE, LEFT MAIN GEAR	MOS		0				L1
		249K83-3	HRSMSC	O/C	0		09-NOV-1996		
		SN-UNKNOWN	AFL		0		5951	2	
		REF: AMM 32-41-00			0		4589		
321181	32.190	TIRE, RIGHT MAIN GEAR	MOS		0				L2
		249K83-3	HRSMSC	O/C	0		09-NOV-1996		
		SN-UNKNOWN	AFL		0		5951	2	
		REF: AMM 32-41-00			0		4589		
320161	32.110	TIRE, LEFT NOSE GEAR	MOS						L3
		164F43-2	HRSMSC	O/C	0		22-NOV-1995		
		31162139	AFL				5720		
		REF: AMM 32-42-00					4401		
320166	32.120	TIRE, RIGHT NOSE GEAR	MOS						L3
		164F43-2	HRSMSC	O/C	0		29-NOV-1995		
		22051064	AFL				5720		
		REF: AMM 32-42-00					4401		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
320626	UPLOCK, LEFT MAIN GEAR							L1
32.250	5-17 3057-501	MOS					11-FEB-1982	
	SN-UNKNOWN	HRSMSC	O/C	0		0		
	REF: AMM 32-32-04	AFL				0		
321126	UPLOCK, RIGHT MAIN GEAR							L2
32.250	5-17 3057-502	MOS					11-FEB-1982	
	SN-UNKNOWN	HRSMSC	O/C	0		0		
	REF: AMM 32-30-04	AFL				0		
320176	VALVE ASSEMBLY, STEERING							L3
32.130	BA1801-2	MOS					11-FEB-1982	
	1L185	HRSMSC	O/C	0		0		
	REF: AMM 32-50-01	AFL				0		
322146	VALVE, ANTI-SKID CONTROL LEFT							F5
32.500	5723578-1	MOS					11-FEB-1982	
	313A	HRSMSC	O/C	0		0		
	REF: AMM 32-44-02	AFL				0		
322149	CLEAN FILTERS							F5
32.500		MOS					22-FEB-2000	
		HRSMSC	1200			7107	8307	
		AFL				5232		
	REF: AMM 32-41-00							
+ 322176	FUNCTIONAL CHECK ANTI-SKID DETECTOR SYSTEM							F3
32.420	PKG 2, 3	MOS					26-JUN-2001	
ASSOCIATED		HRSMSC	400			7687		1
		AFL				5594		
	REF: AMM 32-44-00							
322161	VALVE, ANTI-SKID CONTROL RIGHT							F5
32.500	5723578-1	MOS					11-FEB-1982	
	503A	HRSMSC	O/C	0		0		
	REF: AMM 32-44-02	AFL				0		
322169	CLEAN FILTERS							F5
32.500		MOS					22-FEB-2000	
		HRSMSC	1200			7107	8307	
		AFL				5232		
	REF: AMM 32-41-00							
+ 322176	FUNCTIONAL CHECK ANTI-SKID DETECTOR SYSTEM							F3
32.420	PKG 2, 3	MOS					26-JUN-2001	
ASSOCIATED		HRSMSC	400			7687		1
		AFL				5594		
	REF: AMM 32-44-00							
322106	VALVE, BRAKE SHUTTLE LEFT							W1
32.370	4-71 3066	MOS					11-FEB-1982	
	2752	HRSMSC	O/C	0		0		
	REF: AMM 32-43-03	AFL				0		
322121	VALVE, BRAKE SHUTTLE RIGHT							W2
32.370	4-71 3066	MOS					11-FEB-1982	
	2775	HRSMSC	O/C	0		0		
	REF: AMM 32-43-03	AFL				0		

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
321606	VALVE, EMERGENCY GEAR EXTENSION										F5
32.340	874521B	MOS								11-FEB-1982	
	SN-UNKNOWN	HRSMSC	O/C	0					0		
	REF: AMM 32-30-11	AFL							0		
321601	VALVE, LANDING GEAR CONTROL										F2
32.320	4753036	MOS								11-FEB-1982	\$644.
	372	HRSMSC	O/C	0					0		25
	REF: AMM 32-30-01	AFL							0		
320177	VALVE, NOSE STEERING SOLENOID										L3
32.170	713557-501	MOS								11-FEB-1982	
	SN-UNKNOWN	HRSMSC	O/C						0		
	REF: AMM 32-50-00	AFL							0		
320191	OPERATIONAL CHECK NOSE STEERING										L3
32.160		MOS								11-FEB-1982	
		HRSMSC	C/C						0		
	REF: AMM 32-50-00	AFL							0		
322181	VALVE, PARKING MOTOR										F5
32.510	3-713551	MOS								11-FEB-1982	
	L34900	HRSMSC	O/C	0					0		
	REF: AMM 32-44-03	AFL							0		
+ 322176	FUNCTIONAL CHECK ANTI-SKID DETECTOR SYSTEM										F3
32.420	PKG 2, 3	MOS								26-JUN-2001	
ASSOCIATED		HRSMSC	400						7687		1
	REF: AMM 32-44-00	AFL							5594		
322101	VALVE, POWER BRAKE										F2
32.360	5713001-501	MOS								11-FEB-1982	\$1932.
	617AB	HRSMSC	O/C	0					0		5
	REF: AMM 32-43-02	AFL							0		
320221	VALVE, SHUTTLE NOSE GEAR										L3
32.330	4713066	MOS								11-FEB-1982	
	SN-UNKNOWN	HRSMSC	O/C	0					0		
	REF: AMM 32-30-07	AFL							0		
320671	WHEEL HALF, INBOARD LEFT MAIN GEAR										L1
32.180	5002806-2	MOS								09-NOV-1996	
	JUN89-537	HRSMSC	O/C						5951		1
	REF: AMM 32-41-00	AFL							4589		
320681	CHANGE LEFT MAIN GEAR TIRE										L1
32.180	249K83-3	MOS		0						09-NOV-1996	
ASSOCIATED	SN-UNKNOWN	HRSMSC	O/C	0					5951		2
	REF: AMM 32-41-00	AFL		0					4589		
320672	CHANGE LEFT MAIN GEAR OUTBOARD WHEEL HALF										L1
32.180	5002806-2	MOS								09-NOV-1996	
ASSOCIATED	JUN89-537	HRSMSC	O/C						5951		1
	REF: AMM 32-41-00	AFL							4589		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
320678	DYE PENETRANT CHECK LEFT WHEEL AXLE							L1
32.550	PKG 2, 3	MOS				26-JUN-2001		
ASSOCIATED	REF: AMM 5-20-04	HRSMSC	400			7687		
		AFL				5594		
+ 320691	INSPECT LEFT MAIN GEAR/WELL (A)							L1
32.020	PKG 1, 2, 3	MOS				26-JUN-2001		
ASSOCIATED	REF: AMM 5-20-04	HRSMSC	200			7687	1.5	
		AFL				5594		
+ 322156	INSPECT/CLEAN LEFT ANTI-SKID DETECTOR							L1
32.410	PKG 1, 2, 3	MOS				26-JUN-2001		
ASSOCIATED	REF: AMM 5-20-04	HRSMSC	200			7687	1	
		AFL				5594		
+ 320676	INSPECT/LUBRICATE LEFT MAIN GEAR INBOARD WHEEL BEARINGS							L1
32.180	PKG 1, 2, 3	MOS				26-JUN-2001		
	REF: AMM 32-41-00	HRSMSC	200			7687	1	
		AFL				5594		
+ 322174	OPERATIONAL CHECK ANTI-SKID LIGHTS							F3
32.425	PKG 1, 2, 3	MOS				26-JUN-2001		
ASSOCIATED	REF: AMM 32-44-00	HRSMSC	200			7687	.5	
		AFL				5594		
320686	REPLACE LEFT MAIN WHEEL BOLTS							L1
32.180		MOS				09-NOV-1996		
ASSOCIATED	REF: NO REF	HRSMSC	O/C			5951		
		AFL				4589		
321171	WHEEL HALF, INBOARD RIGHT MAIN GEAR							L2
32.190	5002806-2	MOS				09-NOV-1996		
	MAR84-662	HRSMSC	O/C			5951	1	
	REF: AMM 32-41-00	AFL				4589		
321181	CHANGE RIGHT MAIN GEAR TIRE							L2
32.190	249K83-3	MOS		0		09-NOV-1996		
ASSOCIATED	SN-UNKNOWN	HRSMSC	O/C	0		5951	2	
	REF: AMM 32-41-00	AFL		0		4589		
321172	CHANGE RIGHT MAIN GEAR OUTBOARD WHEEL HALF							L2
32.190	5002806-2	MOS				09-NOV-1996		
ASSOCIATED	MAR84-662	HRSMSC	O/C			5951	1	
	REF: AMM 32-41-00	AFL				4589		
321178	DYE PENETRANT CHECK RIGHT WHEEL AXLE							L2
32.550	PKG 2, 3	MOS				26-JUN-2001		
ASSOCIATED	REF: AMM 5-20-04	HRSMSC	400			7687		
		AFL				5594		
+ 322171	INSPECT/CLEAN RIGHT ANTI-SKID DETECTOR							L2
32.410	PKG 1, 2, 3	MOS				26-JUN-2001		
ASSOCIATED	REF: AMM 5-20-04	HRSMSC	200			7687	1	
		AFL				5594		

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
+ 321176		INSPECT/LUBRICATE RIGHT MAIN GEAR INBOARD WHEEL BEARINGS							L2
	32.180	PKG 1, 2, 3	MOS				26-JUN-2001		
		REF: AMM 32-41-00	HRSMSC	200			7687		1
			AFL				5594		
+ 322174		OPERATIONAL CHECK ANTI-SKID LIGHTS							F3
	32.425	PKG 1, 2, 3	MOS				26-JUN-2001		
	ASSOCIATED		HRSMSC	200			7687		.5
		REF: AMM 32-44-00	AFL				5594		
321186		REPLACE RIGHT MAIN WHEEL BOLTS							L2
	32.180		MOS				09-NOV-1996		
	ASSOCIATED		HRSMSC	O/C			5951		
		REF: NO REF	AFL				4589		
320672		WHEEL HALF, OUTBOARD LEFT MAIN GEAR							L1
	32.180	5002806-2	MOS				09-NOV-1996		
		JUN89-537	HRSMSC	O/C			5951		1
		REF: AMM 32-41-00	AFL				4589		
320681		CHANGE LEFT MAIN GEAR TIRE							L1
	32.180	249K83-3	MOS		0		09-NOV-1996		
	ASSOCIATED	SN-UNKNOWN	HRSMSC	O/C	0		5951		2
		REF: AMM 32-41-00	AFL		0		4589		
320678		DYE PENETRANT CHECK LEFT WHEEL AXLE							L1
	32.550	PKG 2, 3	MOS				26-JUN-2001		
	ASSOCIATED		HRSMSC	400			7687		
		REF: AMM 5-20-04	AFL				5594		
+ 320691		INSPECT LEFT MAIN GEAR/WELL (A)							L1
	32.020	PKG 1, 2, 3	MOS				26-JUN-2001		
	ASSOCIATED		HRSMSC	200			7687		1.5
		REF: AMM 5-20-04	AFL				5594		
+ 322156		INSPECT/CLEAN LEFT ANTI-SKID DETECTOR							L1
	32.410	PKG 1, 2, 3	MOS				26-JUN-2001		
	ASSOCIATED		HRSMSC	200			7687		1
		REF: AMM 5-20-04	AFL				5594		
+ 320680		INSPECT/LUBRICATE LEFT MAIN GEAR OUTBOARD WHEEL BEARINGS							L1
	32.180	PKG 1, 2, 3	MOS				26-JUN-2001		
			HRSMSC	200			7687		
		REF: AMM 32-41-00	AFL				5594		
+ 322174		OPERATIONAL CHECK ANTI-SKID LIGHTS							F3
	32.425	PKG 1, 2, 3	MOS				26-JUN-2001		
	ASSOCIATED		HRSMSC	200			7687		.5
		REF: AMM 32-44-00	AFL				5594		
320686		REPLACE LEFT MAIN WHEEL BOLTS							L1
	32.180		MOS				09-NOV-1996		
	ASSOCIATED		HRSMSC	O/C			5951		
		REF: NO REF	AFL				4589		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Page 56 of 107

Aircraft Model - 1124 WESTWIND

Report Date **11-APR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
321172	WHEEL HALF, OUTBOARD RIGHT MAIN GEAR							L2
32.190	5002806-2	MOS					09-NOV-1996	
	MAR84-662	HRSMSC	O/C			5951		1
	REF: AMM 32-41-00	AFL				4589		
321181	CHANGE RIGHT MAIN GEAR TIRE							L2
32.190	249K83-3	MOS		0			09-NOV-1996	
ASSOCIATED	SN-UNKNOWN	HRSMSC	O/C	0		5951		2
	REF: AMM 32-41-00	AFL		0		4589		
321178	DYE PENETRANT CHECK RIGHT WHEEL AXLE							L2
32.550	PKG 2, 3	MOS					26-JUN-2001	
ASSOCIATED		HRSMSC	400			7687		
	REF: AMM 5-20-04	AFL				5594		
+ 321191	INSPECT RIGHT MAIN GEAR/WELL (A)							L2
32.020	PKG 1, 2, 3	MOS					26-JUN-2001	
		HRSMSC	200			7687		1.5
	REF: AMM 5-20-04	AFL				5594		
+ 322171	INSPECT/CLEAN RIGHT ANTI-SKID DETECTOR							L2
32.410	PKG 1, 2, 3	MOS					26-JUN-2001	
ASSOCIATED		HRSMSC	200			7687		1
	REF: AMM 5-20-04	AFL				5594		
321180	INSPECT/LUBRICATE RIGHT MAIN GEAR OUTBOARD WHEEL BEARINGS							L2
32.180	PKG 1, 2, 3	MOS					26-JUN-2001	
		HRSMSC	200			7687		1
	REF: AMM 32-41-00	AFL				5594		
+ 322174	OPERATIONAL CHECK ANTI-SKID LIGHTS							F3
32.425	PKG 1, 2, 3	MOS					26-JUN-2001	
ASSOCIATED		HRSMSC	200			7687		.5
	REF: AMM 32-44-00	AFL				5594		
321186	REPLACE RIGHT MAIN WHEEL BOLTS							L2
32.180		MOS					09-NOV-1996	
ASSOCIATED		HRSMSC	O/C			5951		
	REF: NO REF	AFL				4589		
320146	WHEEL, LEFT NOSE GEAR							L3
32.110	41874	MOS					22-NOV-1995	
	APR66-109	HRSMSC	O/C	0		5720		4
	REF: AMM 32-42-00	AFL				4401		
320161	CHANGE NOSE GEAR LEFT TIRE							L3
32.110	164F43-2	MOS					22-NOV-1995	
ASSOCIATED	31162139	HRSMSC	O/C	0		5720		
	REF: AMM 32-42-00	AFL				4401		
+ 320156	INSPECT/CLEAN/LUBRICATE BEARINGS							L3
32.110	PKG 1, 2, 3	MOS					26-JUN-2001	
		HRSMSC	200			7687		1.5
	REF: AMM 5-20-01	AFL				5594		

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT----- TSN TSO TSR TSI ADJ	INSTALLATION	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
320151	WHEEL, RIGHT NOSE GEAR								L3
32.120	9541874	MOS					29-NOV-1995		
	OCT75-641	HRSMSC	O/C	0			5720		4
	REF: AMM 32-42-00	AFL					4401		
320166	CHANGE NOSE GEAR RIGHT TIRE								L3
32.120	164F43-2	MOS					29-NOV-1995		
ASSOCIATED	22051064	HRSMSC	O/C	0			5720		
	REF: AMM 32-42-00	AFL					4401		
+ 320158	INSPECT/CLEAN/LUBRICATE BEARINGS								L3
32.120	PKG 1, 2, 3	MOS					26-JUN-2001		
		HRSMSC	200				7687		1.5
	REF: AMM 5-20-01	AFL					5594		
CHAPTER 33	LIGHTS								
330226	BATTERY, EMERGENCY LIGHT								F4
33.100	AD-2058	MOS		0			06-OCT-1998		
	SN-UNKNOWN	HRSMSC	O/C	0			6520		
	REF: AMM 33-50-00	AFL		0			4889		
330320	INVERTER, LIGHT POWER (CF-38-3)								F2
33.070	CF-38-3	MOS					11-FEB-1982		
	291	HRSMSC	O/C	0			0		
	REF: NO REF	AFL					0		
330111	LIGHT, TAIL CONE								F1
33.020	4-823006-501	MOS					11-FEB-1982		
	SN-UNKNOWN	HRSMSC	O/C	0			0		
	REF: AMM 33-40-00	AFL					0		
330161	LIGHT, ANTI-COLLISION LOWER								F1
33.030	G-9950-11	MOS				10/28/1989	28-APR-1989		\$635.
	11709	HRSMSC	O/C				4240		
	REF: AMM 33-40-00	AFL					2767		
330156	LIGHT, ANTI-COLLISION UPPER								T1
33.030	G9950-11	MOS		0			26-JUL-2000		\$635.
	11709	HRSMSC	O/C	0			7325		
	REF: AMM 33-40-00	AFL		0			5360		
330221	LIGHT, EMERGENCY								F4
33.090	3-823551-503	MOS					11-FEB-1982		
	SN-UNKNOWN	HRSMSC	O/C	0			0		
	REF: AMM 33-50-00	AFL					0		
330226	CHANGE EMERGENCY LIGHT BATTERY								F4
33.100	AD-2058	MOS		0			06-OCT-1998		
ASSOCIATED	SN-UNKNOWN	HRSMSC	O/C	0			6520		
	REF: AMM 33-50-00	AFL		0			4889		
330228	CHARGE BATTERY								F4
33.100		MOS	3				06-NOV-2001	06-FEB-2002	
		HRSMSC	200				7774	7974	
	REF: AMM 12-10-06	AFL					5641		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
330136 33.060	LIGHT, LANDING LEFT 5-213004-1 SN-UNKNOWN REF: AMM 33-40-00	MOS HRSMSC AFL	O/C	0		11-FEB-1982 0 0		W1
330146 33.060	LIGHT, LANDING RIGHT 5-213004-2 SN-UNKNOWN REF: AMM 33-40-00	MOS HRSMSC AFL	O/C	0		11-FEB-1982 0 0		W2
330101 33.010	LIGHT, POSITION LEFT WING 301085-1 4224 REF: AMM 33-40-00	MOS HRSMSC AFL	O/C	0		11-FEB-1982 0 0		W1
330106 33.010	LIGHT, POSITION RIGHT WING 301085-2 5772 REF: AMM 33-40-00	MOS HRSMSC AFL	O/C	0		11-FEB-1982 0 0		W2
330166 33.040	LIGHT, STROBE LEFT WING 31-3172-11 SN-UNKNOWN REF: AMM 33-40-00	MOS HRSMSC AFL	O/C	0		11-FEB-1982 0 0		W1
330171 33.040	LIGHT, STROBE RIGHT WING 31-3172-11 SN-UNKNOWN REF: AMM 33-40-00	MOS HRSMSC AFL	O/C	0		11-FEB-1982 0 0		W2
330116 33.050	LIGHT, TAXI LEFT 5-823521-1 GE-4587 REF: AMM 33-40-00	MOS HRSMSC AFL	O/C			30-AUG-1989 4350 2898		L1
330126 33.050	LIGHT, TAXI RIGHT 5-823521-2 GE-4587 REF: AMM 33-40-00	MOS HRSMSC AFL	O/C			30-AUG-1989 4350 2898		L2
330505 33.085	POWER SUPPLY, 60-2799-1 SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL	O/C			11-FEB-1982 0 0		W1
330241 33.080	POWER SUPPLY, NO. 1 60-2799-1 6701 REF: NO REF	MOS HRSMSC AFL	O/C	0		11-FEB-1982 0 0		W1
330246 33.080	POWER SUPPLY, NO. 2 60-2799-1 SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL	O/C	0		25-APR-1984 1641 1010		W2

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
330522 33.085	POWER SUPPLY, NO.4 60-2799-1 SN-UNKNOWN REF: NO REF	MOS HRS/MS AFL	O/C			11-FEB-1982 0 0		W2
330325 33.070	UNIT, LIGHT POWER (CV-38) CV-38 6125 REF: NO REF	MOS HRS/MS AFL	O/C			11-FEB-1982 0 0		F2
CHAPTER 34 NAVIGATION								
340121 34.060	DRAIN PITOT/STATIC SYSTEM PKG 1, 2, 3 REF: AMM 34-10-00	MOS HRS/MS AFL	200			26-JUN-2001 7687 5594		F2 1.5
340111 34.040	LEAK CHECK LEFT PITOT SYSTEM REF: AMM 34-10-01	MOS HRS/MS AFL	O/C			26-MAR-1996		F1
+ 340146 34.050	LEAK CHECK LEFT STATIC SYSTEM REF: AMM 34-10-01	MOS HRS/MS AFL	24			18-JAN-2001 7494 5466	MANDATORY 18-JAN-2003	F1
340116 34.040	LEAK CHECK RIGHT PITOT SYSTEM REF: AMM 34-10-01	MOS HRS/MS AFL	O/C			11-FEB-1982 0 0		F1
+ 340151 34.050	LEAK CHECK RIGHT STATIC SYSTEM REF: AMM 34-10-01	MOS HRS/MS AFL	24			18-JAN-2001 7494 5466	MANDATORY 18-JAN-2003	F1
343141 34.390	SWING CHECK NO.1 COMPASS REF: AMM 34-20-08	MOS HRS/MS AFL	O/C			11-FEB-1982 0 0		F3
343186 34.390	SWING CHECK NO.2 COMPASS REF: AMM 34-20-08	MOS HRS/MS AFL	O/C			11-FEB-1982 0 0		F3
345101 34.490	ADVISORY, FLIGHT PROFILE 622-4569-001 SN-UNKNOWN REF: NO REF	MOS HRS/MS AFL	O/C	0 0		11-FEB-1982 0 0		F3
345629 34.310	ALERTER, ALTITUDE 540-25100-004 SN-UNKNOWN REF: AMM 34-10-03	MOS HRS/MS AFL	O/C	0		11-FEB-1982 0 0		F3

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
341111	ALTIMETER, COPILOT							F3
34.071	4883778-501	MOS				11-FEB-1982		
	3008	HRSMSC	O/C	0		0		
	REF: NO REF	AFL				0		
+ 340151	LEAK CHECK RIGHT STATIC SYSTEM						MANDATORY	F1
34.050		MOS	24			18-JAN-2001	18-JAN-2003	
ASSOCIATED		HRSMSC				7494		
	REF: AMM 34-10-01	AFL				5466		
+ 341116	TEST FAR 91.411						MANDATORY	F3
34.071		MOS	24			18-JAN-2001	18-JAN-2003	
		HRSMSC				7494		
	REF:	AFL				5466		
341101	ALTIMETER, PILOT							F3
34.070	622-3975-003	MOS				11-FEB-1982		
	1323	HRSMSC	O/C	0		0		
	REF: AMM 34-10-03	AFL				0		
+ 340146	LEAK CHECK LEFT STATIC SYSTEM						MANDATORY	F1
34.050		MOS	24			18-JAN-2001	18-JAN-2003	
ASSOCIATED		HRSMSC				7494		
	REF: AMM 34-10-01	AFL				5466		
+ 341106	TEST FAR 91.411						MANDATORY	F3
34.070		MOS	24			18-JAN-2001	18-JAN-2003	
		HRSMSC				7494		
	REF:	AFL				5466		
341121	ALTIMETER, STAND-BY							F3
34.075	622-3975-003	MOS				11-FEB-1982		
	SN-UNKNOWN	HRSMSC	O/C	0		0		
	REF: NO REF	AFL				0		
+ 340146	LEAK CHECK LEFT STATIC SYSTEM						MANDATORY	F1
34.050		MOS	24			18-JAN-2001	18-JAN-2003	
ASSOCIATED		HRSMSC				7494		
	REF: AMM 34-10-01	AFL				5466		
+ 340151	LEAK CHECK RIGHT STATIC SYSTEM						MANDATORY	F1
34.050		MOS	24			18-JAN-2001	18-JAN-2003	
ASSOCIATED		HRSMSC				7494		
	REF: AMM 34-10-01	AFL				5466		
343176	ANNUNCIATOR, COMPASS COPILOT							F3
34.170	PN	MOS				11-FEB-1982		
	SN-UNKNOWN	HRSMSC	O/C	0		0		
	REF: AMM 34-20-08	AFL				0		
343131	ANNUNCIATOR, COMPASS PILOT							F3
34.170	PN	MOS				11-FEB-1982		
	SN-UNKNOWN	HRSMSC	O/C	0		0		
	REF: AMM 34-20-08	AFL				0		

Aircraft Model - 1124 WESTWIND
Report Date 11-APR-2002
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
346681	ANTENNA, #1 VLF										F5
34.640	10085-2	MOS							03-APR-1989		
	6025	HRS/MS	O/C	0					4215		
	REF: AMM 34-60-02	AFL							2745		
347681	ANTENNA, GLIDESLOPE										F2
34.570	DMN-25-1	MOS							11-FEB-1982		
	1896	HRS/MS	O/C	0					0		
	REF: AMM 34-50-01	AFL		0					0		
346611	ANTENNA, NO.1 ADF LOOP										F1
34.350	522-3761-001	MOS							31-JAN-1986		
	4428	HRS/MS	O/C	0					2855		
	REF: AMM 34-50-03/04	AFL							1770		
346131	ANTENNA, NO.1 ATC TRANSPONDER										F1
34.330	DMNI-50-6	MOS							11-FEB-1982		
	323	HRS/MS	O/C	0					0		
	REF: AMM 34-50-06	AFL							0		
347121	ANTENNA, NO.1 DME										F1
34.360	4-873127-501	MOS							11-FEB-1982		
	3234	HRS/MS	O/C	0					0		2
	REF: AMM 34-50-02	AFL							0		
348111	ANTENNA, NO.1 LRN										
34.660	42804-000100-00	MOS							11-FEB-1982		
	1346	HRS/MS	O/C	0					0		
	REF: AMM 34-60-04	AFL		0					0		
346206	ANTENNA, NO.1 MARKER BEACON										F5
34.550	DMN-27-1/A	MOS							11-FEB-1982		
	1919	HRS/MS	O/C	0					0		
	REF: AMM 34-50-01	AFL		0					0		
346546	ANTENNA, NO.1 VOR										F5
34.580	DMN-4-15-3/D	MOS							11-FEB-1982		
	10987	HRS/MS	O/C	0					0		
	REF: NO REF	AFL							0		
346636	ANTENNA, NO.2 ADF LOOP										F1
34.350	522-3761-001	MOS							11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0					0		
	REF: AMM 34-50-03/04	AFL							0		
346136	ANTENNA, NO.2 ATC TRANSPONDER										F1
34.330	DMNI-50-6	MOS							11-FEB-1982		
	3259	HRS/MS	O/C	0					0		
	REF: AMM 34-50-06	AFL							0		
347621	ANTENNA, NO.2 DME										F1
34.360	4-873127-503	MOS							11-FEB-1982		
	3242	HRS/MS	O/C	0					0		2
	REF: AMM 34-50-02	AFL							0		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date **11-APR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
348114 34.700	ANTENNA, NO.2 LRN 42804-000100-00 SN-UNKNOWN REF: AMM 34-60-04	MOS HRSMSC AFL	O/C	0 0			11-FEB-1982 0 0	
346216 34.550	ANTENNA, NO.2 MARKER BEACON PN SN-UNKNOWN REF: AMM 34-50-01	MOS HRSMSC AFL	O/C	0 0			11-FEB-1982 0 0	F5
346576 34.600	ANTENNA, NO.2 VOR DMN-4-15-3A 10993 REF: NO REF	MOS HRSMSC AFL	O/C	0			11-FEB-1982 0 0	F3
345626 34.340	ANTENNA, RADIO ALTIMETER RECEIVER 522-4140-001 509 REF: AMM 34-10-04	MOS HRSMSC AFL	O/C	0			11-FEB-1982 0 0	F1
345621 34.340	ANTENNA, RADIO ALTIMETER TRANSMIT 622-4550-001 459 REF: AMM 34-10-04	MOS HRSMSC AFL	O/C	0			11-FEB-1982 0 0	F1
345831 34.520	ANTENNA, WEATHER RADAR 622-2504-001 270 REF: AMM 34-40-01,-02,-03,-04	MOS HRSMSC AFL	O/C	5222 3870	04/19/1993	19-FEB-1993 5222 3870		F2
344611 34.370	BATTERY, EMERGENCY GYRO POWER SUPPLY 501-1075-05PS823A/T 1186 REF:	MOS HRSMSC AFL	O/C			06-APR-1998 6346 4787		F5 1
344621 34.370	DEEP CYCLE POWER SUPPLY GNS-500 NAV SYSTEM MOS HRSMSC AFL REF: MSC BFG SL-80J/JET TP-329	MOS HRSMSC AFL	O/C			06-APR-1998 6346 4787		F5
+ 344616 34.370	INSPECT EMERGENCY POWER SUPPLY BATTERY/STAND-BY ATTITUDE GYRO MOS HRSMSC AFL REF: AMM NO REF	MOS HRSMSC AFL	3 200			06-NOV-2001 7774 5641	06-FEB-2002 7974	F5
347626 34.150	BOX, DME DUAL CONTROL PN SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL	O/C	0		11-FEB-1982 0 0		F2 1
347641 34.580	BOX, HORIZONTAL SITUATION INDICATOR CONTROL 622-4569-001 SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL	O/C	0 0		11-FEB-1982 0 0		F4

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
346551	BOX, NO.1 VOR CONTROL							F3
34.590	622-2899-012	MOS					11-FEB-1982	
	SN-UNKNOWN	HRSMSC	O/C	0		0		
	REF: NO REF	AFL				0		
346581	BOX, NO.2 VOR CONTROL							F3
34.590	DMN-4-15-3/D	MOS					11-FEB-1982	
	SN-UNKNOWN	HRSMSC	O/C	0		0		
	REF: NO REF	AFL				0		
342601	COMPASS, STAND-BY MAGNETIC							F3
34.100	2-883023-501	MOS					11-FEB-1982	
	1A234	HRSMSC	O/C	0		0		
	REF: NO REF	AFL				0		
342611	SWING CHECK							F3
34.100		MOS					11-FEB-1982	
		HRSMSC	O/C			0		
	REF: CMM	AFL				0		
343113	COMPENSATOR, NO.1							
34.440	656767	MOS					11-FEB-1982	
	81082033	HRSMSC	O/C	0		0		
	REF: NO REF	AFL		0		0		
343158	COMPENSATOR, NO.2							
34.440	656767	MOS					11-FEB-1982	
	81092117	HRSMSC	O/C	0		0		
	REF: NO REF	AFL		0		0		
344131	COMPUTER, FLIGHT COPILOT							F2
34.220	622-5224-005	MOS					11-FEB-1982	
	SN-UNKNOWN	HRSMSC	O/C	0		0		
	REF: AMM 4-20-04/21-04	AFL				0		
343631	COMPUTER, FLIGHT PILOT							F2
34.220	622-5224-004	MOS					11-FEB-1982	
	5128	HRSMSC	O/C	0		0		1
	REF: AMM 4-20-04/21-04	AFL				0		
340201	COMPUTER, NAVIGATION							F3
34.460	622-5107-001	MOS					11-FEB-1982	
	SN-UNKNOWN	HRSMSC	O/C	0		0		
	REF: NO REF	AFL		0		0		
343671	COMPUTER, NO.1 AIR DATA							F3
34.480	622-5465-214	MOS					26-MAR-1996	
	1080	HRSMSC	O/C					
	REF: AMM 22-20-00	AFL						
+ 343672	CALIBRATE FAR 91.411							
34.480		MOS	24				18-JAN-2001	MANDATORY F3
		HRSMSC				7494	18-JAN-2003	
	REF: See Workcard	AFL				5466		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND
 Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
 A/C Serial #: 368 A/C Reg. #: N368MD

Report Date **11-APR-2002**

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
341604	COMPUTER, SAT TAS							
34.410	630-30980-135	MOS					11-FEB-1982	F3
	1589	HRS/MS	O/C	0		0		
	REF: NO REF	AFL		0		0		
346616	CONTROL, NO.1 ADF							F3
34.260	622-4526-003	MOS					11-FEB-1982	
	10601	HRS/MS	O/C	0		0		
	REF: NO REF	AFL				0		
346641	CONTROL, NO.2 ADF							F3
34.260	PN	MOS					11-FEB-1982	
	SN-UNKNOWN	HRS/MS	O/C	0		0		
	REF: NO REF	AFL				0		
346251	CONTROLLER, NO.1 NAVIGATION							F3
34.470	622-4524-079	MOS					14-JAN-1992	
	7898	HRS/MS	O/C	5012		5012		
	REF: NO REF	AFL		3648		3648		
346261	CONTROLLER, NO.2 NAVIGATION							F3
34.470	622-4524-079	MOS			0	07/15/1992	15-JAN-1992	
	7863	HRS/MS	O/C		0	5012		
	REF: NO REF	AFL			0	3648		
346141	CONTROLLER, TRANSPONDER							F4
34.540	622-4527-011	MOS					11-FEB-1982	
	6475	HRS/MS	O/C	0		0		
	REF: NO REF	AFL		0		0		
346306	CONVERTER, NAV RECEIVER/VHF POWER							F3
34.460	622-2093-001	MOS					11-FEB-1982	
	17233	HRS/MS	O/C	0		0		
	REF: NO REF	AFL		0		0		
347201	CONVERTER, NO.1 DME SYNCHRO							F3
34.650	622-1920-001	MOS					11-FEB-1982	
	SN-UNKNOWN	HRS/MS	O/C	0		0		
	REF: AMM 34-50-02	AFL		0		0		
347211	CONVERTER, NO.2 DME SYNCHRO							F3
34.650	622-1920-001	MOS					11-FEB-1982	
	SN-UNKNOWN	HRS/MS	O/C	0		0		
	REF: AMM 34-50-02	AFL		0		0		
341096	CONVERTER, RADIO ALTIMETER							F3
34.420	995-29400-112	MOS					11-FEB-1982	
	SN-UNKNOWN	HRS/MS	O/C	0		0		
	REF: NO REF	AFL		0		0		
343641	COUPLER, NO.1 FLIGHT DIRECTOR MODE							F2
34.230	161E-2A	MOS					11-FEB-1982	
	SN-UNKNOWN	HRS/MS	O/C	0		0		
	REF: AMM 22-03-06	AFL				0		

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
348146	COUPLER, NO.1 LRN											
34.740	42807-001 100-001	MOS								11-FEB-1982		
	1585	HRS/MS	O/C	0						0		
	REF: NO REF	AFL		0						0		
344141	COUPLER, NO.2 FLIGHT DIRECTOR MODE											F2
34.230	161E-2A	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0						0		
	REF: AMM 22-03-06	AFL								0		
348151	COUPLER, NO.2 LRN											
34.740	42807-001 100-001	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0						0		
	REF: NO REF	AFL		0						0		
345833	DISH, WEATHER RADAR FLAT											F2
34.530	ANT-318	MOS							04/19/1993	19-FEB-1993		
	270	HRS/MS	O/C	5222						5222		
	REF: AMM 34-40-01	AFL		3870						3870		
348116	DISPLAY, NO.1 LRN CONTROL											
34.670	622-5493-001	MOS								11-FEB-1982		
	040	HRS/MS	O/C	0						0		
	REF: AMM 34-60-04	AFL		0						0		
348121	DISPLAY, NO.2 LRN CONTROL											
34.670	622-5493-001	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0						0		
	REF: AMM 34-60-04	AFL		0						0		
345631	GENERATOR, TONE (ALERTER)											F3
34.300	540-25100-004	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0						0		
	REF: AMM 34-10-03	AFL								0		
343101	GYRO, NO.1 DIRECTIONAL											F4
34.110	622-4176-004	MOS							04/02/1992	02-OCT-1991		
	871	HRS/MS	O/C		0					4931		
	REF: AMM 34-20-08	AFL								3454		
343106	BENCH CHECK											F4
34.110		MOS								11-FEB-1982		
		HRS/MS	O/C							0		
	REF: CMM	AFL								0		
343651	GYRO, NO.1 VERTICAL											F3
34.200	792-6694-001	MOS								06-JAN-1986		
	6381	HRS/MS	O/C	0						2808		2
	REF: AMM 34-20-07(1124/A), 34-21-05(1124A)	AFL								1739		
343146	GYRO, NO.2 DIRECTIONAL											F4
34.110	2587193-43	MOS								24-SEP-1987		
	81095980	HRS/MS	O/C	0						3737		
	REF: AMM 34-20-08	AFL								2345		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Page 66 of 107

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
343151 34.110	BENCH CHECK	MOS				11-FEB-1982		F4
	REF: CMM	HRS/MSA	O/C			0		
		AFL				0		
344151 34.200	GYRO, NO.2 VERTICAL	MOS				11-FEB-1982		F3
	792-6694-001	HRS/MSA	O/C	0		0		
	SN-UNKNOWN	AFL				0		
	REF: AMM 34-20-07(1124/A),34-21-05(1124A)							
347611 34.140	INDICATOR, DME COPILOT	MOS				11-FEB-1982		F3
	PN	HRS/MSA	O/C	0		0		
	SN-UNKNOWN	AFL				0		
	REF: NO REF							
347111 34.140	INDICATOR, DME PILOT	MOS				11-FEB-1982		F3
	PN	HRS/MSA	O/C	0		0		
	SN-UNKNOWN	AFL				0		
	REF: NO REF							
344101 34.280	INDICATOR, FLIGHT DIRECTOR COPILOT	MOS				11-FEB-1982		F3
	622-4808-004	HRS/MSA	O/C	0		0		
	SN-UNKNOWN	AFL				0		
	REF: AMM 4-20-01/21-02							
343601 34.280	INDICATOR, FLIGHT DIRECTOR PILOT	MOS				11-FEB-1982		F3
	622-4808-004	HRS/MSA	O/C	0		0		
	823	AFL				0		
	REF: AMM 4-20-01/21-02							
341601 34.080	INDICATOR, LEFT MACH/AIRSPD	MOS				07-APR-1987		F3
	622-4382-013	HRS/MSA	O/C	0		3676		
	1302	AFL				2288		
	REF: NO REF							
341606 34.080	CALIBRATE	MOS				10-APR-1990		F3
		HRS/MSA	O/C			4560		
	REF: CMM	AFL				3132		
340111 34.040	LEAK CHECK LEFT PITOT SYSTEM	MOS				26-MAR-1996		F1
	ASSOCIATED	HRS/MSA	O/C					
	REF: AMM 34-10-01	AFL						
+ 340146 34.050	LEAK CHECK LEFT STATIC SYSTEM	MOS	24			18-JAN-2001	MANDATORY 18-JAN-2003	F1
	ASSOCIATED	HRS/MSA				7494		
	REF: AMM 34-10-01	AFL				5466		
342090 34.380	INDICATOR, LEFT VERTICAL NAV/SPEED	MOS				22-OCT-1982		F3
	622-4782-003/VNI-80	HRS/MSA	O/C	0		482		
	SN-UNKNOWN	AFL						
	REF: NO REF							

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT----- TSN TSO TSR TSI ADJ	INSTALLATION	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
342101	INDICATOR, LEFT VERTICAL SPEED								F3
34.090	4883748-1	MOS					11-FEB-1982		\$486.
	640	HRS/MS	O/C	0			0		
	REF: AMM 34-10-03	AFL					0		
342106	BENCH CHECK								F3
34.090		MOS					11-FEB-1982		
		HRS/MS	O/C				0		
	REF: See Workcard	AFL					0		
+ 340146	LEAK CHECK LEFT STATIC SYSTEM							MANDATORY	F1
34.050		MOS	24				18-JAN-2001	18-JAN-2003	
ASSOCIATED		HRS/MS					7494		
	REF: AMM 34-10-01	AFL					5466		
342801	INDICATOR, NO.1 GYRO ATTITUDE								F3
34.430	4020531-170	MOS			0		25-MAR-1991		
	80110830	HRS/MS	O/C		0		4830		
	REF: NO REF	AFL			0		3441		
347651	INDICATOR, NO.1 HORIZONTAL SITUATION								F3
34.560	622-4176-004	MOS					10-MAR-1987		
	871	HRS/MS	O/C	0			3623		
	REF: AMM 4-20-02/21-02	AFL		0			2255		
342811	INDICATOR, NO.2 GYRO ATTITUDE								F3
34.430	4020531-170	MOS					19-MAR-1991		
	6020225	HRS/MS	O/C				4827		
	REF: NO REF	AFL					3439		
347655	INDICATOR, NO.2 HORIZONTAL SITUATION								F3
34.560	622-4176-004	MOS					11-FEB-1982		
	1854	HRS/MS	O/C	0			0		
	REF: AMM 4-20-02/21-02	AFL					0		
340601	INDICATOR, OUTSIDE AIR TEMPERATURE								F3
34.380	4883753-3	MOS					14-APR-1984		
	64128-13	HRS/MS	O/C	0			1645		
	REF: NO REF	AFL							
345611	INDICATOR, RADIO ALTIMETER								F3
34.250	521-29007-203	MOS					11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0			0		
	REF: NO REF	AFL					0		
343166	INDICATOR, RADIO MAGNETIC COPILOT								F3
34.160	622-2506-002	MOS					14-DEC-1986		
	1546	HRS/MS	O/C	0			3484		1
	REF: AMM 34-50-05	AFL					2157		
343121	INDICATOR, RADIO MAGNETIC PILOT								F3
34.160	622-2506-002	MOS					05-NOV-1986		
	1213	HRS/MS	O/C	0			3385		1
	REF: AMM 34-50-05	AFL					2098		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Page 68 of 107

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT----- TSN TSO TSR TSI ADJ	INSTALLATION	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
341056	INDICATOR, RATE OF CLIMB COPILOT								F3
34.400	229-0324-010	MOS						11-FEB-1982	
	SN-UNKNOWN	HRSMSC	O/C	0			0		
	REF: NO REF	AFL		0			0		
341046	INDICATOR, RATE OF CLIMB PILOT								F3
34.400	622-7689-003	MOS						31-MAY-1993	
	166	HRSMSC	O/C		0		5278		
	REF: NO REF	AFL					3928		
341611	INDICATOR, RIGHT MACH/AIRSPEED								F3
34.080	883615-513	MOS						11-FEB-1982	
	149	HRSMSC	O/C	0			0		
	REF: NO REF	AFL					0		
341616	CALIBRATE								F3
34.080		MOS						11-FEB-1982	
		HRSMSC	O/C				0		
	REF: CMM VENDOR	AFL					0		
340116	LEAK CHECK RIGHT PITOT SYSTEM								F1
34.040		MOS						11-FEB-1982	
ASSOCIATED		HRSMSC	O/C				0		
	REF: AMM 34-10-01	AFL					0		
+ 340151	LEAK CHECK RIGHT STATIC SYSTEM							MANDATORY	F1
34.050		MOS	24					18-JAN-2001	18-JAN-2003
ASSOCIATED		HRSMSC					7494		
	REF: AMM 34-10-01	AFL					5466		
342111	INDICATOR, RIGHT VERTICAL SPEED								F3
34.090	RCS-60-IL-10	MOS						11-FEB-1982	\$486.
	MD12158	HRSMSC	O/C	0			0		
	REF: AMM 34-10-03	AFL					0		
342116	BENCH CHECK								F3
34.090		MOS						11-FEB-1982	
		HRSMSC	O/C				0		
	REF: See Workcard	AFL					0		
+ 340151	LEAK CHECK RIGHT STATIC SYSTEM							MANDATORY	F1
34.050		MOS	24					18-JAN-2001	18-JAN-2003
ASSOCIATED		HRSMSC					7494		
	REF: AMM 34-10-01	AFL					5466		
341605	INDICATOR, SAT TAS								F3
34.410	622-2294-002	MOS						11-FEB-1982	
	SN-UNKNOWN	HRSMSC	O/C	0			0		
	REF: NO REF	AFL		0			0		
344601	INDICATOR, STAND-BY HORIZON								F3
34.290	501-1105-03	MOS						18-NOV-1984	
	6010212	HRSMSC	O/C	0			2085		
	REF: AMM 34-20-09	AFL					1284		

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT----- TSN TSO TSR TSI ADJ	INSTALLATION Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
345801 34.500	INDICATOR, WEATHER RADAR 622-4331-001 176 REF: AMM 34-40-01,-02,-03,-04	MOS HRS/MS AFL	O/C	0	09/18/1993	18-MAR-1993 5231 3880		F3
347101 34.270	INTERROGATOR, NO.1 DME 622-1233-001 13710 REF: AMM 34-50-02	MOS HRS/MS AFL	O/C	0		11-FEB-1982 0 0		F2
347601 34.270	INTERROGATOR, NO.2 DME 622-1233-001 15123 REF: AMM 34-50-02	MOS HRS/MS AFL	O/C	0		11-FEB-1982 0 0		F2
343663 34.190	PANEL, NO.1 FLIGHT GUIDANCE 622-2313-029 2661 REF: AMM 34-21-03	MOS HRS/MS AFL	O/C	0 0		11-FEB-1982		F3
343665 34.190	PANEL, NO.2 FLIGHT GUIDANCE 622-2265-030 SN-UNKNOWN REF: AMM 34-21-03	MOS HRS/MS AFL	O/C	0 0		11-FEB-1982 0 0		F3
345811 34.540	PANEL, WEATHER RADAR CONTROL DCP-320 SN-UNKNOWN REF: NO REF	MOS HRS/MS AFL	O/C	0 0		11-FEB-1982 0 0		F3
340126 34.020	PORT, LEFT HEATED STATIC 3-883053-501 SN-UNKNOWN REF: AMM 34-10-01	MOS HRS/MS AFL	O/C	0		11-FEB-1982 0 0		F1
340121 34.060 ASSOCIATED	DRAIN PITOT/STATIC SYSTEM PKG 1, 2, 3 REF: AMM 34-10-00	MOS HRS/MS AFL	200			26-JUN-2001 7687 5594		F2 1.5
+ 340146 34.050 ASSOCIATED	LEAK CHECK LEFT STATIC SYSTEM REF: AMM 34-10-01	MOS HRS/MS AFL	24			18-JAN-2001 7494 5466	MANDATORY 18-JAN-2003	F1
340131 34.030	PORT, LEFT UNHEATED STATIC 4-883050 SN-UNKNOWN REF: AMM 34-10-01	MOS HRS/MS AFL	O/C	0		11-FEB-1982 0 0		F1
340121 34.060 ASSOCIATED	DRAIN PITOT/STATIC SYSTEM PKG 1, 2, 3 REF: AMM 34-10-00	MOS HRS/MS AFL	200			26-JUN-2001 7687 5594		F2 1.5

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Page 70 of 107

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
+ 340146 34.050 ASSOCIATED	LEAK CHECK LEFT STATIC SYSTEM REF: AMM 34-10-01	MOS HRSMSC AFL	24			18-JAN-2001 7494 5466	MANDATORY 18-JAN-2003	F1
340136 34.020	PORT, RIGHT HEATED STATIC 3-883053-502 SN-UNKNOWN REF: AMM 34-10-01	MOS HRSMSC AFL	O/C	0		11-FEB-1982 0 0		F1
340121 34.060 ASSOCIATED	DRAIN PITOT/STATIC SYSTEM PKG 1, 2, 3 REF: AMM 34-10-00	MOS HRSMSC AFL	200			26-JUN-2001 7687 5594		F2 1.5
+ 340151 34.050 ASSOCIATED	LEAK CHECK RIGHT STATIC SYSTEM REF: AMM 34-10-01	MOS HRSMSC AFL	24			18-JAN-2001 7494 5466	MANDATORY 18-JAN-2003	F1
340141 34.030	PORT, RIGHT UNHEATED STATIC 4-883050 SN-UNKNOWN REF: AMM 34-10-01	MOS HRSMSC AFL	O/C	0		11-FEB-1982 0 0		F1
340121 34.060 ASSOCIATED	DRAIN PITOT/STATIC SYSTEM PKG 1, 2, 3 REF: AMM 34-10-00	MOS HRSMSC AFL	200			26-JUN-2001 7687 5594		F2 1.5
+ 340151 34.050 ASSOCIATED	LEAK CHECK RIGHT STATIC SYSTEM REF: AMM 34-10-01	MOS HRSMSC AFL	24			18-JAN-2001 7494 5466	MANDATORY 18-JAN-2003	F1
340606 34.380	PROBE, OUTSIDE AIR TEMPERATURE MS28038-1 9223 REF: NO REF	MOS HRSMSC AFL	O/C	0		11-FEB-1982 0 0		F1
347659 34.740	PROGRAMMER, RNS 622-5110-001 SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL	O/C	0 0		11-FEB-1982		
346601 34.130	RECEIVER, NO.1 ADF 622-2362-001 8945 REF: AMM 34-50-03/04	MOS HRSMSC AFL	O/C	0		11-FEB-1982 0 0		F4 1
346301 34.450	RECEIVER, NO.1 VHF NAVIGATION 622-0876-001 16803 REF: AMM 34-50-01	MOS HRSMSC AFL	O/C	0 0		11-FEB-1982 0 0		F3

Aircraft Model - 1124 WESTWIND
Report Date 11-APR-2002
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
346536		RECEIVER, NO.1 VOR							F3
34.580		PN	MOS				11-FEB-1982		
		SN-UNKNOWN	HRS/MSC	O/C	0		0		
		REF: NO REF	AFL				0		
346626		RECEIVER, NO.2 ADF							F4
34.130		622-2362-001	MOS				06-APR-1985		
		8946	HRS/MSC	O/C	0		2317		
		REF: AMM 34-50-03/04	AFL				1423		
346311		RECEIVER, NO.2 VHF NAVIGATION							F3
34.450		622-0876-001	MOS				11-FEB-1982		
		SN-UNKNOWN	HRS/MSC	O/C	0		0		
		REF: AMM 34-50-01	AFL		0		0		
346566		RECEIVER, NO.2 VOR							F3
34.600		PN	MOS				11-FEB-1982		
		SN-UNKNOWN	HRS/MSC	O/C	0		0		
		REF: NO REF	AFL				0		
345608		RECEIVER, RADIO ALTIMETER							F3
34.420		622-3201-001	MOS				11-FEB-1982		
		SN-UNKNOWN	HRS/MSC	O/C	0		0		
		REF: NO REF	AFL		0		0		
346201		RECEIVER/TRANSMITTER, MARKER BEACON							F3
34.540		PN	MOS				11-FEB-1982		
		SN-UNKNOWN	HRS/MSC	O/C	0		0		
		REF: NO REF	AFL		0		0		
345601		RECEIVER/TRANSMITTER, RADIO ALTIMETER							F2
34.240		622-3201-001	MOS				11-FEB-1982		
		3652	HRS/MSC	O/C	0		0		
		REF: AMM 34-10-04	AFL				0		
345821		RECEIVER/TRANSMITTER, WEATHER RADAR							F3
34.510		622-4022-001	MOS				12-APR-1995		
		2126	HRS/MSC	O/C			5613		
		REF: AMM 34-40-01,-02,-03,-04	AFL				4281		
344161		SELECTOR, MODE COPILOT							F3
34.210		614E-23R	MOS				11-FEB-1982		
		SN-UNKNOWN	HRS/MSC	O/C	0		0		
		REF: AMM 34-20-03	AFL				0		
343661		SELECTOR, MODE PILOT							F3
34.210		614E-20R	MOS				11-FEB-1982		
		SN-UNKNOWN	HRS/MSC	O/C	0		0		1
		REF: AMM 34-20-03	AFL				0		
343677		SELECTOR, NO.1 REMOTE							F3
34.490		622-4178-003	MOS				11-FEB-1982		
		SN-UNKNOWN	HRS/MSC	O/C	0		0		
		REF: NO REF	AFL		0		0		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
344177	SELECTOR, NO.2 REMOTE							
34.490	622-4178-003	MOS					11-FEB-1982	
	SN-UNKNOWN	HRSMSC	O/C	0		0		
	REF: NO REF	AFL		0		0		
344121	SENSOR, RATE-OF-TURN COPILOT							F3
34.180	622-0181-001	MOS					11-FEB-1982	
	SN-UNKNOWN	HRSMSC	O/C	0		0		
	REF: AMM 22-11-05(1124A),34-20-06(1124)	AFL				0		
343621	SENSOR, RATE-OF-TURN PILOT							F3
34.180	772-5140-001	MOS					05-OCT-1983	
	3984	HRSMSC	O/C	0		1300		
	REF: AMM 22-11-05(1124A),34-20-06(1124)	AFL				794		
346101	TRANSPONDER, NO.1 ATC							F3
34.320	622-1270-001	MOS				06/11/1996	11-DEC-1995	
	9608	HRSMSC	O/C			5726		1
	REF: AMM 34-50-06	AFL				4410		
346106	BENCH CHECK							F3
34.320		MOS					25-SEP-1991	
		HRSMSC	O/C					
	REF: See Workcard	AFL						
+ 346111	TEST FAR 91.413						MANDATORY	F3
34.320		MOS	24				18-JAN-2001 18-JAN-2003	
		HRSMSC				7494		
	REF: CMM FAR 91.413	AFL				5466		
346116	TRANSPONDER, NO.2 ATC							F3
34.320	622-1270-001	MOS					11-FEB-1982	
	13112	HRSMSC	O/C	0		0		3
	REF: AMM 34-50-06	AFL				0		
346121	BENCH CHECK							F3
34.320		MOS					25-SEP-1991	
		HRSMSC	O/C					4
	REF: CMM VENDOR MM	AFL						
+ 346126	TEST FAR 91.413						MANDATORY	F3
34.320		MOS	24				18-JAN-2001 18-JAN-2003	
		HRSMSC				7494		
	REF: CMM FAR 91.413	AFL				5466		
340101	TUBE, LEFT PITOT							F1
34.010	4883049-1	MOS					11-FEB-1982	
	59912	HRSMSC	O/C	0		0		
	REF: AMM 34-10-01	AFL				0		
340121	DRAIN PITOT/STATIC SYSTEM							F2
34.060	PKG 1, 2, 3	MOS					26-JUN-2001	
ASSOCIATED		HRSMSC	200			7687		1.5
	REF: AMM 34-10-00	AFL				5594		

Aircraft Model- 1124 WESTWIND
Report Date 11-APR-2002
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
340111	LEAK CHECK LEFT PITOT SYSTEM	MOS						F1
34.040		HRSMSC	O/C				26-MAR-1996	
	ASSOCIATED	AFL						
	REF: AMM 34-10-01							
340106	TUBE, RIGHT PITOT	MOS						F1
34.010	4883049-1	HRSMSC	O/C	0			11-FEB-1982	
	58348	AFL				0		
	REF: AMM 34-10-01					0		
340121	DRAIN PITOT/STATIC SYSTEM	MOS						F2
34.060	PKG 1, 2, 3	HRSMSC	200				26-JUN-2001	
	ASSOCIATED	AFL				7687		1.5
	REF: AMM 34-10-00					5594		
340116	LEAK CHECK RIGHT PITOT SYSTEM	MOS						F1
34.040		HRSMSC	O/C				11-FEB-1982	
	ASSOCIATED	AFL				0		
	REF: AMM 34-10-01					0		
346648	UNIT, CONTROL DISPLAY PROCESS	MOS						F3
34.460	622-2899-016	HRSMSC	O/C	0			11-FEB-1982	
	SN-UNKNOWN	AFL		0		0		
	REF: NO REF					0		
348165	UNIT, FMS AUXILIARY EQUIPMENT	MOS						F3
34.770	622-5615-001/AEU-90	HRSMSC	O/C				10/27/1989	
	92	AFL				4311	27-JUL-1989	
	REF: AMM 34-60-03					2856		
348160	UNIT, FMS COMPUTER RECEIVER	MOS						F3
34.760	622-5614-020/CRU-90	HRSMSC	O/C				12-FEB-1990	
	52	AFL				4504		
	REF: AMM 34-60-03					3073		
348170	UNIT, FMS CONTROL DISPLAY	MOS						F3
34.790	622-5611-001/CDU-90	HRSMSC	O/C	0			11-FEB-1982	
	040	AFL				0		
	REF: AMM 34-60-03					0		
348175	UNIT, FMS DATA ENTRY	MOS						F3
34.780	622-5613-001/DEU-90	HRSMSC	O/C	0			16-AUG-1984	
	183	AFL				1890		
	REF: NO REF							
348155	UNIT, FMS RADIO TUNING	MOS						F3
34.750	622-5612-007/RTU-90	HRSMSC	O/C	0			10-MAR-1987	
	50	AFL				3623		
	REF: AMM 34-60-03					2255		
348136	UNIT, NO.1 LRN EQUIPMENT	MOS						
34.690	622-5494-001	HRSMSC	O/C	0			11-FEB-1982	
	SN-UNKNOWN	AFL		0		0		
	REF: AMM 34-60-04					0		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
348126	UNIT, NO.1 LRN RECEIVER COMP											
34.680	622-5492-001	MOS									11-FEB-1982	
	SN-UNKNOWN	HRS/MS	O/C	0						0		
	REF: AMM 34-60-04	AFL		0						0		
348141	UNIT, NO.2 LRN EQUIPMENT											
34.690	622-5494-001	MOS									11-FEB-1982	
	SN-UNKNOWN	HRS/MS	O/C	0						0		
	REF: AMM 34-60-04	AFL		0						0		
348131	UNIT, NO.2 LRN RECEIVER COMP											
34.720	622-5494-001	MOS									11-FEB-1982	
	SN-UNKNOWN	HRS/MS	O/C	0						0		
	REF: AMM 34-60-04	AFL		0						0		
346651	UNIT, VLF CONTROL DISPLAY											F3
34.610	10060-6	MOS									24-SEP-1987	
	2579	HRS/MS	O/C	0						3737		
	REF: AMM 34-10-06	AFL								2345		
346671	UNIT, VLF OPTIONAL EQUIPMENT											F3
34.630	10600-2-210	MOS									05-SEP-1989	
	2695	HRS/MS	O/C		0					4355		
	REF: AMM 34-60-02	AFL								2904		
346661	UNIT, VLF RECEIVER COMPUTER											F5
34.620	10050-4-4A-3140	MOS									05-SEP-1989	
	1937	HRS/MS	O/C		0					4355		
	REF: AMM 34-60-02	AFL								2904		
343111	VALVE, NO.1 FLUX											W1
34.120	2594484	MOS									11-FEB-1982	
	81096488	HRS/MS	O/C	0						0		
	REF: AMM 34-20-01	AFL								0		
343156	VALVE, NO.2 FLUX											W2
34.120	2594484	MOS									11-FEB-1982	
	81096489	HRS/MS	O/C	0						0		
	REF: AMM 34-20-08	AFL								0		
CHAPTER 35 OXYGEN												
350101	CYLINDER, OXYGEN										LIFE LIMIT	F2
35.010	6350A25-EE-Z	MOS	288	0						04-FEB-1982	04-FEB-2006	
	49928W	HRS/MS										
	REF: AMM 35-00-00	AFL										
350106	HYDROSTATIC TEST											F2
35.010		MOS	36							26-JUL-2000	26-JUL-2003	
		HRS/MS	3000							7325	10325	
	REF: AMM 35-00-00	AFL								5360		
350141	GAUGE, OXYGEN PRESSURE											F3
35.040	PN	MOS									11-FEB-1982	
	SN-UNKNOWN	HRS/MS	O/C	0						0		
	REF: NO REF	AFL								0		

Aircraft Model - 1124 WESTWIND

Report Date **11-APR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
350126	INDICATOR, OXYGEN DISCHARGE											F1
35.040	118082	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C	0						0		
	REF: NO REF	AFL								0		
350181	MASK, PASSENGER OXYGEN L1											F4
35.080	PN	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C	0						0		
	REF: NO REF	AFL								0		
350191	MASK, PASSENGER OXYGEN L2											F4
35.080	PN	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C	0						0		
	REF: NO REF	AFL								0		
350201	MASK, PASSENGER OXYGEN R1											F4
35.090	PN	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C	0						0		
	REF: NO REF	AFL								0		
350211	MASK, PASSENGER OXYGEN R2											F4
35.090	PN	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C	0						0		
	REF: NO REF	AFL								0		
350221	MASK, PASSENGER OXYGEN R3											F4
35.090	PN	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C	0						0		
	REF: NO REF	AFL								0		
350246	OUTLET, THERAPEUTIC OXYGEN											F4
35.120	23599-11	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C	0						0		
	REF: NO REF	AFL								0		
350158	REGULATOR, MASK COPILOT										OVERHAUL	F3
35.120	MC-1013-02	MOS	72	0						09-NOV-1996	09-NOV-2002	
	8161	HRS/MSC								5951		
	REF: NO REF	AFL								4589		
+ 350169U	CHECK											F3
35.070		MOS	12							26-JUN-2001	26-JUN-2002	
		HRS/MSC	600							7687	8287	
	REF: AMM 35-00-00	AFL								5594		
350148	REGULATOR, MASK PILOT										OVERHAUL	F3
35.120	MC-1013-02	MOS	72	0						09-NOV-1996	09-NOV-2002	
	7750	HRS/MSC		0						5951		
	REF: NO REF	AFL		0						4589		
+ 350166U	CHECK											F3
35.070		MOS	12							26-JUN-2001	26-JUN-2002	
		HRS/MSC	600							7687	8287	
	REF: AMM 35-00-00	AFL								5594		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
350241	REGULATOR, OXYGEN DEMAND CONTROL PANEL (PURITAN) COPILOT							F3
35.110	101202-11	MOS					11-FEB-1982	
	SN-UNKNOWN	HRSMSC	O/C	0		0		
	REF: AMM 35-10-00	AFL				0		
350236	REGULATOR, OXYGEN DEMAND CONTROL PANEL (PURITAN) PILOT							F3
35.110	101202-11	MOS					11-FEB-1982	
	SN-UNKNOWN	HRSMSC	O/C	0		0		
	REF: AMM 35-10-00	AFL				0		
350116	REGULATOR, PRESSURE REDUCER							F3
35.030	112031-06	MOS					11-FEB-1982	\$970.
	670A	HRSMSC	O/C	0		0		8
	REF: AMM 35-00-00	AFL				0		
350136	SWITCH, ALTITUDE PRESSURE							F3
35.060	101800	MOS					11-FEB-1982	
	8024154	HRSMSC	O/C	0		0		
	REF: AMM 35-00-00	AFL				0		
350231	SYSTEM, PASSENGER OXYGEN SUPPLY							F3
35.100	5753004-400	MOS					11-FEB-1982	\$950.
	189	HRSMSC	O/C	0		0		6
	REF: AMM 35-20-00	AFL				0		
350163	INSPECT/SERVICE OXYGEN SYSTEM							F3
35.140		MOS					13-NOV-1995	
	189	HRSMSC	O/C			5718		
	REF: AMM 35-00-00	AFL				4397		
+ 350243	TEST							F4
35.130	PKG 3	MOS					26-JUL-2000	
		HRSMSC	800			7325		
	REF: AMM 35-00-00	AFL				5360		
350103	VALVE, OXYGEN CYLINDER							F2
35.150	6350-A25-DDC	MOS					11-DEC-1984	
	SN-UNKNOWN	HRSMSC	O/C			2119		
	REF: NO REF	AFL				1302		
350111	VALVE, OXYGEN FILLER							F1
35.020	26875-48	MOS					11-FEB-1982	
	SN-UNKNOWN	HRSMSC	O/C	0		0		
	REF: AMM 35-00-00	AFL				0		
350131	VALVE, OXYGEN SHUTOFF							F2
35.050	110115	MOS					11-FEB-1982	
	SN-UNKNOWN	HRSMSC	O/C	0		0		
	REF: AMM 35-00-00	AFL				0		
350108	VALVE, TOGGLE							F2
35.150	170001	MOS					11-FEB-1982	
	8894	HRSMSC	O/C	0		0		
	REF: NO REF	AFL				0		
CHAPTER 49	AIRBORNE AUXILIARY POWER							

Aircraft Model - 1124 WESTWIND
Report Date 11-APR-2002
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
49APU1	APU, PN SN-UNKNOWN REF:	MOS HRS/MSA AFL	E/C								
CHAPTER 52	DOORS										
520181	LUBRICATE CABIN ENTRANCE STEP										F4
52.020		MOS HRS/MSA AFL	O/C						11-FEB-1982 0 0		
	REF: AMM 12-20-00										
520161	DOOR, COMPARTMENT										F5
52.040	CMA21212-002 SN-UNKNOWN REF: AMM 52-30-00	MOS HRS/MSA AFL	O/C	0					11-FEB-1982 0 0		
520171	DOOR, COMPARTMENT REAR BAGGAGE										F5
52.050	CMA22211-001 SN-UNKNOWN REF: AMM 52-30-01	MOS HRS/MSA AFL	O/C	0					11-FEB-1982 0 0		
520101	DOOR, ENTRANCE CABIN										F4
52.010	333045-505 SN-UNKNOWN REF:	MOS HRS/MSA AFL	O/C	0					11-FEB-1982 0 0		
+ 520106	INSPECT/LUBRICATE										F4
52.010	PKG 1, 2, 3	MOS HRS/MSA AFL	200						26-JUN-2001 7687 5594		
	REF: AMM 52-10-00/12-20-00										
+ 520116	OPERATIONAL CHECK										F4
52.010	PKG 1, 2, 3	MOS HRS/MSA AFL	200						26-JUN-2001 7687 5594		
	REF: AMM 52-10-00										
520136	HATCH, EMERGENCY EXIT LEFT										F4
52.030	5-333031-501 SN-UNKNOWN REF: AMM 52-20-00	MOS HRS/MSA AFL	O/C	0					11-FEB-1982 0 0		
+ 520141	INSPECT/LUBRICATE SEAL										F4
52.030	PKG 3	MOS HRS/MSA AFL	800						26-JUL-2000 7325 5360		
	REF: See Workcard										
520146	HATCH, EMERGENCY EXIT RIGHT										F4
52.030	5-333031-501 SN-UNKNOWN REF: AMM 52-20-00	MOS HRS/MSA AFL	O/C	0					11-FEB-1982 0 0		
+ 520151	INSPECT/LUBRICATE SEAL										F4
52.030	PKG 3	MOS HRS/MSA AFL	800						26-JUL-2000 7325 5360		
	REF: See Workcard										

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT----- TSN TSO TSR TSI ADJ	INSTALLATION	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
520166 52.060	SEAL, COMPARTMENT DOOR CMA21212-057 SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL	O/C	0			11-FEB-1982 0 0		F5
520173 52.060	SEAL, COMPARTMENT DOOR REAR BAGGAGE CMA22211-006 SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL	O/C	0			11-FEB-1982 0 0		F5
520126 52.010	SEAL, ENTRANCE DOOR CABIN 333045-181 SN-UNKNOWN REF: AMM 52-10-00	MOS HRSMSC AFL	O/C	0			01-DEC-1995 5727 4410		F4
520176 52.020	STEP, ENTRANCE CABIN 5-123580-1 SN-UNKNOWN REF: AMM 52-60-00	MOS HRSMSC AFL	O/C	0			11-FEB-1982 0 0		F4
CHAPTER 53 FUSELAGE									
+ 530121 53.0202	INSPECT NOSE COMPARTMENT (B) PKG 2, 3 REF: AMM 5-20-01,-05	MOS HRSMSC AFL	400				26-JUN-2001 7687 5594		F2
+ 530300 53.170	INSPECT AFT FUSELAGE STRUCTURE REF: AMM 5-40-02	MOS HRSMSC AFL	4800				24-AUG-1993 5326 3975	MANDATORY 10126	F5
+ 530235 53.120	INSPECT AFT PRESSURE BULKHEAD AFT WEBS REF: AMM 5-40-01	MOS HRSMSC AFL	15000					MANDATORY 15000	F5
+ 530230 53.110	INSPECT AFT PRESSURE BULKHEAD FORWARD WEBS. REF: AMM 5-40-01	MOS HRSMSC AFL	9600					MANDATORY 9600	F5
+ 530250 53.150	INSPECT AFT PRESSURE BULKHEAD J-BEAM SPLICE FROM CABIN SIDE REF: AMM 5-40-01	MOS HRSMSC AFL	9600					MANDATORY 9600	F5
+ 530255 53.160	INSPECT AFT PRESSURE BULKHEAD J-BEAM SPLICE FROM FUEL COMPARTMENT REF: AMM 5-40-01	MOS HRSMSC AFL	15000					MANDATORY 15000	F5
+ 530240 53.130	INSPECT AFT PRESSURE BULKHEAD PERIPHERAL SECTION FROM CABIN SIDE. REF: AMM 5-40-01	MOS HRSMSC AFL	9600					MANDATORY 9600	F5

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEMNO	WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
+ 530245	53.140	INSPECT AFT PRESSURE BULKHEAD PERIPHERAL SECTION FROM FUEL COMPARTMENT	MOS					MANDATORY	F5
		REF: AMM 5-40-01	HRS/MSAFL	15000				15000	
+ 530176	53.060	INSPECT AUXILIARY FUEL TANK STRUCTURE	MOS				26-JUL-2000		F5
		PKG 3	HRS/MSAFL	800			73255360		
		REF: AMM 5-20-09							
+ 530146	53.0401	INSPECT CABIN (A)	MOS				26-JUN-2001		F4
		PKG 1, 2, 3	HRS/MSAFL	200			76875594		
		REF: AMM 5-20-02							
+ 530156	53.0402	INSPECT CABIN (C)	MOS				26-JUL-2000		F4
		PKG 3	HRS/MSAFL	800			73255360		
		REF: AMM 5-20-02							
+ 530131	53.0301	INSPECT COCKPIT (A)	MOS				26-JUN-2001		F3
		PKG 1, 2, 3	HRS/MSAFL	200			76875594		
		REF: AMM 5-20-02,-03							
+ 530136	53.0302	INSPECT COCKPIT (B)	MOS				26-JUN-2001		F3
		PKG 2, 3	HRS/MSAFL	400			76875594		
		REF: AMM 5-20-02							
+ 530141	53.0303	INSPECT COCKPIT (C)	MOS				26-JUL-2000		F3
		PKG 3	HRS/MSAFL	800			73255360		
		REF: AMM 5-20-02							
+ 530220	53.100	INSPECT ENTRY DOOR STOPS	MOS				24-AUG-1993	MANDATORY	F4
		REF: AMM 5-40-01	HRS/MSAFL	5400			53263975	10726	
		REF: AMM 5-40-01							
+ 530205	53.180	INSPECT FORWARD TO AFT MAIN FRAME	MOS				26-JUL-2000		F4
		REF: AMM 5-40-01	HRS/MSAFL	800			73255360	8125	
		REF: AMM 5-40-01							
+ 530200	53.080	INSPECT FORWARD TO AFT PRESSURE BULKHEAD-FUSELAGE	MOS				26-JUL-2000	MANDATORY	F4
		REF: AMM 5-40-01	HRS/MSAFL	800			73255360	8125	
		REF: AMM 5-40-01							
+ 530101	53.010	INSPECT FUSELAGE (A)	MOS				26-JUN-2001		F1
		PKG 1, 2, 3	HRS/MSAFL	200			76875594		
		REF: AMM 5-20-02							

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
+ 530210 53.090	INSPECT FUSELAGE SKINS FLIGHT COMPARTMENT SIDE WINDOW	MOS				24-AUG-1993	MANDATORY	F4
	REF: AMM 5-40-01	HRSMSC AFL	4800			5326 3975	10126	
+ 530116 53.0201	INSPECT NOSE COMPARTMENT (A) PKG 1, 2, 3	MOS				26-JUN-2001		F2
	REF: AMM 5-20-01,-05	HRSMSC AFL	200			7687 5594		
+ 530161 53.0501	INSPECT REAR COMPARTMENT (A) PKG 1, 2, 3	MOS				26-JUN-2001		F5
	REF: AMM 5-20-05	HRSMSC AFL	200			7687 5594		
+ 530166 53.0502	INSPECT REAR COMPARTMENT (B) PKG 2, 3	MOS				26-JUN-2001		F5
	REF: AMM 5-20-05	HRSMSC AFL	400			7687 5594		
531101 53.070	CONE, NOSE F10A-5-RD5-20000-7 SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL	O/C	0 0		11-FEB-1982 0 0		F2
CHAPTER 54 NACELLES/PYLONS								
+ 540200 54.020	INSPECT ENGINE SUPPORT INSTALLATION	MOS				24-AUG-1993	MANDATORY	
	REF: AMM 5-40-04	HRSMSC AFL	4800			5326 3975	10126	
+ 540101U 54.0101	INSPECT NO. 1 ENGINE NACELLE/PYLON (A) PKG 1, 2, 3	MOS				26-JUN-2001		E1
	REF: AMM 5-20-07,-08/12-02-00	HRSMSC AFL	200			7687 5594		
+ 540106U 54.0102	INSPECT NO. 1 ENGINE NACELLE/PYLON (B) PKG 2, 3	MOS				26-JUN-2001		E1
	REF: AMM 5-20-07,-08/12-02-00	HRSMSC AFL	400			7687 5594		3
+ 540111U 54.0103	INSPECT NO. 1 ENGINE NACELLE/PYLON (C) PKG 3	MOS				26-JUL-2000		E1
	REF: AMM 5-20-07,-08/12-02-00	HRSMSC AFL	800			7325 5360		
+ 540121U 54.0101	INSPECT NO. 2 ENGINE NACELLE/PYLON (A) PKG 1, 2, 3	MOS				26-JUN-2001		E2
	REF: AMM 5-20-07,-08/12-02-00	HRSMSC AFL	200			7687 5594		
+ 540126U 54.0102	INSPECT NO. 2 ENGINE NACELLE/PYLON (B) PKG 2, 3	MOS				26-JUN-2001		E2
	REF: AMM 5-20-07,-08/12-02-00	HRSMSC AFL	400			7687 5594		3

Aircraft Model - 1124 WESTWIND
Report Date 11-APR-2002
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
+ 540131U 54.0103	INSPECT NO. 2 ENGINE NACELLE/PYLON (C) PKG 3	MOS HRS/MS AFL	800			26-JUL-2000 7325 5360		E2
CHAPTER 55 STABILIZERS								
+ 550101 55.0101	INSPECT EMPENNAGE (A) PKG 1, 2, 3	MOS HRS/MS AFL	200			26-JUN-2001 7687 5594		T1
REF: AMM 5-20-07,-08/12-02-00								
+ 550106 55.0102	INSPECT EMPENNAGE (B) PKG 2, 3	MOS HRS/MS AFL	400			26-JUN-2001 7687 5594		T1
REF: AMM 5-20-06/12-20-00								
+ 550200 55.060	INSPECT EMPENNAGE (MAJOR)	MOS HRS/MS AFL	4800			24-AUG-1993 5326 3975	MANDATORY 10126	T1
REF: AMM 5-40-03								
550651 55.030	STABILIZER, HORIZONTAL 5453015-4 13-1 SN-UNKNOWN REF: AMM 55-10-00	MOS HRS/MS AFL	O/C	0		11-FEB-1982 0 0		T1
550656 55.040	CHECK AFT SPAR SPLICE-HINGE FITTING OUTBOARD LUGS FOR CRACKS PKG 1, 2, 3	MOS HRS/MS AFL	200			26-JUN-2001 7687 5594		T1
REF: AMM 55-10-00								
550658 55.050	CHECK ASSEMBLY RADIAL/AXIAL PLAY PKG 3	MOS HRS/MS AFL	800			26-JUL-2000 7325 5360		T1
REF: See Workcard								
270214 27.195 ASSOCIATED	LUBRICATE AFT HINGE FITTING BEARINGS PKG 1, 2, 3	MOS HRS/MS AFL	200			26-JUN-2001 7687 5594		T1
REF: NO REF								
270215 27.195 ASSOCIATED	LUBRICATE FORWARD SCISSOR ASSEMBLY PKG 1, 2, 3	MOS HRS/MS AFL	200			26-JUN-2001 7687 5594		T1
REF: NO REF								
SB 1124-55-097 ASSOCIATED	STABILIZER SCISSR SERVICE BULLETIN	MOS HRS/MS AFL	A/R			0 0		T1
REF: See Workcard								
Method of Compliance: OPEN								
550601 55.020	STABILIZER, VERTICAL 5413027-4 11 SN-UNKNOWN REF: See Workcard	MOS HRS/MS AFL	O/C	0		11-FEB-1982 0 0		T1

CHAPTER 56 WINDOWS

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
561601	WINDOW, EMERGENCY EXIT NO.L3 LEFT											F4
56.075	PN	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0						0		
	REF: AMM 56-20-00	AFL								0		
561606	WINDOW, EMERGENCY EXIT NO.R4 RIGHT											F4
56.075	PN	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0						0		
	REF: AMM 56-20-00	AFL								0		
560601	WINDOW, NO.L1 LEFT											F4
56.050	5-343016-501	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0						0		
	REF: AMM 56-20-00	AFL								0		
560606	WINDOW, NO.L2 LEFT											F4
56.060	5-343016-501	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0						0		
	REF: AMM 56-20-00	AFL								0		
560611	WINDOW, NO.L4 LEFT											F4
56.070	5-343016-501	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0						0		
	REF: AMM 56-20-00	AFL								0		
560616	WINDOW, NO.L5 LEFT											F4
56.080	5-343016-501	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0						0		
	REF: AMM 56-20-00	AFL								0		
561101	WINDOW, NO.R1 RIGHT											F4
56.050	5-343016-501	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0						0		
	REF: AMM 56-20-00	AFL								0		
561106	WINDOW, NO.R2 RIGHT											F4
56.060	5-343016-501	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0						0		
	REF: AMM 56-20-00	AFL								0		
561111	WINDOW, NO.R3 RIGHT											F4
56.070	5-343016-501	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0						0		
	REF: AMM 56-20-00	AFL								0		
561116	WINDOW, NO.R5 RIGHT											F4
56.080	5-343016-501	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0						0		
	REF: AMM 56-20-00	AFL								0		
561121	WINDOW, NO.R6 RIGHT											F4
56.080	5-343016-501	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0						0		
	REF: AMM 56-20-00	AFL								0		

Aircraft Model - 1124 WESTWIND
Report Date 11-APR-2002
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
560121		WINDOW, OVERHEAD							F3
56.040		5-343021-1	MOS				11-FEB-1982		
		SN-UNKNOWN	HRS/MS	O/C	0		0		
		REF: AMM 56-10-02	AFL		0		0		
560126		WINDOW, OVERHEAD							F3
56.040		5-343021-2	MOS				11-FEB-1982		
		SN-UNKNOWN	HRS/MS	O/C	0		0		
		REF: AMM 56-10-02	AFL		0		0		
560116		WINDOW, SIDE COPILOT							F3
56.030		5-343003-501	MOS				11-FEB-1982		
		SN-UNKNOWN	HRS/MS	O/C	0		0		
		REF: AMM 56-10-04	AFL		0		0		
+ 560118		INSPECT							F3
56.030		PKG 3	MOS				26-JUL-2000		
			HRS/MS	800			7325		
		REF: See Workcard	AFL				5360		
560111		WINDOW, SIDE PILOT							F3
56.030		5-343017-505	MOS				11-FEB-1982		
		SN-UNKNOWN	HRS/MS	O/C	0		0		
		REF: AMM 56-10-03	AFL		0		0		
+ 560112		INSPECT							F3
56.030		PKG 3	MOS				26-JUL-2000		
			HRS/MS	800			7325		
		REF: AMM 56-10-03	AFL				5360		
560107		WINDSHIELD, INNER COPILOT							F3
56.020		5343035	MOS				11-FEB-1982		
		SN-UNKNOWN	HRS/MS	O/C	0		0		
		REF: AMM 56-10-01	AFL				0		
560102		WINDSHIELD, INNER PILOT							F3
56.020		5343035	MOS				11-FEB-1982		
		SN-UNKNOWN	HRS/MS	O/C	0		0		
		REF: AMM 56-10-01	AFL				0		
560106		WINDSHIELD, OUTER COPILOT							F3
56.010		PPG 343030-2	MOS				26-AUG-2000		
		99064H0109	HRS/MS	O/C	0		7352		
		REF: AMM 56-10-01	AFL		0		5381		
560101		WINDSHIELD, OUTER PILOT							F3
56.010		343030-1	MOS				22-FEB-2000		
		98342H0422	HRS/MS	O/C	0		7107		
		REF: AMM 56-10-01	AFL		0		5232		
CHAPTER 57									
WINGS									
+ 570220		INSPECT LEFT OUTER WING PANELS						MANDATORY	W1
57.050			MOS				24-AUG-1993		
			HRS/MS	4800			5326	10126	
		REF: AMM 5-40-05	AFL				3975		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT----- TSN TSO TSR TSI ADJ	INSTALLATION	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
+ 570101 57.0101	INSPECT LEFT WING (A) PKG 1, 2, 3	MOS HRSMSC AFL	200				26-JUN-2001 7687 5594		W1 1.5
	REF: AMM 5-20-03								
+ 570104 57.0102	INSPECT LEFT WING (B) PKG 2, 3	MOS HRSMSC AFL	400				26-JUN-2001 7687 5594		W1
	REF: AMM 5-20-03								
+ 570200 57.040	INSPECT LEFT WING STRUCTURE	MOS HRSMSC AFL	15000					MANDATORY 15000	W1
	REF: AMM 5-40-05								
+ 570120 57.020	INSPECT RIGHT AILERON BELL CRANK PKG 1, 2, 3	MOS HRSMSC AFL	200				26-JUN-2001 7687 5594		W2
	REF: AMM 5-20-03								
+ 570221 57.050	INSPECT RIGHT OUTER WING PANELS	MOS HRSMSC AFL	4800				24-AUG-1993 5326 3975	MANDATORY 10126	W2
	REF: AMM 5-40-05								
+ 570116 57.0101	INSPECT RIGHT WING (A) PKG 1, 2, 3	MOS HRSMSC AFL	200				26-JUN-2001 7687 5594		W2 1.5
	REF: AMM 5-20-03								
+ 570119 57.0102	INSPECT RIGHT WING (B) PKG 2, 3	MOS HRSMSC AFL	400				26-JUN-2001 7687 5594		W2
	REF: AMM 5-20-03								
+ 570201 57.040	INSPECT RIGHT WING STRUCTURE	MOS HRSMSC AFL	15000					MANDATORY 15000	W2
	REF: AMM 5-40-05								
570031 57.030	TANK, TIP LEFT 5213003-405 SN-UNKNOWN REF: AMM 57-20-00	MOS HRSMSC AFL	O/C	0			11-FEB-1982 0 0		W1
570041 57.030	TANK, TIP RIGHT 5213003-406 SN-UNKNOWN REF: AMM 57-20-00	MOS HRSMSC AFL	O/C	0			11-FEB-1982 0 0		W2
CHAPTER 71 POWER PLANT									
+ 710650U	- INSP #1 ENG INLET NACELLE PKG 1, 2, 3	MOS HRSMSC AFL	200				26-JUN-2001 7687 5594		E1
	REF:								

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT----- TSN TSO TSR TSI ADJ	INSTALLATION	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
+ 713650U	-- INSP #2 ENG INLET NACELLE PKG 1, 2, 3	MOS							E2
	REF:	HRS/MSC AFL	200				26-JUN-2001 7687 5594		
71EN1	ENGINE, NO. 1 3072500-2 P-77482	MOS							
	REF:	HRS/MSC AFL	E/C						
71EN2	ENGINE, NO. 2 3072500-2 P77488	MOS							
	REF:	HRS/MSC AFL	E/C						
CHAPTER 73 ENGINE FUEL AND CONTROL									
731101U	COMPUTER, FUEL CONT ENG #1 2101144-1	MOS							F5
	SN-UNKNOWN	HRS/MSC	O/C	3972			03-APR-1989 4215		\$4400.
	REF:	AFL		2456			2745		3
733601U	COMPUTER, FUEL CONT ENG #2 2101144-1	MOS							F5
	51-2172	HRS/MSC	O/C	4215			31-MAY-1989 4265		\$4400.
	REF:	AFL		2745			2793		3
732106U	INDICATOR, FUEL FLO ENG #1 6-883708-1	MOS							F3
	SN-UNKNOWN	HRS/MSC	O/C	3209			30-JUL-1986 3209		\$372.
	REF:	AFL		1976			1976		
734606U	INDICATOR, FUEL FLO ENG #2 6-883708-1	MOS							F3
	SN-UNKNOWN	HRS/MSC	O/C	3017			30-JUL-1986 3209		\$372.
	REF:	AFL		1772			1976		
CHAPTER 75 AIR									
750116	SENSOR, TEMPERATURE INLET 3070816-2	MOS							E1
75.030	SN-UNKNOWN	HRS/MSC	O/C	3972			03-APR-1989 4215		
	REF: See Workcard	AFL		2456			2745		
750616	SENSOR, TEMPERATURE INLET 3070816-2	MOS							E2
75.030	15594	HRS/MSC	O/C	1592			31-MAY-1989 4265		
	REF: See Workcard	AFL					2793		
CHAPTER 77 ENGINE INDICATING									
771606	INDICATOR, (N1) LOW-PRESSURE NO. 2 ENGINE 6-883619-1	MOS							F3
77.020	4162	HRS/MSC	O/C	0			11-FEB-1982 0		\$1100.
	REF: AMM 77-00-00	AFL					0		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
770106	INDICATOR, (N1) LOW-PRESSURE NO. 1 ENGINE											F3
77.020	6883619-1	MOS								11-FEB-1982		\$1100.
	SN-UNKNOWN	HRS/MS	O/C	0						0		
	REF: AMM 77-00-00	AFL								0		
770606	INDICATOR, (N2) HIGH-PRESSURE NO. 1 ENGINE											F3
77.040	6883620-1	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0						0		
	REF: AMM 77-00-00	AFL								0		
772106	INDICATOR, (N2) HIGH-PRESSURE NO. 2 ENGINE											F3
77.040	6-883620-1	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0						0		
	REF: AMM 77-00-00	AFL								0		
771106	INDICATOR, ITT NO. 1 ENGINE											F3
77.060	6883621-503	MOS								31-MAY-1993		\$507.
	R0097	HRS/MS	O/C		0					5278		
	REF: AMM 77-00-00	AFL								3928		
772606	INDICATOR, ITT NO. 2 ENGINE											F3
77.060	6883621-503	MOS								31-MAY-1993		\$507.
	R0031R	HRS/MS	O/C		0					5278		
	REF: AMM 77-00-00	AFL								3928		
CHAPTER 78												
EXHAUST												
+ 780119	CHECK #1 THRUST REVERSER SECONDARY LATCH SOLENOID SWITCH											E1
78.140	PKG 3	MOS								26-JUL-2000		
		HRS/MS	800							7325		
	REF: AMM 78-30-00	AFL								5360		
+ 780120	CHECK #2 THRUST REVERSER SECONDARY LATCH SOLENOID SWITCH											E2
78.140	PKG 3	MOS								26-JUL-2000		
		HRS/MS	800							7325		
	REF: AMM 78-30-00	AFL								5360		
+ 780116	OPERATIONAL CHECK NO.1 THRUST REVERSER											E1
78.110	PKG 3	MOS								26-JUL-2000		
		HRS/MS	800							7325		
	REF: AMM 78-30-00	AFL								5360		
+ 780616	OPERATIONAL CHECK NO.2 THRUST REVERSER											E2
78.110	PKG 3	MOS								26-JUL-2000		
		HRS/MS	800							7325		
	REF: AMM 78-30-00	AFL								5360		
780156	ACCUMULATOR, THRUST REVERSER											F5
78.040	4723565-1	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0						0		
	REF: AMM 78-34-00	AFL								0		
780146	ACTUATOR, THRUST REVERSER NO. 1											E1
78.020	F10A-5-SCH203-1	MOS								02-JAN-1987		
	0419	HRS/MS	O/C	0						3504		
	REF: AMM 78-34-00	AFL								2168		

Aircraft Model- 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT----- TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
780646		ACTUATOR, THRUST REVERSER NO. 2							E2
	78.020	F10A-5-SCH203-1	MOS				11-FEB-1982		
		SN-UNKNOWN	HRSMSC	O/C	0		0		
		REF: AMM 78-34-00	AFL				0		
780161		BOTTLE, THRUST REVERSER GAS STORAGE						LIFE LIMIT	F5
	78.050	3753015-501	MOS	288	0		11-FEB-1982	11-FEB-2006	
		07511A1	HRSMSC						
		REF: AMM 78-34-00	AFL						
+ 780163		HYDROSTATIC TEST							F5
	78.050		MOS	36			26-OCT-1999	26-OCT-2002	
			HRSMSC				6961		
		REF: See Workcard	AFL				5135		
780131		CONTROL ASSEMBLY, THROTTLE RETARDER FEEDBACK NO. 1						LIFE LIMIT	E1
	78.090	F10A-5SCP203-1	MOS				11-FEB-1982		
		SN-UNKNOWN	HRSMSC	10000	0		0	10000	
		REF: AMM 78-32-00	AFL				0		
780136		CLEAN/LUBRICATE NO.1 THROTTLE RETARDER CABLE AND CASING							E1
	78.090		MOS	36			06-NOV-2001	06-NOV-2004	
			HRSMSC				7774		
		REF: AMM 12-20-00	AFL				5641		
780631		CONTROL ASSEMBLY, THROTTLE RETARDER FEEDBACK NO. 2						LIFE LIMIT	E2
	78.090	F10A-5SCP203-2	MOS				11-FEB-1982		
		SN-UNKNOWN	HRSMSC	10000	0		0	10000	
		REF: AMM 78-32-00	AFL				0		
780636		CLEAN/LUBRICATE NO.2 THROTTLE RETARDER CABLE AND CASING							E2
	78.090		MOS	36			06-NOV-2001	06-NOV-2004	
			HRSMSC				7774		
		REF: AMM 78-32-00	AFL				5641		
780171		RELEASE VALVE, THRUST REVERSER							F5
	78.070	3723581-1	MOS				11-FEB-1982		
		SN-UNKNOWN	HRSMSC	O/C	0		0		
		REF: AMM 78-34-00	AFL				0		
780158		SWITCH, THRUST REVERSER LOW-PRESSURE							F5
	78.080	4713533-1	MOS				11-FEB-1982		
		SN-UNKNOWN	HRSMSC	O/C	0		0		
		REF: AMM 78-34-00	AFL				0		
780141		THRUST REVERSER ASSEMBLY, NO. 1							E1
	78.010	F10A-5-B20202-1	MOS				11-FEB-1982		
		SN-UNKNOWN	HRSMSC	O/C	0		0		
		REF: NO REF	AFL				0		
+ 780148		INSPECT						INSPECT	E1
	78.130		MOS				20-AUG-1991		
			HRSMSC	5000			4906	9906	
		REF: See Workcard	AFL						

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND

Report Date **11-APR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
780143 78.100	LUBRICATE PKG 3	MOS HRSMSC AFL	800							26-JUL-2000 7325 5360		E1
	REF: AMM 12-20-00											
780641 78.011	THRUST REVERSER ASSEMBLY, NO. 2 F10A-5-B20202-2 SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0		E2
+ 780648 78.130	INSPECT	MOS HRSMSC AFL	5000							20-AUG-1991 4906	INSPECT 9906	E2
	REF: See Workcard											
780643 78.100	LUBRICATE PKG 3	MOS HRSMSC AFL	800							26-JUL-2000 7325 5360		E2
	REF: AMM 12-20-00											
780166 78.060	VALVE, RELIEF PN SN-UNKNOWN REF: AMM 78-34-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0		F5
780151 78.030	VALVE, THRUST REVERSER CONTROL NO. 1 723573 525 REF: AMM 78-34-00	MOS HRSMSC AFL	O/C	0						08-APR-1987 3684 2293		F5 \$588. 2
780651 78.030	VALVE, THRUST REVERSER CONTROL NO. 2 723573 SN-UNKNOWN REF: AMM 78-34-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0		F5 \$588. 2
CHAPTER 79 OIL												
791121U	IND, PRESS/TEMP ENG #1 6-883706-1 SN-UNKNOWN REF:	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0		F3 \$805.
792621U	IND, PRESS/TEMP ENG #2 6-883706-1 SN-UNKNOWN REF:	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0		F3 \$805.
790616U	VALVE, OIL TEMP ENG #1 157025-2 SN-UNKNOWN REF:	MOS HRSMSC AFL	O/C	3972 2456						03-APR-1989 4215 2745		E1
792116U	VALVE, OIL TEMP ENG #2 157025-2 SN-UNKNOWN REF:	MOS HRSMSC AFL	O/C	4215						31-MAY-1989 4265 2793		E2

Engine Model - TFE731-3
Report Date 11-APR-2002
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
ENGINE NO. 1								
CHAPTER 71 POWER PLANT								
710140U	NO. 1 ENGINE - -- RUN ADJ/TEST #1 ENG	MOS					13-NOV-1999	
	REF:	HRS/MSC	C/C			6961		
		ENC				5135		
		(AFL)						
+ 714010	NO. 1 ENGINE - CHECK ELECTRICAL WIRES AND CONNECTIONS	MOS				26-JUL-2000		
71.040		HRS/MSC	800			7325	8125	
	REF: EMM 72-00-00	ENC				5360		
		(AFL)						
+ 715010	NO. 1 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS	MOS				26-JUL-2000		
71.050		HRS/MSC	800			7325	8125	
	REF: EMM 72-00-00	ENC				5360		
		(AFL)						
+ 710130	NO. 1 ENGINE - INSPECT FAN ROTOR ASSEMBLY BLADES	MOS				16-FEB-2001		
71.020	PKG 6, 6	HRS/MSC	300			7551		.5
	REF: EMM 72-00-00	ENC				5515		
		(AFL)						
+ 710120	NO. 1 ENGINE - MAJOR PERIODIC INSPECTION	MOS				13-NOV-1999		
71.010		HRS/MSC	1400			6961	8361	
	REF: EMM 72-00-00	ENC				5135		
		(AFL)						
710110U	NO. 1 ENGINE - ENGINE, #1	MOS				03-APR-1989		
	3072500-2	HRS/MSC	O/C	3972		4215		
	P-77482	ENC				2745		
	REF:	(AFL)		2456				
CHAPTER 72 ENGINE								
+ 724120	NO. 1 ENGINE - INSPECT COMBUSTION PLENUM CASE	MOS				13-NOV-1999		
72.030		HRS/MSC	1400			6961	8361	
	REF: EMM 72-40-04	ENC				5135		
		(AFL)						
+ 723110	NO. 1 ENGINE - INSPECT COMPRESSOR CORE	MOS				26-APR-1994		
72.010		HRS/MSC	4200			5442	9642	
	REF: NO REF	ENC				4106		
		(AFL)						

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Engine Model - TFE731-3
Report Date 11-APR-2002
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
+ 727110 72.300	NO. 1 ENGINE - PERIODIC INSPECT FAN SUPPORT ASSEMBLY	MOS				26-APR-1994		
	REF: EMM 72-70-06	HRS/MS ENC (AFL)	4200			5442	9642	
724110 72.020	NO. 1 ENGINE - CASE, COMBUSTION PLENUM 3072443-4 IP8088 REF: NO REF	MOS HRS/MS ENC (AFL)	O/C	3972		03-APR-1989 4215		
				2456		2745		
+ 724120 72.030 ASSOCIATED	NO. 1 ENGINE - INSPECT COMBUSTION PLENUM CASE	MOS				13-NOV-1999		
	REF: EMM 72-40-04	HRS/MS ENC (AFL)	1400			6961	8361	
725050 72.090	NO. 1 ENGINE - DISC, FAN ROTOR 3073563-2 970322902451 REF: NO REF	MOS HRS/MS ENC (AFL)		0		13-NOV-1999 6961		
			10000	0		5135	15135	
725060 72.100	NO. 1 ENGINE - DISC, STAGE 1 LOW PRESSURE COMPRESSOR 3072395 1-12112-1531 REF: NO REF	MOS HRS/MS ENC (AFL)				03-APR-1989 4215		
			10000	2456		2745	10289	
725010 72.040	NO. 1 ENGINE - DISC, STAGE 1 LOW PRESSURE TURBINE 3072352-4 0-03229-1212 REF: NO REF	MOS HRS/MS ENC (AFL)		0		12-JUL-1991 4879		
			3000	0		3494	6494	
725070 72.110	NO. 1 ENGINE - DISC, STAGE 2 LOW PRESSURE COMPRESSOR 3072396 1-12112-429 REF: NO REF	MOS HRS/MS ENC (AFL)		3972		03-APR-1989 4215		
			10000	2456		2745	10289	
725020 72.050	NO. 1 ENGINE - DISC, STAGE 2 LOW PRESSURE TURBINE 3072351-5 1-03226-1486 REF: NO REF	MOS HRS/MS ENC (AFL)		0		20-MAY-1993 5278		
			3000	0		3928	6928	
725080 72.120	NO. 1 ENGINE - DISC, STAGE 3 LOW PRESSURE COMPRESSOR 3072397 0-12112-4057 REF: NO REF	MOS HRS/MS ENC (AFL)		3972		03-APR-1989 4215		
			10000	2456		2745	10289	

Engine Model - TFE731-3
Report Date 11-APR-2002
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT----- TSN TSO TSR TSI ADJ	INSTALLATION	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
725030	NO. 1 ENGINE - DISC, STAGE 3 LOW PRESSURE TURBINE							LIFE LIMIT	
72.060	3074097-1	MOS					13-NOV-1999		
	975332202025	HRSMSC		0			6961		
	REF: NO REF	ENC							
	(AFL)		7000	0			5135	12135	
725090	NO. 1 ENGINE - DISC, STAGE 4 LOW PRESSURE COMPRESSOR							LIFE LIMIT	
72.130	3072398	MOS					03-APR-1989		
	0-03160-3697	HRSMSC		3972			4215		
	REF: NO REF	ENC							
	(AFL)		10000	2456			2745	10289	
725160	NO. 1 ENGINE - DUCT, TURBINE INTERSTAGE TRANSITION								
72.200	3072318	MOS					03-APR-1989		
	SN-UNKNOWN	HRSMSC	O/C				4215		
	REF: EMM 72-50-05	ENC							
	(AFL)						2745		
726110	NO. 1 ENGINE - GEARBOX, ACCESSORY								
72.250	3070003-5	MOS					03-APR-1989		
	SN-UNKNOWN	HRSMSC	O/C	3972			4215		
	REF: EMM 72-60-01	ENC							
	(AFL)			2456			2745		
+ 726120	NO. 1 ENGINE - INSPECT								
72.260		MOS					26-APR-1994		
	REF: EMM 72-60-02	HRSMSC	4200				5442	9642	
	(AFL)	ENC							
							4106		
726130	NO. 1 ENGINE - GEARBOX, TRANSFER								
72.270	3070093-3	MOS					03-APR-1989		
	P-2768	HRSMSC	O/C	0			4215		
	REF: EMM 72-60-01	ENC							
	(AFL)			0			2745		
725110	NO. 1 ENGINE - IMPELLER, HIGH PRESSURE							LIFE LIMIT	
72.150	3073398-1	MOS					03-APR-1989		
	4-23365-1094	HRSMSC		3972			4215		
	REF: NO REF	ENC							
	(AFL)		10000	2456			2745	10289	
725180	NO. 1 ENGINE - NOZZLE, STAGE 1 LOW PRESSURE TURBINE								
72.220	3072319-11	MOS					13-NOV-1999		
	990134506659	HRSMSC	O/C	0			6961		
	REF: NO REF	ENC							
	(AFL)			0			5135		
725140	NO. 1 ENGINE - PLATE, HIGH PRESSURE ROTOR SEAL							LIFE LIMIT	
72.180	3072411-1	MOS					13-NOV-1999		
	7-18040-2569	HRSMSC		3816			6961		
	REF: NO REF	ENC							
	(AFL)		10000	2507			5135	12628	

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Engine Model - TFE731-3
Report Date 11-APR-2002
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
725040	NO. 1 ENGINE - ROTOR, HIGH PRESSURE TURBINE						LIFE LIMIT	
72.070	3072316 1-18040-598 REF: EMM 72-50-06	MOS HRSMSC ENC (AFL)	7000	3972 2456		03-APR-1989 4215 2745		
725170	NO. 1 ENGINE - SEAL PLATE, STAGE 1 LOW PRESSURE TURBINE							
72.210	3073552 SN-UNKNOWN REF: NO REF	MOS HRSMSC ENC (AFL)	O/C			11-FEB-1982 0 0		
725190	NO. 1 ENGINE - SEAL, LOW PRESSURE TURBINE ROTATING AIR							
72.230	3073355 SN-UNKNOWN REF: NO REF	MOS HRSMSC ENC (AFL)	O/C	0 0 0		0 0 0		
725120	NO. 1 ENGINE - SEAL, ROTATING							
72.160	3072729-1 0-23151-343 REF: NO REF	MOS HRSMSC ENC (AFL)	O/C	0 0 0		12-JUL-1991 4879 3494		
725150	NO. 1 ENGINE - SHAFT, FAN DRIVE							
72.190	3071955-3 1P-39726 REF: NO REF	MOS HRSMSC ENC (AFL)	O/C	3972 2456		03-APR-1989 4215 2745		
725130	NO. 1 ENGINE - SHAFT, HIGH PRESSURE SHOULDERED						LIFE LIMIT	
72.170	3072545-1 1P-39446 REF: NO REF	MOS HRSMSC ENC (AFL)	12000	3972 3456		03-APR-1989 4215 2745	11289	
725191	NO. 1 ENGINE - SUPPORT, LOW PRESSURE TURBINE ROTATING AIR SEAL							
72.240	3073764 SN-UNKNOWN REF: NO REF	MOS HRSMSC ENC (AFL)	O/C					
725091	NO. 1 ENGINE - TIE ROD, LOW PRESSURE							
72.140	3073049-1 1P-15433 REF: EMM 72-30-10	MOS HRSMSC ENC (AFL)	O/C	3972 2456		03-APR-1989 4215 2745		
CHAPTER 73 ENGINE FUEL AND CONTROL								
+ 731120	NO. 1 ENGINE - REMOVE AND REPLACE FILTER ELEMENT							
73.020	PKG 6, 6 REF: EMM 73-21-02	MOS HRSMSC ENC (AFL)	300			16-FEB-2001 7551 5515		

Engine Model - TFE731-3
Report Date 11-APR-2002
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
732110	NO. 1 ENGINE - CONTROL UNIT, FUEL							
73.060	3070800-8	MOS					18-MAY-1989	
	SN-UNKNOWN	HRSMSC	O/C	3972		4215		
	REF: EMM 73-20-01	ENC						
		(AFL)		2456		2745		
732120	NO. 1 ENGINE - CHANGE PRESSURE LIMITER VALVE							
73.070	3070685-4	MOS					03-APR-1989	
ASSOCIATED	SN-UNKNOWN	HRSMSC	O/C	3972		4215		
	REF: NO REF	ENC						
		(AFL)		2456		2745		
731150	NO. 1 ENGINE - COOLER, FUEL/OIL							
73.050	158610-5	MOS					03-APR-1989	
	SN-UNKNOWN	HRSMSC	O/C	3972		4215		
	REF: EMM 79-20-07	ENC						
		(AFL)		2456		2745		
731140	NO. 1 ENGINE - HEATER, FUEL							
73.040	158670-3	MOS					03-APR-1989	
	SN-UNKNOWN	HRSMSC	O/C	3972		4215		
	REF: EMM 73-10-04	ENC						
		(AFL)		2456		2745		
731110	NO. 1 ENGINE - PUMP, ENGINE FUEL							
73.010	3070850-8	MOS					03-APR-1989	
	SN-UNKNOWN	HRSMSC	O/C	3972		4215		
	REF: EMM 73-20-01	ENC						
		(AFL)		2456		2745		
+ 731120	NO. 1 ENGINE - REMOVE AND REPLACE FILTER ELEMENT							
73.020	PKG 6, 6	MOS					16-FEB-2001	
ASSOCIATED		HRSMSC	300			7551		
	REF: EMM 73-21-02	ENC						
		(AFL)				5515		
732160	NO. 1 ENGINE - TRANSMITTER, FUEL FLOW							
73.110	6883709-1	MOS		0			06-MAY-1992	
	564	HRSMSC	O/C	0		5105		
	REF: NO REF	ENC						
		(AFL)		0		3725		
731130	NO. 1 ENGINE - VALVE, FLOW DIVIDER/DRAIN							
73.030	394366-4	MOS					03-APR-1989	
	SN-UNKNOWN	HRSMSC	O/C	3972		4215		
	REF: NO REF	ENC						
		(AFL)		2456		2745		
732110	NO. 1 ENGINE - CHANGE FUEL CONTROL UNIT							
73.060	3070800-8	MOS					18-MAY-1989	
ASSOCIATED	SN-UNKNOWN	HRSMSC	O/C	3972		4215		
	REF: EMM 73-20-01	ENC						
		(AFL)		2456		2745		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Engine Model - TFE731-3
Report Date 11-APR-2002
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
732120	NO. 1 ENGINE - CHANGE PRESSURE LIMITER VALVE							
73.070	3070685-4	MOS					03-APR-1989	
ASSOCIATED	SN-UNKNOWN	HRS/MS	O/C	3972			4215	
	REF: NO REF	ENC						
	(AFL)			2456			2745	
732120	NO. 1 ENGINE - VALVE, PRESSURE LIMITER							
73.070	3070685-4	MOS					03-APR-1989	
	SN-UNKNOWN	HRS/MS	O/C	3972			4215	
	REF: NO REF	ENC						
	(AFL)			2456			2745	
732140	NO. 1 ENGINE - VALVE, SOLENOID CONTROL							
73.090	109696-3-1	MOS					03-APR-1989	
	SN-UNKNOWN	HRS/MS	O/C	3972			4215	
	REF: EMM 76-10-01	ENC						
	(AFL)			2456			2745	
732130	NO. 1 ENGINE - VALVE, SURGE BLEED							
73.080	978812-4-1	MOS					03-APR-1989	
	SN-UNKNOWN	HRS/MS	O/C	3972			4215	
	REF: EMM 76-10-01	ENC						
	(AFL)			2456			2745	
CHAPTER 74 IGNITION								
+ 742120	NO. 1 ENGINE - INSPECT 6 O'CLOCK IGNITER PLUG							
74.040		MOS					26-JUL-2000	
		HRS/MS	800				7325	8125
	REF: EMM 74-00-01	ENC						
	(AFL)						5360	
+ 742140	NO. 1 ENGINE - INSPECT 7 O'CLOCK IGNITER PLUG							
74.060		MOS					26-JUL-2000	
		HRS/MS	800				7325	8125
	REF: EMM 74-00-01	ENC						
	(AFL)						5360	
+ 741120	NO. 1 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM							
74.020		MOS					26-JUL-2000	
		HRS/MS	800				7325	8125
	REF: EMM 74-00-01	ENC						1
	(AFL)						5360	
742110	NO. 1 ENGINE - IGNITER PLUG, 6 O'CLOCK							
74.030	3071589-2	MOS					03-APR-1989	
	SN-UNKNOWN	HRS/MS	O/C	3972			4215	
	REF: EMM 72-00-00	ENC						
	(AFL)			2456			2745	
+ 742120	NO. 1 ENGINE - INSPECT 6 O'CLOCK IGNITER PLUG							
74.040		MOS					26-JUL-2000	
ASSOCIATED		HRS/MS	800				7325	8125
	REF: EMM 74-00-01	ENC						
	(AFL)						5360	

Engine Model - TFE731-3
Report Date 11-APR-2002
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT----- TSN TSO TSR TSI ADJ	INSTALLATION	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
742130	NO. 1 ENGINE - IGNITER PLUG, 7 O'CLOCK								
74.050	3071589-2	MOS					03-APR-1989		
	SN-UNKNOWN	HRS/MS	O/C	3972			4215		
	REF: EMM 72-00-00	ENC							
	(AFL)			2456			2745		
+ 742140	NO. 1 ENGINE - INSPECT 7 O'CLOCK IGNITER PLUG								
74.060		MOS					26-JUL-2000		
ASSOCIATED		HRS/MS	800				7325	8125	
	REF: EMM 74-00-01	ENC							
	(AFL)						5360		
741110	NO. 1 ENGINE - UNIT, IGNITION								
74.010	3070378-2	MOS					03-APR-1989		
	SN-UNKNOWN	HRS/MS	O/C	3972			4215		
	REF: EMM 72-00-00	ENC							
	(AFL)			2456			2745		
+ 741120	NO. 1 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM								
74.020		MOS					26-JUL-2000		
ASSOCIATED		HRS/MS	800				7325	8125	1
	REF: EMM 74-00-01	ENC							
	(AFL)						5360		
CHAPTER 75	AIR								
751010	NO. 1 ENGINE - VALVE, ANTI-ICE SHUTOFF								
75.010	978944-1-1	MOS					03-APR-1989		
	SN-UNKNOWN	HRS/MS	O/C	3972			4215		
	REF: EMM 75-10-01	ENC							
	(AFL)			2456			2745		
CHAPTER 77	ENGINE INDICATING								
772110	NO. 1 ENGINE - HARNESS, ITT THERMOCOUPLE								
77.030	3073595-1	MOS					12-JUL-1991		
	1-20219-407	HRS/MS	O/C	0			4879		
	REF: EMM 77-20-01	ENC							
	(AFL)						3494		
771120	NO. 1 ENGINE - TRANSDUCER, HIGH PRESSURE (N2)								
77.020	3070722-2	MOS					03-APR-1989		
	SN-UNKNOWN	HRS/MS	O/C	3972			4215		
	REF: EMM 77-10-05	ENC							
	(AFL)			2456			2745		
771110	NO. 1 ENGINE - TRANSDUCER, LOW PRESSURE (N1)								
77.010	3071928-5	MOS					03-APR-1989		
	SN-UNKNOWN	HRS/MS	O/C	3972			4215		
	REF: EMM 77-10-03	ENC							
	(AFL)			2456			2745		
CHAPTER 79	OIL								

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Engine Model - TFE731-3

 Report Date **11-APR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
+ 790110 79.010	NO. 1 ENGINE - ANALYZE ENGINE OIL PKG 4, 4,6, 6	MOS HRS/MSC ENC (AFL)	150			26-JUN-2001 7687		1
	REF: EMM 72-00-00					5594		
790120 79.020	NO. 1 ENGINE - CHANGE OIL	MOS HRS/MSC ENC (AFL)	1400			13-NOV-1999 6961	8361	
	REF: See Workcard					5135		
+ 790130 79.030	NO. 1 ENGINE - INSPECT CHIP DETECTOR PKG 4, 4,6, 6	MOS HRS/MSC ENC (AFL)	150			26-JUN-2001 7687		
	REF: EMM 72-00-00					5594		
792150 79.080	NO. 1 ENGINE - COOLER, OIL LOWER LEFT 159900-1 SN-UNKNOWN REF: EMM 79-20-09	MOS HRS/MSC ENC (AFL)	O/C	3972		03-APR-1989 4215		
				2456		2745		
792160 79.090	NO. 1 ENGINE - COOLER, OIL LOWER RIGHT 159910-1 SN-UNKNOWN REF: EMM 79-20-09	MOS HRS/MSC ENC (AFL)	O/C	3972		03-APR-1989 4215		
				2456		2745		
792140 79.070	NO. 1 ENGINE - COOLER, OIL UPPER 158600-4 SN-UNKNOWN REF: EMM 79-20-09	MOS HRS/MSC ENC (AFL)	O/C	3972		03-APR-1989 4215		
				2456		2745		
792110 79.040	NO. 1 ENGINE - PUMP, OIL 3071949-7 SN-UNKNOWN REF: EMM 79-20-03	MOS HRS/MSC ENC (AFL)	O/C	3972		03-APR-1989 4215		
				2456		2745		
790120 79.020 ASSOCIATED	NO. 1 ENGINE - CHANGE OIL	MOS HRS/MSC ENC (AFL)	1400			13-NOV-1999 6961	8361	
	REF: See Workcard					5135		
793120 79.120	NO. 1 ENGINE - SWITCH, OIL PRESSURE 3833518 SN-UNKNOWN REF: NO REF	MOS HRS/MSC ENC (AFL)	O/C	3972		03-APR-1989 4215		
				2456		2745		

Engine Model - TFE731-3
Report Date 11-APR-2002
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
793110	NO. 1 ENGINE - TRANSMITTER, OIL PRESSURE											
79.110	101-412-80-13	MOS									03-APR-1989	
	SN-UNKNOWN	HRS/MSC	O/C	3972							4215	
	REF: NO REF	ENC										
		(AFL)		2456							2745	
792120	NO. 1 ENGINE - VALVE, OIL FILTER BYPASS											
79.050	3070000NP69	MOS									03-APR-1989	
	SN-UNKNOWN	HRS/MSC	O/C	3972							4215	
	REF: EMM 79-30-01	ENC										
		(AFL)		2456							2745	
792130	NO. 1 ENGINE - VALVE, PRESSURE BREATHER											
79.060	3071564-8	MOS									18-MAY-1989	
	SN-UNKNOWN	HRS/MSC	O/C								4215	
	REF: EMM 79-20-02	ENC										
		(AFL)									2745	

Engine Model - TFE731-3

Report Date **11-APR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
ENGINE NO. 2								
CHAPTER 71 POWER PLANT								
710140U	NO. 2 ENGINE - -- RUN ADJ/TEST #2 ENG	MOS					31-MAY-1993	
	REF:	HRS/MS	C/C				5278	
		ENC						
		(AFL)					3928	
+ 714010	NO. 2 ENGINE - CHECK ELECTRICAL WIRES AND CONNECTIONS	MOS					26-JUL-2000	
71.040		HRS/MS	800				7325	8125
	REF: EMM 72-00-00	ENC						
		(AFL)					5360	
+ 715010	NO. 2 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS	MOS					26-JUL-2000	
71.050		HRS/MS	800				7325	8125
	REF: EMM 72-00-00	ENC						
		(AFL)					5360	
+ 710130	NO. 2 ENGINE - INSPECT FAN ROTOR ASSEMBLY BLADES	MOS					16-FEB-2001	
71.020	PKG 7, 7	HRS/MS	300				7551	.5
	REF: EMM 72-00-00	ENC						
		(AFL)					5515	
+ 710120	NO. 2 ENGINE - MAJOR PERIODIC INSPECTION	MOS					17-OCT-1998	
71.010		HRS/MS	1400				6520	7920
	REF: EMM 72-00-00	ENC						
		(AFL)					4889	
710110U	NO. 2 ENGINE - ENGINE, #2	MOS					31-MAY-1993	
	3072500-2	HRS/MS	O/C	5227			5278	
	P77488	ENC						
	REF:	(AFL)		3867			3928	
CHAPTER 72 ENGINE								
+ 724120	NO. 2 ENGINE - INSPECT COMBUSTION PLENUM CASE	MOS					17-SEP-1998	
72.030		HRS/MS	1400				6520	7920
	REF: EMM 72-40-04	ENC						
		(AFL)					4889	
+ 723110	NO. 2 ENGINE - INSPECT COMPRESSOR CORE	MOS					17-OCT-1998	
72.010		HRS/MS	4200				6520	10720
	REF: NO REF	ENC						
		(AFL)					4889	

Engine Model - TFE731-3
Report Date 11-APR-2002
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
+ 727110 72.300	NO. 2 ENGINE - PERIODIC INSPECT FAN SUPPORT ASSEMBLY	MOS				17-MAY-1989		
	REF: EMM 72-70-06	HRS/MS ENC (AFL)	4200			4265	8465	
724110 72.020	NO. 2 ENGINE - CASE, COMBUSTION PLENUM	MOS				31-MAY-1989		
	3072443-4	HRS/MS ENC (AFL)	O/C	4215		4265		
	REF: NO REF			2745		2793		
+ 724120 72.030 ASSOCIATED	NO. 2 ENGINE - INSPECT COMBUSTION PLENUM CASE	MOS				17-SEP-1998		
	REF: EMM 72-40-04	HRS/MS ENC (AFL)	1400			6520	7920	
725050 72.090	NO. 2 ENGINE - DISC, FAN ROTOR	MOS				20-MAY-1993	LIFE LIMIT	
	3073539-2	HRS/MS ENC (AFL)		4087		5278		
	0-18040-4768							
	REF: NO REF		4100	2660		3928	5368	
725060 72.100	NO. 2 ENGINE - DISC, STAGE 1 LOW PRESSURE COMPRESSOR	MOS				31-MAY-1989	LIFE LIMIT	
	3072395	HRS/MS ENC (AFL)		4215		4265		
	1-12112-1647		10000	2745		2793	10048	
	REF: NO REF						LIFE LIMIT	
725010 72.040	NO. 2 ENGINE - DISC, STAGE 1 LOW PRESSURE TURBINE	MOS				20-MAY-1993		
	3072351-5	HRS/MS ENC (AFL)		0		5278		
	1-03229-1486		3000	0		3928	6928	
	REF: NO REF						LIFE LIMIT	
725070 72.110	NO. 2 ENGINE - DISC, STAGE 2 LOW PRESSURE COMPRESSOR	MOS				31-MAY-1989		
	3072396	HRS/MS ENC (AFL)		4215		4265		
	1-12112-581		10000	2745		2793	10048	
	REF: NO REF						LIFE LIMIT	
725020 72.050	NO. 2 ENGINE - DISC, STAGE 2 LOW PRESSURE TURBINE	MOS				20-MAY-1993		
	3072542-5	HRS/MS ENC (AFL)		0		5278		
	1-03229-1277		3000	0		3928	6928	
	REF: NO REF						LIFE LIMIT	
725080 72.120	NO. 2 ENGINE - DISC, STAGE 3 LOW PRESSURE COMPRESSOR	MOS				31-MAY-1989		
	3072397	HRS/MS ENC (AFL)		4215		4265		
	0-12112-1718		10000	2745		2793	10048	
	REF: NO REF							

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Engine Model - TFE731-3
Report Date 11-APR-2002
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
725030	NO. 2 ENGINE - DISC, STAGE 3 LOW PRESSURE TURBINE						LIFE LIMIT	
72.060	3072544-2	MOS				31-MAY-1989		
	6-18040-4905	HRS/MS		0		4265		
	REF: NO REF	ENC						
		(AFL)	3000	0		2793	5793	
725090	NO. 2 ENGINE - DISC, STAGE 4 LOW PRESSURE COMPRESSOR						LIFE LIMIT	
72.130	3072398	MOS				31-MAY-1989		
	0-12112-3229	HRS/MS		4215		4265		
	REF: NO REF	ENC						
		(AFL)	10000	2745		2793	10048	
725160	NO. 2 ENGINE - DUCT, TURBINE INTERSTAGE TRANSITION							
72.200	3072318	MOS				31-MAY-1989		
	SN-UNKNOWN	HRS/MS	O/C			4265		
	REF: EMM 72-50-05	ENC						
		(AFL)				2793		
726110	NO. 2 ENGINE - GEARBOX, ACCESSORY							
72.250	3070003-5	MOS				31-MAY-1989		
	P-948	HRS/MS	O/C	4215		4265		
	REF: EMM 72-60-01	ENC						
		(AFL)		2745		2793		
+ 726120	NO. 2 ENGINE - INSPECT							
72.260		MOS				17-MAY-1989		
		HRS/MS	4200			4265	8465	
	REF: EMM 72-60-02	ENC						
		(AFL)				2793		
726130	NO. 2 ENGINE - GEARBOX, TRANSFER							
72.270	3070093-3	MOS				31-MAY-1989		
	P-3691	HRS/MS	O/C	4215		4265		
	REF: EMM 72-60-01	ENC						
		(AFL)		2745		2793		
725110	NO. 2 ENGINE - IMPELLER, HIGH PRESSURE						LIFE LIMIT	
72.150	3073394-1	MOS				31-MAY-1989		
	0-23369-4190	HRS/MS		0		4265		
	REF: NO REF	ENC						
		(AFL)	10000	0		2793	12793	
725180	NO. 2 ENGINE - NOZZLE, STAGE 1 LOW PRESSURE TURBINE							
72.220	3072319	MOS				31-MAY-1989		
	SN-UNKNOWN	HRS/MS	O/C			4265		
	REF: NO REF	ENC						
		(AFL)				2793		
725140	NO. 2 ENGINE - PLATE, HIGH PRESSURE ROTOR SEAL						LIFE LIMIT	
72.180	3072411-1	MOS				31-MAY-1989		
	1-18040-5077	HRS/MS		4215		4265		
	REF: NO REF	ENC						
		(AFL)	10000	2745		2793	10048	

Engine Model - TFE731-3

 Report Date **11-APR-2002**

 Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
 A/C Serial #: 368 A/C Reg. #: N368MD

ITEMNO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
725040	NO. 2 ENGINE - ROTOR, HIGH PRESSURE TURBINE						LIFE LIMIT	
72.070	3072316	MOS				31-MAY-1989		
	1-18040-451	HRS/MSC		4215		4265		
	REF: EMM 72-50-06	ENC						
	(AFL)		7000	2745		2793	7048	
725170	NO. 2 ENGINE - SEAL PLATE, STAGE 1 LOW PRESSURE TURBINE							
72.210	3073552	MOS				11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C			0		
	REF: NO REF	ENC						
	(AFL)					0		
725190	NO. 2 ENGINE - SEAL, LOW PRESSURE TURBINE ROTATING AIR							
72.230	3073355	MOS		0				
	SN-UNKNOWN	HRS/MSC	O/C	0		0		
	REF: NO REF	ENC						
	(AFL)			0		0		
725120	NO. 2 ENGINE - SEAL, ROTATING							
72.160	3072729-1	MOS				31-MAY-1989		
	7-23151-1814	HRS/MSC	O/C	0		4265		
	REF: NO REF	ENC						
	(AFL)			0		2793		
725150	NO. 2 ENGINE - SHAFT, FAN DRIVE							
72.190	3071955-3	MOS				31-MAY-1989		
	IP-41464	HRS/MSC	O/C	4215		4265		
	REF: NO REF	ENC						
	(AFL)			2745		2793		
725130	NO. 2 ENGINE - SHAFT, HIGH PRESSURE SHOULDERED						LIFE LIMIT	
72.170	3072545-1	MOS				31-MAY-1989		
	1P-39469	HRS/MSC		4215		4265		
	REF: NO REF	ENC						
	(AFL)		12000	2745		2793	12048	
725191	NO. 2 ENGINE - SUPPORT, LOW PRESSURE TURBINE ROTATING AIR SEAL							
72.240	3073764	MOS						
	SN-UNKNOWN	HRS/MSC	O/C					
	REF: NO REF	ENC						
	(AFL)							
725091	NO. 2 ENGINE - TIE ROD, LOW PRESSURE							
72.140	3073049-1	MOS				31-MAY-1989		
	1P-15412	HRS/MSC	O/C	4215		4265		
	REF: EMM 72-30-10	ENC						
	(AFL)			2745		2793		
CHAPTER 73	ENGINE FUEL AND CONTROL							
+ 731120	NO. 2 ENGINE - REMOVE AND REPLACE FILTER ELEMENT							
73.020	PKG 7, 7	MOS				16-FEB-2001		
		HRS/MSC	300			7551		
	REF: EMM 73-21-02	ENC						
	(AFL)					5515		

 ? - Insufficient Information
 + Task exists in FAA Manual
 4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Engine Model - TFE731-3
Report Date 11-APR-2002
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
732110	NO. 2 ENGINE - CONTROL UNIT, FUEL										
73.060	3070800-2	MOS								31-MAY-1989	
	A3593PT	HRS/MS	O/C							4265	
	REF: EMM 73-20-01	ENC									
		(AFL)								2793	
732120	NO. 2 ENGINE - CHANGE PRESSURE LIMITER VALVE										
73.070	3070685-4	MOS								31-MAY-1989	
ASSOCIATED	A6760	HRS/MS	O/C	4215						4265	
	REF: NO REF	ENC									
		(AFL)		2745						2793	
731150	NO. 2 ENGINE - COOLER, FUEL/OIL										
73.050	158610-7	MOS								31-MAY-1989	
	21-3736	HRS/MS	O/C	4215						4265	
	REF: EMM 79-20-07	ENC									
		(AFL)		2745						2793	
731140	NO. 2 ENGINE - HEATER, FUEL										
73.040	158670-3	MOS								31-MAY-1989	
	71-2903	HRS/MS	O/C	4215						4265	
	REF: EMM 73-10-04	ENC									
		(AFL)		2745						2793	
731110	NO. 2 ENGINE - PUMP, ENGINE FUEL										
73.010	3070850-8	MOS								31-MAY-1989	
	MX364112	HRS/MS	O/C	4215						4265	
	REF: EMM 73-20-01	ENC									
		(AFL)		2745						2793	
+ 731120	NO. 2 ENGINE - REMOVE AND REPLACE FILTER ELEMENT										
73.020	PKG 7, 7	MOS								16-FEB-2001	
ASSOCIATED		HRS/MS	300							7551	
	REF: EMM 73-21-02	ENC									
		(AFL)								5515	
732160	NO. 2 ENGINE - TRANSMITTER, FUEL FLOW										
73.110	883709-1	MOS								31-MAY-1989	
	SN-UNKNOWN	HRS/MS	O/C	4215						4265	
	REF: NO REF	ENC									
		(AFL)		2745						2793	
731130	NO. 2 ENGINE - VALVE, FLOW DIVIDER/DRAIN										
73.030	394366-4	MOS								31-MAY-1989	
	SN-UNKNOWN	HRS/MS	O/C	4215						4265	
	REF: NO REF	ENC									
		(AFL)		2745						2793	
732110	NO. 2 ENGINE - CHANGE FUEL CONTROL UNIT										
73.060	3070800-2	MOS								31-MAY-1989	
ASSOCIATED	A3593PT	HRS/MS	O/C							4265	
	REF: EMM 73-20-01	ENC									
		(AFL)								2793	

Engine Model - TFE731-3
Report Date 11-APR-2002
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
732120	NO. 2 ENGINE - CHANGE PRESSURE LIMITER VALVE							
73.070	3070685-4	MOS					31-MAY-1989	
ASSOCIATED	A6760	HRS/MS	O/C	4215		4265		
	REF: NO REF	ENC						
		(AFL)		2745		2793		
732120	NO. 2 ENGINE - VALVE, PRESSURE LIMITER							
73.070	3070685-4	MOS					31-MAY-1989	
	A6760	HRS/MS	O/C	4215		4265		
	REF: NO REF	ENC						
		(AFL)		2745		2793		
732140	NO. 2 ENGINE - VALVE, SOLENOID CONTROL							
73.090	109696-3-1	MOS					31-MAY-1989	
	P-3683	HRS/MS	O/C	4215		4265		
	REF: EMM 76-10-01	ENC						
		(AFL)		2745		2793		
732130	NO. 2 ENGINE - VALVE, SURGE BLEED							
73.080	978812-4-1	MOS					31-MAY-1989	
	P-3683	HRS/MS	O/C	4215		4265		
	REF: EMM 76-10-01	ENC						
		(AFL)		2745		2793		
CHAPTER 74	IGNITION							
+ 742120	NO. 2 ENGINE - INSPECT 6 O'CLOCK IGNITER PLUG							
74.040		MOS					26-JUL-2000	
		HRS/MS	800			7325	8125	
	REF: EMM 74-00-01	ENC						
		(AFL)				5360		
+ 742140	NO. 2 ENGINE - INSPECT 7 O'CLOCK IGNITER PLUG							
74.060		MOS					26-JUL-2000	
		HRS/MS	800			7325	8125	
	REF: EMM 74-00-01	ENC						
		(AFL)				5360		
+ 741120	NO. 2 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM							
74.020		MOS					26-JUL-2000	
		HRS/MS	800			7325	8125	1
	REF: EMM 74-00-01	ENC						
		(AFL)				5360		
742110	NO. 2 ENGINE - IGNITER PLUG, 6 O'CLOCK							
74.030	3071589-2	MOS					17-OCT-1998	
	SN-UNKNOWN	HRS/MS	O/C			6520		
	REF: EMM 72-00-00	ENC						
		(AFL)				4889		
+ 742120	NO. 2 ENGINE - INSPECT 6 O'CLOCK IGNITER PLUG							
74.040		MOS					26-JUL-2000	
ASSOCIATED		HRS/MS	800			7325	8125	
	REF: EMM 74-00-01	ENC						
		(AFL)				5360		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Engine Model - TFE731-3
Report Date 11-APR-2002
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
742130	NO. 2 ENGINE - IGNITER PLUG, 7 O'CLOCK										
74.050	3071589-2	MOS								09-NOV-1996	
	SN-UNKNOWN	HRSMSC	O/C							5951	
	REF: EMM 72-00-00	ENC									
		(AFL)								4589	
+ 742140	NO. 2 ENGINE - INSPECT 7 O'CLOCK IGNITER PLUG										
74.060		MOS								26-JUL-2000	
ASSOCIATED		HRSMSC	800							7325	8125
	REF: EMM 74-00-01	ENC									
		(AFL)								5360	
741110	NO. 2 ENGINE - UNIT, IGNITION										
74.010	3070378-2	MOS								31-MAY-1989	
	SN-UNKNOWN	HRSMSC	O/C	1142						4265	
	REF: EMM 72-00-00	ENC									
		(AFL)								2793	
+ 741120	NO. 2 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM										
74.020		MOS								26-JUL-2000	
ASSOCIATED		HRSMSC	800							7325	8125
	REF: EMM 74-00-01	ENC									1
		(AFL)								5360	
CHAPTER 75 AIR											
751010	NO. 2 ENGINE - VALVE, ANTI-ICE SHUTOFF										
75.010	978944-1-1	MOS								31-MAY-1989	
	SN-UNKNOWN	HRSMSC	O/C	4215						4265	
	REF: EMM 75-10-01	ENC									
		(AFL)								2793	
CHAPTER 77 ENGINE INDICATING											
772110	NO. 2 ENGINE - HARNESS, ITT THERMOCOUPLE										
77.030	3071849-3	MOS								31-MAY-1989	
	9-20219-358	HRSMSC	O/C							4265	
	REF: EMM 77-20-01	ENC									
		(AFL)								2793	
771120	NO. 2 ENGINE - TRANSDUCER, HIGH PRESSURE (N2)										
77.020	3070722-2	MOS								31-MAY-1989	
	SN-UNKNOWN	HRSMSC	O/C	4215						4265	
	REF: EMM 77-10-05	ENC									
		(AFL)								2793	
771110	NO. 2 ENGINE - TRANSDUCER, LOW PRESSURE (N1)										
77.010	3071928-5	MOS								31-MAY-1989	
	SN-UNKNOWN	HRSMSC	O/C	4215						4265	
	REF: EMM 77-10-03	ENC									
		(AFL)								2793	
CHAPTER 79 OIL											

Engine Model - TFE731-3
Report Date 11-APR-2002
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
+ 790110 79.010	NO. 2 ENGINE - ANALYZE ENGINE OIL PKG 5, 5, 7, 7	MOS HRS/MS ENC (AFL)	150			26-JUN-2001 7687		1
	REF: EMM 72-00-00					5594		
790120 79.020	NO. 2 ENGINE - CHANGE OIL	MOS HRS/MS ENC (AFL)	1400			17-OCT-1998 6520	7920	
	REF: See Workcard					4889		
+ 790130 79.030	NO. 2 ENGINE - INSPECT CHIP DETECTOR PKG 5, 5, 7, 7	MOS HRS/MS ENC (AFL)	150			26-JUN-2001 7687		
	REF: EMM 72-00-00					5594		
792150 79.080	NO. 2 ENGINE - COOLER, OIL LOWER LEFT 159900-1 SN-UNKNOWN REF: EMM 79-20-09	MOS HRS/MS ENC (AFL)	O/C			31-MAY-1989 4265		
						2793		
792160 79.090	NO. 2 ENGINE - COOLER, OIL LOWER RIGHT 159910-1 SN-UNKNOWN REF: EMM 79-20-09	MOS HRS/MS ENC (AFL)	O/C	4215		31-MAY-1989 4265		
						2793		
792140 79.070	NO. 2 ENGINE - COOLER, OIL UPPER 158600-4 SN-UNKNOWN REF: EMM 79-20-09	MOS HRS/MS ENC (AFL)	O/C	4215		31-MAY-1989 4265		
						2793		
792110 79.040	NO. 2 ENGINE - PUMP, OIL 3071949-7 0683 REF: EMM 79-20-03	MOS HRS/MS ENC (AFL)	O/C			31-MAY-1989 4265		
						2793		
790120 79.020 ASSOCIATED	NO. 2 ENGINE - CHANGE OIL	MOS HRS/MS ENC (AFL)	1400			17-OCT-1998 6520	7920	
	REF: See Workcard					4889		
793120 79.120	NO. 2 ENGINE - SWITCH, OIL PRESSURE 3-833518 1041 REF: NO REF	MOS HRS/MS ENC (AFL)	O/C	482		31-MAY-1989 4265		
						2793		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Engine Model - TFE731-3
Report Date 11-APR-2002
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
793110	NO. 2 ENGINE - TRANSMITTER, OIL PRESSURE											
79.110	101-412-80-13	MOS									31-MAY-1989	
	SN-UNKNOWN	HRS/MS	O/C	4215							4265	
	REF: NO REF	ENC										
		(AFL)									2793	
792120	NO. 2 ENGINE - VALVE, OIL FILTER BYPASS											
79.050	3070000NP69	MOS									31-MAY-1989	
	SN-UNKNOWN	HRS/MS	O/C	4215							4265	
	REF: EMM 79-30-01	ENC										
		(AFL)									2793	
792130	NO. 2 ENGINE - VALVE, PRESSURE BREATHER											
79.060	3075323-1	MOS									04-FEB-1994	
	6376	HRS/MS	O/C		0						5390	
	REF: EMM 79-20-02	ENC										
		(AFL)									4040	

Aircraft Model - 1124 WESTWIND
 Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
 A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
AIRCRAFT								
AD 1974-08-09 R2	AIRWORTHINESS DIRECTIVE TO PREVENT POSSIBLE FIRES THAT COULD RESULT FROM SMOKING MATERIALS BEING DROPPED INTO LAVATORY PAPER OR LINEN WASTE RECEPTACLES							F4
		MOS				17-JAN-2001		
		HRS/MS	1000			7494	8494	
		AFL				5466		
	REF:							
	Method of Compliance: OPEN							
AD 1989-12-08	AIRWORTHINESS DIRECTIVE TO DETECT CRACKS IN THE HINGE LUGS OF THE HORIZONTAL STABILIZER AFT SPAR SPLICE FITTING (HINGE ASSEMBLY)							
		MOS				17-JAN-2001		
		HRS/MS	300			7494	7794	
		AFL				5466		
	REF: See Workcard							
	Method of Compliance: OPEN							
AD 1996-24-11 LEFT AILERON	AIRWORTHINESS DIRECTIVE TO PREVENT EXCESSIVE WEAR OF THE AILERON PUSH-PULL TUBE, WHICH COULD RESULT IN UNEVEN MOVEMENT OF THE CONTROL WHEEL, PERFORATION OF THE AILERON PUSH-PULL TUBE, AND CONSEQUENT REDUCED ROLL CONTROL OF THE AIRPLANE							W1
		MOS				26-JUL-2000		
		HRS/MS	600			7325	7925	
		AFL				5360		
	REF: AD							
	Method of Compliance: OPEN							
SB 1124-27-129 LEFT AILERON	FLIGHT CONTROLS SERVICE BULLETIN							W1
		MOS				26-JUL-2000		
ASSOCIATED		HRS/MS	600			7325	7925	
		AFL				5360		
	REF: BULLETINS							
	Method of Compliance: OPEN							
AD 1996-24-11 RIGHT AILERON	AIRWORTHINESS DIRECTIVE TO PREVENT EXCESSIVE WEAR OF THE AILERON PUSH-PULL TUBE, WHICH COULD RESULT IN UNEVEN MOVEMENT OF THE CONTROL WHEEL, PERFORATION OF THE AILERON PUSH-PULL TUBE, AND CONSEQUENT REDUCED ROLL CONTROL OF THE AIRPLANE							W2
		MOS				26-JUL-2000		
		HRS/MS	600			7325	7925	
		AFL				5360		
	REF: AD							
	Method of Compliance: OPEN							
SB 1124-27-129 RIGHT AILERON	FLIGHT CONTROLS SERVICE BULLETIN							W2
		MOS				26-JUL-2000		
ASSOCIATED		HRS/MS	600			7325	7925	
		AFL				5360		
	REF: BULLETINS							
	Method of Compliance: OPEN							
AD 1998-06-10	AIRWORTHINESS DIRECTIVE TO PREVENT FAILURE OF THE HYDRAULIC FUSE TO OPERATE PROPERLY IN THE EVENT OF AN EXTERNAL LEAK DOWNSTREAM OF THE FUSE, WHICH COULD RESULT IN LOSS OF HYDRAULIC SYSTEMS							
		MOS	36			06-NOV-2001	06-NOV-2004	
		HRS/MS	1200			7774	8974	
		AFL				5641		
	REF: AD							
	Method of Compliance: OPEN							

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
AD 2002-01-26	AIRWORTHINESS DIRECTIVE TO PREVENT FAILURE OF ATTACHMENT BOLTS DUE TO FATIGUE, WHICH COULD RESULT IN SEPARATION OF THE ENGINE INLET COWL AND AFT NACELLE, AND CONSEQUENT DAMAGE TO THE HORIZONTAL OR VERTICAL STABILIZER									MANDATORY	
		MOS									
		HRS/MS	DUE							50	
	REF:	AFL									
	Method of Compliance: OPEN										
SB ASB1124-54A-138	SERVICE BULLETIN									MANDATORY	
		MOS									
ASSOCIATED		HRS/MS	A/R								
	REF:	AFL									
	Method of Compliance: OPEN										
SB 1124-27-129 LEFT AILERON	SERVICE BULLETIN FLIGHT CONTROLS										W1
		MOS							26-JUL-2000		
		HRS/MS	600						7325	7925	
		AFL							5360		
	REF: BULLETINS										
	Method of Compliance: OPEN										
SB 1124-27-129 RIGHT AILERON	SERVICE BULLETIN FLIGHT CONTROLS										W2
		MOS							26-JUL-2000		
		HRS/MS	600						7325	7925	
		AFL							5360		
	REF: BULLETINS										
	Method of Compliance: OPEN										
SB 1124-30-036 PART II	SERVICE BULLETIN ICE AND RAIN PROTECTION										F3
	PKG 1, 2, 3	MOS							26-JUN-2001		
		HRS/MS	150						7687	7837	
		AFL							5594		
	REF: See Workcard										
	Method of Compliance: OPEN										
SB 1124-32-139 UPPER	SERVICE BULLETIN LANDING GEAR										
	PKG 3	MOS							26-JUL-2000		
		HRS/MS	800						7325	8125	
		AFL							5360		
	REF:										
	Method of Compliance: OPEN										
SB 1124-55-020 R2	SERVICE BULLETIN STABILIZERS										T1
	PKG 2, 3	MOS							26-JUN-2001		
		HRS/MS	300						7687	7987	
		AFL							5594		
	REF: See Workcard										
	Method of Compliance: OPEN										
SB 900280	SERVICE BULLETIN SB WW 24-28A										L3
		MOS							22-FEB-2000		
		HRS/MS	1200						7107		
		AFL							5232		
	REF: See Workcard										
	Method of Compliance: OPEN										
SB 972850U	SERVICE BULLETIN SB 731-A72-3668 #1 ENG									RECOMMENDED	
		MOS								31-DEC-2002	
		HRS/MS	A/R								
	REF:	AFL									

 ? - Insufficient Information
 + Task exists in FAA Manual
 4/12/2002 12:26:41 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L



AIRCRAFT Status Report (AD/SI)

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
SB 972851U	SERVICE BULLETIN SB 731-A72-3668 #2 ENG	MOS								RECOMMENDED 31-DEC-2002	
	REF:	HRS/MSAFL	A/R								
SB 972B40U	SERVICE BULLETIN GSBA72-3569 R/E FAN ROTOR	MOS									
	REF:	HRS/MSAFL	A/R							5722	
SL WW-2492	SERVICE LETTER HYD HOSE INSP PKG 1, 2, 3	MOS							26-JUN-2001		
	REF:	HRS/MSAFL	200						7687 5594	7887	
	Method of Compliance: OPEN										
SL WW-2494 R3 LEFT	SERVICE LETTER LANDING GEAR	MOS							26-JUN-2001		L1
	REF: See Workcard	HRS/MSAFL	300						7687 5594	7987	
	Method of Compliance: OPEN										
SL WW-2494 R3 RIGHT	SERVICE LETTER LANDING GEAR	MOS							26-JUN-2001		L2
	REF: See Workcard	HRS/MSAFL	300						7687 5594	7987	
	Method of Compliance: OPEN										

Engine Model - TFE731-3

Report Date **11-APR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
ENGINE NO. 1								
AD 2000-15-09	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE HPC IMPELLER							
		MOS					10-OCT-2000	
		HRSMSC	4200					
	REF:	ENC						
	Method of Compliance: OPEN							
AD 2001-23-09	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE TO PREVENT FAILURE OF THE FAN ROTOR DISC DUE TO FATIGUE CRACKING IN THE DOVETAIL SLOTS						MANDATORY	
		MOS					31-DEC-2002	
		HRSMSC	DUE					
	REF:	ENC						
	Method of Compliance: OPEN							
SB TFE731-A72-3668	NO. 1 ENGINE - REMOVE FAN ROTOR DISC FROM SERVICE SERVICE BULLETIN						MANDATORY	
		MOS					31-DEC-2002	
ASSOCIATED		HRSMSC	A/R					
	REF: BULLETINS	ENC						
	Method of Compliance: OPEN							

Engine Model - TFE731-3

Report Date **11-APR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
ENGINE NO. 2								
AD 2000-15-09	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE HPC IMPELLER							
		MOS					10-OCT-2000	
		HRS/MS	4200					
	REF:	ENC						
	Method of Compliance: OPEN							
AD 2001-23-09	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE TO PREVENT FAILURE OF THE FAN ROTOR DISC DUE TO FATIGUE CRACKING IN THE DOVETAIL SLOTS						MANDATORY	
		MOS					31-DEC-2002	
		HRS/MS	DUE					
	REF:	ENC						
	Method of Compliance: OPEN							
SB TFE731-A72-3668	NO. 2 ENGINE - REMOVE FAN ROTOR DISC FROM SERVICE SERVICE BULLETIN						MANDATORY	
		MOS					31-DEC-2002	
ASSOCIATED		HRS/MS	A/R					
	REF: BULLETINS	ENC						
	Method of Compliance: OPEN							

OWNER: R&S AIRCRAFT INVESTMENTS, LLC
ADDRESS: P.O. BOX 43 HOUSTON TX 77001-0043

OPERATOR: R&S AIRCRAFT INVESTMENTS, LLC
ADDRESS: P.O. BOX 43 HOUSTON TX 77001-0043

PHONE: 713-830-9584
FAX: 713-918-5925

PHONE: 713-830-9584
FAX: 713-918-5925

PROJECTED : 2 MOS. to 11-JUN-2002

AIRCRAFT

S/N: 368 **REG NO:** N368MD **MODEL:** 1124A WESTWIND **MANUFACTURER:** GULFSTREAM AEROSPACE CORPORATION

NOTE:
INSPECTION PROGRAM: 3
CERTIFICATE DATE: 11-FEB-1982

UOM	LAST ACTUAL	LAST ACTUAL DATE	PROJECTED
HRS	7806	28-FEB-2002	7926.8
AFL	5706	28-FEB-2002	5827

ENGINE NO. 1

S/N: P-77482 **PART NO:** 3072500-2 **MODEL:** TFE731-3 **MANUFACTURER:** HONEYWELL

INSTALLED DATE: 4/3/1989
A/C HRS: 4215
ENGINE HRS: 3972
ENGINE CYCLES: 2456

UOM	LAST ACTUAL	LAST ACTUAL DATE	PROJECTED
HRS	7806	28-FEB-2002	7926.8
ENC	0		0
(AFL)	5706	28-FEB-2002	5827

ENGINE NO. 2

S/N: P77488 **PART NO:** 3072500-2 **MODEL:** TFE731-3 **MANUFACTURER:** HONEYWELL

INSTALLED DATE: 5/31/1993
A/C HRS: 5278
ENGINE HRS: 5227
ENGINE CYCLES: 3867

UOM	LAST ACTUAL	LAST ACTUAL DATE	PROJECTED
HRS	7806	28-FEB-2002	7926.8
ENC	0		0
(AFL)	5706	28-FEB-2002	5827

Aircraft Model - 1124A WESTWIND

Serial #: 368 Reg. #: N368MD

Maintenance Due List/Time Remaining - AIRCRAFT(CALENDAR)

Report Date 11-APR-2002

ITEM NO WORK CARD WORK ORDER	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL TIME-----AT-----INSTALLATION				COMPLIANCE WARR EXP	DISPOSITION NEXT DUE		TIME REMAINING OVD = Overdue	AREA PRICE LABOR
			TSN	TSO	TSR			(ENH)	AFH (xEXT)		
R	AD 2000-15-09	NO. 1 ENGINE - HPC IMPELLER AIRWORTHINESS DIRECTIVE									
		DUE NEXT	MOS	4200				10-OCT-2000		New Reqmt	
	REF:		HRS/MS								
		ENC									
R	AD 2000-15-09	NO. 2 ENGINE - HPC IMPELLER AIRWORTHINESS DIRECTIVE									
		DUE NEXT	MOS	4200				10-OCT-2000		New Reqmt	
	REF:		HRS/MS								
		ENC									
R	260169	VISUAL INSPECTION COCKPIT PORTABLE EXTINGUISHER COCKPIT FIRE EXTINGUISHER									F3
	26.060		DAYS	30			06-NOV-2001	06-DEC-2001		OVD	
		REF: NO REF	HRS/MS				7774				
		AFL					5641				
R	260180	VISUAL INSPECTION CABIN PORTABLE EXTINGUISHER CABIN FIRE EXTINGUISHER									F3
	26.060		DAYS	30			06-NOV-2001	06-DEC-2001		OVD	
		REF: NO REF	HRS/MS				7774				
		AFL					5641				
R	330228	CHARGE EMERGENCY LIGHT BATTERY									F4
	33.100		MOS	3			06-NOV-2001	06-FEB-2002		OVD	
		REF: AMM 12-10-06	HRS/MS	200			7774	7974		168	
		AFL					5641				
R	344616	INSPECT EMERGENCY GYRO POWER SUPPLY BATTERY EMERGENCY POWER SUPPLY BATTERY/STAND-BY ATTITUDE GYRO									F5
	34.370		MOS	3			06-NOV-2001	06-FEB-2002		OVD	
		REF: AMM NO REF	HRS/MS	200			7774	7974		168	
		AFL					5641				
R	320118	INSPECT/LUBRICATE NOSE GEAR ASSEMBLY UPPER/LOWER STRUT BEARINGS BODY									L3
	32.540		MOS	24			22-FEB-2000	22-FEB-2002		OVD	
		REF: AMM 32-20-01	HRS/MS	1200			7107	8307		501	
		AFL					5232				
R	230400	CLEAN/TEST COCKPIT VOICE RECORDER BEACON									T1
	23.130		MOS	6			06-NOV-2001	06-MAY-2002		0.8	
		REF: NO REF	HRS/MS				7774				
		AFL					5641				

Total Labor Hours

Total Price :

R - Task was due on previous due lists

(xEXT) - Extension incorporated in the next due calculation

Aircraft Model- 1124A WESTWIND
Serial #: 368 Reg. #: N368MD

Maintenance Due List/Time Remaining - AIRCRAFT(HOURS)

Report Date 11-APR-2002

ITEM NO WORK CARD WORK ORDER	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL TIME-----AT-----INSTALLATION				COMPLIANCE WARR EXP	DISPOSITION NEXT DUE		TIME REMAINING OVD = Overdue	AREA PRICE LABOR
			TSN	TSO	TSR			(ENH)	AFH (xEXT)		
724120 72.030	NO. 2 ENGINE - INSPECT COMBUSTION PLENUM CASE										
	REF: EMM 72-40-04	MOS HRS/MS ENC (AFL)	1400				17-SEP-1998 6520 4889		7920	114	
790120 79.020	NO. 2 ENGINE - CHANGE OIL										
	REF: See Workcard	MOS HRS/MS ENC (AFL)	1400				17-OCT-1998 6520 4889		7920	114	
AD 1996-24-11 LEFT AILERON	TO PREVENT EXCESSIVE WEAR OF THE AILERON PUSH-PULL TUBE, WHICH COULD RESULT IN UNEVEN MOVEMENT OF THE CONTROL WHEEL, PERFORATION OF THE AILERON PUSH-PULL TUBE, AND CONSEQUENT REDUCED ROLL CONTROL OF THE AIRPLANE AIRWORTHINESS DIRECTIVE										W1
	REF: AD	MOS HRS/MS AFL	600				26-JUL-2000 7325 5360		7925	119	
AD 1996-24-11 RIGHT AILERON	TO PREVENT EXCESSIVE WEAR OF THE AILERON PUSH-PULL TUBE, WHICH COULD RESULT IN UNEVEN MOVEMENT OF THE CONTROL WHEEL, PERFORATION OF THE AILERON PUSH-PULL TUBE, AND CONSEQUENT REDUCED ROLL CONTROL OF THE AIRPLANE AIRWORTHINESS DIRECTIVE										W2
	REF: AD	MOS HRS/MS AFL	600				26-JUL-2000 7325 5360		7925	119	
SB 1124-27-129 LEFT AILERON	FLIGHT CONTROLS SERVICE BULLETIN										W1
	REF: BULLETINS	MOS HRS/MS AFL	600				26-JUL-2000 7325 5360		7925	119	
SB 1124-27-129 RIGHT AILERON	FLIGHT CONTROLS SERVICE BULLETIN										W2
	REF: BULLETINS	MOS HRS/MS AFL	600				26-JUL-2000 7325 5360		7925	119	

Total Labor Hours 36.0
Total Price :

R - Task was due on previous due lists
(xEXT) - Extension incorporated in the next due calculation



Maintenance Due List/Time Remaining - AIRCRAFT(AFL)

Aircraft Model - 1124A WESTWIND

Serial #: 368 Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO	TASK DESCRIPTION	UNIT	INTERVAL TIME-----AT-----INSTALLATION				COMPLIANCE	DISPOSITION	TIME	AREA					
			WORK CARD	PART NUMBER/PKG	TSN	TSO					TSR	WARR EXP	NEXT DUE	REMAINING	PRICE
R	SB 972B40U	SERVICE BULLETIN G SBA72-3569 R/E FAN ROTOR													
		MOS													
		HRS/MS													
		AFL													
		A/R													
	REF:							5722	16						

REF:
Total Labor Hours
Total Price :

R - Task was due on previous due lists
(xEXT) - Extension incorporated in the next due calculation

Aircraft Model - 1124A WESTWIND

Serial #: 368 Reg. #: N368MD

Maintenance Due List/Time Remaining - ENGINE((AFL))

Report Date **11-APR-2002**

	ITEM NO WORK CARD WORK ORDER	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL TIME-----AT-----INSTALLATION				COMPLIANCE WARR EXP	DISPOSITION NEXT DUE		TIME REMAINING OVD = Overdue	AREA PRICE LABOR
				TSN	TSO	TSR			(ENH)	AFH (xEXT)		
R	725050	NO. 2 ENGINE - CHANGE FAN ROTOR DISC										
	72.090	3073539-2 0-18040-4768 REF: NO REF	MOS HRS/MS ENC (AFL)	4100	2660			20-MAY-1993 5278 3928		5368		OVD
R	725030	NO. 2 ENGINE - CHANGE STAGE 3 LOW PRESSURE TURBINE DISC										
	72.060	3072544-2 6-18040-4905 REF: NO REF	MOS HRS/MS ENC (AFL)	3000	0			31-MAY-1989 4265 2793		5793		87

Total Labor Hours

Total Price :

R - Task was due on previous due lists
(xEXT) - Extension incorporated in the next due calculation

OWNER: R&S AIRCRAFT INVESTMENTS, LLC
ADDRESS: P.O. BOX 43 HOUSTON TX 77001-0043

OPERATOR: R&S AIRCRAFT INVESTMENTS, LLC
ADDRESS: P.O. BOX 43 HOUSTON TX 77001-0043

PHONE: 713-830-9584
FAX: 713-918-5925

PHONE: 713-830-9584
FAX: 713-918-5925

PROJECTED : 2 MOS. to 11-AUG-2002

EXTENDED DUE LIST - FOR PLANNING PURPOSES ONLY - Scheduled Work Cards were not issued with this Report.

AIRCRAFT

S/N: 368 **REG NO:** N368MD **MODEL:** 1124A WESTWIND **MANUFACTURER:** GULFSTREAM AEROSPACE CORPORATION

NOTE:
INSPECTION PROGRAM: 3
CERTIFICATE DATE: 11-FEB-1982

UOM	LAST ACTUAL	LAST ACTUAL DATE	PROJECTED
HRS	7806	28-FEB-2002	7996.8
AFL	5706	28-FEB-2002	5897

ENGINE NO. 1

S/N: P-77482 **PART NO:** 3072500-2 **MODEL:** TFE731-3 **MANUFACTURER:** HONEYWELL

INSTALLED DATE: 4/3/1989
A/C HRS: 4215
ENGINE HRS: 3972
ENGINE CYCLES: 2456

UOM	LAST ACTUAL	LAST ACTUAL DATE	PROJECTED
HRS	7806	28-FEB-2002	7996.8
ENC	0		0
(AFL)	5706	28-FEB-2002	5897

ENGINE NO. 2

S/N: P77488 **PART NO:** 3072500-2 **MODEL:** TFE731-3 **MANUFACTURER:** HONEYWELL

INSTALLED DATE: 5/31/1993
A/C HRS: 5278
ENGINE HRS: 5227
ENGINE CYCLES: 3867

UOM	LAST ACTUAL	LAST ACTUAL DATE	PROJECTED
HRS	7806	28-FEB-2002	7996.8
ENC	0		0
(AFL)	5706	28-FEB-2002	5897

Extended Due List - AIRCRAFT(CALENDAR)

Aircraft Model - 1124A WESTWIND

Serial #: 368 Reg. #: N368MD

Report Date **11-APR-2002**
EXTENDED DUE LIST - FOR PLANNING PURPOSE ONLY - Scheduled Work Cards were not issued with this Report.

ITEM NO WORK CARD WORK ORDER	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL TIME-----AT-----INSTALLATION				COMPLIANCE	DISPOSITION NEXT DUE		AREA PRICE LABOR
			TSN	TSO	TSR	WARR EXP		(ENH)	AFH (xEXT)	
270080	X-RAY INSPECT LEFT AILERON CONTROL ROD	LEFT AILERON CONTROL ROD ASSEMBLIES								W1
27.530	513506-503 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	60 5000				16-JUN-1997 6135 4707	16-JUN-2002 11135		
270081	X-RAY INSPECT RIGHT AILERON CONTROL ROD ASSEMBLY									W2
27.535	513506-503 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	60 5000				16-JUN-1997 6135 4707	16-JUN-2002 11135		
270150	X-RAY INSPECT RUDDER CONTROL ROD ASSEMBLY									T1
27.560		MOS HRS/MSC AFL	60 5000				16-JUN-1997 6135 4707	16-JUN-2002 11135		
	REF: NO REF									
270210	VISUAL INSPECT ELEVATOR CONTROL BELLCRANK ASSEMBLY									
27.570		MOS HRS/MSC AFL	60 5000				16-JUN-1997 6135 4707	16-JUN-2002 11135		
	REF: AMM 5-10-00									
320110	X-RAY INSPECT NOSE GEAR ASSEMBLY NOSE GEAR SHAFT AND DOOR ASSEMBLIES									L3
32.560		MOS HRS/MSC AFL	60 5000				16-JUN-1997 6135 4707	16-JUN-2002 11135		
	REF: AMM 5-10-00									
260171	WEIGHT CHECK COCKPIT PORTABLE EXTINGUISHER COCKPIT FIRE EXTINGUISHER									F3
26.030		MOS HRS/MSC AFL	12				26-JUN-2001 7687 5594	26-JUN-2002		
	REF: AMM 5-10-00									
260181	WEIGHT CHECK CABIN PORTABLE EXTINGUISHER CABIN FIRE EXTINGUISHER									F4
26.030		MOS HRS/MSC AFL	12				26-JUN-2001 7687 5594	26-JUN-2002		
	REF: AMM 5-10-00									
350166U	CHECK PILOT OXYGEN MASK									F3
35.070		MOS HRS/MSC AFL	12 600				26-JUN-2001 7687 5594	26-JUN-2002 8287		
	REF: AMM 35-00-00									
350169U	CHECK COPILOT OXYGEN MASK									F3
35.070		MOS HRS/MSC AFL	12 600				26-JUN-2001 7687 5594	26-JUN-2002 8287		
	REF: AMM 35-00-00									

Total Labor Hours

Total Price :

R - Task was due on previous due lists

(xEXT) - Extension incorporated in the next due calculation

Aircraft Model - 1124A WESTWIND

Serial #: 368 Reg. #: N368MD

Report Date 11-APR-2002

EXTENDED DUE LIST - FOR PLANNING PURPOSE ONLY - Scheduled Work Cards were not issued with this Report.

	ITEM NO WORK CARD WORK ORDER	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL TIME-----AT-----INSTALLATION				COMPLIANCE	DISPOSITION		AREA PRICE LABOR
				TSN	TSO	TSR	WARR EXP		NEXT DUE	(ENH) AFH (xEXT)	
R	330228 33.100	CHARGE EMERGENCY LIGHT BATTERY	MOS HRS/MS AFL	3 200				06-NOV-2001 7774 5641	06-FEB-2002 7974		F4
		REF: AMM 12-10-06									
R	344616 34.370	INSPECT EMERGENCY GYRO POWER SUPPLY BATTERY EMERGENCY POWER SUPPLY BATTERY/STAND-BY ATTITUDE GYRO	MOS HRS/MS AFL	3 200				06-NOV-2001 7774 5641	06-FEB-2002 7974		F5
		REF: AMM NO REF									
	SB 1124-55-020 R2	STABILIZERS SERVICE BULLETIN	MOS HRS/MS AFL	300				26-JUN-2001 7687 5594	7987		T1
		REF: See Workcard									
	SL WW-2494 R3 LEFT	LANDING GEAR SERVICE LETTER	MOS HRS/MS AFL	300				26-JUN-2001 7687 5594	7987		L1
		REF: See Workcard									
	SL WW-2494 R3 RIGHT	LANDING GEAR SERVICE LETTER	MOS HRS/MS AFL	300				26-JUN-2001 7687 5594	7987		L2
		REF: See Workcard									

Total Labor Hours
Total Price :

R - Task was due on previous due lists
(xEXT) - Extension incorporated in the next due calculation

A/C Serial No.: 368 A/C Regn No.: N368MD Model:1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

Report Date **11-APR-2002**

Compliance From 01/01/2001 To 4/11/2002

ITEM NO PART NO.	DESCRIPTION SERIAL NO.	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED				COMPONENT TIMES AFTER REMOVAL					
		C/W	TSN	TSO	TSR	C/W	TSN	TSO	TSR		
CHAPTER 05-TIME LIMITS/MAINTENANCE CHECKS											
050150U	200 HOUR INSPECTION										
		MOS	1/17/2001							TECH :	INSP :
		HRS	7494								LABOR HRS :
		AFL	5466								SERVICE REMARKS --
CHAPTER 10-PARKING, MOORING, STORE AND RET TO SERV											
100310	CHECK AIRWORTHY DIRECTIVES										
		MOS	1/17/2001							TECH :	INSP :
		HRS	7494								LABOR HRS :
		AFL	5466								SERVICE REMARKS --
100320	CHECK SERVICE BULLETINS										
		MOS	1/17/2001							TECH :	INSP :
		HRS	7494								LABOR HRS :
		AFL	5466								SERVICE REMARKS --
100330	CHECK SERVICE LETTERS										
		MOS	1/17/2001							TECH :	INSP :
		HRS	7494								LABOR HRS :
		AFL	5466								SERVICE REMARKS --
CHAPTER 12-SERVICING											
120150	CHECK PRE-FLIGHT										
		MOS	1/17/2001							TECH :	INSP :
		HRS	7494								LABOR HRS :
		AFL	5466								SERVICE REMARKS --
120160	CHECK NO.1 ENGINE PREFLIGHT COMPLETE										
		MOS	2/16/2001							TECH :	INSP :
		HRS	7551								LABOR HRS :
		AFL	5515								SERVICE REMARKS --
120161	CHECK NO.2 ENGINE PREFLIGHT COMPLETE										
		MOS	2/16/2001							TECH :	INSP :
		HRS	7551								LABOR HRS :
		AFL	5515								SERVICE REMARKS --
CHAPTER 21-AIR CONDITIONING											
210622	INSPECT 35 DEGREE TEMPERATURE SENSOR 35 DEGREE DUCT SENSOR										
		MOS	1/17/2001							TECH :	INSP :
		HRS	7494								LABOR HRS :
		AFL	5466								SERVICE REMARKS --
210671	CLEAN/REPLACE WATER SEPARATOR CONDENSER/FILTER										
		MOS	1/17/2001							TECH :	INSP :
		HRS	7494								LABOR HRS :
		AFL	5466								SERVICE REMARKS --
210681	CHANGE COOLING TURBINE OIL										
		MOS	1/17/2001							TECH :	INSP :
		HRS	7494								LABOR HRS :
		AFL	5466								SERVICE REMARKS --
CHAPTER 24-ELECTRICAL POWER											
240116	CHANGE NO. 1 STARTER GENERATOR										
23065-018-1	3684	MOS	1/17/2001	0		11/6/2001	10			TECH :	INSP :
		HRS	7494	0		7774	280			REASON : WORN	LABOR HRS :
		AFL	5466	0		5641	175			PRICE : 0	
240118	INSPECT NO. 1 STARTER GENERATOR										

A/C Serial No.: 368 A/C Regn No.: N368MD Model:1124A WESTWIND
 Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

Report Date 11-APR-2002

Compliance

From 01/01/2001

To 4/11/2002

ITEM NO PART NO.	DESCRIPTION SERIAL NO.	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED				COMPONENT TIMES AFTER REMOVAL				TECH :	INSP :
		C/W	TSN	TSO	TSR	C/W	TSN	TSO	TSR		
		MOS	6/26/2001								
		HRS	7687								
		AFL	5594								
240121	CHECK NO. 1 STARTER GENERATOR	BRUSH WEAR/TENSION									
		MOS	6/26/2001								
		HRS	7687								
		AFL	5594								
240123	INSPECT NO. 1 STARTER GENERATOR	SPLINE									
		MOS	6/26/2001								
		HRS	7687								
		AFL	5594								
240128	INSPECT NO. 2 STARTER GENERATOR										
		MOS	6/26/2001								
		HRS	7687								
		AFL	5594								
240131	CHECK NO. 2 STARTER GENERATOR	BRUSH WEAR/TENSION									
		MOS	6/26/2001								
		HRS	7687								
		AFL	5594								
240133	INSPECT NO. 2 STARTER GENERATOR	SPLINE									
		MOS	6/26/2001								
		HRS	7687								
		AFL	5594								
240161	CHECK LEFT BATTERY	ELECTROLYTE LEVEL									
		MOS	1/17/2001								
		HRS	7494								
		AFL	5466								
240166	DEEP CYCLE LEFT BATTERY										
		MOS	6/26/2001								
		HRS	7687								
		AFL	5594								
240176	CHECK RIGHT BATTERY	ELECTROLYTE LEVEL									
		MOS	1/17/2001								
		HRS	7494								
		AFL	5466								
240181	DEEP CYCLE RIGHT BATTERY										
		MOS	6/26/2001								
		HRS	7687								
		AFL	5594								
240203	FUNCTIONALLY CHECK EXTERNAL POWER RECEPTACLE	BATTERY TEMPERATURE AND WARNING SYSTEM									
		MOS	1/17/2001								
		HRS	7494								
		AFL	5466								
CHAPTER 26-FIRE PROTECTION											
260169	VISUAL INSPECTION COCKPIT PORTABLE EXTINGUISHER	COCKPIT FIRE EXTINGUISHER									
		MOS	6/26/2001								
		HRS	7687								
		AFL	5594								
260174	INSPECT COCKPIT PORTABLE EXTINGUISHER	COCKPIT FIRE EXTINGUISHER									
		MOS	1/17/2001								
		HRS	7494								
		AFL	5466								

A/C Serial No.: 368 A/C Regn No.: N368MD Model:1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

Report Date **11-APR-2002**

Compliance From 01/01/2001 To 4/11/2002

ITEM NO PART NO.	DESCRIPTION SERIAL NO.	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED				COMPONENT TIMES AFTER REMOVAL			
		C/W	TSN	TSO	TSR	C/W	TSN	TSO	TSR
260180	VISUAL INSPECTION CABIN PORTABLE EXTINGUISHER	CABIN FIRE EXTINGUISHER							
	MOS	6/26/2001				TECH :		INSP :	
	HRS	7687						LABOR HRS :	
	AFL	5594						SERVICE REMARKS	--
260184	INSPECT CABIN PORTABLE EXTINGUISHER	CABIN FIRE EXTINGUISHER							
	MOS	1/17/2001				TECH :		INSP :	
	HRS	7494						LABOR HRS :	
	AFL	5466						SERVICE REMARKS	--
CHAPTER 27-FLIGHT CONTROLS									
270158	INSPECT RUDDER TRIM TAB	FREEPLAY							
	MOS	1/17/2001				TECH :		INSP :	
	HRS	7494						LABOR HRS :	
	AFL	5466						SERVICE REMARKS	--
270193	INSPECT LEFT ELEVATOR	SKIN SEPARATION							
	MOS	1/17/2001				TECH :		INSP :	
	HRS	7494						LABOR HRS :	
	AFL	5466						SERVICE REMARKS	--
270203	INSPECT RIGHT ELEVATOR	SKIN SEPARATION							
	MOS	1/17/2001				TECH :		INSP :	
	HRS	7494						LABOR HRS :	
	AFL	5466						SERVICE REMARKS	--
270213	LUBRICATE ELEVATOR ATTACH POINTS								
	MOS	1/17/2001				TECH :		INSP :	
	HRS	7494						LABOR HRS :	
	AFL	5466						SERVICE REMARKS	--
270214	LUBRICATE AFT HINGE FITTING BEARINGS								
	MOS	1/17/2001				TECH :		INSP :	
	HRS	7494						LABOR HRS :	
	AFL	5466						SERVICE REMARKS	--
270215	LUBRICATE FORWARD SCISSOR ASSEMBLY								
	MOS	1/17/2001				TECH :		INSP :	
	HRS	7494						LABOR HRS :	
	AFL	5466						SERVICE REMARKS	--
270237	INSPECT LEFT FLAP/VANE	LEFT FLAP VANE							
	MOS	1/17/2001				TECH :		INSP :	
	HRS	7494						LABOR HRS :	
	AFL	5466						SERVICE REMARKS	--
270240	INSPECT LEFT FLAP/VANE	LEFT FLAP HINGE AND BEARING 200 HOURS							
	MOS	1/17/2001				TECH :		INSP :	
	HRS	7494						LABOR HRS :	
	AFL	5466						SERVICE REMARKS	--
270242	INSPECT RIGHT FLAP/VANE	RIGHT FLAP HINGE AND BEARING 200 HOURS							
	MOS	1/17/2001				TECH :		INSP :	
	HRS	7494						LABOR HRS :	
	AFL	5466						SERVICE REMARKS	--
270247	INSPECT RIGHT FLAP/VANE								
	MOS	1/17/2001				TECH :		INSP :	
	HRS	7494						LABOR HRS :	
	AFL	5466						SERVICE REMARKS	--
270335	OPERATIONAL CHECK	SPEED BRAKES AND LIFT DUMPERS							

A/C Serial No.: 368 A/C Regn No.: N368MD Model:1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

Report Date 11-APR-2002

Compliance From 01/01/2001 To 4/11/2002

ITEM NO PART NO.	DESCRIPTION SERIAL NO.	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED				COMPONENT TIMES AFTER REMOVAL				TECH :	INSP :
		C/W	TSN	TSO	TSR	C/W	TSN	TSO	TSR		
		MOS	1/17/2001								
		HRS	7494								LABOR HRS :
		AFL	5466								SERVICE REMARKS --
CHAPTER 28-FUEL											
281150	CHECK OPERATION OF FUEL BOOST PUMPS										
		MOS	1/17/2001								
		HRS	7494								LABOR HRS :
		AFL	5466								SERVICE REMARKS --
CHAPTER 29-HYDRAULIC POWER											
290143	INSPECT/LUBRICATE NO. 1 HYDRAULIC PUMP NO.1 ENGINE HYDRAULIC PUMP SPLINES										
		MOS	1/17/2001								
		HRS	7494								LABOR HRS :
		AFL	5466								SERVICE REMARKS --
290178	INSPECT/LUBRICATE NO. 2 HYDRAULIC PUMP NO.2 ENGINE HYDRAULIC PUMP SPLINES										
		MOS	1/17/2001								
		HRS	7494								LABOR HRS :
		AFL	5466								SERVICE REMARKS --
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN										
		MOS	1/17/2001								
		HRS	7494								LABOR HRS :
		AFL	5466								SERVICE REMARKS --
CHAPTER 30-ICE AND RAIN PROTECTION											
300147	INSPECT PILOT WINDSHIELD CYCLING CONTACTOR										
		MOS	1/17/2001								
		HRS	7494								LABOR HRS :
		AFL	5466								SERVICE REMARKS --
300150	INSPECT COPILOT WINDSHIELD CYCLING CONTACTOR										
		MOS	1/17/2001								
		HRS	7494								LABOR HRS :
		AFL	5466								SERVICE REMARKS --
300163	INSPECT WINDSHIELD WIPER ASSEMBLY										
		MOS	1/17/2001								
		HRS	7494								LABOR HRS :
		AFL	5466								SERVICE REMARKS --
300170	OPERATIONAL TEST P2T2 SENSOR HEATER										
		MOS	1/17/2001								
		HRS	7494								LABOR HRS :
		AFL	5466								SERVICE REMARKS --
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN										
		MOS	1/17/2001								
		HRS	7494								LABOR HRS :
		AFL	5466								SERVICE REMARKS --
CHAPTER 32-LANDING GEAR											
320106	LUBRICATE NOSE GEAR ASSEMBLY NOSE GEAR/DOORS										
		MOS	1/17/2001								
		HRS	7494								LABOR HRS :
		AFL	5466								SERVICE REMARKS --
320156	INSPECT/CLEAN/LUBRICATE NOSE GEAR LEFT WHEEL BEARINGS										
		MOS	1/17/2001								
		HRS	7494								LABOR HRS :
		AFL	5466								SERVICE REMARKS --

A/C Serial No.: 368 A/C Regn No.: N368MD Model:1124A WESTWIND
 Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

Report Date **11-APR-2002**

Compliance From 01/01/2001 To 4/11/2002

ITEM NO PART NO.	DESCRIPTION SERIAL NO.	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED				COMPONENT TIMES AFTER REMOVAL				TECH :	INSP :
		C/W	TSN	TSO	TSR	C/W	TSN	TSO	TSR		
322131	INSPECT/CHECK RIGHT MAIN GEAR BRAKE RIGHT BRAKE LININGS										
	MOS	1/17/2001									
	HRS	7494									
	AFL	5466									
322156	INSPECT/CLEAN LEFT ANTI-SKID DETECTOR										
	MOS	1/17/2001									
	HRS	7494									
	AFL	5466									
322171	INSPECT/CLEAN RIGHT ANTI-SKID DETECTOR										
	MOS	1/17/2001									
	HRS	7494									
	AFL	5466									
322174	OPERATIONAL CHECK ANTI-SKID LIGHTS										
	MOS	1/17/2001									
	HRS	7494									
	AFL	5466									
322206	FUNCTIONAL TEST EMERGENCY GEAR EXTENSION CONTROL CABLE										
	MOS	1/17/2001									
	HRS	7494									
	AFL	5466									
CHAPTER 33-LIGHTS											
330228	CHARGE EMERGENCY LIGHT BATTERY										
	MOS	6/26/2001									
	HRS	7687									
	AFL	5594									
CHAPTER 34-NAVIGATION											
340121	DRAIN PITOT/STATIC SYSTEM										
	MOS	1/17/2001									
	HRS	7494									
	AFL	5466									
344616	INSPECT EMERGENCY GYRO POWER SUPPLY BATTERY EMERGENCY POWER SUPPLY BATTERY/STAND-BY ATTITUDE GYRO										
	MOS	6/26/2001									
	HRS	7687									
	AFL	5594									
CHAPTER 52-DOORS											
520106	INSPECT/LUBRICATE CABIN ENTRANCE DOOR										
	MOS	1/17/2001									
	HRS	7494									
	AFL	5466									
520116	OPERATIONAL CHECK CABIN ENTRANCE DOOR										
	MOS	1/17/2001									
	HRS	7494									
	AFL	5466									
CHAPTER 53-FUSELAGE											
530101	INSPECT FUSELAGE (A)										
	MOS	1/17/2001									
	HRS	7494									
	AFL	5466									
530116	INSPECT NOSE COMPARTMENT (A)										

A/C Serial No.: 368 A/C Regn No.: N368MD Model:1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

Report Date **11-APR-2002**

Compliance From 01/01/2001 To 4/11/2002

ITEM NO PART NO.	DESCRIPTION SERIAL NO.	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED				COMPONENT TIMES AFTER REMOVAL				TECH :	INSP :
		C/W	TSN	TSO	TSR	C/W	TSN	TSO	TSR		
		MOS	1/17/2001								
		HRS	7494								LABOR HRS :
		AFL	5466								SERVICE REMARKS --
530131	INSPECT COCKPIT (A)	MOS	1/17/2001								
		HRS	7494								LABOR HRS :
		AFL	5466								SERVICE REMARKS --
530146	INSPECT CABIN (A)	MOS	1/17/2001								
		HRS	7494								LABOR HRS :
		AFL	5466								SERVICE REMARKS --
530161	INSPECT REAR COMPARTMENT (A)	MOS	1/17/2001								
		HRS	7494								LABOR HRS :
		AFL	5466								SERVICE REMARKS --
CHAPTER 54-NACELLES/PYLONS											
540101U	INSPECT NO. 1 ENGINE NACELLE/PYLON (A)	MOS	1/17/2001								
		HRS	7494								LABOR HRS :
		AFL	5466								SERVICE REMARKS --
540121U	INSPECT NO. 2 ENGINE NACELLE/PYLON (A)	MOS	1/17/2001								
		HRS	7494								LABOR HRS :
		AFL	5466								SERVICE REMARKS --
CHAPTER 55-STABILIZERS											
550101	INSPECT EMPENNAGE (A)	MOS	1/17/2001								
		HRS	7494								LABOR HRS :
		AFL	5466								SERVICE REMARKS --
550656	CHECK HORIZONTAL STABILIZER AFT SPAR SPLICE-HINGE FITTING OUTBOARD LUGS FOR CRACKS	MOS	1/17/2001								
		HRS	7494								LABOR HRS :
		AFL	5466								SERVICE REMARKS --
CHAPTER 57-WINGS											
570101	INSPECT LEFT WING (A)	MOS	1/17/2001								
		HRS	7494								LABOR HRS :
		AFL	5466								SERVICE REMARKS --
570106	INSPECT LEFT AILERON BELLCRANK	MOS	1/17/2001								
		HRS	7494								LABOR HRS :
		AFL	5466								SERVICE REMARKS --
570116	INSPECT RIGHT WING (A)	MOS	1/17/2001								
		HRS	7494								LABOR HRS :
		AFL	5466								SERVICE REMARKS --
570120	INSPECT RIGHT AILERON BELLCRANK	MOS	1/17/2001								
		HRS	7494								LABOR HRS :
		AFL	5466								SERVICE REMARKS --
CHAPTER 71-POWER PLANT											

A/C Serial No.: 368 A/C Regn No.: N368MD Model:1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

Report Date **11-APR-2002**

Compliance From 01/01/2001 To 4/11/2002

ITEM NO PART NO.	DESCRIPTION SERIAL NO.	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED				COMPONENT TIMES AFTER REMOVAL				TECH :	INSP :
		C/W	TSN	TSO	TSR	C/W	TSN	TSO	TSR		
710650U	-- INSP #1 ENG INLET NACELLE										
		MOS	1/17/2001								
		HRS	7494								
		AFL	5466								
713650U	-- INSP #2 ENG INLET NACELLE										
		MOS	1/17/2001								
		HRS	7494								
		AFL	5466								

LABOR HRS :
SERVICE REMARKS --

LABOR HRS :
SERVICE REMARKS --