



**CAMP SYSTEMS INTERNATIONAL, LLC**  
**LONG ISLAND MAC ARTHUR AIRPORT**  
**999 MARCONI AVE.**  
**RONKONKOMA, NY 11779**

**POSTAL**

**R&S AIRCRAFT INVESTMENTS, LLC**  
**ATTN: YANDELL ROGERS III**  
**P.O. BOX 43**  
**HOUSTON, TX 77001-0043**



PLEASE FILL IN THE INFORMATION REQUESTED BELOW AND RETURN CARD TO  
**CAMP SYSTEMS, INT'L.**

**1124 WESTWIND 368**

**AIRCRAFT MODEL** \_\_\_\_\_

**Y 05/02 UNITED STATES OF AMERICA** \_\_\_\_\_

RECORD PRESENT:

**AIRCRAFT HOURS** \_\_\_\_\_

**LANDINGS** \_\_\_\_\_

**NO. 1 ENG. HOURS** \_\_\_\_\_

**CYCLES** \_\_\_\_\_

**NO. 2 ENG. HOURS** \_\_\_\_\_

**CYCLES** \_\_\_\_\_

**NO. 3 ENG. HOURS** \_\_\_\_\_

**CYCLES** \_\_\_\_\_

**NO. 4 ENG. HOURS** \_\_\_\_\_

**CYCLES** \_\_\_\_\_

**APU HOURS** \_\_\_\_\_

**STARTS** \_\_\_\_\_

**DATE** \_\_\_\_\_



**OWNER:** R&S AIRCRAFT INVESTMENTS, LLC  
**ADDRESS:** P.O. BOX 43 HOUSTON TX 77001-0043

**PHONE:** 713-830-9584  
**FAX:** 713-918-5925

**OPERATOR:** R&S AIRCRAFT INVESTMENTS, LLC  
**ADDRESS:** P.O. BOX 43 HOUSTON TX 77001-0043

**PHONE:** 713-830-9584  
**FAX:** 713-918-5925

**AIRCRAFT**

**S/N:** 368      **REG NO:** N368MD      **MODEL:** 1124A WESTWIND      **MANUFACTURER:** GULFSTREAM AEROSPACE CORPORATION

**NOTE:**  
**INSPECTION PROGRAM:** 3  
**CERTIFICATE DATE:** 11-FEB-1982

| UOM | LAST ACTUAL | LAST ACTUAL DATE |
|-----|-------------|------------------|
| HRS | 7806        | 28-FEB-2002      |
| AFL | 5706        | 28-FEB-2002      |

**ENGINE NO. 1**

**S/N:** P-77482      **PART NO:** 3072500-2      **MODEL:** TFE731-3      **MANUFACTURER:** HONEYWELL

**INSTALLED DATE:** 4/3/1989  
**A/C HRS:** 4215  
**ENGINE HRS:** 3972  
**ENGINE CYCLES:** 2456

| UOM   | LAST ACTUAL | LAST ACTUAL DATE |
|-------|-------------|------------------|
| HRS   | 7806        | 28-FEB-2002      |
| ENC   | 0           |                  |
| (AFL) | 5706        | 28-FEB-2002      |

**ENGINE NO. 2**

**S/N:** P77488      **PART NO:** 3072500-2      **MODEL:** TFE731-3      **MANUFACTURER:** HONEYWELL

**INSTALLED DATE:** 5/31/1993  
**A/C HRS:** 5278  
**ENGINE HRS:** 5227  
**ENGINE CYCLES:** 3867

| UOM   | LAST ACTUAL | LAST ACTUAL DATE |
|-------|-------------|------------------|
| HRS   | 7806        | 28-FEB-2002      |
| ENC   | 0           |                  |
| (AFL) | 5706        | 28-FEB-2002      |





# AIRCRAFT Status Report ( Work Packages )

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name R&S AIRCRAFT INVESTMENTS, LLC  
A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PKG NUMBER            | UNIT                  | ACT | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE                  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|-------------------------------------------|-----------------------|-----|----------|-----------------------------------------------------|----------|-----------------------------|-------------------------|----------------------------|
| AIRCRAFT            |                                           |                       |     |          |                                                     |          |                             |                         |                            |
| CHAPTER 05          | TIME LIMITS/MAINTENANCE CHECKS            |                       |     |          |                                                     |          |                             |                         |                            |
| + 050150U           | 200 HOUR INSPECTION<br>PKG 1 in PKG 2, 3  | MOS<br>HRS/MSC<br>AFL | R   | 200      |                                                     |          | 26-JUN-2001<br>7687<br>5594 | 7887                    | 31                         |
| REF:                |                                           |                       |     |          |                                                     |          |                             |                         |                            |
| + 050300U           | 400/200 HOUR INSPECTION<br>PKG 2 in PKG 3 | MOS<br>HRS/MSC<br>AFL | R   | 400      |                                                     |          | 26-JUN-2001<br>7687<br>5594 | 8087                    | 45.5                       |
| REF:                |                                           |                       |     |          |                                                     |          |                             |                         |                            |
| + 050600U           | 800/400/200 HOUR INSPECT<br>PKG 3         | MOS<br>HRS/MSC<br>AFL | R   | 800      |                                                     | -38      | 26-JUL-2000<br>7325<br>5360 | 8087                    | 45.5                       |
| REF:                |                                           |                       |     |          |                                                     |          |                             |                         |                            |
| + 057110U           | 150HR #1 ENGINE INSP NO. 1<br>PKG 4       | MOS<br>HRS/MSC<br>AFL |     | 150      |                                                     |          | 26-JUN-2001<br>7687<br>5594 |                         | E1<br>1.5                  |
| REF:                |                                           |                       |     |          |                                                     |          |                             |                         |                            |
| + 057110U           | 150HR #2 ENGINE INSP NO. 2<br>PKG 5       | MOS<br>HRS/MSC<br>AFL |     | 150      |                                                     |          | 26-JUN-2001<br>7687<br>5594 |                         | E2<br>1                    |
| REF:                |                                           |                       |     |          |                                                     |          |                             |                         |                            |
| + 057120U           | 300HR #1 ENGINE INSP NO. 1<br>PKG 6       | MOS<br>HRS/MSC<br>AFL |     | 300      |                                                     |          | 16-FEB-2001<br>7551<br>5515 |                         | E1                         |
| REF:                |                                           |                       |     |          |                                                     |          |                             |                         |                            |
| + 057120U           | 300HR #2 ENGINE INSP NO. 2<br>PKG 7       | MOS<br>HRS/MSC<br>AFL |     | 300      |                                                     |          | 16-FEB-2001<br>7551<br>5515 |                         | E2                         |
| REF:                |                                           |                       |     |          |                                                     |          |                             |                         |                            |



**Engine Model-** TFE731-3

**Report Date** 11-APR-2002

**Owner Name** R&S AIRCRAFT INVESTMENTS, LLC

**A/C Serial #:** 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD                              | TASK DESCRIPTION<br>PKG NUMBER      | UNIT   | ACT | INTERVAL | TIME-----AT-----INSTALLATION | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|--------------------------------------------------|-------------------------------------|--------|-----|----------|------------------------------|----------|-------------|-------------------------|----------------------------|
|                                                  |                                     |        |     |          | TSN TSO TSR TSI ADJ          |          |             |                         |                            |
| <b>ENGINE NO. 1</b>                              |                                     |        |     |          |                              |          |             |                         |                            |
| <b>CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS</b> |                                     |        |     |          |                              |          |             |                         |                            |
| + 057110U                                        | NO. 1 ENGINE - 150HR #1 ENGINE INSP |        |     |          |                              |          |             |                         |                            |
|                                                  | PKG 4 in PKG 4, 6, 6                | MOS    |     |          |                              |          | 26-JUN-2001 |                         |                            |
|                                                  | REF:                                | HRS/MS | 150 |          |                              |          | 7687        | 7837                    | 1                          |
|                                                  |                                     | ENC    |     |          |                              |          | 5594        |                         |                            |
|                                                  |                                     | (AFL)  |     |          |                              |          |             |                         |                            |
| + 057120U                                        | NO. 1 ENGINE - 300HR #1 ENGINE INSP |        |     |          |                              |          |             |                         |                            |
|                                                  | PKG 6 in PKG 6                      | MOS    |     |          |                              |          | 16-FEB-2001 |                         |                            |
|                                                  | REF:                                | HRS/MS | 300 |          |                              |          | 7551        | 7851                    | 1.5                        |
|                                                  |                                     | ENC    |     |          |                              |          | 5515        |                         |                            |
|                                                  |                                     | (AFL)  |     |          |                              |          |             |                         |                            |





# AIRCRAFT Status Report ( Work Packages )

Engine Model - TFE731-3

Report Date 11-APR-2002

Owner Name R&S AIRCRAFT INVESTMENTS, LLC  
A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PKG NUMBER       | UNIT   | ACT | INTERVAL TIME-----AT-----INSTALLATION |     |     |     |     | Warr Exp | COMPLIANCE | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|--------------------------------------|--------|-----|---------------------------------------|-----|-----|-----|-----|----------|------------|-------------------------|----------------------------|
|                     |                                      |        |     | TSN                                   | TSO | TSR | TSI | ADJ |          |            |                         |                            |
| ENGINE NO. 2        |                                      |        |     |                                       |     |     |     |     |          |            |                         |                            |
| CHAPTER 05          | TIME LIMITS/MAINTENANCE CHECKS       |        |     |                                       |     |     |     |     |          |            |                         |                            |
| + 057110U           | NO. 2 ENGINE - 150 HR #2 ENGINE INSP |        |     |                                       |     |     |     |     |          |            |                         |                            |
|                     | PKG 5 in PKG 5, 7,                   | MOS    |     |                                       |     |     |     |     |          |            | 26-JUN-2001             |                            |
|                     |                                      | HRSMSC |     | 150                                   |     |     |     |     |          |            | 7687                    | 7837 1                     |
|                     | REF:                                 | ENC    |     |                                       |     |     |     |     |          |            |                         |                            |
|                     |                                      | (AFL)  |     |                                       |     |     |     |     |          |            | 5594                    |                            |
| + 057120U           | NO. 2 ENGINE - 300 HR #2 ENGINE INSP |        |     |                                       |     |     |     |     |          |            |                         |                            |
|                     | PKG 7 in PKG 7                       | MOS    |     |                                       |     |     |     |     |          |            | 16-FEB-2001             |                            |
|                     |                                      | HRSMSC |     | 300                                   |     |     |     |     |          |            | 7551                    | 7851 1.5                   |
|                     | REF:                                 | ENC    |     |                                       |     |     |     |     |          |            |                         |                            |
|                     |                                      | (AFL)  |     |                                       |     |     |     |     |          |            | 5515                    |                            |



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD                                       | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|-----------------------------------------------------------|------------------------------------------------------|--------|----------|-----------------------------------------------------|----------|------------|-------------------------|----------------------------|
| <b>AIRCRAFT</b>                                           |                                                      |        |          |                                                     |          |            |                         |                            |
| <b>CHAPTER 00 INFORMATION</b>                             |                                                      |        |          |                                                     |          |            |                         |                            |
| 000004U                                                   | -- ICON HEALTH AND FITNESS                           | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                                                           |                                                      | HRSMSC | N/R      |                                                     |          |            | 0                       |                            |
|                                                           | REF:                                                 | AFL    |          |                                                     |          |            | 0                       |                            |
| <b>CHAPTER 10 PARKING, MOORING, STORE AND RET TO SERV</b> |                                                      |        |          |                                                     |          |            |                         |                            |
| + 100310                                                  | CHECK AIRWORTHY DIRECTIVES                           | MOS    |          |                                                     |          |            | 26-JUN-2001             |                            |
| 10.010                                                    | PKG 1, 2, 3                                          | HRSMSC | 200      |                                                     |          |            | 7687                    |                            |
|                                                           | REF: NO REF                                          | AFL    |          |                                                     |          |            | 5594                    |                            |
| + 100320                                                  | CHECK SERVICE BULLETINS                              | MOS    |          |                                                     |          |            | 26-JUN-2001             |                            |
| 10.020                                                    | PKG 1, 2, 3                                          | HRSMSC | 200      |                                                     |          |            | 7687                    |                            |
|                                                           | REF: NO REF                                          | AFL    |          |                                                     |          |            | 5594                    |                            |
| + 100330                                                  | CHECK SERVICE LETTERS                                | MOS    |          |                                                     |          |            | 26-JUN-2001             |                            |
| 10.030                                                    | PKG 1, 2, 3                                          | HRSMSC | 200      |                                                     |          |            | 7687                    |                            |
|                                                           | REF: NO REF                                          | AFL    |          |                                                     |          |            | 5594                    |                            |
| <b>CHAPTER 12 SERVICING</b>                               |                                                      |        |          |                                                     |          |            |                         |                            |
| + 120160                                                  | CHECK NO.1 ENGINE PREFLIGHT COMPLETE                 | MOS    |          |                                                     |          |            | 26-JUN-2001             | E1                         |
| 12.020                                                    | PKG 4                                                | HRSMSC | 150      |                                                     |          |            | 7687                    |                            |
|                                                           | REF: AMM 5-21-00                                     | AFL    |          |                                                     |          |            | 5594                    |                            |
| + 120161                                                  | CHECK NO.2 ENGINE PREFLIGHT COMPLETE                 | MOS    |          |                                                     |          |            | 26-JUN-2001             | E2                         |
| 12.020                                                    | PKG 5                                                | HRSMSC | 150      |                                                     |          |            | 7687                    |                            |
|                                                           | REF: AMM 5-21-00                                     | AFL    |          |                                                     |          |            | 5594                    |                            |
| + 120150                                                  | CHECK PRE-FLIGHT                                     | MOS    |          |                                                     |          |            | 26-JUN-2001             |                            |
| 12.010                                                    | PKG 1, 2, 3                                          | HRSMSC | 200      |                                                     |          |            | 7687                    |                            |
|                                                           | REF: AMM 5-30-00                                     | AFL    |          |                                                     |          |            | 5594                    |                            |
| <b>CHAPTER 21 AIR CONDITIONING</b>                        |                                                      |        |          |                                                     |          |            |                         |                            |
| 210280                                                    | CHECK BLEED AIR DUCT OVERPRESSURE SWITCH             | MOS    |          |                                                     |          |            | 26-JUL-2000             | F3                         |
| 21.270                                                    | PKG 3                                                | HRSMSC | 800      |                                                     |          |            | 7325                    |                            |
|                                                           | REF: AMM 21-00-00                                    | AFL    |          |                                                     |          |            | 5360                    |                            |
| + 210276                                                  | OPERATIONAL CHECK PRESSURIZATION SWITCHES AND VALVES | MOS    |          |                                                     |          |            | 26-JUN-2001             | F3                         |
| 21.030                                                    | PKG 2, 3                                             | HRSMSC | 400      |                                                     |          |            | 7687                    |                            |
|                                                           | REF: AMM 21-00-00                                    | AFL    |          |                                                     |          |            | 5594                    |                            |
| 210641                                                    | ANTICIPATOR, TEMPERATURE SENSOR                      | MOS    |          |                                                     |          |            | 11-FEB-1982             | F4                         |
| 21.310                                                    | 548486-1                                             | HRSMSC | O/C      | 0                                                   |          |            | 0                       |                            |
|                                                           | SN-UNKNOWN                                           | AFL    |          |                                                     |          |            | 0                       |                            |
|                                                           | REF: AMM 21-60-00                                    |        |          |                                                     |          |            |                         |                            |



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT    | INTERVAL | TIME-----AT-----INSTALLATION |     |     |     |     | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|---------|----------|------------------------------|-----|-----|-----|-----|----------|-------------|-------------------------|----------------------------|
|                     |                                                      |         |          | TSN                          | TSO | TSR | TSI | ADJ |          |             |                         |                            |
| 210673              | ASPIRATOR, ENVIRONMENTAL CONTROL SYSTEM              |         |          |                              |     |     |     |     |          |             |                         | F5                         |
| 21.430              | PN                                                   | MOS     |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MSC | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 21-50-00                                    | AFL     |          |                              |     |     |     |     |          | 0           |                         |                            |
| 210661              | BULB, CABIN TEMPERATURE INDICATOR SENSOR             |         |          |                              |     |     |     |     |          |             |                         | F4                         |
| 21.350              | PN                                                   | MOS     |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MSC | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 21-60-00                                    | AFL     |          |                              |     |     |     |     |          | 0           |                         |                            |
| 210626              | CONTROL BOX, CABIN TEMPERATURE                       |         |          |                              |     |     |     |     |          |             |                         | F4                         |
| 21.450              | 548482-5                                             | MOS     |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | 030C154                                              | HRS/MSC | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 21-60-00                                    | AFL     |          |                              |     |     |     |     |          | 0           |                         |                            |
| 210118              | CONTROL UNIT, BLEED AIR CONTROL RIGHT                |         |          |                              |     |     |     |     |          |             |                         | F5                         |
| 21.360              | 3213894-4-1                                          | MOS     |          |                              |     |     |     |     | 0        | 06-NOV-1990 |                         |                            |
|                     | P402C                                                | HRS/MSC | O/C      |                              |     |     |     |     | 0        | 4731        |                         |                            |
|                     | REF: NO REF                                          | AFL     |          |                              |     |     |     |     | 0        | 3324        |                         |                            |
| 210108              | CONTROL UNIT, BLEED AIR LEFT                         |         |          |                              |     |     |     |     |          |             |                         | F5                         |
| 21.360              | 32131894-4-1                                         | MOS     |          |                              |     |     |     |     |          | 06-NOV-1990 |                         |                            |
|                     | P336C                                                | HRS/MSC | O/C      |                              |     |     |     |     |          | 4731        |                         |                            |
|                     | REF: NO REF                                          | AFL     |          |                              |     |     |     |     |          | 3324        |                         |                            |
| 210176              | CONTROLLER, CABIN AIR PRESSURE                       |         |          |                              |     |     |     |     |          |             |                         | F3                         |
| 21.180              | 130398-3                                             | MOS     |          |                              |     |     |     |     |          | 11-FEB-1982 |                         | \$1455.                    |
|                     | 31340                                                | HRS/MSC | O/C      | 0                            |     |     |     |     |          | 0           |                         | 3                          |
|                     | REF: AMM 21-30-00                                    | AFL     |          |                              |     |     |     |     |          | 0           |                         |                            |
| 210178              | CLEAN FILTER                                         |         |          |                              |     |     |     |     |          |             |                         | F3                         |
| 21.480              | PKG 3                                                | MOS     |          |                              |     |     |     |     |          | 26-JUL-2000 |                         |                            |
|                     |                                                      | HRS/MSC | 800      |                              |     |     |     |     |          | 7325        |                         |                            |
|                     | REF: AMM 21-30-00                                    | AFL     |          |                              |     |     |     |     |          | 5360        |                         |                            |
| 210606              | EXCHANGER, REFRIGERATION UNIT HEAT                   |         |          |                              |     |     |     |     |          |             |                         | F5                         |
| 21.240              | PN                                                   | MOS     |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MSC | O/C      | 0                            |     |     |     |     |          | 0           |                         | 20                         |
|                     | REF: AMM 21-50-00                                    | AFL     |          |                              |     |     |     |     |          | 0           |                         |                            |
| 210636              | FAN, CABIN TEMPERATURE                               |         |          |                              |     |     |     |     |          |             |                         | F4                         |
| 21.300              | 5783661-5                                            | MOS     |          |                              |     |     |     |     |          | 04-APR-1996 |                         | \$302.                     |
|                     | 120713                                               | HRS/MSC | O/C      |                              |     |     |     |     |          | 5747        |                         |                            |
|                     | REF: AMM 21-60-00                                    | AFL     |          |                              |     |     |     |     |          | 4430        |                         |                            |
| 210206              | INDICATOR, CABIN ALTITUDE/PRESSURE                   |         |          |                              |     |     |     |     |          |             |                         | F3                         |
| 21.390              | 4883747-1                                            | MOS     |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | 495                                                  | HRS/MSC | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 21-31-00                                    | AFL     |          |                              |     |     |     |     |          | 0           |                         |                            |
| 210208              | INDICATOR, CABIN RATE-OF-CLIMB                       |         |          |                              |     |     |     |     |          |             |                         | F3                         |
| 21.400              | 4883788                                              | MOS     |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MSC | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 21-31-00                                    | AFL     |          |                              |     |     |     |     |          | 0           |                         |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|--------|----------|-----------------------------------------------------|----------|------------|-------------------------|----------------------------|
| 210633              | INDICATOR, CABIN TEMPERATURE                         |        |          |                                                     |          |            |                         | F3                         |
| 21.410              | 883767-501                                           | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | 197                                                  | HRS/MS | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 21-60-00                                    | AFL    |          |                                                     |          | 0          |                         |                            |
| 210156              | PLENUM, MIXING                                       |        |          |                                                     |          |            |                         | F4                         |
| 21.160              | 5-783584-1                                           | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                                                     |          | 0          |                         |                            |
| 210241              | REGULATOR, ABSOLUTE AIR PRESSURE LOWER               |        |          |                                                     |          |            |                         | F3                         |
| 21.200              | 102466-1                                             | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | 1203419                                              | HRS/MS | O/C      | 0                                                   |          | 0          |                         | 4                          |
|                     | REF: AMM 21-30-00                                    | AFL    |          |                                                     |          | 0          |                         |                            |
| 210221              | REPLACE LOWER INLET AIR FILTER ELEMENT               |        |          |                                                     |          |            |                         | F3                         |
| 21.080              | PKG 3                                                | MOS    |          |                                                     |          |            | 26-JUL-2000             |                            |
|                     | 1203419                                              | HRS/MS | 800      |                                                     |          | 7325       |                         |                            |
|                     | REF: AMM 21-30-00                                    | AFL    |          |                                                     |          | 5360       |                         |                            |
| 210236              | REGULATOR, ABSOLUTE AIR PRESSURE UPPER               |        |          |                                                     |          |            |                         | F3                         |
| 21.200              | 102466-1                                             | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | 313613                                               | HRS/MS | O/C      | 0                                                   |          | 0          |                         | 4                          |
|                     | REF: AMM 21-30-00                                    | AFL    |          |                                                     |          | 0          |                         |                            |
| 210621              | REGULATOR, PNEUMATIC PRESSURE                        |        |          |                                                     |          |            |                         | F5                         |
| 21.280              | PN                                                   | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 21-50-00                                    | AFL    |          |                                                     |          | 0          |                         |                            |
| 210246              | RELAY, PNEUMATIC                                     |        |          |                                                     |          |            |                         | F3                         |
| 21.210              | 107312-2                                             | MOS    |          |                                                     |          |            | 22-OCT-1982             | \$383.                     |
|                     | 11-9440                                              | HRS/MS | O/C      | 0                                                   |          | 482        |                         | 4                          |
|                     | REF: AMM 21-30-00                                    | AFL    |          |                                                     |          |            |                         |                            |
| 210619              | SENSOR, 35 DEGREE TEMPERATURE                        |        |          |                                                     |          |            |                         | F5                         |
| 21.420              | 783649-1                                             | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | 071C730                                              | HRS/MS | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 21-50-00                                    | AFL    |          |                                                     |          | 0          |                         |                            |
| + 210622            | INSPECT 35 DEGREE DUCT SENSOR                        |        |          |                                                     |          |            |                         | F5                         |
| 21.420              | PKG 1, 2, 3                                          | MOS    |          |                                                     |          |            | 26-JUN-2001             |                            |
|                     |                                                      | HRS/MS | 200      |                                                     |          | 7687       |                         |                            |
|                     | REF: AMM 21-50-00                                    | AFL    |          |                                                     |          | 5594       |                         |                            |
| 210631              | SENSOR, CABIN TEMPERATURE                            |        |          |                                                     |          |            |                         | F4                         |
| 21.460              | 548484-1                                             | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | 070C482                                              | HRS/MS | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 21-60-00                                    | AFL    |          |                                                     |          | 0          |                         |                            |
| 210646              | SENSOR, HIGH TEMPERATURE                             |        |          |                                                     |          |            |                         | F4                         |
| 21.320              | 627962-2                                             | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | 011C955                                              | HRS/MS | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 21-60-00                                    | AFL    |          |                                                     |          | 0          |                         |                            |



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----<br>TSN TSO TSR TSI ADJ | INSTALLATION<br>Warr Exp | COMPLIANCE | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|--------|----------|-----------------------------------------|--------------------------|------------|-------------------------|----------------------------|
| 210665              | SENSOR, REFRIGERATION TEMPERATURE CONTROL            |        |          |                                         |                          |            |                         | F3                         |
| 21.440              | 3783649-1                                            | MOS    |          |                                         |                          |            | 03-NOV-1984             |                            |
|                     | 11166                                                | HRSMSC | O/C      | 0                                       |                          |            | 2044                    |                            |
|                     | REF: NO REF                                          | AFL    |          |                                         |                          |            |                         |                            |
| 210666              | SEPARATOR, WATER                                     |        |          |                                         |                          |            |                         | F5                         |
| 21.050              | 179510-1                                             | MOS    |          |                                         |                          |            | 11-FEB-1982             |                            |
|                     | 31535                                                | HRSMSC | O/C      | 0                                       |                          |            | 0                       |                            |
|                     | REF: AMM 21-70-00                                    | AFL    |          |                                         |                          |            | 0                       |                            |
| + 210671            | CLEAN/REPLACE CONDENSER/FILTER                       |        |          |                                         |                          |            |                         | F5                         |
| 21.050              | PKG 1, 2, 3                                          | MOS    |          |                                         |                          |            | 26-JUN-2001             |                            |
|                     |                                                      | HRSMSC | 200      |                                         |                          |            | 7687                    | 1                          |
|                     | REF: AMM 21-70-00                                    | AFL    |          |                                         |                          |            | 5594                    |                            |
| 210286              | SWITCH, CABIN AIR SELECTOR                           |        |          |                                         |                          |            |                         | F3                         |
| 21.380              | 823073-501                                           | MOS    |          |                                         |                          |            | 11-FEB-1982             |                            |
|                     | 8128133                                              | HRSMSC | O/C      | 0                                       |                          |            | 0                       |                            |
|                     | REF: NO REF                                          | AFL    |          | 0                                       |                          |            | 0                       |                            |
| 210656              | SWITCH, OVERPRESSURE                                 |        |          |                                         |                          |            |                         | F5                         |
| 21.340              | 3-783646-2                                           | MOS    |          |                                         |                          |            | 11-FEB-1982             |                            |
|                     | 194                                                  | HRSMSC | O/C      | 0                                       |                          |            | 0                       |                            |
|                     | REF: AMM 21-60-00                                    | AFL    |          |                                         |                          |            | 0                       |                            |
| 210651              | SWITCH, OVERTEMPERATURE                              |        |          |                                         |                          |            |                         | F4                         |
| 21.330              | 3-783645-1                                           | MOS    |          |                                         |                          |            | 11-FEB-1982             |                            |
|                     | 211                                                  | HRSMSC | O/C      | 0                                       |                          |            | 0                       |                            |
|                     | REF: AMM 21-60-00                                    | AFL    |          |                                         |                          |            | 0                       |                            |
| 210623              | TANK, AUXILIARY ENVIRONMENTAL CONTROL SYSTEM VOLUME  |        |          |                                         |                          |            |                         | F2                         |
| 21.440              | 131358-1                                             | MOS    |          |                                         |                          |            | 11-FEB-1982             |                            |
|                     | 311533                                               | HRSMSC | O/C      | 0                                       |                          |            | 0                       |                            |
|                     | REF: NO REF                                          | AFL    |          |                                         |                          |            | 0                       |                            |
| 210677              | TURBINE, COOLING                                     |        |          |                                         |                          |            |                         | F5                         |
| 21.290              | 572375-2                                             | MOS    |          |                                         |                          |            | 15-MAR-1995             |                            |
|                     | 56-133                                               | HRSMSC | O/C      | 0                                       |                          |            | 5585                    |                            |
|                     | REF: AMM 21-50-00                                    | AFL    |          |                                         |                          |            | 4260                    |                            |
| 210681              | CHANGE OIL                                           |        |          |                                         |                          |            |                         | F5                         |
| 21.290              | PKG 1, 2, 3                                          | MOS    |          |                                         |                          |            | 26-JUN-2001             |                            |
|                     |                                                      | HRSMSC | 200      |                                         |                          |            | 7687                    |                            |
|                     | REF: AMM 21-50-00                                    | AFL    |          |                                         |                          |            | 5594                    |                            |
| 210601              | UNIT, REFRIGERATION                                  |        |          |                                         |                          |            |                         | F5                         |
| 21.230              | 3783648-1                                            | MOS    |          |                                         |                          |            | 21-AUG-1983             |                            |
|                     | 120-333                                              | HRSMSC | O/C      | 0                                       |                          |            | 1200                    |                            |
|                     | REF: AMM 21-50-00                                    | AFL    |          |                                         |                          |            | 667                     |                            |
| 210616              | VALVE, 35 DEGREE TEMPERATURE CONTROL                 |        |          |                                         |                          |            |                         | F5                         |
| 21.260              | 898730-1                                             | MOS    |          |                                         |                          |            | 11-FEB-1982             |                            |
|                     | SN-UNKNOWN                                           | HRSMSC | O/C      | 0                                       |                          |            | 0                       |                            |
|                     | REF: AMM 21-50-00                                    | AFL    |          |                                         |                          |            | 0                       |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION |     |     |     |     | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|--------|----------|------------------------------|-----|-----|-----|-----|----------|-------------|-------------------------|----------------------------|
|                     |                                                      |        |          | TSN                          | TSO | TSR | TSI | ADJ |          |             |                         |                            |
| 210121              | VALVE, AIR CONDITIONING PRESSURE RELIEF              |        |          |                              |     |     |     |     |          |             |                         | F5                         |
| 21.060              | 3-783644-1                                           | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | 162                                                  | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 21-11-00                                    | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 210101              | VALVE, BLEED AIR SWITCHING LEFT                      |        |          |                              |     |     |     |     |          |             |                         | F5                         |
| 21.010              | 3783647-3                                            | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         | \$1698.                    |
|                     | P511                                                 | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 21-11-00                                    | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| + 210102            | VISUALLY INSPECT                                     |        |          |                              |     |     |     |     |          |             |                         | F5                         |
| 21.500              | PKG 2, 3                                             | MOS    |          |                              |     |     |     |     |          | 26-JUN-2001 |                         |                            |
|                     |                                                      | HRS/MS | 400      |                              |     |     |     |     |          | 7687        |                         |                            |
|                     | REF: AMM 5-20-05                                     | AFL    |          |                              |     |     |     |     |          | 5594        |                         |                            |
| 210111              | VALVE, BLEED AIR SWITCHING RIGHT                     |        |          |                              |     |     |     |     |          |             |                         | F5                         |
| 21.010              | 3783647-3                                            | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         | \$1698.                    |
|                     | P506                                                 | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 21-11-00                                    | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| + 210112            | VISUALLY INSPECT                                     |        |          |                              |     |     |     |     |          |             |                         | F5                         |
| 21.500              | PKG 2, 3                                             | MOS    |          |                              |     |     |     |     |          | 26-JUN-2001 |                         |                            |
|                     |                                                      | HRS/MS | 400      |                              |     |     |     |     |          | 7687        |                         |                            |
|                     | REF: AMM 5-20-05                                     | AFL    |          |                              |     |     |     |     |          | 5594        |                         |                            |
| 210146              | VALVE, CABIN AIR CHECK LEFT                          |        |          |                              |     |     |     |     |          |             |                         | F4                         |
| 21.130              | PN                                                   | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 21-20-00                                    | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 210151              | VALVE, CABIN AIR CHECK RIGHT                         |        |          |                              |     |     |     |     |          |             |                         | F4                         |
| 21.130              | PN                                                   | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 21-20-00                                    | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 210153              | VALVE, COLD AIR CHECK                                |        |          |                              |     |     |     |     |          |             |                         | F5                         |
| 21.370              | PN                                                   | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 21-20-00                                    | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 210166              | VALVE, CONDITION AIR PILOT                           |        |          |                              |     |     |     |     |          |             |                         | F3                         |
| 21.150              | PN                                                   | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 21-20-00                                    | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 210143              | VALVE, EMERGENCY AIR CHECK                           |        |          |                              |     |     |     |     |          |             |                         | F5                         |
| 21.470              | PN                                                   | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 210141              | VALVE, EMERGENCY AIR SHUTOFF                         |        |          |                              |     |     |     |     |          |             |                         | F5                         |
| 21.120              | 321760-2-1                                           | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         | \$1099.                    |
|                     | P1222                                                | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 21-14-00                                    | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |



Aircraft Model - 1124 WESTWIND

Report Date **11-APR-2002**

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION |     |     |     |     | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|--------|----------|------------------------------|-----|-----|-----|-----|-------------|-------------------------|----------------------------|
|                     |                                                      |        |          | TSN                          | TSO | TSR | TSI | ADJ |             |                         |                            |
| 210161              | VALVE, FLOOD DUCT                                    |        |          |                              |     |     |     |     |             |                         | F4                         |
| 21.140              | PN                                                   | MOS    |          |                              |     |     |     |     | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     | 0           |                         |                            |
|                     | REF: AMM 21-20-00                                    | AFL    |          |                              |     |     |     |     | 0           |                         |                            |
| 210136              | VALVE, GROUND BY-PASS                                |        |          |                              |     |     |     |     |             |                         | F5                         |
| 21.110              | 4-783622-1                                           | MOS    |          |                              |     |     |     |     | 11-FEB-1982 |                         | \$1099.                    |
|                     | P4380                                                | HRS/MS | O/C      | 0                            |     |     |     |     | 0           |                         |                            |
|                     | REF: AMM 21-13-00                                    | AFL    |          |                              |     |     |     |     | 0           |                         |                            |
| 210211              | REPLACE UPPER INLET AIR FILTER ELEMENT               |        |          |                              |     |     |     |     |             |                         | F3                         |
| 21.080              | PKG 3                                                | MOS    |          |                              |     |     |     |     | 26-JUL-2000 |                         |                            |
|                     |                                                      | HRS/MS | 800      |                              |     |     |     |     | 7325        |                         |                            |
|                     | REF: AMM 21-30-00                                    | AFL    |          |                              |     |     |     |     | 5360        |                         |                            |
| 210611              | VALVE, HOT AIR                                       |        |          |                              |     |     |     |     |             |                         | F5                         |
| 21.250              | 321760-2-1                                           | MOS    |          |                              |     |     |     |     | 11-FEB-1982 |                         | \$1099.                    |
|                     | P1108                                                | HRS/MS | O/C      | 0                            |     |     |     |     | 0           |                         |                            |
|                     | REF: AMM 21-60-00                                    | AFL    |          |                              |     |     |     |     | 0           |                         |                            |
| 210158              | VALVE, HOT AIR CHECK                                 |        |          |                              |     |     |     |     |             |                         | F4                         |
| 21.380              | PN                                                   | MOS    |          |                              |     |     |     |     | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     | 0           |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                              |     |     |     |     | 0           |                         |                            |
| 210226              | VALVE, ISOBARIC SHUTOFF                              |        |          |                              |     |     |     |     |             |                         | F3                         |
| 21.070              | 3-783105                                             | MOS    |          |                              |     |     |     |     | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     | 0           |                         |                            |
|                     | REF: AMM 21-30-00                                    | AFL    |          |                              |     |     |     |     | 0           |                         |                            |
| 210171              | VALVE, MANUAL DEFOG                                  |        |          |                              |     |     |     |     |             |                         | F3                         |
| 21.170              | PN                                                   | MOS    |          |                              |     |     |     |     | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     | 0           |                         |                            |
|                     | REF: AMM 21-20-00                                    | AFL    |          |                              |     |     |     |     | 0           |                         |                            |
| 210181              | VALVE, MANUAL DUMP                                   |        |          |                              |     |     |     |     |             |                         | F3                         |
| 21.190              | 5-723018-401                                         | MOS    |          |                              |     |     |     |     | 11-FEB-1982 |                         |                            |
|                     | 21563                                                | HRS/MS | O/C      | 0                            |     |     |     |     | 0           |                         |                            |
|                     | REF: AMM 21-30-00                                    | AFL    |          |                              |     |     |     |     | 0           |                         |                            |
| 210186              | VALVE, NORMAL OUTFLOW                                |        |          |                              |     |     |     |     |             |                         | F4                         |
| 21.040              | 130374-6                                             | MOS    |          |                              |     |     |     |     | 11-FEB-1982 |                         |                            |
|                     | 110870                                               | HRS/MS | O/C      | 0                            |     |     |     |     | 0           |                         |                            |
|                     | REF: AMM 21-30-00                                    | AFL    |          |                              |     |     |     |     | 0           |                         |                            |
| 210256              | VALVE, PRESSURE SOLENOID LOWER                       |        |          |                              |     |     |     |     |             |                         | F3                         |
| 21.220              | 3783686                                              | MOS    |          |                              |     |     |     |     | 11-FEB-1982 |                         |                            |
|                     | 175                                                  | HRS/MS | O/C      | 0                            |     |     |     |     | 0           |                         |                            |
|                     | REF: AMM 21-30-00                                    | AFL    |          |                              |     |     |     |     | 0           |                         |                            |
| 210251              | VALVE, PRESSURE SOLENOID UPPER                       |        |          |                              |     |     |     |     |             |                         | F3                         |
| 21.220              | 3783686                                              | MOS    |          |                              |     |     |     |     | 11-FEB-1982 |                         |                            |
|                     | 214                                                  | HRS/MS | O/C      | 0                            |     |     |     |     | 0           |                         |                            |
|                     | REF: AMM 21-30-00                                    | AFL    |          |                              |     |     |     |     | 0           |                         |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L



Aircraft Model - 1124 WESTWIND

Report Date **11-APR-2002**

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD              | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER                            | UNIT                 | INTERVAL | TIME-----AT-----INSTALLATION |     |              |     |     | Warr Exp | COMPLIANCE                  | DISPOSITION<br>NEXT DUE  | AREA<br>PRICE<br>LABOR HRS |
|----------------------------------|---------------------------------------------------------------------------------|----------------------|----------|------------------------------|-----|--------------|-----|-----|----------|-----------------------------|--------------------------|----------------------------|
|                                  |                                                                                 |                      |          | TSN                          | TSO | TSR          | TSI | ADJ |          |                             |                          |                            |
| 210131<br>21.100                 | VALVE, RAM AIR SHUTOFF<br>398712-1-1<br>P222<br>REF: AMM 21-12-00               | MOS<br>HRSMSC<br>AFL | O/C      | 0                            |     |              |     |     |          | 11-FEB-1982<br>0<br>0       |                          | F5                         |
| 210196<br>21.040                 | VALVE, SAFETY OUTFLOW<br>103278-8<br>11905<br>REF: AMM 21-30-00                 | MOS<br>HRSMSC<br>AFL | O/C      | 0                            |     |              |     |     |          | 11-FEB-1982<br>0<br>0       |                          | F4                         |
| 210261<br>21.160                 | VENTURI, AIRFLOW<br>131052-1<br>703075<br>REF: NO REF                           | MOS<br>HRSMSC<br>AFL | O/C      | 0                            |     |              |     |     |          | 11-FEB-1982<br>0<br>0       |                          | F3                         |
| 210266<br>21.090                 | INSPECT/CLEAN SCREEN<br><br>REF: NO REF                                         | MOS<br>HRSMSC<br>AFL | O/C      |                              |     |              |     |     |          | 11-FEB-1982<br>0<br>0       |                          | F3                         |
| <b>CHAPTER 22 AUTO FLIGHT</b>    |                                                                                 |                      |          |                              |     |              |     |     |          |                             |                          |                            |
| 220166<br>22.020                 | AMPLIFIER, NO.1 AUTOPILOT SERVO<br>622-3108-016<br>2120LNR<br>REF: AMM 22-10-03 | MOS<br>HRSMSC<br>AFL | O/C      |                              |     |              |     |     |          | 27-AUG-1996                 |                          | F3                         |
| 220156<br>22.050                 | COMPUTER, AUTO PILOT<br>522-2901-016<br>2198<br>REF: AMM 22-13-13               | MOS<br>HRSMSC<br>AFL | O/C      |                              |     | 4165<br>3382 |     |     |          | 15-FEB-1995<br>5554<br>4242 |                          | F3                         |
| 220163<br>22.040                 | COMPUTER, AUTOPILOT YAW DAMPER<br>622-3167-028<br>4078<br>REF: AMM 22-10-05     | MOS<br>HRSMSC<br>AFL | O/C      | 0                            |     |              |     |     |          | 11-FEB-1982<br>0<br>0       |                          | F3                         |
| 221021<br>22.030                 | CONTROLLER, AIR DATA NO. 1<br>590A-3J<br>SN-UNKNOWN<br>REF: AMM 22-10-04        | MOS<br>HRSMSC<br>AFL | O/C      | 0                            |     |              |     |     |          | 11-FEB-1982<br>0<br>0       |                          | F3                         |
| + 340146<br>34.050<br>ASSOCIATED | LEAK CHECK LEFT STATIC SYSTEM<br><br>REF: AMM 34-10-01                          | MOS<br>HRSMSC<br>AFL | 24       |                              |     |              |     |     |          | 18-JAN-2001<br>7494<br>5466 | MANDATORY<br>18-JAN-2003 | F1                         |
| + 340151<br>34.050<br>ASSOCIATED | LEAK CHECK RIGHT STATIC SYSTEM<br><br>REF: AMM 34-10-01                         | MOS<br>HRSMSC<br>AFL | 24       |                              |     |              |     |     |          | 18-JAN-2001<br>7494<br>5466 | MANDATORY<br>18-JAN-2003 | F1                         |
| 221031<br>22.030                 | CONTROLLER, AIR DATA NO. 2<br>590A-3J1<br>SN-UNKNOWN<br>REF: AMM 22-10-04       | MOS<br>HRSMSC<br>AFL | O/C      | 0                            |     |              |     |     |          | 11-FEB-1982<br>0<br>0       |                          | F3                         |



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD       | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----<br>TSN TSO TSR TSI ADJ | INSTALLATION | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------------|------------------------------------------------------|--------|----------|-----------------------------------------|--------------|----------|-------------|-------------------------|----------------------------|
| + 340146                  | LEAK CHECK LEFT STATIC SYSTEM                        |        |          |                                         |              |          |             | MANDATORY               | F1                         |
| 34.050                    |                                                      | MOS    | 24       |                                         |              |          | 18-JAN-2001 | 18-JAN-2003             |                            |
| ASSOCIATED                |                                                      | HRS/MS |          |                                         |              |          | 7494        |                         |                            |
|                           | REF: AMM 34-10-01                                    | AFL    |          |                                         |              |          | 5466        |                         |                            |
| + 340151                  | LEAK CHECK RIGHT STATIC SYSTEM                       |        |          |                                         |              |          |             | MANDATORY               | F1                         |
| 34.050                    |                                                      | MOS    | 24       |                                         |              |          | 18-JAN-2001 | 18-JAN-2003             |                            |
| ASSOCIATED                |                                                      | HRS/MS |          |                                         |              |          | 7494        |                         |                            |
|                           | REF: AMM 34-10-01                                    | AFL    |          |                                         |              |          | 5466        |                         |                            |
| 222001                    | CONTROLLER, ALTITUDE PRESELECT                       |        |          |                                         |              |          |             |                         | F3                         |
| 22.090                    | 622-2923-066                                         | MOS    |          |                                         |              |          | 11-FEB-1982 |                         |                            |
|                           | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                                       |              |          | 0           |                         |                            |
|                           | REF: NO REF                                          | AFL    |          | 0                                       |              |          | 0           |                         |                            |
| 220161                    | CONTROLLER, AUTOPILOT                                |        |          |                                         |              |          |             |                         | F3                         |
| 22.010                    | 792-6348-002                                         | MOS    |          |                                         |              |          | 11-FEB-1982 |                         |                            |
|                           | 2759                                                 | HRS/MS | O/C      | 0                                       |              |          | 0           |                         | 1                          |
|                           | REF: AMM 22-10-02                                    | AFL    |          |                                         |              |          | 0           |                         |                            |
| 220181                    | MOUNT, AUTOPILOT AILERON SERVO                       |        |          |                                         |              |          |             |                         | F5                         |
| 22.080                    | 792-6783-001                                         | MOS    |          |                                         |              |          | 11-FEB-1982 |                         |                            |
|                           | 1191                                                 | HRS/MS | O/C      | 0                                       |              |          | 0           |                         |                            |
|                           | REF:                                                 | AFL    |          |                                         |              |          | 0           |                         |                            |
| 220191                    | MOUNT, AUTOPILOT ELEVATOR SERVO                      |        |          |                                         |              |          |             |                         | F5                         |
| 22.080                    | 792-6783-001                                         | MOS    |          |                                         |              |          | 11-FEB-1982 |                         |                            |
|                           | 1160                                                 | HRS/MS | O/C      | 0                                       |              |          | 0           |                         |                            |
|                           | REF:                                                 | AFL    |          |                                         |              |          | 0           |                         |                            |
| 220201                    | MOUNT, AUTOPILOT RUDDER SERVO                        |        |          |                                         |              |          |             |                         | F5                         |
| 22.080                    | 792-6783-001                                         | MOS    |          |                                         |              |          | 11-FEB-1982 |                         |                            |
|                           | 1166                                                 | HRS/MS | O/C      | 0                                       |              |          | 0           |                         |                            |
|                           | REF:                                                 | AFL    |          |                                         |              |          | 0           |                         |                            |
| 220150                    | PANEL, AUTOPILOT                                     |        |          |                                         |              |          |             |                         | F3                         |
| 22.060                    | 622-0141-023                                         | MOS    |          |                                         |              |          | 11-FEB-1982 |                         |                            |
|                           | SN-UNKNOWN                                           | HRS/MS | O/C      |                                         |              |          | 0           |                         |                            |
|                           | REF: AMM 22-11-02                                    | AFL    |          |                                         |              |          | 0           |                         |                            |
| 220176                    | SERVO, AUTOPILOT AILERON                             |        |          |                                         |              |          |             |                         | F5                         |
| 22.070                    | 792-6781-001                                         | MOS    |          |                                         |              |          | 15-FEB-1995 |                         |                            |
|                           | 726                                                  | HRS/MS | O/C      | 5554                                    |              |          | 5554        |                         |                            |
|                           | REF: AMM 22-10-06(1124),22-11-07(1124A)              | AFL    |          | 4242                                    |              |          | 4242        |                         |                            |
| 220186                    | SERVO, AUTOPILOT ELEVATOR                            |        |          |                                         |              |          |             |                         | F5                         |
| 22.070                    | 792-6781-001                                         | MOS    |          |                                         |              |          | 15-FEB-1995 |                         |                            |
|                           | 791                                                  | HRS/MS | O/C      | 5554                                    |              |          | 5554        |                         |                            |
|                           | REF: AMM 22-10-06(1124),22-11-07(1124A)              | AFL    |          | 4242                                    |              |          | 4242        |                         |                            |
| 220196                    | SERVO, AUTOPILOT RUDDER                              |        |          |                                         |              |          |             |                         | F5                         |
| 22.070                    | 792-6781-001                                         | MOS    |          |                                         |              |          | 11-FEB-1982 |                         |                            |
|                           | 3915                                                 | HRS/MS | O/C      | 0                                       |              |          | 0           |                         |                            |
|                           | REF: AMM 22-10-06(1124),22-11-07(1124A)              | AFL    |          |                                         |              |          | 0           |                         |                            |
| CHAPTER 23 COMMUNICATIONS |                                                      |        |          |                                         |              |          |             |                         |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC  
A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|--------|----------|-----------------------------------------------------|----------|-------------|-------------------------|----------------------------|
| 230450U             | -- REPLACE BEACON BATTERY                            | MOS    |          |                                                     |          | 17-OCT-1998 | ?                       |                            |
|                     |                                                      | HRS/MS |          |                                                     |          | 6520        |                         |                            |
|                     |                                                      | AFL    |          |                                                     |          | 4889        |                         |                            |
| + 230218            | REF: INSPECT/CHECK STATIC DISCHARGE WICK RESISTANCE  |        |          |                                                     |          |             |                         | F1                         |
| 23.120              | PKG 2, 3                                             | MOS    |          |                                                     |          | 26-JUN-2001 |                         |                            |
|                     |                                                      | HRS/MS | 400      |                                                     |          | 7687        |                         |                            |
|                     | REF: AMM 23-60-00                                    | AFL    |          |                                                     |          | 5594        |                         |                            |
| 230166              | RENEW FCC RADIO/TELEPHONE LICENSE                    |        |          |                                                     |          |             |                         | F3                         |
| 23.100              |                                                      | MOS    | 60       |                                                     |          | 27-OCT-1999 | 27-OCT-2004             |                            |
|                     |                                                      | HRS/MS |          |                                                     |          | 6961        |                         |                            |
|                     | REF: See Workcard                                    | AFL    |          |                                                     |          | 5135        |                         |                            |
| 238004U             | -- INTERCOM, COPILOTS NAT LTD                        |        |          |                                                     |          |             |                         |                            |
|                     | AA80-020                                             | MOS    |          |                                                     |          | 15-APR-1993 |                         |                            |
|                     | 9688                                                 | HRS/MS | O/C      |                                                     |          | 5252        |                         |                            |
|                     | REF:                                                 | AFL    |          |                                                     |          | 3907        |                         |                            |
| 238006U             | -- INTERCOM, PILOTS NAT LTD.                         |        |          |                                                     |          |             |                         |                            |
|                     | AA80020                                              | MOS    |          |                                                     |          | 15-APR-1993 |                         |                            |
|                     | 9689                                                 | HRS/MS | O/C      | 0                                                   |          | 5252        |                         |                            |
|                     | REF:                                                 | AFL    |          |                                                     |          | 3907        |                         |                            |
| 230111              | AMPLIFIER, HF POWER                                  |        |          |                                                     |          |             |                         | F3                         |
| 23.030              | 622-2883-001                                         | MOS    |          |                                                     |          | 26-SEP-1995 |                         |                            |
|                     | 1033                                                 | HRS/MS | O/C      |                                                     |          | 5707        |                         |                            |
|                     | REF: AMM REF BELOW                                   | AFL    |          |                                                     |          | 4380        |                         |                            |
| 230156              | ANTENNA, RADIO/TELEPHONE                             |        |          |                                                     |          |             |                         | F1                         |
| 23.110              | 121-0011-000                                         | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                     | 3272                                                 | HRS/MS | O/C      | 0                                                   |          | 0           |                         |                            |
|                     | REF: AMM 23-21-00                                    | AFL    |          |                                                     |          | 0           |                         |                            |
| 230136              | ANTENNA, VHF BLADE                                   |        |          |                                                     |          |             |                         | F1                         |
| 23.070              | DMC-81-1                                             | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                     | 387                                                  | HRS/MS | O/C      | 0                                                   |          | 0           |                         |                            |
|                     | REF: AMM 23-20-00                                    | AFL    |          |                                                     |          | 0           |                         |                            |
| 230131              | ANTENNA, VHF FIN CAP                                 |        |          |                                                     |          |             |                         | F1                         |
| 23.060              | VFS-10-90-2                                          | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                     | 866                                                  | HRS/MS | O/C      | 0                                                   |          | 0           |                         | 5                          |
|                     | REF: AMM 23-20-00                                    | AFL    |          |                                                     |          | 0           |                         |                            |
| 230399              | BEACON, VOICE RECORDER                               |        |          |                                                     |          |             |                         | T1                         |
| 23.130              | DK-100                                               | MOS    |          |                                                     |          | 09-NOV-1996 |                         |                            |
|                     | DL4928                                               | HRS/MS | O/C      |                                                     |          | 5951        |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                                                     |          | 4589        |                         |                            |
| 230171              | CONTROL, COMMUNICATION 1                             |        |          |                                                     |          |             |                         | F3                         |
| 23.140              | 622-4523-011                                         | MOS    |          |                                                     |          | 09-JAN-1986 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                                                   |          | 2812        |                         |                            |
|                     | REF: NO REF                                          | AFL    |          | 0                                                   |          | 1743        |                         |                            |



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|--------|----------|-----------------------------------------------------|----------|-------------|-------------------------|----------------------------|
| 230181              | CONTROL, COMMUNICATION 2                             |        |          |                                                     |          |             |                         | F3                         |
| 23.140              | 622-4523-003                                         | MOS    |          |                                                     |          | 09-JAN-1986 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                                                   |          | 2812        |                         |                            |
|                     | REF: NO REF                                          | AFL    |          | 0                                                   |          | 1743        |                         |                            |
| 230196              | CONTROL, NO.1 AUDIO CENTER                           |        |          |                                                     |          |             |                         | F3                         |
| 23.150              | 522-3763-001                                         | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                     | 3747                                                 | HRS/MS | O/C      | 0                                                   |          | 0           |                         |                            |
|                     | REF: AMM 23-50-00                                    | AFL    |          |                                                     |          | 0           |                         |                            |
| 230201              | CONTROL, NO.2 AUDIO CENTER                           |        |          |                                                     |          |             |                         | F3                         |
| 23.150              | 522-3763-001                                         | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                     | 3749                                                 | HRS/MS | O/C      | 0                                                   |          | 0           |                         |                            |
|                     | REF: AMM 23-50-00                                    | AFL    |          |                                                     |          | 0           |                         |                            |
| 230116              | COUPLER, HF ANTENNA                                  |        |          |                                                     |          |             |                         | F3                         |
| 23.040              | 622-2884-001                                         | MOS    |          |                                                     |          | 16-AUG-1995 |                         |                            |
|                     | 2427                                                 | HRS/MS | O/C      | 5702                                                |          | 5702        |                         |                            |
|                     | REF: AMM REF BELOW                                   | AFL    |          | 4372                                                |          | 4372        |                         |                            |
| 230101              | PANEL, HF CONTROL                                    |        |          |                                                     |          |             |                         | F3                         |
| 23.010              | 622-4545-001                                         | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                                                   |          | 0           |                         |                            |
|                     | REF: AMM REF BELOW                                   | AFL    |          |                                                     |          | 0           |                         |                            |
| 230106              | RECEIVER/EXCITER, HF                                 |        |          |                                                     |          |             |                         | F3                         |
| 23.020              | 622-5337-001                                         | MOS    |          |                                                     |          | 26-SEP-1995 |                         |                            |
|                     | 1554                                                 | HRS/MS | O/C      |                                                     |          | 5707        |                         |                            |
|                     | REF: AMM REF BELOW                                   | AFL    |          |                                                     |          | 4380        |                         |                            |
| 230151              | RECEIVER/TRANSMITTER, RADIO/TELEPHONE                |        |          |                                                     |          |             |                         | F3                         |
| 23.100              | 400-0033-000                                         | MOS    |          |                                                     |          | 29-JUL-1994 |                         |                            |
|                     | 603                                                  | HRS/MS | O/C      |                                                     |          | 5472        |                         |                            |
|                     | REF: AMM 23-21-00                                    | AFL    |          |                                                     |          | 4150        |                         |                            |
| 230206              | RECORDER, COCKPIT VOICE                              |        |          |                                                     |          |             |                         | T1                         |
| 23.130              | 89094-003111                                         | MOS    |          |                                                     |          | 16-AUG-1995 |                         |                            |
|                     | A01001                                               | HRS/MS | O/C      |                                                     |          | 5702        |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                                                     |          | 4372        |                         |                            |
| 230400              | CLEAN/TEST BEACON                                    |        |          |                                                     |          |             |                         | T1                         |
| 23.130              |                                                      | MOS    | 6        |                                                     |          | 06-NOV-2001 | 06-MAY-2002             |                            |
|                     |                                                      | HRS/MS |          |                                                     |          | 7774        |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                                                     |          | 5641        |                         |                            |
| 230207              | REPLACE BATTERY                                      |        |          |                                                     |          |             |                         | T1                         |
| 23.130              |                                                      | MOS    |          |                                                     |          | 17-OCT-1998 | ?                       |                            |
|                     |                                                      | HRS/MS |          |                                                     |          | 6520        |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                                                     |          | 4889        |                         |                            |
| 230121              | TRANSCIVER, VHF NO. 1                                |        |          |                                                     |          |             |                         | F3                         |
| 23.050              | 622-1334-002                                         | MOS    |          |                                                     |          | 24-JUN-1991 |                         |                            |
|                     | 4589                                                 | HRS/MS | O/C      | 0                                                   |          | 4880        |                         |                            |
|                     | REF: AMM 23-20-00                                    | AFL    |          |                                                     |          | 3495        |                         |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L



Aircraft Model - 1124 WESTWIND  
 Owner Name - R&S AIRCRAFT INVESTMENTS, LLC  
 A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

| ITEM NO<br>WORKCARD                | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|------------------------------------|------------------------------------------------------|--------|----------|-----------------------------------------------------|----------|-------------|-------------------------|----------------------------|
| 230126                             | TRANSCIVER, VHF NO. 2                                |        |          |                                                     |          |             |                         | F3                         |
| 23.050                             | 622-1879-002                                         | MOS    |          | 0                                                   |          | 28-MAY-1991 |                         |                            |
|                                    | 16718                                                | HRS/MS | O/C      | 0                                                   |          | 4877        |                         |                            |
|                                    | REF: AMM 23-20-00                                    | AFL    |          | 0                                                   |          | 3493        |                         |                            |
| 230146                             | UNIT, RADIO/TELEPHONE CABIN                          |        |          |                                                     |          |             |                         | F4                         |
| 23.090                             | 400-0030-004                                         | MOS    |          |                                                     |          | 06-FEB-1989 |                         |                            |
|                                    | 77790                                                | HRS/MS | O/C      | 0                                                   |          | 4149        |                         |                            |
|                                    | REF: AMM 23-21-00                                    | AFL    |          |                                                     |          | 2658        |                         |                            |
| 230141                             | UNIT, RADIO/TELEPHONE COCKPIT                        |        |          |                                                     |          |             |                         | F3                         |
| 23.080                             | 400-0032-002                                         | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                                    | 2506                                                 | HRS/MS | O/C      | 0                                                   |          | 0           |                         |                            |
|                                    | REF: AMM 23-21-00                                    | AFL    |          |                                                     |          | 0           |                         |                            |
| 230191                             | UNIT, UHF COMMUNICATION REMOTE DISPLAY               |        |          |                                                     |          |             |                         | F3                         |
| 23.140                             | 622-1945-011                                         | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                                    | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                                                   |          | 0           |                         |                            |
|                                    | REF: NO REF                                          | AFL    |          | 0                                                   |          | 0           |                         |                            |
| <b>CHAPTER 24 ELECTRICAL POWER</b> |                                                      |        |          |                                                     |          |             |                         |                            |
| + 241653                           | CHECK CIRCUIT BREAKER RESISTANCE/INSPECT BUS         |        |          |                                                     |          |             |                         | F3                         |
| 24.140                             | PKG 3                                                | MOS    |          |                                                     |          | 26-JUL-2000 |                         |                            |
|                                    |                                                      | HRS/MS | 800      |                                                     |          | 7325        |                         |                            |
|                                    | REF: AMM 24-50-00                                    | AFL    |          |                                                     |          | 5360        |                         |                            |
| + 241655                           | INSPECT DISTRIBUTION BUS CIRCUIT BREAKER             |        |          |                                                     |          |             |                         | F3                         |
| 24.150                             | PKG 3                                                | MOS    |          |                                                     |          | 26-JUL-2000 |                         |                            |
|                                    |                                                      | HRS/MS | 800      |                                                     |          | 7325        |                         |                            |
|                                    | REF: AMM 24-50-00                                    | AFL    |          |                                                     |          | 5360        |                         |                            |
| + 241657                           | INSPECT TEST PRIORITY BUS DIODES                     |        |          |                                                     |          |             |                         | F3                         |
| 24.160                             | PKG 3                                                | MOS    |          |                                                     |          | 26-JUL-2000 |                         |                            |
|                                    |                                                      | HRS/MS | 800      |                                                     |          | 7325        |                         |                            |
|                                    | REF: AMM 24-50-00                                    | AFL    |          |                                                     |          | 5360        |                         |                            |
| 240156                             | BATTERY, LEFT                                        |        |          |                                                     |          |             |                         | F2                         |
| 24.030                             | 4833517-1                                            | MOS    |          |                                                     |          | 09-NOV-1996 |                         | \$2100.                    |
|                                    | 8812674                                              | HRS/MS | O/C      |                                                     |          | 5951        |                         | 1                          |
|                                    | REF: AMM 24-30-00                                    | AFL    |          |                                                     |          | 4589        |                         |                            |
| 240168                             | ANALYZE                                              |        |          |                                                     |          |             |                         | F2                         |
| 24.030                             |                                                      | MOS    |          |                                                     |          | 09-NOV-1996 |                         |                            |
|                                    |                                                      | HRS/MS | C/C      |                                                     |          | 5951        |                         |                            |
|                                    | REF: NO REF                                          | AFL    |          |                                                     |          | 4589        |                         |                            |
| + 240161                           | CHECK ELECTROLYTE LEVEL                              |        |          |                                                     |          |             |                         | F2                         |
| 24.030                             | PKG 1, 2, 3                                          | MOS    |          |                                                     |          | 26-JUN-2001 |                         |                            |
|                                    |                                                      | HRS/MS | 200      |                                                     |          | 7687        |                         | 1                          |
|                                    | REF: AMM 12-10-06                                    | AFL    |          |                                                     |          | 5594        |                         |                            |
| 240166                             | DEEP CYCLE                                           |        |          |                                                     |          |             |                         | F2                         |
| 24.030                             | PKG 1, 2, 3                                          | MOS    |          |                                                     |          | 06-NOV-2001 |                         |                            |
|                                    |                                                      | HRS/MS | 200      |                                                     |          | 7774        |                         | 2                          |
|                                    | REF: AMM 12-10-06                                    | AFL    |          |                                                     |          | 5641        |                         |                            |



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION |     |     |     |     | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|--------|----------|------------------------------|-----|-----|-----|-----|-------------|-------------------------|----------------------------|
|                     |                                                      |        |          | TSN                          | TSO | TSR | TSI | ADJ |             |                         |                            |
| 240171              | BATTERY, RIGHT                                       |        |          |                              |     |     |     |     |             |                         | F2                         |
| 24.020              | 4833517-1                                            | MOS    |          |                              |     |     |     |     | 09-NOV-1996 |                         | \$2100.                    |
|                     | 8506152                                              | HRS/MS | O/C      |                              |     |     |     |     | 5951        |                         | 1                          |
|                     | REF: AMM 24-30-00                                    | AFL    |          |                              |     |     |     |     | 4589        |                         |                            |
| 240184              | ANALYZE                                              |        |          |                              |     |     |     |     |             |                         | F2                         |
| 24.020              |                                                      | MOS    |          |                              |     |     |     |     | 09-NOV-1996 |                         |                            |
|                     |                                                      | HRS/MS | C/C      |                              |     |     |     |     | 5951        |                         |                            |
|                     |                                                      | AFL    |          |                              |     |     |     |     | 4589        |                         |                            |
| + 240176            | CHECK ELECTROLYTE LEVEL                              |        |          |                              |     |     |     |     |             |                         | F2                         |
| 24.020              | PKG 1, 2, 3                                          | MOS    |          |                              |     |     |     |     | 26-JUN-2001 |                         |                            |
|                     |                                                      | HRS/MS | 200      |                              |     |     |     |     | 7687        |                         | 1                          |
|                     |                                                      | AFL    |          |                              |     |     |     |     | 5594        |                         |                            |
|                     | REF: AMM 12-10-06                                    |        |          |                              |     |     |     |     |             |                         |                            |
| 240181              | DEEP CYCLE                                           |        |          |                              |     |     |     |     |             |                         | F2                         |
| 24.020              | PKG 1, 2, 3                                          | MOS    |          |                              |     |     |     |     | 06-NOV-2001 |                         |                            |
|                     |                                                      | HRS/MS | 200      |                              |     |     |     |     | 7774        |                         | 2                          |
|                     |                                                      | AFL    |          |                              |     |     |     |     | 5641        |                         |                            |
|                     | REF: AMM 12-10-06                                    |        |          |                              |     |     |     |     |             |                         |                            |
| 240111              | BLOWER, INVERTER COOLING                             |        |          |                              |     |     |     |     |             |                         | F2                         |
| 24.100              | M125J-9A1                                            | MOS    |          |                              |     |     |     |     | 11-FEB-1982 |                         |                            |
|                     | 200                                                  | HRS/MS | O/C      |                              |     |     |     |     | 0           |                         |                            |
|                     | REF: AMM 24-20-00                                    | AFL    |          |                              |     |     |     |     | 0           |                         |                            |
| 240136              | BOX, D.C. CONTACTOR LEFT                             |        |          |                              |     |     |     |     |             |                         | F5                         |
| 24.050              | PN                                                   | MOS    |          |                              |     |     |     |     | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      |                              |     |     |     |     | 0           |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                              |     |     |     |     | 0           |                         |                            |
| 240141              | BOX, D.C. CONTACTOR RIGHT                            |        |          |                              |     |     |     |     |             |                         | F5                         |
| 24.050              | PN                                                   | MOS    |          |                              |     |     |     |     | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      |                              |     |     |     |     | 0           |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                              |     |     |     |     | 0           |                         |                            |
| 240146              | CONTROL UNIT, GENERATOR NO. 1                        |        |          |                              |     |     |     |     |             |                         | F5                         |
| 24.040              | 5833515-1                                            | MOS    |          |                              |     |     |     |     | 30-NOV-1989 |                         |                            |
|                     | 6681927M1                                            | HRS/MS | O/C      |                              |     |     |     |     | 4430        |                         | 1                          |
|                     | REF: AMM 24-30-00                                    | AFL    |          |                              |     |     |     |     | 2987        |                         |                            |
| 240151              | CONTROL UNIT, GENERATOR NO. 2                        |        |          |                              |     |     |     |     |             |                         | F5                         |
| 24.040              | 5833515-1                                            | MOS    |          |                              |     |     |     |     | 01-MAY-1990 |                         |                            |
|                     | 663958M1                                             | HRS/MS | O/C      |                              |     |     |     |     | 4578        |                         | 1                          |
|                     | REF: AMM 24-30-00                                    | AFL    |          |                              |     |     |     |     | 3154        |                         |                            |
| 240116              | GENERATOR, STARTER NO. 1                             |        |          |                              |     |     |     |     |             | OVERHAUL                | E1                         |
| 24.010              | 23065-018-1                                          | MOS    |          |                              |     |     |     |     | 06-NOV-2001 |                         | \$813.                     |
|                     | 3684                                                 | HRS/MS | 1000     |                              |     |     |     |     | 7774        | ?                       | 1                          |
|                     | REF: AMM 80-10-00                                    | AFL    |          |                              |     |     |     |     | 5641        |                         |                            |
| + 240121            | CHECK BRUSH WEAR/TENSION                             |        |          |                              |     |     |     |     |             |                         | E1                         |
| 24.010              | PKG 4                                                | MOS    |          |                              |     |     |     |     | 06-NOV-2001 |                         |                            |
|                     |                                                      | HRS/MS | 150      |                              |     |     |     |     | 7774        |                         | .5                         |
|                     | REF: See Workcard                                    | AFL    |          |                              |     |     |     |     | 5641        |                         |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER     | UNIT                 | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE                  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|----------------------------------------------------------|----------------------|----------|-----------------------------------------------------|----------|-----------------------------|-------------------------|----------------------------|
| + 240118<br>24.170  | INSPECT<br>PKG 4                                         | MOS<br>HRSMSC<br>AFL | 150      |                                                     |          | 06-NOV-2001<br>7774<br>5641 |                         | E1                         |
|                     | REF: AMM 5-21-00                                         |                      |          |                                                     |          |                             |                         |                            |
| + 240123<br>24.010  | INSPECT SPLINE<br>PKG 4                                  | MOS<br>HRSMSC<br>AFL | 150      |                                                     |          | 06-NOV-2001<br>7774<br>5641 |                         | E1                         |
|                     | REF: AMM                                                 |                      |          |                                                     |          |                             |                         |                            |
| 240126<br>24.010    | GENERATOR, STARTER NO. 2<br>23065-018-1                  | MOS<br>HRSMSC<br>AFL | 1000     |                                                     |          | 06-NOV-2001<br>7774<br>5641 | OVERHAUL<br>?           | E2<br>\$813.<br>1          |
|                     | 2562<br>REF: AMM 80-10-00                                |                      |          |                                                     |          |                             |                         |                            |
| + 240131<br>24.010  | CHECK BRUSH WEAR/TENSION<br>PKG 5                        | MOS<br>HRSMSC<br>AFL | 150      |                                                     |          | 06-NOV-2001<br>7774<br>5641 |                         | E2                         |
|                     | REF: See Workcard                                        |                      |          |                                                     |          |                             |                         |                            |
| + 240128<br>24.170  | INSPECT<br>PKG 5                                         | MOS<br>HRSMSC<br>AFL | 150      |                                                     |          | 06-NOV-2001<br>7774<br>5641 |                         | E2                         |
|                     | REF: AMM 5-21-00                                         |                      |          |                                                     |          |                             |                         |                            |
| + 240133<br>24.010  | INSPECT SPLINE<br>PKG 5                                  | MOS<br>HRSMSC<br>AFL | 150      |                                                     |          | 06-NOV-2001<br>7774<br>5641 |                         | E2<br>1                    |
|                     | REF: AMM 80-10-00                                        |                      |          |                                                     |          |                             |                         |                            |
| 240196<br>24.050    | INDICATOR, BATTERY TEMPERATURE<br>4883754-501            | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | F3                         |
|                     | 1955<br>REF: NO REF                                      |                      |          |                                                     |          |                             |                         |                            |
| 240101<br>24.080    | INVERTER, NO. 1<br>6833508-501                           | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 12-JUL-1989<br>4305<br>2845 |                         | F2<br>\$1150.<br>1         |
|                     | C0253094<br>REF: AMM 24-20-00                            |                      |          |                                                     |          |                             |                         |                            |
| 240108<br>24.080    | INVERTER, NO. 2<br>6833508-501                           | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 09-DEC-1985<br>2762<br>1713 |                         | F2<br>\$1150.<br>1         |
|                     | 1135<br>REF: AMM 24-20-00                                |                      |          |                                                     |          |                             |                         |                            |
| 241651<br>24.120    | METER, VOLT/AMP<br>6883091-513                           | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         |                            |
|                     | SN-UNKNOWN<br>REF: NO REF                                |                      |          |                                                     |          |                             |                         |                            |
| 241601<br>24.130    | POWER SUPPLY, VHF EMERGENCY COMMUNICATION<br>501-1015-02 | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         |                            |
|                     | SN-UNKNOWN<br>REF: NO REF                                |                      |          |                                                     |          |                             |                         |                            |



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO                                 | WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER      | UNIT      | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE   | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|-----------------------------------------|----------|-----------------------------------------------------------|-----------|----------|-----------------------------------------------------|----------|--------------|-------------------------|----------------------------|
| 241606                                  | 24.130   | INSPECT BATTERY                                           | MOS       |          |                                                     |          |              | 11-OCT-1990             |                            |
|                                         |          | REF: NO REF                                               | HRS/MSAFL | O/C      |                                                     |          | 4718<br>3309 |                         |                            |
| 240211                                  | 24.060   | RECEPTACLE, EXTERNAL POWER                                | MOS       |          |                                                     |          |              | 11-FEB-1982             | F1                         |
|                                         |          | PN                                                        | HRS/MSAFL | O/C      | 0                                                   |          | 0<br>0       |                         |                            |
| + 240203                                | 24.070   | FUNCTIONALLY CHECK BATTERY TEMPERATURE AND WARNING SYSTEM | MOS       |          |                                                     |          |              | 26-JUN-2001             | F3                         |
|                                         |          | PKG 1, 2, 3                                               | HRS/MSAFL | 200      |                                                     |          | 7687<br>5594 |                         |                            |
| 240186                                  | 24.030   | THERMISTOR, BATTERY LEFT                                  | MOS       |          |                                                     |          |              | 11-JAN-1989             | F2                         |
|                                         |          | PN                                                        | HRS/MSAFL | O/C      | 0                                                   |          | 4127<br>2632 |                         |                            |
| 240191                                  | 24.020   | THERMISTOR, BATTERY RIGHT                                 | MOS       |          |                                                     |          |              | 11-JAN-1989             | F2                         |
|                                         |          | PN                                                        | HRS/MSAFL | O/C      | 0                                                   |          | 4127<br>2632 |                         |                            |
| 240103                                  |          | VOLTMETER, AC LEFT                                        | MOS       |          |                                                     |          |              | 11-FEB-1982             | F3                         |
|                                         |          | 3883035-501                                               | HRS/MSAFL | O/C      | 0                                                   |          | 0<br>0       |                         |                            |
| 240108                                  | 24.090   | VOLTMETER, AC RIGHT                                       | MOS       |          |                                                     |          |              | 11-FEB-1982             | F3                         |
|                                         |          | 3883035-501                                               | HRS/MSAFL | O/C      | 0                                                   |          | 0<br>0       |                         |                            |
| 240143                                  | 24.110   | VOLTMETER, DC LEFT                                        | MOS       |          |                                                     |          |              | 11-FEB-1982             | F3                         |
|                                         |          | 6883091-505                                               | HRS/MSAFL | O/C      | 0                                                   |          | 0<br>0       |                         |                            |
| 240148                                  | 24.110   | VOLTMETER, DC RIGHT                                       | MOS       |          |                                                     |          |              | 25-FEB-1994             | F3                         |
|                                         |          | 6883091-505                                               | HRS/MSAFL | O/C      | 0                                                   |          | 5408<br>4066 |                         |                            |
| <b>CHAPTER 25 EQUIPMENT/FURNISHINGS</b> |          |                                                           |           |          |                                                     |          |              |                         |                            |
| + 250162                                | 25.050   | INSPECT FIRST AID KIT                                     | MOS       | 12       |                                                     |          |              | 06-NOV-2001 06-NOV-2002 | F4                         |
|                                         |          | REF: NO REF                                               | HRS/MSAFL |          |                                                     |          | 7774<br>5641 |                         |                            |
| + 250156                                | 25.050   | INSPECT LIFE PRESERVERS                                   | MOS       | 12       |                                                     |          |              | 06-NOV-2001 06-NOV-2002 | F4                         |
|                                         |          | REF: NO REF                                               | HRS/MSAFL |          |                                                     |          | 7774<br>5641 |                         |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL



Aircraft Model - 1124 WESTWIND

Report Date **11-APR-2002**

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION |     |     |     |     | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|--------|----------|------------------------------|-----|-----|-----|-----|----------|-------------|-------------------------|----------------------------|
|                     |                                                      |        |          | TSN                          | TSO | TSR | TSI | ADJ |          |             |                         |                            |
| 250141              | DISPLAY, CABIN INFORMATION                           |        |          |                              |     |     |     |     |          |             |                         | F4                         |
| 25.040              | 32940-004                                            | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 250146              | OPERATIONAL CHECK                                    |        |          |                              |     |     |     |     |          |             |                         | F4                         |
| 25.040              |                                                      | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     |                                                      | HRS/MS | O/C      |                              |     |     |     |     |          | 0           |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 250116              | INERTIA REEL, COPILOT                                |        |          |                              |     |     |     |     |          |             |                         | F3                         |
| 25.020              | PN                                                   | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 250111              | INERTIA REEL, PILOT                                  |        |          |                              |     |     |     |     |          |             |                         | F3                         |
| 25.020              | PN                                                   | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 250106              | SEAT, COPILOT                                        |        |          |                              |     |     |     |     |          |             |                         | F3                         |
| 25.010              | 1024-0                                               | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 25-10-01                                    | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 250101              | SEAT, PILOT                                          |        |          |                              |     |     |     |     |          |             |                         | F3                         |
| 25.010              | 1025-0                                               | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 25-10-01                                    | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 250131              | SEATBELT, COPILOT                                    |        |          |                              |     |     |     |     |          |             |                         | F3                         |
| 25.030              | PN                                                   | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 250121              | SEATBELT, PILOT                                      |        |          |                              |     |     |     |     |          |             |                         | F3                         |
| 25.030              | PN                                                   | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 250166              | TRANSMITTER, EMERGENCY LOCATOR                       |        |          |                              |     |     |     |     |          |             |                         | F4                         |
| 25.060              | 607690-2                                             | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| <b>CHAPTER 26</b>   | <b>FIRE PROTECTION</b>                               |        |          |                              |     |     |     |     |          |             |                         |                            |
| + 260186            | OPERATIONAL CHECK FIRE PROTECTION SYSTEM             |        |          |                              |     |     |     |     |          |             |                         | F3                         |
| 26.020              | PKG 2, 3                                             | MOS    |          |                              |     |     |     |     |          | 26-JUN-2001 |                         |                            |
|                     |                                                      | HRS/MS | 400      |                              |     |     |     |     |          | 7687        |                         |                            |
|                     | REF: AMM 26-00-00                                    | AFL    |          |                              |     |     |     |     |          | 5594        |                         |                            |
| + 260148            | REPLACE LEFT FIRE EXTINGUISHER NO.1 CARTRIDGE        |        |          |                              |     |     |     |     |          |             | SCRAP                   | F5                         |
| 26.010              |                                                      | MOS    | 48       |                              |     |     |     |     |          | 17-JAN-2001 | 17-JAN-2005             |                            |
|                     |                                                      | HRS/MS |          |                              |     |     |     |     |          |             |                         |                            |
|                     | REF: AMM 26-20-00                                    | AFL    |          |                              |     |     |     |     |          |             |                         |                            |



Aircraft Model - 1124 WESTWIND

Report Date **11-APR-2002**

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO | WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER           | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------|----------|----------------------------------------------------------------|--------|----------|-----------------------------------------------------|----------|-------------|-------------------------|----------------------------|
| +       | 260153   | REPLACE LEFT FIRE EXTINGUISHER NO.2 CARTRIDGE                  |        |          |                                                     |          |             | SCRAP                   | F5                         |
|         | 26.010   |                                                                | MOS    | 48       |                                                     |          | 17-JAN-2001 | 17-JAN-2005             |                            |
|         |          |                                                                | HRS/MS |          |                                                     |          |             |                         |                            |
|         |          | REF: AMM 26-20-00                                              | AFL    |          |                                                     |          |             |                         |                            |
| +       | 260158   | REPLACE RIGHT FIRE EXTINGUISHER NO.1 CARTRIDGE                 |        |          |                                                     |          |             | SCRAP                   | F5                         |
|         | 26.015   |                                                                | MOS    | 48       |                                                     |          | 17-JAN-2001 | 17-JAN-2005             |                            |
|         |          |                                                                | HRS/MS |          |                                                     |          |             |                         |                            |
|         |          | REF: AMM 26-20-00                                              | AFL    |          |                                                     |          |             |                         |                            |
| +       | 260163   | REPLACE RIGHT FIRE EXTINGUISHER NO.2 CARTRIDGE                 |        |          |                                                     |          |             | SCRAP                   | F5                         |
|         | 26.015   |                                                                | MOS    | 48       |                                                     |          | 17-JAN-2001 | 17-JAN-2005             |                            |
|         |          |                                                                | HRS/MS |          |                                                     |          |             |                         |                            |
|         |          | REF: AMM 26-20-00                                              | AFL    |          |                                                     |          |             |                         |                            |
| 260176  |          | EXTINGUISHER, CABIN PORTABLE                                   |        |          |                                                     |          |             |                         | F4                         |
|         | 26.030   | MODEL 2-10                                                     | MOS    |          | 13                                                  |          | 21-JAN-1989 |                         |                            |
|         |          | U-329516                                                       | HRS/MS | O/C      | 0                                                   |          | 4131        |                         |                            |
|         |          | REF: AMM 5-10-00                                               | AFL    |          |                                                     |          | 2636        |                         |                            |
| 260182  |          | DISCHARGE /VALVE OVERHAUL AND REFILL CABIN FIRE EXINGUISHER    |        |          |                                                     |          |             |                         | F3                         |
|         | 26.030   |                                                                | MOS    | 72       |                                                     |          | 06-NOV-2001 | 06-NOV-2007             |                            |
|         |          |                                                                | HRS/MS |          |                                                     |          | 7774        |                         |                            |
|         |          | REF: MSC SIL 1124-25-059R1                                     | AFL    |          |                                                     |          | 5641        |                         |                            |
| 260183  |          | HYDROSTATIC TEST CABIN FIRE EXTINGUISHER                       |        |          |                                                     |          |             |                         | F4                         |
|         | 26.030   |                                                                | MOS    | 144      |                                                     |          | 01-JAN-1995 | 01-JAN-2007             |                            |
|         |          |                                                                | HRS/MS |          |                                                     |          |             |                         |                            |
|         |          | REF: See Workcard                                              | AFL    |          |                                                     |          |             |                         |                            |
| +       | 260184   | INSPECT CABIN FIRE EXTINGUISHER                                |        |          |                                                     |          |             |                         | F4                         |
|         | 26.030   | PKG 1, 2, 3                                                    | MOS    |          |                                                     |          | 26-JUN-2001 |                         |                            |
|         |          |                                                                | HRS/MS | 200      |                                                     |          | 7687        |                         |                            |
|         |          | REF: AMM 26-20-00                                              | AFL    |          |                                                     |          | 5594        |                         |                            |
| +       | 260180   | VISUAL INSPECTION CABIN FIRE EXTINGUISHER                      |        |          |                                                     |          |             |                         | F3                         |
|         | 26.060   |                                                                | DAYS   | 30       |                                                     |          | 06-NOV-2001 | 06-DEC-2001             |                            |
|         |          |                                                                | HRS/MS |          |                                                     |          | 7774        |                         |                            |
|         |          | REF: NO REF                                                    | AFL    |          |                                                     |          | 5641        |                         |                            |
| 260181  |          | WEIGHT CHECK CABIN FIRE EXTINGUISHER                           |        |          |                                                     |          |             |                         | F4                         |
|         | 26.030   |                                                                | MOS    | 12       |                                                     |          | 26-JUN-2001 | 26-JUN-2002             |                            |
|         |          |                                                                | HRS/MS |          |                                                     |          | 7687        |                         |                            |
|         |          | REF: AMM 5-10-00                                               | AFL    |          |                                                     |          | 5594        |                         |                            |
| 260166  |          | EXTINGUISHER, COCKPIT PORTABLE                                 |        |          |                                                     |          |             |                         | F3                         |
|         | 26.030   | MODEL 2-10                                                     | MOS    |          | 13                                                  |          | 21-JAN-1989 |                         |                            |
|         |          | U-329659                                                       | HRS/MS | O/C      | 0                                                   |          | 4131        |                         |                            |
|         |          | REF: AMM 5-10-00                                               | AFL    |          |                                                     |          | 2636        |                         |                            |
| 260172  |          | DISCHARGE /VALVE OVERHAUL AND REFILL COCKPIT FIRE EXTINGUISHER |        |          |                                                     |          |             |                         | F3                         |
|         | 26.030   |                                                                | MOS    | 72       |                                                     |          | 06-NOV-2001 | 06-NOV-2007             |                            |
|         |          |                                                                | HRS/MS |          |                                                     |          | 7774        |                         |                            |
|         |          | REF: MSC SIL 1124-25-059R1                                     | AFL    |          |                                                     |          | 5641        |                         |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L



Aircraft Model - 1124 WESTWIND

Report Date **11-APR-2002**

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD              | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT          | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE   | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|----------------------------------|------------------------------------------------------|---------------|----------|-----------------------------------------------------|----------|--------------|-------------------------|----------------------------|
| 260173<br>26.030                 | HYDROSTATIC TEST COCKPIT FIRE EXTINGUISHER           | MOS           | 144      |                                                     |          | 01-JAN-1995  | 01-JAN-2007             | F3                         |
|                                  | REF: MSC SIL 1124-25-059R1                           | HRS/MS<br>AFL |          |                                                     |          |              |                         |                            |
| + 260174<br>26.030               | INSPECT COCKPIT FIRE EXTINGUISHER<br>PKG 1, 2, 3     | MOS           | 200      |                                                     |          | 26-JUN-2001  |                         | F3                         |
|                                  | REF: AMM 26-20-00                                    | HRS/MS<br>AFL |          |                                                     |          | 7687<br>5594 |                         |                            |
| + 260169<br>26.060               | VISUAL INSPECTION COCKPIT FIRE EXTINGUISHER          | MOS           | 30       |                                                     |          | 06-NOV-2001  | 06-DEC-2001             | F3                         |
|                                  | REF: NO REF                                          | HRS/MS<br>AFL |          |                                                     |          | 7774<br>5641 |                         |                            |
| 260171<br>26.030                 | WEIGHT CHECK COCKPIT FIRE EXTINGUISHER               | MOS           | 12       |                                                     |          | 26-JUN-2001  | 26-JUN-2002             | F3                         |
|                                  | REF: AMM 5-10-00                                     | HRS/MS<br>AFL |          |                                                     |          | 7687<br>5594 |                         |                            |
| 260111<br>26.010                 | EXTINGUISHER, FIRE LEFT<br>3643507-1                 | MOS           | O/C      | 0                                                   |          | 11-FEB-1982  |                         | F5<br>\$795.               |
|                                  | 02447C1                                              | HRS/MS<br>AFL |          |                                                     |          | 0<br>0       |                         |                            |
|                                  | REF: AMM 26-20-00                                    |               |          |                                                     |          |              |                         |                            |
| 260121<br>26.010                 | HYDROSTATIC TEST                                     | MOS           | 60       |                                                     |          | 06-NOV-2001  | 06-NOV-2006             | F5                         |
|                                  | REF: AMM 5-10-00                                     | HRS/MS<br>AFL |          |                                                     |          | 7774<br>5641 |                         |                            |
| + 260146<br>26.010               | RECORD DATE STAMPED ON NEW CARTRIDGE (SERVICE LIFE)  | MOS           | 72       |                                                     |          | 17-JAN-2001  | 17-JAN-2007             | F5                         |
|                                  | REF: AMM 26-20-00                                    | HRS/MS<br>AFL |          |                                                     |          |              |                         |                            |
| + 260151<br>26.010               | RECORD DATE STAMPED ON NEW CARTRIDGE (SERVICE LIFE)  | MOS           | 72       |                                                     |          | 17-JAN-2001  | 17-JAN-2007             | F5                         |
|                                  | REF: AMM 26-20-00                                    | HRS/MS<br>AFL |          |                                                     |          |              |                         |                            |
| + 260148<br>26.010<br>ASSOCIATED | REPLACE LEFT FIRE EXTINGUISHER NO.1 CARTRIDGE        | MOS           | 48       |                                                     |          | 17-JAN-2001  | 17-JAN-2005             | F5                         |
|                                  | REF: AMM 26-20-00                                    | HRS/MS<br>AFL |          |                                                     |          |              |                         |                            |
| + 260153<br>26.010<br>ASSOCIATED | REPLACE LEFT FIRE EXTINGUISHER NO.2 CARTRIDGE        | MOS           | 48       |                                                     |          | 17-JAN-2001  | 17-JAN-2005             | F5                         |
|                                  | REF: AMM 26-20-00                                    | HRS/MS<br>AFL |          |                                                     |          |              |                         |                            |
| 260116<br>26.010                 | WEIGHT CHECK                                         | MOS           | O/C      |                                                     |          | 17-JAN-2001  |                         | F5                         |
|                                  | REF: See Workcard                                    | HRS/MS<br>AFL |          |                                                     |          | 7494<br>5466 |                         |                            |



Aircraft Model - 1124 WESTWIND

Report Date **11-APR-2002**

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO           | WORKCARD   | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|-------------------|------------|------------------------------------------------------|--------|----------|-----------------------------------------|----------|-------------|-------------------------|----------------------------|
| 260126            |            | EXTINGUISHER, FIRE RIGHT                             |        |          |                                         |          |             |                         | F5                         |
|                   | 26.015     | 23700004                                             | MOS    |          |                                         |          | 10-JAN-1994 |                         | \$795.                     |
|                   |            | 02429C1                                              | HRS/MS | O/C      | 0                                       |          | 5382        |                         |                            |
|                   |            | REF: AMM 26-20-00                                    | AFL    |          |                                         |          | 4036        |                         |                            |
| 260136            |            | HYDROSTATIC TEST                                     |        |          |                                         |          |             | MANDATORY               | F5                         |
|                   | 26.015     |                                                      | MOS    | 60       |                                         |          | 07-APR-1999 | 07-APR-2004             |                            |
|                   |            |                                                      | HRS/MS |          |                                         |          | 6727        |                         |                            |
|                   |            | REF: AMM 5-10-00                                     | AFL    |          |                                         |          | 4999        |                         |                            |
| + 260156          |            | RECORD DATE STAMPED ON NEW CARTRIDGE (SERVICE LIFE)  |        |          |                                         |          |             | LIFE LIMIT              | F5                         |
|                   | 26.015     |                                                      | MOS    | 72       |                                         |          | 17-JAN-2001 | 17-JAN-2007             |                            |
|                   |            |                                                      | HRS/MS |          |                                         |          |             |                         |                            |
|                   |            | REF: AMM 26-20-00                                    | AFL    |          |                                         |          |             |                         |                            |
| + 260161          |            | RECORD DATE STAMPED ON NEW CARTRIDGE (SERVICE LIFE)  |        |          |                                         |          |             | LIFE LIMIT              | F5                         |
|                   | 26.015     |                                                      | MOS    | 72       |                                         |          | 17-JAN-2001 | 17-JAN-2007             |                            |
|                   |            |                                                      | HRS/MS |          |                                         |          |             |                         |                            |
|                   |            | REF: AMM 26-20-00                                    | AFL    |          |                                         |          |             |                         |                            |
| + 260158          |            | REPLACE RIGHT FIRE EXTINGUISHER NO.1 CARTRIDGE       |        |          |                                         |          |             | SCRAP                   | F5                         |
|                   | 26.015     |                                                      | MOS    | 48       |                                         |          | 17-JAN-2001 | 17-JAN-2005             |                            |
|                   | ASSOCIATED |                                                      | HRS/MS |          |                                         |          |             |                         |                            |
|                   |            | REF: AMM 26-20-00                                    | AFL    |          |                                         |          |             |                         |                            |
| + 260163          |            | REPLACE RIGHT FIRE EXTINGUISHER NO.2 CARTRIDGE       |        |          |                                         |          |             | SCRAP                   | F5                         |
|                   | 26.015     |                                                      | MOS    | 48       |                                         |          | 17-JAN-2001 | 17-JAN-2005             |                            |
|                   | ASSOCIATED |                                                      | HRS/MS |          |                                         |          |             |                         |                            |
|                   |            | REF: AMM 26-20-00                                    | AFL    |          |                                         |          |             |                         |                            |
| 260131            |            | WEIGHT CHECK                                         |        |          |                                         |          |             |                         | F5                         |
|                   | 26.015     |                                                      | MOS    |          |                                         |          | 17-JAN-2001 |                         |                            |
|                   |            |                                                      | HRS/MS | O/C      |                                         |          | 7494        |                         |                            |
|                   |            | REF: See Workcard                                    | AFL    |          |                                         |          | 5466        |                         |                            |
| 260101            |            | FIRE DETECTOR, LEFT                                  |        |          |                                         |          |             |                         | E1                         |
|                   | 26.040     | 4643506-3                                            | MOS    |          |                                         |          | 11-FEB-1982 |                         |                            |
|                   |            | 19491                                                | HRS/MS | O/C      | 0                                       |          | 0           |                         |                            |
|                   |            | REF: AMM 26-10-00                                    | AFL    |          |                                         |          | 0           |                         |                            |
| 260106            |            | FIRE DETECTOR, RIGHT                                 |        |          |                                         |          |             |                         | E2                         |
|                   | 26.040     | 4643506-3                                            | MOS    |          |                                         |          | 11-FEB-1982 |                         |                            |
|                   |            | 19503                                                | HRS/MS | O/C      | 0                                       |          | 0           |                         |                            |
|                   |            | REF: AMM 26-10-00                                    | AFL    |          |                                         |          | 0           |                         |                            |
| 260141            |            | INDICATOR, EXTINGUISHER DISCHARGE                    |        |          |                                         |          |             |                         | F5                         |
|                   | 26.050     | PN                                                   | MOS    |          |                                         |          | 11-FEB-1982 |                         |                            |
|                   |            | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                                       |          | 0           |                         |                            |
|                   |            | REF: NO REF                                          | AFL    |          |                                         |          | 0           |                         |                            |
| <b>CHAPTER 27</b> |            | <b>FLIGHT CONTROLS</b>                               |        |          |                                         |          |             |                         |                            |
| + 270271          |            | ADJUST/TEST FLAP COMPARATOR                          |        |          |                                         |          |             |                         | F3                         |
|                   | 27.430     | PKG 3                                                | MOS    |          |                                         |          | 26-JUL-2000 |                         |                            |
|                   |            |                                                      | HRS/MS | 800      |                                         |          | 7325        |                         |                            |
|                   |            | REF: AMM 27-50-00                                    | AFL    |          |                                         |          | 5360        |                         |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER                   | UNIT                 | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE                  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------------------------|----------------------|----------|-----------------------------------------------------|----------|-----------------------------|-------------------------|----------------------------|
| + 270140<br>27.070  | CHECK AILERON CONTROL SYSTEM FREEPLAY<br>PKG 3                         | MOS<br>HRS/MS<br>AFL | 800      |                                                     |          | 26-JUL-2000<br>7325<br>5360 |                         | F5                         |
|                     | REF: AMM 27-10-00                                                      |                      |          |                                                     |          |                             |                         |                            |
| + 270341<br>27.440  | CHECK CABLE TENSION AFT FUSELAGE<br>PKG 2, 3                           | MOS<br>HRS/MS<br>AFL | 400      |                                                     |          | 26-JUN-2001<br>7687<br>5594 |                         | F5                         |
|                     | REF: AMM 27-00-00                                                      |                      |          |                                                     |          |                             |                         |                            |
| + 270340<br>27.440  | CHECK CABLE TENSION FLIGHT/PASSENGER COMPARTMENT<br>PKG 3              | MOS<br>HRS/MS<br>AFL | 800      |                                                     |          | 26-JUL-2000<br>7325<br>5360 |                         | F3                         |
|                     | REF: AMM 27-00-00                                                      |                      |          |                                                     |          |                             |                         |                            |
| + 270280<br>27.230  | CLEAN/INSPECT/LUBRICATE LEFT INBOARD/OUTBOARD FLEXIBLE SHAFT<br>PKG 3  | MOS<br>HRS/MS<br>AFL | 1200     |                                                     |          | 16-FEB-2001<br>7551<br>5515 | 8751                    | W1                         |
|                     | REF: AMM 27-50-00                                                      |                      |          |                                                     |          |                             |                         |                            |
| + 270285<br>27.230  | CLEAN/INSPECT/LUBRICATE RIGHT INBOARD/OUTBOARD FLEXIBLE SHAFT<br>PKG 3 | MOS<br>HRS/MS<br>AFL | 1200     |                                                     |          | 16-FEB-2001<br>7551<br>5515 | 8751                    | W2                         |
|                     | REF: AMM 27-50-00                                                      |                      |          |                                                     |          |                             |                         |                            |
| + 270248<br>27.200  | FUNCTIONAL CHECK FLAP TIME EXCEED RELAY<br>PKG 2, 3                    | MOS<br>HRS/MS<br>AFL | 400      |                                                     |          | 26-JUN-2001<br>7687<br>5594 |                         | F3                         |
|                     | REF: AMM 27-50-00                                                      |                      |          |                                                     |          |                             |                         |                            |
| + 270211<br>27.500  | INSPECT SCISSORS/ASSEMBLY<br>PKG 2, 3                                  | MOS<br>HRS/MS<br>AFL | 400      |                                                     |          | 26-JUN-2001<br>7687<br>5594 |                         | T1                         |
|                     | REF: See Workcard                                                      |                      |          |                                                     |          |                             |                         |                            |
| + 270351<br>27.380  | INSPECT/LUBRICATE PRESSURE SEALS<br>PKG 3                              | MOS<br>HRS/MS<br>AFL | 800      |                                                     |          | 26-JUL-2000<br>7325<br>5360 |                         | F4                         |
|                     | REF: AMM 12-20-00                                                      |                      |          |                                                     |          |                             |                         |                            |
| 270214<br>27.195    | LUBRICATE AFT HINGE FITTING BEARINGS<br>PKG 1, 2, 3                    | MOS<br>HRS/MS<br>AFL | 200      |                                                     |          | 26-JUN-2001<br>7687<br>5594 |                         | T1                         |
|                     | REF: NO REF                                                            |                      |          |                                                     |          |                             |                         |                            |
| 270179<br>27.350    | LUBRICATE CONTROL COLUMNS<br>PKG 3                                     | MOS<br>HRS/MS<br>AFL | 800      |                                                     |          | 26-JUL-2000<br>7325<br>5360 |                         | F3                         |
|                     | REF: AMM 12-20-00                                                      |                      |          |                                                     |          |                             |                         |                            |
| 270213<br>27.190    | LUBRICATE ELEVATOR ATTACH POINTS<br>PKG 1, 2, 3                        | MOS<br>HRS/MS<br>AFL | 200      |                                                     |          | 26-JUN-2001<br>7687<br>5594 |                         | T1                         |
|                     | REF: AMM 12-20-00                                                      |                      |          |                                                     |          |                             |                         |                            |



Aircraft Model - 1124 WESTWIND  
 Owner Name - R&S AIRCRAFT INVESTMENTS, LLC  
 A/C Serial #: 368 A/C Reg. #: N368MD

Report Date **11-APR-2002**

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|--------|----------|-----------------------------------------------------|----------|-------------|-------------------------|----------------------------|
| 270346              | LUBRICATE FLIGHT CONTROL FORWARD/AFT BELLCRANKS      |        |          |                                                     |          |             |                         | F4                         |
| 27.360              | PKG 3                                                | MOS    |          |                                                     |          | 26-JUL-2000 |                         |                            |
|                     | REF: AMM 12-20-00                                    | HRS/MS | 800      |                                                     |          | 7325        |                         |                            |
|                     |                                                      | AFL    |          |                                                     |          | 5360        |                         |                            |
| 270215              | LUBRICATE FORWARD SCISSOR ASSEMBLY                   |        |          |                                                     |          |             |                         | T1                         |
| 27.195              | PKG 1, 2, 3                                          | MOS    |          |                                                     |          | 26-JUN-2001 |                         |                            |
|                     | REF: NO REF                                          | HRS/MS | 200      |                                                     |          | 7687        |                         |                            |
|                     |                                                      | AFL    |          |                                                     |          | 5594        |                         |                            |
| 270356              | LUBRICATE GUST LOCK                                  |        |          |                                                     |          |             |                         | F3                         |
| 27.370              | PKG 3                                                | MOS    |          |                                                     |          | 26-JUL-2000 |                         |                            |
|                     | REF: AMM 12-20-00                                    | HRS/MS | 800      |                                                     |          | 7325        |                         |                            |
|                     |                                                      | AFL    |          |                                                     |          | 5360        |                         |                            |
| 270176              | LUBRICATE RUDDER PEDAL ARMS                          |        |          |                                                     |          |             |                         | F3                         |
| 27.340              | PKG 3                                                | MOS    |          |                                                     |          | 26-JUL-2000 |                         |                            |
|                     | REF: AMM 12-20-00                                    | HRS/MS | 800      |                                                     |          | 7325        |                         |                            |
|                     |                                                      | AFL    |          |                                                     |          | 5360        |                         |                            |
| + 270335            | OPERATIONAL CHECK SPEED BRAKES AND LIFT DUMPERS      |        |          |                                                     |          |             |                         | F2                         |
| 27.280              | PKG 1, 2, 3                                          | MOS    |          |                                                     |          | 26-JUN-2001 |                         |                            |
|                     | REF: AMM 27-60-00                                    | HRS/MS | 200      |                                                     |          | 7687        |                         |                            |
|                     |                                                      | AFL    |          |                                                     |          | 5594        |                         |                            |
| 270145              | STATIC FRICTION TEST AILERON AND RUDDER              |        |          |                                                     |          |             |                         |                            |
| 27.045              | PKG 3                                                | MOS    |          |                                                     |          | 26-JUL-2000 |                         |                            |
|                     | REF: AMM 27-00-00                                    | HRS/MS | 800      |                                                     |          | 7325        |                         |                            |
|                     |                                                      | AFL    |          |                                                     |          | 5360        |                         |                            |
| 270210              | VISUAL INSPECT ELEVATOR CONTROL BELLCRANK ASSEMBLY   |        |          |                                                     |          |             |                         |                            |
| 27.570              |                                                      | MOS    | 60       |                                                     |          | 16-JUN-1997 | 16-JUN-2002             |                            |
|                     | REF: AMM 5-10-00                                     | HRS/MS | 5000     |                                                     |          | 6135        | 11135                   |                            |
|                     |                                                      | AFL    |          |                                                     |          | 4707        |                         |                            |
| 270331              | ACCUMULATOR, LIFT DUMPER RIGHT WING INBOARD          |        |          |                                                     |          |             |                         | W2                         |
| 27.320              | 3-713515-501                                         | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                                                   |          | 0           |                         |                            |
|                     | REF: AMM 27-60-00                                    | AFL    |          |                                                     |          | 0           |                         |                            |
| 270116              | ACTUATOR, AILERON TRIM TAB                           |        |          |                                                     |          |             |                         | W1                         |
| 27.060              | 5793500-1                                            | MOS    |          |                                                     |          | 09-NOV-1996 |                         |                            |
|                     | 1010                                                 | HRS/MS | O/C      |                                                     |          | 5951        |                         |                            |
|                     | REF: AMM 27-10-00                                    | AFL    |          |                                                     |          | 4589        |                         |                            |
| 270251              | ACTUATOR, FLAP LEFT INBOARD                          |        |          |                                                     |          |             | LIFE LIMIT              | W1                         |
| 27.210              | 1390T100-5                                           | MOS    |          |                                                     |          | 16-JUN-1997 |                         | \$1006.                    |
|                     | 610A                                                 | HRS/MS | 10000    |                                                     |          | 6135        | ?                       | 8                          |
|                     | REF: AMM 27-50-00                                    | AFL    |          |                                                     |          | 4707        |                         |                            |
| 270256              | ACTUATOR, FLAP LEFT OUTBOARD                         |        |          |                                                     |          |             | OVERHAUL                | W1                         |
| 27.220              | 1391T100-7                                           | MOS    |          |                                                     |          | 06-APR-1998 |                         | \$1046.                    |
|                     | 519A                                                 | HRS/MS | 10000    | 0                                                   |          | 6346        | 16346                   |                            |
|                     | REF: AMM 27-50-00                                    | AFL    |          |                                                     |          | 4787        |                         |                            |

? - Insufficient Information  
 + Task exists in FAA Manual  
 4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER                                         | UNIT                 | INTERVAL | TIME-----AT-----<br>TSN TSO TSR TSI ADJ | INSTALLATION | Warr Exp | COMPLIANCE                  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|----------------------------------------------------------------------------------------------|----------------------|----------|-----------------------------------------|--------------|----------|-----------------------------|-------------------------|----------------------------|
| 270261<br>27.210    | ACTUATOR, FLAP RIGHT INBOARD<br>193544-1<br>749A<br>REF: AMM 27-50-00                        | MOS<br>HRSMSC<br>AFL | 10000    | 0                                       |              |          | 15-JUL-1986<br>3201<br>1972 | OVERHAUL<br>13201       | W2<br>\$1006.<br>8         |
| 270266<br>27.220    | ACTUATOR, FLAP RIGHT OUTBOARD<br>193544-502<br>120<br>REF: AMM 27-50-00                      | MOS<br>HRSMSC<br>AFL | 10000    | 0                                       |              |          | 22-OCT-1982<br>482          | LIFE LIMIT<br>10482     | W2<br>\$1046.              |
| 270216<br>27.170    | ACTUATOR, HORIZONTAL STABILIZER TRIM<br>21164-005<br>0481-11AA<br>REF: AMM 27-40-00          | MOS<br>HRSMSC<br>AFL | 2500     | 0                                       |              |          | 06-APR-1998<br>6346<br>4787 | OVERHAUL<br>7287        | T1<br>\$4158.              |
| + 270217<br>27.170  | INSPECT<br>PKG 2, 3<br><br>REF: See Workcard                                                 | MOS<br>HRSMSC<br>AFL | 400      |                                         |              |          | 26-JUN-2001<br>7687<br>5594 |                         | T1                         |
| 270328<br>27.310    | ACTUATOR, LIFT DUMPER LEFT WING INBOARD<br>3-713515-501<br>SN-UNKNOWN<br>REF: AMM 27-60-00   | MOS<br>HRSMSC<br>AFL | O/C      | 0                                       |              |          | 11-FEB-1982<br>0<br>0       |                         | W1                         |
| 270326<br>27.310    | ACTUATOR, LIFT DUMPER LEFT WING OUTBOARD<br>3-713515-501<br>SN-UNKNOWN<br>REF: AMM 27-60-00  | MOS<br>HRSMSC<br>AFL | O/C      | 0                                       |              |          | 11-FEB-1982<br>0<br>0       |                         | W1                         |
| 270333<br>27.320    | ACTUATOR, LIFT DUMPER RIGHT WING OUTBOARD<br>3-713515-501<br>SN-UNKNOWN<br>REF: AMM 27-60-00 | MOS<br>HRSMSC<br>AFL | O/C      | 0                                       |              |          | 11-FEB-1982<br>0<br>0       |                         | W2                         |
| 270166<br>27.090    | ACTUATOR, LOWER RUDDER TRIM<br>5793500-501<br>3219<br>REF: AMM 27-20-00                      | MOS<br>HRSMSC<br>AFL | O/C      | 0                                       |              |          | 11-FEB-1982<br>0<br>0       |                         | T1<br>\$1000.<br>16        |
| 270301<br>27.260    | ACTUATOR, SPEED BRAKE LEFT<br>3713515-503<br>1L-466P<br>REF: AMM 27-60-00                    | MOS<br>HRSMSC<br>AFL | O/C      | 0                                       |              |          | 11-FEB-1982<br>0<br>0       |                         | W1                         |
| 270306<br>27.260    | ACTUATOR, SPEED BRAKE RIGHT<br>3713515-503<br>1L-470P<br>REF: AMM 27-60-00                   | MOS<br>HRSMSC<br>AFL | O/C      | 0                                       |              |          | 11-FEB-1982<br>0<br>0       |                         | W2                         |
| 270161<br>27.090    | ACTUATOR, UPPER RUDDER TRIM<br>5793500-503<br>5220<br>REF: AMM 27-20-00                      | MOS<br>HRSMSC<br>AFL | O/C      | 0                                       |              |          | 11-FEB-1982<br>0<br>0       |                         | T1<br>\$1000.<br>16        |



Aircraft Model- 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD            | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER                                                                                                                                                                                           | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|--------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|----------|-----------------------------------------------------|----------|-------------|-------------------------|----------------------------|
| 270101                         | AILERON, LEFT                                                                                                                                                                                                                                  |        |          |                                                     |          |             |                         | W1                         |
| 27.010                         | 5183003-407-2                                                                                                                                                                                                                                  | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                                | 4376                                                                                                                                                                                                                                           | HRS/MS | O/C      | 0                                                   |          | 0           |                         |                            |
|                                | REF: AMM 27-10-00                                                                                                                                                                                                                              | AFL    |          |                                                     |          | 0           |                         |                            |
| + 270140                       | CHECK AILERON CONTROL SYSTEM FREEPLAY                                                                                                                                                                                                          |        |          |                                                     |          |             |                         | F5                         |
| 27.070                         | PKG 3                                                                                                                                                                                                                                          | MOS    |          |                                                     |          | 26-JUL-2000 |                         |                            |
| ASSOCIATED                     |                                                                                                                                                                                                                                                | HRS/MS | 800      |                                                     |          | 7325        |                         |                            |
|                                | REF: AMM 27-10-00                                                                                                                                                                                                                              | AFL    |          |                                                     |          | 5360        |                         |                            |
| + 270264                       | CLEAN/CHECK LEFT GUIDE ROLLERS                                                                                                                                                                                                                 |        |          |                                                     |          |             |                         | W1                         |
| 27.550                         | PKG 2, 3                                                                                                                                                                                                                                       | MOS    |          |                                                     |          | 26-JUN-2001 |                         |                            |
|                                |                                                                                                                                                                                                                                                | HRS/MS | 400      |                                                     |          | 7687        |                         |                            |
|                                | REF: AMM 5-20-03                                                                                                                                                                                                                               | AFL    |          |                                                     |          | 5594        |                         |                            |
| SB 1124-27-100 R2 L/H<br>RODS  | FLIGHT CONTROLS SERVICE BULLETIN                                                                                                                                                                                                               |        |          |                                                     |          |             |                         | W1                         |
|                                |                                                                                                                                                                                                                                                | MOS    |          |                                                     |          |             |                         |                            |
| ASSOCIATED                     |                                                                                                                                                                                                                                                | HRS/MS | A/R      |                                                     |          | 0           |                         |                            |
|                                | REF: BULLETINS                                                                                                                                                                                                                                 | AFL    |          |                                                     |          | 0           |                         |                            |
|                                | Method of Compliance: OPEN                                                                                                                                                                                                                     |        |          |                                                     |          |             |                         |                            |
| SB 1124-27-129 LEFT<br>AILERON | FLIGHT CONTROLS SERVICE BULLETIN                                                                                                                                                                                                               |        |          |                                                     |          |             |                         | W1                         |
|                                |                                                                                                                                                                                                                                                | MOS    |          |                                                     |          | 26-JUL-2000 |                         |                            |
| ASSOCIATED                     |                                                                                                                                                                                                                                                | HRS/MS | 600      |                                                     |          | 7325        | 7925                    |                            |
|                                | REF: BULLETINS                                                                                                                                                                                                                                 | AFL    |          |                                                     |          | 5360        |                         |                            |
|                                | Method of Compliance: OPEN                                                                                                                                                                                                                     |        |          |                                                     |          |             |                         |                            |
| + 570106                       | INSPECT BELLCRANK                                                                                                                                                                                                                              |        |          |                                                     |          |             |                         | W1                         |
| 57.020                         | PKG 1, 2, 3                                                                                                                                                                                                                                    | MOS    |          |                                                     |          | 26-JUN-2001 |                         |                            |
|                                |                                                                                                                                                                                                                                                | HRS/MS | 200      |                                                     |          | 7687        |                         |                            |
|                                | REF: AMM 5-20-03                                                                                                                                                                                                                               | AFL    |          |                                                     |          | 5594        |                         |                            |
| + 270262                       | INSPECT LEFT EXTERNAL PUSH-PULL TUBE                                                                                                                                                                                                           |        |          |                                                     |          |             |                         | W1                         |
| 27.540                         | PKG 2, 3                                                                                                                                                                                                                                       | MOS    |          |                                                     |          | 26-JUN-2001 |                         |                            |
|                                |                                                                                                                                                                                                                                                | HRS/MS | 400      |                                                     |          | 7687        |                         |                            |
|                                | REF: AMM 5-20-03                                                                                                                                                                                                                               | AFL    |          |                                                     |          | 5594        |                         |                            |
| AD 1996-24-11 LEFT<br>AILERON  | TO PREVENT EXCESSIVE WEAR OF THE AILERON PUSH-PULL TUBE, WHICH COULD RESULT IN UNEVEN MOVEMENT OF THE CONTROL WHEEL,<br>PERFORATION OF THE AILERON PUSH-PULL TUBE, AND CONSEQUENT REDUCED ROLL CONTROL OF THE AIRPLANE AIRWORTHINESS DIRECTIVE |        |          |                                                     |          |             |                         | W1                         |
|                                |                                                                                                                                                                                                                                                | MOS    |          |                                                     |          | 26-JUL-2000 |                         |                            |
| ASSOCIATED                     |                                                                                                                                                                                                                                                | HRS/MS | 600      |                                                     |          | 7325        | 7925                    |                            |
|                                | REF: AD                                                                                                                                                                                                                                        | AFL    |          |                                                     |          | 5360        |                         |                            |
|                                | Method of Compliance: OPEN                                                                                                                                                                                                                     |        |          |                                                     |          |             |                         |                            |
| AD 1992-12-02 LEFT<br>AILERON  | TO PREVENT REDUCED CONTROLLABILITY OF THE AIRPLANE AIRWORTHINESS DIRECTIVE                                                                                                                                                                     |        |          |                                                     |          |             |                         | W1                         |
|                                |                                                                                                                                                                                                                                                | MOS    |          |                                                     |          |             |                         |                            |
| ASSOCIATED                     |                                                                                                                                                                                                                                                | HRS/MS | 150      |                                                     |          | 0           |                         |                            |
|                                | REF: AD                                                                                                                                                                                                                                        | AFL    |          |                                                     |          | 0           |                         |                            |
|                                | Method of Compliance: OPEN                                                                                                                                                                                                                     |        |          |                                                     |          |             |                         |                            |
| 270106                         | AILERON, RIGHT                                                                                                                                                                                                                                 |        |          |                                                     |          |             |                         | W2                         |
| 27.010                         | 5183003-406-2                                                                                                                                                                                                                                  | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                                | 4376                                                                                                                                                                                                                                           | HRS/MS | O/C      | 0                                                   |          | 0           |                         |                            |
|                                | REF: AMM 27-10-00                                                                                                                                                                                                                              | AFL    |          |                                                     |          | 0           |                         |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD             | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER                                                                                                                                                                                           | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|----------|-----------------------------------------------------|----------|-------------|-------------------------|----------------------------|
| + 270140                        | CHECK AILERON CONTROL SYSTEM FREEPLAY                                                                                                                                                                                                          |        |          |                                                     |          |             |                         | F5                         |
| 27.070                          | PKG 3                                                                                                                                                                                                                                          | MOS    |          |                                                     |          | 26-JUL-2000 |                         |                            |
| ASSOCIATED                      |                                                                                                                                                                                                                                                | HRSMSC | 800      |                                                     |          | 7325        |                         |                            |
|                                 | REF: AMM 27-10-00                                                                                                                                                                                                                              | AFL    |          |                                                     |          | 5360        |                         |                            |
| + 270265                        | CLEAN/CHECK RIGHT GUIDE ROLLERS                                                                                                                                                                                                                |        |          |                                                     |          |             |                         | W2                         |
| 27.550                          | PKG 2, 3                                                                                                                                                                                                                                       | MOS    |          |                                                     |          | 26-JUN-2001 |                         |                            |
|                                 |                                                                                                                                                                                                                                                | HRSMSC | 400      |                                                     |          | 7687        |                         |                            |
|                                 | REF: AMM 5-20-03                                                                                                                                                                                                                               | AFL    |          |                                                     |          | 5594        |                         |                            |
| SB 1124-27-100 R2 R/H<br>RODS   | FLIGHT CONTROLS SERVICE BULLETIN                                                                                                                                                                                                               |        |          |                                                     |          |             |                         | W2                         |
|                                 |                                                                                                                                                                                                                                                | MOS    |          |                                                     |          |             |                         |                            |
| ASSOCIATED                      |                                                                                                                                                                                                                                                | HRSMSC | A/R      |                                                     |          | 0           |                         |                            |
|                                 | REF: BULLETINS                                                                                                                                                                                                                                 | AFL    |          |                                                     |          | 0           |                         |                            |
|                                 | Method of Compliance: OPEN                                                                                                                                                                                                                     |        |          |                                                     |          |             |                         |                            |
| SB 1124-27-129 RIGHT<br>AILERON | FLIGHT CONTROLS SERVICE BULLETIN                                                                                                                                                                                                               |        |          |                                                     |          |             |                         | W2                         |
|                                 |                                                                                                                                                                                                                                                | MOS    |          |                                                     |          | 26-JUL-2000 |                         |                            |
| ASSOCIATED                      |                                                                                                                                                                                                                                                | HRSMSC | 600      |                                                     |          | 7325        | 7925                    |                            |
|                                 | REF: BULLETINS                                                                                                                                                                                                                                 | AFL    |          |                                                     |          | 5360        |                         |                            |
|                                 | Method of Compliance: OPEN                                                                                                                                                                                                                     |        |          |                                                     |          |             |                         |                            |
| + 270263                        | INSPECT RIGHT EXTERNAL PUSH-PULL TUBE                                                                                                                                                                                                          |        |          |                                                     |          |             |                         | W2                         |
| 27.540                          | PKG 2, 3                                                                                                                                                                                                                                       | MOS    |          |                                                     |          | 26-JUN-2001 |                         |                            |
|                                 |                                                                                                                                                                                                                                                | HRSMSC | 400      |                                                     |          | 7687        |                         |                            |
|                                 | REF: AMM 5-20-03                                                                                                                                                                                                                               | AFL    |          |                                                     |          | 5594        |                         |                            |
| AD 1996-24-11 RIGHT<br>AILERON  | TO PREVENT EXCESSIVE WEAR OF THE AILERON PUSH-PULL TUBE, WHICH COULD RESULT IN UNEVEN MOVEMENT OF THE CONTROL WHEEL,<br>PERFORATION OF THE AILERON PUSH-PULL TUBE, AND CONSEQUENT REDUCED ROLL CONTROL OF THE AIRPLANE AIRWORTHINESS DIRECTIVE |        |          |                                                     |          |             |                         | W2                         |
|                                 |                                                                                                                                                                                                                                                | MOS    |          |                                                     |          | 26-JUL-2000 |                         |                            |
| ASSOCIATED                      |                                                                                                                                                                                                                                                | HRSMSC | 600      |                                                     |          | 7325        | 7925                    |                            |
|                                 | REF: AD                                                                                                                                                                                                                                        | AFL    |          |                                                     |          | 5360        |                         |                            |
|                                 | Method of Compliance: OPEN                                                                                                                                                                                                                     |        |          |                                                     |          |             |                         |                            |
| AD 1992-12-02 RIGHT<br>AILERON  | TO PREVENT REDUCED CONTROLLABILITY OF THE AIRPLANE AIRWORTHINESS DIRECTIVE                                                                                                                                                                     |        |          |                                                     |          |             |                         | W2                         |
|                                 |                                                                                                                                                                                                                                                | MOS    |          |                                                     |          |             |                         |                            |
| ASSOCIATED                      |                                                                                                                                                                                                                                                | HRSMSC | 150      |                                                     |          | 0           |                         |                            |
|                                 | REF: AD                                                                                                                                                                                                                                        | AFL    |          |                                                     |          | 0           |                         |                            |
|                                 | Method of Compliance: OPEN                                                                                                                                                                                                                     |        |          |                                                     |          |             |                         |                            |
| 270291                          | BRAKE, SPEED LEFT                                                                                                                                                                                                                              |        |          |                                                     |          |             |                         | W1                         |
| 27.250                          | 5-203007-507                                                                                                                                                                                                                                   | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                                 | SN-UNKNOWN                                                                                                                                                                                                                                     | HRSMSC | O/C      | 0                                                   |          | 0           |                         |                            |
|                                 | REF: AMM 27-60-00                                                                                                                                                                                                                              | AFL    |          |                                                     |          | 0           |                         |                            |
| + 270335                        | OPERATIONAL CHECK SPEED BRAKES AND LIFT DUMPERS                                                                                                                                                                                                |        |          |                                                     |          |             |                         | F2                         |
| 27.280                          | PKG 1, 2, 3                                                                                                                                                                                                                                    | MOS    |          |                                                     |          | 26-JUN-2001 |                         |                            |
| ASSOCIATED                      |                                                                                                                                                                                                                                                | HRSMSC | 200      |                                                     |          | 7687        |                         |                            |
|                                 | REF: AMM 27-60-00                                                                                                                                                                                                                              | AFL    |          |                                                     |          | 5594        |                         |                            |
| 270296                          | BRAKE, SPEED RIGHT                                                                                                                                                                                                                             |        |          |                                                     |          |             |                         | W2                         |
| 27.250                          | 5-203007-506                                                                                                                                                                                                                                   | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                                 | SN-UNKNOWN                                                                                                                                                                                                                                     | HRSMSC | O/C      | 0                                                   |          | 0           |                         |                            |
|                                 | REF: AMM 27-60-00                                                                                                                                                                                                                              | AFL    |          |                                                     |          | 0           |                         |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO  | WORKCARD   | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|----------|------------|------------------------------------------------------|--------|----------|-----------------------------------------------------|----------|-------------|-------------------------|----------------------------|
| + 270335 |            | OPERATIONAL CHECK SPEED BRAKES AND LIFT DUMPERS      |        |          |                                                     |          |             |                         | F2                         |
|          | 27.280     | PKG 1, 2, 3                                          | MOS    |          |                                                     |          | 26-JUN-2001 |                         |                            |
|          | ASSOCIATED |                                                      | HRSMSC | 200      |                                                     |          | 7687        |                         |                            |
|          |            | REF: AMM 27-60-00                                    | AFL    |          |                                                     |          | 5594        |                         |                            |
| 270138   |            | CHAIN, AILERON LEFT                                  |        |          |                                                     |          |             |                         | F3                         |
|          | 27.080     | 3533516-1                                            | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|          |            | SN-UNKNOWN                                           | HRSMSC | O/C      | 0                                                   |          | 0           |                         |                            |
|          |            | REF: AMM 27-30-00                                    | AFL    |          |                                                     |          | 0           |                         |                            |
| 270139   |            | CHAIN, AILERON RIGHT                                 |        |          |                                                     |          |             |                         | F3                         |
|          | 27.080     | 3533516-1                                            | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|          |            | SN-UNKNOWN                                           | HRSMSC | O/C      | 0                                                   |          | 0           |                         |                            |
|          |            | REF: AMM 27-30-00                                    | AFL    |          |                                                     |          | 0           |                         |                            |
| 270186   |            | COLUMN, CONTROL COPILOT                              |        |          |                                                     |          |             |                         | F3                         |
|          | 27.140     | PN                                                   | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|          |            | SN-UNKNOWN                                           | HRSMSC | O/C      | 0                                                   |          | 0           |                         |                            |
|          |            | REF: AMM 27-30-00                                    | AFL    |          |                                                     |          | 0           |                         |                            |
| 270181   |            | COLUMN, CONTROL PILOT                                |        |          |                                                     |          |             |                         | F3                         |
|          | 27.140     | PN                                                   | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|          |            | SN-UNKNOWN                                           | HRSMSC | O/C      | 0                                                   |          | 0           |                         |                            |
|          |            | REF: AMM 27-30-00                                    | AFL    |          |                                                     |          | 0           |                         |                            |
| 270191   |            | ELEVATOR, LEFT                                       |        |          |                                                     |          |             |                         | T1                         |
|          | 27.150     | 5463012-401-1                                        | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|          |            | 4381                                                 | HRSMSC | O/C      | 0                                                   |          | 0           |                         |                            |
|          |            | REF: AMM 27-30-00                                    | AFL    |          |                                                     |          | 0           |                         |                            |
| + 270193 |            | INSPECT SKIN SEPARATION                              |        |          |                                                     |          |             |                         | T1                         |
|          | 27.150     | PKG 1, 2, 3                                          | MOS    |          |                                                     |          | 26-JUN-2001 |                         |                            |
|          |            |                                                      | HRSMSC | 200      |                                                     |          | 7687        |                         |                            |
|          |            | REF: AMM 27-30-00                                    | AFL    |          |                                                     |          | 5594        |                         |                            |
| 270213   |            | LUBRICATE ELEVATOR ATTACH POINTS                     |        |          |                                                     |          |             |                         | T1                         |
|          | 27.190     | PKG 1, 2, 3                                          | MOS    |          |                                                     |          | 26-JUN-2001 |                         |                            |
|          | ASSOCIATED |                                                      | HRSMSC | 200      |                                                     |          | 7687        |                         |                            |
|          |            | REF: AMM 12-20-00                                    | AFL    |          |                                                     |          | 5594        |                         |                            |
| 270210   |            | VISUAL INSPECT ELEVATOR CONTROL BELLCRANK ASSEMBLY   |        |          |                                                     |          |             |                         |                            |
|          | 27.570     |                                                      | MOS    | 60       |                                                     |          | 16-JUN-1997 | 16-JUN-2002             |                            |
|          | ASSOCIATED |                                                      | HRSMSC | 5000     |                                                     |          | 6135        | 11135                   |                            |
|          |            | REF: AMM 5-10-00                                     | AFL    |          |                                                     |          | 4707        |                         |                            |
| 270201   |            | ELEVATOR, RIGHT                                      |        |          |                                                     |          |             |                         | T1                         |
|          | 27.150     | 5463012-402-1                                        | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|          |            | 4381                                                 | HRSMSC | O/C      | 0                                                   |          | 0           |                         |                            |
|          |            | REF: AMM 27-30-00                                    | AFL    |          |                                                     |          | 0           |                         |                            |
| + 270203 |            | INSPECT SKIN SEPARATION                              |        |          |                                                     |          |             |                         | T1                         |
|          | 27.150     | PKG 1, 2, 3                                          | MOS    |          |                                                     |          | 26-JUN-2001 |                         |                            |
|          |            |                                                      | HRSMSC | 200      |                                                     |          | 7687        |                         |                            |
|          |            | REF: AMM 27-30-00                                    | AFL    |          |                                                     |          | 5594        |                         |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----<br>TSN TSO TSR TSI ADJ | INSTALLATION | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|--------|----------|-----------------------------------------|--------------|----------|-------------|-------------------------|----------------------------|
| 270213              | LUBRICATE ELEVATOR ATTACH POINTS                     |        |          |                                         |              |          |             |                         | T1                         |
| 27.190              | PKG 1, 2, 3                                          | MOS    |          |                                         |              |          | 26-JUN-2001 |                         |                            |
| ASSOCIATED          | REF: AMM 12-20-00                                    | HRS/MS | 200      |                                         |              |          | 7687        |                         |                            |
|                     |                                                      | AFL    |          |                                         |              |          | 5594        |                         |                            |
| 270210              | VISUAL INSPECT ELEVATOR CONTROL BELLCRANK ASSEMBLY   |        |          |                                         |              |          |             |                         |                            |
| 27.570              |                                                      | MOS    | 60       |                                         |              |          | 16-JUN-1997 | 16-JUN-2002             |                            |
| ASSOCIATED          | REF: AMM 5-10-00                                     | HRS/MS | 5000     |                                         |              |          | 6135        | 11135                   |                            |
|                     |                                                      | AFL    |          |                                         |              |          | 4707        |                         |                            |
| 270233              | FLAP ASSEMBLY, CONTROL BOX                           |        |          |                                         |              |          |             |                         | F3                         |
| 27.490              | 2813521-                                             | MOS    |          |                                         |              |          | 11-FEB-1982 |                         |                            |
|                     | 286                                                  | HRS/MS | O/C      | 0                                       |              |          | 0           |                         |                            |
|                     | REF: NO REF                                          | AFL    |          | 0                                       |              |          | 0           |                         |                            |
| 270236              | FLAP/VANE, LEFT                                      |        |          |                                         |              |          |             |                         | W1                         |
| 27.200              | 5193502-401                                          | MOS    |          |                                         |              |          | 11-FEB-1982 |                         |                            |
|                     | 4369                                                 | HRS/MS | O/C      | 0                                       |              |          | 0           |                         |                            |
|                     | REF: AMM 27-50-00                                    | AFL    |          |                                         |              |          | 0           |                         |                            |
| + 270248            | FUNCTIONAL CHECK FLAP TIME EXCEED RELAY              |        |          |                                         |              |          |             |                         | F3                         |
| 27.200              | PKG 2, 3                                             | MOS    |          |                                         |              |          | 26-JUN-2001 |                         |                            |
| ASSOCIATED          | REF: AMM 27-50-00                                    | HRS/MS | 400      |                                         |              |          | 7687        |                         |                            |
|                     |                                                      | AFL    |          |                                         |              |          | 5594        |                         |                            |
| + 270240            | INSPECT LEFT FLAP HINGE AND BEARING 200 HOURS        |        |          |                                         |              |          |             |                         | W1                         |
| 27.200              | PKG 1, 2, 3                                          | MOS    |          |                                         |              |          | 26-JUN-2001 |                         |                            |
|                     |                                                      | HRS/MS | 200      |                                         |              |          | 7687        |                         |                            |
|                     | REF: AMM 27-50-00                                    | AFL    |          |                                         |              |          | 5594        |                         |                            |
| + 270244            | INSPECT LEFT FLAP HINGE AND BEARING 800 HOURS        |        |          |                                         |              |          |             |                         | W1                         |
| 27.200              | PKG 3                                                | MOS    |          |                                         |              |          | 26-JUL-2000 |                         |                            |
|                     |                                                      | HRS/MS | 800      |                                         |              |          | 7325        |                         |                            |
|                     | REF: AMM 27-50-00                                    | AFL    |          |                                         |              |          | 5360        |                         |                            |
| + 270237            | INSPECT LEFT FLAP VANE                               |        |          |                                         |              |          |             |                         | W1                         |
| 27.200              | PKG 1, 2, 3                                          | MOS    |          |                                         |              |          | 26-JUN-2001 |                         |                            |
|                     |                                                      | HRS/MS | 200      |                                         |              |          | 7687        |                         |                            |
|                     | REF: AMM 27-50-00                                    | AFL    |          |                                         |              |          | 5594        |                         |                            |
| + 270238            | TAP TEST LEFT FLAP                                   |        |          |                                         |              |          |             |                         | W1                         |
| 27.200              | PKG 2, 3                                             | MOS    |          |                                         |              |          | 26-JUN-2001 |                         |                            |
|                     |                                                      | HRS/MS | 400      |                                         |              |          | 7687        | .5                      |                            |
|                     | REF: AMM 27-50-00                                    | AFL    |          |                                         |              |          | 5594        |                         |                            |
| 270241              | FLAP/VANE, RIGHT                                     |        |          |                                         |              |          |             |                         | W2                         |
| 27.200              | 5193502-402                                          | MOS    |          |                                         |              |          | 11-FEB-1982 |                         |                            |
|                     | 4370                                                 | HRS/MS | O/C      | 0                                       |              |          | 0           |                         |                            |
|                     | REF: AMM 27-50-00                                    | AFL    |          |                                         |              |          | 0           |                         |                            |
| + 270248            | FUNCTIONAL CHECK FLAP TIME EXCEED RELAY              |        |          |                                         |              |          |             |                         | F3                         |
| 27.200              | PKG 2, 3                                             | MOS    |          |                                         |              |          | 26-JUN-2001 |                         |                            |
| ASSOCIATED          | REF: AMM 27-50-00                                    | HRS/MS | 400      |                                         |              |          | 7687        |                         |                            |
|                     |                                                      | AFL    |          |                                         |              |          | 5594        |                         |                            |



Aircraft Model - 1124 WESTWIND

Report Date **11-APR-2002**

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT      | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|-----------|----------|-----------------------------------------------------|----------|-------------|-------------------------|----------------------------|
| + 270247            | INSPECT                                              |           |          |                                                     |          |             |                         | W1                         |
| 27.200              | PKG 1, 2, 3                                          | MOS       |          |                                                     |          | 26-JUN-2001 |                         |                            |
|                     | REF: AMM 27-50-00                                    | HRSMSC    | 200      |                                                     |          | 7687        |                         |                            |
|                     |                                                      | AFL       |          |                                                     |          | 5594        |                         |                            |
| + 270242            | INSPECT RIGHT FLAP HINGE AND BEARING                 | 200 HOURS |          |                                                     |          |             |                         | W2                         |
| 27.200              | PKG 1, 2, 3                                          | MOS       |          |                                                     |          | 26-JUN-2001 |                         |                            |
|                     | REF: AMM 27-50-00                                    | HRSMSC    | 200      |                                                     |          | 7687        |                         |                            |
|                     |                                                      | AFL       |          |                                                     |          | 5594        |                         |                            |
| + 270245            | INSPECT RIGHT FLAP HINGE AND BEARING                 | 800 HOURS |          |                                                     |          |             |                         | W2                         |
| 27.200              | PKG 3                                                | MOS       |          |                                                     |          | 26-JUL-2000 |                         |                            |
|                     | REF: AMM 27-50-00                                    | HRSMSC    | 800      |                                                     |          | 7325        |                         |                            |
|                     |                                                      | AFL       |          |                                                     |          | 5360        |                         |                            |
| + 270243            | TAP TEST                                             |           |          |                                                     |          |             |                         | W2                         |
| 27.200              | PKG 2, 3                                             | MOS       |          |                                                     |          | 26-JUN-2001 |                         |                            |
|                     | REF: AMM 27-50-00                                    | HRSMSC    | 400      |                                                     |          | 7687        | .5                      |                            |
|                     |                                                      | AFL       |          |                                                     |          | 5594        |                         |                            |
| 270276              | GEARBOX, COMPARATOR LEFT                             |           |          |                                                     |          |             |                         | W1                         |
| 27.400              | 5-703541-501                                         | MOS       |          |                                                     |          | 11-FEB-1982 |                         | \$1570.                    |
|                     | SN-UNKNOWN                                           | HRSMSC    | O/C      | 0                                                   |          | 0           |                         |                            |
|                     | REF: AMM 27-50-00                                    | AFL       |          |                                                     |          | 0           |                         |                            |
| + 270271            | ADJUST/TEST FLAP COMPARATOR                          |           |          |                                                     |          |             |                         | F3                         |
| 27.430              | PKG 3                                                | MOS       |          |                                                     |          | 26-JUL-2000 |                         |                            |
| ASSOCIATED          | REF: AMM 27-50-00                                    | HRSMSC    | 800      |                                                     |          | 7325        |                         |                            |
|                     |                                                      | AFL       |          |                                                     |          | 5360        |                         |                            |
| 270281              | GEARBOX, COMPARATOR RIGHT                            |           |          |                                                     |          |             |                         | W2                         |
| 27.400              | 5-703541-502                                         | MOS       |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRSMSC    | O/C      | 0                                                   |          | 0           |                         |                            |
|                     | REF: AMM 27-50-00                                    | AFL       |          |                                                     |          | 0           |                         |                            |
| + 270271            | ADJUST/TEST FLAP COMPARATOR                          |           |          |                                                     |          |             |                         | F3                         |
| 27.430              | PKG 3                                                | MOS       |          |                                                     |          | 26-JUL-2000 |                         |                            |
| ASSOCIATED          | REF: AMM 27-50-00                                    | HRSMSC    | 800      |                                                     |          | 7325        |                         |                            |
|                     |                                                      | AFL       |          |                                                     |          | 5360        |                         |                            |
| 270121              | INDICATOR, AILERON TRIM TAB                          |           |          |                                                     |          |             |                         | F3                         |
| 27.030              | 3883026-515                                          | MOS       |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                     | S0451                                                | HRSMSC    | O/C      | 0                                                   |          | 0           |                         |                            |
|                     | REF: AMM 27-10-00                                    | AFL       |          |                                                     |          | 0           |                         |                            |
| 271101              | INDICATOR, ANGLE-OF-ATTACK LEFT                      |           |          |                                                     |          |             |                         | F3                         |
| 27.470              | 3883765-501                                          | MOS       |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                     | JN1066                                               | HRSMSC    | O/C      | 0                                                   |          | 0           |                         |                            |
|                     | REF: AMM 34-10-05                                    | AFL       |          | 0                                                   |          | 0           |                         |                            |
| 271106              | INDICATOR, ANGLE-OF-ATTACK RIGHT                     |           |          |                                                     |          |             |                         | F3                         |
| 27.470              | 3883765-501                                          | MOS       |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRSMSC    | O/C      | 0                                                   |          | 0           |                         |                            |
|                     | REF: AMM 34-10-05                                    | AFL       |          | 0                                                   |          | 0           |                         |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER                                               | UNIT                 | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE                  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|----------------------------------------------------------------------------------------------------|----------------------|----------|-----------------------------------------------------|----------|-----------------------------|-------------------------|----------------------------|
| 270288<br>27.420    | INDICATOR, FLAP POSITION COPILOT<br>6883739-1<br>SN-UNKNOWN<br>REF: AMM 27-50-00                   | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | F3                         |
| 270286<br>27.420    | INDICATOR, FLAP POSITION PILOT<br>6883789-1<br>81090110<br>REF: AMM 27-50-00                       | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | F3<br>\$338.               |
| 270226<br>27.160    | INDICATOR, HORIZONTAL STABILIZER TRIM<br>3883026-525<br>T0119<br>REF: AMM 27-40-00                 | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | F3<br>\$306.               |
| 270171<br>27.120    | INDICATOR, RUDDER TRIM<br>3883026-517<br>T0163<br>REF: AMM 27-20-00                                | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | F3                         |
| 270224<br>27.185    | JACKSCREW, HORIZONTAL STABILIZER ACTUATOR NO.1<br>21164-005 (ACT.ASSY)<br>0481-11A<br>REF: NO REF  | MOS<br>HRSMSC<br>AFL | 10000    | 0                                                   |          | 06-APR-1998<br>6346<br>4787 | LIFE LIMIT<br>14787     | T1                         |
| 270225<br>27.185    | JACKSCREW, HORIZONTAL STABILIZER ACTUATOR NO.2<br>21164-005 (ACT.ASSY)<br>0481-11AA<br>REF: NO REF | MOS<br>HRSMSC<br>AFL | 10000    | 0                                                   |          | 06-APR-1998<br>6346<br>4787 | LIFE LIMIT<br>14787     | T1                         |
| 270318<br>27.290    | LIFT DUMPER, LEFT WING INBOARD<br>3713515-501<br>1L-900<br>REF: AMM 27-60-00                       | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | W1                         |
| 270316<br>27.290    | LIFT DUMPER, LEFT WING OUTBOARD<br>3713515-501<br>1L687P<br>REF: AMM 27-60-00                      | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | W1                         |
| 270321<br>27.300    | LIFT DUMPER, RIGHT WING INBOARD<br>3713515-501<br>1L862P<br>REF: AMM 27-60-00                      | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | W2                         |
| 270323<br>27.300    | LIFT DUMPER, RIGHT WING OUTBOARD<br>5-203007-510<br>1L881P<br>REF: AMM 27-60-00                    | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | W2                         |
| 270119<br>27.450    | MOTOR, AILERON TRIM<br>PN<br>SN-UNKNOWN<br>REF: NO REF                                             | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | W1                         |



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO  | WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT    | INTERVAL | TIME-----AT-----<br>TSN TSO TSR TSI ADJ | INSTALLATION | Warr Exp   | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|----------|----------|------------------------------------------------------|---------|----------|-----------------------------------------|--------------|------------|-------------|-------------------------|----------------------------|
| 270246   |          | MOTOR, FLAP PRIME                                    |         |          |                                         |              |            |             | OVERHAUL                | F5                         |
| 27.180   |          | 193543-1                                             | MOS     |          |                                         |              | 06/01/1993 | 01-DEC-1992 |                         | \$4235.                    |
|          |          | 160                                                  | HRS/MSC | 10000    | 0                                       |              |            | 5188        | 15188                   | 1                          |
|          |          | REF: AMM 27-50-00                                    | AFL     |          |                                         |              |            | 3829        |                         |                            |
| 270221   |          | MOTOR, PRIMARY HORIZONTAL STABILIZER                 |         |          |                                         |              |            |             |                         | T1                         |
| 27.460   |          | PN                                                   | MOS     |          |                                         |              |            | 11-FEB-1982 |                         |                            |
|          |          | SN-UNKNOWN                                           | HRS/MSC | O/C      | 0                                       |              |            | 0           |                         |                            |
|          |          | REF: NO REF                                          | AFL     |          |                                         |              |            | 0           |                         |                            |
| 270169   |          | MOTOR, RUDDER TRIM                                   |         |          |                                         |              |            |             |                         | T1                         |
| 27.450   |          | PN                                                   | MOS     |          |                                         |              |            | 11-FEB-1982 |                         |                            |
|          |          | SN-UNKNOWN                                           | HRS/MSC | O/C      | 0                                       |              |            | 0           |                         |                            |
|          |          | REF: NO REF                                          | AFL     |          |                                         |              |            | 0           |                         |                            |
| 270223   |          | MOTOR, SECONDARY HORIZONTAL STABILIZER               |         |          |                                         |              |            |             |                         | T1                         |
| 27.460   |          | PN                                                   | MOS     |          |                                         |              |            | 11-FEB-1982 |                         |                            |
|          |          | SN-UNKNOWN                                           | HRS/MSC | O/C      | 0                                       |              |            | 0           |                         |                            |
|          |          | REF: NO REF                                          | AFL     |          |                                         |              |            | 0           |                         |                            |
| 270274   |          | POTENTIOMETER, LINEAR LEFT                           |         |          |                                         |              |            |             |                         | W1                         |
| 27.410   |          | 833523-501                                           | MOS     |          |                                         |              |            | 10-AUG-1986 |                         |                            |
|          |          | SN-UNKNOWN                                           | HRS/MSC | O/C      |                                         |              |            | 3515        |                         |                            |
|          |          | REF: AMM 27-50-00                                    | AFL     |          |                                         |              |            |             |                         |                            |
| 270282   |          | POTENTIOMETER, LINEAR RIGHT                          |         |          |                                         |              |            |             |                         | W2                         |
| 27.410   |          | 833523-501                                           | MOS     |          |                                         |              |            | 10-AUG-1986 |                         |                            |
|          |          | 589                                                  | HRS/MSC | O/C      |                                         |              |            | 3515        |                         |                            |
|          |          | REF: AMM 27-50-00                                    | AFL     |          |                                         |              |            |             |                         |                            |
| 270128   |          | ROD, CONTROL LEFT AILERON                            |         |          |                                         |              |            |             |                         | W1                         |
| 27.530   |          | 513506-503                                           | MOS     |          |                                         |              |            | 11-FEB-1982 |                         |                            |
|          |          | SN-UNKNOWN                                           | HRS/MSC | O/C      |                                         |              |            | 0           |                         |                            |
|          |          | REF: NO REF                                          | AFL     |          |                                         |              |            | 0           |                         |                            |
| + 270080 |          | X-RAY INSPECT LEFT AILERON CONTROL ROD ASSEMBLIES    |         |          |                                         |              |            |             |                         | W1                         |
| 27.530   |          |                                                      | MOS     | 60       |                                         |              |            | 16-JUN-1997 | 16-JUN-2002             |                            |
|          |          | SN-UNKNOWN                                           | HRS/MSC | 5000     |                                         |              |            | 6135        | 11135                   |                            |
|          |          | REF: NO REF                                          | AFL     |          |                                         |              |            | 4707        |                         |                            |
| 270129   |          | ROD, CONTROL RIGHT AILERON                           |         |          |                                         |              |            |             |                         | W2                         |
| 27.535   |          | 513506-503                                           | MOS     |          |                                         |              |            | 11-FEB-1982 |                         |                            |
|          |          | SN-UNKNOWN                                           | HRS/MSC | O/C      |                                         |              |            | 0           |                         |                            |
|          |          | REF: NO REF                                          | AFL     |          |                                         |              |            | 0           |                         |                            |
| + 270081 |          | X-RAY INSPECT ASSEMBLY                               |         |          |                                         |              |            |             |                         | W2                         |
| 27.535   |          |                                                      | MOS     | 60       |                                         |              |            | 16-JUN-1997 | 16-JUN-2002             |                            |
|          |          | SN-UNKNOWN                                           | HRS/MSC | 5000     |                                         |              |            | 6135        | 11135                   |                            |
|          |          | REF: NO REF                                          | AFL     |          |                                         |              |            | 4707        |                         |                            |
| 270141   |          | RUDDER,                                              |         |          |                                         |              |            |             |                         | T1                         |
| 27.100   |          | 5423026-402-2                                        | MOS     |          |                                         |              |            | 11-FEB-1982 |                         |                            |
|          |          | 4370                                                 | HRS/MSC | O/C      | 0                                       |              |            | 0           |                         |                            |
|          |          | REF: AMM 27-20-00                                    | AFL     |          |                                         |              |            | 0           |                         |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD              | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER          | UNIT   | INTERVAL | TIME-----AT-----<br>TSN TSO TSR TSI ADJ | INSTALLATION | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|----------------------------------|---------------------------------------------------------------|--------|----------|-----------------------------------------|--------------|----------|-------------|-------------------------|----------------------------|
| + 270150<br>27.560               | X-RAY INSPECT CONTROL ROD ASSEMBLY                            | MOS    | 60       |                                         |              |          | 16-JUN-1997 | 16-JUN-2002             | T1                         |
|                                  |                                                               | HRSMSC | 5000     |                                         |              |          | 6135        | 11135                   |                            |
|                                  | REF: NO REF                                                   | AFL    |          |                                         |              |          | 4707        |                         |                            |
| 270279<br>27.230                 | SHAFT, FLEXIBLE INBOARD LEFT                                  | MOS    |          |                                         |              |          | 11-FEB-1982 | LIFE LIMIT              | W1                         |
|                                  | 193545-501                                                    | HRSMSC | 10000    | 0                                       |              |          | 0           | 10000                   |                            |
|                                  | 1200269                                                       | AFL    |          |                                         |              |          | 0           |                         |                            |
|                                  | REF: AMM 27-50-00                                             |        |          |                                         |              |          |             |                         |                            |
| + 270280<br>27.230<br>ASSOCIATED | CLEAN/INSPECT/LUBRICATE LEFT INBOARD/OUTBOARD FLEXIBLE SHAFT  | MOS    |          |                                         |              |          | 16-FEB-2001 |                         | W1                         |
|                                  |                                                               | HRSMSC | 1200     |                                         |              |          | 7551        | 8751                    |                            |
|                                  | REF: AMM 27-50-00                                             | AFL    |          |                                         |              |          | 5515        |                         |                            |
| 270284<br>27.240                 | SHAFT, FLEXIBLE INBOARD RIGHT                                 | MOS    |          |                                         |              |          | 11-FEB-1982 | LIFE LIMIT              | W2                         |
|                                  | 193545-505                                                    | HRSMSC | 10000    | 0                                       |              |          | 0           | 10000                   |                            |
|                                  | 1200241                                                       | AFL    |          |                                         |              |          | 0           |                         |                            |
|                                  | REF: AMM 27-50-00                                             |        |          |                                         |              |          |             |                         |                            |
| + 270285<br>27.230<br>ASSOCIATED | CLEAN/INSPECT/LUBRICATE RIGHT INBOARD/OUTBOARD FLEXIBLE SHAFT | MOS    |          |                                         |              |          | 16-FEB-2001 |                         | W2                         |
|                                  |                                                               | HRSMSC | 1200     |                                         |              |          | 7551        | 8751                    |                            |
|                                  | REF: AMM 27-50-00                                             | AFL    |          |                                         |              |          | 5515        |                         |                            |
| 270278<br>27.230                 | SHAFT, FLEXIBLE OUTBOARD LEFT                                 | MOS    |          |                                         |              |          | 11-FEB-1982 | LIFE LIMIT              | W1                         |
|                                  | 193545-501                                                    | HRSMSC | 10000    | 0                                       |              |          | 0           | 10000                   |                            |
|                                  | 1200446                                                       | AFL    |          |                                         |              |          | 0           |                         |                            |
|                                  | REF: AMM 27-50-00                                             |        |          |                                         |              |          |             |                         |                            |
| + 270280<br>27.230<br>ASSOCIATED | CLEAN/INSPECT/LUBRICATE LEFT INBOARD/OUTBOARD FLEXIBLE SHAFT  | MOS    |          |                                         |              |          | 16-FEB-2001 |                         | W1                         |
|                                  |                                                               | HRSMSC | 1200     |                                         |              |          | 7551        | 8751                    |                            |
|                                  | REF: AMM 27-50-00                                             | AFL    |          |                                         |              |          | 5515        |                         |                            |
| 270283<br>27.240                 | SHAFT, FLEXIBLE OUTBOARD RIGHT                                | MOS    |          |                                         |              |          | 11-FEB-1982 | LIFE LIMIT              | W2                         |
|                                  | 193545-501                                                    | HRSMSC | 10000    | 0                                       |              |          | 0           | 10000                   |                            |
|                                  | 1200514                                                       | AFL    |          |                                         |              |          | 0           |                         |                            |
|                                  | REF: AMM 27-50-00                                             |        |          |                                         |              |          |             |                         |                            |
| + 270285<br>27.230<br>ASSOCIATED | CLEAN/INSPECT/LUBRICATE RIGHT INBOARD/OUTBOARD FLEXIBLE SHAFT | MOS    |          |                                         |              |          | 16-FEB-2001 |                         | W2                         |
|                                  |                                                               | HRSMSC | 1200     |                                         |              |          | 7551        | 8751                    |                            |
|                                  | REF: AMM 27-50-00                                             | AFL    |          |                                         |              |          | 5515        |                         |                            |
| 270126<br>27.040                 | TAB, AILERON SERVO                                            | MOS    |          |                                         |              |          | 11-FEB-1982 |                         | W2                         |
|                                  | 5-183005-505                                                  | HRSMSC | O/C      | 0                                       |              |          | 0           |                         |                            |
|                                  | SN-UNKNOWN                                                    | AFL    |          |                                         |              |          | 0           |                         |                            |
|                                  | REF: AMM 27-10-00                                             |        |          |                                         |              |          |             |                         |                            |
| 270111<br>27.020                 | TAB, AILERON TRIM                                             | MOS    |          |                                         |              |          | 11-FEB-1982 |                         | W1                         |
|                                  | 5-183005-503                                                  | HRSMSC | O/C      | 0                                       |              |          | 0           |                         |                            |
|                                  | SN-UNKNOWN                                                    | AFL    |          |                                         |              |          | 0           |                         |                            |
|                                  | REF: AMM 27-10-00                                             |        |          |                                         |              |          |             |                         |                            |



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD    | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT    | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|------------------------|------------------------------------------------------|---------|----------|-----------------------------------------------------|----------|-------------|-------------------------|----------------------------|
| 270156                 | TAB, RUDDER TRIM                                     |         |          |                                                     |          |             |                         | T1                         |
| 27.110                 | PN                                                   | MOS     |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                        | SN-UNKNOWN                                           | HRS/MSC | O/C      | 0                                                   |          | 0           |                         |                            |
|                        | REF: AMM 27-20-00                                    | AFL     |          |                                                     |          | 0           |                         |                            |
| + 270158               | INSPECT FREEPLAY                                     |         |          |                                                     |          |             |                         | T1                         |
| 27.130                 | PKG 1, 2, 3                                          | MOS     |          |                                                     |          | 26-JUN-2001 |                         |                            |
|                        |                                                      | HRS/MSC | 200      |                                                     |          | 7687        |                         |                            |
|                        | REF: AMM 27-20-00                                    | AFL     |          |                                                     |          | 5594        |                         |                            |
| 271111                 | TRANSMITTER, ANGLE-OF-ATTACK LEFT                    |         |          |                                                     |          |             |                         | W1                         |
| 27.480                 | SLZ7259                                              | MOS     |          |                                                     |          | 06-APR-1998 |                         |                            |
|                        | KE1141                                               | HRS/MSC | O/C      |                                                     |          | 6346        |                         |                            |
|                        | REF: AMM 34-10-05                                    | AFL     |          |                                                     |          | 4787        |                         |                            |
| 271116                 | TRANSMITTER, ANGLE-OF-ATTACK RIGHT                   |         |          |                                                     |          |             |                         | W2                         |
| 27.480                 | SLZ-9280                                             | MOS     |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                        | SN-UNKNOWN                                           | HRS/MSC | O/C      | 0                                                   |          | 0           |                         |                            |
|                        | REF: AMM 34-10-05                                    | AFL     |          | 0                                                   |          | 0           |                         |                            |
| 270231                 | TRANSMITTER, TRIM POSITION INDICATOR                 |         |          |                                                     |          |             |                         | T1                         |
| 27.390                 | 8TJ39-BAR-2                                          | MOS     |          |                                                     |          | 11-FEB-1982 |                         | \$543.                     |
|                        | T1353                                                | HRS/MSC | O/C      | 0                                                   |          | 0           |                         |                            |
|                        | REF: AMM 27-40-00                                    | AFL     |          |                                                     |          | 0           |                         |                            |
| 270336                 | VALVE, LIFT DUMPER CONTROL                           |         |          |                                                     |          |             |                         | F5                         |
| 27.330                 | 723573-1                                             | MOS     |          |                                                     |          | 11-FEB-1982 |                         | \$362.                     |
|                        | 698                                                  | HRS/MSC | O/C      | 0                                                   |          | 0           |                         |                            |
|                        | REF: AMM 27-60-00                                    | AFL     |          |                                                     |          | 0           |                         |                            |
| 270311                 | VALVE, SPEED BRAKE CONTROL                           |         |          |                                                     |          |             |                         | F5                         |
| 27.270                 | 723573-1                                             | MOS     |          |                                                     |          | 11-FEB-1982 |                         | \$362.                     |
|                        | 845                                                  | HRS/MSC | O/C      | 0                                                   |          | 0           |                         |                            |
|                        | REF: AMM 27-60-00                                    | AFL     |          |                                                     |          | 0           |                         |                            |
| 270138                 | WHEEL, CONTROL COPILOT                               |         |          |                                                     |          |             |                         | F3                         |
| 27.050                 | 5-533060-35                                          | MOS     |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                        | SN-UNKNOWN                                           | HRS/MSC | O/C      | 0                                                   |          | 0           |                         |                            |
|                        | REF: AMM 27-10-00                                    | AFL     |          |                                                     |          | 0           |                         |                            |
| 270131                 | WHEEL, CONTROL PILOT                                 |         |          |                                                     |          |             |                         | F3                         |
| 27.050                 | 5-533060-37                                          | MOS     |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                        | SN-UNKNOWN                                           | HRS/MSC | O/C      | 0                                                   |          | 0           |                         |                            |
|                        | REF: AMM 27-10-00                                    | AFL     |          |                                                     |          | 0           |                         |                            |
| <b>CHAPTER 28 FUEL</b> |                                                      |         |          |                                                     |          |             |                         |                            |
| + 281150               | CHECK OPERATION OF FUEL BOOST PUMPS                  |         |          |                                                     |          |             |                         | F5                         |
| 28.010                 | PKG 1, 2, 3                                          | MOS     |          |                                                     |          | 26-JUN-2001 |                         |                            |
|                        |                                                      | HRS/MSC | 200      |                                                     |          | 7687        |                         |                            |
|                        | REF: AMM 28-00-00                                    | AFL     |          |                                                     |          | 5594        |                         |                            |
| + 281603               | FUNCTIONAL CHECK FUEL DUMP SYSTEM                    |         |          |                                                     |          |             |                         | F5                         |
| 28.090                 |                                                      | MOS     |          |                                                     |          | 22-FEB-2000 |                         |                            |
|                        |                                                      | HRS/MSC | 1200     |                                                     |          | 7107        | 8307                    |                            |
|                        | REF: AMM 28-00-00                                    | AFL     |          |                                                     |          | 5232        |                         |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER                    | UNIT                 | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE                  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|-------------------------------------------------------------------------|----------------------|----------|-----------------------------------------------------|----------|-----------------------------|-------------------------|----------------------------|
| + 281602<br>28.090  | OPERATIONAL CHECK FUEL DUMP SYSTEM<br>PKG 3                             | MOS<br>HRSMSC<br>AFL | 800      |                                                     |          | 26-JUL-2000<br>7325<br>5360 |                         | F5                         |
| 281101<br>28.200    | INDICATOR, FUEL QUANTITY LEFT<br>6883707-1<br>359<br>REF: AMM 28-00-00  | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | F3<br>\$444.<br>1          |
| 281106<br>28.200    | INDICATOR, FUEL QUANTITY RIGHT<br>6883707-1<br>361<br>REF: AMM 28-40-00 | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | F3<br>\$444.<br>1          |
| 281108<br>28.210    | INDICATOR, FUEL STATUS<br>6883710-501<br>173<br>REF: NO REF             | MOS<br>HRSMSC<br>AFL | O/C      |                                                     |          | 11-FEB-1982                 |                         | F3                         |
| 280626<br>28.160    | PROBE, LEFT TIP TANK<br>6653505-519<br>227<br>REF: AMM 28-40-00         | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | W1                         |
| 280616<br>28.140    | PROBE, LEFT WING INBOARD<br>5653505-507<br>207<br>REF: AMM 28-40-00     | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | W1                         |
| 280621<br>28.140    | PROBE, LEFT WING OUTBOARD<br>5653505-505<br>214<br>REF: AMM 28-40-00    | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | W1                         |
| 280646<br>28.160    | PROBE, RIGHT TIP TANK<br>6653505-519<br>233<br>REF: AMM 28-40-00        | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | W2                         |
| 280636<br>28.150    | PROBE, RIGHT WING INBOARD<br>5653505-507<br>266<br>REF: AMM 28-40-00    | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | W2                         |
| 280641<br>28.150    | PROBE, RIGHT WING OUTBOARD<br>5653505-505<br>235<br>REF: AMM 28-40-00   | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | W2                         |
| 280611<br>28.130    | PROBE, FUSELAGE LEFT<br>3653505-509<br>224<br>REF: AMM 28-40-00         | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | F5                         |



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|--------|----------|-----------------------------------------------------|----------|-------------|-------------------------|----------------------------|
| 280631              | PROBE, FUSELAGE RIGHT                                |        |          |                                                     |          |             |                         | F5                         |
| 28.130              | 6653505-509                                          | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                     | 291                                                  | HRS/MS | O/C      | 0                                                   |          | 0           |                         |                            |
|                     | REF: AMM 28-40-00                                    | AFL    |          |                                                     |          | 0           |                         |                            |
| 280126              | PUMP, ALTERNATE BOOST LEFT                           |        |          |                                                     |          |             |                         | W1                         |
| 28.020              | 5653744-505                                          | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                     | T514                                                 | HRS/MS | O/C      | 0                                                   |          | 0           |                         |                            |
|                     | REF: AMM 28-20-00                                    | AFL    |          |                                                     |          | 0           |                         |                            |
| 280128              | CHECK BRUSH WEAR                                     |        |          |                                                     |          |             |                         | W1                         |
| 28.020              |                                                      | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                     |                                                      | HRS/MS | O/C      |                                                     |          | 0           |                         |                            |
|                     | REF: See Workcard                                    | AFL    |          |                                                     |          | 0           |                         |                            |
| + 281150            | CHECK OPERATION OF FUEL BOOST PUMPS                  |        |          |                                                     |          |             |                         | F5                         |
| 28.010              | PKG 1, 2, 3                                          | MOS    |          |                                                     |          | 26-JUN-2001 |                         |                            |
| ASSOCIATED          |                                                      | HRS/MS | 200      |                                                     |          | 7687        |                         |                            |
|                     | REF: AMM 28-00-00                                    | AFL    |          |                                                     |          | 5594        |                         |                            |
| 280136              | PUMP, ALTERNATE BOOST RIGHT                          |        |          |                                                     |          |             |                         | W2                         |
| 28.020              | 5653744                                              | MOS    |          |                                                     |          | 30-OCT-1989 |                         |                            |
|                     | 853                                                  | HRS/MS | O/C      |                                                     |          | 4401        |                         |                            |
|                     | REF: AMM 28-20-00                                    | AFL    |          |                                                     |          | 2956        |                         |                            |
| 280138              | CHECK BRUSH WEAR                                     |        |          |                                                     |          |             |                         | W2                         |
| 28.020              |                                                      | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                     |                                                      | HRS/MS | O/C      |                                                     |          | 0           |                         |                            |
|                     | REF: See Workcard                                    | AFL    |          |                                                     |          | 0           |                         |                            |
| + 281150            | CHECK OPERATION OF FUEL BOOST PUMPS                  |        |          |                                                     |          |             |                         | F5                         |
| 28.010              | PKG 1, 2, 3                                          | MOS    |          |                                                     |          | 26-JUN-2001 |                         |                            |
| ASSOCIATED          |                                                      | HRS/MS | 200      |                                                     |          | 7687        |                         |                            |
|                     | REF: AMM 28-00-00                                    | AFL    |          |                                                     |          | 5594        |                         |                            |
| 280161              | PUMP, FUSELAGE JET LEFT                              |        |          |                                                     |          |             |                         | F5                         |
| 28.110              | 3-653015                                             | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                     | 1095                                                 | HRS/MS | O/C      | 0                                                   |          | 0           |                         |                            |
|                     | REF: AMM 28-20-00                                    | AFL    |          |                                                     |          | 0           |                         |                            |
| 280166              | PUMP, FUSELAGE JET RIGHT                             |        |          |                                                     |          |             |                         | F5                         |
| 28.110              | 3-653015                                             | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                     | 1099                                                 | HRS/MS | O/C      | 0                                                   |          | 0           |                         |                            |
|                     | REF: AMM 28-20-00                                    | AFL    |          |                                                     |          | 0           |                         |                            |
| 280181              | PUMP, JET LEFT TIP TANK                              |        |          |                                                     |          |             |                         | W1                         |
| 28.100              | 3-653015                                             | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                     | 1309                                                 | HRS/MS | O/C      | 0                                                   |          | 0           |                         |                            |
|                     | REF: AMM 28-20-00                                    | AFL    |          |                                                     |          | 0           |                         |                            |
| 280186              | PUMP, JET RIGHT TIP TANK                             |        |          |                                                     |          |             |                         | W2                         |
| 28.100              | 3-653015                                             | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                     | 1311                                                 | HRS/MS | O/C      | 0                                                   |          | 0           |                         |                            |
|                     | REF: AMM 28-20-00                                    | AFL    |          |                                                     |          | 0           |                         |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Page 32 of 107



**Aircraft Model - 1124 WESTWIND**
**Report Date 11-APR-2002**
**Owner Name - R&S AIRCRAFT INVESTMENTS, LLC**  
**A/C Serial #: 368 A/C Reg. #: N368MD**

| ITEM NO  | WORKCARD             | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER                         | UNIT                 | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE                  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|----------|----------------------|------------------------------------------------------------------------------|----------------------|----------|-----------------------------------------------------|----------|-----------------------------|-------------------------|----------------------------|
| 280167   | 28.230               | PUMP, LONG RANGE BOOST<br>653009-513<br>SN-UNKNOWN<br>REF: AMM 28-50-00      | MOS<br>HRSMSC<br>AFL | O/C      |                                                     |          | 11-FEB-1982                 |                         | F4                         |
| 280121   | 28.010               | PUMP, MAIN BOOST LEFT<br>2070C01T3<br>T-330<br>REF: AMM 28-20-00             | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 24-APR-2000<br>7233<br>5301 |                         | W1                         |
| 280123   | 28.010               | CHECK BRUSH WEAR<br><br>REF: NO REF                                          | MOS<br>HRSMSC<br>AFL | O/C      |                                                     |          | 24-APR-2000<br>7233<br>5301 |                         | W1                         |
| + 281150 | 28.010<br>ASSOCIATED | CHECK OPERATION OF FUEL BOOST PUMPS<br>PKG 1, 2, 3<br><br>REF: AMM 28-00-00  | MOS<br>HRSMSC<br>AFL | 200      |                                                     |          | 26-JUN-2001<br>7687<br>5594 |                         | F5                         |
| 280131   | 28.010               | PUMP, MAIN BOOST RIGHT<br>2070C01T3<br>T1222<br>REF: AMM 28-20-00            | MOS<br>HRSMSC<br>AFL | O/C      | 0<br>0<br>0                                         |          | 26-AUG-1992<br>5151<br>3777 |                         | W2                         |
| 280133   | 28.010               | CHECK BRUSH WEAR<br><br>REF: See Workcard                                    | MOS<br>HRSMSC<br>AFL | O/C      |                                                     |          | 26-AUG-1992<br>5151<br>3777 |                         | W2                         |
| + 281150 | 28.010<br>ASSOCIATED | CHECK OPERATION OF FUEL BOOST PUMPS<br>PKG 1, 2, 3<br><br>REF: AMM 28-00-00  | MOS<br>HRSMSC<br>AFL | 200      |                                                     |          | 26-JUN-2001<br>7687<br>5594 |                         | F5                         |
| 281121   | 28.210               | SIGNAL CONDITIONER, FUEL<br>883711-501<br>157<br>REF: NO REF                 | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | F2                         |
| 280281   | 28.190               | SWITCH, FUEL FLOAT LEFT<br>833006<br>A966<br>REF: NO REF                     | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | F5                         |
| 280286   | 28.190               | SWITCH, FUEL FLOAT RIGHT<br>833006<br>A920<br>REF: NO REF                    | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | F5                         |
| 281141   | 28.170               | SWITCH, LOW-LEVEL WARNING LEFT<br>3833006<br>SN-UNKNOWN<br>REF: AMM 28-40-00 | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | F5                         |



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD              | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER                          | UNIT                 | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE                  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|----------------------------------|-------------------------------------------------------------------------------|----------------------|----------|-----------------------------------------------------|----------|-----------------------------|-------------------------|----------------------------|
| 281146<br>28.170                 | SWITCH, LOW-LEVEL WARNING RIGHT<br>3833006<br>SN-UNKNOWN<br>REF: AMM 28-40-00 | MOS<br>HRS/MS<br>AFL |          |                                                     |          | 11-FEB-1982<br>0<br>0       |                         | F5                         |
| 281139<br>28.240                 | SWITCH, PRESSURE(LONG RANGE)<br>833010-518<br>A-149<br>REF: NO REF            | MOS<br>HRS/MS<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | F4                         |
| 280250<br>28.220                 | TANK, FUEL (LONG RANGE)<br>CMA61032-501<br>NSN<br>REF: AMM 28-50-00           | MOS<br>HRS/MS<br>AFL |          | 0<br>0<br>0                                         |          | 07-DEC-1989<br>4437<br>2994 |                         | F5                         |
| 281110<br>28.240                 | TRANSMITTER, QUANTITY (LONG RANGE)<br>DA515A050<br>SN-UNKNOWN<br>REF: NO REF  | MOS<br>HRS/MS<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | F4                         |
| 280191<br>28.090                 | VALVE, DUMP LEFT<br>3653014<br>168<br>REF: AMM 28-30-00                       | MOS<br>HRS/MS<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | W1<br>\$725.               |
| + 281603<br>28.090<br>ASSOCIATED | FUNCTIONAL CHECK FUEL DUMP SYSTEM<br>REF: AMM 28-00-00                        | MOS<br>HRS/MS<br>AFL | 1200     |                                                     |          | 22-FEB-2000<br>7107<br>5232 | 8307                    | F5                         |
| + 281602<br>28.090<br>ASSOCIATED | OPERATIONAL CHECK FUEL DUMP SYSTEM<br>PKG 3<br>REF: AMM 28-00-00              | MOS<br>HRS/MS<br>AFL | 800      |                                                     |          | 26-JUL-2000<br>7325<br>5360 |                         | F5                         |
| 280196<br>28.090                 | VALVE, DUMP RIGHT<br>3653014<br>31360<br>REF: AMM 28-30-00                    | MOS<br>HRS/MS<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | W2<br>\$725.               |
| + 281603<br>28.090<br>ASSOCIATED | FUNCTIONAL CHECK FUEL DUMP SYSTEM<br>REF: AMM 28-00-00                        | MOS<br>HRS/MS<br>AFL | 1200     |                                                     |          | 22-FEB-2000<br>7107<br>5232 | 8307                    | F5                         |
| + 281602<br>28.090<br>ASSOCIATED | OPERATIONAL CHECK FUEL DUMP SYSTEM<br>PKG 3<br>REF: AMM 28-00-00              | MOS<br>HRS/MS<br>AFL | 800      |                                                     |          | 26-JUL-2000<br>7325<br>5360 |                         | F5                         |
| 280141<br>28.040                 | VALVE, FIREWALL SHUTOFF LEFT<br>3653012<br>L38199<br>REF: AMM 28-20-00        | MOS<br>HRS/MS<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | E1                         |

 ? - Insufficient Information  
 + Task exists in FAA Manual  
 4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER                         | UNIT                 | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE                  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------------------------------|----------------------|----------|-----------------------------------------------------|----------|-----------------------------|-------------------------|----------------------------|
| 280151<br>28.040    | VALVE, FIREWALL SHUTOFF RIGHT<br>3-653012<br>L35008<br>REF: AMM 28-20-00     | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | E2<br>\$725.               |
| 280251<br>28.050    | VALVE, FUEL AUTO SHUTOFF LEFT<br>3653669<br>0114<br>REF: AMM 28-10-00        | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | F5                         |
| 280256<br>28.050    | VALVE, FUEL AUTO SHUTOFF RIGHT<br>3653669<br>0087<br>REF: AMM 28-10-00       | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | F5                         |
| 280106<br>28.030    | VALVE, FUEL INTERCONNECT AFT<br>3653014<br>31395<br>REF: AMM 28-10-00        | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | F5<br>\$725.               |
| 280101<br>28.030    | VALVE, FUEL INTERCONNECT FORWARD<br>AV16B1683<br>L18181<br>REF: AMM 28-10-00 | MOS<br>HRSMSC<br>AFL | O/C      |                                                     |          | 16-JUN-1997<br>6135<br>4707 |                         | F5<br>\$725.               |
| 280261<br>28.060    | VALVE, FUEL PILOT LEFT<br>3653671<br>7732<br>REF: AMM 28-10-00               | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | F5                         |
| 280266<br>28.060    | VALVE, FUEL PILOT RIGHT<br>3653671<br>7728<br>REF: AMM 28-10-00              | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | F5                         |
| 280194<br>28.070    | VALVE, FUEL PRECHECK LEFT<br>PN<br>SN-UNKNOWN<br>REF: AMM 28-10-00           | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | F5                         |
| 280203<br>28.070    | VALVE, FUEL PRECHECK RIGHT<br>PN<br>SN-UNKNOWN<br>REF: AMM 28-10-00          | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | F5                         |
| 280206<br>28.180    | VALVE, FUEL SOLENOID LEFT<br>MS-29527-1<br>744<br>REF: NO REF                | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | F5                         |
| 280211<br>28.180    | VALVE, FUEL SOLENOID RIGHT<br>MS-29527-1<br>752<br>REF: NO REF               | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | F5                         |



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD               | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION |     |     |     |     | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|-----------------------------------|------------------------------------------------------|--------|----------|------------------------------|-----|-----|-----|-----|----------|-------------|-------------------------|----------------------------|
|                                   |                                                      |        |          | TSN                          | TSO | TSR | TSI | ADJ |          |             |                         |                            |
| 280171                            | VALVE, FUEL TRANSFER LEFT                            |        |          |                              |     |     |     |     |          |             |                         | F5                         |
| 28.120                            | 4653572                                              | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         | \$805.                     |
|                                   | 101                                                  | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                                   | REF: AMM 28-20-00                                    | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 280176                            | VALVE, FUEL TRANSFER RIGHT                           |        |          |                              |     |     |     |     |          |             |                         | F5                         |
| 28.120                            | 4653572                                              | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         | \$805.                     |
|                                   | 126                                                  | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                                   | REF: AMM 28-20-00                                    | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 280290                            | VALVE, SINGLE POINT REFUEL ADAPTER                   |        |          |                              |     |     |     |     |          |             |                         | F5                         |
| 28.250                            | 3653670                                              | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                                   | 205                                                  | HRS/MS | O/C      |                              |     |     |     |     |          | 0           |                         |                            |
|                                   | REF: NO REF                                          | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 280271                            | VALVE, SINGLE POINT REFUEL VENT LEFT                 |        |          |                              |     |     |     |     |          |             |                         | F5                         |
| 28.080                            | 3653672                                              | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                                   | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                                   | REF: AMM 28-10-00                                    | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 280276                            | VALVE, SINGLE POINT REFUEL VENT RIGHT                |        |          |                              |     |     |     |     |          |             |                         | F5                         |
| 28.080                            | 3653672                                              | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                                   | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                                   | REF: AMM 28-10-00                                    | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| <b>CHAPTER 29 HYDRAULIC POWER</b> |                                                      |        |          |                              |     |     |     |     |          |             |                         |                            |
| 290221                            | ACCUMULATOR, EMERGENCY                               |        |          |                              |     |     |     |     |          |             |                         | F5                         |
| 29.080                            | 3713008                                              | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         | \$472.                     |
|                                   | 601                                                  | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                                   | REF: AMM 29-20-00                                    | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 290151                            | ACCUMULATOR, LEFT HYDRAULIC                          |        |          |                              |     |     |     |     |          |             |                         | F5                         |
| 29.130                            | 4-713569-1                                           | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                                   | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                                   | REF: NO REF                                          | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 290186                            | ACCUMULATOR, RIGHT HYDRAULIC                         |        |          |                              |     |     |     |     |          |             |                         | F5                         |
| 29.130                            | 4-713569-1                                           | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                                   | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                                   | REF: NO REF                                          | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 290261                            | ATTENUATOR, NO.1 ENG HYDRAULIC                       |        |          |                              |     |     |     |     |          |             |                         | F5                         |
| 29.040                            | 3713562-1                                            | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                                   | 0601                                                 | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                                   | REF: AMM 29-10-00                                    | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 290266                            | ATTENUATOR, NO.2 ENG HYDRAULIC                       |        |          |                              |     |     |     |     |          |             |                         | F5                         |
| 29.040                            | 3713562-1                                            | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                                   | 0591                                                 | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                                   | REF: AMM 29-10-00                                    | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 290119                            | CHECK VALVE, RESERVOIR BLEED AIR                     |        |          |                              |     |     |     |     |          |             |                         | F5                         |
| 29.180                            | PN                                                   | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                                   | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                                   | REF: NO REF                                          | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L



Aircraft Model - 1124 WESTWIND

Report Date **11-APR-2002**

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|--------|----------|-----------------------------------------------------|----------|------------|-------------------------|----------------------------|
| 290248              | FUSE, EMERGENCY HYDRAULIC                            |        |          |                                                     |          |            |                         | F2                         |
| 29.110              | 3713047                                              | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | 3383                                                 | HRS/MS | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 29-30-00                                    | AFL    |          |                                                     |          | 0          |                         |                            |
| 290248              | GAUGE, EMERGENCY HYDRAULIC PRESSURE                  |        |          |                                                     |          |            |                         | F3                         |
| 29.100              | 4883746-1                                            | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 29-30-00                                    | AFL    |          |                                                     |          | 0          |                         |                            |
| 290148              | GAUGE, LEFT ACCUMULATOR PRESSURE                     |        |          |                                                     |          |            |                         | F5                         |
| 29.140              | 7253014-501                                          | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                                                     |          | 0          |                         |                            |
| 290183              | GAUGE, RIGHT ACCUMULATOR PRESSURE                    |        |          |                                                     |          |            |                         | F5                         |
| 29.140              | 7253014-501                                          | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                                                     |          | 0          |                         |                            |
| 290236              | INDICATOR, HYDRAULIC PRESSURE                        |        |          |                                                     |          |            |                         | F3                         |
| 29.160              | 4883746-1                                            | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | 8007104                                              | HRS/MS | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 29-30-00                                    | AFL    |          |                                                     |          | 0          |                         |                            |
| 290211              | PUMP, EMERGENCY HYDRAULIC                            |        |          |                                                     |          |            |                         | F5                         |
| 29.060              | 3713010-505                                          | MOS    |          |                                                     |          |            | 11-FEB-1982             | \$805.                     |
|                     | 13747                                                | HRS/MS | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 29-20-00                                    | AFL    |          |                                                     |          | 0          |                         |                            |
| 290215              | FUNCTIONAL TEST EMERGENCY HYDRAULIC FUSE             |        |          |                                                     |          |            |                         |                            |
| 29.110              |                                                      | MOS    | 36       |                                                     |          |            | 30-NOV-1999             | 30-NOV-2002                |
|                     |                                                      | HRS/MS | 1200     |                                                     |          | 6991       | 8191                    |                            |
|                     | REF: AMM 29-30-06                                    | AFL    |          |                                                     |          | 5163       |                         |                            |
| 290141              | PUMP, HYDRAULIC NO. 1                                |        |          |                                                     |          |            |                         | E1                         |
| 29.120              | 5713524-507                                          | MOS    |          |                                                     | 0        |            | 09-OCT-1990             |                            |
|                     | B1-58                                                | HRS/MS | O/C      |                                                     | 0        | 4718       |                         |                            |
|                     | REF: AMM 29-10-00                                    | AFL    |          |                                                     | 0        | 3309       |                         |                            |
| + 290143            | INSPECT/LUBRICATE NO.1 ENGINE HYDRAULIC PUMP SPLINES |        |          |                                                     |          |            |                         | E1                         |
| 29.120              | PKG 1, 2, 3                                          | MOS    |          |                                                     |          |            | 26-JUN-2001             |                            |
|                     |                                                      | HRS/MS | 200      |                                                     |          | 7687       |                         | 1                          |
|                     | REF: AMM 29-10-00                                    | AFL    |          |                                                     |          | 5594       |                         |                            |
| 290176              | PUMP, HYDRAULIC NO. 2                                |        |          |                                                     |          |            |                         | E2                         |
| 29.120              | 5713524-507                                          | MOS    |          |                                                     |          |            | 04-FEB-1994             |                            |
|                     | A2-84                                                | HRS/MS | O/C      |                                                     | 0        | 5390       |                         | 1                          |
|                     | REF: AMM 29-10-00                                    | AFL    |          |                                                     |          | 4040       |                         |                            |
| + 290178            | INSPECT/LUBRICATE NO.2 ENGINE HYDRAULIC PUMP SPLINES |        |          |                                                     |          |            |                         | E2                         |
| 29.120              | PKG 1, 2, 3                                          | MOS    |          |                                                     |          |            | 26-JUN-2001             |                            |
|                     |                                                      | HRS/MS | 200      |                                                     |          | 7687       |                         | 1                          |
|                     | REF: AMM 29-10-00                                    | AFL    |          |                                                     |          | 5594       |                         |                            |



Aircraft Model - 1124 WESTWIND

Report Date **11-APR-2002**

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER       | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION |     |     |     |     | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------------|--------|----------|------------------------------|-----|-----|-----|-----|----------|-------------|-------------------------|----------------------------|
|                     |                                                            |        |          | TSN                          | TSO | TSR | TSI | ADJ |          |             |                         |                            |
| 290121              | REGULATOR, RESERVOIR AIR PRESSURE                          |        |          |                              |     |     |     |     |          |             |                         | F5                         |
| 29.050              | 3713015                                                    | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         | \$1046.                    |
|                     | 509                                                        | HRSMSC | O/C      |                              | 0   |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 29-10-00                                          | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 290118              | CLEAN/CHECK HYDRAULIC RESERVOIR AIR PRESSURE CHECK VALVE   |        |          |                              |     |     |     |     |          |             |                         | F5                         |
| 29.050              | PKG 2, 3                                                   | MOS    |          |                              |     |     |     |     |          | 26-JUN-2001 |                         |                            |
|                     | 509                                                        | HRSMSC | 400      |                              |     |     |     |     |          | 7687        |                         |                            |
|                     | REF: AMM 5-20-00                                           | AFL    |          |                              |     |     |     |     |          | 5594        |                         |                            |
| + 290131            | INSPECT/REPLACE RESERVOIR AIR PRESSURE FILTER              |        |          |                              |     |     |     |     |          |             |                         | F5                         |
| 29.050              | PKG 3                                                      | MOS    |          |                              |     |     |     |     |          | 26-JUL-2000 |                         |                            |
|                     |                                                            | HRSMSC | 800      |                              |     |     |     |     |          | 7325        |                         |                            |
|                     | REF: AMM 29-10-00                                          | AFL    |          |                              |     |     |     |     |          | 5360        |                         |                            |
| + 290116            | INSPECT/REPLACE RESERVOIR AIR VENT FILTER                  |        |          |                              |     |     |     |     |          |             |                         | F5                         |
| 29.050              | PKG 3                                                      | MOS    |          |                              |     |     |     |     |          | 26-JUL-2000 |                         |                            |
|                     | 509                                                        | HRSMSC | 800      |                              |     |     |     |     |          | 7325        |                         |                            |
|                     | REF: AMM 29-10-10                                          | AFL    |          |                              |     |     |     |     |          | 5360        |                         |                            |
| 290171              | REPLACE NO.1 ENGINE HIGH PRESSURE HYDRAULIC FILTER ELEMENT |        |          |                              |     |     |     |     |          |             |                         | F5                         |
| 29.050              | PKG 3                                                      | MOS    |          |                              |     |     |     |     |          | 26-JUL-2000 |                         |                            |
|                     |                                                            | HRSMSC | 800      |                              |     |     |     |     |          | 7325        |                         |                            |
|                     | REF: AMM 29-10-10                                          | AFL    |          |                              |     |     |     |     |          | 5360        |                         |                            |
| 290206              | REPLACE NO.2 ENGINE HIGH PRESSURE HYDRAULIC FILTER ELEMENT |        |          |                              |     |     |     |     |          |             |                         | F5                         |
| 29.050              | PKG 3                                                      | MOS    |          |                              |     |     |     |     |          | 26-JUL-2000 |                         |                            |
|                     |                                                            | HRSMSC | 800      |                              |     |     |     |     |          | 7325        |                         |                            |
|                     | REF: AMM 29-10-10                                          | AFL    |          |                              |     |     |     |     |          | 5360        |                         |                            |
| 290101              | RESERVOIR, HYDRAULIC                                       |        |          |                              |     |     |     |     |          |             |                         | F5                         |
| 29.010              | 5713014-505                                                | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                                 | HRSMSC | O/C      |                              | 0   |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 29-10-00                                          | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 290106              | REPLACE FILTER                                             |        |          |                              |     |     |     |     |          |             |                         | F5                         |
| 29.010              | PKG 3                                                      | MOS    |          |                              |     |     |     |     |          | 26-JUL-2000 |                         |                            |
|                     |                                                            | HRSMSC | 800      |                              |     |     |     |     |          | 7325        |                         |                            |
|                     | REF: AMM 29-10-00                                          | AFL    |          |                              |     |     |     |     |          | 5360        |                         |                            |
| 290226              | SWITCH, EMERGENCY HYDRAULIC PRESSURE                       |        |          |                              |     |     |     |     |          |             |                         | F5                         |
| 29.090              | 4833010-515                                                | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | 872                                                        | HRSMSC | O/C      |                              | 0   |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 29-20-00                                          | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 290241              | SWITCH, NO.1 LOW HYDRAULIC PRESSURE WARNING                |        |          |                              |     |     |     |     |          |             |                         | F5                         |
| 29.170              | 4713533-1                                                  | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | 798                                                        | HRSMSC | O/C      |                              | 0   |     |     |     |          | 0           |                         | 1                          |
|                     | REF: AMM 29-30-00                                          | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 290243              | SWITCH, NO.2 LOW HYDRAULIC PRESSURE WARNING                |        |          |                              |     |     |     |     |          |             |                         | F5                         |
| 29.170              | 4713533-1                                                  | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | 788                                                        | HRSMSC | O/C      |                              | 0   |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 29-30-00                                          | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|--------|----------|-----------------------------------------------------|----------|------------|-------------------------|----------------------------|
| 290231              | TRANSMITTER, HYDRAULIC PRESSURE                      |        |          |                                                     |          |            |                         | F5                         |
| 29.150              | 3883028                                              | MOS    |          |                                                     |          |            | 11-FEB-1982             | \$507.                     |
|                     | 8005119                                              | HRS/MS | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 29-30-00                                    | AFL    |          |                                                     |          | 0          |                         |                            |
| 290133              | VALVE, BLEED RETURN                                  |        |          |                                                     |          |            |                         | F5                         |
| 29.180              | PN                                                   | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                                                     |          | 0          |                         |                            |
| 290216              | VALVE, EMERGENCY THERMAL RELIEF                      |        |          |                                                     |          |            |                         | F5                         |
| 29.070              | 4713011-1                                            | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | 1L82                                                 | HRS/MS | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                                                     |          | 0          |                         |                            |
| 290138              | VALVE, HYDRAULIC PRESSURE RELIEF                     |        |          |                                                     |          |            |                         | F5                         |
| 29.190              | 373596-501                                           | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | 158                                                  | HRS/MS | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                                                     |          | 0          |                         |                            |
| 290146              | VALVE, LEFT HYDRAULIC SHUTOFF                        |        |          |                                                     |          |            |                         | E1                         |
| 29.020              | 713020-                                              | MOS    |          |                                                     |          |            | 11-FEB-1982             | \$322.                     |
|                     | 080                                                  | HRS/MS | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 29-10-00                                    | AFL    |          |                                                     |          | 0          |                         |                            |
| 290136              | VALVE, MANUAL HIGH-PRESSURE RELIEF                   |        |          |                                                     |          |            |                         | F5                         |
| 29.030              | 3723628                                              | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                                                     |          | 0          |                         |                            |
| 290181              | VALVE, RIGHT HYDRAULIC SHUTOFF                       |        |          |                                                     |          |            |                         | E2                         |
| 29.020              | 713020-                                              | MOS    |          |                                                     |          |            | 11-FEB-1982             | \$322.                     |
|                     | 074                                                  | HRS/MS | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 29-10-00                                    | AFL    |          |                                                     |          | 0          |                         |                            |
| 290271              | VALVE, THERMAL HYDRAULIC RELIEF                      |        |          |                                                     |          |            |                         | F5                         |
| 29.190              | 3713554                                              | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | 0168                                                 | HRS/MS | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                                                     |          | 0          |                         |                            |
| CHAPTER 30          | ICE AND RAIN PROTECTION                              |        |          |                                                     |          |            |                         |                            |
| + 300133            | FUNCTIONAL CHECK PNEUMATIC DE-ICER BOOTS             |        |          |                                                     |          |            |                         | F3                         |
| 30.100              | PKG 3                                                | MOS    |          |                                                     |          |            | 26-JUL-2000             |                            |
|                     |                                                      | HRS/MS | 800      |                                                     |          | 7325       |                         |                            |
|                     | REF: AMM 30-10-00                                    | AFL    |          |                                                     |          | 5360       |                         |                            |
| + 300150            | INSPECT COPILOT WINDSHIELD CYCLING CONTACTOR         |        |          |                                                     |          |            |                         | F3                         |
| 30.140              | PKG 1, 2, 3                                          | MOS    |          |                                                     |          |            | 26-JUN-2001             |                            |
|                     |                                                      | HRS/MS | 200      |                                                     |          | 7687       |                         |                            |
|                     | REF: AMM 30-40-00                                    | AFL    |          |                                                     |          | 5594       |                         |                            |
| + 300147            | INSPECT PILOT WINDSHIELD CYCLING CONTACTOR           |        |          |                                                     |          |            |                         | F3                         |
| 30.140              | PKG 1, 2, 3                                          | MOS    |          |                                                     |          |            | 26-JUN-2001             |                            |
|                     |                                                      | HRS/MS | 200      |                                                     |          | 7687       |                         |                            |
|                     | REF: AMM 30-40-00                                    | AFL    |          |                                                     |          | 5594       |                         |                            |



Aircraft Model- 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO  | WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER                                                                  | UNIT                 | INTERVAL | TIME-----AT-----<br>TSN TSO TSR TSI ADJ | INSTALLATION | Warr Exp | COMPLIANCE                  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|----------|----------|-----------------------------------------------------------------------------------------------------------------------|----------------------|----------|-----------------------------------------|--------------|----------|-----------------------------|-------------------------|----------------------------|
| + 300163 | 30.160   | INSPECT WINDSHIELD WIPER ASSEMBLY<br>PKG 1, 2, 3                                                                      | MOS<br>HRSMSC<br>AFL | 200      |                                         |              |          | 26-JUN-2001<br>7687<br>5594 |                         |                            |
|          |          | REF: AMM 30-40-00                                                                                                     |                      |          |                                         |              |          |                             |                         |                            |
| 300170   | 30.150   | OPERATIONAL TEST P2T2 SENSOR HEATER<br>PKG 1, 2, 3                                                                    | MOS<br>HRSMSC<br>AFL | 200      |                                         |              |          | 26-JUN-2001<br>7687<br>5594 |                         |                            |
|          |          | REF: AMM 30-20-00                                                                                                     |                      |          |                                         |              |          |                             |                         |                            |
| 300165   | 30.170   | REPLACE WIPER BLADE ELEMENT<br>NOTE: IT IS RECOMMENDED TO REPLACE WIPER BLADE ELEMENT EVERY 6 MONTHS<br>OR 250 HOURS. | MOS<br>HRSMSC<br>AFL |          |                                         |              |          | 06-NOV-2001<br>7774<br>5641 |                         |                            |
|          |          | REF: AMM 30-40-00                                                                                                     |                      |          |                                         |              |          |                             |                         |                            |
| 300101   | 30.010   | CHECK VALVE, DE-ICER LEFT<br>PN<br>SN-UNKNOWN<br>REF: AMM 30-10-00                                                    | MOS<br>HRSMSC<br>AFL | O/C      | 0                                       |              |          | 11-FEB-1982<br>0<br>0       |                         | F4                         |
| + 300102 | 30.010   | INSPECT<br>PKG 2, 3                                                                                                   | MOS<br>HRSMSC<br>AFL | 400      |                                         |              |          | 26-JUN-2001<br>7687<br>5594 |                         | F4                         |
|          |          | REF: AMM 30-10-00                                                                                                     |                      |          |                                         |              |          |                             |                         |                            |
| 300103   | 30.010   | CHECK VALVE, DE-ICER RIGHT<br>PN<br>SN-UNKNOWN<br>REF: AMM 30-10-00                                                   | MOS<br>HRSMSC<br>AFL | O/C      | 0                                       |              |          | 11-FEB-1982<br>0<br>0       |                         | F4                         |
| + 300104 | 30.010   | INSPECT<br>PKG 2, 3                                                                                                   | MOS<br>HRSMSC<br>AFL | 400      |                                         |              |          | 26-JUN-2001<br>7687<br>5594 |                         | F4                         |
|          |          | REF: AMM 30-10-00                                                                                                     |                      |          |                                         |              |          |                             |                         |                            |
| 300146   | 30.110   | CONTROLLER, WINDSHIELD TEMPERATURE LEFT<br>HYLZ9661<br>982B<br>REF: AMM 30-40-00                                      | MOS<br>HRSMSC<br>AFL | O/C      | 0<br>0<br>0                             |              |          | 22-FEB-2000<br>7107<br>5232 |                         | F3                         |
| 300148   | 30.110   | CONTROLLER, WINDSHIELD TEMPERATURE RIGHT<br>833034-1<br>SN-UNKNOWN<br>REF: AMM 30-40-00                               | MOS<br>HRSMSC<br>AFL | O/C      | 0                                       |              |          | 11-FEB-1982<br>0<br>0       |                         | F3                         |
| 300111   | 30.030   | EJECTOR, AIR<br>850278-1<br>RF3295<br>REF: AMM 30-10-00                                                               | MOS<br>HRSMSC<br>AFL | O/C      | 0                                       |              |          | 11-FEB-1982<br>0<br>0       |                         | F4                         |
| 300156   | 30.130   | MOTOR, WINDSHIELD WIPER LEFT<br>XW21126-315-R32<br>2-22826<br>REF: AMM 30-40-00                                       | MOS<br>HRSMSC<br>AFL | O/C      | 0<br>0<br>0                             |              |          | 26-JUL-2000<br>7325<br>5360 |                         | F3<br>\$354.<br>7          |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|--------|----------|-----------------------------------------------------|----------|------------|-------------------------|----------------------------|
| 300161              | MOTOR, WINDSHIELD WIPER RIGHT                        |        |          |                                                     |          |            |                         |                            |
| 30.130              | 5823099-402                                          | MOS    |          |                                                     |          |            | 11-FEB-1982             | F3                         |
|                     | 213743                                               | HRSMSC | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 30-40-00                                    | AFL    |          |                                                     |          | 0          |                         |                            |
| 300106              | REGULATOR, PRESSURE                                  |        |          |                                                     |          |            |                         |                            |
| 30.020              | 4753042-501                                          | MOS    |          |                                                     |          |            | 11-FEB-1982             | F4                         |
|                     | 3300U                                                | HRSMSC | O/C      | 0                                                   |          | 0          |                         | \$403.                     |
|                     | REF: AMM 30-10-00                                    | AFL    |          |                                                     |          | 0          |                         |                            |
| 300116              | SWITCH, PRESSURE                                     |        |          |                                                     |          |            |                         |                            |
| 30.040              | 3753045-507                                          | MOS    |          |                                                     |          |            | 31-OCT-1992             | F4                         |
|                     | 287                                                  | HRSMSC | O/C      | 0                                                   |          | 5170       |                         |                            |
|                     | REF: AMM 30-10-00                                    | AFL    |          |                                                     |          | 3802       |                         |                            |
| 300141              | SWITCH, PRESSURE INDICATOR NO. 1 ENGINE              |        |          |                                                     |          |            |                         |                            |
| 30.090              | 12299                                                | MOS    |          |                                                     |          |            | 11-FEB-1982             | E1                         |
|                     | SN-UNKNOWN                                           | HRSMSC | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 30-20-00                                    | AFL    |          |                                                     |          | 0          |                         |                            |
| 300144              | SWITCH, PRESSURE INDICATOR NO. 2 ENGINE              |        |          |                                                     |          |            |                         |                            |
| 30.090              | 12299                                                | MOS    |          |                                                     |          | 06/29/1993 | 29-DEC-1992             | E2                         |
|                     | 1246                                                 | HRSMSC | O/C      | 0                                                   |          | 5203       |                         |                            |
|                     | REF: AMM 30-20-00                                    | AFL    |          |                                                     |          | 4938       |                         |                            |
| 300121              | SWITCH, VACUUM                                       |        |          |                                                     |          |            |                         |                            |
| 30.050              | 3-753064-501                                         | MOS    |          |                                                     |          |            | 11-FEB-1982             | F4                         |
|                     | 277                                                  | HRSMSC | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 30-10-00                                    | AFL    |          |                                                     |          | 0          |                         |                            |
| 300151              | SWITCH, WINDSHIELD THERMOSTAT LEFT                   |        |          |                                                     |          |            |                         |                            |
| 30.120              | PN                                                   | MOS    |          |                                                     |          |            | 11-FEB-1982             | F3                         |
|                     | SN-UNKNOWN                                           | HRSMSC | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 30-40-00                                    | AFL    |          |                                                     |          | 0          |                         |                            |
| 300153              | SWITCH, WINDSHIELD THERMOSTAT RIGHT                  |        |          |                                                     |          |            |                         |                            |
| 30.120              | PN                                                   | MOS    |          |                                                     |          |            | 11-FEB-1982             | F3                         |
|                     | SN-UNKNOWN                                           | HRSMSC | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 30-40-00                                    | AFL    |          |                                                     |          | 0          |                         |                            |
| 300131              | TIMER, DE-ICER                                       |        |          |                                                     |          |            |                         |                            |
| 30.070              | 3-753046-1                                           | MOS    |          |                                                     |          |            | 11-FEB-1982             | F4                         |
|                     | G426                                                 | HRSMSC | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 30-10-00                                    | AFL    |          |                                                     |          | 0          |                         |                            |
| 300126              | VALVE, DISTRIBUTOR                                   |        |          |                                                     |          |            |                         |                            |
| 30.060              | 753511-1                                             | MOS    |          |                                                     |          |            | 11-FEB-1982             | F4                         |
|                     | 41359U                                               | HRSMSC | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 30-10-00                                    | AFL    |          |                                                     |          | 0          |                         |                            |
| 300136              | VALVE, NO. 1 NACELLE ANTI-ICE                        |        |          |                                                     |          |            |                         |                            |
| 30.080              | F10A-5-SCP-102-5                                     | MOS    |          |                                                     |          |            | 30-JAN-1984             | E1                         |
|                     | 193RW                                                | HRSMSC | O/C      | 0                                                   |          | 1468       |                         |                            |
|                     | REF: AMM 30-20-00                                    | AFL    |          |                                                     |          | 908        |                         |                            |



Aircraft Model - 1124 WESTWIND

Report Date **11-APR-2002**

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD                            | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER                                       | UNIT                  | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE                  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|------------------------------------------------|--------------------------------------------------------------------------------------------|-----------------------|----------|-----------------------------------------------------|----------|-----------------------------|-------------------------|----------------------------|
| 300138<br>30.080                               | VALVE, NO.2 NACELLE ANTI-ICE<br>F10A-5-SCP-102-5<br>8100435<br>REF: AMM 30-20-00           | MOS<br>HRS/MSC<br>AFL | O/C      | 0                                                   |          | 12-OCT-1983<br>1321<br>810  |                         | E2                         |
| <b>CHAPTER 31 INDICATING/RECORDING SYSTEMS</b> |                                                                                            |                       |          |                                                     |          |                             |                         |                            |
| 310101<br>31.010                               | CLOCK, COCKPIT DIGITAL<br>811-B<br>15324<br>REF: NO REF                                    | MOS<br>HRS/MSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | F3                         |
| <b>CHAPTER 32 LANDING GEAR</b>                 |                                                                                            |                       |          |                                                     |          |                             |                         |                            |
| 321189U                                        | -- REPL SPARE MAIN WHEEL BLT                                                               | MOS<br>HRS/MSC<br>AFL | O/C      |                                                     |          | 26-NOV-1989<br>4427<br>2984 |                         |                            |
| 322136<br>32.400                               | BLEED BRAKE SYSTEM<br>REF: AMM 32-43-00                                                    | MOS<br>HRS/MSC<br>AFL | O/C      |                                                     |          | 17-JAN-2001<br>7494<br>5466 |                         | L2                         |
| 320678<br>32.550                               | DYE PENETRANT CHECK LEFT WHEEL AXLE<br>PKG 2, 3<br>REF: AMM 5-20-04                        | MOS<br>HRS/MSC<br>AFL | 400      |                                                     |          | 26-JUN-2001<br>7687<br>5594 |                         | L1                         |
| 321178<br>32.550                               | DYE PENETRANT CHECK RIGHT WHEEL AXLE<br>PKG 2, 3<br>REF: AMM 5-20-04                       | MOS<br>HRS/MSC<br>AFL | 400      |                                                     |          | 26-JUN-2001<br>7687<br>5594 |                         | L2                         |
| + 322176<br>32.420                             | FUNCTIONAL CHECK ANTI-SKID DETECTOR SYSTEM<br>PKG 2, 3<br>REF: AMM 32-44-00                | MOS<br>HRS/MSC<br>AFL | 400      |                                                     |          | 26-JUN-2001<br>7687<br>5594 |                         | F3                         |
| + 322211<br>32.450                             | FUNCTIONAL TEST EMERGENCY GEAR EXTENSION<br>PKG 3<br>REF: AMM 32-30-00                     | MOS<br>HRS/MSC<br>AFL | 800      |                                                     |          | 26-JUL-2000<br>7325<br>5360 |                         | F3                         |
| + 322206<br>32.440                             | FUNCTIONAL TEST EMERGENCY GEAR EXTENSION CONTROL CABLE<br>PKG 1, 2, 3<br>REF: AMM 32-30-00 | MOS<br>HRS/MSC<br>AFL | 200      |                                                     |          | 26-JUN-2001<br>7687<br>5594 |                         | F3                         |
| + 322191<br>32.430                             | FUNCTIONAL TEST LANDING GEAR (NORMAL)<br>PKG 2, 3<br>REF: AMM 32-30-00                     | MOS<br>HRS/MSC<br>AFL | 400      |                                                     |          | 26-JUN-2001<br>7687<br>5594 |                         | F3                         |
| + 322201<br>32.430                             | FUNCTIONAL TEST LANDING GEAR FREE FALL<br>PKG 2, 3<br>REF: See Workcard                    | MOS<br>HRS/MSC<br>AFL | 400      |                                                     |          | 26-JUN-2001<br>7687<br>5594 |                         | F3                         |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER  | UNIT                  | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE                  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|-------------------------------------------------------|-----------------------|----------|-----------------------------------------------------|----------|-----------------------------|-------------------------|----------------------------|
| + 320691<br>32.020  | INSPECT LEFT MAIN GEAR/WELL (A)<br>PKG 1, 2, 3        | MOS<br>HRS/MSA<br>AFL | 200      |                                                     |          | 26-JUN-2001<br>7687<br>5594 |                         | L1<br>1.5                  |
|                     | REF: AMM 5-20-04                                      |                       |          |                                                     |          |                             |                         |                            |
| + 320201<br>32.0101 | INSPECT NOSE GEAR (A)<br>PKG 1, 2, 3                  | MOS<br>HRS/MSA<br>AFL | 200      |                                                     |          | 26-JUN-2001<br>7687<br>5594 |                         | L3<br>1.5                  |
|                     | REF: AMM 5-20-01                                      |                       |          |                                                     |          |                             |                         |                            |
| + 320206<br>32.0102 | INSPECT NOSE GEAR (B)<br>PKG 2, 3                     | MOS<br>HRS/MSA<br>AFL | 400      |                                                     |          | 26-JUN-2001<br>7687<br>5594 |                         | L3                         |
|                     | REF: AMM 5-20-01                                      |                       |          |                                                     |          |                             |                         |                            |
| + 322156<br>32.410  | INSPECT/CLEAN LEFT ANTI-SKID DETECTOR<br>PKG 1, 2, 3  | MOS<br>HRS/MSA<br>AFL | 200      |                                                     |          | 26-JUN-2001<br>7687<br>5594 |                         | L1<br>1                    |
|                     | REF: AMM 5-20-04                                      |                       |          |                                                     |          |                             |                         |                            |
| + 322171<br>32.410  | INSPECT/CLEAN RIGHT ANTI-SKID DETECTOR<br>PKG 1, 2, 3 | MOS<br>HRS/MSA<br>AFL | 200      |                                                     |          | 26-JUN-2001<br>7687<br>5594 |                         | L2<br>1                    |
|                     | REF: AMM 5-20-04                                      |                       |          |                                                     |          |                             |                         |                            |
| 320607<br>32.570    | LUBRICATE LEFT ACTUATOR BOLTS<br>PKG 2, 3             | MOS<br>HRS/MSA<br>AFL | 400      |                                                     |          | 26-JUN-2001<br>7687<br>5594 |                         | L1                         |
|                     | REF: AMM 5-20-04/SL WW-2494R3                         |                       |          |                                                     |          |                             |                         |                            |
| 321107<br>32.570    | LUBRICATE RIGHT ACTUATOR BOLTS<br>PKG 2, 3            | MOS<br>HRS/MSA<br>AFL | 400      |                                                     |          | 26-JUN-2001<br>7687<br>5594 |                         | L2                         |
|                     | REF: AMM 5-20-04/SL WW-2494R3                         |                       |          |                                                     |          |                             |                         |                            |
| + 322174<br>32.425  | OPERATIONAL CHECK ANTI-SKID LIGHTS<br>PKG 1, 2, 3     | MOS<br>HRS/MSA<br>AFL | 200      |                                                     |          | 26-JUN-2001<br>7687<br>5594 |                         | F3<br>.5                   |
|                     | REF: AMM 32-44-00                                     |                       |          |                                                     |          |                             |                         |                            |
| 320686<br>32.180    | REPLACE LEFT MAIN WHEEL BOLTS                         | MOS<br>HRS/MSA<br>AFL | O/C      |                                                     |          | 09-NOV-1996<br>5951<br>4589 |                         | L1                         |
|                     | REF: NO REF                                           |                       |          |                                                     |          |                             |                         |                            |
| 321186<br>32.180    | REPLACE RIGHT MAIN WHEEL BOLTS                        | MOS<br>HRS/MSA<br>AFL | O/C      |                                                     |          | 09-NOV-1996<br>5951<br>4589 |                         | L2                         |
|                     | REF: NO REF                                           |                       |          |                                                     |          |                             |                         |                            |
| 320186<br>32.150    | RIG STEERING SYSTEM                                   | MOS<br>HRS/MSA<br>AFL | C/C      |                                                     |          | 11-FEB-1982<br>0<br>0       |                         | L3                         |
|                     | REF: AMM 32-50-00                                     |                       |          |                                                     |          |                             |                         |                            |



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEMNO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----<br>TSN TSO TSR TSI ADJ | INSTALLATION | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|--------------------|------------------------------------------------------|--------|----------|-----------------------------------------|--------------|----------|-------------|-------------------------|----------------------------|
| 320621             | AXLE, PISTON ROD FORK/ LEFT                          |        |          |                                         |              |          |             |                         | L1                         |
| 32.220             | ES12908-503                                          | MOS    |          |                                         |              |          | 11-FEB-1982 |                         |                            |
|                    | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                                       |              |          | 0           |                         |                            |
|                    | REF: AMM 32-20-01                                    | AFL    |          |                                         |              |          | 0           |                         |                            |
| 321121             | AXLE, PISTON ROD FORK/ RIGHT                         |        |          |                                         |              |          |             |                         | L2                         |
| 32.220             | ES12908-504                                          | MOS    |          |                                         |              |          | 11-FEB-1982 |                         |                            |
|                    | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                                       |              |          | 0           |                         |                            |
|                    | REF: AMM 32-20-01                                    | AFL    |          |                                         |              |          | 0           |                         |                            |
| 321611             | BOTTLE, EMERGENCY STORAGE                            |        |          |                                         |              |          |             | LIFE LIMIT              | F5                         |
| 32.350             | 3753015-501                                          | MOS    | 288      | 0                                       |              |          | 11-FEB-1982 | 11-FEB-2006             |                            |
|                    | 07510A1                                              | HRS/MS |          | 0                                       |              |          | 0           |                         | 1                          |
|                    | REF: AMM 32-30-12                                    | AFL    |          | 0                                       |              |          | 0           |                         |                            |
| + 321616           | CHECK LANDING GEAR EMERGENCY SYSTEM PRESSURE         |        |          |                                         |              |          |             |                         | F5                         |
| 32.350             | PKG 2, 3                                             | MOS    |          |                                         |              |          | 26-JUN-2001 |                         |                            |
|                    |                                                      | HRS/MS | 400      |                                         |              |          | 7687        |                         |                            |
|                    | REF: AMM 12-10-04                                    | AFL    |          |                                         |              |          | 5594        |                         |                            |
| + 321613           | HYDROSTATIC TEST                                     |        |          |                                         |              |          |             |                         | F5                         |
| 32.350             |                                                      | MOS    | 36       |                                         |              |          | 26-OCT-1999 | 26-OCT-2002             |                            |
|                    |                                                      | HRS/MS |          |                                         |              |          | 6961        |                         |                            |
|                    | REF: AMM 32-30-12                                    | AFL    |          |                                         |              |          | 5135        |                         |                            |
| 320171             | BRACE ASSEMBLY, DRAG NOSE GEAR                       |        |          |                                         |              |          |             |                         | L3                         |
| 32.240             | PN                                                   | MOS    |          |                                         |              |          | 11-FEB-1982 |                         |                            |
|                    | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                                       |              |          | 0           |                         |                            |
|                    | REF: AMM 32-20-02                                    | AFL    |          |                                         |              |          | 0           |                         |                            |
| 320173             | ADJUST PRELOAD                                       |        |          |                                         |              |          |             |                         | L3                         |
| 32.240             |                                                      | MOS    |          |                                         |              |          | 11-FEB-1982 |                         |                            |
|                    |                                                      | HRS/MS | C/C      |                                         |              |          | 0           |                         |                            |
|                    | REF: AMM 32-20-02                                    | AFL    |          |                                         |              |          | 0           |                         |                            |
| 320611             | BRACE ASSEMBLY, SIDE/JURY LEFT MAIN GEAR             |        |          |                                         |              |          |             |                         | L1                         |
| 32.230             | EA1681-503                                           | MOS    |          |                                         |              |          | 11-FEB-1982 |                         |                            |
|                    | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                                       |              |          | 0           |                         |                            |
|                    | REF: AMM 32-10-02                                    | AFL    |          |                                         |              |          | 0           |                         |                            |
| 320616             | ADJUST LEFT JURY BRACE PRELOAD                       |        |          |                                         |              |          |             |                         | L1                         |
| 32.230             |                                                      | MOS    |          |                                         |              |          | 11-FEB-1982 |                         |                            |
|                    |                                                      | HRS/MS | C/C      |                                         |              |          | 0           |                         |                            |
|                    | REF: AMM 32-10-02                                    | AFL    |          |                                         |              |          | 0           |                         |                            |
| 321111             | BRACE ASSEMBLY, SIDE/JURY RIGHT MAIN GEAR            |        |          |                                         |              |          |             |                         | L2                         |
| 32.230             | EA1681-503                                           | MOS    |          |                                         |              |          | 11-FEB-1982 |                         |                            |
|                    | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                                       |              |          | 0           |                         |                            |
|                    | REF: AMM 32-10-02                                    | AFL    |          |                                         |              |          | 0           |                         |                            |
| 321116             | ADJUST RIGHT JURY BRACE PRELOAD                      |        |          |                                         |              |          |             |                         | L2                         |
| 32.230             |                                                      | MOS    |          |                                         |              |          | 11-FEB-1982 |                         |                            |
|                    |                                                      | HRS/MS | C/C      |                                         |              |          | 0           |                         |                            |
|                    | REF: AMM 32-10-02                                    | AFL    |          |                                         |              |          | 0           |                         |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Page 44 of 107



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD                | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER                                     | UNIT                 | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE                  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|------------------------------------|------------------------------------------------------------------------------------------|----------------------|----------|-----------------------------------------------------|----------|-----------------------------|-------------------------|----------------------------|
| 320232<br>32.600                   | BRACKET, LOWER STEERING NOSE GEAR<br>A0122360300-001<br>SN-UNKNOWN<br>REF: AMM 32-50-08  | MOS<br>HRS/MS<br>AFL | O/C      |                                                     |          | 22-FEB-2000<br>7107<br>5232 |                         | L3                         |
| + 320238<br>32.600                 | INSPECT<br><br>REF: AMM 32-50-08                                                         | MOS<br>HRS/MS<br>AFL | 1600     |                                                     |          | 22-FEB-2000<br>7107<br>5232 | 8707                    | L3                         |
| SB 1124-32-139 LOWER<br>ASSOCIATED | LANDING GEAR SERVICE BULLETIN<br><br>REF:<br>Method of Compliance: OPEN                  | MOS<br>HRS/MS<br>AFL | A/R      |                                                     |          | 0<br>0                      |                         |                            |
| 320231<br>32.600                   | BRACKET, UPPER STEERING NOSE GEAR<br>A01223603000-001<br>SN-UNKNOWN<br>REF: AMM 32-50-08 | MOS<br>HRS/MS<br>AFL | O/C      |                                                     |          | 22-FEB-2000<br>7107<br>5232 |                         | L3                         |
| + 320237<br>32.600                 | INSPECT<br><br>REF: AMM 32-50-08                                                         | MOS<br>HRS/MS<br>AFL | 1600     |                                                     |          | 22-FEB-2000<br>7107<br>5232 | 8707                    | L3                         |
| SB 1124-32-139 UPPER<br>ASSOCIATED | LANDING GEAR SERVICE BULLETIN<br>PKG 3<br><br>REF:<br>Method of Compliance: OPEN         | MOS<br>HRS/MS<br>AFL | 800      |                                                     |          | 26-JUL-2000<br>7325<br>5360 | 8125                    |                            |
| 322113<br>32.390                   | BRAKE, LEFT MAIN GEAR<br>5002805-3<br>21139-1<br>REF: AMM 32-43-01                       | MOS<br>HRS/MS<br>AFL | O/C      | 0<br>0<br>0                                         |          | 17-JAN-2001<br>7494<br>5466 |                         | L1<br>\$1978.<br>2         |
| 322136<br>32.400<br>ASSOCIATED     | BLEED BRAKE SYSTEM<br><br>REF: AMM 32-43-00                                              | MOS<br>HRS/MS<br>AFL | O/C      |                                                     |          | 17-JAN-2001<br>7494<br>5466 |                         | L2                         |
| + 322116<br>32.390                 | INSPECT/CHECK LEFT BRAKE LININGS<br>PKG 1, 2, 3<br><br>REF: AMM 32-43-01                 | MOS<br>HRS/MS<br>AFL | 200      |                                                     |          | 26-JUN-2001<br>7687<br>5594 | 1                       | L1                         |
| 322128<br>32.390                   | BRAKE, RIGHT MAIN GEAR<br>5002805-3<br>JAN86-531<br>REF: AMM 32-43-01                    | MOS<br>HRS/MS<br>AFL | O/C      | 0<br>0<br>0                                         |          | 17-JAN-2001<br>7494<br>5466 |                         | L2<br>\$1978.<br>2         |
| 322136<br>32.400<br>ASSOCIATED     | BLEED BRAKE SYSTEM<br><br>REF: AMM 32-43-00                                              | MOS<br>HRS/MS<br>AFL | O/C      |                                                     |          | 17-JAN-2001<br>7494<br>5466 |                         | L2                         |



**Aircraft Model - 1124 WESTWIND**
**Report Date 11-APR-2002**
**Owner Name - R&S AIRCRAFT INVESTMENTS, LLC**
**A/C Serial #: 368 A/C Reg. #: N368MD**

| ITEM NO  | WORKCARD   | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER       | UNIT                 | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE                  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|----------|------------|------------------------------------------------------------|----------------------|----------|-----------------------------------------------------|----------|-----------------------------|-------------------------|----------------------------|
| + 322131 | 32.390     | INSPECT/CHECK RIGHT BRAKE LININGS<br>PKG 1, 2, 3           | MOS<br>HRS/MS<br>AFL | 200      |                                                     |          | 26-JUN-2001<br>7687<br>5594 |                         | L2<br>1                    |
|          |            | REF: AMM 32-43-01                                          |                      |          |                                                     |          |                             |                         |                            |
| 322141   | 32.490     | CONTROL BOX, ANTI-SKID<br>5-823519-503                     | MOS<br>HRS/MS<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | F5<br>2                    |
|          |            | REF: AMM 32-44-01                                          |                      |          |                                                     |          |                             |                         |                            |
| + 322176 | 32.420     | FUNCTIONAL CHECK ANTI-SKID DETECTOR SYSTEM<br>PKG 2, 3     | MOS<br>HRS/MS<br>AFL | 400      |                                                     |          | 26-JUN-2001<br>7687<br>5594 |                         | F3<br>1                    |
|          | ASSOCIATED | REF: AMM 32-44-00                                          |                      |          |                                                     |          |                             |                         |                            |
| 320121   | 32.060     | CYLINDER, ACTUATOR NOSE GEAR<br>5713059-505                | MOS<br>HRS/MS<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | L3<br>\$483.<br>3          |
|          |            | REF: AMM 32-30-06                                          |                      |          |                                                     |          |                             |                         |                            |
| 320646   | 32.310     | CYLINDER, AFT ACTUATING LEFT MAIN GEAR<br>5713061-505      | MOS<br>HRS/MS<br>AFL | O/C      |                                                     |          | 09-JUN-1989<br>4274<br>2800 |                         | L1<br>\$443.               |
|          |            | SN-UNKNOWN                                                 |                      |          |                                                     |          |                             |                         |                            |
|          |            | REF: AMM 32-30-03                                          |                      |          |                                                     |          |                             |                         |                            |
| 321146   | 32.310     | CYLINDER, AFT ACTUATING RIGHT MAIN GEAR<br>5713061-505     | MOS<br>HRS/MS<br>AFL | O/C      | 0                                                   |          | 13-NOV-1995<br>5718<br>4397 |                         | L2<br>\$443.               |
|          |            | REF: AMM 32-30-03                                          |                      |          |                                                     |          |                             |                         |                            |
| 320641   | 32.300     | CYLINDER, FORWARD ACTUATING LEFT MAIN GEAR<br>5713061-505  | MOS<br>HRS/MS<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | L1<br>\$443.               |
|          |            | REF: AMM 32-30-03                                          |                      |          |                                                     |          |                             |                         |                            |
| 321141   | 32.300     | CYLINDER, FORWARD ACTUATING RIGHT MAIN GEAR<br>5713061-505 | MOS<br>HRS/MS<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | L2<br>\$443.               |
|          |            | REF: AMM 32-30-03                                          |                      |          |                                                     |          |                             |                         |                            |
| 320181   | 32.140     | CYLINDER, STEERING ACTUATING LEFT<br>4713096-509           | MOS<br>HRS/MS<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | L3<br>5                    |
|          |            | REF: AMM 32-50-02                                          |                      |          |                                                     |          |                             |                         |                            |
| 320184   | 32.140     | CYLINDER, STEERING ACTUATING RIGHT<br>4713096-509          | MOS<br>HRS/MS<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | L3<br>5                    |
|          |            | REF: AMM 32-50-02                                          |                      |          |                                                     |          |                             |                         |                            |
| 320651   | 32.260     | CYLINDER, UNLOCK LEFT MAIN GEAR<br>4713058-505             | MOS<br>HRS/MS<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | L1                         |
|          |            | REF: AMM 32-30-05                                          |                      |          |                                                     |          |                             |                         |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L



Aircraft Model - 1124 WESTWIND  
 Owner Name - R&S AIRCRAFT INVESTMENTS, LLC  
 A/C Serial #: 368 A/C Reg. #: N368MD

Report Date **11-APR-2002**

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|--------|----------|-----------------------------------------------------|----------|------------|-------------------------|----------------------------|
| 321151              | CYLINDER, UNLOCK RIGHT MAIN GEAR                     |        |          |                                                     |          |            |                         | L2                         |
| 32.260              | 4713058-505                                          | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | 1091                                                 | HRSMSC | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 32-30-05                                    | AFL    |          |                                                     |          | 0          |                         |                            |
| 320126              | CYLINDER, UNLOCK NOSE GEAR                           |        |          |                                                     |          |            |                         | L3                         |
| 32.070              | 4713005-501                                          | MOS    |          |                                                     |          | 06/08/1995 | 08-DEC-1994             |                            |
|                     | 0567                                                 | HRSMSC | O/C      | 0                                                   |          | 5526       |                         |                            |
|                     | REF: AMM 32-30-08                                    | AFL    |          |                                                     |          | 4218       |                         |                            |
| 322151              | DETECTOR, ANTI-SKID LEFT MAIN GEAR                   |        |          |                                                     |          |            |                         | L1                         |
| 32.410              | 5-713513-503                                         | MOS    |          |                                                     |          |            | 13-JUL-1988             | \$1064.                    |
|                     | 200                                                  | HRSMSC | O/C      | 0                                                   |          | 3978       |                         | 1                          |
|                     | REF: AMM 32-44-06                                    | AFL    |          |                                                     |          | 2511       |                         |                            |
| + 322176            | FUNCTIONAL CHECK ANTI-SKID DETECTOR SYSTEM           |        |          |                                                     |          |            |                         | F3                         |
| 32.420              | PKG 2, 3                                             | MOS    |          |                                                     |          |            | 26-JUN-2001             |                            |
| ASSOCIATED          |                                                      | HRSMSC | 400      |                                                     |          | 7687       |                         | 1                          |
|                     | REF: AMM 32-44-00                                    | AFL    |          |                                                     |          | 5594       |                         |                            |
| + 322156            | INSPECT/CLEAN LEFT ANTI-SKID DETECTOR                |        |          |                                                     |          |            |                         | L1                         |
| 32.410              | PKG 1, 2, 3                                          | MOS    |          |                                                     |          |            | 26-JUN-2001             |                            |
| ASSOCIATED          |                                                      | HRSMSC | 200      |                                                     |          | 7687       |                         | 1                          |
|                     | REF: AMM 5-20-04                                     | AFL    |          |                                                     |          | 5594       |                         |                            |
| + 322174            | OPERATIONAL CHECK ANTI-SKID LIGHTS                   |        |          |                                                     |          |            |                         | F3                         |
| 32.425              | PKG 1, 2, 3                                          | MOS    |          |                                                     |          |            | 26-JUN-2001             |                            |
| ASSOCIATED          |                                                      | HRSMSC | 200      |                                                     |          | 7687       |                         | .5                         |
|                     | REF: AMM 32-44-00                                    | AFL    |          |                                                     |          | 5594       |                         |                            |
| 322166              | DETECTOR, ANTI-SKID RIGHT MAIN GEAR                  |        |          |                                                     |          |            |                         | L2                         |
| 32.410              | 5-713513-504                                         | MOS    |          |                                                     |          |            | 17-DEC-1983             | \$1064.                    |
|                     | 553                                                  | HRSMSC | O/C      | 0                                                   |          | 1454       |                         | 1                          |
|                     | REF: AMM 32-44-06                                    | AFL    |          |                                                     |          | 878        |                         |                            |
| + 322176            | FUNCTIONAL CHECK ANTI-SKID DETECTOR SYSTEM           |        |          |                                                     |          |            |                         | F3                         |
| 32.420              | PKG 2, 3                                             | MOS    |          |                                                     |          |            | 26-JUN-2001             |                            |
| ASSOCIATED          |                                                      | HRSMSC | 400      |                                                     |          | 7687       |                         | 1                          |
|                     | REF: AMM 32-44-00                                    | AFL    |          |                                                     |          | 5594       |                         |                            |
| + 322171            | INSPECT/CLEAN RIGHT ANTI-SKID DETECTOR               |        |          |                                                     |          |            |                         | L2                         |
| 32.410              | PKG 1, 2, 3                                          | MOS    |          |                                                     |          |            | 26-JUN-2001             |                            |
| ASSOCIATED          |                                                      | HRSMSC | 200      |                                                     |          | 7687       |                         | 1                          |
|                     | REF: AMM 5-20-04                                     | AFL    |          |                                                     |          | 5594       |                         |                            |
| + 322174            | OPERATIONAL CHECK ANTI-SKID LIGHTS                   |        |          |                                                     |          |            |                         | F3                         |
| 32.425              | PKG 1, 2, 3                                          | MOS    |          |                                                     |          |            | 26-JUN-2001             |                            |
| ASSOCIATED          |                                                      | HRSMSC | 200      |                                                     |          | 7687       |                         | .5                         |
|                     | REF: AMM 32-44-00                                    | AFL    |          |                                                     |          | 5594       |                         |                            |
| 322111              | FUSE, BRAKE HYDRAULIC LEFT                           |        |          |                                                     |          |            |                         | W1                         |
| 32.380              | 3-713047                                             | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | 1797                                                 | HRSMSC | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 32-43-04                                    | AFL    |          |                                                     |          | 0          |                         |                            |



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO            | WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER   | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|--------------------|----------|--------------------------------------------------------|--------|----------|-----------------------------------------------------|----------|-------------|-------------------------|----------------------------|
| 322126             |          | FUSE, BRAKE HYDRAULIC RIGHT                            |        |          |                                                     |          |             |                         | W2                         |
| 32.380             |          | 3-713047                                               | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                    |          | 3371                                                   | HRS/MS | O/C      | 0                                                   |          | 0           |                         |                            |
|                    |          | REF: AMM 32-43-04                                      | AFL    |          |                                                     |          | 0           |                         |                            |
| 320601             |          | GEAR ASSEMBLY, MAIN LEFT                               |        |          |                                                     |          |             |                         | L1                         |
| 32.210             |          | 400-144-511                                            | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                    |          | 1L195                                                  | HRS/MS | O/C      | 0                                                   |          | 0           |                         |                            |
|                    |          | REF: AMM 32-10-01                                      | AFL    |          |                                                     |          | 0           |                         |                            |
| 320631             |          | CHECK MAIN GEAR PARALLELISM                            |        |          |                                                     |          |             |                         | L1                         |
| 32.470             |          |                                                        | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                    |          |                                                        | HRS/MS | C/C      |                                                     |          | 0           |                         |                            |
|                    |          | REF: AMM 32-10-01                                      | AFL    |          |                                                     |          | 0           |                         |                            |
| 320634             |          | CHECK LEFT MAIN GEAR CLEARANCE                         |        |          |                                                     |          |             |                         | L1                         |
| 32.480             |          |                                                        | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                    |          |                                                        | HRS/MS | C/C      |                                                     |          | 0           |                         |                            |
|                    |          | REF: AMM 32-10-01                                      | AFL    |          |                                                     |          | 0           |                         |                            |
| + 322211           |          | FUNCTIONAL TEST EMERGENCY GEAR EXTENSION               |        |          |                                                     |          |             |                         | F3                         |
| 32.450             |          | PKG 3                                                  | MOS    |          |                                                     |          | 26-JUL-2000 |                         |                            |
| ASSOCIATED         |          |                                                        | HRS/MS | 800      |                                                     |          | 7325        |                         |                            |
|                    |          | REF: AMM 32-30-00                                      | AFL    |          |                                                     |          | 5360        |                         |                            |
| + 322208           |          | FUNCTIONAL TEST EMERGENCY GEAR EXTENSION CONTROL CABLE |        |          |                                                     |          |             |                         | F3                         |
| 32.440             |          | PKG 1, 2, 3                                            | MOS    |          |                                                     |          | 26-JUN-2001 |                         |                            |
| ASSOCIATED         |          |                                                        | HRS/MS | 200      |                                                     |          | 7687        |                         | 1                          |
|                    |          | REF: AMM 32-30-00                                      | AFL    |          |                                                     |          | 5594        |                         |                            |
| + 322191           |          | FUNCTIONAL TEST LANDING GEAR (NORMAL)                  |        |          |                                                     |          |             |                         | F3                         |
| 32.430             |          | PKG 2, 3                                               | MOS    |          |                                                     |          | 26-JUN-2001 |                         |                            |
| ASSOCIATED         |          |                                                        | HRS/MS | 400      |                                                     |          | 7687        |                         |                            |
|                    |          | REF: AMM 32-30-00                                      | AFL    |          |                                                     |          | 5594        |                         |                            |
| + 322201           |          | FUNCTIONAL TEST LANDING GEAR FREE FALL                 |        |          |                                                     |          |             |                         | F3                         |
| 32.430             |          | PKG 2, 3                                               | MOS    |          |                                                     |          | 26-JUN-2001 |                         |                            |
| ASSOCIATED         |          |                                                        | HRS/MS | 400      |                                                     |          | 7687        |                         |                            |
|                    |          | REF: See Workcard                                      | AFL    |          |                                                     |          | 5594        |                         |                            |
| SL WW-2494 R3 LEFT |          | LANDING GEAR SERVICE LETTER                            |        |          |                                                     |          |             |                         | L1                         |
| ASSOCIATED         |          |                                                        | MOS    |          |                                                     |          | 26-JUN-2001 |                         |                            |
|                    |          |                                                        | HRS/MS | 300      |                                                     |          | 7687        | 7987                    |                            |
|                    |          | REF: See Workcard                                      | AFL    |          |                                                     |          | 5594        |                         |                            |
|                    |          | Method of Compliance: OPEN                             |        |          |                                                     |          |             |                         |                            |
| 320606             |          | LUBRICATE LEFT MAIN GEAR                               |        |          |                                                     |          |             |                         | L1                         |
| 32.030             |          | PKG 1, 2, 3                                            | MOS    |          |                                                     |          | 26-JUN-2001 |                         |                            |
|                    |          |                                                        | HRS/MS | 200      |                                                     |          | 7687        |                         | .5                         |
|                    |          | REF: AMM 12-20-00                                      | AFL    |          |                                                     |          | 5594        |                         |                            |
| 320636             |          | SERVICE LEFT MAIN GEAR SHOCK STRUT                     |        |          |                                                     |          |             |                         | L1                         |
| 32.040             |          | PKG 2, 3                                               | MOS    |          |                                                     |          | 26-JUN-2001 |                         |                            |
|                    |          |                                                        | HRS/MS | 400      |                                                     |          | 7687        |                         | 2                          |
|                    |          | REF: AMM 12-10-04                                      | AFL    |          |                                                     |          | 5594        |                         |                            |

 ? - Insufficient Information  
 + Task exists in FAA Manual  
 4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L



Aircraft Model - 1124 WESTWIND  
 Owner Name - R&S AIRCRAFT INVESTMENTS, LLC  
 A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

| ITEM NO  | WORKCARD         | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER   | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|----------|------------------|--------------------------------------------------------|--------|----------|-----------------------------------------------------|----------|-------------|-------------------------|----------------------------|
| SL       | WW-24103 LEFT    | SERVICE LETTER                                         |        |          |                                                     |          |             |                         | L1                         |
|          | ASSOCIATED       |                                                        | MOS    |          |                                                     |          |             |                         |                            |
|          |                  | REF:                                                   | HRS/MS | A/R      |                                                     |          | 0           |                         |                            |
|          |                  | Method of Compliance: OPEN                             | AFL    |          |                                                     |          | 0           |                         |                            |
| 321101   |                  | GEAR ASSEMBLY, MAIN RIGHT                              |        |          |                                                     |          |             |                         | L2                         |
| 32.210   |                  | 400-144-512                                            | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|          |                  | 1L195                                                  | HRS/MS | O/C      | 0                                                   |          | 0           |                         |                            |
|          |                  | REF: AMM 32-10-01                                      | AFL    |          |                                                     |          | 0           |                         |                            |
| 321134   |                  | CHECK RIGHT MAIN GEAR CLEARANCE                        |        |          |                                                     |          |             |                         | L2                         |
| 32.480   |                  |                                                        | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|          |                  |                                                        | HRS/MS | C/C      |                                                     |          | 0           |                         |                            |
|          |                  | REF: AMM 32-10-01                                      | AFL    |          |                                                     |          | 0           |                         |                            |
| + 322211 |                  | FUNCTIONAL TEST EMERGENCY GEAR EXTENSION               |        |          |                                                     |          |             |                         | F3                         |
| 32.450   |                  | PKG 3                                                  | MOS    |          |                                                     |          | 26-JUL-2000 |                         |                            |
|          | ASSOCIATED       |                                                        | HRS/MS | 800      |                                                     |          | 7325        |                         |                            |
|          |                  | REF: AMM 32-30-00                                      | AFL    |          |                                                     |          | 5360        |                         |                            |
| + 322206 |                  | FUNCTIONAL TEST EMERGENCY GEAR EXTENSION CONTROL CABLE |        |          |                                                     |          |             |                         | F3                         |
| 32.440   |                  | PKG 1, 2, 3                                            | MOS    |          |                                                     |          | 26-JUN-2001 |                         |                            |
|          | ASSOCIATED       |                                                        | HRS/MS | 200      |                                                     |          | 7687        | 1                       |                            |
|          |                  | REF: AMM 32-30-00                                      | AFL    |          |                                                     |          | 5594        |                         |                            |
| + 322191 |                  | FUNCTIONAL TEST LANDING GEAR (NORMAL)                  |        |          |                                                     |          |             |                         | F3                         |
| 32.430   |                  | PKG 2, 3                                               | MOS    |          |                                                     |          | 26-JUN-2001 |                         |                            |
|          | ASSOCIATED       |                                                        | HRS/MS | 400      |                                                     |          | 7687        |                         |                            |
|          |                  | REF: AMM 32-30-00                                      | AFL    |          |                                                     |          | 5594        |                         |                            |
| + 322201 |                  | FUNCTIONAL TEST LANDING GEAR FREE FALL                 |        |          |                                                     |          |             |                         | F3                         |
| 32.430   |                  | PKG 2, 3                                               | MOS    |          |                                                     |          | 26-JUN-2001 |                         |                            |
|          | ASSOCIATED       |                                                        | HRS/MS | 400      |                                                     |          | 7687        |                         |                            |
|          |                  | REF: See Workcard                                      | AFL    |          |                                                     |          | 5594        |                         |                            |
| SL       | WW-2494 R3 RIGHT | LANDING GEAR SERVICE LETTER                            |        |          |                                                     |          |             |                         | L2                         |
|          | ASSOCIATED       |                                                        | MOS    |          |                                                     |          | 26-JUN-2001 |                         |                            |
|          |                  | REF: See Workcard                                      | HRS/MS | 300      |                                                     |          | 7687        | 7987                    |                            |
|          |                  | Method of Compliance: OPEN                             | AFL    |          |                                                     |          | 5594        |                         |                            |
| 321106   |                  | LUBRICATE RIGHT MAIN GEAR                              |        |          |                                                     |          |             |                         | L2                         |
| 32.030   |                  | PKG 1, 2, 3                                            | MOS    |          |                                                     |          | 26-JUN-2001 |                         |                            |
|          |                  |                                                        | HRS/MS | 200      |                                                     |          | 7687        | .5                      |                            |
|          |                  | REF: AMM 12-20-00                                      | AFL    |          |                                                     |          | 5594        |                         |                            |
| SL       | WW-24103 RIGHT   | SERVICE LETTER                                         |        |          |                                                     |          |             |                         | L2                         |
|          | ASSOCIATED       |                                                        | MOS    |          |                                                     |          |             |                         |                            |
|          |                  | REF:                                                   | HRS/MS | A/R      |                                                     |          | 0           |                         |                            |
|          |                  | Method of Compliance: OPEN                             | AFL    |          |                                                     |          | 0           |                         |                            |
| 321136   |                  | SERVICE RIGHT MAIN GEAR SHOCK STRUT                    |        |          |                                                     |          |             |                         | L2                         |
| 32.040   |                  | PKG 2, 3                                               | MOS    |          |                                                     |          | 26-JUN-2001 |                         |                            |
|          |                  |                                                        | HRS/MS | 400      |                                                     |          | 7687        | 2                       |                            |
|          |                  | REF: AMM 12-10-04                                      | AFL    |          |                                                     |          | 5594        |                         |                            |



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO   | WORKCARD   | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp   | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|-----------|------------|------------------------------------------------------|--------|----------|-----------------------------------------------------|------------|-------------|-------------------------|----------------------------|
| 320101    |            | NOSE GEAR ASSEMBLY,                                  |        |          |                                                     |            |             |                         | L3                         |
|           | 32.050     | 400-143-511                                          | MOS    |          |                                                     |            | 11-FEB-1982 |                         |                            |
|           |            | 1L184                                                | HRS/MS | O/C      | 0                                                   |            | 0           |                         |                            |
|           |            | REF: AMM 32-20-01                                    | AFL    |          |                                                     |            | 0           |                         |                            |
| 320179    |            | INSPECT NOSE STEERING CABLES                         |        |          |                                                     |            |             |                         | L1                         |
|           | 32.580     | PKG 3                                                | MOS    |          |                                                     |            | 26-JUL-2000 |                         |                            |
|           |            |                                                      | HRS/MS | 800      |                                                     |            | 7325        |                         |                            |
|           |            | REF: AMM 32-50-07                                    | AFL    |          |                                                     |            | 5360        |                         |                            |
| 320120    |            | INSPECT OUTER STRUT BODY FORGING                     |        |          |                                                     |            |             |                         | L3                         |
|           | 32.520     |                                                      | MOS    |          |                                                     |            | 22-FEB-2000 |                         |                            |
|           |            |                                                      | HRS/MS | 1200     |                                                     |            | 7107        | 8307                    |                            |
|           |            | REF: AMM 32-20-01                                    | AFL    |          |                                                     |            | 5232        |                         |                            |
| 320118    |            | INSPECT/LUBRICATE UPPER/LOWER STRUT BEARINGS BODY    |        |          |                                                     |            |             |                         | L3                         |
|           | 32.540     |                                                      | MOS    | 24       |                                                     |            | 22-FEB-2000 | 22-FEB-2002             |                            |
|           |            |                                                      | HRS/MS | 1200     |                                                     |            | 7107        | 8307                    |                            |
|           |            | REF: AMM 32-20-01                                    | AFL    |          |                                                     |            | 5232        |                         |                            |
| 320106    |            | LUBRICATE NOSE GEAR/DOORS                            |        |          |                                                     |            |             |                         | L3                         |
|           | 32.030     | PKG 1, 2, 3                                          | MOS    |          |                                                     |            | 26-JUN-2001 |                         |                            |
|           |            |                                                      | HRS/MS | 200      |                                                     |            | 7687        |                         | .5                         |
|           |            | REF: AMM 12-20-00                                    | AFL    |          |                                                     |            | 5594        |                         |                            |
| 320180    |            | LUBRICATE NOSE STEERING CONTROL CABLES               |        |          |                                                     |            |             |                         | L1                         |
|           | 32.590     | PKG 3                                                | MOS    |          |                                                     |            | 26-JUL-2000 |                         |                            |
|           |            |                                                      | HRS/MS | 800      |                                                     |            | 7325        |                         |                            |
|           |            | REF: AMM 12-20-00                                    | AFL    |          |                                                     |            | 5360        |                         |                            |
| SB 900280 |            | SB WW 24-28A SERVICE BULLETIN                        |        |          |                                                     |            |             |                         | L3                         |
|           | ASSOCIATED |                                                      | MOS    |          |                                                     |            | 22-FEB-2000 |                         |                            |
|           |            |                                                      | HRS/MS | 1200     |                                                     |            | 7107        |                         |                            |
|           |            | REF: See Workcard                                    | AFL    |          |                                                     |            | 5232        |                         |                            |
|           |            | Method of Compliance: OPEN                           |        |          |                                                     |            |             |                         |                            |
| 320116    |            | SERVICE SHOCK STRUT                                  |        |          |                                                     |            |             |                         | L3                         |
|           | 32.040     | PKG 2, 3                                             | MOS    |          |                                                     |            | 26-JUN-2001 |                         |                            |
|           |            |                                                      | HRS/MS | 400      |                                                     |            | 7687        |                         | 2.5                        |
|           |            | REF: AMM 12-10-04                                    | AFL    |          |                                                     |            | 5594        |                         |                            |
| 320172    |            | TEST DRAG BRACE DOWNLOCK TENSION                     |        |          |                                                     |            |             |                         | L3                         |
|           | 32.240     | PKG 3                                                | MOS    |          |                                                     |            | 26-JUL-2000 |                         |                            |
|           |            |                                                      | HRS/MS | 800      |                                                     |            | 7325        |                         |                            |
|           |            | REF: AMM 32-20-02                                    | AFL    |          |                                                     |            | 5360        |                         |                            |
| + 320110  |            | X-RAY INSPECT NOSE GEAR SHAFT AND DOOR ASSEMBLIES    |        |          |                                                     |            |             |                         | L3                         |
|           | 32.560     |                                                      | MOS    | 60       |                                                     |            | 16-JUN-1997 | 16-JUN-2002             |                            |
|           |            |                                                      | HRS/MS | 5000     |                                                     |            | 6135        | 11135                   |                            |
|           |            | REF: AMM 5-10-00                                     | AFL    |          |                                                     |            | 4707        |                         |                            |
| 321603    |            | SELECTOR, GEAR VALVE                                 |        |          |                                                     |            |             |                         | F3                         |
|           | 32.200     | 713025-501                                           | MOS    |          |                                                     | 06/09/1995 | 09-DEC-1994 |                         |                            |
|           |            | IL-41                                                | HRS/MS | O/C      | 0                                                   |            | 5526        |                         |                            |
|           |            | REF: NO REF                                          | AFL    |          |                                                     |            | 4218        |                         |                            |

? - Insufficient Information

+ Task exists in FAA Manual

4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL



Aircraft Model - 1124 WESTWIND

Report Date **11-APR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC  
A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION |     |     |     |     | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|--------|----------|------------------------------|-----|-----|-----|-----|----------|-------------|-------------------------|----------------------------|
|                     |                                                      |        |          | TSN                          | TSO | TSR | TSI | ADJ |          |             |                         |                            |
| 320661              | SWITCH, DOWNLOCK LEFT MAIN GEAR                      |        |          |                              |     |     |     |     |          |             |                         | L1                         |
| 32.280              | 4-823051                                             | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 320663              | ADJUST                                               |        |          |                              |     |     |     |     |          |             |                         | L1                         |
| 32.280              |                                                      | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     |                                                      | HRS/MS | C/C      |                              |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 32-60-00                                    | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 320131              | SWITCH, DOWNLOCK NOSE GEAR                           |        |          |                              |     |     |     |     |          |             |                         | L3                         |
| 32.080              | 4-823012-501                                         | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 32-60-00                                    | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 320133              | ADJUST                                               |        |          |                              |     |     |     |     |          |             |                         | L3                         |
| 32.080              |                                                      | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     |                                                      | HRS/MS | C/C      |                              |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 32-60-00                                    | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 321161              | SWITCH, DOWNLOCK RIGHT MAIN GEAR                     |        |          |                              |     |     |     |     |          |             |                         | L2                         |
| 32.280              | 4-823051                                             | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 321163              | ADJUST                                               |        |          |                              |     |     |     |     |          |             |                         | L2                         |
| 32.280              |                                                      | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     |                                                      | HRS/MS | C/C      |                              |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 32-60-00                                    | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 320666              | SWITCH, GROUND CONTACT LEFT MAIN GEAR                |        |          |                              |     |     |     |     |          |             |                         | L1                         |
| 32.290              | 4-823051                                             | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 320668              | ADJUST                                               |        |          |                              |     |     |     |     |          |             |                         | L1                         |
| 32.290              |                                                      | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     |                                                      | HRS/MS | C/C      |                              |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 32-60-00                                    | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 320141              | SWITCH, GROUND CONTACT NOSE GEAR                     |        |          |                              |     |     |     |     |          |             |                         | L3                         |
| 32.100              | 4-823053-501                                         | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: See Workcard                                    | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 320143              | ADJUST                                               |        |          |                              |     |     |     |     |          |             |                         | L3                         |
| 32.100              |                                                      | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     |                                                      | HRS/MS | C/C      |                              |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 32-60-00                                    | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 321166              | SWITCH, GROUND CONTACT RIGHT MAIN GEAR               |        |          |                              |     |     |     |     |          |             |                         | L2                         |
| 32.290              | 4-823024-505                                         | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: See Workcard                                    | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO | WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------|----------|------------------------------------------------------|--------|----------|-----------------------------------------------------|----------|-------------|-------------------------|----------------------------|
| 321168  | 32.290   | ADJUST                                               | MOS    |          |                                                     |          |             |                         | L2                         |
|         |          | REF: AMM 32-60-00                                    | HRSMSC | C/C      |                                                     |          | 11-FEB-1982 |                         |                            |
|         |          |                                                      | AFL    |          |                                                     |          | 0           |                         |                            |
|         |          |                                                      |        |          |                                                     |          | 0           |                         |                            |
| 320656  | 32.270   | SWITCH, UPLOCK LEFT MAIN GEAR                        | MOS    |          |                                                     |          |             |                         | L1                         |
|         |          | 3-823003                                             | HRSMSC | O/C      | 0                                                   |          | 11-FEB-1982 |                         |                            |
|         |          | SN-UNKNOWN                                           | AFL    |          |                                                     |          | 0           |                         |                            |
|         |          | REF: NO REF                                          |        |          |                                                     |          | 0           |                         |                            |
| 320658  | 32.270   | ADJUST                                               | MOS    |          |                                                     |          |             |                         | L1                         |
|         |          | REF: AMM 32-60-00                                    | HRSMSC | C/C      |                                                     |          | 11-FEB-1982 |                         |                            |
|         |          |                                                      | AFL    |          |                                                     |          | 0           |                         |                            |
|         |          |                                                      |        |          |                                                     |          | 0           |                         |                            |
| 320136  | 32.090   | SWITCH, UPLOCK NOSE GEAR                             | MOS    |          |                                                     |          |             |                         | L3                         |
|         |          | 3-823003                                             | HRSMSC | O/C      | 0                                                   |          | 11-FEB-1982 |                         |                            |
|         |          | SN-UNKNOWN                                           | AFL    |          |                                                     |          | 0           |                         |                            |
|         |          | REF: AMM 32-60-00                                    |        |          |                                                     |          | 0           |                         |                            |
| 320138  | 32.090   | ADJUST                                               | MOS    |          |                                                     |          |             |                         | L3                         |
|         |          | REF: AMM 32-60-00                                    | HRSMSC | C/C      |                                                     |          | 11-FEB-1982 |                         |                            |
|         |          |                                                      | AFL    |          |                                                     |          | 0           |                         |                            |
|         |          |                                                      |        |          |                                                     |          | 0           |                         |                            |
| 321156  | 32.270   | SWITCH, UPLOCK RIGHT MAIN GEAR                       | MOS    |          |                                                     |          |             |                         | L2                         |
|         |          | 3-823003                                             | HRSMSC | O/C      | 0                                                   |          | 11-FEB-1982 |                         |                            |
|         |          | SN-UNKNOWN                                           | AFL    |          |                                                     |          | 0           |                         |                            |
|         |          | REF: NO REF                                          |        |          |                                                     |          | 0           |                         |                            |
| 321158  | 32.270   | ADJUST                                               | MOS    |          |                                                     |          |             |                         | L2                         |
|         |          | REF: AMM 32-60-00                                    | HRSMSC | C/C      |                                                     |          | 11-FEB-1982 |                         |                            |
|         |          |                                                      | AFL    |          |                                                     |          | 0           |                         |                            |
|         |          |                                                      |        |          |                                                     |          | 0           |                         |                            |
| 320681  | 32.180   | TIRE, LEFT MAIN GEAR                                 | MOS    |          | 0                                                   |          |             |                         | L1                         |
|         |          | 249K83-3                                             | HRSMSC | O/C      | 0                                                   |          | 09-NOV-1996 |                         |                            |
|         |          | SN-UNKNOWN                                           | AFL    |          | 0                                                   |          | 5951        | 2                       |                            |
|         |          | REF: AMM 32-41-00                                    |        |          | 0                                                   |          | 4589        |                         |                            |
| 321181  | 32.190   | TIRE, RIGHT MAIN GEAR                                | MOS    |          | 0                                                   |          |             |                         | L2                         |
|         |          | 249K83-3                                             | HRSMSC | O/C      | 0                                                   |          | 09-NOV-1996 |                         |                            |
|         |          | SN-UNKNOWN                                           | AFL    |          | 0                                                   |          | 5951        | 2                       |                            |
|         |          | REF: AMM 32-41-00                                    |        |          | 0                                                   |          | 4589        |                         |                            |
| 320161  | 32.110   | TIRE, LEFT NOSE GEAR                                 | MOS    |          |                                                     |          |             |                         | L3                         |
|         |          | 164F43-2                                             | HRSMSC | O/C      | 0                                                   |          | 22-NOV-1995 |                         |                            |
|         |          | 31162139                                             | AFL    |          |                                                     |          | 5720        |                         |                            |
|         |          | REF: AMM 32-42-00                                    |        |          |                                                     |          | 4401        |                         |                            |
| 320166  | 32.120   | TIRE, RIGHT NOSE GEAR                                | MOS    |          |                                                     |          |             |                         | L3                         |
|         |          | 164F43-2                                             | HRSMSC | O/C      | 0                                                   |          | 29-NOV-1995 |                         |                            |
|         |          | 22051064                                             | AFL    |          |                                                     |          | 5720        |                         |                            |
|         |          | REF: AMM 32-42-00                                    |        |          |                                                     |          | 4401        |                         |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL



Aircraft Model - 1124 WESTWIND  
 Owner Name - R&S AIRCRAFT INVESTMENTS, LLC  
 A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|--------|----------|-----------------------------------------------------|----------|------------|-------------------------|----------------------------|
| 320626              | UPLOCK, LEFT MAIN GEAR                               |        |          |                                                     |          |            |                         | L1                         |
| 32.250              | 5-173057-501                                         | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | SN-UNKNOWN                                           | HRSMSC | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 32-32-04                                    | AFL    |          |                                                     |          | 0          |                         |                            |
| 321126              | UPLOCK, RIGHT MAIN GEAR                              |        |          |                                                     |          |            |                         | L2                         |
| 32.250              | 5-173057-502                                         | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | SN-UNKNOWN                                           | HRSMSC | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 32-30-04                                    | AFL    |          |                                                     |          | 0          |                         |                            |
| 320176              | VALVE ASSEMBLY, STEERING                             |        |          |                                                     |          |            |                         | L3                         |
| 32.130              | BA1801-2                                             | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | 1L185                                                | HRSMSC | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 32-50-01                                    | AFL    |          |                                                     |          | 0          |                         |                            |
| 322146              | VALVE, ANTI-SKID CONTROL LEFT                        |        |          |                                                     |          |            |                         | F5                         |
| 32.500              | 5723578-1                                            | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | 313A                                                 | HRSMSC | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 32-44-02                                    | AFL    |          |                                                     |          | 0          |                         |                            |
| 322149              | CLEAN FILTERS                                        |        |          |                                                     |          |            |                         | F5                         |
| 32.500              |                                                      | MOS    |          |                                                     |          |            | 22-FEB-2000             |                            |
|                     |                                                      | HRSMSC | 1200     |                                                     |          | 7107       | 8307                    |                            |
|                     |                                                      | AFL    |          |                                                     |          | 5232       |                         |                            |
|                     | REF: AMM 32-41-00                                    |        |          |                                                     |          |            |                         |                            |
| + 322176            | FUNCTIONAL CHECK ANTI-SKID DETECTOR SYSTEM           |        |          |                                                     |          |            |                         | F3                         |
| 32.420              | PKG 2, 3                                             | MOS    |          |                                                     |          |            | 26-JUN-2001             |                            |
| ASSOCIATED          |                                                      | HRSMSC | 400      |                                                     |          | 7687       |                         | 1                          |
|                     |                                                      | AFL    |          |                                                     |          | 5594       |                         |                            |
|                     | REF: AMM 32-44-00                                    |        |          |                                                     |          |            |                         |                            |
| 322161              | VALVE, ANTI-SKID CONTROL RIGHT                       |        |          |                                                     |          |            |                         | F5                         |
| 32.500              | 5723578-1                                            | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | 503A                                                 | HRSMSC | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 32-44-02                                    | AFL    |          |                                                     |          | 0          |                         |                            |
| 322169              | CLEAN FILTERS                                        |        |          |                                                     |          |            |                         | F5                         |
| 32.500              |                                                      | MOS    |          |                                                     |          |            | 22-FEB-2000             |                            |
|                     |                                                      | HRSMSC | 1200     |                                                     |          | 7107       | 8307                    |                            |
|                     |                                                      | AFL    |          |                                                     |          | 5232       |                         |                            |
|                     | REF: AMM 32-41-00                                    |        |          |                                                     |          |            |                         |                            |
| + 322176            | FUNCTIONAL CHECK ANTI-SKID DETECTOR SYSTEM           |        |          |                                                     |          |            |                         | F3                         |
| 32.420              | PKG 2, 3                                             | MOS    |          |                                                     |          |            | 26-JUN-2001             |                            |
| ASSOCIATED          |                                                      | HRSMSC | 400      |                                                     |          | 7687       |                         | 1                          |
|                     |                                                      | AFL    |          |                                                     |          | 5594       |                         |                            |
|                     | REF: AMM 32-44-00                                    |        |          |                                                     |          |            |                         |                            |
| 322106              | VALVE, BRAKE SHUTTLE LEFT                            |        |          |                                                     |          |            |                         | W1                         |
| 32.370              | 4-713066                                             | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | 2752                                                 | HRSMSC | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 32-43-03                                    | AFL    |          |                                                     |          | 0          |                         |                            |
| 322121              | VALVE, BRAKE SHUTTLE RIGHT                           |        |          |                                                     |          |            |                         | W2                         |
| 32.370              | 4-713066                                             | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | 2775                                                 | HRSMSC | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 32-43-03                                    | AFL    |          |                                                     |          | 0          |                         |                            |



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|--------|----------|-----------------------------------------------------|----------|------------|-------------------------|----------------------------|
| 321606              | VALVE, EMERGENCY GEAR EXTENSION                      |        |          |                                                     |          |            |                         | F5                         |
| 32.340              | 874521B                                              | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | SN-UNKNOWN                                           | HRSMSC | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 32-30-11                                    | AFL    |          |                                                     |          | 0          |                         |                            |
| 321601              | VALVE, LANDING GEAR CONTROL                          |        |          |                                                     |          |            |                         | F2                         |
| 32.320              | 4753036                                              | MOS    |          |                                                     |          |            | 11-FEB-1982             | \$644.                     |
|                     | 372                                                  | HRSMSC | O/C      | 0                                                   |          | 0          |                         | 25                         |
|                     | REF: AMM 32-30-01                                    | AFL    |          |                                                     |          | 0          |                         |                            |
| 320177              | VALVE, NOSE STEERING SOLENOID                        |        |          |                                                     |          |            |                         | L3                         |
| 32.170              | 713557-501                                           | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | SN-UNKNOWN                                           | HRSMSC | O/C      |                                                     |          | 0          |                         |                            |
|                     | REF: AMM 32-50-00                                    | AFL    |          |                                                     |          | 0          |                         |                            |
| 320191              | OPERATIONAL CHECK NOSE STEERING                      |        |          |                                                     |          |            |                         | L3                         |
| 32.160              |                                                      | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     |                                                      | HRSMSC | C/C      |                                                     |          | 0          |                         |                            |
|                     | REF: AMM 32-50-00                                    | AFL    |          |                                                     |          | 0          |                         |                            |
| 322181              | VALVE, PARKING MOTOR                                 |        |          |                                                     |          |            |                         | F5                         |
| 32.510              | 3-713551                                             | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | L34900                                               | HRSMSC | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 32-44-03                                    | AFL    |          |                                                     |          | 0          |                         |                            |
| + 322176            | FUNCTIONAL CHECK ANTI-SKID DETECTOR SYSTEM           |        |          |                                                     |          |            |                         | F3                         |
| 32.420              | PKG 2, 3                                             | MOS    |          |                                                     |          |            | 26-JUN-2001             |                            |
| ASSOCIATED          |                                                      | HRSMSC | 400      |                                                     |          | 7687       |                         | 1                          |
|                     | REF: AMM 32-44-00                                    | AFL    |          |                                                     |          | 5594       |                         |                            |
| 322101              | VALVE, POWER BRAKE                                   |        |          |                                                     |          |            |                         | F2                         |
| 32.360              | 5713001-501                                          | MOS    |          |                                                     |          |            | 11-FEB-1982             | \$1932.                    |
|                     | 617AB                                                | HRSMSC | O/C      | 0                                                   |          | 0          |                         | 5                          |
|                     | REF: AMM 32-43-02                                    | AFL    |          |                                                     |          | 0          |                         |                            |
| 320221              | VALVE, SHUTTLE NOSE GEAR                             |        |          |                                                     |          |            |                         | L3                         |
| 32.330              | 4713066                                              | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | SN-UNKNOWN                                           | HRSMSC | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 32-30-07                                    | AFL    |          |                                                     |          | 0          |                         |                            |
| 320671              | WHEEL HALF, INBOARD LEFT MAIN GEAR                   |        |          |                                                     |          |            |                         | L1                         |
| 32.180              | 5002806-2                                            | MOS    |          |                                                     |          |            | 09-NOV-1996             |                            |
|                     | JUN89-537                                            | HRSMSC | O/C      |                                                     |          | 5951       |                         | 1                          |
|                     | REF: AMM 32-41-00                                    | AFL    |          |                                                     |          | 4589       |                         |                            |
| 320681              | CHANGE LEFT MAIN GEAR TIRE                           |        |          |                                                     |          |            |                         | L1                         |
| 32.180              | 249K83-3                                             | MOS    |          | 0                                                   |          |            | 09-NOV-1996             |                            |
| ASSOCIATED          | SN-UNKNOWN                                           | HRSMSC | O/C      | 0                                                   |          | 5951       |                         | 2                          |
|                     | REF: AMM 32-41-00                                    | AFL    |          | 0                                                   |          | 4589       |                         |                            |
| 320672              | CHANGE LEFT MAIN GEAR OUTBOARD WHEEL HALF            |        |          |                                                     |          |            |                         | L1                         |
| 32.180              | 5002806-2                                            | MOS    |          |                                                     |          |            | 09-NOV-1996             |                            |
| ASSOCIATED          | JUN89-537                                            | HRSMSC | O/C      |                                                     |          | 5951       |                         | 1                          |
|                     | REF: AMM 32-41-00                                    | AFL    |          |                                                     |          | 4589       |                         |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER    | UNIT   | INTERVAL | TIME-----AT-----<br>TSN TSO TSR TSI ADJ | INSTALLATION | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|---------------------------------------------------------|--------|----------|-----------------------------------------|--------------|----------|-------------|-------------------------|----------------------------|
| 320678              | DYE PENETRANT CHECK LEFT WHEEL AXLE                     |        |          |                                         |              |          |             |                         | L1                         |
| 32.550              | PKG 2, 3                                                | MOS    |          |                                         |              |          | 26-JUN-2001 |                         |                            |
| ASSOCIATED          | REF: AMM 5-20-04                                        | HRSMSC | 400      |                                         |              |          | 7687        |                         |                            |
|                     |                                                         | AFL    |          |                                         |              |          | 5594        |                         |                            |
| + 320691            | INSPECT LEFT MAIN GEAR/WELL (A)                         |        |          |                                         |              |          |             |                         | L1                         |
| 32.020              | PKG 1, 2, 3                                             | MOS    |          |                                         |              |          | 26-JUN-2001 |                         |                            |
| ASSOCIATED          | REF: AMM 5-20-04                                        | HRSMSC | 200      |                                         |              |          | 7687        |                         | 1.5                        |
|                     |                                                         | AFL    |          |                                         |              |          | 5594        |                         |                            |
| + 322156            | INSPECT/CLEAN LEFT ANTI-SKID DETECTOR                   |        |          |                                         |              |          |             |                         | L1                         |
| 32.410              | PKG 1, 2, 3                                             | MOS    |          |                                         |              |          | 26-JUN-2001 |                         |                            |
| ASSOCIATED          | REF: AMM 5-20-04                                        | HRSMSC | 200      |                                         |              |          | 7687        |                         | 1                          |
|                     |                                                         | AFL    |          |                                         |              |          | 5594        |                         |                            |
| + 320676            | INSPECT/LUBRICATE LEFT MAIN GEAR INBOARD WHEEL BEARINGS |        |          |                                         |              |          |             |                         | L1                         |
| 32.180              | PKG 1, 2, 3                                             | MOS    |          |                                         |              |          | 26-JUN-2001 |                         |                            |
|                     | REF: AMM 32-41-00                                       | HRSMSC | 200      |                                         |              |          | 7687        |                         | 1                          |
|                     |                                                         | AFL    |          |                                         |              |          | 5594        |                         |                            |
| + 322174            | OPERATIONAL CHECK ANTI-SKID LIGHTS                      |        |          |                                         |              |          |             |                         | F3                         |
| 32.425              | PKG 1, 2, 3                                             | MOS    |          |                                         |              |          | 26-JUN-2001 |                         |                            |
| ASSOCIATED          | REF: AMM 32-44-00                                       | HRSMSC | 200      |                                         |              |          | 7687        |                         | .5                         |
|                     |                                                         | AFL    |          |                                         |              |          | 5594        |                         |                            |
| 320686              | REPLACE LEFT MAIN WHEEL BOLTS                           |        |          |                                         |              |          |             |                         | L1                         |
| 32.180              |                                                         | MOS    |          |                                         |              |          | 09-NOV-1996 |                         |                            |
| ASSOCIATED          | REF: NO REF                                             | HRSMSC | O/C      |                                         |              |          | 5951        |                         |                            |
|                     |                                                         | AFL    |          |                                         |              |          | 4589        |                         |                            |
| 321171              | WHEEL HALF, INBOARD RIGHT MAIN GEAR                     |        |          |                                         |              |          |             |                         | L2                         |
| 32.190              | 5002806-2                                               | MOS    |          |                                         |              |          | 09-NOV-1996 |                         |                            |
|                     | MAR84-662                                               | HRSMSC | O/C      |                                         |              |          | 5951        |                         | 1                          |
|                     | REF: AMM 32-41-00                                       | AFL    |          |                                         |              |          | 4589        |                         |                            |
| 321181              | CHANGE RIGHT MAIN GEAR TIRE                             |        |          |                                         |              |          |             |                         | L2                         |
| 32.190              | 249K83-3                                                | MOS    |          |                                         |              | 0        | 09-NOV-1996 |                         |                            |
| ASSOCIATED          | SN-UNKNOWN                                              | HRSMSC | O/C      |                                         |              | 0        | 5951        |                         | 2                          |
|                     | REF: AMM 32-41-00                                       | AFL    |          |                                         |              | 0        | 4589        |                         |                            |
| 321172              | CHANGE RIGHT MAIN GEAR OUTBOARD WHEEL HALF              |        |          |                                         |              |          |             |                         | L2                         |
| 32.190              | 5002806-2                                               | MOS    |          |                                         |              |          | 09-NOV-1996 |                         |                            |
| ASSOCIATED          | MAR84-662                                               | HRSMSC | O/C      |                                         |              |          | 5951        |                         | 1                          |
|                     | REF: AMM 32-41-00                                       | AFL    |          |                                         |              |          | 4589        |                         |                            |
| 321178              | DYE PENETRANT CHECK RIGHT WHEEL AXLE                    |        |          |                                         |              |          |             |                         | L2                         |
| 32.550              | PKG 2, 3                                                | MOS    |          |                                         |              |          | 26-JUN-2001 |                         |                            |
| ASSOCIATED          | REF: AMM 5-20-04                                        | HRSMSC | 400      |                                         |              |          | 7687        |                         |                            |
|                     |                                                         | AFL    |          |                                         |              |          | 5594        |                         |                            |
| + 322171            | INSPECT/CLEAN RIGHT ANTI-SKID DETECTOR                  |        |          |                                         |              |          |             |                         | L2                         |
| 32.410              | PKG 1, 2, 3                                             | MOS    |          |                                         |              |          | 26-JUN-2001 |                         |                            |
| ASSOCIATED          | REF: AMM 5-20-04                                        | HRSMSC | 200      |                                         |              |          | 7687        |                         | 1                          |
|                     |                                                         | AFL    |          |                                         |              |          | 5594        |                         |                            |



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO | WORKCARD   | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER     | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------|------------|----------------------------------------------------------|--------|----------|-----------------------------------------------------|----------|-------------|-------------------------|----------------------------|
| +       | 321176     | INSPECT/LUBRICATE RIGHT MAIN GEAR INBOARD WHEEL BEARINGS |        |          |                                                     |          |             |                         | L2                         |
|         | 32.180     | PKG 1, 2, 3                                              | MOS    |          |                                                     |          | 26-JUN-2001 |                         |                            |
|         |            | REF: AMM 32-41-00                                        | HRSMSC | 200      |                                                     |          | 7687        |                         | 1                          |
|         |            |                                                          | AFL    |          |                                                     |          | 5594        |                         |                            |
| +       | 322174     | OPERATIONAL CHECK ANTI-SKID LIGHTS                       |        |          |                                                     |          |             |                         | F3                         |
|         | 32.425     | PKG 1, 2, 3                                              | MOS    |          |                                                     |          | 26-JUN-2001 |                         |                            |
|         | ASSOCIATED |                                                          | HRSMSC | 200      |                                                     |          | 7687        |                         | .5                         |
|         |            | REF: AMM 32-44-00                                        | AFL    |          |                                                     |          | 5594        |                         |                            |
|         | 321186     | REPLACE RIGHT MAIN WHEEL BOLTS                           |        |          |                                                     |          |             |                         | L2                         |
|         | 32.180     |                                                          | MOS    |          |                                                     |          | 09-NOV-1996 |                         |                            |
|         | ASSOCIATED |                                                          | HRSMSC | O/C      |                                                     |          | 5951        |                         |                            |
|         |            | REF: NO REF                                              | AFL    |          |                                                     |          | 4589        |                         |                            |
|         | 320672     | WHEEL HALF, OUTBOARD LEFT MAIN GEAR                      |        |          |                                                     |          |             |                         | L1                         |
|         | 32.180     | 5002806-2                                                | MOS    |          |                                                     |          | 09-NOV-1996 |                         |                            |
|         |            | JUN89-537                                                | HRSMSC | O/C      |                                                     |          | 5951        |                         | 1                          |
|         |            | REF: AMM 32-41-00                                        | AFL    |          |                                                     |          | 4589        |                         |                            |
|         | 320681     | CHANGE LEFT MAIN GEAR TIRE                               |        |          |                                                     |          |             |                         | L1                         |
|         | 32.180     | 249K83-3                                                 | MOS    |          | 0                                                   |          | 09-NOV-1996 |                         |                            |
|         | ASSOCIATED | SN-UNKNOWN                                               | HRSMSC | O/C      | 0                                                   |          | 5951        |                         | 2                          |
|         |            | REF: AMM 32-41-00                                        | AFL    |          | 0                                                   |          | 4589        |                         |                            |
|         | 320678     | DYE PENETRANT CHECK LEFT WHEEL AXLE                      |        |          |                                                     |          |             |                         | L1                         |
|         | 32.550     | PKG 2, 3                                                 | MOS    |          |                                                     |          | 26-JUN-2001 |                         |                            |
|         | ASSOCIATED |                                                          | HRSMSC | 400      |                                                     |          | 7687        |                         |                            |
|         |            | REF: AMM 5-20-04                                         | AFL    |          |                                                     |          | 5594        |                         |                            |
| +       | 320691     | INSPECT LEFT MAIN GEAR/WELL (A)                          |        |          |                                                     |          |             |                         | L1                         |
|         | 32.020     | PKG 1, 2, 3                                              | MOS    |          |                                                     |          | 26-JUN-2001 |                         |                            |
|         | ASSOCIATED |                                                          | HRSMSC | 200      |                                                     |          | 7687        |                         | 1.5                        |
|         |            | REF: AMM 5-20-04                                         | AFL    |          |                                                     |          | 5594        |                         |                            |
| +       | 322156     | INSPECT/CLEAN LEFT ANTI-SKID DETECTOR                    |        |          |                                                     |          |             |                         | L1                         |
|         | 32.410     | PKG 1, 2, 3                                              | MOS    |          |                                                     |          | 26-JUN-2001 |                         |                            |
|         | ASSOCIATED |                                                          | HRSMSC | 200      |                                                     |          | 7687        |                         | 1                          |
|         |            | REF: AMM 5-20-04                                         | AFL    |          |                                                     |          | 5594        |                         |                            |
| +       | 320680     | INSPECT/LUBRICATE LEFT MAIN GEAR OUTBOARD WHEEL BEARINGS |        |          |                                                     |          |             |                         | L1                         |
|         | 32.180     | PKG 1, 2, 3                                              | MOS    |          |                                                     |          | 26-JUN-2001 |                         |                            |
|         |            |                                                          | HRSMSC | 200      |                                                     |          | 7687        |                         |                            |
|         |            | REF: AMM 32-41-00                                        | AFL    |          |                                                     |          | 5594        |                         |                            |
| +       | 322174     | OPERATIONAL CHECK ANTI-SKID LIGHTS                       |        |          |                                                     |          |             |                         | F3                         |
|         | 32.425     | PKG 1, 2, 3                                              | MOS    |          |                                                     |          | 26-JUN-2001 |                         |                            |
|         | ASSOCIATED |                                                          | HRSMSC | 200      |                                                     |          | 7687        |                         | .5                         |
|         |            | REF: AMM 32-44-00                                        | AFL    |          |                                                     |          | 5594        |                         |                            |
|         | 320686     | REPLACE LEFT MAIN WHEEL BOLTS                            |        |          |                                                     |          |             |                         | L1                         |
|         | 32.180     |                                                          | MOS    |          |                                                     |          | 09-NOV-1996 |                         |                            |
|         | ASSOCIATED |                                                          | HRSMSC | O/C      |                                                     |          | 5951        |                         |                            |
|         |            | REF: NO REF                                              | AFL    |          |                                                     |          | 4589        |                         |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Page 56 of 107



Aircraft Model - 1124 WESTWIND

Report Date **11-APR-2002**

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER      | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|-----------------------------------------------------------|--------|----------|-----------------------------------------------------|----------|------------|-------------------------|----------------------------|
| 321172              | WHEEL HALF, OUTBOARD RIGHT MAIN GEAR                      |        |          |                                                     |          |            |                         | L2                         |
| 32.190              | 5002806-2                                                 | MOS    |          |                                                     |          |            | 09-NOV-1996             |                            |
|                     | MAR84-662                                                 | HRSMSC | O/C      |                                                     |          | 5951       |                         | 1                          |
|                     | REF: AMM 32-41-00                                         | AFL    |          |                                                     |          | 4589       |                         |                            |
| 321181              | CHANGE RIGHT MAIN GEAR TIRE                               |        |          |                                                     |          |            |                         | L2                         |
| 32.190              | 249K83-3                                                  | MOS    |          | 0                                                   |          |            | 09-NOV-1996             |                            |
| ASSOCIATED          | SN-UNKNOWN                                                | HRSMSC | O/C      | 0                                                   |          | 5951       |                         | 2                          |
|                     | REF: AMM 32-41-00                                         | AFL    |          | 0                                                   |          | 4589       |                         |                            |
| 321178              | DYE PENETRANT CHECK RIGHT WHEEL AXLE                      |        |          |                                                     |          |            |                         | L2                         |
| 32.550              | PKG 2, 3                                                  | MOS    |          |                                                     |          |            | 26-JUN-2001             |                            |
| ASSOCIATED          |                                                           | HRSMSC | 400      |                                                     |          | 7687       |                         |                            |
|                     | REF: AMM 5-20-04                                          | AFL    |          |                                                     |          | 5594       |                         |                            |
| + 321191            | INSPECT RIGHT MAIN GEAR/WELL (A)                          |        |          |                                                     |          |            |                         | L2                         |
| 32.020              | PKG 1, 2, 3                                               | MOS    |          |                                                     |          |            | 26-JUN-2001             |                            |
|                     |                                                           | HRSMSC | 200      |                                                     |          | 7687       |                         | 1.5                        |
|                     | REF: AMM 5-20-04                                          | AFL    |          |                                                     |          | 5594       |                         |                            |
| + 322171            | INSPECT/CLEAN RIGHT ANTI-SKID DETECTOR                    |        |          |                                                     |          |            |                         | L2                         |
| 32.410              | PKG 1, 2, 3                                               | MOS    |          |                                                     |          |            | 26-JUN-2001             |                            |
| ASSOCIATED          |                                                           | HRSMSC | 200      |                                                     |          | 7687       |                         | 1                          |
|                     | REF: AMM 5-20-04                                          | AFL    |          |                                                     |          | 5594       |                         |                            |
| 321180              | INSPECT/LUBRICATE RIGHT MAIN GEAR OUTBOARD WHEEL BEARINGS |        |          |                                                     |          |            |                         | L2                         |
| 32.180              | PKG 1, 2, 3                                               | MOS    |          |                                                     |          |            | 26-JUN-2001             |                            |
|                     |                                                           | HRSMSC | 200      |                                                     |          | 7687       |                         | 1                          |
|                     | REF: AMM 32-41-00                                         | AFL    |          |                                                     |          | 5594       |                         |                            |
| + 322174            | OPERATIONAL CHECK ANTI-SKID LIGHTS                        |        |          |                                                     |          |            |                         | F3                         |
| 32.425              | PKG 1, 2, 3                                               | MOS    |          |                                                     |          |            | 26-JUN-2001             |                            |
| ASSOCIATED          |                                                           | HRSMSC | 200      |                                                     |          | 7687       |                         | .5                         |
|                     | REF: AMM 32-44-00                                         | AFL    |          |                                                     |          | 5594       |                         |                            |
| 321186              | REPLACE RIGHT MAIN WHEEL BOLTS                            |        |          |                                                     |          |            |                         | L2                         |
| 32.180              |                                                           | MOS    |          |                                                     |          |            | 09-NOV-1996             |                            |
| ASSOCIATED          |                                                           | HRSMSC | O/C      |                                                     |          | 5951       |                         |                            |
|                     | REF: NO REF                                               | AFL    |          |                                                     |          | 4589       |                         |                            |
| 320146              | WHEEL, LEFT NOSE GEAR                                     |        |          |                                                     |          |            |                         | L3                         |
| 32.110              | 41874                                                     | MOS    |          |                                                     |          |            | 22-NOV-1995             |                            |
|                     | APR66-109                                                 | HRSMSC | O/C      | 0                                                   |          | 5720       |                         | 4                          |
|                     | REF: AMM 32-42-00                                         | AFL    |          |                                                     |          | 4401       |                         |                            |
| 320161              | CHANGE NOSE GEAR LEFT TIRE                                |        |          |                                                     |          |            |                         | L3                         |
| 32.110              | 164F43-2                                                  | MOS    |          |                                                     |          |            | 22-NOV-1995             |                            |
| ASSOCIATED          | 31162139                                                  | HRSMSC | O/C      | 0                                                   |          | 5720       |                         |                            |
|                     | REF: AMM 32-42-00                                         | AFL    |          |                                                     |          | 4401       |                         |                            |
| + 320156            | INSPECT/CLEAN/LUBRICATE BEARINGS                          |        |          |                                                     |          |            |                         | L3                         |
| 32.110              | PKG 1, 2, 3                                               | MOS    |          |                                                     |          |            | 26-JUN-2001             |                            |
|                     |                                                           | HRSMSC | 200      |                                                     |          | 7687       |                         | 1.5                        |
|                     | REF: AMM 5-20-01                                          | AFL    |          |                                                     |          | 5594       |                         |                            |



Aircraft Model - 1124 WESTWIND

Report Date **11-APR-2002**

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO                  | WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp   | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|--------------------------|----------|------------------------------------------------------|--------|----------|-----------------------------------------------------|------------|-------------|-------------------------|----------------------------|
| 320151                   |          | WHEEL, RIGHT NOSE GEAR                               |        |          |                                                     |            |             |                         | L3                         |
| 32.120                   |          | 9541874                                              | MOS    |          |                                                     |            | 29-NOV-1995 |                         |                            |
|                          |          | OCT75-641                                            | HRSMSC | O/C      | 0                                                   |            | 5720        |                         | 4                          |
|                          |          | REF: AMM 32-42-00                                    | AFL    |          |                                                     |            | 4401        |                         |                            |
| 320166                   |          | CHANGE NOSE GEAR RIGHT TIRE                          |        |          |                                                     |            |             |                         | L3                         |
| 32.120                   |          | 164F43-2                                             | MOS    |          |                                                     |            | 29-NOV-1995 |                         |                            |
| ASSOCIATED               |          | 22051064                                             | HRSMSC | O/C      | 0                                                   |            | 5720        |                         |                            |
|                          |          | REF: AMM 32-42-00                                    | AFL    |          |                                                     |            | 4401        |                         |                            |
| + 320158                 |          | INSPECT/CLEAN/LUBRICATE BEARINGS                     |        |          |                                                     |            |             |                         | L3                         |
| 32.120                   |          | PKG 1, 2, 3                                          | MOS    |          |                                                     |            | 26-JUN-2001 |                         |                            |
|                          |          |                                                      | HRSMSC | 200      |                                                     |            | 7687        |                         | 1.5                        |
|                          |          | REF: AMM 5-20-01                                     | AFL    |          |                                                     |            | 5594        |                         |                            |
| <b>CHAPTER 33 LIGHTS</b> |          |                                                      |        |          |                                                     |            |             |                         |                            |
| 330226                   |          | BATTERY, EMERGENCY LIGHT                             |        |          |                                                     |            |             |                         | F4                         |
| 33.100                   |          | AD-2058                                              | MOS    |          | 0                                                   |            | 06-OCT-1998 |                         |                            |
|                          |          | SN-UNKNOWN                                           | HRSMSC | O/C      | 0                                                   |            | 6520        |                         |                            |
|                          |          | REF: AMM 33-50-00                                    | AFL    |          | 0                                                   |            | 4889        |                         |                            |
| 330320                   |          | INVERTER, LIGHT POWER (CF-38-3)                      |        |          |                                                     |            |             |                         | F2                         |
| 33.070                   |          | CF-38-3                                              | MOS    |          |                                                     |            | 11-FEB-1982 |                         |                            |
|                          |          | 291                                                  | HRSMSC | O/C      | 0                                                   |            | 0           |                         |                            |
|                          |          | REF: NO REF                                          | AFL    |          |                                                     |            | 0           |                         |                            |
| 330111                   |          | LIGHT, TAIL CONE                                     |        |          |                                                     |            |             |                         | F1                         |
| 33.020                   |          | 4-823006-501                                         | MOS    |          |                                                     |            | 11-FEB-1982 |                         |                            |
|                          |          | SN-UNKNOWN                                           | HRSMSC | O/C      | 0                                                   |            | 0           |                         |                            |
|                          |          | REF: AMM 33-40-00                                    | AFL    |          |                                                     |            | 0           |                         |                            |
| 330161                   |          | LIGHT, ANTI-COLLISION LOWER                          |        |          |                                                     |            |             |                         | F1                         |
| 33.030                   |          | G-9950-11                                            | MOS    |          |                                                     | 10/28/1989 | 28-APR-1989 |                         | \$635.                     |
|                          |          | 11709                                                | HRSMSC | O/C      |                                                     |            | 4240        |                         |                            |
|                          |          | REF: AMM 33-40-00                                    | AFL    |          |                                                     |            | 2767        |                         |                            |
| 330156                   |          | LIGHT, ANTI-COLLISION UPPER                          |        |          |                                                     |            |             |                         | T1                         |
| 33.030                   |          | G9950-11                                             | MOS    |          | 0                                                   |            | 26-JUL-2000 |                         | \$635.                     |
|                          |          | 11709                                                | HRSMSC | O/C      | 0                                                   |            | 7325        |                         |                            |
|                          |          | REF: AMM 33-40-00                                    | AFL    |          | 0                                                   |            | 5360        |                         |                            |
| 330221                   |          | LIGHT, EMERGENCY                                     |        |          |                                                     |            |             |                         | F4                         |
| 33.090                   |          | 3-823551-503                                         | MOS    |          |                                                     |            | 11-FEB-1982 |                         |                            |
|                          |          | SN-UNKNOWN                                           | HRSMSC | O/C      | 0                                                   |            | 0           |                         |                            |
|                          |          | REF: AMM 33-50-00                                    | AFL    |          |                                                     |            | 0           |                         |                            |
| 330226                   |          | CHANGE EMERGENCY LIGHT BATTERY                       |        |          |                                                     |            |             |                         | F4                         |
| 33.100                   |          | AD-2058                                              | MOS    |          | 0                                                   |            | 06-OCT-1998 |                         |                            |
| ASSOCIATED               |          | SN-UNKNOWN                                           | HRSMSC | O/C      | 0                                                   |            | 6520        |                         |                            |
|                          |          | REF: AMM 33-50-00                                    | AFL    |          | 0                                                   |            | 4889        |                         |                            |
| 330228                   |          | CHARGE BATTERY                                       |        |          |                                                     |            |             |                         | F4                         |
| 33.100                   |          |                                                      | MOS    | 3        |                                                     |            | 06-NOV-2001 | 06-FEB-2002             |                            |
|                          |          |                                                      | HRSMSC | 200      |                                                     |            | 7774        | 7974                    |                            |
|                          |          | REF: AMM 12-10-06                                    | AFL    |          |                                                     |            | 5641        |                         |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER                      | UNIT                 | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE                  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|---------------------------------------------------------------------------|----------------------|----------|-----------------------------------------------------|----------|-----------------------------|-------------------------|----------------------------|
| 330136<br>33.060    | LIGHT, LANDING LEFT<br>5-213004-1<br>SN-UNKNOWN<br>REF: AMM 33-40-00      | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | W1                         |
| 330146<br>33.060    | LIGHT, LANDING RIGHT<br>5-213004-2<br>SN-UNKNOWN<br>REF: AMM 33-40-00     | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | W2                         |
| 330101<br>33.010    | LIGHT, POSITION LEFT WING<br>301085-1<br>4224<br>REF: AMM 33-40-00        | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | W1                         |
| 330106<br>33.010    | LIGHT, POSITION RIGHT WING<br>301085-2<br>5772<br>REF: AMM 33-40-00       | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | W2                         |
| 330166<br>33.040    | LIGHT, STROBE LEFT WING<br>31-3172-11<br>SN-UNKNOWN<br>REF: AMM 33-40-00  | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | W1                         |
| 330171<br>33.040    | LIGHT, STROBE RIGHT WING<br>31-3172-11<br>SN-UNKNOWN<br>REF: AMM 33-40-00 | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | W2                         |
| 330116<br>33.050    | LIGHT, TAXI LEFT<br>5-823521-1<br>GE-4587<br>REF: AMM 33-40-00            | MOS<br>HRSMSC<br>AFL | O/C      |                                                     |          | 30-AUG-1989<br>4350<br>2898 |                         | L1                         |
| 330126<br>33.050    | LIGHT, TAXI RIGHT<br>5-823521-2<br>GE-4587<br>REF: AMM 33-40-00           | MOS<br>HRSMSC<br>AFL | O/C      |                                                     |          | 30-AUG-1989<br>4350<br>2898 |                         | L2                         |
| 330505<br>33.085    | POWER SUPPLY,<br>60-2799-1<br>SN-UNKNOWN<br>REF: NO REF                   | MOS<br>HRSMSC<br>AFL | O/C      |                                                     |          | 11-FEB-1982<br>0<br>0       |                         | W1                         |
| 330241<br>33.080    | POWER SUPPLY, NO. 1<br>60-2799-1<br>6701<br>REF: NO REF                   | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | W1                         |
| 330246<br>33.080    | POWER SUPPLY, NO. 2<br>60-2799-1<br>SN-UNKNOWN<br>REF: NO REF             | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 25-APR-1984<br>1641<br>1010 |                         | W2                         |



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD          | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER                  | UNIT                 | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE                  | DISPOSITION<br>NEXT DUE  | AREA<br>PRICE<br>LABOR HRS |
|------------------------------|-----------------------------------------------------------------------|----------------------|----------|-----------------------------------------------------|----------|-----------------------------|--------------------------|----------------------------|
| 330522<br>33.085             | POWER SUPPLY, NO.4<br>60-2799-1<br>SN-UNKNOWN<br>REF: NO REF          | MOS<br>HRS/MS<br>AFL | O/C      |                                                     |          | 11-FEB-1982<br>0<br>0       |                          | W2                         |
| 330325<br>33.070             | UNIT, LIGHT POWER (CV-38)<br>CV-38<br>6125<br>REF: NO REF             | MOS<br>HRS/MS<br>AFL | O/C      |                                                     |          | 11-FEB-1982<br>0<br>0       |                          | F2                         |
| <b>CHAPTER 34 NAVIGATION</b> |                                                                       |                      |          |                                                     |          |                             |                          |                            |
| 340121<br>34.060             | DRAIN PITOT/STATIC SYSTEM<br>PKG 1, 2, 3<br>REF: AMM 34-10-00         | MOS<br>HRS/MS<br>AFL | 200      |                                                     |          | 26-JUN-2001<br>7687<br>5594 |                          | F2<br>1.5                  |
| 340111<br>34.040             | LEAK CHECK LEFT PITOT SYSTEM<br>REF: AMM 34-10-01                     | MOS<br>HRS/MS<br>AFL | O/C      |                                                     |          | 26-MAR-1996                 |                          | F1                         |
| + 340146<br>34.050           | LEAK CHECK LEFT STATIC SYSTEM<br>REF: AMM 34-10-01                    | MOS<br>HRS/MS<br>AFL | 24       |                                                     |          | 18-JAN-2001<br>7494<br>5466 | MANDATORY<br>18-JAN-2003 | F1                         |
| 340116<br>34.040             | LEAK CHECK RIGHT PITOT SYSTEM<br>REF: AMM 34-10-01                    | MOS<br>HRS/MS<br>AFL | O/C      |                                                     |          | 11-FEB-1982<br>0<br>0       |                          | F1                         |
| + 340151<br>34.050           | LEAK CHECK RIGHT STATIC SYSTEM<br>REF: AMM 34-10-01                   | MOS<br>HRS/MS<br>AFL | 24       |                                                     |          | 18-JAN-2001<br>7494<br>5466 | MANDATORY<br>18-JAN-2003 | F1                         |
| 343141<br>34.390             | SWING CHECK NO.1 COMPASS<br>REF: AMM 34-20-08                         | MOS<br>HRS/MS<br>AFL | O/C      |                                                     |          | 11-FEB-1982<br>0<br>0       |                          | F3                         |
| 343186<br>34.390             | SWING CHECK NO.2 COMPASS<br>REF: AMM 34-20-08                         | MOS<br>HRS/MS<br>AFL | O/C      |                                                     |          | 11-FEB-1982<br>0<br>0       |                          | F3                         |
| 345101<br>34.490             | ADVISORY, FLIGHT PROFILE<br>622-4569-001<br>SN-UNKNOWN<br>REF: NO REF | MOS<br>HRS/MS<br>AFL | O/C      | 0<br>0                                              |          | 11-FEB-1982<br>0<br>0       |                          | F3                         |
| 345629<br>34.310             | ALERTER, ALTITUDE<br>540-25100-004<br>SN-UNKNOWN<br>REF: AMM 34-10-03 | MOS<br>HRS/MS<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                          | F3                         |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|--------|----------|-----------------------------------------------------|----------|-------------|-------------------------|----------------------------|
| 341111              | ALTIMETER, COPILOT                                   |        |          |                                                     |          |             |                         | F3                         |
| 34.071              | 4883778-501                                          | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                     | 3008                                                 | HRSMSC | O/C      | 0                                                   |          | 0           |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                                                     |          | 0           |                         |                            |
| + 340151            | LEAK CHECK RIGHT STATIC SYSTEM                       |        |          |                                                     |          |             | MANDATORY               | F1                         |
| 34.050              |                                                      | MOS    | 24       |                                                     |          | 18-JAN-2001 | 18-JAN-2003             |                            |
| ASSOCIATED          |                                                      | HRSMSC |          |                                                     |          | 7494        |                         |                            |
|                     | REF: AMM 34-10-01                                    | AFL    |          |                                                     |          | 5466        |                         |                            |
| + 341116            | TEST FAR 91.411                                      |        |          |                                                     |          |             | MANDATORY               | F3                         |
| 34.071              |                                                      | MOS    | 24       |                                                     |          | 18-JAN-2001 | 18-JAN-2003             |                            |
|                     |                                                      | HRSMSC |          |                                                     |          | 7494        |                         |                            |
|                     | REF:                                                 | AFL    |          |                                                     |          | 5466        |                         |                            |
| 341101              | ALTIMETER, PILOT                                     |        |          |                                                     |          |             |                         | F3                         |
| 34.070              | 622-3975-003                                         | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                     | 1323                                                 | HRSMSC | O/C      | 0                                                   |          | 0           |                         |                            |
|                     | REF: AMM 34-10-03                                    | AFL    |          |                                                     |          | 0           |                         |                            |
| + 340146            | LEAK CHECK LEFT STATIC SYSTEM                        |        |          |                                                     |          |             | MANDATORY               | F1                         |
| 34.050              |                                                      | MOS    | 24       |                                                     |          | 18-JAN-2001 | 18-JAN-2003             |                            |
| ASSOCIATED          |                                                      | HRSMSC |          |                                                     |          | 7494        |                         |                            |
|                     | REF: AMM 34-10-01                                    | AFL    |          |                                                     |          | 5466        |                         |                            |
| + 341106            | TEST FAR 91.411                                      |        |          |                                                     |          |             | MANDATORY               | F3                         |
| 34.070              |                                                      | MOS    | 24       |                                                     |          | 18-JAN-2001 | 18-JAN-2003             |                            |
|                     |                                                      | HRSMSC |          |                                                     |          | 7494        |                         |                            |
|                     | REF:                                                 | AFL    |          |                                                     |          | 5466        |                         |                            |
| 341121              | ALTIMETER, STAND-BY                                  |        |          |                                                     |          |             |                         | F3                         |
| 34.075              | 622-3975-003                                         | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRSMSC | O/C      | 0                                                   |          | 0           |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                                                     |          | 0           |                         |                            |
| + 340146            | LEAK CHECK LEFT STATIC SYSTEM                        |        |          |                                                     |          |             | MANDATORY               | F1                         |
| 34.050              |                                                      | MOS    | 24       |                                                     |          | 18-JAN-2001 | 18-JAN-2003             |                            |
| ASSOCIATED          |                                                      | HRSMSC |          |                                                     |          | 7494        |                         |                            |
|                     | REF: AMM 34-10-01                                    | AFL    |          |                                                     |          | 5466        |                         |                            |
| + 340151            | LEAK CHECK RIGHT STATIC SYSTEM                       |        |          |                                                     |          |             | MANDATORY               | F1                         |
| 34.050              |                                                      | MOS    | 24       |                                                     |          | 18-JAN-2001 | 18-JAN-2003             |                            |
| ASSOCIATED          |                                                      | HRSMSC |          |                                                     |          | 7494        |                         |                            |
|                     | REF: AMM 34-10-01                                    | AFL    |          |                                                     |          | 5466        |                         |                            |
| 343176              | ANNUNCIATOR, COMPASS COPILOT                         |        |          |                                                     |          |             |                         | F3                         |
| 34.170              | PN                                                   | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRSMSC | O/C      | 0                                                   |          | 0           |                         |                            |
|                     | REF: AMM 34-20-08                                    | AFL    |          |                                                     |          | 0           |                         |                            |
| 343131              | ANNUNCIATOR, COMPASS PILOT                           |        |          |                                                     |          |             |                         | F3                         |
| 34.170              | PN                                                   | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRSMSC | O/C      | 0                                                   |          | 0           |                         |                            |
|                     | REF: AMM 34-20-08                                    | AFL    |          |                                                     |          | 0           |                         |                            |



**Aircraft Model - 1124 WESTWIND**
**Report Date 11-APR-2002**
**Owner Name - R&S AIRCRAFT INVESTMENTS, LLC**
**A/C Serial #: 368 A/C Reg. #: N368MD**

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION |     |     |     |     | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|--------|----------|------------------------------|-----|-----|-----|-----|----------|-------------|-------------------------|----------------------------|
|                     |                                                      |        |          | TSN                          | TSO | TSR | TSI | ADJ |          |             |                         |                            |
| 346681              | ANTENNA, #1 VLF                                      |        |          |                              |     |     |     |     |          |             |                         | F5                         |
| 34.640              | 10085-2                                              | MOS    |          |                              |     |     |     |     |          | 03-APR-1989 |                         |                            |
|                     | 6025                                                 | HRS/MS | O/C      | 0                            |     |     |     |     |          | 4215        |                         |                            |
|                     | REF: AMM 34-60-02                                    | AFL    |          |                              |     |     |     |     |          | 2745        |                         |                            |
| 347681              | ANTENNA, GLIDESLOPE                                  |        |          |                              |     |     |     |     |          |             |                         | F2                         |
| 34.570              | DMN-25-1                                             | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | 1896                                                 | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 34-50-01                                    | AFL    |          | 0                            |     |     |     |     |          | 0           |                         |                            |
| 346611              | ANTENNA, NO.1 ADF LOOP                               |        |          |                              |     |     |     |     |          |             |                         | F1                         |
| 34.350              | 522-3761-001                                         | MOS    |          |                              |     |     |     |     |          | 31-JAN-1986 |                         |                            |
|                     | 4428                                                 | HRS/MS | O/C      | 0                            |     |     |     |     |          | 2855        |                         |                            |
|                     | REF: AMM 34-50-03/04                                 | AFL    |          |                              |     |     |     |     |          | 1770        |                         |                            |
| 346131              | ANTENNA, NO.1 ATC TRANSPONDER                        |        |          |                              |     |     |     |     |          |             |                         | F1                         |
| 34.330              | DMNI-50-6                                            | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | 323                                                  | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 34-50-06                                    | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 347121              | ANTENNA, NO.1 DME                                    |        |          |                              |     |     |     |     |          |             |                         | F1                         |
| 34.360              | 4-873127-501                                         | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | 3234                                                 | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         | 2                          |
|                     | REF: AMM 34-50-02                                    | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 348111              | ANTENNA, NO.1 LRN                                    |        |          |                              |     |     |     |     |          |             |                         |                            |
| 34.660              | 42804-000100-00                                      | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | 1346                                                 | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 34-60-04                                    | AFL    |          | 0                            |     |     |     |     |          | 0           |                         |                            |
| 346206              | ANTENNA, NO.1 MARKER BEACON                          |        |          |                              |     |     |     |     |          |             |                         | F5                         |
| 34.550              | DMN-27-1/A                                           | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | 1919                                                 | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 34-50-01                                    | AFL    |          | 0                            |     |     |     |     |          | 0           |                         |                            |
| 346546              | ANTENNA, NO.1 VOR                                    |        |          |                              |     |     |     |     |          |             |                         | F5                         |
| 34.580              | DMN-4-15-3/D                                         | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | 10987                                                | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 346636              | ANTENNA, NO.2 ADF LOOP                               |        |          |                              |     |     |     |     |          |             |                         | F1                         |
| 34.350              | 522-3761-001                                         | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 34-50-03/04                                 | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 346136              | ANTENNA, NO.2 ATC TRANSPONDER                        |        |          |                              |     |     |     |     |          |             |                         | F1                         |
| 34.330              | DMNI-50-6                                            | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | 3259                                                 | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 34-50-06                                    | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 347621              | ANTENNA, NO.2 DME                                    |        |          |                              |     |     |     |     |          |             |                         | F1                         |
| 34.360              | 4-873127-503                                         | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | 3242                                                 | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         | 2                          |
|                     | REF: AMM 34-50-02                                    | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L



Aircraft Model - 1124 WESTWIND

Report Date **11-APR-2002**

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER                                                     | UNIT                 | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp   | COMPLIANCE | DISPOSITION<br>NEXT DUE     | AREA<br>PRICE<br>LABOR HRS |
|---------------------|----------------------------------------------------------------------------------------------------------|----------------------|----------|-----------------------------------------------------|------------|------------|-----------------------------|----------------------------|
| 348114<br>34.700    | ANTENNA, NO.2 LRN<br>42804-000100-00<br>SN-UNKNOWN<br>REF: AMM 34-60-04                                  | MOS<br>HRSMSC<br>AFL | O/C      | 0<br>0                                              |            |            | 11-FEB-1982<br>0<br>0       |                            |
| 346216<br>34.550    | ANTENNA, NO.2 MARKER BEACON<br>PN<br>SN-UNKNOWN<br>REF: AMM 34-50-01                                     | MOS<br>HRSMSC<br>AFL | O/C      | 0<br>0                                              |            |            | 11-FEB-1982<br>0<br>0       | F5                         |
| 346576<br>34.600    | ANTENNA, NO.2 VOR<br>DMN-4-15-3A<br>10993<br>REF: NO REF                                                 | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |            |            | 11-FEB-1982<br>0<br>0       | F3                         |
| 345626<br>34.340    | ANTENNA, RADIO ALTIMETER RECEIVER<br>522-4140-001<br>509<br>REF: AMM 34-10-04                            | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |            |            | 11-FEB-1982<br>0<br>0       | F1                         |
| 345621<br>34.340    | ANTENNA, RADIO ALTIMETER TRANSMIT<br>622-4550-001<br>459<br>REF: AMM 34-10-04                            | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |            |            | 11-FEB-1982<br>0<br>0       | F1                         |
| 345831<br>34.520    | ANTENNA, WEATHER RADAR<br>622-2504-001<br>270<br>REF: AMM 34-40-01,-02,-03,-04                           | MOS<br>HRSMSC<br>AFL | O/C      | 5222<br>3870                                        | 04/19/1993 |            | 19-FEB-1993<br>5222<br>3870 | F2                         |
| 344611<br>34.370    | BATTERY, EMERGENCY GYRO POWER SUPPLY<br>501-1075-05PS823A/T<br>1186<br>REF:                              | MOS<br>HRSMSC<br>AFL | O/C      |                                                     |            |            | 06-APR-1998<br>6346<br>4787 | F5<br>1                    |
| 344621<br>34.370    | DEEP CYCLE POWER SUPPLY GNS-500 NAV SYSTEM<br>MOS<br>HRSMSC<br>AFL<br>REF: MSC BFG SL-80J/JET TP-329     | MOS<br>HRSMSC<br>AFL | O/C      |                                                     |            |            | 06-APR-1998<br>6346<br>4787 | F5                         |
| + 344616<br>34.370  | INSPECT EMERGENCY POWER SUPPLY BATTERY/STAND-BY ATTITUDE GYRO<br>MOS<br>HRSMSC<br>AFL<br>REF: AMM NO REF | MOS<br>HRSMSC<br>AFL | 3<br>200 |                                                     |            |            | 06-NOV-2001<br>7774<br>5641 | 06-FEB-2002<br>7974<br>F5  |
| 347626<br>34.150    | BOX, DME DUAL CONTROL<br>PN<br>SN-UNKNOWN<br>REF: NO REF                                                 | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |            |            | 11-FEB-1982<br>0<br>0       | F2<br>1                    |
| 347641<br>34.580    | BOX, HORIZONTAL SITUATION INDICATOR CONTROL<br>622-4569-001<br>SN-UNKNOWN<br>REF: NO REF                 | MOS<br>HRSMSC<br>AFL | O/C      | 0<br>0                                              |            |            | 11-FEB-1982<br>0<br>0       | F4                         |



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|--------|----------|-----------------------------------------------------|----------|-------------|-------------------------|----------------------------|
| 346551              | BOX, NO.1 VOR CONTROL                                |        |          |                                                     |          |             |                         | F3                         |
| 34.590              | 622-2899-012                                         | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRSMSC | O/C      | 0                                                   |          | 0           |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                                                     |          | 0           |                         |                            |
| 346581              | BOX, NO.2 VOR CONTROL                                |        |          |                                                     |          |             |                         | F3                         |
| 34.590              | DMN-4-15-3/D                                         | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRSMSC | O/C      | 0                                                   |          | 0           |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                                                     |          | 0           |                         |                            |
| 342601              | COMPASS, STAND-BY MAGNETIC                           |        |          |                                                     |          |             |                         | F3                         |
| 34.100              | 2-883023-501                                         | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                     | 1A234                                                | HRSMSC | O/C      | 0                                                   |          | 0           |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                                                     |          | 0           |                         |                            |
| 342611              | SWING CHECK                                          |        |          |                                                     |          |             |                         | F3                         |
| 34.100              |                                                      | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                     |                                                      | HRSMSC | O/C      |                                                     |          | 0           |                         |                            |
|                     | REF: CMM                                             | AFL    |          |                                                     |          | 0           |                         |                            |
| 343113              | COMPENSATOR, NO.1                                    |        |          |                                                     |          |             |                         |                            |
| 34.440              | 656767                                               | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                     | 81082033                                             | HRSMSC | O/C      | 0                                                   |          | 0           |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                                                     |          | 0           |                         |                            |
| 343158              | COMPENSATOR, NO.2                                    |        |          |                                                     |          |             |                         |                            |
| 34.440              | 656767                                               | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                     | 81092117                                             | HRSMSC | O/C      | 0                                                   |          | 0           |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                                                     |          | 0           |                         |                            |
| 344131              | COMPUTER, FLIGHT COPILOT                             |        |          |                                                     |          |             |                         | F2                         |
| 34.220              | 622-5224-005                                         | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRSMSC | O/C      | 0                                                   |          | 0           |                         |                            |
|                     | REF: AMM 4-20-04/21-04                               | AFL    |          |                                                     |          | 0           |                         |                            |
| 343631              | COMPUTER, FLIGHT PILOT                               |        |          |                                                     |          |             |                         | F2                         |
| 34.220              | 622-5224-004                                         | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                     | 5128                                                 | HRSMSC | O/C      | 0                                                   |          | 0           |                         | 1                          |
|                     | REF: AMM 4-20-04/21-04                               | AFL    |          |                                                     |          | 0           |                         |                            |
| 340201              | COMPUTER, NAVIGATION                                 |        |          |                                                     |          |             |                         | F3                         |
| 34.460              | 622-5107-001                                         | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRSMSC | O/C      | 0                                                   |          | 0           |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                                                     |          | 0           |                         |                            |
| 343671              | COMPUTER, NO.1 AIR DATA                              |        |          |                                                     |          |             |                         | F3                         |
| 34.480              | 622-5465-214                                         | MOS    |          |                                                     |          | 26-MAR-1996 |                         |                            |
|                     | 1080                                                 | HRSMSC | O/C      |                                                     |          |             |                         |                            |
|                     | REF: AMM 22-20-00                                    | AFL    |          |                                                     |          |             |                         |                            |
| + 343672            | CALIBRATE FAR 91.411                                 |        |          |                                                     |          |             | MANDATORY               | F3                         |
| 34.480              |                                                      | MOS    | 24       |                                                     |          | 18-JAN-2001 | 18-JAN-2003             |                            |
|                     |                                                      | HRSMSC |          |                                                     |          | 7494        |                         |                            |
|                     | REF: See Workcard                                    | AFL    |          |                                                     |          | 5466        |                         |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L



Aircraft Model - 1124 WESTWIND  
 Owner Name - R&S AIRCRAFT INVESTMENTS, LLC  
 A/C Serial #: 368 A/C Reg. #: N368MD

Report Date **11-APR-2002**

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|--------|----------|-----------------------------------------------------|----------|------------|-------------------------|----------------------------|
| 341604              | COMPUTER, SAT TAS                                    |        |          |                                                     |          |            |                         |                            |
| 34.410              | 630-30980-135                                        | MOS    |          |                                                     |          |            | 11-FEB-1982             | F3                         |
|                     | 1589                                                 | HRS/MS | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: NO REF                                          | AFL    |          | 0                                                   |          | 0          |                         |                            |
| 346616              | CONTROL, NO.1 ADF                                    |        |          |                                                     |          |            |                         | F3                         |
| 34.260              | 622-4526-003                                         | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | 10601                                                | HRS/MS | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                                                     |          | 0          |                         |                            |
| 346641              | CONTROL, NO.2 ADF                                    |        |          |                                                     |          |            |                         | F3                         |
| 34.260              | PN                                                   | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                                                     |          | 0          |                         |                            |
| 346251              | CONTROLLER, NO.1 NAVIGATION                          |        |          |                                                     |          |            |                         | F3                         |
| 34.470              | 622-4524-079                                         | MOS    |          |                                                     |          |            | 14-JAN-1992             |                            |
|                     | 7898                                                 | HRS/MS | O/C      | 5012                                                |          | 5012       |                         |                            |
|                     | REF: NO REF                                          | AFL    |          | 3648                                                |          | 3648       |                         |                            |
| 346261              | CONTROLLER, NO.2 NAVIGATION                          |        |          |                                                     |          |            |                         | F3                         |
| 34.470              | 622-4524-079                                         | MOS    |          |                                                     |          |            | 15-JAN-1992             |                            |
|                     | 7863                                                 | HRS/MS | O/C      |                                                     |          | 5012       |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                                                     |          | 3648       |                         |                            |
| 346141              | CONTROLLER, TRANSPONDER                              |        |          |                                                     |          |            |                         | F4                         |
| 34.540              | 622-4527-011                                         | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | 6475                                                 | HRS/MS | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: NO REF                                          | AFL    |          | 0                                                   |          | 0          |                         |                            |
| 346306              | CONVERTER, NAV RECEIVER/VHF POWER                    |        |          |                                                     |          |            |                         | F3                         |
| 34.460              | 622-2093-001                                         | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | 17233                                                | HRS/MS | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: NO REF                                          | AFL    |          | 0                                                   |          | 0          |                         |                            |
| 347201              | CONVERTER, NO.1 DME SYNCHRO                          |        |          |                                                     |          |            |                         | F3                         |
| 34.650              | 622-1920-001                                         | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 34-50-02                                    | AFL    |          | 0                                                   |          | 0          |                         |                            |
| 347211              | CONVERTER, NO.2 DME SYNCHRO                          |        |          |                                                     |          |            |                         | F3                         |
| 34.650              | 622-1920-001                                         | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 34-50-02                                    | AFL    |          | 0                                                   |          | 0          |                         |                            |
| 341096              | CONVERTER, RADIO ALTIMETER                           |        |          |                                                     |          |            |                         | F3                         |
| 34.420              | 995-29400-112                                        | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: NO REF                                          | AFL    |          | 0                                                   |          | 0          |                         |                            |
| 343641              | COUPLER, NO.1 FLIGHT DIRECTOR MODE                   |        |          |                                                     |          |            |                         | F2                         |
| 34.230              | 161E-2A                                              | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 22-03-06                                    | AFL    |          |                                                     |          | 0          |                         |                            |



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC  
A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION |     |     |     |     | Warr Exp   | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|--------|----------|------------------------------|-----|-----|-----|-----|------------|-------------|-------------------------|----------------------------|
|                     |                                                      |        |          | TSN                          | TSO | TSR | TSI | ADJ |            |             |                         |                            |
| 348146              | COUPLER, NO.1 LRN                                    |        |          |                              |     |     |     |     |            |             |                         |                            |
| 34.740              | 42807-001 100-001                                    | MOS    |          |                              |     |     |     |     |            | 11-FEB-1982 |                         |                            |
|                     | 1585                                                 | HRS/MS | O/C      | 0                            |     |     |     |     |            | 0           |                         |                            |
|                     | REF: NO REF                                          | AFL    |          | 0                            |     |     |     |     |            | 0           |                         |                            |
| 344141              | COUPLER, NO.2 FLIGHT DIRECTOR MODE                   |        |          |                              |     |     |     |     |            |             |                         | F2                         |
| 34.230              | 161E-2A                                              | MOS    |          |                              |     |     |     |     |            | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |            | 0           |                         |                            |
|                     | REF: AMM 22-03-06                                    | AFL    |          |                              |     |     |     |     |            | 0           |                         |                            |
| 348151              | COUPLER, NO.2 LRN                                    |        |          |                              |     |     |     |     |            |             |                         |                            |
| 34.740              | 42807-001 100-001                                    | MOS    |          |                              |     |     |     |     |            | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |            | 0           |                         |                            |
|                     | REF: NO REF                                          | AFL    |          | 0                            |     |     |     |     |            | 0           |                         |                            |
| 345833              | DISH, WEATHER RADAR FLAT                             |        |          |                              |     |     |     |     |            |             |                         | F2                         |
| 34.530              | ANT-318                                              | MOS    |          |                              |     |     |     |     | 04/19/1993 | 19-FEB-1993 |                         |                            |
|                     | 270                                                  | HRS/MS | O/C      | 5222                         |     |     |     |     |            | 5222        |                         |                            |
|                     | REF: AMM 34-40-01                                    | AFL    |          | 3870                         |     |     |     |     |            | 3870        |                         |                            |
| 348116              | DISPLAY, NO.1 LRN CONTROL                            |        |          |                              |     |     |     |     |            |             |                         |                            |
| 34.670              | 622-5493-001                                         | MOS    |          |                              |     |     |     |     |            | 11-FEB-1982 |                         |                            |
|                     | 040                                                  | HRS/MS | O/C      | 0                            |     |     |     |     |            | 0           |                         |                            |
|                     | REF: AMM 34-60-04                                    | AFL    |          | 0                            |     |     |     |     |            | 0           |                         |                            |
| 348121              | DISPLAY, NO.2 LRN CONTROL                            |        |          |                              |     |     |     |     |            |             |                         |                            |
| 34.670              | 622-5493-001                                         | MOS    |          |                              |     |     |     |     |            | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |            | 0           |                         |                            |
|                     | REF: AMM 34-60-04                                    | AFL    |          | 0                            |     |     |     |     |            | 0           |                         |                            |
| 345631              | GENERATOR, TONE (ALERTER)                            |        |          |                              |     |     |     |     |            |             |                         | F3                         |
| 34.300              | 540-25100-004                                        | MOS    |          |                              |     |     |     |     |            | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |            | 0           |                         |                            |
|                     | REF: AMM 34-10-03                                    | AFL    |          |                              |     |     |     |     |            | 0           |                         |                            |
| 343101              | GYRO, NO.1 DIRECTIONAL                               |        |          |                              |     |     |     |     |            |             |                         | F4                         |
| 34.110              | 622-4176-004                                         | MOS    |          |                              |     |     |     |     | 04/02/1992 | 02-OCT-1991 |                         |                            |
|                     | 871                                                  | HRS/MS | O/C      |                              | 0   |     |     |     |            | 4931        |                         |                            |
|                     | REF: AMM 34-20-08                                    | AFL    |          |                              |     |     |     |     |            | 3454        |                         |                            |
| 343106              | BENCH CHECK                                          |        |          |                              |     |     |     |     |            |             |                         | F4                         |
| 34.110              |                                                      | MOS    |          |                              |     |     |     |     |            | 11-FEB-1982 |                         |                            |
|                     |                                                      | HRS/MS | O/C      |                              |     |     |     |     |            | 0           |                         |                            |
|                     | REF: CMM                                             | AFL    |          |                              |     |     |     |     |            | 0           |                         |                            |
| 343651              | GYRO, NO.1 VERTICAL                                  |        |          |                              |     |     |     |     |            |             |                         | F3                         |
| 34.200              | 792-6694-001                                         | MOS    |          |                              |     |     |     |     |            | 06-JAN-1986 |                         |                            |
|                     | 6381                                                 | HRS/MS | O/C      | 0                            |     |     |     |     |            | 2808        |                         | 2                          |
|                     | REF: AMM 34-20-07(1124/A), 34-21-05(1124A)           | AFL    |          |                              |     |     |     |     |            | 1739        |                         |                            |
| 343146              | GYRO, NO.2 DIRECTIONAL                               |        |          |                              |     |     |     |     |            |             |                         | F4                         |
| 34.110              | 2587193-43                                           | MOS    |          |                              |     |     |     |     |            | 24-SEP-1987 |                         |                            |
|                     | 81095980                                             | HRS/MS | O/C      | 0                            |     |     |     |     |            | 3737        |                         |                            |
|                     | REF: AMM 34-20-08                                    | AFL    |          |                              |     |     |     |     |            | 2345        |                         |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE  | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|--------|----------|-----------------------------------------------------|----------|-------------|--------------------------|----------------------------|
| 343151<br>34.110    | BENCH CHECK                                          | MOS    |          |                                                     |          | 11-FEB-1982 |                          | F4                         |
|                     | REF: CMM                                             | HRS/MS | O/C      |                                                     |          | 0           |                          |                            |
|                     |                                                      | AFL    |          |                                                     |          | 0           |                          |                            |
| 344151<br>34.200    | GYRO, NO 2 VERTICAL                                  | MOS    |          |                                                     |          | 11-FEB-1982 |                          | F3                         |
|                     | 792-6694-001                                         | HRS/MS | O/C      | 0                                                   |          | 0           |                          |                            |
|                     | SN-UNKNOWN                                           | AFL    |          |                                                     |          | 0           |                          |                            |
|                     | REF: AMM 34-20-07(1124/A), 34-21-05(1124A)           |        |          |                                                     |          |             |                          |                            |
| 347611<br>34.140    | INDICATOR, DME COPILOT                               | MOS    |          |                                                     |          | 11-FEB-1982 |                          | F3                         |
|                     | PN                                                   | HRS/MS | O/C      | 0                                                   |          | 0           |                          |                            |
|                     | SN-UNKNOWN                                           | AFL    |          |                                                     |          | 0           |                          |                            |
|                     | REF: NO REF                                          |        |          |                                                     |          |             |                          |                            |
| 347111<br>34.140    | INDICATOR, DME PILOT                                 | MOS    |          |                                                     |          | 11-FEB-1982 |                          | F3                         |
|                     | PN                                                   | HRS/MS | O/C      | 0                                                   |          | 0           |                          |                            |
|                     | SN-UNKNOWN                                           | AFL    |          |                                                     |          | 0           |                          |                            |
|                     | REF: NO REF                                          |        |          |                                                     |          |             |                          |                            |
| 344101<br>34.280    | INDICATOR, FLIGHT DIRECTOR COPILOT                   | MOS    |          |                                                     |          | 11-FEB-1982 |                          | F3                         |
|                     | 622-4808-004                                         | HRS/MS | O/C      | 0                                                   |          | 0           |                          |                            |
|                     | SN-UNKNOWN                                           | AFL    |          |                                                     |          | 0           |                          |                            |
|                     | REF: AMM 4-20-01/21-02                               |        |          |                                                     |          |             |                          |                            |
| 343601<br>34.280    | INDICATOR, FLIGHT DIRECTOR PILOT                     | MOS    |          |                                                     |          | 11-FEB-1982 |                          | F3                         |
|                     | 622-4808-004                                         | HRS/MS | O/C      | 0                                                   |          | 0           |                          |                            |
|                     | 823                                                  | AFL    |          |                                                     |          | 0           |                          |                            |
|                     | REF: AMM 4-20-01/21-02                               |        |          |                                                     |          |             |                          |                            |
| 341601<br>34.080    | INDICATOR, LEFT MACH/AIRSPD                          | MOS    |          |                                                     |          | 07-APR-1987 |                          | F3                         |
|                     | 622-4382-013                                         | HRS/MS | O/C      | 0                                                   |          | 3676        |                          |                            |
|                     | 1302                                                 | AFL    |          |                                                     |          | 2288        |                          |                            |
|                     | REF: NO REF                                          |        |          |                                                     |          |             |                          |                            |
| 341606<br>34.080    | CALIBRATE                                            | MOS    |          |                                                     |          | 10-APR-1990 |                          | F3                         |
|                     |                                                      | HRS/MS | O/C      |                                                     |          | 4560        |                          |                            |
|                     | REF: CMM                                             | AFL    |          |                                                     |          | 3132        |                          |                            |
| 340111<br>34.040    | LEAK CHECK LEFT PITOT SYSTEM                         | MOS    |          |                                                     |          | 26-MAR-1996 |                          | F1                         |
|                     |                                                      | HRS/MS | O/C      |                                                     |          |             |                          |                            |
|                     | ASSOCIATED                                           | AFL    |          |                                                     |          |             |                          |                            |
|                     | REF: AMM 34-10-01                                    |        |          |                                                     |          |             |                          |                            |
| + 340146<br>34.050  | LEAK CHECK LEFT STATIC SYSTEM                        | MOS    | 24       |                                                     |          | 18-JAN-2001 | MANDATORY<br>18-JAN-2003 | F1                         |
|                     |                                                      | HRS/MS |          |                                                     |          | 7494        |                          |                            |
|                     | ASSOCIATED                                           | AFL    |          |                                                     |          | 5466        |                          |                            |
|                     | REF: AMM 34-10-01                                    |        |          |                                                     |          |             |                          |                            |
| 342090<br>34.380    | INDICATOR, LEFT VERTICAL NAV/SPEED                   | MOS    |          |                                                     |          | 22-OCT-1982 |                          | F3                         |
|                     | 622-4782-003/VNI-80                                  | HRS/MS | O/C      | 0                                                   |          | 482         |                          |                            |
|                     | SN-UNKNOWN                                           | AFL    |          |                                                     |          |             |                          |                            |
|                     | REF: NO REF                                          |        |          |                                                     |          |             |                          |                            |



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----<br>TSN TSO TSR TSI ADJ | INSTALLATION | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|--------|----------|-----------------------------------------|--------------|----------|-------------|-------------------------|----------------------------|
| 342101              | INDICATOR, LEFT VERTICAL SPEED                       |        |          |                                         |              |          |             |                         | F3                         |
| 34.090              | 4883748-1                                            | MOS    |          |                                         |              |          | 11-FEB-1982 |                         | \$486.                     |
|                     | 640                                                  | HRS/MS | O/C      | 0                                       |              |          | 0           |                         |                            |
|                     | REF: AMM 34-10-03                                    | AFL    |          |                                         |              |          | 0           |                         |                            |
| 342106              | BENCH CHECK                                          |        |          |                                         |              |          |             |                         | F3                         |
| 34.090              |                                                      | MOS    |          |                                         |              |          | 11-FEB-1982 |                         |                            |
|                     |                                                      | HRS/MS | O/C      |                                         |              |          | 0           |                         |                            |
|                     | REF: See Workcard                                    | AFL    |          |                                         |              |          | 0           |                         |                            |
| + 340146            | LEAK CHECK LEFT STATIC SYSTEM                        |        |          |                                         |              |          |             | MANDATORY               | F1                         |
| 34.050              |                                                      | MOS    | 24       |                                         |              |          | 18-JAN-2001 | 18-JAN-2003             |                            |
| ASSOCIATED          |                                                      | HRS/MS |          |                                         |              |          | 7494        |                         |                            |
|                     | REF: AMM 34-10-01                                    | AFL    |          |                                         |              |          | 5466        |                         |                            |
| 342801              | INDICATOR, NO.1 GYRO ATTITUDE                        |        |          |                                         |              |          |             |                         | F3                         |
| 34.430              | 4020531-170                                          | MOS    |          |                                         | 0            |          | 25-MAR-1991 |                         |                            |
|                     | 80110830                                             | HRS/MS | O/C      |                                         | 0            |          | 4830        |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                                         | 0            |          | 3441        |                         |                            |
| 347651              | INDICATOR, NO.1 HORIZONTAL SITUATION                 |        |          |                                         |              |          |             |                         | F3                         |
| 34.560              | 622-4176-004                                         | MOS    |          |                                         |              |          | 10-MAR-1987 |                         |                            |
|                     | 871                                                  | HRS/MS | O/C      | 0                                       |              |          | 3623        |                         |                            |
|                     | REF: AMM 4-20-02/21-02                               | AFL    |          | 0                                       |              |          | 2255        |                         |                            |
| 342811              | INDICATOR, NO.2 GYRO ATTITUDE                        |        |          |                                         |              |          |             |                         | F3                         |
| 34.430              | 4020531-170                                          | MOS    |          |                                         |              |          | 19-MAR-1991 |                         |                            |
|                     | 6020225                                              | HRS/MS | O/C      |                                         |              |          | 4827        |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                                         |              |          | 3439        |                         |                            |
| 347655              | INDICATOR, NO.2 HORIZONTAL SITUATION                 |        |          |                                         |              |          |             |                         | F3                         |
| 34.560              | 622-4176-004                                         | MOS    |          |                                         |              |          | 11-FEB-1982 |                         |                            |
|                     | 1854                                                 | HRS/MS | O/C      | 0                                       |              |          | 0           |                         |                            |
|                     | REF: AMM 4-20-02/21-02                               | AFL    |          |                                         |              |          | 0           |                         |                            |
| 340601              | INDICATOR, OUTSIDE AIR TEMPERATURE                   |        |          |                                         |              |          |             |                         | F3                         |
| 34.380              | 4883753-3                                            | MOS    |          |                                         |              |          | 14-APR-1984 |                         |                            |
|                     | 64128-13                                             | HRS/MS | O/C      | 0                                       |              |          | 1645        |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                                         |              |          |             |                         |                            |
| 345611              | INDICATOR, RADIO ALTIMETER                           |        |          |                                         |              |          |             |                         | F3                         |
| 34.250              | 521-29007-203                                        | MOS    |          |                                         |              |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                                       |              |          | 0           |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                                         |              |          | 0           |                         |                            |
| 343166              | INDICATOR, RADIO MAGNETIC COPILOT                    |        |          |                                         |              |          |             |                         | F3                         |
| 34.160              | 622-2506-002                                         | MOS    |          |                                         |              |          | 14-DEC-1986 |                         |                            |
|                     | 1546                                                 | HRS/MS | O/C      | 0                                       |              |          | 3484        |                         | 1                          |
|                     | REF: AMM 34-50-05                                    | AFL    |          |                                         |              |          | 2157        |                         |                            |
| 343121              | INDICATOR, RADIO MAGNETIC PILOT                      |        |          |                                         |              |          |             |                         | F3                         |
| 34.160              | 622-2506-002                                         | MOS    |          |                                         |              |          | 05-NOV-1986 |                         |                            |
|                     | 1213                                                 | HRS/MS | O/C      | 0                                       |              |          | 3385        |                         | 1                          |
|                     | REF: AMM 34-50-05                                    | AFL    |          |                                         |              |          | 2098        |                         |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Page 68 of 107



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|--------|----------|-----------------------------------------------------|----------|-------------|-------------------------|----------------------------|
| 341056              | INDICATOR, RATE OF CLIMB COPILOT                     |        |          |                                                     |          |             |                         | F3                         |
| 34.400              | 229-0324-010                                         | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRSMSC | O/C      | 0                                                   |          | 0           |                         |                            |
|                     | REF: NO REF                                          | AFL    |          | 0                                                   |          | 0           |                         |                            |
| 341046              | INDICATOR, RATE OF CLIMB PILOT                       |        |          |                                                     |          |             |                         | F3                         |
| 34.400              | 622-7689-003                                         | MOS    |          |                                                     |          | 31-MAY-1993 |                         |                            |
|                     | 166                                                  | HRSMSC | O/C      | 0                                                   |          | 5278        |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                                                     |          | 3928        |                         |                            |
| 341611              | INDICATOR, RIGHT MACH/AIRSPEED                       |        |          |                                                     |          |             |                         | F3                         |
| 34.080              | 883615-513                                           | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                     | 149                                                  | HRSMSC | O/C      | 0                                                   |          | 0           |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                                                     |          | 0           |                         |                            |
| 341616              | CALIBRATE                                            |        |          |                                                     |          |             |                         | F3                         |
| 34.080              |                                                      | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                     |                                                      | HRSMSC | O/C      |                                                     |          | 0           |                         |                            |
|                     | REF: CMM VENDOR                                      | AFL    |          |                                                     |          | 0           |                         |                            |
| 340116              | LEAK CHECK RIGHT PITOT SYSTEM                        |        |          |                                                     |          |             |                         | F1                         |
| 34.040              |                                                      | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
| ASSOCIATED          |                                                      | HRSMSC | O/C      |                                                     |          | 0           |                         |                            |
|                     | REF: AMM 34-10-01                                    | AFL    |          |                                                     |          | 0           |                         |                            |
| + 340151            | LEAK CHECK RIGHT STATIC SYSTEM                       |        |          |                                                     |          |             | MANDATORY               | F1                         |
| 34.050              |                                                      | MOS    | 24       |                                                     |          | 18-JAN-2001 | 18-JAN-2003             |                            |
| ASSOCIATED          |                                                      | HRSMSC |          |                                                     |          | 7494        |                         |                            |
|                     | REF: AMM 34-10-01                                    | AFL    |          |                                                     |          | 5466        |                         |                            |
| 342111              | INDICATOR, RIGHT VERTICAL SPEED                      |        |          |                                                     |          |             |                         | F3                         |
| 34.090              | RCS-60-IL-10                                         | MOS    |          |                                                     |          | 11-FEB-1982 |                         | \$486.                     |
|                     | MD12158                                              | HRSMSC | O/C      | 0                                                   |          | 0           |                         |                            |
|                     | REF: AMM 34-10-03                                    | AFL    |          |                                                     |          | 0           |                         |                            |
| 342116              | BENCH CHECK                                          |        |          |                                                     |          |             |                         | F3                         |
| 34.090              |                                                      | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                     |                                                      | HRSMSC | O/C      |                                                     |          | 0           |                         |                            |
|                     | REF: See Workcard                                    | AFL    |          |                                                     |          | 0           |                         |                            |
| + 340151            | LEAK CHECK RIGHT STATIC SYSTEM                       |        |          |                                                     |          |             | MANDATORY               | F1                         |
| 34.050              |                                                      | MOS    | 24       |                                                     |          | 18-JAN-2001 | 18-JAN-2003             |                            |
| ASSOCIATED          |                                                      | HRSMSC |          |                                                     |          | 7494        |                         |                            |
|                     | REF: AMM 34-10-01                                    | AFL    |          |                                                     |          | 5466        |                         |                            |
| 341605              | INDICATOR, SAT TAS                                   |        |          |                                                     |          |             |                         | F3                         |
| 34.410              | 622-2294-002                                         | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRSMSC | O/C      | 0                                                   |          | 0           |                         |                            |
|                     | REF: NO REF                                          | AFL    |          | 0                                                   |          | 0           |                         |                            |
| 344601              | INDICATOR, STAND-BY HORIZON                          |        |          |                                                     |          |             |                         | F3                         |
| 34.290              | 501-1105-03                                          | MOS    |          |                                                     |          | 18-NOV-1984 |                         |                            |
|                     | 6010212                                              | HRSMSC | O/C      | 0                                                   |          | 2085        |                         |                            |
|                     | REF: AMM 34-20-09                                    | AFL    |          |                                                     |          | 1284        |                         |                            |



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD              | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER                             | UNIT                 | INTERVAL | TIME-----AT-----<br>TSN TSO TSR TSI ADJ | INSTALLATION<br>Warr Exp | COMPLIANCE                  | DISPOSITION<br>NEXT DUE  | AREA<br>PRICE<br>LABOR HRS |
|----------------------------------|----------------------------------------------------------------------------------|----------------------|----------|-----------------------------------------|--------------------------|-----------------------------|--------------------------|----------------------------|
| 345801<br>34.500                 | INDICATOR, WEATHER RADAR<br>622-4331-001<br>176<br>REF: AMM 34-40-01,-02,-03,-04 | MOS<br>HRS/MS<br>AFL | O/C      | 0                                       | 09/18/1993               | 18-MAR-1993<br>5231<br>3880 |                          | F3                         |
| 347101<br>34.270                 | INTERROGATOR, NO.1 DME<br>622-1233-001<br>13710<br>REF: AMM 34-50-02             | MOS<br>HRS/MS<br>AFL | O/C      | 0                                       |                          | 11-FEB-1982<br>0<br>0       |                          | F2                         |
| 347601<br>34.270                 | INTERROGATOR, NO.2 DME<br>622-1233-001<br>15123<br>REF: AMM 34-50-02             | MOS<br>HRS/MS<br>AFL | O/C      | 0                                       |                          | 11-FEB-1982<br>0<br>0       |                          | F2                         |
| 343663<br>34.190                 | PANEL, NO.1 FLIGHT GUIDANCE<br>622-2313-029<br>2661<br>REF: AMM 34-21-03         | MOS<br>HRS/MS<br>AFL | O/C      | 0<br>0                                  |                          | 11-FEB-1982                 |                          | F3                         |
| 343665<br>34.190                 | PANEL, NO.2 FLIGHT GUIDANCE<br>622-2265-030<br>SN-UNKNOWN<br>REF: AMM 34-21-03   | MOS<br>HRS/MS<br>AFL | O/C      | 0<br>0                                  |                          | 11-FEB-1982<br>0<br>0       |                          | F3                         |
| 345811<br>34.540                 | PANEL, WEATHER RADAR CONTROL<br>DCP-320<br>SN-UNKNOWN<br>REF: NO REF             | MOS<br>HRS/MS<br>AFL | O/C      | 0<br>0                                  |                          | 11-FEB-1982<br>0<br>0       |                          | F3                         |
| 340126<br>34.020                 | PORT, LEFT HEATED STATIC<br>3-883053-501<br>SN-UNKNOWN<br>REF: AMM 34-10-01      | MOS<br>HRS/MS<br>AFL | O/C      | 0                                       |                          | 11-FEB-1982<br>0<br>0       |                          | F1                         |
| 340121<br>34.060<br>ASSOCIATED   | DRAIN PITOT/STATIC SYSTEM<br>PKG 1, 2, 3<br>REF: AMM 34-10-00                    | MOS<br>HRS/MS<br>AFL | 200      |                                         |                          | 26-JUN-2001<br>7687<br>5594 |                          | F2                         |
| + 340146<br>34.050<br>ASSOCIATED | LEAK CHECK LEFT STATIC SYSTEM<br>REF: AMM 34-10-01                               | MOS<br>HRS/MS<br>AFL | 24       |                                         |                          | 18-JAN-2001<br>7494<br>5466 | MANDATORY<br>18-JAN-2003 | F1                         |
| 340131<br>34.030                 | PORT, LEFT UNHEATED STATIC<br>4-883050<br>SN-UNKNOWN<br>REF: AMM 34-10-01        | MOS<br>HRS/MS<br>AFL | O/C      | 0                                       |                          | 11-FEB-1982<br>0<br>0       |                          | F1                         |
| 340121<br>34.060<br>ASSOCIATED   | DRAIN PITOT/STATIC SYSTEM<br>PKG 1, 2, 3<br>REF: AMM 34-10-00                    | MOS<br>HRS/MS<br>AFL | 200      |                                         |                          | 26-JUN-2001<br>7687<br>5594 |                          | F2                         |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD              | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER                         | UNIT                 | INTERVAL | TIME-----AT-----<br>TSN TSO TSR TSI ADJ | INSTALLATION | Warr Exp | COMPLIANCE                  | DISPOSITION<br>NEXT DUE  | AREA<br>PRICE<br>LABOR HRS |
|----------------------------------|------------------------------------------------------------------------------|----------------------|----------|-----------------------------------------|--------------|----------|-----------------------------|--------------------------|----------------------------|
| + 340146<br>34.050<br>ASSOCIATED | LEAK CHECK LEFT STATIC SYSTEM<br>REF: AMM 34-10-01                           | MOS<br>HRSMSC<br>AFL | 24       |                                         |              |          | 18-JAN-2001<br>7494<br>5466 | MANDATORY<br>18-JAN-2003 | F1                         |
| 340136<br>34.020                 | PORT, RIGHT HEATED STATIC<br>3-883053-502<br>SN-UNKNOWN<br>REF: AMM 34-10-01 | MOS<br>HRSMSC<br>AFL | O/C      | 0                                       |              |          | 11-FEB-1982<br>0<br>0       |                          | F1                         |
| 340121<br>34.060<br>ASSOCIATED   | DRAIN PITOT/STATIC SYSTEM<br>PKG 1, 2, 3<br>REF: AMM 34-10-00                | MOS<br>HRSMSC<br>AFL | 200      |                                         |              |          | 26-JUN-2001<br>7687<br>5594 |                          | F2<br>1.5                  |
| + 340151<br>34.050<br>ASSOCIATED | LEAK CHECK RIGHT STATIC SYSTEM<br>REF: AMM 34-10-01                          | MOS<br>HRSMSC<br>AFL | 24       |                                         |              |          | 18-JAN-2001<br>7494<br>5466 | MANDATORY<br>18-JAN-2003 | F1                         |
| 340141<br>34.030                 | PORT, RIGHT UNHEATED STATIC<br>4-883050<br>SN-UNKNOWN<br>REF: AMM 34-10-01   | MOS<br>HRSMSC<br>AFL | O/C      | 0                                       |              |          | 11-FEB-1982<br>0<br>0       |                          | F1                         |
| 340121<br>34.060<br>ASSOCIATED   | DRAIN PITOT/STATIC SYSTEM<br>PKG 1, 2, 3<br>REF: AMM 34-10-00                | MOS<br>HRSMSC<br>AFL | 200      |                                         |              |          | 26-JUN-2001<br>7687<br>5594 |                          | F2<br>1.5                  |
| + 340151<br>34.050<br>ASSOCIATED | LEAK CHECK RIGHT STATIC SYSTEM<br>REF: AMM 34-10-01                          | MOS<br>HRSMSC<br>AFL | 24       |                                         |              |          | 18-JAN-2001<br>7494<br>5466 | MANDATORY<br>18-JAN-2003 | F1                         |
| 340606<br>34.380                 | PROBE, OUTSIDE AIR TEMPERATURE<br>MS28038-1<br>9223<br>REF: NO REF           | MOS<br>HRSMSC<br>AFL | O/C      | 0                                       |              |          | 11-FEB-1982<br>0<br>0       |                          | F1                         |
| 347659<br>34.740                 | PROGRAMMER, RNS<br>622-5110-001<br>SN-UNKNOWN<br>REF: NO REF                 | MOS<br>HRSMSC<br>AFL | O/C      | 0<br>0                                  |              |          | 11-FEB-1982                 |                          |                            |
| 346601<br>34.130                 | RECEIVER, NO.1 ADF<br>622-2362-001<br>8945<br>REF: AMM 34-50-03/04           | MOS<br>HRSMSC<br>AFL | O/C      | 0                                       |              |          | 11-FEB-1982<br>0<br>0       |                          | F4<br>1                    |
| 346301<br>34.450                 | RECEIVER, NO.1 VHF NAVIGATION<br>622-0876-001<br>16803<br>REF: AMM 34-50-01  | MOS<br>HRSMSC<br>AFL | O/C      | 0<br>0                                  |              |          | 11-FEB-1982<br>0<br>0       |                          | F3                         |



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO | WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT    | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------|----------|------------------------------------------------------|---------|----------|-----------------------------------------------------|----------|-------------|-------------------------|----------------------------|
| 346536  |          | RECEIVER, NO.1 VOR                                   |         |          |                                                     |          |             |                         | F3                         |
| 34.580  |          | PN                                                   | MOS     |          |                                                     |          | 11-FEB-1982 |                         |                            |
|         |          | SN-UNKNOWN                                           | HRS/MSC | O/C      | 0                                                   |          | 0           |                         |                            |
|         |          | REF: NO REF                                          | AFL     |          |                                                     |          | 0           |                         |                            |
| 346626  |          | RECEIVER, NO.2 ADF                                   |         |          |                                                     |          |             |                         | F4                         |
| 34.130  |          | 622-2362-001                                         | MOS     |          |                                                     |          | 06-APR-1985 |                         |                            |
|         |          | 8946                                                 | HRS/MSC | O/C      | 0                                                   |          | 2317        |                         |                            |
|         |          | REF: AMM 34-50-03/04                                 | AFL     |          |                                                     |          | 1423        |                         |                            |
| 346311  |          | RECEIVER, NO.2 VHF NAVIGATION                        |         |          |                                                     |          |             |                         | F3                         |
| 34.450  |          | 622-0876-001                                         | MOS     |          |                                                     |          | 11-FEB-1982 |                         |                            |
|         |          | SN-UNKNOWN                                           | HRS/MSC | O/C      | 0                                                   |          | 0           |                         |                            |
|         |          | REF: AMM 34-50-01                                    | AFL     |          | 0                                                   |          | 0           |                         |                            |
| 346566  |          | RECEIVER, NO.2 VOR                                   |         |          |                                                     |          |             |                         | F3                         |
| 34.600  |          | PN                                                   | MOS     |          |                                                     |          | 11-FEB-1982 |                         |                            |
|         |          | SN-UNKNOWN                                           | HRS/MSC | O/C      | 0                                                   |          | 0           |                         |                            |
|         |          | REF: NO REF                                          | AFL     |          |                                                     |          | 0           |                         |                            |
| 345608  |          | RECEIVER, RADIO ALTIMETER                            |         |          |                                                     |          |             |                         | F3                         |
| 34.420  |          | 622-3201-001                                         | MOS     |          |                                                     |          | 11-FEB-1982 |                         |                            |
|         |          | SN-UNKNOWN                                           | HRS/MSC | O/C      | 0                                                   |          | 0           |                         |                            |
|         |          | REF: NO REF                                          | AFL     |          | 0                                                   |          | 0           |                         |                            |
| 346201  |          | RECEIVER/TRANSMITTER, MARKER BEACON                  |         |          |                                                     |          |             |                         | F3                         |
| 34.540  |          | PN                                                   | MOS     |          |                                                     |          | 11-FEB-1982 |                         |                            |
|         |          | SN-UNKNOWN                                           | HRS/MSC | O/C      | 0                                                   |          | 0           |                         |                            |
|         |          | REF: NO REF                                          | AFL     |          | 0                                                   |          | 0           |                         |                            |
| 345601  |          | RECEIVER/TRANSMITTER, RADIO ALTIMETER                |         |          |                                                     |          |             |                         | F2                         |
| 34.240  |          | 622-3201-001                                         | MOS     |          |                                                     |          | 11-FEB-1982 |                         |                            |
|         |          | 3652                                                 | HRS/MSC | O/C      | 0                                                   |          | 0           |                         |                            |
|         |          | REF: AMM 34-10-04                                    | AFL     |          |                                                     |          | 0           |                         |                            |
| 345821  |          | RECEIVER/TRANSMITTER, WEATHER RADAR                  |         |          |                                                     |          |             |                         | F3                         |
| 34.510  |          | 622-4022-001                                         | MOS     |          |                                                     |          | 12-APR-1995 |                         |                            |
|         |          | 2126                                                 | HRS/MSC | O/C      |                                                     |          | 5613        |                         |                            |
|         |          | REF: AMM 34-40-01,-02,-03,-04                        | AFL     |          |                                                     |          | 4281        |                         |                            |
| 344161  |          | SELECTOR, MODE COPILOT                               |         |          |                                                     |          |             |                         | F3                         |
| 34.210  |          | 614E-23R                                             | MOS     |          |                                                     |          | 11-FEB-1982 |                         |                            |
|         |          | SN-UNKNOWN                                           | HRS/MSC | O/C      | 0                                                   |          | 0           |                         |                            |
|         |          | REF: AMM 34-20-03                                    | AFL     |          |                                                     |          | 0           |                         |                            |
| 343661  |          | SELECTOR, MODE PILOT                                 |         |          |                                                     |          |             |                         | F3                         |
| 34.210  |          | 614E-20R                                             | MOS     |          |                                                     |          | 11-FEB-1982 |                         |                            |
|         |          | SN-UNKNOWN                                           | HRS/MSC | O/C      | 0                                                   |          | 0           |                         | 1                          |
|         |          | REF: AMM 34-20-03                                    | AFL     |          |                                                     |          | 0           |                         |                            |
| 343677  |          | SELECTOR, NO.1 REMOTE                                |         |          |                                                     |          |             |                         | F3                         |
| 34.490  |          | 622-4178-003                                         | MOS     |          |                                                     |          | 11-FEB-1982 |                         |                            |
|         |          | SN-UNKNOWN                                           | HRS/MSC | O/C      | 0                                                   |          | 0           |                         |                            |
|         |          | REF: NO REF                                          | AFL     |          | 0                                                   |          | 0           |                         |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|--------|----------|-----------------------------------------------------|----------|------------|-------------------------|----------------------------|
| 344177              | SELECTOR, NO.2 REMOTE                                |        |          |                                                     |          |            |                         |                            |
| 34.490              | 622-4178-003                                         | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | SN-UNKNOWN                                           | HRSMSC | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: NO REF                                          | AFL    |          | 0                                                   |          | 0          |                         |                            |
| 344121              | SENSOR, RATE-OF-TURN COPILOT                         |        |          |                                                     |          |            |                         | F3                         |
| 34.180              | 622-0181-001                                         | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | SN-UNKNOWN                                           | HRSMSC | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 22-11-05(1124A), 34-20-06(1124)             | AFL    |          |                                                     |          | 0          |                         |                            |
| 343621              | SENSOR, RATE-OF-TURN PILOT                           |        |          |                                                     |          |            |                         | F3                         |
| 34.180              | 772-5140-001                                         | MOS    |          |                                                     |          |            | 05-OCT-1983             |                            |
|                     | 3984                                                 | HRSMSC | O/C      | 0                                                   |          | 1300       |                         |                            |
|                     | REF: AMM 22-11-05(1124A), 34-20-06(1124)             | AFL    |          |                                                     |          | 794        |                         |                            |
| 346101              | TRANSPONDER, NO.1 ATC                                |        |          |                                                     |          |            |                         | F3                         |
| 34.320              | 622-1270-001                                         | MOS    |          |                                                     |          | 06/11/1996 | 11-DEC-1995             |                            |
|                     | 9608                                                 | HRSMSC | O/C      |                                                     |          | 5726       |                         | 1                          |
|                     | REF: AMM 34-50-06                                    | AFL    |          |                                                     |          | 4410       |                         |                            |
| 346106              | BENCH CHECK                                          |        |          |                                                     |          |            |                         | F3                         |
| 34.320              |                                                      | MOS    |          |                                                     |          |            | 25-SEP-1991             |                            |
|                     |                                                      | HRSMSC | O/C      |                                                     |          |            |                         |                            |
|                     | REF: See Workcard                                    | AFL    |          |                                                     |          |            |                         |                            |
| + 346111            | TEST FAR 91.413                                      |        |          |                                                     |          |            | MANDATORY               | F3                         |
| 34.320              |                                                      | MOS    | 24       |                                                     |          |            | 18-JAN-2001             | 18-JAN-2003                |
|                     |                                                      | HRSMSC |          |                                                     |          | 7494       |                         |                            |
|                     | REF: CMM FAR 91.413                                  | AFL    |          |                                                     |          | 5466       |                         |                            |
| 346116              | TRANSPONDER, NO.2 ATC                                |        |          |                                                     |          |            |                         | F3                         |
| 34.320              | 622-1270-001                                         | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | 13112                                                | HRSMSC | O/C      | 0                                                   |          | 0          |                         | 3                          |
|                     | REF: AMM 34-50-06                                    | AFL    |          |                                                     |          | 0          |                         |                            |
| 346121              | BENCH CHECK                                          |        |          |                                                     |          |            |                         | F3                         |
| 34.320              |                                                      | MOS    |          |                                                     |          |            | 25-SEP-1991             |                            |
|                     |                                                      | HRSMSC | O/C      |                                                     |          |            |                         | 4                          |
|                     | REF: CMM VENDOR MM                                   | AFL    |          |                                                     |          |            |                         |                            |
| + 346126            | TEST FAR 91.413                                      |        |          |                                                     |          |            | MANDATORY               | F3                         |
| 34.320              |                                                      | MOS    | 24       |                                                     |          |            | 18-JAN-2001             | 18-JAN-2003                |
|                     |                                                      | HRSMSC |          |                                                     |          | 7494       |                         |                            |
|                     | REF: CMM FAR 91.413                                  | AFL    |          |                                                     |          | 5466       |                         |                            |
| 340101              | TUBE, LEFT PITOT                                     |        |          |                                                     |          |            |                         | F1                         |
| 34.010              | 4883049-1                                            | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | 59912                                                | HRSMSC | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 34-10-01                                    | AFL    |          |                                                     |          | 0          |                         |                            |
| 340121              | DRAIN PITOT/STATIC SYSTEM                            |        |          |                                                     |          |            |                         | F2                         |
| 34.060              | PKG 1, 2, 3                                          | MOS    |          |                                                     |          |            | 26-JUN-2001             |                            |
| ASSOCIATED          |                                                      | HRSMSC | 200      |                                                     |          | 7687       |                         | 1.5                        |
|                     | REF: AMM 34-10-00                                    | AFL    |          |                                                     |          | 5594       |                         |                            |



**Aircraft Model - 1124 WESTWIND**
**Report Date 11-APR-2002**
**Owner Name - R&S AIRCRAFT INVESTMENTS, LLC**
**A/C Serial #: 368 A/C Reg. #: N368MD**

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|--------|----------|-----------------------------------------------------|----------|------------|-------------------------|----------------------------|
| 340111              | LEAK CHECK LEFT PITOT SYSTEM                         |        |          |                                                     |          |            |                         | F1                         |
| 34.040              |                                                      | MOS    |          |                                                     |          |            | 26-MAR-1996             |                            |
| ASSOCIATED          |                                                      | HRSMSC | O/C      |                                                     |          |            |                         |                            |
|                     | REF: AMM 34-10-01                                    | AFL    |          |                                                     |          |            |                         |                            |
| 340106              | TUBE, RIGHT PITOT                                    |        |          |                                                     |          |            |                         | F1                         |
| 34.010              | 4883049-1                                            | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | 58348                                                | HRSMSC | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 34-10-01                                    | AFL    |          |                                                     |          | 0          |                         |                            |
| 340121              | DRAIN PITOT/STATIC SYSTEM                            |        |          |                                                     |          |            |                         | F2                         |
| 34.060              | PKG 1, 2, 3                                          | MOS    |          |                                                     |          |            | 26-JUN-2001             |                            |
| ASSOCIATED          |                                                      | HRSMSC | 200      |                                                     |          | 7687       |                         | 1.5                        |
|                     | REF: AMM 34-10-00                                    | AFL    |          |                                                     |          | 5594       |                         |                            |
| 340116              | LEAK CHECK RIGHT PITOT SYSTEM                        |        |          |                                                     |          |            |                         | F1                         |
| 34.040              |                                                      | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
| ASSOCIATED          |                                                      | HRSMSC | O/C      |                                                     |          | 0          |                         |                            |
|                     | REF: AMM 34-10-01                                    | AFL    |          |                                                     |          | 0          |                         |                            |
| 346648              | UNIT, CONTROL DISPLAY PROCESS                        |        |          |                                                     |          |            |                         | F3                         |
| 34.460              | 622-2899-016                                         | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | SN-UNKNOWN                                           | HRSMSC | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: NO REF                                          | AFL    |          | 0                                                   |          | 0          |                         |                            |
| 348165              | UNIT, FMS AUXILIARY EQUIPMENT                        |        |          |                                                     |          |            |                         | F3                         |
| 34.770              | 622-5615-001/AEU-90                                  | MOS    |          |                                                     |          | 10/27/1989 | 27-JUL-1989             |                            |
|                     | 92                                                   | HRSMSC | O/C      |                                                     |          | 4311       |                         |                            |
|                     | REF: AMM 34-60-03                                    | AFL    |          |                                                     |          | 2856       |                         |                            |
| 348160              | UNIT, FMS COMPUTER RECEIVER                          |        |          |                                                     |          |            |                         | F3                         |
| 34.760              | 622-5614-020/CRU-90                                  | MOS    |          |                                                     |          |            | 12-FEB-1990             |                            |
|                     | 52                                                   | HRSMSC | O/C      |                                                     |          | 4504       |                         |                            |
|                     | REF: AMM 34-60-03                                    | AFL    |          |                                                     |          | 3073       |                         |                            |
| 348170              | UNIT, FMS CONTROL DISPLAY                            |        |          |                                                     |          |            |                         | F3                         |
| 34.790              | 622-5611-001/CDU-90                                  | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | 040                                                  | HRSMSC | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 34-60-03                                    | AFL    |          |                                                     |          | 0          |                         |                            |
| 348175              | UNIT, FMS DATA ENTRY                                 |        |          |                                                     |          |            |                         | F3                         |
| 34.780              | 622-5613-001/DEU-90                                  | MOS    |          |                                                     |          |            | 16-AUG-1984             |                            |
|                     | 183                                                  | HRSMSC | O/C      | 0                                                   |          | 1890       |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                                                     |          |            |                         |                            |
| 348155              | UNIT, FMS RADIO TUNING                               |        |          |                                                     |          |            |                         | F3                         |
| 34.750              | 622-5612-007/RTU-90                                  | MOS    |          |                                                     |          |            | 10-MAR-1987             |                            |
|                     | 50                                                   | HRSMSC | O/C      | 0                                                   |          | 3623       |                         |                            |
|                     | REF: AMM 34-60-03                                    | AFL    |          |                                                     |          | 2255       |                         |                            |
| 348136              | UNIT, NO. 1 LRN EQUIPMENT                            |        |          |                                                     |          |            |                         |                            |
| 34.690              | 622-5494-001                                         | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | SN-UNKNOWN                                           | HRSMSC | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 34-60-04                                    | AFL    |          | 0                                                   |          | 0          |                         |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|--------|----------|-----------------------------------------------------|----------|-------------|-------------------------|----------------------------|
| 348126              | UNIT, NO.1 LRN RECEIVER COMP                         |        |          |                                                     |          |             |                         |                            |
| 34.680              | 622-5492-001                                         | MOS    |          |                                                     |          |             | 11-FEB-1982             |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                                                   |          | 0           |                         |                            |
|                     | REF: AMM 34-60-04                                    | AFL    |          | 0                                                   |          | 0           |                         |                            |
| 348141              | UNIT, NO.2 LRN EQUIPMENT                             |        |          |                                                     |          |             |                         |                            |
| 34.690              | 622-5494-001                                         | MOS    |          |                                                     |          |             | 11-FEB-1982             |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                                                   |          | 0           |                         |                            |
|                     | REF: AMM 34-60-04                                    | AFL    |          | 0                                                   |          | 0           |                         |                            |
| 348131              | UNIT, NO.2 LRN RECEIVER COMP                         |        |          |                                                     |          |             |                         |                            |
| 34.720              | 622-5494-001                                         | MOS    |          |                                                     |          |             | 11-FEB-1982             |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                                                   |          | 0           |                         |                            |
|                     | REF: AMM 34-60-04                                    | AFL    |          | 0                                                   |          | 0           |                         |                            |
| 346651              | UNIT, VLF CONTROL DISPLAY                            |        |          |                                                     |          |             |                         | F3                         |
| 34.610              | 10060-6                                              | MOS    |          |                                                     |          |             | 24-SEP-1987             |                            |
|                     | 2579                                                 | HRS/MS | O/C      | 0                                                   |          | 3737        |                         |                            |
|                     | REF: AMM 34-10-06                                    | AFL    |          |                                                     |          | 2345        |                         |                            |
| 346671              | UNIT, VLF OPTIONAL EQUIPMENT                         |        |          |                                                     |          |             |                         | F3                         |
| 34.630              | 10600-2-210                                          | MOS    |          |                                                     |          |             | 05-SEP-1989             |                            |
|                     | 2695                                                 | HRS/MS | O/C      |                                                     | 0        | 4355        |                         |                            |
|                     | REF: AMM 34-60-02                                    | AFL    |          |                                                     |          | 2904        |                         |                            |
| 346661              | UNIT, VLF RECEIVER COMPUTER                          |        |          |                                                     |          |             |                         | F5                         |
| 34.620              | 10050-4-4A-3140                                      | MOS    |          |                                                     |          |             | 05-SEP-1989             |                            |
|                     | 1937                                                 | HRS/MS | O/C      |                                                     | 0        | 4355        |                         |                            |
|                     | REF: AMM 34-60-02                                    | AFL    |          |                                                     |          | 2904        |                         |                            |
| 343111              | VALVE, NO.1 FLUX                                     |        |          |                                                     |          |             |                         | W1                         |
| 34.120              | 2594484                                              | MOS    |          |                                                     |          |             | 11-FEB-1982             |                            |
|                     | 81096488                                             | HRS/MS | O/C      | 0                                                   |          | 0           |                         |                            |
|                     | REF: AMM 34-20-01                                    | AFL    |          |                                                     |          | 0           |                         |                            |
| 343156              | VALVE, NO.2 FLUX                                     |        |          |                                                     |          |             |                         | W2                         |
| 34.120              | 2594484                                              | MOS    |          |                                                     |          |             | 11-FEB-1982             |                            |
|                     | 81096489                                             | HRS/MS | O/C      | 0                                                   |          | 0           |                         |                            |
|                     | REF: AMM 34-20-08                                    | AFL    |          |                                                     |          | 0           |                         |                            |
| <b>CHAPTER 35</b>   | <b>OXYGEN</b>                                        |        |          |                                                     |          |             |                         |                            |
| 350101              | CYLINDER, OXYGEN                                     |        |          |                                                     |          |             | LIFE LIMIT              | F2                         |
| 35.010              | 6350A25-EE-Z                                         | MOS    | 288      | 0                                                   |          | 04-FEB-1982 | 04-FEB-2006             |                            |
|                     | 49928W                                               | HRS/MS |          |                                                     |          |             |                         |                            |
|                     | REF: AMM 35-00-00                                    | AFL    |          |                                                     |          |             |                         |                            |
| 350106              | HYDROSTATIC TEST                                     |        |          |                                                     |          |             |                         | F2                         |
| 35.010              |                                                      | MOS    | 36       |                                                     |          | 26-JUL-2000 | 26-JUL-2003             |                            |
|                     |                                                      | HRS/MS | 3000     |                                                     |          | 7325        | 10325                   |                            |
|                     | REF: AMM 35-00-00                                    | AFL    |          |                                                     |          | 5360        |                         |                            |
| 350141              | GAUGE, OXYGEN PRESSURE                               |        |          |                                                     |          |             |                         | F3                         |
| 35.040              | PN                                                   | MOS    |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                                                   |          | 0           |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                                                     |          | 0           |                         |                            |



Aircraft Model - 1124 WESTWIND

Report Date **11-APR-2002**

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION |     |     |     |     | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|--------|----------|------------------------------|-----|-----|-----|-----|----------|-------------|-------------------------|----------------------------|
|                     |                                                      |        |          | TSN                          | TSO | TSR | TSI | ADJ |          |             |                         |                            |
| 350126              | INDICATOR, OXYGEN DISCHARGE                          |        |          |                              |     |     |     |     |          |             |                         | F1                         |
| 35.040              | 118082                                               | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 350181              | MASK, PASSENGER OXYGEN L1                            |        |          |                              |     |     |     |     |          |             |                         | F4                         |
| 35.080              | PN                                                   | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 350191              | MASK, PASSENGER OXYGEN L2                            |        |          |                              |     |     |     |     |          |             |                         | F4                         |
| 35.080              | PN                                                   | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 350201              | MASK, PASSENGER OXYGEN R1                            |        |          |                              |     |     |     |     |          |             |                         | F4                         |
| 35.090              | PN                                                   | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 350211              | MASK, PASSENGER OXYGEN R2                            |        |          |                              |     |     |     |     |          |             |                         | F4                         |
| 35.090              | PN                                                   | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 350221              | MASK, PASSENGER OXYGEN R3                            |        |          |                              |     |     |     |     |          |             |                         | F4                         |
| 35.090              | PN                                                   | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 350246              | OUTLET, THERAPEUTIC OXYGEN                           |        |          |                              |     |     |     |     |          |             |                         | F4                         |
| 35.120              | 23599-11                                             | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 350158              | REGULATOR, MASK COPILOT                              |        |          |                              |     |     |     |     |          |             | OVERHAUL                | F3                         |
| 35.120              | MC-1013-02                                           | MOS    | 72       | 0                            |     |     |     |     |          | 09-NOV-1996 | 09-NOV-2002             |                            |
|                     | 8161                                                 | HRS/MS |          |                              |     |     |     |     |          | 5951        |                         |                            |
|                     | REF: NO REF                                          | AFL    |          |                              |     |     |     |     |          | 4589        |                         |                            |
| + 350169U           | CHECK                                                |        |          |                              |     |     |     |     |          |             |                         | F3                         |
| 35.070              |                                                      | MOS    | 12       |                              |     |     |     |     |          | 26-JUN-2001 | 26-JUN-2002             |                            |
|                     |                                                      | HRS/MS | 600      |                              |     |     |     |     |          | 7687        | 8287                    |                            |
|                     | REF: AMM 35-00-00                                    | AFL    |          |                              |     |     |     |     |          | 5594        |                         |                            |
| 350148              | REGULATOR, MASK PILOT                                |        |          |                              |     |     |     |     |          |             | OVERHAUL                | F3                         |
| 35.120              | MC-1013-02                                           | MOS    | 72       | 0                            |     |     |     |     |          | 09-NOV-1996 | 09-NOV-2002             |                            |
|                     | 7750                                                 | HRS/MS |          | 0                            |     |     |     |     |          | 5951        |                         |                            |
|                     | REF: NO REF                                          | AFL    |          | 0                            |     |     |     |     |          | 4589        |                         |                            |
| + 350166U           | CHECK                                                |        |          |                              |     |     |     |     |          |             |                         | F3                         |
| 35.070              |                                                      | MOS    | 12       |                              |     |     |     |     |          | 26-JUN-2001 | 26-JUN-2002             |                            |
|                     |                                                      | HRS/MS | 600      |                              |     |     |     |     |          | 7687        | 8287                    |                            |
|                     | REF: AMM 35-00-00                                    | AFL    |          |                              |     |     |     |     |          | 5594        |                         |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER     | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|----------------------------------------------------------|--------|----------|-----------------------------------------------------|----------|------------|-------------------------|----------------------------|
| 350241              | REGULATOR, OXYGEN DEMAND CONTROL PANEL (PURITAN) COPILOT |        |          |                                                     |          |            |                         | F3                         |
| 35.110              | 101202-11                                                | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | SN-UNKNOWN                                               | HRSMSC | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 35-10-00                                        | AFL    |          |                                                     |          | 0          |                         |                            |
| 350236              | REGULATOR, OXYGEN DEMAND CONTROL PANEL (PURITAN) PILOT   |        |          |                                                     |          |            |                         | F3                         |
| 35.110              | 101202-11                                                | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | SN-UNKNOWN                                               | HRSMSC | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 35-10-00                                        | AFL    |          |                                                     |          | 0          |                         |                            |
| 350116              | REGULATOR, PRESSURE REDUCER                              |        |          |                                                     |          |            |                         | F3                         |
| 35.030              | 112031-06                                                | MOS    |          |                                                     |          |            | 11-FEB-1982             | \$970.                     |
|                     | 670A                                                     | HRSMSC | O/C      | 0                                                   |          | 0          |                         | 8                          |
|                     | REF: AMM 35-00-00                                        | AFL    |          |                                                     |          | 0          |                         |                            |
| 350136              | SWITCH, ALTITUDE PRESSURE                                |        |          |                                                     |          |            |                         | F3                         |
| 35.060              | 101800                                                   | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | 8024154                                                  | HRSMSC | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 35-00-00                                        | AFL    |          |                                                     |          | 0          |                         |                            |
| 350231              | SYSTEM, PASSENGER OXYGEN SUPPLY                          |        |          |                                                     |          |            |                         | F3                         |
| 35.100              | 5753004-400                                              | MOS    |          |                                                     |          |            | 11-FEB-1982             | \$950.                     |
|                     | 189                                                      | HRSMSC | O/C      | 0                                                   |          | 0          |                         | 6                          |
|                     | REF: AMM 35-20-00                                        | AFL    |          |                                                     |          | 0          |                         |                            |
| 350163              | INSPECT/SERVICE OXYGEN SYSTEM                            |        |          |                                                     |          |            |                         | F3                         |
| 35.140              |                                                          | MOS    |          |                                                     |          |            | 13-NOV-1995             |                            |
|                     | 189                                                      | HRSMSC | O/C      |                                                     |          | 5718       |                         |                            |
|                     | REF: AMM 35-00-00                                        | AFL    |          |                                                     |          | 4397       |                         |                            |
| + 350243            | TEST                                                     |        |          |                                                     |          |            |                         | F4                         |
| 35.130              | PKG 3                                                    | MOS    |          |                                                     |          |            | 26-JUL-2000             |                            |
|                     |                                                          | HRSMSC | 800      |                                                     |          | 7325       |                         |                            |
|                     | REF: AMM 35-00-00                                        | AFL    |          |                                                     |          | 5360       |                         |                            |
| 350103              | VALVE, OXYGEN CYLINDER                                   |        |          |                                                     |          |            |                         | F2                         |
| 35.150              | 6350-A25-DDC                                             | MOS    |          |                                                     |          |            | 11-DEC-1984             |                            |
|                     | SN-UNKNOWN                                               | HRSMSC | O/C      |                                                     |          | 2119       |                         |                            |
|                     | REF: NO REF                                              | AFL    |          |                                                     |          | 1302       |                         |                            |
| 350111              | VALVE, OXYGEN FILLER                                     |        |          |                                                     |          |            |                         | F1                         |
| 35.020              | 26875-48                                                 | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | SN-UNKNOWN                                               | HRSMSC | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 35-00-00                                        | AFL    |          |                                                     |          | 0          |                         |                            |
| 350131              | VALVE, OXYGEN SHUTOFF                                    |        |          |                                                     |          |            |                         | F2                         |
| 35.050              | 110115                                                   | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | SN-UNKNOWN                                               | HRSMSC | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: AMM 35-00-00                                        | AFL    |          |                                                     |          | 0          |                         |                            |
| 350108              | VALVE, TOGGLE                                            |        |          |                                                     |          |            |                         | F2                         |
| 35.150              | 170001                                                   | MOS    |          |                                                     |          |            | 11-FEB-1982             |                            |
|                     | 8894                                                     | HRSMSC | O/C      | 0                                                   |          | 0          |                         |                            |
|                     | REF: NO REF                                              | AFL    |          |                                                     |          | 0          |                         |                            |
| CHAPTER 49          | AIRBORNE AUXILIARY POWER                                 |        |          |                                                     |          |            |                         |                            |



**Aircraft Model - 1124 WESTWIND**
**Report Date 11-APR-2002**
**Owner Name - R&S AIRCRAFT INVESTMENTS, LLC**
**A/C Serial #: 368 A/C Reg. #: N368MD**

| ITEM NO                 | WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER                              | UNIT                 | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE                  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|-------------------------|----------|-----------------------------------------------------------------------------------|----------------------|----------|-----------------------------------------------------|----------|-----------------------------|-------------------------|----------------------------|
| 49                      | APU1     | APU,<br>PN<br>SN-UNKNOWN<br>REF:                                                  | MOS<br>HRS/MS<br>AFL | E/C      |                                                     |          |                             |                         |                            |
| <b>CHAPTER 52 DOORS</b> |          |                                                                                   |                      |          |                                                     |          |                             |                         |                            |
| 520181                  | 52.020   | LUBRICATE CABIN ENTRANCE STEP                                                     | MOS<br>HRS/MS<br>AFL | O/C      |                                                     |          | 11-FEB-1982<br>0<br>0       |                         | F4                         |
|                         |          | REF: AMM 12-20-00                                                                 |                      |          |                                                     |          |                             |                         |                            |
| 520161                  | 52.040   | DOOR, COMPARTMENT<br>CMA21212-002<br>SN-UNKNOWN<br>REF: AMM 52-30-00              | MOS<br>HRS/MS<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | F5                         |
| 520171                  | 52.050   | DOOR, COMPARTMENT REAR BAGGAGE<br>CMA22211-001<br>SN-UNKNOWN<br>REF: AMM 52-30-01 | MOS<br>HRS/MS<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | F5                         |
| 520101                  | 52.010   | DOOR, ENTRANCE CABIN<br>333045-505<br>SN-UNKNOWN<br>REF:                          | MOS<br>HRS/MS<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | F4                         |
| +                       | 520106   | INSPECT/LUBRICATE<br>PKG 1, 2, 3                                                  | MOS<br>HRS/MS<br>AFL | 200      |                                                     |          | 26-JUN-2001<br>7687<br>5594 |                         | F4                         |
|                         |          | REF: AMM 52-10-00/12-20-00                                                        |                      |          |                                                     |          |                             |                         |                            |
| +                       | 520116   | OPERATIONAL CHECK<br>PKG 1, 2, 3                                                  | MOS<br>HRS/MS<br>AFL | 200      |                                                     |          | 26-JUN-2001<br>7687<br>5594 |                         | F4                         |
|                         |          | REF: AMM 52-10-00                                                                 |                      |          |                                                     |          |                             |                         |                            |
| 520136                  | 52.030   | HATCH, EMERGENCY EXIT LEFT<br>5-333031-501<br>SN-UNKNOWN<br>REF: AMM 52-20-00     | MOS<br>HRS/MS<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | F4                         |
| +                       | 520141   | INSPECT/LUBRICATE SEAL<br>PKG 3                                                   | MOS<br>HRS/MS<br>AFL | 800      |                                                     |          | 26-JUL-2000<br>7325<br>5360 |                         | F4                         |
|                         |          | REF: See Workcard                                                                 |                      |          |                                                     |          |                             |                         |                            |
| 520146                  | 52.030   | HATCH, EMERGENCY EXIT RIGHT<br>5-333031-501<br>SN-UNKNOWN<br>REF: AMM 52-20-00    | MOS<br>HRS/MS<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | F4                         |
| +                       | 520151   | INSPECT/LUBRICATE SEAL<br>PKG 3                                                   | MOS<br>HRS/MS<br>AFL | 800      |                                                     |          | 26-JUL-2000<br>7325<br>5360 |                         | F4                         |
|                         |          | REF: See Workcard                                                                 |                      |          |                                                     |          |                             |                         |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD        | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER                                  | UNIT                 | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE                  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|----------------------------|---------------------------------------------------------------------------------------|----------------------|----------|-----------------------------------------------------|----------|-----------------------------|-------------------------|----------------------------|
| 520166<br>52.060           | SEAL, COMPARTMENT DOOR<br>CMA21212-057<br>SN-UNKNOWN<br>REF: NO REF                   | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | F5                         |
| 520173<br>52.060           | SEAL, COMPARTMENT DOOR REAR BAGGAGE<br>CMA22211-006<br>SN-UNKNOWN<br>REF: NO REF      | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | F5                         |
| 520126<br>52.010           | SEAL, ENTRANCE DOOR CABIN<br>333045-181<br>SN-UNKNOWN<br>REF: AMM 52-10-00            | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 01-DEC-1995<br>5727<br>4410 |                         | F4                         |
| 520176<br>52.020           | STEP, ENTRANCE CABIN<br>5-123580-1<br>SN-UNKNOWN<br>REF: AMM 52-60-00                 | MOS<br>HRSMSC<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | F4                         |
| <b>CHAPTER 53 FUSELAGE</b> |                                                                                       |                      |          |                                                     |          |                             |                         |                            |
| + 530121<br>53.0202        | INSPECT NOSE COMPARTMENT (B)<br>PKG 2, 3<br>REF: AMM 5-20-01,-05                      | MOS<br>HRSMSC<br>AFL | 400      |                                                     |          | 26-JUN-2001<br>7687<br>5594 |                         | F2                         |
| + 530300<br>53.170         | INSPECT AFT FUSELAGE STRUCTURE<br>REF: AMM 5-40-02                                    | MOS<br>HRSMSC<br>AFL | 4800     |                                                     |          | 24-AUG-1993<br>5326<br>3975 | MANDATORY               | F5                         |
| + 530235<br>53.120         | INSPECT AFT PRESSURE BULKHEAD AFT WEBS<br>REF: AMM 5-40-01                            | MOS<br>HRSMSC<br>AFL | 15000    |                                                     |          |                             | MANDATORY               | F5                         |
| + 530230<br>53.110         | INSPECT AFT PRESSURE BULKHEAD FORWARD WEBS.<br>REF: AMM 5-40-01                       | MOS<br>HRSMSC<br>AFL | 9600     |                                                     |          |                             | MANDATORY               | F5                         |
| + 530250<br>53.150         | INSPECT AFT PRESSURE BULKHEAD J-BEAM SPLICE FROM CABIN SIDE<br>REF: AMM 5-40-01       | MOS<br>HRSMSC<br>AFL | 9600     |                                                     |          |                             | MANDATORY               | F5                         |
| + 530255<br>53.160         | INSPECT AFT PRESSURE BULKHEAD J-BEAM SPLICE FROM FUEL COMPARTMENT<br>REF: AMM 5-40-01 | MOS<br>HRSMSC<br>AFL | 15000    |                                                     |          |                             | MANDATORY               | F5                         |
| + 530240<br>53.130         | INSPECT AFT PRESSURE BULKHEAD PERIPHERAL SECTION FROM CABIN SIDE<br>REF: AMM 5-40-01  | MOS<br>HRSMSC<br>AFL | 9600     |                                                     |          |                             | MANDATORY               | F5                         |



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEMNO   | WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER                   | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|----------|----------|------------------------------------------------------------------------|--------|----------|-----------------------------------------------------|----------|-------------|-------------------------|----------------------------|
| + 530245 | 53.140   | INSPECT AFT PRESSURE BULKHEAD PERIPHERAL SECTION FROM FUEL COMPARTMENT | MOS    |          |                                                     |          |             | MANDATORY               | F5                         |
|          |          | REF: AMM 5-40-01                                                       | HRS/MS | 15000    |                                                     |          |             | 15000                   |                            |
|          |          | AFL                                                                    |        |          |                                                     |          |             |                         |                            |
| + 530176 | 53.060   | INSPECT AUXILIARY FUEL TANK STRUCTURE                                  | MOS    |          |                                                     |          | 26-JUL-2000 |                         | F5                         |
|          |          | PKG 3                                                                  | HRS/MS | 800      |                                                     |          | 7325        |                         |                            |
|          |          | REF: AMM 5-20-09                                                       | AFL    |          |                                                     |          | 5360        |                         |                            |
| + 530146 | 53.0401  | INSPECT CABIN (A)                                                      | MOS    |          |                                                     |          | 26-JUN-2001 |                         | F4                         |
|          |          | PKG 1, 2, 3                                                            | HRS/MS | 200      |                                                     |          | 7687        |                         |                            |
|          |          | REF: AMM 5-20-02                                                       | AFL    |          |                                                     |          | 5594        |                         |                            |
| + 530156 | 53.0402  | INSPECT CABIN (C)                                                      | MOS    |          |                                                     |          | 26-JUL-2000 |                         | F4                         |
|          |          | PKG 3                                                                  | HRS/MS | 800      |                                                     |          | 7325        |                         |                            |
|          |          | REF: AMM 5-20-02                                                       | AFL    |          |                                                     |          | 5360        |                         |                            |
| + 530131 | 53.0301  | INSPECT COCKPIT (A)                                                    | MOS    |          |                                                     |          | 26-JUN-2001 |                         | F3                         |
|          |          | PKG 1, 2, 3                                                            | HRS/MS | 200      |                                                     |          | 7687        |                         |                            |
|          |          | REF: AMM 5-20-02,-03                                                   | AFL    |          |                                                     |          | 5594        |                         |                            |
| + 530136 | 53.0302  | INSPECT COCKPIT (B)                                                    | MOS    |          |                                                     |          | 26-JUN-2001 |                         | F3                         |
|          |          | PKG 2, 3                                                               | HRS/MS | 400      |                                                     |          | 7687        |                         |                            |
|          |          | REF: AMM 5-20-02                                                       | AFL    |          |                                                     |          | 5594        |                         |                            |
| + 530141 | 53.0303  | INSPECT COCKPIT (C)                                                    | MOS    |          |                                                     |          | 26-JUL-2000 |                         | F3                         |
|          |          | PKG 3                                                                  | HRS/MS | 800      |                                                     |          | 7325        |                         |                            |
|          |          | REF: AMM 5-20-02                                                       | AFL    |          |                                                     |          | 5360        |                         |                            |
| + 530220 | 53.100   | INSPECT ENTRY DOOR STOPS                                               | MOS    |          |                                                     |          | 24-AUG-1993 | MANDATORY               | F4                         |
|          |          | REF: AMM 5-40-01                                                       | HRS/MS | 5400     |                                                     |          | 5326        | 10726                   |                            |
|          |          | AFL                                                                    |        |          |                                                     |          | 3975        |                         |                            |
| + 530205 | 53.180   | INSPECT FORWARD TO AFT MAIN FRAME                                      | MOS    |          |                                                     |          | 26-JUL-2000 |                         | F4                         |
|          |          | REF: AMM 5-40-01                                                       | HRS/MS | 800      |                                                     |          | 7325        | 8125                    |                            |
|          |          | AFL                                                                    |        |          |                                                     |          | 5360        |                         |                            |
| + 530200 | 53.080   | INSPECT FORWARD TO AFT PRESSURE BULKHEAD-FUSELAGE                      | MOS    |          |                                                     |          | 26-JUL-2000 | MANDATORY               | F4                         |
|          |          | REF: AMM 5-40-01                                                       | HRS/MS | 800      |                                                     |          | 7325        | 8125                    |                            |
|          |          | AFL                                                                    |        |          |                                                     |          | 5360        |                         |                            |
| + 530101 | 53.010   | INSPECT FUSELAGE (A)                                                   | MOS    |          |                                                     |          | 26-JUN-2001 |                         | F1                         |
|          |          | PKG 1, 2, 3                                                            | HRS/MS | 200      |                                                     |          | 7687        |                         |                            |
|          |          | REF: AMM 5-20-02                                                       | AFL    |          |                                                     |          | 5594        |                         |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD               | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER          | UNT                  | INTERVAL | TIME-----AT-----<br>TSN TSO TSR TSI ADJ | INSTALLATION | Warr Exp | COMPLIANCE            | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|-----------------------------------|---------------------------------------------------------------|----------------------|----------|-----------------------------------------|--------------|----------|-----------------------|-------------------------|----------------------------|
| + 530210<br>53.090                | INSPECT FUSELAGE SKINS FLIGHT COMPARTMENT SIDE WINDOW         | MOS                  |          |                                         |              |          | 24-AUG-1993           | MANDATORY               | F4                         |
|                                   | REF: AMM 5-40-01                                              | HRSMSC<br>AFL        | 4800     |                                         |              |          | 5326<br>3975          | 10126                   |                            |
| + 530116<br>53.0201               | INSPECT NOSE COMPARTMENT (A)<br>PKG 1, 2, 3                   | MOS                  |          |                                         |              |          | 26-JUN-2001           |                         | F2                         |
|                                   | REF: AMM 5-20-01,-05                                          | HRSMSC<br>AFL        | 200      |                                         |              |          | 7687<br>5594          |                         |                            |
| + 530161<br>53.0501               | INSPECT REAR COMPARTMENT (A)<br>PKG 1, 2, 3                   | MOS                  |          |                                         |              |          | 26-JUN-2001           |                         | F5                         |
|                                   | REF: AMM 5-20-05                                              | HRSMSC<br>AFL        | 200      |                                         |              |          | 7687<br>5594          |                         |                            |
| + 530166<br>53.0502               | INSPECT REAR COMPARTMENT (B)<br>PKG 2, 3                      | MOS                  |          |                                         |              |          | 26-JUN-2001           |                         | F5                         |
|                                   | REF: AMM 5-20-05                                              | HRSMSC<br>AFL        | 400      |                                         |              |          | 7687<br>5594          |                         |                            |
| 531101<br>53.070                  | CONE, NOSE<br>F10A-5-RD5-20000-7<br>SN-UNKNOWN<br>REF: NO REF | MOS<br>HRSMSC<br>AFL |          | O/C                                     | 0<br>0       |          | 11-FEB-1982<br>0<br>0 |                         | F2                         |
| <b>CHAPTER 54 NACELLES/PYLONS</b> |                                                               |                      |          |                                         |              |          |                       |                         |                            |
| + 540200<br>54.020                | INSPECT ENGINE SUPPORT INSTALLATION                           | MOS                  |          |                                         |              |          | 24-AUG-1993           | MANDATORY               |                            |
|                                   | REF: AMM 5-40-04                                              | HRSMSC<br>AFL        | 4800     |                                         |              |          | 5326<br>3975          | 10126                   |                            |
| + 540101U<br>54.0101              | INSPECT NO. 1 ENGINE NACELLE/PYLON (A)<br>PKG 1, 2, 3         | MOS                  |          |                                         |              |          | 26-JUN-2001           |                         | E1                         |
|                                   | REF: AMM 5-20-07,-08/12-02-00                                 | HRSMSC<br>AFL        | 200      |                                         |              |          | 7687<br>5594          |                         |                            |
| + 540106U<br>54.0102              | INSPECT NO. 1 ENGINE NACELLE/PYLON (B)<br>PKG 2, 3            | MOS                  |          |                                         |              |          | 26-JUN-2001           |                         | E1                         |
|                                   | REF: AMM 5-20-07,-08/12-02-00                                 | HRSMSC<br>AFL        | 400      |                                         |              |          | 7687<br>5594          |                         | 3                          |
| + 540111U<br>54.0103              | INSPECT NO. 1 ENGINE NACELLE/PYLON (C)<br>PKG 3               | MOS                  |          |                                         |              |          | 26-JUL-2000           |                         | E1                         |
|                                   | REF: AMM 5-20-07,-08/12-02-00                                 | HRSMSC<br>AFL        | 800      |                                         |              |          | 7325<br>5360          |                         |                            |
| + 540121U<br>54.0101              | INSPECT NO. 2 ENGINE NACELLE/PYLON (A)<br>PKG 1, 2, 3         | MOS                  |          |                                         |              |          | 26-JUN-2001           |                         | E2                         |
|                                   | REF: AMM 5-20-07,-08/12-02-00                                 | HRSMSC<br>AFL        | 200      |                                         |              |          | 7687<br>5594          |                         |                            |
| + 540126U<br>54.0102              | INSPECT NO. 2 ENGINE NACELLE/PYLON (B)<br>PKG 2, 3            | MOS                  |          |                                         |              |          | 26-JUN-2001           |                         | E2                         |
|                                   | REF: AMM 5-20-07,-08/12-02-00                                 | HRSMSC<br>AFL        | 400      |                                         |              |          | 7687<br>5594          |                         | 3                          |



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD            | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER                        | UNIT                 | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE                  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|--------------------------------|-----------------------------------------------------------------------------|----------------------|----------|-----------------------------------------------------|----------|-----------------------------|-------------------------|----------------------------|
| + 540131U<br>54.0103           | INSPECT NO. 2 ENGINE NACELLE/PYLON (C)<br>PKG 3                             | MOS<br>HRS/MS<br>AFL | 800      |                                                     |          | 26-JUL-2000<br>7325<br>5360 |                         | E2                         |
|                                | REF: AMM 5-20-07,-08/12-02-00                                               |                      |          |                                                     |          |                             |                         |                            |
| <b>CHAPTER 55 STABILIZERS</b>  |                                                                             |                      |          |                                                     |          |                             |                         |                            |
| + 550101<br>55.0101            | INSPECT EMPENNAGE (A)<br>PKG 1, 2, 3                                        | MOS<br>HRS/MS<br>AFL | 200      |                                                     |          | 26-JUN-2001<br>7687<br>5594 |                         | T1                         |
|                                | REF: AMM 5-20-06/12-20-00                                                   |                      |          |                                                     |          |                             |                         |                            |
| + 550106<br>55.0102            | INSPECT EMPENNAGE (B)<br>PKG 2, 3                                           | MOS<br>HRS/MS<br>AFL | 400      |                                                     |          | 26-JUN-2001<br>7687<br>5594 |                         | T1                         |
|                                | REF: AMM 5-20-05,-06/12-20-00                                               |                      |          |                                                     |          |                             |                         |                            |
| + 550200<br>55.060             | INSPECT EMPENNAGE (MAJOR)                                                   | MOS<br>HRS/MS<br>AFL | 4800     |                                                     |          | 24-AUG-1993<br>5326<br>3975 | MANDATORY<br>10126      | T1                         |
|                                | REF: AMM 5-40-03                                                            |                      |          |                                                     |          |                             |                         |                            |
| 550651<br>55.030               | STABILIZER, HORIZONTAL<br>5453015-4 13-1<br>SN-UNKNOWN<br>REF: AMM 55-10-00 | MOS<br>HRS/MS<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | T1                         |
| 550656<br>55.040               | CHECK AFT SPAR SPLICE-HINGE FITTING OUTBOARD LUGS FOR CRACKS<br>PKG 1, 2, 3 | MOS<br>HRS/MS<br>AFL | 200      |                                                     |          | 26-JUN-2001<br>7687<br>5594 |                         | T1                         |
|                                | REF: AMM 55-10-00                                                           |                      |          |                                                     |          |                             |                         |                            |
| 550658<br>55.050               | CHECK ASSEMBLY RADIAL/AXIAL PLAY<br>PKG 3                                   | MOS<br>HRS/MS<br>AFL | 800      |                                                     |          | 26-JUL-2000<br>7325<br>5360 |                         | T1                         |
|                                | REF: See Workcard                                                           |                      |          |                                                     |          |                             |                         |                            |
| 270214<br>27.195<br>ASSOCIATED | LUBRICATE AFT HINGE FITTING BEARINGS<br>PKG 1, 2, 3                         | MOS<br>HRS/MS<br>AFL | 200      |                                                     |          | 26-JUN-2001<br>7687<br>5594 |                         | T1                         |
|                                | REF: NO REF                                                                 |                      |          |                                                     |          |                             |                         |                            |
| 270215<br>27.195<br>ASSOCIATED | LUBRICATE FORWARD SCISSOR ASSEMBLY<br>PKG 1, 2, 3                           | MOS<br>HRS/MS<br>AFL | 200      |                                                     |          | 26-JUN-2001<br>7687<br>5594 |                         | T1                         |
|                                | REF: NO REF                                                                 |                      |          |                                                     |          |                             |                         |                            |
| SB 1124-55-097<br>ASSOCIATED   | STABILIZER SCISSR SERVICE BULLETIN                                          | MOS<br>HRS/MS<br>AFL | A/R      |                                                     |          | 0<br>0                      |                         | T1                         |
|                                | REF: See Workcard                                                           |                      |          |                                                     |          |                             |                         |                            |
| 550601<br>55.020               | STABILIZER, VERTICAL<br>5413027-4 11<br>SN-UNKNOWN<br>REF: See Workcard     | MOS<br>HRS/MS<br>AFL | O/C      | 0                                                   |          | 11-FEB-1982<br>0<br>0       |                         | T1                         |

**CHAPTER 56 WINDOWS**

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION |     |     |     |     | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|--------|----------|------------------------------|-----|-----|-----|-----|----------|-------------|-------------------------|----------------------------|
|                     |                                                      |        |          | TSN                          | TSO | TSR | TSI | ADJ |          |             |                         |                            |
| 561601              | WINDOW, EMERGENCY EXIT NO.L3 LEFT                    |        |          |                              |     |     |     |     |          |             |                         | F4                         |
| 56.075              | PN                                                   | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 56-20-00                                    | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 561606              | WINDOW, EMERGENCY EXIT NO.R4 RIGHT                   |        |          |                              |     |     |     |     |          |             |                         | F4                         |
| 56.075              | PN                                                   | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 56-20-00                                    | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 560601              | WINDOW, NO.L1 LEFT                                   |        |          |                              |     |     |     |     |          |             |                         | F4                         |
| 56.050              | 5-343016-501                                         | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 56-20-00                                    | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 560606              | WINDOW, NO.L2 LEFT                                   |        |          |                              |     |     |     |     |          |             |                         | F4                         |
| 56.060              | 5-343016-501                                         | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 56-20-00                                    | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 560611              | WINDOW, NO.L4 LEFT                                   |        |          |                              |     |     |     |     |          |             |                         | F4                         |
| 56.070              | 5-343016-501                                         | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 56-20-00                                    | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 560616              | WINDOW, NO.L5 LEFT                                   |        |          |                              |     |     |     |     |          |             |                         | F4                         |
| 56.080              | 5-343016-501                                         | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 56-20-00                                    | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 561101              | WINDOW, NO.R1 RIGHT                                  |        |          |                              |     |     |     |     |          |             |                         | F4                         |
| 56.050              | 5-343016-501                                         | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 56-20-00                                    | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 561106              | WINDOW, NO.R2 RIGHT                                  |        |          |                              |     |     |     |     |          |             |                         | F4                         |
| 56.060              | 5-343016-501                                         | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 56-20-00                                    | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 561111              | WINDOW, NO.R3 RIGHT                                  |        |          |                              |     |     |     |     |          |             |                         | F4                         |
| 56.070              | 5-343016-501                                         | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 56-20-00                                    | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 561116              | WINDOW, NO.R5 RIGHT                                  |        |          |                              |     |     |     |     |          |             |                         | F4                         |
| 56.080              | 5-343016-501                                         | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 56-20-00                                    | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 561121              | WINDOW, NO.R6 RIGHT                                  |        |          |                              |     |     |     |     |          |             |                         | F4                         |
| 56.080              | 5-343016-501                                         | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 56-20-00                                    | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |



**Aircraft Model - 1124 WESTWIND**
**Report Date 11-APR-2002**
**Owner Name - R&S AIRCRAFT INVESTMENTS, LLC**
**A/C Serial #: 368 A/C Reg. #: N368MD**

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT    | INTERVAL | TIME-----AT-----INSTALLATION |     |     |     |     | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|---------|----------|------------------------------|-----|-----|-----|-----|----------|-------------|-------------------------|----------------------------|
|                     |                                                      |         |          | TSN                          | TSO | TSR | TSI | ADJ |          |             |                         |                            |
| 560121              | WINDOW, OVERHEAD                                     |         |          |                              |     |     |     |     |          |             |                         | F3                         |
| 56.040              | 5-343021-1                                           | MOS     |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MSC | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 56-10-02                                    | AFL     |          | 0                            |     |     |     |     |          | 0           |                         |                            |
| 560126              | WINDOW, OVERHEAD                                     |         |          |                              |     |     |     |     |          |             |                         | F3                         |
| 56.040              | 5-343021-2                                           | MOS     |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MSC | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 56-10-02                                    | AFL     |          | 0                            |     |     |     |     |          | 0           |                         |                            |
| 560116              | WINDOW, SIDE COPILOT                                 |         |          |                              |     |     |     |     |          |             |                         | F3                         |
| 56.030              | 5-343003-501                                         | MOS     |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MSC | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 56-10-04                                    | AFL     |          | 0                            |     |     |     |     |          | 0           |                         |                            |
| + 560118            | INSPECT                                              |         |          |                              |     |     |     |     |          |             |                         | F3                         |
| 56.030              | PKG 3                                                | MOS     |          |                              |     |     |     |     |          | 26-JUL-2000 |                         |                            |
|                     |                                                      | HRS/MSC | 800      |                              |     |     |     |     |          | 7325        |                         |                            |
|                     | REF: See Workcard                                    | AFL     |          |                              |     |     |     |     |          | 5360        |                         |                            |
| 560111              | WINDOW, SIDE PILOT                                   |         |          |                              |     |     |     |     |          |             |                         | F3                         |
| 56.030              | 5-343017-505                                         | MOS     |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MSC | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 56-10-03                                    | AFL     |          | 0                            |     |     |     |     |          | 0           |                         |                            |
| + 560112            | INSPECT                                              |         |          |                              |     |     |     |     |          |             |                         | F3                         |
| 56.030              | PKG 3                                                | MOS     |          |                              |     |     |     |     |          | 26-JUL-2000 |                         |                            |
|                     |                                                      | HRS/MSC | 800      |                              |     |     |     |     |          | 7325        |                         |                            |
|                     | REF: AMM 56-10-03                                    | AFL     |          |                              |     |     |     |     |          | 5360        |                         |                            |
| 560107              | WINDSHIELD, INNER COPILOT                            |         |          |                              |     |     |     |     |          |             |                         | F3                         |
| 56.020              | 5343035                                              | MOS     |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MSC | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 56-10-01                                    | AFL     |          |                              |     |     |     |     |          | 0           |                         |                            |
| 560102              | WINDSHIELD, INNER PILOT                              |         |          |                              |     |     |     |     |          |             |                         | F3                         |
| 56.020              | 5343035                                              | MOS     |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MSC | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 56-10-01                                    | AFL     |          |                              |     |     |     |     |          | 0           |                         |                            |
| 560106              | WINDSHIELD, OUTER COPILOT                            |         |          |                              |     |     |     |     |          |             |                         | F3                         |
| 56.010              | PPG 343030-2                                         | MOS     |          |                              |     |     |     |     |          | 26-AUG-2000 |                         |                            |
|                     | 99064H0109                                           | HRS/MSC | O/C      | 0                            |     |     |     |     |          | 7352        |                         |                            |
|                     | REF: AMM 56-10-01                                    | AFL     |          | 0                            |     |     |     |     |          | 5381        |                         |                            |
| 560101              | WINDSHIELD, OUTER PILOT                              |         |          |                              |     |     |     |     |          |             |                         | F3                         |
| 56.010              | 343030-1                                             | MOS     |          |                              |     |     |     |     |          | 22-FEB-2000 |                         |                            |
|                     | 98342H0422                                           | HRS/MSC | O/C      | 0                            |     |     |     |     |          | 7107        |                         |                            |
|                     | REF: AMM 56-10-01                                    | AFL     |          | 0                            |     |     |     |     |          | 5232        |                         |                            |
| CHAPTER 57          |                                                      | WINGS   |          |                              |     |     |     |     |          |             |                         |                            |
| + 570220            | INSPECT LEFT OUTER WING PANELS                       |         |          |                              |     |     |     |     |          |             | MANDATORY               | W1                         |
| 57.050              |                                                      | MOS     |          |                              |     |     |     |     |          | 24-AUG-1993 |                         |                            |
|                     |                                                      | HRS/MSC | 4800     |                              |     |     |     |     |          | 5326        | 10126                   |                            |
|                     | REF: AMM 5-40-05                                     | AFL     |          |                              |     |     |     |     |          | 3975        |                         |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----<br>TSN TSO TSR TSI ADJ | INSTALLATION | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|--------|----------|-----------------------------------------|--------------|----------|-------------|-------------------------|----------------------------|
| + 570101            | INSPECT LEFT WING (A)                                |        |          |                                         |              |          |             |                         | W1                         |
| 57.0101             | PKG 1, 2, 3                                          | MOS    |          |                                         |              |          | 26-JUN-2001 |                         |                            |
|                     | REF: AMM 5-20-03                                     | HRSMSC | 200      |                                         |              |          | 7687        |                         | 1.5                        |
|                     |                                                      | AFL    |          |                                         |              |          | 5594        |                         |                            |
| + 570104            | INSPECT LEFT WING (B)                                |        |          |                                         |              |          |             |                         | W1                         |
| 57.0102             | PKG 2, 3                                             | MOS    |          |                                         |              |          | 26-JUN-2001 |                         |                            |
|                     | REF: AMM 5-20-03                                     | HRSMSC | 400      |                                         |              |          | 7687        |                         |                            |
|                     |                                                      | AFL    |          |                                         |              |          | 5594        |                         |                            |
| + 570200            | INSPECT LEFT WING STRUCTURE                          |        |          |                                         |              |          |             | MANDATORY               | W1                         |
| 57.040              |                                                      | MOS    |          |                                         |              |          |             |                         |                            |
|                     | REF: AMM 5-40-05                                     | HRSMSC | 15000    |                                         |              |          |             | 15000                   |                            |
|                     |                                                      | AFL    |          |                                         |              |          |             |                         |                            |
| + 570120            | INSPECT RIGHT AILERON BELL CRANK                     |        |          |                                         |              |          |             |                         | W2                         |
| 57.020              | PKG 1, 2, 3                                          | MOS    |          |                                         |              |          | 26-JUN-2001 |                         |                            |
|                     | REF: AMM 5-20-03                                     | HRSMSC | 200      |                                         |              |          | 7687        |                         |                            |
|                     |                                                      | AFL    |          |                                         |              |          | 5594        |                         |                            |
| + 570221            | INSPECT RIGHT OUTER WING PANELS                      |        |          |                                         |              |          |             | MANDATORY               | W2                         |
| 57.050              |                                                      | MOS    |          |                                         |              |          | 24-AUG-1993 |                         |                            |
|                     | REF: AMM 5-40-05                                     | HRSMSC | 4800     |                                         |              |          | 5326        | 10126                   |                            |
|                     |                                                      | AFL    |          |                                         |              |          | 3975        |                         |                            |
| + 570116            | INSPECT RIGHT WING (A)                               |        |          |                                         |              |          |             |                         | W2                         |
| 57.0101             | PKG 1, 2, 3                                          | MOS    |          |                                         |              |          | 26-JUN-2001 |                         |                            |
|                     | REF: AMM 5-20-03                                     | HRSMSC | 200      |                                         |              |          | 7687        |                         | 1.5                        |
|                     |                                                      | AFL    |          |                                         |              |          | 5594        |                         |                            |
| + 570119            | INSPECT RIGHT WING (B)                               |        |          |                                         |              |          |             |                         | W2                         |
| 57.0102             | PKG 2, 3                                             | MOS    |          |                                         |              |          | 26-JUN-2001 |                         |                            |
|                     | REF: AMM 5-20-03                                     | HRSMSC | 400      |                                         |              |          | 7687        |                         |                            |
|                     |                                                      | AFL    |          |                                         |              |          | 5594        |                         |                            |
| + 570201            | INSPECT RIGHT WING STRUCTURE                         |        |          |                                         |              |          |             | MANDATORY               | W2                         |
| 57.040              |                                                      | MOS    |          |                                         |              |          |             |                         |                            |
|                     | REF: AMM 5-40-05                                     | HRSMSC | 15000    |                                         |              |          |             | 15000                   |                            |
|                     |                                                      | AFL    |          |                                         |              |          |             |                         |                            |
| 570031              | TANK, TIP LEFT                                       |        |          |                                         |              |          |             |                         | W1                         |
| 57.030              | 5213003-405                                          | MOS    |          |                                         |              |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRSMSC | O/C      | 0                                       |              |          | 0           |                         |                            |
|                     | REF: AMM 57-20-00                                    | AFL    |          |                                         |              |          | 0           |                         |                            |
| 570041              | TANK, TIP RIGHT                                      |        |          |                                         |              |          |             |                         | W2                         |
| 57.030              | 5213003-406                                          | MOS    |          |                                         |              |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                           | HRSMSC | O/C      | 0                                       |              |          | 0           |                         |                            |
|                     | REF: AMM 57-20-00                                    | AFL    |          |                                         |              |          | 0           |                         |                            |
| <b>CHAPTER 71</b>   | <b>POWER PLANT</b>                                   |        |          |                                         |              |          |             |                         |                            |
| + 710650U           | - INSP #1 ENG INLET NACELLE                          |        |          |                                         |              |          |             |                         | E1                         |
|                     | PKG 1, 2, 3                                          | MOS    |          |                                         |              |          | 26-JUN-2001 |                         |                            |
|                     | REF:                                                 | HRSMSC | 200      |                                         |              |          | 7687        |                         |                            |
|                     |                                                      | AFL    |          |                                         |              |          | 5594        |                         |                            |



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO                                   | TASK DESCRIPTION                                        | UNIT    | INTERVAL | TIME-----AT-----    | INSTALLATION | DISPOSITION | AREA               |
|-------------------------------------------|---------------------------------------------------------|---------|----------|---------------------|--------------|-------------|--------------------|
| WORKCARD                                  | PART NUMBER/PKG<br>SERIAL NUMBER                        |         |          | TSN TSO TSR TSI ADJ | Warr Exp     | COMPLIANCE  | PRICE<br>LABOR HRS |
| + 713650U                                 | - INSP #2 ENG INLET NACELLE<br>PKG 1, 2, 3              | MOS     |          |                     |              | 26-JUN-2001 | E2                 |
|                                           | REF:                                                    | HRS/MSC | 200      |                     |              | 7687        |                    |
|                                           |                                                         | AFL     |          |                     |              | 5594        |                    |
| 71EN1                                     | ENGINE, NO. 1<br>3072500-2                              | MOS     |          |                     |              |             |                    |
|                                           | P-77482                                                 | HRS/MSC | E/C      |                     |              |             |                    |
|                                           | REF:                                                    | AFL     |          |                     |              |             |                    |
| 71EN2                                     | ENGINE, NO. 2<br>3072500-2                              | MOS     |          |                     |              |             |                    |
|                                           | P77488                                                  | HRS/MSC | E/C      |                     |              |             |                    |
|                                           | REF:                                                    | AFL     |          |                     |              |             |                    |
| <b>CHAPTER 73 ENGINE FUEL AND CONTROL</b> |                                                         |         |          |                     |              |             |                    |
| 731101U                                   | COMPUTER, FUEL CONT ENG #1<br>2101144-1                 | MOS     |          |                     |              | 03-APR-1989 | F5                 |
|                                           | SN-UNKNOWN                                              | HRS/MSC | O/C      | 3972                |              | 4215        | \$4400.            |
|                                           | REF:                                                    | AFL     |          | 2456                |              | 2745        | 3                  |
| 733601U                                   | COMPUTER, FUEL CONT ENG #2<br>2101144-1                 | MOS     |          |                     |              | 31-MAY-1989 | F5                 |
|                                           | 51-2172                                                 | HRS/MSC | O/C      | 4215                |              | 4265        | \$4400.            |
|                                           | REF:                                                    | AFL     |          | 2745                |              | 2793        | 3                  |
| 732106U                                   | INDICATOR, FUEL FLO ENG #1<br>6-883708-1                | MOS     |          |                     |              | 30-JUL-1986 | F3                 |
|                                           | SN-UNKNOWN                                              | HRS/MSC | O/C      | 3209                |              | 3209        | \$372.             |
|                                           | REF:                                                    | AFL     |          | 1976                |              | 1976        |                    |
| 734606U                                   | INDICATOR, FUEL FLO ENG #2<br>6-883708-1                | MOS     |          |                     |              | 30-JUL-1986 | F3                 |
|                                           | SN-UNKNOWN                                              | HRS/MSC | O/C      | 3017                |              | 3209        | \$372.             |
|                                           | REF:                                                    | AFL     |          | 1772                |              | 1976        |                    |
| <b>CHAPTER 75 AIR</b>                     |                                                         |         |          |                     |              |             |                    |
| 750116                                    | SENSOR, TEMPERATURE INLET<br>3070816-2                  | MOS     |          |                     |              | 03-APR-1989 | E1                 |
| 75.030                                    | SN-UNKNOWN                                              | HRS/MSC | O/C      | 3972                |              | 4215        |                    |
|                                           | REF: See Workcard                                       | AFL     |          | 2456                |              | 2745        |                    |
| 750616                                    | SENSOR, TEMPERATURE INLET<br>3070816-2                  | MOS     |          |                     |              | 31-MAY-1989 | E2                 |
| 75.030                                    | 15594                                                   | HRS/MSC | O/C      | 1592                |              | 4265        |                    |
|                                           | REF: See Workcard                                       | AFL     |          |                     |              | 2793        |                    |
| <b>CHAPTER 77 ENGINE INDICATING</b>       |                                                         |         |          |                     |              |             |                    |
| 771606                                    | INDICATOR, (N1) LOW-PRESSURE NO. 2 ENGINE<br>6-883619-1 | MOS     |          |                     |              | 11-FEB-1982 | F3                 |
| 77.020                                    | 4162                                                    | HRS/MSC | O/C      | 0                   |              | 0           | \$1100.            |
|                                           | REF: AMM 77-00-00                                       | AFL     |          |                     |              | 0           |                    |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER     | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION |     |     |     |     | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|----------------------------------------------------------|--------|----------|------------------------------|-----|-----|-----|-----|----------|-------------|-------------------------|----------------------------|
|                     |                                                          |        |          | TSN                          | TSO | TSR | TSI | ADJ |          |             |                         |                            |
| 770106              | INDICATOR, (N1) LOW-PRESSURE NO. 1 ENGINE                |        |          |                              |     |     |     |     |          |             |                         | F3                         |
| 77.020              | 6883619-1                                                | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         | \$1100.                    |
|                     | SN-UNKNOWN                                               | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 77-00-00                                        | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 770606              | INDICATOR, (N2) HIGH-PRESSURE NO. 1 ENGINE               |        |          |                              |     |     |     |     |          |             |                         | F3                         |
| 77.040              | 6883620-1                                                | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                               | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 77-00-00                                        | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 772106              | INDICATOR, (N2) HIGH-PRESSURE NO. 2 ENGINE               |        |          |                              |     |     |     |     |          |             |                         | F3                         |
| 77.040              | 6-883620-1                                               | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                               | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 77-00-00                                        | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 771106              | INDICATOR, ITT NO. 1 ENGINE                              |        |          |                              |     |     |     |     |          |             |                         | F3                         |
| 77.060              | 6883621-503                                              | MOS    |          |                              |     |     |     |     |          | 31-MAY-1993 |                         | \$507.                     |
|                     | R0097                                                    | HRS/MS | O/C      |                              | 0   |     |     |     |          | 5278        |                         |                            |
|                     | REF: AMM 77-00-00                                        | AFL    |          |                              |     |     |     |     |          | 3928        |                         |                            |
| 772606              | INDICATOR, ITT NO. 2 ENGINE                              |        |          |                              |     |     |     |     |          |             |                         | F3                         |
| 77.060              | 6883621-503                                              | MOS    |          |                              |     |     |     |     |          | 31-MAY-1993 |                         | \$507.                     |
|                     | R0031R                                                   | HRS/MS | O/C      |                              | 0   |     |     |     |          | 5278        |                         |                            |
|                     | REF: AMM 77-00-00                                        | AFL    |          |                              |     |     |     |     |          | 3928        |                         |                            |
| <b>CHAPTER 78</b>   |                                                          |        |          |                              |     |     |     |     |          |             |                         |                            |
| + 780119            | CHECK #1 THRUST REVERSER SECONDARY LATCH SOLENOID SWITCH |        |          |                              |     |     |     |     |          |             |                         | E1                         |
| 78.140              | PKG 3                                                    | MOS    |          |                              |     |     |     |     |          | 26-JUL-2000 |                         |                            |
|                     |                                                          | HRS/MS | 800      |                              |     |     |     |     |          | 7325        |                         |                            |
|                     | REF: AMM 78-30-00                                        | AFL    |          |                              |     |     |     |     |          | 5360        |                         |                            |
| + 780120            | CHECK #2 THRUST REVERSER SECONDARY LATCH SOLENOID SWITCH |        |          |                              |     |     |     |     |          |             |                         | E2                         |
| 78.140              | PKG 3                                                    | MOS    |          |                              |     |     |     |     |          | 26-JUL-2000 |                         |                            |
|                     |                                                          | HRS/MS | 800      |                              |     |     |     |     |          | 7325        |                         |                            |
|                     | REF: AMM 78-30-00                                        | AFL    |          |                              |     |     |     |     |          | 5360        |                         |                            |
| + 780116            | OPERATIONAL CHECK NO.1 THRUST REVERSER                   |        |          |                              |     |     |     |     |          |             |                         | E1                         |
| 78.110              | PKG 3                                                    | MOS    |          |                              |     |     |     |     |          | 26-JUL-2000 |                         |                            |
|                     |                                                          | HRS/MS | 800      |                              |     |     |     |     |          | 7325        |                         |                            |
|                     | REF: AMM 78-30-00                                        | AFL    |          |                              |     |     |     |     |          | 5360        |                         |                            |
| + 780616            | OPERATIONAL CHECK NO.2 THRUST REVERSER                   |        |          |                              |     |     |     |     |          |             |                         | E2                         |
| 78.110              | PKG 3                                                    | MOS    |          |                              |     |     |     |     |          | 26-JUL-2000 |                         |                            |
|                     |                                                          | HRS/MS | 800      |                              |     |     |     |     |          | 7325        |                         |                            |
|                     | REF: AMM 78-30-00                                        | AFL    |          |                              |     |     |     |     |          | 5360        |                         |                            |
| 780156              | ACCUMULATOR, THRUST REVERSER                             |        |          |                              |     |     |     |     |          |             |                         | F5                         |
| 78.040              | 4723565-1                                                | MOS    |          |                              |     |     |     |     |          | 11-FEB-1982 |                         |                            |
|                     | SN-UNKNOWN                                               | HRS/MS | O/C      | 0                            |     |     |     |     |          | 0           |                         |                            |
|                     | REF: AMM 78-34-00                                        | AFL    |          |                              |     |     |     |     |          | 0           |                         |                            |
| 780146              | ACTUATOR, THRUST REVERSER NO. 1                          |        |          |                              |     |     |     |     |          |             |                         | E1                         |
| 78.020              | F10A-5-SCH203-1                                          | MOS    |          |                              |     |     |     |     |          | 02-JAN-1987 |                         |                            |
|                     | 0419                                                     | HRS/MS | O/C      | 0                            |     |     |     |     |          | 3504        |                         |                            |
|                     | REF: AMM 78-34-00                                        | AFL    |          |                              |     |     |     |     |          | 2168        |                         |                            |



Aircraft Model- 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO  | WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER    | UNIT   | INTERVAL | TIME-----AT-----<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|----------|----------|---------------------------------------------------------|--------|----------|-----------------------------------------|----------|-------------|-------------------------|----------------------------|
| 780646   |          | ACTUATOR, THRUST REVERSER NO. 2                         |        |          |                                         |          |             |                         | E2                         |
| 78.020   |          | F10A-5-SCH203-1                                         | MOS    |          |                                         |          | 11-FEB-1982 |                         |                            |
|          |          | SN-UNKNOWN                                              | HRSMSC | O/C      | 0                                       |          | 0           |                         |                            |
|          |          | REF: AMM 78-34-00                                       | AFL    |          |                                         |          | 0           |                         |                            |
| 780161   |          | BOTTLE, THRUST REVERSER GAS STORAGE                     |        |          |                                         |          |             | LIFE LIMIT              | F5                         |
| 78.050   |          | 3753015-501                                             | MOS    | 288      | 0                                       |          | 11-FEB-1982 | 11-FEB-2006             |                            |
|          |          | 07511A1                                                 | HRSMSC |          |                                         |          |             |                         |                            |
|          |          | REF: AMM 78-34-00                                       | AFL    |          |                                         |          |             |                         |                            |
| + 780163 |          | HYDROSTATIC TEST                                        |        |          |                                         |          |             |                         | F5                         |
| 78.050   |          |                                                         | MOS    | 36       |                                         |          | 26-OCT-1999 | 26-OCT-2002             |                            |
|          |          |                                                         | HRSMSC |          |                                         |          | 6961        |                         |                            |
|          |          | REF: See Workcard                                       | AFL    |          |                                         |          | 5135        |                         |                            |
| 780131   |          | CONTROL ASSEMBLY, THROTTLE RETARDER FEEDBACK NO. 1      |        |          |                                         |          |             | LIFE LIMIT              | E1                         |
| 78.090   |          | F10A-5SCP203-1                                          | MOS    |          |                                         |          | 11-FEB-1982 |                         |                            |
|          |          | SN-UNKNOWN                                              | HRSMSC | 10000    | 0                                       |          | 0           | 10000                   |                            |
|          |          | REF: AMM 78-32-00                                       | AFL    |          |                                         |          | 0           |                         |                            |
| 780136   |          | CLEAN/LUBRICATE NO.1 THROTTLE RETARDER CABLE AND CASING |        |          |                                         |          |             |                         | E1                         |
| 78.090   |          |                                                         | MOS    | 36       |                                         |          | 06-NOV-2001 | 06-NOV-2004             |                            |
|          |          |                                                         | HRSMSC |          |                                         |          | 7774        |                         |                            |
|          |          | REF: AMM 12-20-00                                       | AFL    |          |                                         |          | 5641        |                         |                            |
| 780631   |          | CONTROL ASSEMBLY, THROTTLE RETARDER FEEDBACK NO. 2      |        |          |                                         |          |             | LIFE LIMIT              | E2                         |
| 78.090   |          | F10A-5SCP203-2                                          | MOS    |          |                                         |          | 11-FEB-1982 |                         |                            |
|          |          | SN-UNKNOWN                                              | HRSMSC | 10000    | 0                                       |          | 0           | 10000                   |                            |
|          |          | REF: AMM 78-32-00                                       | AFL    |          |                                         |          | 0           |                         |                            |
| 780636   |          | CLEAN/LUBRICATE NO.2 THROTTLE RETARDER CABLE AND CASING |        |          |                                         |          |             |                         | E2                         |
| 78.090   |          |                                                         | MOS    | 36       |                                         |          | 06-NOV-2001 | 06-NOV-2004             |                            |
|          |          |                                                         | HRSMSC |          |                                         |          | 7774        |                         |                            |
|          |          | REF: AMM 78-32-00                                       | AFL    |          |                                         |          | 5641        |                         |                            |
| 780171   |          | RELEASE VALVE, THRUST REVERSER                          |        |          |                                         |          |             |                         | F5                         |
| 78.070   |          | 3723581-1                                               | MOS    |          |                                         |          | 11-FEB-1982 |                         |                            |
|          |          | SN-UNKNOWN                                              | HRSMSC | O/C      | 0                                       |          | 0           |                         |                            |
|          |          | REF: AMM 78-34-00                                       | AFL    |          |                                         |          | 0           |                         |                            |
| 780158   |          | SWITCH, THRUST REVERSER LOW-PRESSURE                    |        |          |                                         |          |             |                         | F5                         |
| 78.080   |          | 4713533-1                                               | MOS    |          |                                         |          | 11-FEB-1982 |                         |                            |
|          |          | SN-UNKNOWN                                              | HRSMSC | O/C      | 0                                       |          | 0           |                         |                            |
|          |          | REF: AMM 78-34-00                                       | AFL    |          |                                         |          | 0           |                         |                            |
| 780141   |          | THRUST REVERSER ASSEMBLY, NO. 1                         |        |          |                                         |          |             |                         | E1                         |
| 78.010   |          | F10A-5-B20202-1                                         | MOS    |          |                                         |          | 11-FEB-1982 |                         |                            |
|          |          | SN-UNKNOWN                                              | HRSMSC | O/C      | 0                                       |          | 0           |                         |                            |
|          |          | REF: NO REF                                             | AFL    |          |                                         |          | 0           |                         |                            |
| + 780148 |          | INSPECT                                                 |        |          |                                         |          |             | INSPECT                 | E1                         |
| 78.130   |          |                                                         | MOS    |          |                                         |          | 20-AUG-1991 |                         |                            |
|          |          |                                                         | HRSMSC | 5000     |                                         |          | 4906        | 9906                    |                            |
|          |          | REF: See Workcard                                       | AFL    |          |                                         |          |             |                         |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER                              | UNIT                 | INTERVAL | TIME-----AT-----INSTALLATION |     |     |     |     | Warr Exp | COMPLIANCE                  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|-----------------------------------------------------------------------------------|----------------------|----------|------------------------------|-----|-----|-----|-----|----------|-----------------------------|-------------------------|----------------------------|
|                     |                                                                                   |                      |          | TSN                          | TSO | TSR | TSI | ADJ |          |                             |                         |                            |
| 780143<br>78.100    | LUBRICATE<br>PKG 3                                                                | MOS<br>HRSMSC<br>AFL | 800      |                              |     |     |     |     |          | 26-JUL-2000<br>7325<br>5360 |                         | E1                         |
|                     | REF: AMM 12-20-00                                                                 |                      |          |                              |     |     |     |     |          |                             |                         |                            |
| 780641<br>78.011    | THRUST REVERSER ASSEMBLY, NO. 2<br>F10A-5-B20202-2<br>SN-UNKNOWN<br>REF: NO REF   | MOS<br>HRSMSC<br>AFL | O/C      | 0                            |     |     |     |     |          | 11-FEB-1982<br>0<br>0       |                         | E2                         |
| + 780648<br>78.130  | INSPECT                                                                           | MOS<br>HRSMSC<br>AFL | 5000     |                              |     |     |     |     |          | 20-AUG-1991<br>4906         | INSPECT<br>9906         | E2                         |
|                     | REF: See Workcard                                                                 |                      |          |                              |     |     |     |     |          |                             |                         |                            |
| 780643<br>78.100    | LUBRICATE<br>PKG 3                                                                | MOS<br>HRSMSC<br>AFL | 800      |                              |     |     |     |     |          | 26-JUL-2000<br>7325<br>5360 |                         | E2                         |
|                     | REF: AMM 12-20-00                                                                 |                      |          |                              |     |     |     |     |          |                             |                         |                            |
| 780166<br>78.060    | VALVE, RELIEF<br>PN<br>SN-UNKNOWN<br>REF: AMM 78-34-00                            | MOS<br>HRSMSC<br>AFL | O/C      | 0                            |     |     |     |     |          | 11-FEB-1982<br>0<br>0       |                         | F5                         |
| 780151<br>78.030    | VALVE, THRUST REVERSER CONTROL NO. 1<br>723573<br>525<br>REF: AMM 78-34-00        | MOS<br>HRSMSC<br>AFL | O/C      | 0                            |     |     |     |     |          | 08-APR-1987<br>3684<br>2293 |                         | F5<br>\$588.<br>2          |
| 780651<br>78.030    | VALVE, THRUST REVERSER CONTROL NO. 2<br>723573<br>SN-UNKNOWN<br>REF: AMM 78-34-00 | MOS<br>HRSMSC<br>AFL | O/C      | 0                            |     |     |     |     |          | 11-FEB-1982<br>0<br>0       |                         | F5<br>\$588.<br>2          |
| <b>CHAPTER 79</b>   | <b>OIL</b>                                                                        |                      |          |                              |     |     |     |     |          |                             |                         |                            |
| 791121U             | IND, PRESS/TEMP ENG #1<br>6-883706-1<br>SN-UNKNOWN<br>REF:                        | MOS<br>HRSMSC<br>AFL | O/C      | 0                            |     |     |     |     |          | 11-FEB-1982<br>0<br>0       |                         | F3<br>\$805.               |
| 792621U             | IND, PRESS/TEMP ENG #2<br>6-883706-1<br>SN-UNKNOWN<br>REF:                        | MOS<br>HRSMSC<br>AFL | O/C      | 0                            |     |     |     |     |          | 11-FEB-1982<br>0<br>0       |                         | F3<br>\$805.               |
| 790616U             | VALVE, OIL TEMP ENG #1<br>157025-2<br>SN-UNKNOWN<br>REF:                          | MOS<br>HRSMSC<br>AFL | O/C      | 3972<br>2456                 |     |     |     |     |          | 03-APR-1989<br>4215<br>2745 |                         | E1                         |
| 792116U             | VALVE, OIL TEMP ENG #2<br>157025-2<br>SN-UNKNOWN<br>REF:                          | MOS<br>HRSMSC<br>AFL | O/C      | 4215                         |     |     |     |     |          | 31-MAY-1989<br>4265<br>2793 |                         | E2                         |



**Engine Model - TFE731-3**
**Report Date 11-APR-2002**
**Owner Name - R&S AIRCRAFT INVESTMENTS, LLC**
**A/C Serial #: 368 A/C Reg. #: N368MD**

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER  | UNIT    | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|-------------------------------------------------------|---------|----------|-----------------------------------------------------|----------|------------|-------------------------|----------------------------|
| <b>ENGINE NO. 1</b> |                                                       |         |          |                                                     |          |            |                         |                            |
| <b>CHAPTER 71</b>   |                                                       |         |          |                                                     |          |            |                         |                            |
| 710140U             | NO. 1 ENGINE - -- RUN ADJ/TEST #1 ENG                 | MOS     |          |                                                     |          |            | 13-NOV-1999             |                            |
|                     | REF:                                                  | HRS/MSC | C/C      |                                                     |          | 6961       |                         |                            |
|                     |                                                       | ENC     |          |                                                     |          | 5135       |                         |                            |
|                     |                                                       | (AFL)   |          |                                                     |          |            |                         |                            |
| + 714010            | NO. 1 ENGINE - CHECK ELECTRICAL WIRES AND CONNECTIONS | MOS     |          |                                                     |          |            | 26-JUL-2000             |                            |
| 71.040              |                                                       | HRS/MSC | 800      |                                                     |          | 7325       | 8125                    |                            |
|                     | REF: EMM 72-00-00                                     | ENC     |          |                                                     |          | 5360       |                         |                            |
|                     |                                                       | (AFL)   |          |                                                     |          |            |                         |                            |
| + 715010            | NO. 1 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS   | MOS     |          |                                                     |          |            | 26-JUL-2000             |                            |
| 71.050              |                                                       | HRS/MSC | 800      |                                                     |          | 7325       | 8125                    |                            |
|                     | REF: EMM 72-00-00                                     | ENC     |          |                                                     |          | 5360       |                         |                            |
|                     |                                                       | (AFL)   |          |                                                     |          |            |                         |                            |
| + 710130            | NO. 1 ENGINE - INSPECT FAN ROTOR ASSEMBLY BLADES      | MOS     |          |                                                     |          |            | 16-FEB-2001             |                            |
| 71.020              | PKG 6, 6                                              | HRS/MSC | 300      |                                                     |          | 7551       |                         | .5                         |
|                     | REF: EMM 72-00-00                                     | ENC     |          |                                                     |          | 5515       |                         |                            |
|                     |                                                       | (AFL)   |          |                                                     |          |            |                         |                            |
| + 710120            | NO. 1 ENGINE - MAJOR PERIODIC INSPECTION              | MOS     |          |                                                     |          |            | 13-NOV-1999             |                            |
| 71.010              |                                                       | HRS/MSC | 1400     |                                                     |          | 6961       | 8361                    |                            |
|                     | REF: EMM 72-00-00                                     | ENC     |          |                                                     |          | 5135       |                         |                            |
|                     |                                                       | (AFL)   |          |                                                     |          |            |                         |                            |
| 710110U             | NO. 1 ENGINE - ENGINE, #1                             | MOS     |          |                                                     |          |            | 03-APR-1989             |                            |
|                     | 3072500-2                                             | HRS/MSC | O/C      | 3972                                                |          | 4215       |                         |                            |
|                     | P-77482                                               | ENC     |          |                                                     |          | 2745       |                         |                            |
|                     | REF:                                                  | (AFL)   |          | 2456                                                |          |            |                         |                            |
| <b>CHAPTER 72</b>   |                                                       |         |          |                                                     |          |            |                         |                            |
| <b>ENGINE</b>       |                                                       |         |          |                                                     |          |            |                         |                            |
| + 724120            | NO. 1 ENGINE - INSPECT COMBUSTION PLENUM CASE         | MOS     |          |                                                     |          |            | 13-NOV-1999             |                            |
| 72.030              |                                                       | HRS/MSC | 1400     |                                                     |          | 6961       | 8361                    |                            |
|                     | REF: EMM 72-40-04                                     | ENC     |          |                                                     |          | 5135       |                         |                            |
|                     |                                                       | (AFL)   |          |                                                     |          |            |                         |                            |
| + 723110            | NO. 1 ENGINE - INSPECT COMPRESSOR CORE                | MOS     |          |                                                     |          |            | 26-APR-1994             |                            |
| 72.010              |                                                       | HRS/MSC | 4200     |                                                     |          | 5442       | 9642                    |                            |
|                     | REF: NO REF                                           | ENC     |          |                                                     |          | 4106       |                         |                            |
|                     |                                                       | (AFL)   |          |                                                     |          |            |                         |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L



**Engine Model - TFE731-3**
**Report Date 11-APR-2002**
**Owner Name - R&S AIRCRAFT INVESTMENTS, LLC**  
**A/C Serial #: 368 A/C Reg. #: N368MD**

| ITEMNO<br>WORKCARD               | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER                                           | UNIT                          | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE          | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|----------------------------------|------------------------------------------------------------------------------------------------|-------------------------------|----------|-----------------------------------------------------|----------|---------------------|-------------------------|----------------------------|
| + 727110<br>72.300               | NO. 1 ENGINE - PERIODIC INSPECT FAN SUPPORT ASSEMBLY                                           | MOS                           |          |                                                     |          | 26-APR-1994         |                         |                            |
|                                  | REF: EMM 72-70-06                                                                              | HRS/MS<br>ENC<br>(AFL)        | 4200     |                                                     |          | 5442                | 9642                    |                            |
| 724110<br>72.020                 | NO. 1 ENGINE - CASE, COMBUSTION PLENUM<br>3072443-4<br>IP8088<br>REF: NO REF                   | MOS<br>HRS/MS<br>ENC<br>(AFL) | O/C      | 3972                                                |          | 03-APR-1989<br>4215 |                         |                            |
|                                  |                                                                                                |                               |          | 2456                                                |          | 2745                |                         |                            |
| + 724120<br>72.030<br>ASSOCIATED | NO. 1 ENGINE - INSPECT COMBUSTION PLENUM CASE                                                  | MOS                           |          |                                                     |          | 13-NOV-1999         |                         |                            |
|                                  | REF: EMM 72-40-04                                                                              | HRS/MS<br>ENC<br>(AFL)        | 1400     |                                                     |          | 6961                | 8361                    |                            |
| 725050<br>72.090                 | NO. 1 ENGINE - DISC, FAN ROTOR<br>3073563-2<br>970322902451<br>REF: NO REF                     | MOS<br>HRS/MS<br>ENC<br>(AFL) |          | 0                                                   |          | 13-NOV-1999<br>6961 |                         |                            |
|                                  |                                                                                                |                               | 10000    | 0                                                   |          | 5135                | 15135                   |                            |
| 725060<br>72.100                 | NO. 1 ENGINE - DISC, STAGE 1 LOW PRESSURE COMPRESSOR<br>3072395<br>1-12112-1531<br>REF: NO REF | MOS<br>HRS/MS<br>ENC<br>(AFL) |          |                                                     |          | 03-APR-1989<br>4215 |                         |                            |
|                                  |                                                                                                |                               | 10000    | 2456                                                |          | 2745                | 10289                   |                            |
| 725010<br>72.040                 | NO. 1 ENGINE - DISC, STAGE 1 LOW PRESSURE TURBINE<br>3072352-4<br>0-03229-1212<br>REF: NO REF  | MOS<br>HRS/MS<br>ENC<br>(AFL) |          | 0                                                   |          | 12-JUL-1991<br>4879 |                         |                            |
|                                  |                                                                                                |                               | 3000     | 0                                                   |          | 3494                | 6494                    |                            |
| 725070<br>72.110                 | NO. 1 ENGINE - DISC, STAGE 2 LOW PRESSURE COMPRESSOR<br>3072396<br>1-12112-429<br>REF: NO REF  | MOS<br>HRS/MS<br>ENC<br>(AFL) |          | 3972                                                |          | 03-APR-1989<br>4215 |                         |                            |
|                                  |                                                                                                |                               | 10000    | 2456                                                |          | 2745                | 10289                   |                            |
| 725020<br>72.050                 | NO. 1 ENGINE - DISC, STAGE 2 LOW PRESSURE TURBINE<br>3072351-5<br>1-03226-1486<br>REF: NO REF  | MOS<br>HRS/MS<br>ENC<br>(AFL) |          | 0                                                   |          | 20-MAY-1993<br>5278 |                         |                            |
|                                  |                                                                                                |                               | 3000     | 0                                                   |          | 3928                | 6928                    |                            |
| 725080<br>72.120                 | NO. 1 ENGINE - DISC, STAGE 3 LOW PRESSURE COMPRESSOR<br>3072397<br>0-12112-4057<br>REF: NO REF | MOS<br>HRS/MS<br>ENC<br>(AFL) |          | 3972                                                |          | 03-APR-1989<br>4215 |                         |                            |
|                                  |                                                                                                |                               | 10000    | 2456                                                |          | 2745                | 10289                   |                            |



**Engine Model - TFE731-3**
**Report Date 11-APR-2002**
**Owner Name - R&S AIRCRAFT INVESTMENTS, LLC**
**A/C Serial #: 368 A/C Reg. #: N368MD**

| ITEM NO  | WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|----------|----------|------------------------------------------------------|--------|----------|-----------------------------------------------------|----------|-------------|-------------------------|----------------------------|
| 725030   |          | NO. 1 ENGINE - DISC, STAGE 3 LOW PRESSURE TURBINE    |        |          |                                                     |          |             | LIFE LIMIT              |                            |
|          | 72.060   | 3074097-1                                            | MOS    |          |                                                     |          | 13-NOV-1999 |                         |                            |
|          |          | 975332202025                                         | HRSMSC |          | 0                                                   |          | 6961        |                         |                            |
|          |          | REF: NO REF                                          | ENC    |          |                                                     |          |             |                         |                            |
|          |          | (AFL)                                                |        | 7000     | 0                                                   |          | 5135        | 12135                   |                            |
| 725090   |          | NO. 1 ENGINE - DISC, STAGE 4 LOW PRESSURE COMPRESSOR |        |          |                                                     |          |             | LIFE LIMIT              |                            |
|          | 72.130   | 3072398                                              | MOS    |          |                                                     |          | 03-APR-1989 |                         |                            |
|          |          | 0-03160-3697                                         | HRSMSC |          | 3972                                                |          | 4215        |                         |                            |
|          |          | REF: NO REF                                          | ENC    |          |                                                     |          |             |                         |                            |
|          |          | (AFL)                                                |        | 10000    | 2456                                                |          | 2745        | 10289                   |                            |
| 725160   |          | NO. 1 ENGINE - DUCT, TURBINE INTERSTAGE TRANSITION   |        |          |                                                     |          |             |                         |                            |
|          | 72.200   | 3072318                                              | MOS    |          |                                                     |          | 03-APR-1989 |                         |                            |
|          |          | SN-UNKNOWN                                           | HRSMSC | O/C      |                                                     |          | 4215        |                         |                            |
|          |          | REF: EMM 72-50-05                                    | ENC    |          |                                                     |          |             |                         |                            |
|          |          | (AFL)                                                |        |          |                                                     |          | 2745        |                         |                            |
| 726110   |          | NO. 1 ENGINE - GEARBOX, ACCESSORY                    |        |          |                                                     |          |             |                         |                            |
|          | 72.250   | 3070003-5                                            | MOS    |          |                                                     |          | 03-APR-1989 |                         |                            |
|          |          | SN-UNKNOWN                                           | HRSMSC | O/C      | 3972                                                |          | 4215        |                         |                            |
|          |          | REF: EMM 72-60-01                                    | ENC    |          |                                                     |          |             |                         |                            |
|          |          | (AFL)                                                |        |          | 2456                                                |          | 2745        |                         |                            |
| + 726120 |          | NO. 1 ENGINE - INSPECT                               |        |          |                                                     |          |             |                         |                            |
|          | 72.260   |                                                      | MOS    |          |                                                     |          | 26-APR-1994 |                         |                            |
|          |          | REF: EMM 72-60-02                                    | HRSMSC | 4200     |                                                     |          | 5442        | 9642                    |                            |
|          |          | (AFL)                                                | ENC    |          |                                                     |          |             |                         |                            |
|          |          |                                                      | (AFL)  |          |                                                     |          | 4106        |                         |                            |
| 726130   |          | NO. 1 ENGINE - GEARBOX, TRANSFER                     |        |          |                                                     |          |             |                         |                            |
|          | 72.270   | 3070093-3                                            | MOS    |          |                                                     |          | 03-APR-1989 |                         |                            |
|          |          | P-2768                                               | HRSMSC | O/C      | 0                                                   |          | 4215        |                         |                            |
|          |          | REF: EMM 72-60-01                                    | ENC    |          |                                                     |          |             |                         |                            |
|          |          | (AFL)                                                |        |          | 0                                                   |          | 2745        |                         |                            |
| 725110   |          | NO. 1 ENGINE - IMPELLER, HIGH PRESSURE               |        |          |                                                     |          |             | LIFE LIMIT              |                            |
|          | 72.150   | 3073398-1                                            | MOS    |          |                                                     |          | 03-APR-1989 |                         |                            |
|          |          | 4-23365-1094                                         | HRSMSC |          | 3972                                                |          | 4215        |                         |                            |
|          |          | REF: NO REF                                          | ENC    |          |                                                     |          |             |                         |                            |
|          |          | (AFL)                                                |        | 10000    | 2456                                                |          | 2745        | 10289                   |                            |
| 725180   |          | NO. 1 ENGINE - NOZZLE, STAGE 1 LOW PRESSURE TURBINE  |        |          |                                                     |          |             |                         |                            |
|          | 72.220   | 3072319-11                                           | MOS    |          |                                                     |          | 13-NOV-1999 |                         |                            |
|          |          | 990134506659                                         | HRSMSC | O/C      | 0                                                   |          | 6961        |                         |                            |
|          |          | REF: NO REF                                          | ENC    |          |                                                     |          |             |                         |                            |
|          |          | (AFL)                                                |        |          | 0                                                   |          | 5135        |                         |                            |
| 725140   |          | NO. 1 ENGINE - PLATE, HIGH PRESSURE ROTOR SEAL       |        |          |                                                     |          |             | LIFE LIMIT              |                            |
|          | 72.180   | 3072411-1                                            | MOS    |          |                                                     |          | 13-NOV-1999 |                         |                            |
|          |          | 7-18040-2569                                         | HRSMSC |          | 3816                                                |          | 6961        |                         |                            |
|          |          | REF: NO REF                                          | ENC    |          |                                                     |          |             |                         |                            |
|          |          | (AFL)                                                |        | 10000    | 2507                                                |          | 5135        | 12628                   |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L



**Engine Model - TFE731-3**
**Report Date 11-APR-2002**
**Owner Name - R&S AIRCRAFT INVESTMENTS, LLC**
**A/C Serial #: 368 A/C Reg. #: N368MD**

| ITEM NO<br>WORKCARD            | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER           | UNIT                           | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE                  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|--------------------------------|----------------------------------------------------------------|--------------------------------|----------|-----------------------------------------------------|----------|-----------------------------|-------------------------|----------------------------|
| 725040                         | NO. 1 ENGINE - ROTOR, HIGH PRESSURE TURBINE                    |                                |          |                                                     |          |                             | LIFE LIMIT              |                            |
| 72.070                         | 3072316<br>1-18040-598<br>REF: EMM 72-50-06                    | MOS<br>HRS/MSC<br>ENC<br>(AFL) | 7000     | 3972<br>2456                                        |          | 03-APR-1989<br>4215<br>2745 |                         |                            |
| 725170                         | NO. 1 ENGINE - SEAL PLATE, STAGE 1 LOW PRESSURE TURBINE        |                                |          |                                                     |          |                             |                         |                            |
| 72.210                         | 3073552<br>SN-UNKNOWN<br>REF: NO REF                           | MOS<br>HRS/MSC<br>ENC<br>(AFL) | O/C      |                                                     |          | 11-FEB-1982<br>0<br>0       |                         |                            |
| 725190                         | NO. 1 ENGINE - SEAL, LOW PRESSURE TURBINE ROTATING AIR         |                                |          |                                                     |          |                             |                         |                            |
| 72.230                         | 3073355<br>SN-UNKNOWN<br>REF: NO REF                           | MOS<br>HRS/MSC<br>ENC<br>(AFL) | O/C      | 0<br>0<br>0                                         |          | 0<br>0<br>0                 |                         |                            |
| 725120                         | NO. 1 ENGINE - SEAL, ROTATING                                  |                                |          |                                                     |          |                             |                         |                            |
| 72.160                         | 3072729-1<br>0-23151-343<br>REF: NO REF                        | MOS<br>HRS/MSC<br>ENC<br>(AFL) | O/C      | 0<br>0<br>0                                         |          | 12-JUL-1991<br>4879<br>3494 |                         |                            |
| 725150                         | NO. 1 ENGINE - SHAFT, FAN DRIVE                                |                                |          |                                                     |          |                             |                         |                            |
| 72.190                         | 3071955-3<br>1P-39726<br>REF: NO REF                           | MOS<br>HRS/MSC<br>ENC<br>(AFL) | O/C      | 3972<br>2456                                        |          | 03-APR-1989<br>4215<br>2745 |                         |                            |
| 725130                         | NO. 1 ENGINE - SHAFT, HIGH PRESSURE SHOULDERED                 |                                |          |                                                     |          |                             | LIFE LIMIT              |                            |
| 72.170                         | 3072545-1<br>1P-39446<br>REF: NO REF                           | MOS<br>HRS/MSC<br>ENC<br>(AFL) | 12000    | 3972<br>3456                                        |          | 03-APR-1989<br>4215<br>2745 | 11289                   |                            |
| 725191                         | NO. 1 ENGINE - SUPPORT, LOW PRESSURE TURBINE ROTATING AIR SEAL |                                |          |                                                     |          |                             |                         |                            |
| 72.240                         | 3073764<br>SN-UNKNOWN<br>REF: NO REF                           | MOS<br>HRS/MSC<br>ENC<br>(AFL) | O/C      |                                                     |          |                             |                         |                            |
| 725091                         | NO. 1 ENGINE - TIE ROD, LOW PRESSURE                           |                                |          |                                                     |          |                             |                         |                            |
| 72.140                         | 3073049-1<br>1P-15433<br>REF: EMM 72-30-10                     | MOS<br>HRS/MSC<br>ENC<br>(AFL) | O/C      | 3972<br>2456                                        |          | 03-APR-1989<br>4215<br>2745 |                         |                            |
| <b>CHAPTER 73</b>              |                                                                |                                |          |                                                     |          |                             |                         |                            |
| <b>ENGINE FUEL AND CONTROL</b> |                                                                |                                |          |                                                     |          |                             |                         |                            |
| + 731120                       | NO. 1 ENGINE - REMOVE AND REPLACE FILTER ELEMENT               |                                |          |                                                     |          |                             |                         |                            |
| 73.020                         | PKG 6, 6<br>REF: EMM 73-21-02                                  | MOS<br>HRS/MSC<br>ENC<br>(AFL) | 300      |                                                     |          | 16-FEB-2001<br>7551<br>5515 |                         |                            |



**Engine Model - TFE731-3**
**Report Date 11-APR-2002**
**Owner Name - R&S AIRCRAFT INVESTMENTS, LLC**
**A/C Serial #: 368 A/C Reg. #: N368MD**

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION |     |     |     |     | Warr Exp | COMPLIANCE | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|--------|----------|------------------------------|-----|-----|-----|-----|----------|------------|-------------------------|----------------------------|
|                     |                                                      |        |          | TSN                          | TSO | TSR | TSI | ADJ |          |            |                         |                            |
| 732110              | NO. 1 ENGINE - CONTROL UNIT, FUEL                    |        |          |                              |     |     |     |     |          |            |                         |                            |
| 73.060              | 3070800-8                                            | MOS    |          |                              |     |     |     |     |          |            | 18-MAY-1989             |                            |
|                     | SN-UNKNOWN                                           | HRSMSC | O/C      | 3972                         |     |     |     |     |          |            | 4215                    |                            |
|                     | REF: EMM 73-20-01                                    | ENC    |          |                              |     |     |     |     |          |            |                         |                            |
|                     |                                                      | (AFL)  |          | 2456                         |     |     |     |     |          |            | 2745                    |                            |
| 732120              | NO. 1 ENGINE - CHANGE PRESSURE LIMITER VALVE         |        |          |                              |     |     |     |     |          |            |                         |                            |
| 73.070              | 3070685-4                                            | MOS    |          |                              |     |     |     |     |          |            | 03-APR-1989             |                            |
| ASSOCIATED          | SN-UNKNOWN                                           | HRSMSC | O/C      | 3972                         |     |     |     |     |          |            | 4215                    |                            |
|                     | REF: NO REF                                          | ENC    |          |                              |     |     |     |     |          |            |                         |                            |
|                     |                                                      | (AFL)  |          | 2456                         |     |     |     |     |          |            | 2745                    |                            |
| 731150              | NO. 1 ENGINE - COOLER, FUEL/OIL                      |        |          |                              |     |     |     |     |          |            |                         |                            |
| 73.050              | 158610-5                                             | MOS    |          |                              |     |     |     |     |          |            | 03-APR-1989             |                            |
|                     | SN-UNKNOWN                                           | HRSMSC | O/C      | 3972                         |     |     |     |     |          |            | 4215                    |                            |
|                     | REF: EMM 79-20-07                                    | ENC    |          |                              |     |     |     |     |          |            |                         |                            |
|                     |                                                      | (AFL)  |          | 2456                         |     |     |     |     |          |            | 2745                    |                            |
| 731140              | NO. 1 ENGINE - HEATER, FUEL                          |        |          |                              |     |     |     |     |          |            |                         |                            |
| 73.040              | 158670-3                                             | MOS    |          |                              |     |     |     |     |          |            | 03-APR-1989             |                            |
|                     | SN-UNKNOWN                                           | HRSMSC | O/C      | 3972                         |     |     |     |     |          |            | 4215                    |                            |
|                     | REF: EMM 73-10-04                                    | ENC    |          |                              |     |     |     |     |          |            |                         |                            |
|                     |                                                      | (AFL)  |          | 2456                         |     |     |     |     |          |            | 2745                    |                            |
| 731110              | NO. 1 ENGINE - PUMP, ENGINE FUEL                     |        |          |                              |     |     |     |     |          |            |                         |                            |
| 73.010              | 3070850-8                                            | MOS    |          |                              |     |     |     |     |          |            | 03-APR-1989             |                            |
|                     | SN-UNKNOWN                                           | HRSMSC | O/C      | 3972                         |     |     |     |     |          |            | 4215                    |                            |
|                     | REF: EMM 73-20-01                                    | ENC    |          |                              |     |     |     |     |          |            |                         |                            |
|                     |                                                      | (AFL)  |          | 2456                         |     |     |     |     |          |            | 2745                    |                            |
| + 731120            | NO. 1 ENGINE - REMOVE AND REPLACE FILTER ELEMENT     |        |          |                              |     |     |     |     |          |            |                         |                            |
| 73.020              | PKG 6, 6                                             | MOS    |          |                              |     |     |     |     |          |            | 16-FEB-2001             |                            |
| ASSOCIATED          |                                                      | HRSMSC | 300      |                              |     |     |     |     |          |            | 7551                    |                            |
|                     | REF: EMM 73-21-02                                    | ENC    |          |                              |     |     |     |     |          |            |                         |                            |
|                     |                                                      | (AFL)  |          |                              |     |     |     |     |          |            | 5515                    |                            |
| 732160              | NO. 1 ENGINE - TRANSMITTER, FUEL FLOW                |        |          |                              |     |     |     |     |          |            |                         |                            |
| 73.110              | 6883709-1                                            | MOS    |          | 0                            |     |     |     |     |          |            | 06-MAY-1992             |                            |
|                     | 564                                                  | HRSMSC | O/C      | 0                            |     |     |     |     |          |            | 5105                    |                            |
|                     | REF: NO REF                                          | ENC    |          |                              |     |     |     |     |          |            |                         |                            |
|                     |                                                      | (AFL)  |          | 0                            |     |     |     |     |          |            | 3725                    |                            |
| 731130              | NO. 1 ENGINE - VALVE, FLOW DIVIDER/DRAIN             |        |          |                              |     |     |     |     |          |            |                         |                            |
| 73.030              | 394366-4                                             | MOS    |          |                              |     |     |     |     |          |            | 03-APR-1989             |                            |
|                     | SN-UNKNOWN                                           | HRSMSC | O/C      | 3972                         |     |     |     |     |          |            | 4215                    |                            |
|                     | REF: NO REF                                          | ENC    |          |                              |     |     |     |     |          |            |                         |                            |
|                     |                                                      | (AFL)  |          | 2456                         |     |     |     |     |          |            | 2745                    |                            |
| 732110              | NO. 1 ENGINE - CHANGE FUEL CONTROL UNIT              |        |          |                              |     |     |     |     |          |            |                         |                            |
| 73.060              | 3070800-8                                            | MOS    |          |                              |     |     |     |     |          |            | 18-MAY-1989             |                            |
| ASSOCIATED          | SN-UNKNOWN                                           | HRSMSC | O/C      | 3972                         |     |     |     |     |          |            | 4215                    |                            |
|                     | REF: EMM 73-20-01                                    | ENC    |          |                              |     |     |     |     |          |            |                         |                            |
|                     |                                                      | (AFL)  |          | 2456                         |     |     |     |     |          |            | 2745                    |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL



**Engine Model - TFE731-3**
**Report Date 11-APR-2002**
**Owner Name - R&S AIRCRAFT INVESTMENTS, LLC**  
**A/C Serial #: 368 A/C Reg. #: N368MD**

| ITEM NO<br>WORKCARD        | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|----------------------------|------------------------------------------------------|--------|----------|-----------------------------------------------------|----------|------------|-------------------------|----------------------------|
| 732120                     | NO. 1 ENGINE - CHANGE PRESSURE LIMITER VALVE         |        |          |                                                     |          |            |                         |                            |
| 73.070                     | 3070685-4                                            | MOS    |          |                                                     |          |            | 03-APR-1989             |                            |
| ASSOCIATED                 | SN-UNKNOWN                                           | HRS/MS | O/C      | 3972                                                |          | 4215       |                         |                            |
|                            | REF: NO REF                                          | ENC    |          |                                                     |          |            |                         |                            |
|                            | (AFL)                                                |        |          | 2456                                                |          | 2745       |                         |                            |
| 732120                     | NO. 1 ENGINE - VALVE, PRESSURE LIMITER               |        |          |                                                     |          |            |                         |                            |
| 73.070                     | 3070685-4                                            | MOS    |          |                                                     |          |            | 03-APR-1989             |                            |
|                            | SN-UNKNOWN                                           | HRS/MS | O/C      | 3972                                                |          | 4215       |                         |                            |
|                            | REF: NO REF                                          | ENC    |          |                                                     |          |            |                         |                            |
|                            | (AFL)                                                |        |          | 2456                                                |          | 2745       |                         |                            |
| 732140                     | NO. 1 ENGINE - VALVE, SOLENOID CONTROL               |        |          |                                                     |          |            |                         |                            |
| 73.090                     | 109696-3-1                                           | MOS    |          |                                                     |          |            | 03-APR-1989             |                            |
|                            | SN-UNKNOWN                                           | HRS/MS | O/C      | 3972                                                |          | 4215       |                         |                            |
|                            | REF: EMM 76-10-01                                    | ENC    |          |                                                     |          |            |                         |                            |
|                            | (AFL)                                                |        |          | 2456                                                |          | 2745       |                         |                            |
| 732130                     | NO. 1 ENGINE - VALVE, SURGE BLEED                    |        |          |                                                     |          |            |                         |                            |
| 73.080                     | 978812-4-1                                           | MOS    |          |                                                     |          |            | 03-APR-1989             |                            |
|                            | SN-UNKNOWN                                           | HRS/MS | O/C      | 3972                                                |          | 4215       |                         |                            |
|                            | REF: EMM 76-10-01                                    | ENC    |          |                                                     |          |            |                         |                            |
|                            | (AFL)                                                |        |          | 2456                                                |          | 2745       |                         |                            |
| <b>CHAPTER 74 IGNITION</b> |                                                      |        |          |                                                     |          |            |                         |                            |
| + 742120                   | NO. 1 ENGINE - INSPECT 6 O'CLOCK IGNITER PLUG        |        |          |                                                     |          |            |                         |                            |
| 74.040                     |                                                      | MOS    |          |                                                     |          |            | 26-JUL-2000             |                            |
|                            |                                                      | HRS/MS | 800      |                                                     |          | 7325       | 8125                    |                            |
|                            | REF: EMM 74-00-01                                    | ENC    |          |                                                     |          |            |                         |                            |
|                            | (AFL)                                                |        |          |                                                     |          | 5360       |                         |                            |
| + 742140                   | NO. 1 ENGINE - INSPECT 7 O'CLOCK IGNITER PLUG        |        |          |                                                     |          |            |                         |                            |
| 74.060                     |                                                      | MOS    |          |                                                     |          |            | 26-JUL-2000             |                            |
|                            |                                                      | HRS/MS | 800      |                                                     |          | 7325       | 8125                    |                            |
|                            | REF: EMM 74-00-01                                    | ENC    |          |                                                     |          |            |                         |                            |
|                            | (AFL)                                                |        |          |                                                     |          | 5360       |                         |                            |
| + 741120                   | NO. 1 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM     |        |          |                                                     |          |            |                         |                            |
| 74.020                     |                                                      | MOS    |          |                                                     |          |            | 26-JUL-2000             |                            |
|                            |                                                      | HRS/MS | 800      |                                                     |          | 7325       | 8125                    | 1                          |
|                            | REF: EMM 74-00-01                                    | ENC    |          |                                                     |          |            |                         |                            |
|                            | (AFL)                                                |        |          |                                                     |          | 5360       |                         |                            |
| 742110                     | NO. 1 ENGINE - IGNITER PLUG, 6 O'CLOCK               |        |          |                                                     |          |            |                         |                            |
| 74.030                     | 3071589-2                                            | MOS    |          |                                                     |          |            | 03-APR-1989             |                            |
|                            | SN-UNKNOWN                                           | HRS/MS | O/C      | 3972                                                |          | 4215       |                         |                            |
|                            | REF: EMM 72-00-00                                    | ENC    |          |                                                     |          |            |                         |                            |
|                            | (AFL)                                                |        |          | 2456                                                |          | 2745       |                         |                            |
| + 742120                   | NO. 1 ENGINE - INSPECT 6 O'CLOCK IGNITER PLUG        |        |          |                                                     |          |            |                         |                            |
| 74.040                     |                                                      | MOS    |          |                                                     |          |            | 26-JUL-2000             |                            |
| ASSOCIATED                 |                                                      | HRS/MS | 800      |                                                     |          | 7325       | 8125                    |                            |
|                            | REF: EMM 74-00-01                                    | ENC    |          |                                                     |          |            |                         |                            |
|                            | (AFL)                                                |        |          |                                                     |          | 5360       |                         |                            |



**Engine Model - TFE731-3**
**Report Date 11-APR-2002**
**Owner Name - R&S AIRCRAFT INVESTMENTS, LLC**
**A/C Serial #: 368 A/C Reg. #: N368MD**

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|--------|----------|-----------------------------------------|----------|-------------|-------------------------|----------------------------|
| 742130              | NO. 1 ENGINE - IGNITER PLUG, 7 O'CLOCK               |        |          |                                         |          |             |                         |                            |
| 74.050              | 3071589-2                                            | MOS    |          |                                         |          | 03-APR-1989 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 3972                                    |          | 4215        |                         |                            |
|                     | REF: EMM 72-00-00                                    | ENC    |          |                                         |          |             |                         |                            |
|                     | (AFL)                                                |        |          | 2456                                    |          | 2745        |                         |                            |
| + 742140            | NO. 1 ENGINE - INSPECT 7 O'CLOCK IGNITER PLUG        |        |          |                                         |          |             |                         |                            |
| 74.060              |                                                      | MOS    |          |                                         |          | 26-JUL-2000 |                         |                            |
| ASSOCIATED          |                                                      | HRS/MS | 800      |                                         |          | 7325        | 8125                    |                            |
|                     | REF: EMM 74-00-01                                    | ENC    |          |                                         |          |             |                         |                            |
|                     | (AFL)                                                |        |          |                                         |          | 5360        |                         |                            |
| 741110              | NO. 1 ENGINE - UNIT, IGNITION                        |        |          |                                         |          |             |                         |                            |
| 74.010              | 3070378-2                                            | MOS    |          |                                         |          | 03-APR-1989 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 3972                                    |          | 4215        |                         |                            |
|                     | REF: EMM 72-00-00                                    | ENC    |          |                                         |          |             |                         |                            |
|                     | (AFL)                                                |        |          | 2456                                    |          | 2745        |                         |                            |
| + 741120            | NO. 1 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM     |        |          |                                         |          |             |                         |                            |
| 74.020              |                                                      | MOS    |          |                                         |          | 26-JUL-2000 |                         |                            |
| ASSOCIATED          |                                                      | HRS/MS | 800      |                                         |          | 7325        | 8125                    | 1                          |
|                     | REF: EMM 74-00-01                                    | ENC    |          |                                         |          |             |                         |                            |
|                     | (AFL)                                                |        |          |                                         |          | 5360        |                         |                            |
| <b>CHAPTER 75</b>   | <b>AIR</b>                                           |        |          |                                         |          |             |                         |                            |
| 751010              | NO. 1 ENGINE - VALVE, ANTI-ICE SHUTOFF               |        |          |                                         |          |             |                         |                            |
| 75.010              | 978944-1-1                                           | MOS    |          |                                         |          | 03-APR-1989 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 3972                                    |          | 4215        |                         |                            |
|                     | REF: EMM 75-10-01                                    | ENC    |          |                                         |          |             |                         |                            |
|                     | (AFL)                                                |        |          | 2456                                    |          | 2745        |                         |                            |
| <b>CHAPTER 77</b>   | <b>ENGINE INDICATING</b>                             |        |          |                                         |          |             |                         |                            |
| 772110              | NO. 1 ENGINE - HARNESS, ITT THERMOCOUPLE             |        |          |                                         |          |             |                         |                            |
| 77.030              | 3073595-1                                            | MOS    |          |                                         |          | 12-JUL-1991 |                         |                            |
|                     | 1-20219-407                                          | HRS/MS | O/C      | 0                                       |          | 4879        |                         |                            |
|                     | REF: EMM 77-20-01                                    | ENC    |          |                                         |          |             |                         |                            |
|                     | (AFL)                                                |        |          |                                         |          | 3494        |                         |                            |
| 771120              | NO. 1 ENGINE - TRANSDUCER, HIGH PRESSURE (N2)        |        |          |                                         |          |             |                         |                            |
| 77.020              | 3070722-2                                            | MOS    |          |                                         |          | 03-APR-1989 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 3972                                    |          | 4215        |                         |                            |
|                     | REF: EMM 77-10-05                                    | ENC    |          |                                         |          |             |                         |                            |
|                     | (AFL)                                                |        |          | 2456                                    |          | 2745        |                         |                            |
| 771110              | NO. 1 ENGINE - TRANSDUCER, LOW PRESSURE (N1)         |        |          |                                         |          |             |                         |                            |
| 77.010              | 3071928-5                                            | MOS    |          |                                         |          | 03-APR-1989 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 3972                                    |          | 4215        |                         |                            |
|                     | REF: EMM 77-10-03                                    | ENC    |          |                                         |          |             |                         |                            |
|                     | (AFL)                                                |        |          | 2456                                    |          | 2745        |                         |                            |
| <b>CHAPTER 79</b>   | <b>OIL</b>                                           |        |          |                                         |          |             |                         |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L



**Engine Model - TFE731-3**
**Report Date 11-APR-2002**
**Owner Name - R&S AIRCRAFT INVESTMENTS, LLC**
**A/C Serial #: 368 A/C Reg. #: N368MD**

| ITEM NO<br>WORKCARD            | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER                                  | UNIT                          | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE          | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|--------------------------------|---------------------------------------------------------------------------------------|-------------------------------|----------|-----------------------------------------------------|----------|---------------------|-------------------------|----------------------------|
| + 790110<br>79.010             | NO. 1 ENGINE - ANALYZE ENGINE OIL<br>PKG 4, 4,6, 6                                    | MOS<br>HRS/MS<br>ENC<br>(AFL) | 150      |                                                     |          | 26-JUN-2001<br>7687 |                         | 1                          |
|                                | REF: EMM 72-00-00                                                                     |                               |          |                                                     |          | 5594                |                         |                            |
| 790120<br>79.020               | NO. 1 ENGINE - CHANGE OIL                                                             | MOS<br>HRS/MS<br>ENC<br>(AFL) | 1400     |                                                     |          | 13-NOV-1999<br>6961 | 8361                    |                            |
|                                | REF: See Workcard                                                                     |                               |          |                                                     |          | 5135                |                         |                            |
| + 790130<br>79.030             | NO. 1 ENGINE - INSPECT CHIP DETECTOR<br>PKG 4, 4,6, 6                                 | MOS<br>HRS/MS<br>ENC<br>(AFL) | 150      |                                                     |          | 26-JUN-2001<br>7687 |                         |                            |
|                                | REF: EMM 72-00-00                                                                     |                               |          |                                                     |          | 5594                |                         |                            |
| 792150<br>79.080               | NO. 1 ENGINE - COOLER, OIL LOWER LEFT<br>159900-1<br>SN-UNKNOWN<br>REF: EMM 79-20-09  | MOS<br>HRS/MS<br>ENC<br>(AFL) | O/C      | 3972                                                |          | 03-APR-1989<br>4215 |                         |                            |
|                                |                                                                                       |                               |          | 2456                                                |          | 2745                |                         |                            |
| 792160<br>79.090               | NO. 1 ENGINE - COOLER, OIL LOWER RIGHT<br>159910-1<br>SN-UNKNOWN<br>REF: EMM 79-20-09 | MOS<br>HRS/MS<br>ENC<br>(AFL) | O/C      | 3972                                                |          | 03-APR-1989<br>4215 |                         |                            |
|                                |                                                                                       |                               |          | 2456                                                |          | 2745                |                         |                            |
| 792140<br>79.070               | NO. 1 ENGINE - COOLER, OIL UPPER<br>158600-4<br>SN-UNKNOWN<br>REF: EMM 79-20-09       | MOS<br>HRS/MS<br>ENC<br>(AFL) | O/C      | 3972                                                |          | 03-APR-1989<br>4215 |                         |                            |
|                                |                                                                                       |                               |          | 2456                                                |          | 2745                |                         |                            |
| 792110<br>79.040               | NO. 1 ENGINE - PUMP, OIL<br>3071949-7<br>SN-UNKNOWN<br>REF: EMM 79-20-03              | MOS<br>HRS/MS<br>ENC<br>(AFL) | O/C      | 3972                                                |          | 03-APR-1989<br>4215 |                         |                            |
|                                |                                                                                       |                               |          | 2456                                                |          | 2745                |                         |                            |
| 790120<br>79.020<br>ASSOCIATED | NO. 1 ENGINE - CHANGE OIL                                                             | MOS<br>HRS/MS<br>ENC<br>(AFL) | 1400     |                                                     |          | 13-NOV-1999<br>6961 | 8361                    |                            |
|                                | REF: See Workcard                                                                     |                               |          |                                                     |          | 5135                |                         |                            |
| 793120<br>79.120               | NO. 1 ENGINE - SWITCH, OIL PRESSURE<br>3833518<br>SN-UNKNOWN<br>REF: NO REF           | MOS<br>HRS/MS<br>ENC<br>(AFL) | O/C      | 3972                                                |          | 03-APR-1989<br>4215 |                         |                            |
|                                |                                                                                       |                               |          | 2456                                                |          | 2745                |                         |                            |



**Engine Model - TFE731-3**
**Report Date 11-APR-2002**
**Owner Name - R&S AIRCRAFT INVESTMENTS, LLC**  
**A/C Serial #: 368 A/C Reg. #: N368MD**

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT    | INTERVAL | TIME-----AT-----INSTALLATION |     |     |     |     | Warr Exp | COMPLIANCE | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|---------|----------|------------------------------|-----|-----|-----|-----|----------|------------|-------------------------|----------------------------|
|                     |                                                      |         |          | TSN                          | TSO | TSR | TSI | ADJ |          |            |                         |                            |
| 793110              | NO. 1 ENGINE - TRANSMITTER, OIL PRESSURE             |         |          |                              |     |     |     |     |          |            |                         |                            |
| 79.110              | 101-412-80-13                                        | MOS     |          |                              |     |     |     |     |          |            | 03-APR-1989             |                            |
|                     | SN-UNKNOWN                                           | HRS/MSC | O/C      | 3972                         |     |     |     |     |          |            | 4215                    |                            |
|                     | REF: NO REF                                          | ENC     |          |                              |     |     |     |     |          |            |                         |                            |
|                     |                                                      | (AFL)   |          | 2456                         |     |     |     |     |          |            | 2745                    |                            |
| 792120              | NO. 1 ENGINE - VALVE, OIL FILTER BYPASS              |         |          |                              |     |     |     |     |          |            |                         |                            |
| 79.050              | 3070000NP69                                          | MOS     |          |                              |     |     |     |     |          |            | 03-APR-1989             |                            |
|                     | SN-UNKNOWN                                           | HRS/MSC | O/C      | 3972                         |     |     |     |     |          |            | 4215                    |                            |
|                     | REF: EMM 79-30-01                                    | ENC     |          |                              |     |     |     |     |          |            |                         |                            |
|                     |                                                      | (AFL)   |          | 2456                         |     |     |     |     |          |            | 2745                    |                            |
| 792130              | NO. 1 ENGINE - VALVE, PRESSURE BREATHER              |         |          |                              |     |     |     |     |          |            |                         |                            |
| 79.060              | 3071564-8                                            | MOS     |          |                              |     |     |     |     |          |            | 18-MAY-1989             |                            |
|                     | SN-UNKNOWN                                           | HRS/MSC | O/C      |                              |     |     |     |     |          |            | 4215                    |                            |
|                     | REF: EMM 79-20-02                                    | ENC     |          |                              |     |     |     |     |          |            |                         |                            |
|                     |                                                      | (AFL)   |          |                              |     |     |     |     |          |            | 2745                    |                            |



**Engine Model - TFE731-3**
**Report Date 11-APR-2002**
**Owner Name - R&S AIRCRAFT INVESTMENTS, LLC**  
**A/C Serial #: 368 A/C Reg. #: N368MD**

| ITEM NO<br>WORKCARD           | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER  | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|-------------------------------|-------------------------------------------------------|--------|----------|-----------------------------------------------------|----------|------------|-------------------------|----------------------------|
| <b>ENGINE NO. 2</b>           |                                                       |        |          |                                                     |          |            |                         |                            |
| <b>CHAPTER 71 POWER PLANT</b> |                                                       |        |          |                                                     |          |            |                         |                            |
| 710140U                       | NO. 2 ENGINE - -- RUN ADJ/TEST #2 ENG                 | MOS    |          |                                                     |          |            | 31-MAY-1993             |                            |
|                               | REF:                                                  | HRS/MS | C/C      |                                                     |          |            | 5278                    |                            |
|                               |                                                       | ENC    |          |                                                     |          |            |                         |                            |
|                               |                                                       | (AFL)  |          |                                                     |          |            | 3928                    |                            |
| + 714010                      | NO. 2 ENGINE - CHECK ELECTRICAL WIRES AND CONNECTIONS | MOS    |          |                                                     |          |            | 26-JUL-2000             |                            |
| 71.040                        |                                                       | HRS/MS | 800      |                                                     |          |            | 7325                    | 8125                       |
|                               | REF: EMM 72-00-00                                     | ENC    |          |                                                     |          |            |                         |                            |
|                               |                                                       | (AFL)  |          |                                                     |          |            | 5360                    |                            |
| + 715010                      | NO. 2 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS   | MOS    |          |                                                     |          |            | 26-JUL-2000             |                            |
| 71.050                        |                                                       | HRS/MS | 800      |                                                     |          |            | 7325                    | 8125                       |
|                               | REF: EMM 72-00-00                                     | ENC    |          |                                                     |          |            |                         |                            |
|                               |                                                       | (AFL)  |          |                                                     |          |            | 5360                    |                            |
| + 710130                      | NO. 2 ENGINE - INSPECT FAN ROTOR ASSEMBLY BLADES      | MOS    |          |                                                     |          |            | 16-FEB-2001             |                            |
| 71.020                        | PKG 7, 7                                              | HRS/MS | 300      |                                                     |          |            | 7551                    | .5                         |
|                               | REF: EMM 72-00-00                                     | ENC    |          |                                                     |          |            |                         |                            |
|                               |                                                       | (AFL)  |          |                                                     |          |            | 5515                    |                            |
| + 710120                      | NO. 2 ENGINE - MAJOR PERIODIC INSPECTION              | MOS    |          |                                                     |          |            | 17-OCT-1998             |                            |
| 71.010                        |                                                       | HRS/MS | 1400     |                                                     |          |            | 6520                    | 7920                       |
|                               | REF: EMM 72-00-00                                     | ENC    |          |                                                     |          |            |                         |                            |
|                               |                                                       | (AFL)  |          |                                                     |          |            | 4889                    |                            |
| 710110U                       | NO. 2 ENGINE - ENGINE, #2                             | MOS    |          |                                                     |          |            | 31-MAY-1993             |                            |
|                               | 3072500-2                                             | HRS/MS | O/C      | 5227                                                |          |            | 5278                    |                            |
|                               | P77488                                                | ENC    |          |                                                     |          |            |                         |                            |
|                               | REF:                                                  | (AFL)  |          | 3867                                                |          |            | 3928                    |                            |
| <b>CHAPTER 72 ENGINE</b>      |                                                       |        |          |                                                     |          |            |                         |                            |
| + 724120                      | NO. 2 ENGINE - INSPECT COMBUSTION PLENUM CASE         | MOS    |          |                                                     |          |            | 17-SEP-1998             |                            |
| 72.030                        |                                                       | HRS/MS | 1400     |                                                     |          |            | 6520                    | 7920                       |
|                               | REF: EMM 72-40-04                                     | ENC    |          |                                                     |          |            |                         |                            |
|                               |                                                       | (AFL)  |          |                                                     |          |            | 4889                    |                            |
| + 723110                      | NO. 2 ENGINE - INSPECT COMPRESSOR CORE                | MOS    |          |                                                     |          |            | 17-OCT-1998             |                            |
| 72.010                        |                                                       | HRS/MS | 4200     |                                                     |          |            | 6520                    | 10720                      |
|                               | REF: NO REF                                           | ENC    |          |                                                     |          |            |                         |                            |
|                               |                                                       | (AFL)  |          |                                                     |          |            | 4889                    |                            |



Engine Model - TFE731-3

 Report Date **11-APR-2002**

 Owner Name - R&S AIRCRAFT INVESTMENTS, LLC  
 A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO | WORKCARD   | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT                   | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------|------------|------------------------------------------------------|------------------------|----------|-----------------------------------------------------|----------|-------------|-------------------------|----------------------------|
| +       | 727110     | NO. 2 ENGINE - PERIODIC INSPECT FAN SUPPORT ASSEMBLY |                        |          |                                                     |          |             |                         |                            |
|         | 72.300     |                                                      | MOS                    |          |                                                     |          | 17-MAY-1989 |                         |                            |
|         |            | REF: EMM 72-70-06                                    | HRS/MS<br>ENC<br>(AFL) | 4200     |                                                     |          | 4265        | 8465                    |                            |
|         |            |                                                      |                        |          |                                                     |          | 2793        |                         |                            |
| 724110  |            | NO. 2 ENGINE - CASE, COMBUSTION PLENUM               |                        |          |                                                     |          |             |                         |                            |
|         | 72.020     | 3072443-4                                            | MOS                    |          |                                                     |          | 31-MAY-1989 |                         |                            |
|         |            | OP-52337                                             | HRS/MS<br>ENC<br>(AFL) | O/C      | 4215                                                |          | 4265        |                         |                            |
|         |            | REF: NO REF                                          |                        |          |                                                     |          | 2793        |                         |                            |
| +       | 724120     | NO. 2 ENGINE - INSPECT COMBUSTION PLENUM CASE        |                        |          |                                                     |          |             |                         |                            |
|         | 72.030     |                                                      | MOS                    |          |                                                     |          | 17-SEP-1998 |                         |                            |
|         | ASSOCIATED | REF: EMM 72-40-04                                    | HRS/MS<br>ENC<br>(AFL) | 1400     |                                                     |          | 6520        | 7920                    |                            |
|         |            |                                                      |                        |          |                                                     |          | 4889        |                         |                            |
| 725050  |            | NO. 2 ENGINE - DISC, FAN ROTOR                       |                        |          |                                                     |          |             | LIFE LIMIT              |                            |
|         | 72.090     | 3073539-2                                            | MOS                    |          |                                                     |          | 20-MAY-1993 |                         |                            |
|         |            | 0-18040-4768                                         | HRS/MS<br>ENC<br>(AFL) |          | 4087                                                |          | 5278        |                         |                            |
|         |            | REF: NO REF                                          |                        |          |                                                     |          | 3928        | 5368                    |                            |
|         |            |                                                      |                        | 4100     | 2660                                                |          |             | LIFE LIMIT              |                            |
| 725060  |            | NO. 2 ENGINE - DISC, STAGE 1 LOW PRESSURE COMPRESSOR |                        |          |                                                     |          |             |                         |                            |
|         | 72.100     | 3072395                                              | MOS                    |          |                                                     |          | 31-MAY-1989 |                         |                            |
|         |            | 1-12112-1647                                         | HRS/MS<br>ENC<br>(AFL) |          | 4215                                                |          | 4265        |                         |                            |
|         |            | REF: NO REF                                          |                        |          |                                                     |          | 2793        | 10048                   |                            |
|         |            |                                                      |                        | 10000    | 2745                                                |          |             | LIFE LIMIT              |                            |
| 725010  |            | NO. 2 ENGINE - DISC, STAGE 1 LOW PRESSURE TURBINE    |                        |          |                                                     |          |             |                         |                            |
|         | 72.040     | 3072351-5                                            | MOS                    |          |                                                     |          | 20-MAY-1993 |                         |                            |
|         |            | 1-03229-1486                                         | HRS/MS<br>ENC<br>(AFL) |          | 0                                                   |          | 5278        |                         |                            |
|         |            | REF: NO REF                                          |                        |          |                                                     |          | 3928        | 6928                    |                            |
|         |            |                                                      |                        | 3000     | 0                                                   |          |             | LIFE LIMIT              |                            |
| 725070  |            | NO. 2 ENGINE - DISC, STAGE 2 LOW PRESSURE COMPRESSOR |                        |          |                                                     |          |             |                         |                            |
|         | 72.110     | 3072396                                              | MOS                    |          |                                                     |          | 31-MAY-1989 |                         |                            |
|         |            | 1-12112-581                                          | HRS/MS<br>ENC<br>(AFL) |          | 4215                                                |          | 4265        |                         |                            |
|         |            | REF: NO REF                                          |                        |          |                                                     |          | 2793        | 10048                   |                            |
|         |            |                                                      |                        | 10000    | 2745                                                |          |             | LIFE LIMIT              |                            |
| 725020  |            | NO. 2 ENGINE - DISC, STAGE 2 LOW PRESSURE TURBINE    |                        |          |                                                     |          |             |                         |                            |
|         | 72.050     | 3072542-5                                            | MOS                    |          |                                                     |          | 20-MAY-1993 |                         |                            |
|         |            | 1-03229-1277                                         | HRS/MS<br>ENC<br>(AFL) |          | 0                                                   |          | 5278        |                         |                            |
|         |            | REF: NO REF                                          |                        |          |                                                     |          | 3928        | 6928                    |                            |
|         |            |                                                      |                        | 3000     | 0                                                   |          |             | LIFE LIMIT              |                            |
| 725080  |            | NO. 2 ENGINE - DISC, STAGE 3 LOW PRESSURE COMPRESSOR |                        |          |                                                     |          |             |                         |                            |
|         | 72.120     | 3072397                                              | MOS                    |          |                                                     |          | 31-MAY-1989 |                         |                            |
|         |            | 0-12112-1718                                         | HRS/MS<br>ENC<br>(AFL) |          | 4215                                                |          | 4265        |                         |                            |
|         |            | REF: NO REF                                          |                        |          |                                                     |          | 2793        | 10048                   |                            |
|         |            |                                                      |                        | 10000    | 2745                                                |          |             |                         |                            |

 ? - Insufficient Information  
 + Task exists in FAA Manual  
 4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L



**Engine Model - TFE731-3**
**Report Date 11-APR-2002**
**Owner Name - R&S AIRCRAFT INVESTMENTS, LLC**  
**A/C Serial #: 368 A/C Reg. #: N368MD**

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION |     |     |     |     | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|--------|----------|------------------------------|-----|-----|-----|-----|----------|-------------|-------------------------|----------------------------|
|                     |                                                      |        |          | TSN                          | TSO | TSR | TSI | ADJ |          |             |                         |                            |
| 725030              | NO. 2 ENGINE - DISC, STAGE 3 LOW PRESSURE TURBINE    |        |          |                              |     |     |     |     |          |             | LIFE LIMIT              |                            |
| 72.060              | 3072544-2                                            | MOS    |          |                              |     |     |     |     |          | 31-MAY-1989 |                         |                            |
|                     | 6-18040-4905                                         | HRS/MS |          | 0                            |     |     |     |     |          | 4265        |                         |                            |
|                     | REF: NO REF                                          | ENC    |          |                              |     |     |     |     |          |             |                         |                            |
|                     |                                                      | (AFL)  | 3000     | 0                            |     |     |     |     |          | 2793        | 5793                    |                            |
| 725090              | NO. 2 ENGINE - DISC, STAGE 4 LOW PRESSURE COMPRESSOR |        |          |                              |     |     |     |     |          |             | LIFE LIMIT              |                            |
| 72.130              | 3072398                                              | MOS    |          |                              |     |     |     |     |          | 31-MAY-1989 |                         |                            |
|                     | 0-12112-3229                                         | HRS/MS |          | 4215                         |     |     |     |     |          | 4265        |                         |                            |
|                     | REF: NO REF                                          | ENC    |          |                              |     |     |     |     |          |             |                         |                            |
|                     |                                                      | (AFL)  | 10000    | 2745                         |     |     |     |     |          | 2793        | 10048                   |                            |
| 725160              | NO. 2 ENGINE - DUCT, TURBINE INTERSTAGE TRANSITION   |        |          |                              |     |     |     |     |          |             |                         |                            |
| 72.200              | 3072318                                              | MOS    |          |                              |     |     |     |     |          | 31-MAY-1989 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      |                              |     |     |     |     |          | 4265        |                         |                            |
|                     | REF: EMM 72-50-05                                    | ENC    |          |                              |     |     |     |     |          |             |                         |                            |
|                     |                                                      | (AFL)  |          |                              |     |     |     |     |          | 2793        |                         |                            |
| 726110              | NO. 2 ENGINE - GEARBOX, ACCESSORY                    |        |          |                              |     |     |     |     |          |             |                         |                            |
| 72.250              | 3070003-5                                            | MOS    |          |                              |     |     |     |     |          | 31-MAY-1989 |                         |                            |
|                     | P-948                                                | HRS/MS | O/C      | 4215                         |     |     |     |     |          | 4265        |                         |                            |
|                     | REF: EMM 72-60-01                                    | ENC    |          |                              |     |     |     |     |          |             |                         |                            |
|                     |                                                      | (AFL)  |          | 2745                         |     |     |     |     |          | 2793        |                         |                            |
| + 726120            | NO. 2 ENGINE - INSPECT                               |        |          |                              |     |     |     |     |          |             |                         |                            |
| 72.260              |                                                      | MOS    |          |                              |     |     |     |     |          | 17-MAY-1989 |                         |                            |
|                     |                                                      | HRS/MS | 4200     |                              |     |     |     |     |          | 4265        | 8465                    |                            |
|                     | REF: EMM 72-60-02                                    | ENC    |          |                              |     |     |     |     |          |             |                         |                            |
|                     |                                                      | (AFL)  |          |                              |     |     |     |     |          | 2793        |                         |                            |
| 726130              | NO. 2 ENGINE - GEARBOX, TRANSFER                     |        |          |                              |     |     |     |     |          |             |                         |                            |
| 72.270              | 3070093-3                                            | MOS    |          |                              |     |     |     |     |          | 31-MAY-1989 |                         |                            |
|                     | P-3691                                               | HRS/MS | O/C      | 4215                         |     |     |     |     |          | 4265        |                         |                            |
|                     | REF: EMM 72-60-01                                    | ENC    |          |                              |     |     |     |     |          |             |                         |                            |
|                     |                                                      | (AFL)  |          | 2745                         |     |     |     |     |          | 2793        |                         |                            |
| 725110              | NO. 2 ENGINE - IMPELLER, HIGH PRESSURE               |        |          |                              |     |     |     |     |          |             | LIFE LIMIT              |                            |
| 72.150              | 3073394-1                                            | MOS    |          |                              |     |     |     |     |          | 31-MAY-1989 |                         |                            |
|                     | 0-23369-4190                                         | HRS/MS |          | 0                            |     |     |     |     |          | 4265        |                         |                            |
|                     | REF: NO REF                                          | ENC    |          |                              |     |     |     |     |          |             |                         |                            |
|                     |                                                      | (AFL)  | 10000    | 0                            |     |     |     |     |          | 2793        | 12793                   |                            |
| 725180              | NO. 2 ENGINE - NOZZLE, STAGE 1 LOW PRESSURE TURBINE  |        |          |                              |     |     |     |     |          |             |                         |                            |
| 72.220              | 3072319                                              | MOS    |          |                              |     |     |     |     |          | 31-MAY-1989 |                         |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      |                              |     |     |     |     |          | 4265        |                         |                            |
|                     | REF: NO REF                                          | ENC    |          |                              |     |     |     |     |          |             |                         |                            |
|                     |                                                      | (AFL)  |          |                              |     |     |     |     |          | 2793        |                         |                            |
| 725140              | NO. 2 ENGINE - PLATE, HIGH PRESSURE ROTOR SEAL       |        |          |                              |     |     |     |     |          |             | LIFE LIMIT              |                            |
| 72.180              | 3072411-1                                            | MOS    |          |                              |     |     |     |     |          | 31-MAY-1989 |                         |                            |
|                     | 1-18040-5077                                         | HRS/MS |          | 4215                         |     |     |     |     |          | 4265        |                         |                            |
|                     | REF: NO REF                                          | ENC    |          |                              |     |     |     |     |          |             |                         |                            |
|                     |                                                      | (AFL)  | 10000    | 2745                         |     |     |     |     |          | 2793        | 10048                   |                            |



**Engine Model - TFE731-3**
**Report Date 11-APR-2002**
**Owner Name - R&S AIRCRAFT INVESTMENTS, LLC**  
**A/C Serial #: 368 A/C Reg. #: N368MD**

| ITEMNO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER           | UNIT    | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|--------------------|----------------------------------------------------------------|---------|----------|-----------------------------------------------------|----------|-------------|-------------------------|----------------------------|
| 725040             | NO. 2 ENGINE - ROTOR, HIGH PRESSURE TURBINE                    |         |          |                                                     |          |             | LIFE LIMIT              |                            |
| 72.070             | 3072316                                                        | MOS     |          |                                                     |          | 31-MAY-1989 |                         |                            |
|                    | 1-18040-451                                                    | HRS/MSC |          | 4215                                                |          | 4265        |                         |                            |
|                    | REF: EMM 72-50-06                                              | ENC     |          |                                                     |          |             |                         |                            |
|                    | (AFL)                                                          |         | 7000     | 2745                                                |          | 2793        | 7048                    |                            |
| 725170             | NO. 2 ENGINE - SEAL PLATE, STAGE 1 LOW PRESSURE TURBINE        |         |          |                                                     |          |             |                         |                            |
| 72.210             | 3073552                                                        | MOS     |          |                                                     |          | 11-FEB-1982 |                         |                            |
|                    | SN-UNKNOWN                                                     | HRS/MSC | O/C      |                                                     |          | 0           |                         |                            |
|                    | REF: NO REF                                                    | ENC     |          |                                                     |          | 0           |                         |                            |
|                    | (AFL)                                                          |         |          |                                                     |          |             |                         |                            |
| 725190             | NO. 2 ENGINE - SEAL, LOW PRESSURE TURBINE ROTATING AIR         |         |          |                                                     |          |             |                         |                            |
| 72.230             | 3073355                                                        | MOS     |          | 0                                                   |          |             |                         |                            |
|                    | SN-UNKNOWN                                                     | HRS/MSC | O/C      | 0                                                   |          | 0           |                         |                            |
|                    | REF: NO REF                                                    | ENC     |          |                                                     |          |             |                         |                            |
|                    | (AFL)                                                          |         |          | 0                                                   |          | 0           |                         |                            |
| 725120             | NO. 2 ENGINE - SEAL, ROTATING                                  |         |          |                                                     |          |             |                         |                            |
| 72.160             | 3072729-1                                                      | MOS     |          |                                                     |          | 31-MAY-1989 |                         |                            |
|                    | 7-23151-1814                                                   | HRS/MSC | O/C      | 0                                                   |          | 4265        |                         |                            |
|                    | REF: NO REF                                                    | ENC     |          |                                                     |          |             |                         |                            |
|                    | (AFL)                                                          |         |          | 0                                                   |          | 2793        |                         |                            |
| 725150             | NO. 2 ENGINE - SHAFT, FAN DRIVE                                |         |          |                                                     |          |             |                         |                            |
| 72.190             | 3071955-3                                                      | MOS     |          |                                                     |          | 31-MAY-1989 |                         |                            |
|                    | IP-41464                                                       | HRS/MSC | O/C      | 4215                                                |          | 4265        |                         |                            |
|                    | REF: NO REF                                                    | ENC     |          |                                                     |          |             |                         |                            |
|                    | (AFL)                                                          |         |          | 2745                                                |          | 2793        |                         |                            |
| 725130             | NO. 2 ENGINE - SHAFT, HIGH PRESSURE SHOULDERED                 |         |          |                                                     |          |             | LIFE LIMIT              |                            |
| 72.170             | 3072545-1                                                      | MOS     |          |                                                     |          | 31-MAY-1989 |                         |                            |
|                    | 1P-39469                                                       | HRS/MSC |          | 4215                                                |          | 4265        |                         |                            |
|                    | REF: NO REF                                                    | ENC     |          |                                                     |          |             |                         |                            |
|                    | (AFL)                                                          |         | 12000    | 2745                                                |          | 2793        | 12048                   |                            |
| 725191             | NO. 2 ENGINE - SUPPORT, LOW PRESSURE TURBINE ROTATING AIR SEAL |         |          |                                                     |          |             |                         |                            |
| 72.240             | 3073764                                                        | MOS     |          |                                                     |          |             |                         |                            |
|                    | SN-UNKNOWN                                                     | HRS/MSC | O/C      |                                                     |          |             |                         |                            |
|                    | REF: NO REF                                                    | ENC     |          |                                                     |          |             |                         |                            |
|                    | (AFL)                                                          |         |          |                                                     |          |             |                         |                            |
| 725091             | NO. 2 ENGINE - TIE ROD, LOW PRESSURE                           |         |          |                                                     |          |             |                         |                            |
| 72.140             | 3073049-1                                                      | MOS     |          |                                                     |          | 31-MAY-1989 |                         |                            |
|                    | 1P-15412                                                       | HRS/MSC | O/C      | 4215                                                |          | 4265        |                         |                            |
|                    | REF: EMM 72-30-10                                              | ENC     |          |                                                     |          |             |                         |                            |
|                    | (AFL)                                                          |         |          | 2745                                                |          | 2793        |                         |                            |
| <b>CHAPTER 73</b>  | <b>ENGINE FUEL AND CONTROL</b>                                 |         |          |                                                     |          |             |                         |                            |
| + 731120           | NO. 2 ENGINE - REMOVE AND REPLACE FILTER ELEMENT               |         |          |                                                     |          |             |                         |                            |
| 73.020             | PKG 7, 7                                                       | MOS     |          |                                                     |          | 16-FEB-2001 |                         |                            |
|                    |                                                                | HRS/MSC | 300      |                                                     |          | 7551        |                         |                            |
|                    | REF: EMM 73-21-02                                              | ENC     |          |                                                     |          |             |                         |                            |
|                    | (AFL)                                                          |         |          |                                                     |          | 5515        |                         |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L



**Engine Model - TFE731-3**
**Report Date 11-APR-2002**
**Owner Name - R&S AIRCRAFT INVESTMENTS, LLC**  
**A/C Serial #: 368 A/C Reg. #: N368MD**

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|--------|----------|-----------------------------------------------------|----------|------------|-------------------------|----------------------------|
| 732110              | NO. 2 ENGINE - CONTROL UNIT, FUEL                    |        |          |                                                     |          |            |                         |                            |
| 73.060              | 3070800-2                                            | MOS    |          |                                                     |          |            | 31-MAY-1989             |                            |
|                     | A3593PT                                              | HRS/MS | O/C      |                                                     |          | 4265       |                         |                            |
|                     | REF: EMM 73-20-01                                    | ENC    |          |                                                     |          |            |                         |                            |
|                     |                                                      | (AFL)  |          |                                                     |          | 2793       |                         |                            |
| 732120              | NO. 2 ENGINE - CHANGE PRESSURE LIMITER VALVE         |        |          |                                                     |          |            |                         |                            |
| 73.070              | 3070685-4                                            | MOS    |          |                                                     |          |            | 31-MAY-1989             |                            |
| ASSOCIATED          | A6760                                                | HRS/MS | O/C      | 4215                                                |          | 4265       |                         |                            |
|                     | REF: NO REF                                          | ENC    |          |                                                     |          |            |                         |                            |
|                     |                                                      | (AFL)  |          | 2745                                                |          | 2793       |                         |                            |
| 731150              | NO. 2 ENGINE - COOLER, FUEL/OIL                      |        |          |                                                     |          |            |                         |                            |
| 73.050              | 158610-7                                             | MOS    |          |                                                     |          |            | 31-MAY-1989             |                            |
|                     | 21-3736                                              | HRS/MS | O/C      | 4215                                                |          | 4265       |                         |                            |
|                     | REF: EMM 79-20-07                                    | ENC    |          |                                                     |          |            |                         |                            |
|                     |                                                      | (AFL)  |          | 2745                                                |          | 2793       |                         |                            |
| 731140              | NO. 2 ENGINE - HEATER, FUEL                          |        |          |                                                     |          |            |                         |                            |
| 73.040              | 158670-3                                             | MOS    |          |                                                     |          |            | 31-MAY-1989             |                            |
|                     | 71-2903                                              | HRS/MS | O/C      | 4215                                                |          | 4265       |                         |                            |
|                     | REF: EMM 73-10-04                                    | ENC    |          |                                                     |          |            |                         |                            |
|                     |                                                      | (AFL)  |          | 2745                                                |          | 2793       |                         |                            |
| 731110              | NO. 2 ENGINE - PUMP, ENGINE FUEL                     |        |          |                                                     |          |            |                         |                            |
| 73.010              | 3070850-8                                            | MOS    |          |                                                     |          |            | 31-MAY-1989             |                            |
|                     | MX364112                                             | HRS/MS | O/C      | 4215                                                |          | 4265       |                         |                            |
|                     | REF: EMM 73-20-01                                    | ENC    |          |                                                     |          |            |                         |                            |
|                     |                                                      | (AFL)  |          | 2745                                                |          | 2793       |                         |                            |
| + 731120            | NO. 2 ENGINE - REMOVE AND REPLACE FILTER ELEMENT     |        |          |                                                     |          |            |                         |                            |
| 73.020              | PKG 7, 7                                             | MOS    |          |                                                     |          |            | 16-FEB-2001             |                            |
| ASSOCIATED          |                                                      | HRS/MS | 300      |                                                     |          | 7551       |                         |                            |
|                     | REF: EMM 73-21-02                                    | ENC    |          |                                                     |          |            |                         |                            |
|                     |                                                      | (AFL)  |          |                                                     |          | 5515       |                         |                            |
| 732160              | NO. 2 ENGINE - TRANSMITTER, FUEL FLOW                |        |          |                                                     |          |            |                         |                            |
| 73.110              | 883709-1                                             | MOS    |          |                                                     |          |            | 31-MAY-1989             |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 4215                                                |          | 4265       |                         |                            |
|                     | REF: NO REF                                          | ENC    |          |                                                     |          |            |                         |                            |
|                     |                                                      | (AFL)  |          | 2745                                                |          | 2793       |                         |                            |
| 731130              | NO. 2 ENGINE - VALVE, FLOW DIVIDER/DRAIN             |        |          |                                                     |          |            |                         |                            |
| 73.030              | 394366-4                                             | MOS    |          |                                                     |          |            | 31-MAY-1989             |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 4215                                                |          | 4265       |                         |                            |
|                     | REF: NO REF                                          | ENC    |          |                                                     |          |            |                         |                            |
|                     |                                                      | (AFL)  |          | 2745                                                |          | 2793       |                         |                            |
| 732110              | NO. 2 ENGINE - CHANGE FUEL CONTROL UNIT              |        |          |                                                     |          |            |                         |                            |
| 73.060              | 3070800-2                                            | MOS    |          |                                                     |          |            | 31-MAY-1989             |                            |
| ASSOCIATED          | A3593PT                                              | HRS/MS | O/C      |                                                     |          | 4265       |                         |                            |
|                     | REF: EMM 73-20-01                                    | ENC    |          |                                                     |          |            |                         |                            |
|                     |                                                      | (AFL)  |          |                                                     |          | 2793       |                         |                            |



**Engine Model - TFE731-3**
**Report Date 11-APR-2002**
**Owner Name - R&S AIRCRAFT INVESTMENTS, LLC**
**A/C Serial #: 368 A/C Reg. #: N368MD**

| ITEM NO<br>WORKCARD        | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION |     |     |     |     | COMPLIANCE | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|----------------------------|------------------------------------------------------|--------|----------|------------------------------|-----|-----|-----|-----|------------|-------------------------|----------------------------|
|                            |                                                      |        |          | TSN                          | TSO | TSR | TSI | ADJ |            |                         |                            |
| 732120                     | NO. 2 ENGINE - CHANGE PRESSURE LIMITER VALVE         |        |          |                              |     |     |     |     |            |                         |                            |
| 73.070                     | 3070685-4                                            | MOS    |          |                              |     |     |     |     |            | 31-MAY-1989             |                            |
| ASSOCIATED                 | A6760                                                | HRS/MS | O/C      | 4215                         |     |     |     |     |            | 4265                    |                            |
|                            | REF: NO REF                                          | ENC    |          |                              |     |     |     |     |            |                         |                            |
|                            | (AFL)                                                |        |          | 2745                         |     |     |     |     |            | 2793                    |                            |
| 732120                     | NO. 2 ENGINE - VALVE, PRESSURE LIMITER               |        |          |                              |     |     |     |     |            |                         |                            |
| 73.070                     | 3070685-4                                            | MOS    |          |                              |     |     |     |     |            | 31-MAY-1989             |                            |
|                            | A6760                                                | HRS/MS | O/C      | 4215                         |     |     |     |     |            | 4265                    |                            |
|                            | REF: NO REF                                          | ENC    |          |                              |     |     |     |     |            |                         |                            |
|                            | (AFL)                                                |        |          | 2745                         |     |     |     |     |            | 2793                    |                            |
| 732140                     | NO. 2 ENGINE - VALVE, SOLENOID CONTROL               |        |          |                              |     |     |     |     |            |                         |                            |
| 73.090                     | 109696-3-1                                           | MOS    |          |                              |     |     |     |     |            | 31-MAY-1989             |                            |
|                            | P-3683                                               | HRS/MS | O/C      | 4215                         |     |     |     |     |            | 4265                    |                            |
|                            | REF: EMM 76-10-01                                    | ENC    |          |                              |     |     |     |     |            |                         |                            |
|                            | (AFL)                                                |        |          | 2745                         |     |     |     |     |            | 2793                    |                            |
| 732130                     | NO. 2 ENGINE - VALVE, SURGE BLEED                    |        |          |                              |     |     |     |     |            |                         |                            |
| 73.080                     | 978812-4-1                                           | MOS    |          |                              |     |     |     |     |            | 31-MAY-1989             |                            |
|                            | P-3683                                               | HRS/MS | O/C      | 4215                         |     |     |     |     |            | 4265                    |                            |
|                            | REF: EMM 76-10-01                                    | ENC    |          |                              |     |     |     |     |            |                         |                            |
|                            | (AFL)                                                |        |          | 2745                         |     |     |     |     |            | 2793                    |                            |
| <b>CHAPTER 74 IGNITION</b> |                                                      |        |          |                              |     |     |     |     |            |                         |                            |
| + 742120                   | NO. 2 ENGINE - INSPECT 6 O'CLOCK IGNITER PLUG        |        |          |                              |     |     |     |     |            |                         |                            |
| 74.040                     |                                                      | MOS    |          |                              |     |     |     |     |            | 26-JUL-2000             |                            |
|                            |                                                      | HRS/MS | 800      |                              |     |     |     |     |            | 7325                    | 8125                       |
|                            | REF: EMM 74-00-01                                    | ENC    |          |                              |     |     |     |     |            |                         |                            |
|                            | (AFL)                                                |        |          |                              |     |     |     |     |            | 5360                    |                            |
| + 742140                   | NO. 2 ENGINE - INSPECT 7 O'CLOCK IGNITER PLUG        |        |          |                              |     |     |     |     |            |                         |                            |
| 74.060                     |                                                      | MOS    |          |                              |     |     |     |     |            | 26-JUL-2000             |                            |
|                            |                                                      | HRS/MS | 800      |                              |     |     |     |     |            | 7325                    | 8125                       |
|                            | REF: EMM 74-00-01                                    | ENC    |          |                              |     |     |     |     |            |                         |                            |
|                            | (AFL)                                                |        |          |                              |     |     |     |     |            | 5360                    |                            |
| + 741120                   | NO. 2 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM     |        |          |                              |     |     |     |     |            |                         |                            |
| 74.020                     |                                                      | MOS    |          |                              |     |     |     |     |            | 26-JUL-2000             |                            |
|                            |                                                      | HRS/MS | 800      |                              |     |     |     |     |            | 7325                    | 8125                       |
|                            | REF: EMM 74-00-01                                    | ENC    |          |                              |     |     |     |     |            |                         | 1                          |
|                            | (AFL)                                                |        |          |                              |     |     |     |     |            | 5360                    |                            |
| 742110                     | NO. 2 ENGINE - IGNITER PLUG, 6 O'CLOCK               |        |          |                              |     |     |     |     |            |                         |                            |
| 74.030                     | 3071589-2                                            | MOS    |          |                              |     |     |     |     |            | 17-OCT-1998             |                            |
|                            | SN-UNKNOWN                                           | HRS/MS | O/C      |                              |     |     |     |     |            | 6520                    |                            |
|                            | REF: EMM 72-00-00                                    | ENC    |          |                              |     |     |     |     |            |                         |                            |
|                            | (AFL)                                                |        |          |                              |     |     |     |     |            | 4889                    |                            |
| + 742120                   | NO. 2 ENGINE - INSPECT 6 O'CLOCK IGNITER PLUG        |        |          |                              |     |     |     |     |            |                         |                            |
| 74.040                     |                                                      | MOS    |          |                              |     |     |     |     |            | 26-JUL-2000             |                            |
| ASSOCIATED                 |                                                      | HRS/MS | 800      |                              |     |     |     |     |            | 7325                    | 8125                       |
|                            | REF: EMM 74-00-01                                    | ENC    |          |                              |     |     |     |     |            |                         |                            |
|                            | (AFL)                                                |        |          |                              |     |     |     |     |            | 5360                    |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L



**Engine Model - TFE731-3**
**Report Date 11-APR-2002**
**Owner Name - R&S AIRCRAFT INVESTMENTS, LLC**
**A/C Serial #: 368 A/C Reg. #: N368MD**

| ITEM NO<br>WORKCARD                 | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION |     |     |     |     | COMPLIANCE | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|-------------------------------------|------------------------------------------------------|--------|----------|------------------------------|-----|-----|-----|-----|------------|-------------------------|----------------------------|
|                                     |                                                      |        |          | TSN                          | TSO | TSR | TSI | ADJ |            |                         |                            |
| 742130                              | NO. 2 ENGINE - IGNITER PLUG, 7 O'CLOCK               |        |          |                              |     |     |     |     |            |                         |                            |
| 74.050                              | 3071589-2                                            | MOS    |          |                              |     |     |     |     |            | 09-NOV-1996             |                            |
|                                     | SN-UNKNOWN                                           | HRSMSC | O/C      |                              |     |     |     |     |            | 5951                    |                            |
|                                     | REF: EMM 72-00-00                                    | ENC    |          |                              |     |     |     |     |            |                         |                            |
|                                     |                                                      | (AFL)  |          |                              |     |     |     |     |            | 4589                    |                            |
| + 742140                            | NO. 2 ENGINE - INSPECT 7 O'CLOCK IGNITER PLUG        |        |          |                              |     |     |     |     |            |                         |                            |
| 74.060                              |                                                      | MOS    |          |                              |     |     |     |     |            | 26-JUL-2000             |                            |
| ASSOCIATED                          |                                                      | HRSMSC | 800      |                              |     |     |     |     |            | 7325                    | 8125                       |
|                                     | REF: EMM 74-00-01                                    | ENC    |          |                              |     |     |     |     |            |                         |                            |
|                                     |                                                      | (AFL)  |          |                              |     |     |     |     |            | 5360                    |                            |
| 741110                              | NO. 2 ENGINE - UNIT, IGNITION                        |        |          |                              |     |     |     |     |            |                         |                            |
| 74.010                              | 3070378-2                                            | MOS    |          |                              |     |     |     |     |            | 31-MAY-1989             |                            |
|                                     | SN-UNKNOWN                                           | HRSMSC | O/C      | 1142                         |     |     |     |     |            | 4265                    |                            |
|                                     | REF: EMM 72-00-00                                    | ENC    |          |                              |     |     |     |     |            |                         |                            |
|                                     |                                                      | (AFL)  |          |                              |     |     |     |     |            | 2793                    |                            |
| + 741120                            | NO. 2 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM     |        |          |                              |     |     |     |     |            |                         |                            |
| 74.020                              |                                                      | MOS    |          |                              |     |     |     |     |            | 26-JUL-2000             |                            |
| ASSOCIATED                          |                                                      | HRSMSC | 800      |                              |     |     |     |     |            | 7325                    | 8125                       |
|                                     | REF: EMM 74-00-01                                    | ENC    |          |                              |     |     |     |     |            |                         | 1                          |
|                                     |                                                      | (AFL)  |          |                              |     |     |     |     |            | 5360                    |                            |
| <b>CHAPTER 75 AIR</b>               |                                                      |        |          |                              |     |     |     |     |            |                         |                            |
| 751010                              | NO. 2 ENGINE - VALVE, ANTI-ICE SHUTOFF               |        |          |                              |     |     |     |     |            |                         |                            |
| 75.010                              | 978944-1-1                                           | MOS    |          |                              |     |     |     |     |            | 31-MAY-1989             |                            |
|                                     | SN-UNKNOWN                                           | HRSMSC | O/C      | 4215                         |     |     |     |     |            | 4265                    |                            |
|                                     | REF: EMM 75-10-01                                    | ENC    |          |                              |     |     |     |     |            |                         |                            |
|                                     |                                                      | (AFL)  |          |                              |     |     |     |     |            | 2793                    |                            |
| <b>CHAPTER 77 ENGINE INDICATING</b> |                                                      |        |          |                              |     |     |     |     |            |                         |                            |
| 772110                              | NO. 2 ENGINE - HARNESS, ITT THERMOCOUPLE             |        |          |                              |     |     |     |     |            |                         |                            |
| 77.030                              | 3071849-3                                            | MOS    |          |                              |     |     |     |     |            | 31-MAY-1989             |                            |
|                                     | 9-20219-358                                          | HRSMSC | O/C      |                              |     |     |     |     |            | 4265                    |                            |
|                                     | REF: EMM 77-20-01                                    | ENC    |          |                              |     |     |     |     |            |                         |                            |
|                                     |                                                      | (AFL)  |          |                              |     |     |     |     |            | 2793                    |                            |
| 771120                              | NO. 2 ENGINE - TRANSDUCER, HIGH PRESSURE (N2)        |        |          |                              |     |     |     |     |            |                         |                            |
| 77.020                              | 3070722-2                                            | MOS    |          |                              |     |     |     |     |            | 31-MAY-1989             |                            |
|                                     | SN-UNKNOWN                                           | HRSMSC | O/C      | 4215                         |     |     |     |     |            | 4265                    |                            |
|                                     | REF: EMM 77-10-05                                    | ENC    |          |                              |     |     |     |     |            |                         |                            |
|                                     |                                                      | (AFL)  |          |                              |     |     |     |     |            | 2793                    |                            |
| 771110                              | NO. 2 ENGINE - TRANSDUCER, LOW PRESSURE (N1)         |        |          |                              |     |     |     |     |            |                         |                            |
| 77.010                              | 3071928-5                                            | MOS    |          |                              |     |     |     |     |            | 31-MAY-1989             |                            |
|                                     | SN-UNKNOWN                                           | HRSMSC | O/C      | 4215                         |     |     |     |     |            | 4265                    |                            |
|                                     | REF: EMM 77-10-03                                    | ENC    |          |                              |     |     |     |     |            |                         |                            |
|                                     |                                                      | (AFL)  |          |                              |     |     |     |     |            | 2793                    |                            |
| <b>CHAPTER 79 OIL</b>               |                                                      |        |          |                              |     |     |     |     |            |                         |                            |



**Engine Model - TFE731-3**
**Report Date 11-APR-2002**
**Owner Name - R&S AIRCRAFT INVESTMENTS, LLC**  
**A/C Serial #: 368 A/C Reg. #: N368MD**

| ITEM NO<br>WORKCARD            | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER                                  | UNIT                           | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE          | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|--------------------------------|---------------------------------------------------------------------------------------|--------------------------------|----------|-----------------------------------------------------|----------|---------------------|-------------------------|----------------------------|
| + 790110<br>79.010             | NO. 2 ENGINE - ANALYZE ENGINE OIL<br>PKG 5, 5, 7, 7                                   | MOS<br>HRS/MSC<br>ENC<br>(AFL) | 150      |                                                     |          | 26-JUN-2001<br>7687 |                         | 1                          |
|                                | REF: EMM 72-00-00                                                                     |                                |          |                                                     |          | 5594                |                         |                            |
| 790120<br>79.020               | NO. 2 ENGINE - CHANGE OIL                                                             | MOS<br>HRS/MSC<br>ENC<br>(AFL) | 1400     |                                                     |          | 17-OCT-1998<br>6520 | 7920                    |                            |
|                                | REF: See Workcard                                                                     |                                |          |                                                     |          | 4889                |                         |                            |
| + 790130<br>79.030             | NO. 2 ENGINE - INSPECT CHIP DETECTOR<br>PKG 5, 5, 7, 7                                | MOS<br>HRS/MSC<br>ENC<br>(AFL) | 150      |                                                     |          | 26-JUN-2001<br>7687 |                         |                            |
|                                | REF: EMM 72-00-00                                                                     |                                |          |                                                     |          | 5594                |                         |                            |
| 792150<br>79.080               | NO. 2 ENGINE - COOLER, OIL LOWER LEFT<br>159900-1<br>SN-UNKNOWN<br>REF: EMM 79-20-09  | MOS<br>HRS/MSC<br>ENC<br>(AFL) | O/C      |                                                     |          | 31-MAY-1989<br>4265 |                         |                            |
|                                |                                                                                       |                                |          |                                                     |          | 2793                |                         |                            |
| 792160<br>79.090               | NO. 2 ENGINE - COOLER, OIL LOWER RIGHT<br>159910-1<br>SN-UNKNOWN<br>REF: EMM 79-20-09 | MOS<br>HRS/MSC<br>ENC<br>(AFL) | O/C      | 4215                                                |          | 31-MAY-1989<br>4265 |                         |                            |
|                                |                                                                                       |                                |          |                                                     |          | 2793                |                         |                            |
| 792140<br>79.070               | NO. 2 ENGINE - COOLER, OIL UPPER<br>158600-4<br>SN-UNKNOWN<br>REF: EMM 79-20-09       | MOS<br>HRS/MSC<br>ENC<br>(AFL) | O/C      | 4215                                                |          | 31-MAY-1989<br>4265 |                         |                            |
|                                |                                                                                       |                                |          |                                                     |          | 2793                |                         |                            |
| 792110<br>79.040               | NO. 2 ENGINE - PUMP, OIL<br>3071949-7<br>0683<br>REF: EMM 79-20-03                    | MOS<br>HRS/MSC<br>ENC<br>(AFL) | O/C      |                                                     |          | 31-MAY-1989<br>4265 |                         |                            |
|                                |                                                                                       |                                |          |                                                     |          | 2793                |                         |                            |
| 790120<br>79.020<br>ASSOCIATED | NO. 2 ENGINE - CHANGE OIL                                                             | MOS<br>HRS/MSC<br>ENC<br>(AFL) | 1400     |                                                     |          | 17-OCT-1998<br>6520 | 7920                    |                            |
|                                | REF: See Workcard                                                                     |                                |          |                                                     |          | 4889                |                         |                            |
| 793120<br>79.120               | NO. 2 ENGINE - SWITCH, OIL PRESSURE<br>3-833518<br>1041<br>REF: NO REF                | MOS<br>HRS/MSC<br>ENC<br>(AFL) | O/C      | 482                                                 |          | 31-MAY-1989<br>4265 |                         |                            |
|                                |                                                                                       |                                |          |                                                     |          | 2793                |                         |                            |

? - Insufficient Information  
+ Task exists in FAA Manual  
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL



**Engine Model - TFE731-3**
**Report Date 11-APR-2002**
**Owner Name - R&S AIRCRAFT INVESTMENTS, LLC**  
**A/C Serial #: 368 A/C Reg. #: N368MD**

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION |     |     |     |     | Warr Exp | COMPLIANCE | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|--------|----------|------------------------------|-----|-----|-----|-----|----------|------------|-------------------------|----------------------------|
|                     |                                                      |        |          | TSN                          | TSO | TSR | TSI | ADJ |          |            |                         |                            |
| 793110              | NO. 2 ENGINE - TRANSMITTER, OIL PRESSURE             |        |          |                              |     |     |     |     |          |            |                         |                            |
| 79.110              | 101-412-80-13                                        | MOS    |          |                              |     |     |     |     |          |            | 31-MAY-1989             |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 4215                         |     |     |     |     |          |            | 4265                    |                            |
|                     | REF: NO REF                                          | ENC    |          |                              |     |     |     |     |          |            |                         |                            |
|                     |                                                      | (AFL)  |          |                              |     |     |     |     |          |            | 2793                    |                            |
| 792120              | NO. 2 ENGINE - VALVE, OIL FILTER BYPASS              |        |          |                              |     |     |     |     |          |            |                         |                            |
| 79.050              | 3070000NP69                                          | MOS    |          |                              |     |     |     |     |          |            | 31-MAY-1989             |                            |
|                     | SN-UNKNOWN                                           | HRS/MS | O/C      | 4215                         |     |     |     |     |          |            | 4265                    |                            |
|                     | REF: EMM 79-30-01                                    | ENC    |          |                              |     |     |     |     |          |            |                         |                            |
|                     |                                                      | (AFL)  |          |                              |     |     |     |     |          |            | 2793                    |                            |
| 792130              | NO. 2 ENGINE - VALVE, PRESSURE BREATHER              |        |          |                              |     |     |     |     |          |            |                         |                            |
| 79.060              | 3075323-1                                            | MOS    |          |                              |     |     |     |     |          |            | 04-FEB-1994             |                            |
|                     | 6376                                                 | HRS/MS | O/C      |                              | 0   |     |     |     |          |            | 5390                    |                            |
|                     | REF: EMM 79-20-02                                    | ENC    |          |                              |     |     |     |     |          |            |                         |                            |
|                     |                                                      | (AFL)  |          |                              |     |     |     |     |          |            | 4040                    |                            |



Aircraft Model - 1124 WESTWIND  
 Owner Name - R&S AIRCRAFT INVESTMENTS, LLC  
 A/C Serial #: 368 A/C Reg. #: N368MD

Report Date **11-APR-2002**

| ITEM NO<br>WORKCARD          | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER                                                                                                                                                                                        | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|----------|-----------------------------------------------------|----------|-------------|-------------------------|----------------------------|
| <b>AIRCRAFT</b>              |                                                                                                                                                                                                                                             |        |          |                                                     |          |             |                         |                            |
| AD 1974-08-09 R2             | AIRWORTHINESS DIRECTIVE TO PREVENT POSSIBLE FIRES THAT COULD RESULT FROM SMOKING MATERIALS BEING DROPPED INTO LAVATORY PAPER OR LINEN WASTE RECEPTACLES                                                                                     |        |          |                                                     |          |             |                         | F4                         |
|                              |                                                                                                                                                                                                                                             | MOS    |          |                                                     |          | 17-JAN-2001 |                         |                            |
|                              |                                                                                                                                                                                                                                             | HRS/MS | 1000     |                                                     |          | 7494        | 8494                    |                            |
|                              |                                                                                                                                                                                                                                             | AFL    |          |                                                     |          | 5466        |                         |                            |
|                              | REF:                                                                                                                                                                                                                                        |        |          |                                                     |          |             |                         |                            |
|                              | Method of Compliance: OPEN                                                                                                                                                                                                                  |        |          |                                                     |          |             |                         |                            |
| AD 1989-12-08                | AIRWORTHINESS DIRECTIVE TO DETECT CRACKS IN THE HINGE LUGS OF THE HORIZONTAL STABILIZER AFT SPAR SPLICE FITTING (HINGE ASSEMBLY)                                                                                                            |        |          |                                                     |          |             |                         |                            |
|                              |                                                                                                                                                                                                                                             | MOS    |          |                                                     |          | 17-JAN-2001 |                         |                            |
|                              |                                                                                                                                                                                                                                             | HRS/MS | 300      |                                                     |          | 7494        | 7794                    |                            |
|                              |                                                                                                                                                                                                                                             | AFL    |          |                                                     |          | 5466        |                         |                            |
|                              | REF: See Workcard                                                                                                                                                                                                                           |        |          |                                                     |          |             |                         |                            |
|                              | Method of Compliance: OPEN                                                                                                                                                                                                                  |        |          |                                                     |          |             |                         |                            |
| AD 1998-24-11 LEFT AILERON   | AIRWORTHINESS DIRECTIVE TO PREVENT EXCESSIVE WEAR OF THE AILERON PUSH-PULL TUBE, WHICH COULD RESULT IN UNEVEN MOVEMENT OF THE CONTROL WHEEL, PERFORATION OF THE AILERON PUSH-PULL TUBE, AND CONSEQUENT REDUCED ROLL CONTROL OF THE AIRPLANE |        |          |                                                     |          |             |                         | W1                         |
|                              |                                                                                                                                                                                                                                             | MOS    |          |                                                     |          | 26-JUL-2000 |                         |                            |
|                              |                                                                                                                                                                                                                                             | HRS/MS | 600      |                                                     |          | 7325        | 7925                    |                            |
|                              |                                                                                                                                                                                                                                             | AFL    |          |                                                     |          | 5360        |                         |                            |
|                              | REF: AD                                                                                                                                                                                                                                     |        |          |                                                     |          |             |                         |                            |
|                              | Method of Compliance: OPEN                                                                                                                                                                                                                  |        |          |                                                     |          |             |                         |                            |
| SB 1124-27-129 LEFT AILERON  | FLIGHT CONTROLS SERVICE BULLETIN                                                                                                                                                                                                            |        |          |                                                     |          |             |                         | W1                         |
|                              |                                                                                                                                                                                                                                             | MOS    |          |                                                     |          | 26-JUL-2000 |                         |                            |
| ASSOCIATED                   |                                                                                                                                                                                                                                             | HRS/MS | 600      |                                                     |          | 7325        | 7925                    |                            |
|                              |                                                                                                                                                                                                                                             | AFL    |          |                                                     |          | 5360        |                         |                            |
|                              | REF: BULLETINS                                                                                                                                                                                                                              |        |          |                                                     |          |             |                         |                            |
|                              | Method of Compliance: OPEN                                                                                                                                                                                                                  |        |          |                                                     |          |             |                         |                            |
| AD 1996-24-11 RIGHT AILERON  | AIRWORTHINESS DIRECTIVE TO PREVENT EXCESSIVE WEAR OF THE AILERON PUSH-PULL TUBE, WHICH COULD RESULT IN UNEVEN MOVEMENT OF THE CONTROL WHEEL, PERFORATION OF THE AILERON PUSH-PULL TUBE, AND CONSEQUENT REDUCED ROLL CONTROL OF THE AIRPLANE |        |          |                                                     |          |             |                         | W2                         |
|                              |                                                                                                                                                                                                                                             | MOS    |          |                                                     |          | 26-JUL-2000 |                         |                            |
|                              |                                                                                                                                                                                                                                             | HRS/MS | 600      |                                                     |          | 7325        | 7925                    |                            |
|                              |                                                                                                                                                                                                                                             | AFL    |          |                                                     |          | 5360        |                         |                            |
|                              | REF: AD                                                                                                                                                                                                                                     |        |          |                                                     |          |             |                         |                            |
|                              | Method of Compliance: OPEN                                                                                                                                                                                                                  |        |          |                                                     |          |             |                         |                            |
| SB 1124-27-129 RIGHT AILERON | FLIGHT CONTROLS SERVICE BULLETIN                                                                                                                                                                                                            |        |          |                                                     |          |             |                         | W2                         |
|                              |                                                                                                                                                                                                                                             | MOS    |          |                                                     |          | 26-JUL-2000 |                         |                            |
| ASSOCIATED                   |                                                                                                                                                                                                                                             | HRS/MS | 600      |                                                     |          | 7325        | 7925                    |                            |
|                              |                                                                                                                                                                                                                                             | AFL    |          |                                                     |          | 5360        |                         |                            |
|                              | REF: BULLETINS                                                                                                                                                                                                                              |        |          |                                                     |          |             |                         |                            |
|                              | Method of Compliance: OPEN                                                                                                                                                                                                                  |        |          |                                                     |          |             |                         |                            |
| AD 1998-06-10                | AIRWORTHINESS DIRECTIVE TO PREVENT FAILURE OF THE HYDRAULIC FUSE TO OPERATE PROPERLY IN THE EVENT OF AN EXTERNAL LEAK DOWNSTREAM OF THE FUSE, WHICH COULD RESULT IN LOSS OF HYDRAULIC SYSTEMS                                               |        |          |                                                     |          |             |                         |                            |
|                              |                                                                                                                                                                                                                                             | MOS    | 36       |                                                     |          | 06-NOV-2001 | 06-NOV-2004             |                            |
|                              |                                                                                                                                                                                                                                             | HRS/MS | 1200     |                                                     |          | 7774        | 8974                    |                            |
|                              |                                                                                                                                                                                                                                             | AFL    |          |                                                     |          | 5641        |                         |                            |
|                              | REF: AD                                                                                                                                                                                                                                     |        |          |                                                     |          |             |                         |                            |
|                              | Method of Compliance: OPEN                                                                                                                                                                                                                  |        |          |                                                     |          |             |                         |                            |



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&amp;S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD          | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER                                                                                                                                                                     | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION |     |     |     |     | COMPLIANCE  | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|----------|------------------------------|-----|-----|-----|-----|-------------|-------------------------|----------------------------|
|                              |                                                                                                                                                                                                                          |        |          | TSN                          | TSO | TSR | TSI | ADJ |             |                         |                            |
| AD 2002-01-26                | AIRWORTHINESS DIRECTIVE TO PREVENT FAILURE OF ATTACHMENT BOLTS DUE TO FATIGUE, WHICH COULD RESULT IN SEPARATION OF THE ENGINE INLET COWL AND AFT NACELLE, AND CONSEQUENT DAMAGE TO THE HORIZONTAL OR VERTICAL STABILIZER |        |          |                              |     |     |     |     |             | MANDATORY               |                            |
|                              |                                                                                                                                                                                                                          | MOS    |          |                              |     |     |     |     |             |                         |                            |
|                              |                                                                                                                                                                                                                          | HRS/MS | DUE      |                              |     |     |     |     |             | 50                      |                            |
|                              |                                                                                                                                                                                                                          | AFL    |          |                              |     |     |     |     |             |                         |                            |
|                              | REF:                                                                                                                                                                                                                     |        |          |                              |     |     |     |     |             |                         |                            |
|                              | Method of Compliance:                                                                                                                                                                                                    | OPEN   |          |                              |     |     |     |     |             |                         |                            |
| SB ASB1124-54A-138           | SERVICE BULLETIN                                                                                                                                                                                                         |        |          |                              |     |     |     |     |             | MANDATORY               |                            |
|                              |                                                                                                                                                                                                                          | MOS    |          |                              |     |     |     |     |             |                         |                            |
| ASSOCIATED                   |                                                                                                                                                                                                                          | HRS/MS | A/R      |                              |     |     |     |     |             |                         |                            |
|                              |                                                                                                                                                                                                                          | AFL    |          |                              |     |     |     |     |             |                         |                            |
|                              | REF:                                                                                                                                                                                                                     |        |          |                              |     |     |     |     |             |                         |                            |
|                              | Method of Compliance:                                                                                                                                                                                                    | OPEN   |          |                              |     |     |     |     |             |                         |                            |
| SB 1124-27-129 LEFT AILERON  | SERVICE BULLETIN FLIGHT CONTROLS                                                                                                                                                                                         |        |          |                              |     |     |     |     |             |                         | W1                         |
|                              |                                                                                                                                                                                                                          | MOS    |          |                              |     |     |     |     | 26-JUL-2000 |                         |                            |
|                              |                                                                                                                                                                                                                          | HRS/MS | 600      |                              |     |     |     |     | 7325        | 7925                    |                            |
|                              |                                                                                                                                                                                                                          | AFL    |          |                              |     |     |     |     | 5360        |                         |                            |
|                              | REF: BULLETINS                                                                                                                                                                                                           |        |          |                              |     |     |     |     |             |                         |                            |
|                              | Method of Compliance:                                                                                                                                                                                                    | OPEN   |          |                              |     |     |     |     |             |                         |                            |
| SB 1124-27-129 RIGHT AILERON | SERVICE BULLETIN FLIGHT CONTROLS                                                                                                                                                                                         |        |          |                              |     |     |     |     |             |                         | W2                         |
|                              |                                                                                                                                                                                                                          | MOS    |          |                              |     |     |     |     | 26-JUL-2000 |                         |                            |
|                              |                                                                                                                                                                                                                          | HRS/MS | 600      |                              |     |     |     |     | 7325        | 7925                    |                            |
|                              |                                                                                                                                                                                                                          | AFL    |          |                              |     |     |     |     | 5360        |                         |                            |
|                              | REF: BULLETINS                                                                                                                                                                                                           |        |          |                              |     |     |     |     |             |                         |                            |
|                              | Method of Compliance:                                                                                                                                                                                                    | OPEN   |          |                              |     |     |     |     |             |                         |                            |
| SB 1124-30-036 PART II       | SERVICE BULLETIN ICE AND RAIN PROTECTION                                                                                                                                                                                 |        |          |                              |     |     |     |     |             |                         | F3                         |
|                              | PKG 1, 2, 3                                                                                                                                                                                                              | MOS    |          |                              |     |     |     |     | 26-JUN-2001 |                         |                            |
|                              |                                                                                                                                                                                                                          | HRS/MS | 150      |                              |     |     |     |     | 7687        | 7837                    |                            |
|                              |                                                                                                                                                                                                                          | AFL    |          |                              |     |     |     |     | 5594        |                         |                            |
|                              | REF: See Workcard                                                                                                                                                                                                        |        |          |                              |     |     |     |     |             |                         |                            |
|                              | Method of Compliance:                                                                                                                                                                                                    | OPEN   |          |                              |     |     |     |     |             |                         |                            |
| SB 1124-32-139 UPPER         | SERVICE BULLETIN LANDING GEAR                                                                                                                                                                                            |        |          |                              |     |     |     |     |             |                         |                            |
|                              | PKG 3                                                                                                                                                                                                                    | MOS    |          |                              |     |     |     |     | 26-JUL-2000 |                         |                            |
|                              |                                                                                                                                                                                                                          | HRS/MS | 800      |                              |     |     |     |     | 7325        | 8125                    |                            |
|                              |                                                                                                                                                                                                                          | AFL    |          |                              |     |     |     |     | 5360        |                         |                            |
|                              | REF:                                                                                                                                                                                                                     |        |          |                              |     |     |     |     |             |                         |                            |
|                              | Method of Compliance:                                                                                                                                                                                                    | OPEN   |          |                              |     |     |     |     |             |                         |                            |
| SB 1124-55-020 R2            | SERVICE BULLETIN STABILIZERS                                                                                                                                                                                             |        |          |                              |     |     |     |     |             |                         | T1                         |
|                              | PKG 2, 3                                                                                                                                                                                                                 | MOS    |          |                              |     |     |     |     | 26-JUN-2001 |                         |                            |
|                              |                                                                                                                                                                                                                          | HRS/MS | 300      |                              |     |     |     |     | 7687        | 7987                    |                            |
|                              |                                                                                                                                                                                                                          | AFL    |          |                              |     |     |     |     | 5594        |                         |                            |
|                              | REF: See Workcard                                                                                                                                                                                                        |        |          |                              |     |     |     |     |             |                         |                            |
|                              | Method of Compliance:                                                                                                                                                                                                    | OPEN   |          |                              |     |     |     |     |             |                         |                            |
| SB 900280                    | SERVICE BULLETIN SB WW 24-28A                                                                                                                                                                                            |        |          |                              |     |     |     |     |             |                         | L3                         |
|                              |                                                                                                                                                                                                                          | MOS    |          |                              |     |     |     |     | 22-FEB-2000 |                         |                            |
|                              |                                                                                                                                                                                                                          | HRS/MS | 1200     |                              |     |     |     |     | 7107        |                         |                            |
|                              |                                                                                                                                                                                                                          | AFL    |          |                              |     |     |     |     | 5232        |                         |                            |
|                              | REF: See Workcard                                                                                                                                                                                                        |        |          |                              |     |     |     |     |             |                         |                            |
|                              | Method of Compliance:                                                                                                                                                                                                    | OPEN   |          |                              |     |     |     |     |             |                         |                            |
| SB 972850U                   | SERVICE BULLETIN SB 731-A72-3668 #1 ENG                                                                                                                                                                                  |        |          |                              |     |     |     |     |             | RECOMMENDED             |                            |
|                              |                                                                                                                                                                                                                          | MOS    |          |                              |     |     |     |     |             | 31-DEC-2002             |                            |
|                              |                                                                                                                                                                                                                          | HRS/MS | A/R      |                              |     |     |     |     |             |                         |                            |
|                              |                                                                                                                                                                                                                          | AFL    |          |                              |     |     |     |     |             |                         |                            |
|                              | REF:                                                                                                                                                                                                                     |        |          |                              |     |     |     |     |             |                         |                            |



Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNIT                  | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE                  | DISPOSITION<br>NEXT DUE    | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|-----------------------|----------|-----------------------------------------------------|----------|-----------------------------|----------------------------|----------------------------|
| SB 972851U          | SERVICE BULLETIN SB 731-A72-3668 #2 ENG              | MOS<br>HRS/MSA<br>AFL | A/R      |                                                     |          |                             | RECOMMENDED<br>31-DEC-2002 |                            |
|                     | REF:                                                 |                       |          |                                                     |          |                             |                            |                            |
| SB 972840U          | SERVICE BULLETIN GSBA72-3569 R/E FAN ROTOR           | MOS<br>HRS/MSA<br>AFL | A/R      |                                                     |          |                             | 5722                       |                            |
|                     | REF:                                                 |                       |          |                                                     |          |                             |                            |                            |
|                     | Method of Compliance: OPEN                           |                       |          |                                                     |          |                             |                            |                            |
| SL WW-2492          | SERVICE LETTER HYD HOSE INSP<br>PKG 1, 2, 3          | MOS<br>HRS/MSA<br>AFL | 200      |                                                     |          | 26-JUN-2001<br>7687<br>5594 | 7887                       |                            |
|                     | REF:                                                 |                       |          |                                                     |          |                             |                            |                            |
|                     | Method of Compliance: OPEN                           |                       |          |                                                     |          |                             |                            |                            |
| SL WW-2494 R3 LEFT  | SERVICE LETTER LANDING GEAR                          | MOS<br>HRS/MSA<br>AFL | 300      |                                                     |          | 26-JUN-2001<br>7687<br>5594 | 7987                       | L1                         |
|                     | REF: See Workcard                                    |                       |          |                                                     |          |                             |                            |                            |
|                     | Method of Compliance: OPEN                           |                       |          |                                                     |          |                             |                            |                            |
| SL WW-2494 R3 RIGHT | SERVICE LETTER LANDING GEAR                          | MOS<br>HRS/MSA<br>AFL | 300      |                                                     |          | 26-JUN-2001<br>7687<br>5594 | 7987                       | L2                         |
|                     | REF: See Workcard                                    |                       |          |                                                     |          |                             |                            |                            |
|                     | Method of Compliance: OPEN                           |                       |          |                                                     |          |                             |                            |                            |



Engine Model - TFE731-3

 Report Date **11-APR-2002**

 Owner Name - R&S AIRCRAFT INVESTMENTS, LLC  
 A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER | UNT                                                                                                                           | INTERVAL | TIME-----AT-----INSTALLATION |     |     |     |     | COMPLIANCE | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------|----------|------------------------------|-----|-----|-----|-----|------------|-------------------------|----------------------------|
|                     |                                                      |                                                                                                                               |          | TSN                          | TSO | TSR | TSI | ADJ |            |                         |                            |
| ENGINE NO. 1        |                                                      |                                                                                                                               |          |                              |     |     |     |     |            |                         |                            |
| AD                  | 2000-15-09                                           | NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE HPC IMPELLER                                                                           |          |                              |     |     |     |     |            |                         |                            |
|                     |                                                      | MOS                                                                                                                           |          |                              |     |     |     |     |            |                         | 10-OCT-2000                |
|                     |                                                      | HRS/MS                                                                                                                        | 4200     |                              |     |     |     |     |            |                         |                            |
|                     |                                                      | ENC                                                                                                                           |          |                              |     |     |     |     |            |                         |                            |
|                     | REF:                                                 |                                                                                                                               |          |                              |     |     |     |     |            |                         |                            |
|                     | Method of Compliance:                                | OPEN                                                                                                                          |          |                              |     |     |     |     |            |                         |                            |
| AD                  | 2001-23-09                                           | NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE TO PREVENT FAILURE OF THE FAN ROTOR DISC DUE TO FATIGUE CRACKING IN THE DOVETAIL SLOTS |          |                              |     |     |     |     |            |                         |                            |
|                     |                                                      | MOS                                                                                                                           |          |                              |     |     |     |     |            | MANDATORY               |                            |
|                     |                                                      | HRS/MS                                                                                                                        | DUE      |                              |     |     |     |     |            | 31-DEC-2002             |                            |
|                     |                                                      | ENC                                                                                                                           |          |                              |     |     |     |     |            |                         |                            |
|                     | REF:                                                 |                                                                                                                               |          |                              |     |     |     |     |            |                         |                            |
|                     | Method of Compliance:                                | OPEN                                                                                                                          |          |                              |     |     |     |     |            |                         |                            |
| SB                  | TFE731-A72-3668                                      | NO. 1 ENGINE - REMOVE FAN ROTOR DISC FROM SERVICE SERVICE BULLETIN                                                            |          |                              |     |     |     |     |            |                         |                            |
|                     |                                                      | MOS                                                                                                                           |          |                              |     |     |     |     |            | MANDATORY               |                            |
|                     |                                                      | HRS/MS                                                                                                                        | A/R      |                              |     |     |     |     |            | 31-DEC-2002             |                            |
|                     | ASSOCIATED                                           | ENC                                                                                                                           |          |                              |     |     |     |     |            |                         |                            |
|                     | REF: BULLETINS                                       |                                                                                                                               |          |                              |     |     |     |     |            |                         |                            |
|                     | Method of Compliance:                                | OPEN                                                                                                                          |          |                              |     |     |     |     |            |                         |                            |



Engine Model - TFE731-3

Report Date **11-APR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC  
A/C Serial #: 368 A/C Reg. #: N368MD

| ITEM NO<br>WORKCARD | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER                                                                          | UNIT   | INTERVAL | TIME-----AT-----INSTALLATION<br>TSN TSO TSR TSI ADJ | Warr Exp | COMPLIANCE | DISPOSITION<br>NEXT DUE | AREA<br>PRICE<br>LABOR HRS |
|---------------------|-------------------------------------------------------------------------------------------------------------------------------|--------|----------|-----------------------------------------------------|----------|------------|-------------------------|----------------------------|
| <b>ENGINE NO. 2</b> |                                                                                                                               |        |          |                                                     |          |            |                         |                            |
| AD 2000-15-09       | NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE HPC IMPELLER                                                                           |        |          |                                                     |          |            |                         |                            |
|                     |                                                                                                                               | MOS    |          |                                                     |          |            | 10-OCT-2000             |                            |
|                     |                                                                                                                               | HRS/MS | 4200     |                                                     |          |            |                         |                            |
|                     | REF:                                                                                                                          | ENC    |          |                                                     |          |            |                         |                            |
|                     | Method of Compliance: OPEN                                                                                                    |        |          |                                                     |          |            |                         |                            |
| AD 2001-23-09       | NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE TO PREVENT FAILURE OF THE FAN ROTOR DISC DUE TO FATIGUE CRACKING IN THE DOVETAIL SLOTS |        |          |                                                     |          |            | MANDATORY               |                            |
|                     |                                                                                                                               | MOS    |          |                                                     |          |            | 31-DEC-2002             |                            |
|                     |                                                                                                                               | HRS/MS | DUE      |                                                     |          |            |                         |                            |
|                     | REF:                                                                                                                          | ENC    |          |                                                     |          |            |                         |                            |
|                     | Method of Compliance: OPEN                                                                                                    |        |          |                                                     |          |            |                         |                            |
| SB TFE731-A72-3668  | NO. 2 ENGINE - REMOVE FAN ROTOR DISC FROM SERVICE SERVICE BULLETIN                                                            |        |          |                                                     |          |            | MANDATORY               |                            |
|                     |                                                                                                                               | MOS    |          |                                                     |          |            | 31-DEC-2002             |                            |
| ASSOCIATED          |                                                                                                                               | HRS/MS | A/R      |                                                     |          |            |                         |                            |
|                     | REF: BULLETINS                                                                                                                | ENC    |          |                                                     |          |            |                         |                            |
|                     | Method of Compliance: OPEN                                                                                                    |        |          |                                                     |          |            |                         |                            |



**OWNER:** R&S AIRCRAFT INVESTMENTS, LLC  
**ADDRESS:** P.O. BOX 43 HOUSTON TX 77001-0043  
**PHONE:** 713-830-9584  
**FAX:** 713-918-5925

**OPERATOR:** R&S AIRCRAFT INVESTMENTS, LLC  
**ADDRESS:** P.O. BOX 43 HOUSTON TX 77001-0043  
**PHONE:** 713-830-9584  
**FAX:** 713-918-5925

PROJECTED : 2 MOS. to 11-JUN-2002

**AIRCRAFT**

**S/N:** 368      **REG NO:** N368MD      **MODEL:** 1124A WESTWIND      **MANUFACTURER:** GULFSTREAM AEROSPACE CORPORATION  
**NOTE:**  
**INSPECTION PROGRAM:** 3  
**CERTIFICATE DATE:** 11-FEB-1982

| UOM | LAST ACTUAL | LAST ACTUAL DATE | PROJECTED |
|-----|-------------|------------------|-----------|
| HRS | 7806        | 28-FEB-2002      | 7926.8    |
| AFL | 5706        | 28-FEB-2002      | 5827      |

**ENGINE NO. 1**

**S/N:** P-77482      **PART NO:** 3072500-2      **MODEL:** TFE731-3      **MANUFACTURER:** HONEYWELL  
**INSTALLED DATE:** 4/3/1989  
**A/C HRS:** 4215  
**ENGINE HRS:** 3972  
**ENGINE CYCLES:** 2456

| UOM   | LAST ACTUAL | LAST ACTUAL DATE | PROJECTED |
|-------|-------------|------------------|-----------|
| HRS   | 7806        | 28-FEB-2002      | 7926.8    |
| ENC   | 0           |                  | 0         |
| (AFL) | 5706        | 28-FEB-2002      | 5827      |

**ENGINE NO. 2**

**S/N:** P77488      **PART NO:** 3072500-2      **MODEL:** TFE731-3      **MANUFACTURER:** HONEYWELL  
**INSTALLED DATE:** 5/31/1993  
**A/C HRS:** 5278  
**ENGINE HRS:** 5227  
**ENGINE CYCLES:** 3867

| UOM   | LAST ACTUAL | LAST ACTUAL DATE | PROJECTED |
|-------|-------------|------------------|-----------|
| HRS   | 7806        | 28-FEB-2002      | 7926.8    |
| ENC   | 0           |                  | 0         |
| (AFL) | 5706        | 28-FEB-2002      | 5827      |



Aircraft Model - 1124A WESTWIND

Serial #: 368 Reg. #: N368MD

# Maintenance Due List/Time Remaining - AIRCRAFT(CALENDAR)

Report Date 11-APR-2002

| ITEM NO           | WORK CARD     | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER                                              | UNIT   | INTERVAL TIME-----AT-----INSTALLATION |     |     |      | COMPLIANCE  | DISPOSITION |                              | TIME<br>REMAINING | AREA<br>PRICE |
|-------------------|---------------|---------------------------------------------------------------------------------------------------|--------|---------------------------------------|-----|-----|------|-------------|-------------|------------------------------|-------------------|---------------|
|                   |               |                                                                                                   |        | TSN                                   | TSO | TSR | WARR |             | EXP         | NEXT DUE<br>(ENH) AFH (xEXT) | OVD = Overdue     | LABOR         |
| R                 | AD 2000-15-09 | NO. 1 ENGINE - HPC IMPELLER<br>AIRWORTHINESS DIRECTIVE                                            |        |                                       |     |     |      |             |             |                              |                   |               |
|                   |               |                                                                                                   | MOS    |                                       |     |     |      |             |             | 10-OCT-2000                  | New Reqmt         |               |
|                   |               | REF:                                                                                              | HRSMSC | 4200                                  |     |     |      |             |             |                              |                   |               |
|                   |               |                                                                                                   | ENC    |                                       |     |     |      |             |             |                              |                   |               |
| R                 | AD 2000-15-09 | NO. 2 ENGINE - HPC IMPELLER<br>AIRWORTHINESS DIRECTIVE                                            |        |                                       |     |     |      |             |             |                              |                   |               |
|                   |               |                                                                                                   | MOS    |                                       |     |     |      |             |             | 10-OCT-2000                  | New Reqmt         |               |
|                   |               | REF:                                                                                              | HRSMSC | 4200                                  |     |     |      |             |             |                              |                   |               |
|                   |               |                                                                                                   | ENC    |                                       |     |     |      |             |             |                              |                   |               |
| R                 | 260169        | VISUAL INSPECTION COCKPIT PORTABLE EXTINGUISHER COCKPIT FIRE EXTINGUISHER                         |        |                                       |     |     |      |             |             |                              |                   | F3            |
|                   | 26.060        |                                                                                                   | DAYS   | 30                                    |     |     |      | 06-NOV-2001 |             | 06-DEC-2001                  | OVD               |               |
|                   |               | REF: NO REF                                                                                       | HRSMSC |                                       |     |     |      | 7774        |             |                              |                   |               |
|                   |               |                                                                                                   | AFL    |                                       |     |     |      | 5641        |             |                              |                   |               |
| R                 | 260180        | VISUAL INSPECTION CABIN PORTABLE EXTINGUISHER CABIN FIRE EXTINGUISHER                             |        |                                       |     |     |      |             |             |                              |                   | F3            |
|                   | 26.060        |                                                                                                   | DAYS   | 30                                    |     |     |      | 06-NOV-2001 |             | 06-DEC-2001                  | OVD               |               |
|                   |               | REF: NO REF                                                                                       | HRSMSC |                                       |     |     |      | 7774        |             |                              |                   |               |
|                   |               |                                                                                                   | AFL    |                                       |     |     |      | 5641        |             |                              |                   |               |
| R                 | 330228        | CHARGE EMERGENCY LIGHT BATTERY                                                                    |        |                                       |     |     |      |             |             |                              |                   | F4            |
|                   | 33.100        |                                                                                                   | MOS    | 3                                     |     |     |      | 06-NOV-2001 |             | 06-FEB-2002                  | OVD               |               |
|                   |               | REF: AMM 12-10-06                                                                                 | HRSMSC | 200                                   |     |     |      | 7774        |             | 7974                         | 168               |               |
|                   |               |                                                                                                   | AFL    |                                       |     |     |      | 5641        |             |                              |                   |               |
| R                 | 344616        | INSPECT EMERGENCY GYRO POWER SUPPLY BATTERY EMERGENCY POWER SUPPLY BATTERY/STAND-BY ATTITUDE GYRO |        |                                       |     |     |      |             |             |                              |                   | F5            |
|                   | 34.370        |                                                                                                   | MOS    | 3                                     |     |     |      | 06-NOV-2001 |             | 06-FEB-2002                  | OVD               |               |
|                   |               | REF: AMM NO REF                                                                                   | HRSMSC | 200                                   |     |     |      | 7774        |             | 7974                         | 168               |               |
|                   |               |                                                                                                   | AFL    |                                       |     |     |      | 5641        |             |                              |                   |               |
| R                 | 320118        | INSPECT/LUBRICATE NOSE GEAR ASSEMBLY UPPER/LOWER STRUT BEARINGS BODY                              |        |                                       |     |     |      |             |             |                              |                   | L3            |
|                   | 32.540        |                                                                                                   | MOS    | 24                                    |     |     |      | 22-FEB-2000 |             | 22-FEB-2002                  | OVD               |               |
|                   |               | REF: AMM 32-20-01                                                                                 | HRSMSC | 1200                                  |     |     |      | 7107        |             | 8307                         | 501               |               |
|                   |               |                                                                                                   | AFL    |                                       |     |     |      | 5232        |             |                              |                   |               |
| R                 | 230400        | CLEAN/TEST COCKPIT VOICE RECORDER BEACON                                                          |        |                                       |     |     |      |             |             |                              |                   | T1            |
|                   | 23.130        |                                                                                                   | MOS    | 6                                     |     |     |      | 06-NOV-2001 |             | 06-MAY-2002                  | 0.8               |               |
|                   |               | REF: NO REF                                                                                       | HRSMSC |                                       |     |     |      | 7774        |             |                              |                   |               |
|                   |               |                                                                                                   | AFL    |                                       |     |     |      | 5641        |             |                              |                   |               |
| Total Labor Hours |               |                                                                                                   |        |                                       |     |     |      |             |             |                              |                   |               |
| Total Price :     |               |                                                                                                   |        |                                       |     |     |      |             |             |                              |                   |               |

R - Task was due on previous due lists  
(xEXT) - Extension incorporated in the next due calculation







Aircraft Model- 1124A WESTWIND  
Serial #: 368 Reg. #: N368MD

Maintenance Due List/Time Remaining - AIRCRAFT(HOURS)

Report Date 11-APR-2002

| ITEM NO<br>WORK CARD<br>WORK ORDER | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER                                                                                                                                                                                        | UNIT         | INTERVAL TIME-----AT-----INSTALLATION |     |     |  | COMPLIANCE<br>WARR EXP | DISPOSITION<br>NEXT DUE |            | TIME<br>REMAINING<br>OVD = Overdue | AREA<br>PRICE<br>LABOR |
|------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------|---------------------------------------|-----|-----|--|------------------------|-------------------------|------------|------------------------------------|------------------------|
|                                    |                                                                                                                                                                                                                                             |              | TSN                                   | TSO | TSR |  |                        | (ENH)                   | AFH (xEXT) |                                    |                        |
| 724120<br>72.030                   | NO. 2 ENGINE - INSPECT COMBUSTION PLENUM CASE                                                                                                                                                                                               | MOS          |                                       |     |     |  | 17-SEP-1998            |                         |            |                                    |                        |
|                                    | REF: EMM 72-40-04                                                                                                                                                                                                                           | HRS/MS       | 1400                                  |     |     |  | 6520                   |                         | 7920       | 114                                |                        |
|                                    |                                                                                                                                                                                                                                             | ENC<br>(AFL) |                                       |     |     |  | 4889                   |                         |            |                                    |                        |
| 790120<br>79.020                   | NO. 2 ENGINE - CHANGE OIL                                                                                                                                                                                                                   | MOS          |                                       |     |     |  | 17-OCT-1998            |                         |            |                                    |                        |
|                                    | REF: See Workcard                                                                                                                                                                                                                           | HRS/MS       | 1400                                  |     |     |  | 6520                   |                         | 7920       | 114                                |                        |
|                                    |                                                                                                                                                                                                                                             | ENC<br>(AFL) |                                       |     |     |  | 4889                   |                         |            |                                    |                        |
| AD 1996-24-11<br>LEFT AILERON      | TO PREVENT EXCESSIVE WEAR OF THE AILERON PUSH-PULL TUBE, WHICH COULD RESULT IN UNEVEN MOVEMENT OF THE CONTROL WHEEL, PERFORATION OF THE AILERON PUSH-PULL TUBE, AND CONSEQUENT REDUCED ROLL CONTROL OF THE AIRPLANE AIRWORTHINESS DIRECTIVE | MOS          |                                       |     |     |  | 26-JUL-2000            |                         |            |                                    | W1                     |
|                                    | REF: AD                                                                                                                                                                                                                                     | HRS/MS       | 600                                   |     |     |  | 7325                   |                         | 7925       | 119                                |                        |
|                                    |                                                                                                                                                                                                                                             | AFL          |                                       |     |     |  | 5360                   |                         |            |                                    |                        |
| AD 1996-24-11<br>RIGHT AILERON     | TO PREVENT EXCESSIVE WEAR OF THE AILERON PUSH-PULL TUBE, WHICH COULD RESULT IN UNEVEN MOVEMENT OF THE CONTROL WHEEL, PERFORATION OF THE AILERON PUSH-PULL TUBE, AND CONSEQUENT REDUCED ROLL CONTROL OF THE AIRPLANE AIRWORTHINESS DIRECTIVE | MOS          |                                       |     |     |  | 26-JUL-2000            |                         |            |                                    | W2                     |
|                                    | REF: AD                                                                                                                                                                                                                                     | HRS/MS       | 600                                   |     |     |  | 7325                   |                         | 7925       | 119                                |                        |
|                                    |                                                                                                                                                                                                                                             | AFL          |                                       |     |     |  | 5360                   |                         |            |                                    |                        |
| SB 1124-27-129<br>LEFT AILERON     | FLIGHT CONTROLS SERVICE BULLETIN                                                                                                                                                                                                            | MOS          |                                       |     |     |  | 26-JUL-2000            |                         |            |                                    | W1                     |
|                                    | REF: BULLETINS                                                                                                                                                                                                                              | HRS/MS       | 600                                   |     |     |  | 7325                   |                         | 7925       | 119                                |                        |
|                                    |                                                                                                                                                                                                                                             | AFL          |                                       |     |     |  | 5360                   |                         |            |                                    |                        |
| SB 1124-27-129<br>RIGHT AILERON    | FLIGHT CONTROLS SERVICE BULLETIN                                                                                                                                                                                                            | MOS          |                                       |     |     |  | 26-JUL-2000            |                         |            |                                    | W2                     |
|                                    | REF: BULLETINS                                                                                                                                                                                                                              | HRS/MS       | 600                                   |     |     |  | 7325                   |                         | 7925       | 119                                |                        |
|                                    |                                                                                                                                                                                                                                             | AFL          |                                       |     |     |  | 5360                   |                         |            |                                    |                        |

Total Labor Hours 36:0  
Total Price :

R - Task was due on previous due lists  
(xEXT) - Extension incorporated in the next due calculation





Maintenance Due List/Time Remaining - AIRCRAFT(AFL)

Aircraft Model - 1124A WESTWIND

Serial #: 368 Reg. #: N368MD

Report Date 11-APR-2002

| ITEM NO | TASK DESCRIPTION | UNIT                                        | INTERVAL TIME-----AT-----INSTALLATION |                 |     |     | COMPLIANCE | DISPOSITION | TIME | AREA |     |          |          |           |       |
|---------|------------------|---------------------------------------------|---------------------------------------|-----------------|-----|-----|------------|-------------|------|------|-----|----------|----------|-----------|-------|
|         |                  |                                             | WORK CARD                             | PART NUMBER/PKG | TSN | TSO |            |             |      |      | TSR | WARR EXP | NEXT DUE | REMAINING | PRICE |
|         |                  |                                             |                                       |                 |     |     |            |             |      |      |     |          |          |           |       |
| R       | SB 972B40U       | SERVICE BULLETIN G SBA72-3569 R/E FAN ROTOR |                                       |                 |     |     |            |             |      |      |     |          |          |           |       |
|         |                  | MOS                                         |                                       |                 |     |     |            |             |      |      |     |          |          |           |       |
|         |                  | HRS/MS                                      |                                       |                 |     |     |            |             |      |      |     |          |          |           |       |
|         |                  | AFL                                         |                                       |                 |     |     |            |             |      |      |     |          |          |           |       |
|         |                  | A/R                                         |                                       |                 |     |     |            |             |      |      |     |          |          |           |       |
|         | REF:             |                                             |                                       |                 |     |     |            | 5722        | 16   |      |     |          |          |           |       |

REF:  
Total Labor Hours  
Total Price :

R - Task was due on previous due lists  
(xEXT) - Extension incorporated in the next due calculation



# Maintenance Due List/Time Remaining - ENGINE((AFL))

Aircraft Model - 1124A WESTWIND

Serial #: 368 Reg. #: N368MD

Report Date 11-APR-2002

|   | ITEM NO<br>WORK CARD<br>WORK ORDER | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER    | UNIT                          | INTERVAL TIME-----AT-----INSTALLATION |      |     |  | COMPLIANCE<br>WARR EXP      | DISPOSITION<br>NEXT DUE |            | TIME<br>REMAINING<br>OVD = Overdue | AREA<br>PRICE<br>LABOR |
|---|------------------------------------|---------------------------------------------------------|-------------------------------|---------------------------------------|------|-----|--|-----------------------------|-------------------------|------------|------------------------------------|------------------------|
|   |                                    |                                                         |                               | TSN                                   | TSO  | TSR |  |                             | (ENH)                   | AFH (xEXT) |                                    |                        |
| R | 725050                             | NO. 2 ENGINE - CHANGE FAN ROTOR DISC                    |                               |                                       |      |     |  |                             |                         |            |                                    |                        |
|   | 72.090                             | 3073539-2<br>0-18040-4768<br>REF: NO REF                | MOS<br>HRS/MS<br>ENC<br>(AFL) | 4100                                  | 2660 |     |  | 20-MAY-1993<br>5278<br>3928 |                         | 5368       |                                    | OVD                    |
| R | 725030                             | NO. 2 ENGINE - CHANGE STAGE 3 LOW PRESSURE TURBINE DISC |                               |                                       |      |     |  |                             |                         |            |                                    |                        |
|   | 72.060                             | 3072544-2<br>6-18040-4905<br>REF: NO REF                | MOS<br>HRS/MS<br>ENC<br>(AFL) | 3000                                  | 0    |     |  | 31-MAY-1989<br>4265<br>2793 |                         | 5793       |                                    | 87                     |

Total Labor Hours

Total Price :

R - Task was due on previous due lists  
(xEXT) - Extension incorporated in the next due calculation



**OWNER:** R&S AIRCRAFT INVESTMENTS, LLC  
**ADDRESS:** P.O. BOX 43 HOUSTON TX 77001-0043

**OPERATOR:** R&S AIRCRAFT INVESTMENTS, LLC  
**ADDRESS:** P.O. BOX 43 HOUSTON TX 77001-0043

**PHONE:** 713-830-9584  
**FAX:** 713-918-5925

**PHONE:** 713-830-9584  
**FAX:** 713-918-5925

PROJECTED : 2 MOS. to 11-AUG-2002

**EXTENDED DUE LIST - FOR PLANNING PURPOSES ONLY - Scheduled Work Cards were not issued with this Report.**

**AIRCRAFT**

**S/N:** 368

**REG NO:** N368MD

**MODEL:** 1124A WESTWIND

**MANUFACTURER:** GULFSTREAM AEROSPACE CORPORATION

**NOTE:**  
**INSPECTION PROGRAM:** 3  
**CERTIFICATE DATE:** 11-FEB-1982

| UOM | LAST ACTUAL | LAST ACTUAL DATE | PROJECTED |
|-----|-------------|------------------|-----------|
| HRS | 7806        | 28-FEB-2002      | 7996.8    |
| AFL | 5706        | 28-FEB-2002      | 5897      |

**ENGINE NO. 1**

**S/N:** P-77482

**PART NO:** 3072500-2

**MODEL:** TFE731-3

**MANUFACTURER:** HONEYWELL

**INSTALLED DATE:** 4/3/1989  
**A/C HRS:** 4215  
**ENGINE HRS:** 3972  
**ENGINE CYCLES:** 2456

| UOM   | LAST ACTUAL | LAST ACTUAL DATE | PROJECTED |
|-------|-------------|------------------|-----------|
| HRS   | 7806        | 28-FEB-2002      | 7996.8    |
| ENC   | 0           |                  | 0         |
| (AFL) | 5706        | 28-FEB-2002      | 5897      |

**ENGINE NO. 2**

**S/N:** P77488

**PART NO:** 3072500-2

**MODEL:** TFE731-3

**MANUFACTURER:** HONEYWELL

**INSTALLED DATE:** 5/31/1993  
**A/C HRS:** 5278  
**ENGINE HRS:** 5227  
**ENGINE CYCLES:** 3867

| UOM   | LAST ACTUAL | LAST ACTUAL DATE | PROJECTED |
|-------|-------------|------------------|-----------|
| HRS   | 7806        | 28-FEB-2002      | 7996.8    |
| ENC   | 0           |                  | 0         |
| (AFL) | 5706        | 28-FEB-2002      | 5897      |



# Extended Due List - AIRCRAFT(CALENDAR)

Aircraft Model - 1124A WESTWIND

Serial #: 368 Reg. #: N368MD

Report Date 11-APR-2002

EXTENDED DUE LIST - FOR PLANNING PURPOSE ONLY - Scheduled Work Cards were not issued with this Report.

| ITEM NO<br>WORK CARD<br>WORK ORDER | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER                 | UNIT                                | INTERVAL TIME-----AT-----INSTALLATION |     |     |          | COMPLIANCE                  | DISPOSITION<br>NEXT DUE |            | AREA<br>PRICE<br>LABOR |
|------------------------------------|----------------------------------------------------------------------|-------------------------------------|---------------------------------------|-----|-----|----------|-----------------------------|-------------------------|------------|------------------------|
|                                    |                                                                      |                                     | TSN                                   | TSO | TSR | WARR EXP |                             | (ENH)                   | AFH (xEXT) |                        |
| 270080                             | X-RAY INSPECT LEFT AILERON CONTROL ROD                               | LEFT AILERON CONTROL ROD ASSEMBLIES |                                       |     |     |          |                             |                         |            | W1                     |
| 27.530                             | 513506-503<br>SN-UNKNOWN<br>REF: NO REF                              | MOS<br>HRS/MSC<br>AFL               | 60<br>5000                            |     |     |          | 16-JUN-1997<br>6135<br>4707 | 16-JUN-2002<br>11135    |            |                        |
| 270081                             | X-RAY INSPECT RIGHT AILERON CONTROL ROD ASSEMBLY                     |                                     |                                       |     |     |          |                             |                         |            | W2                     |
| 27.535                             | 513506-503<br>SN-UNKNOWN<br>REF: NO REF                              | MOS<br>HRS/MSC<br>AFL               | 60<br>5000                            |     |     |          | 16-JUN-1997<br>6135<br>4707 | 16-JUN-2002<br>11135    |            |                        |
| 270150                             | X-RAY INSPECT RUDDER CONTROL ROD ASSEMBLY                            |                                     |                                       |     |     |          |                             |                         |            | T1                     |
| 27.560                             |                                                                      | MOS<br>HRS/MSC<br>AFL               | 60<br>5000                            |     |     |          | 16-JUN-1997<br>6135<br>4707 | 16-JUN-2002<br>11135    |            |                        |
|                                    | REF: NO REF                                                          |                                     |                                       |     |     |          |                             |                         |            |                        |
| 270210                             | VISUAL INSPECT ELEVATOR CONTROL BELLCRANK ASSEMBLY                   |                                     |                                       |     |     |          |                             |                         |            |                        |
| 27.570                             |                                                                      | MOS<br>HRS/MSC<br>AFL               | 60<br>5000                            |     |     |          | 16-JUN-1997<br>6135<br>4707 | 16-JUN-2002<br>11135    |            |                        |
|                                    | REF: AMM 5-10-00                                                     |                                     |                                       |     |     |          |                             |                         |            |                        |
| 320110                             | X-RAY INSPECT NOSE GEAR ASSEMBLY NOSE GEAR SHAFT AND DOOR ASSEMBLIES |                                     |                                       |     |     |          |                             |                         |            | L3                     |
| 32.560                             |                                                                      | MOS<br>HRS/MSC<br>AFL               | 60<br>5000                            |     |     |          | 16-JUN-1997<br>6135<br>4707 | 16-JUN-2002<br>11135    |            |                        |
|                                    | REF: AMM 5-10-00                                                     |                                     |                                       |     |     |          |                             |                         |            |                        |
| 260171                             | WEIGHT CHECK COCKPIT PORTABLE EXTINGUISHER COCKPIT FIRE EXTINGUISHER |                                     |                                       |     |     |          |                             |                         |            | F3                     |
| 26.030                             |                                                                      | MOS<br>HRS/MSC<br>AFL               | 12                                    |     |     |          | 26-JUN-2001<br>7687<br>5594 | 26-JUN-2002             |            |                        |
|                                    | REF: AMM 5-10-00                                                     |                                     |                                       |     |     |          |                             |                         |            |                        |
| 260181                             | WEIGHT CHECK CABIN PORTABLE EXTINGUISHER CABIN FIRE EXTINGUISHER     |                                     |                                       |     |     |          |                             |                         |            | F4                     |
| 26.030                             |                                                                      | MOS<br>HRS/MSC<br>AFL               | 12                                    |     |     |          | 26-JUN-2001<br>7687<br>5594 | 26-JUN-2002             |            |                        |
|                                    | REF: AMM 5-10-00                                                     |                                     |                                       |     |     |          |                             |                         |            |                        |
| 350166U                            | CHECK PILOT OXYGEN MASK                                              |                                     |                                       |     |     |          |                             |                         |            | F3                     |
| 35.070                             |                                                                      | MOS<br>HRS/MSC<br>AFL               | 12<br>600                             |     |     |          | 26-JUN-2001<br>7687<br>5594 | 26-JUN-2002<br>8287     |            |                        |
|                                    | REF: AMM 35-00-00                                                    |                                     |                                       |     |     |          |                             |                         |            |                        |
| 350169U                            | CHECK COPILOT OXYGEN MASK                                            |                                     |                                       |     |     |          |                             |                         |            | F3                     |
| 35.070                             |                                                                      | MOS<br>HRS/MSC<br>AFL               | 12<br>600                             |     |     |          | 26-JUN-2001<br>7687<br>5594 | 26-JUN-2002<br>8287     |            |                        |
|                                    | REF: AMM 35-00-00                                                    |                                     |                                       |     |     |          |                             |                         |            |                        |

Total Labor Hours

Total Price :

R - Task was due on previous due lists

(xEXT) - Extension incorporated in the next due calculation



Aircraft Model - 1124A WESTWIND

Serial #: 368 Reg. #: N368MD

Report Date **11-APR-2002**
**EXTENDED DUE LIST - FOR PLANNING PURPOSE ONLY - Scheduled Work Cards were not issued with this Report.**

|   | ITEM NO<br>WORK CARD<br>WORK ORDER | TASK DESCRIPTION<br>PART NUMBER/PKG<br>SERIAL NUMBER                                              | UNIT                  | INTERVAL TIME-----AT-----INSTALLATION |     |     |          | COMPLIANCE                  | DISPOSITION         |            | AREA<br>PRICE<br>LABOR |
|---|------------------------------------|---------------------------------------------------------------------------------------------------|-----------------------|---------------------------------------|-----|-----|----------|-----------------------------|---------------------|------------|------------------------|
|   |                                    |                                                                                                   |                       | TSN                                   | TSO | TSR | WARR EXP |                             | NEXT DUE<br>( ENH ) | AFH (xEXT) |                        |
| R | 330228<br>33.100                   | CHARGE EMERGENCY LIGHT BATTERY                                                                    | MOS<br>HRS/MSC<br>AFL | 3<br>200                              |     |     |          | 06-NOV-2001<br>7774<br>5641 | 06-FEB-2002<br>7974 |            | F4                     |
|   |                                    | REF: AMM 12-10-06                                                                                 |                       |                                       |     |     |          |                             |                     |            |                        |
| R | 344616<br>34.370                   | INSPECT EMERGENCY GYRO POWER SUPPLY BATTERY EMERGENCY POWER SUPPLY BATTERY/STAND-BY ATTITUDE GYRO | MOS<br>HRS/MSC<br>AFL | 3<br>200                              |     |     |          | 06-NOV-2001<br>7774<br>5641 | 06-FEB-2002<br>7974 |            | F5                     |
|   |                                    | REF: AMM NO REF                                                                                   |                       |                                       |     |     |          |                             |                     |            |                        |
|   | SB 1124-55-020 R2                  | STABILIZERS SERVICE BULLETIN                                                                      | MOS<br>HRS/MSC<br>AFL | 300                                   |     |     |          | 26-JUN-2001<br>7687<br>5594 | 7987                |            | T1                     |
|   |                                    | REF: See Workcard                                                                                 |                       |                                       |     |     |          |                             |                     |            |                        |
|   | SL WW-2494 R3<br>LEFT              | LANDING GEAR SERVICE LETTER                                                                       | MOS<br>HRS/MSC<br>AFL | 300                                   |     |     |          | 26-JUN-2001<br>7687<br>5594 | 7987                |            | L1                     |
|   |                                    | REF: See Workcard                                                                                 |                       |                                       |     |     |          |                             |                     |            |                        |
|   | SL WW-2494 R3<br>RIGHT             | LANDING GEAR SERVICE LETTER                                                                       | MOS<br>HRS/MSC<br>AFL | 300                                   |     |     |          | 26-JUN-2001<br>7687<br>5594 | 7987                |            | L2                     |
|   |                                    | REF: See Workcard                                                                                 |                       |                                       |     |     |          |                             |                     |            |                        |

**Total Labor Hours**  
**Total Price :**

R - Task was due on previous due lists  
(xEXT) - Extension incorporated in the next due calculation



A/C Serial No.: 368 A/C Regn No.: N368MD Model:1124A WESTWIND  
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

Report Date **11-APR-2002**

Compliance From 01/01/2001 To 4/11/2002

| ITEM NO<br>PART NO.                                       | DESCRIPTION<br>SERIAL NO.                                  | COMPONENT INSTALLED AND/OR<br>SERVICE/INSPECTION COMPLIED |           |     |     | COMPONENT TIMES AFTER REMOVAL |     |     |     |               |                    |
|-----------------------------------------------------------|------------------------------------------------------------|-----------------------------------------------------------|-----------|-----|-----|-------------------------------|-----|-----|-----|---------------|--------------------|
|                                                           |                                                            | C/W                                                       | TSN       | TSO | TSR | C/W                           | TSN | TSO | TSR |               |                    |
| <b>CHAPTER 05-TIME LIMITS/MAINTENANCE CHECKS</b>          |                                                            |                                                           |           |     |     |                               |     |     |     |               |                    |
| 050150U                                                   | 200 HOUR INSPECTION                                        |                                                           |           |     |     |                               |     |     |     |               |                    |
|                                                           |                                                            | MOS                                                       | 1/17/2001 |     |     |                               |     |     |     | TECH :        | INSP :             |
|                                                           |                                                            | HRS                                                       | 7494      |     |     |                               |     |     |     |               | LABOR HRS :        |
|                                                           |                                                            | AFL                                                       | 5466      |     |     |                               |     |     |     |               | SERVICE REMARKS -- |
| <b>CHAPTER 10-PARKING, MOORING, STORE AND RET TO SERV</b> |                                                            |                                                           |           |     |     |                               |     |     |     |               |                    |
| 100310                                                    | CHECK AIRWORTHY DIRECTIVES                                 |                                                           |           |     |     |                               |     |     |     |               |                    |
|                                                           |                                                            | MOS                                                       | 1/17/2001 |     |     |                               |     |     |     | TECH :        | INSP :             |
|                                                           |                                                            | HRS                                                       | 7494      |     |     |                               |     |     |     |               | LABOR HRS :        |
|                                                           |                                                            | AFL                                                       | 5466      |     |     |                               |     |     |     |               | SERVICE REMARKS -- |
| 100320                                                    | CHECK SERVICE BULLETINS                                    |                                                           |           |     |     |                               |     |     |     |               |                    |
|                                                           |                                                            | MOS                                                       | 1/17/2001 |     |     |                               |     |     |     | TECH :        | INSP :             |
|                                                           |                                                            | HRS                                                       | 7494      |     |     |                               |     |     |     |               | LABOR HRS :        |
|                                                           |                                                            | AFL                                                       | 5466      |     |     |                               |     |     |     |               | SERVICE REMARKS -- |
| 100330                                                    | CHECK SERVICE LETTERS                                      |                                                           |           |     |     |                               |     |     |     |               |                    |
|                                                           |                                                            | MOS                                                       | 1/17/2001 |     |     |                               |     |     |     | TECH :        | INSP :             |
|                                                           |                                                            | HRS                                                       | 7494      |     |     |                               |     |     |     |               | LABOR HRS :        |
|                                                           |                                                            | AFL                                                       | 5466      |     |     |                               |     |     |     |               | SERVICE REMARKS -- |
| <b>CHAPTER 12-SERVICING</b>                               |                                                            |                                                           |           |     |     |                               |     |     |     |               |                    |
| 120150                                                    | CHECK PRE-FLIGHT                                           |                                                           |           |     |     |                               |     |     |     |               |                    |
|                                                           |                                                            | MOS                                                       | 1/17/2001 |     |     |                               |     |     |     | TECH :        | INSP :             |
|                                                           |                                                            | HRS                                                       | 7494      |     |     |                               |     |     |     |               | LABOR HRS :        |
|                                                           |                                                            | AFL                                                       | 5466      |     |     |                               |     |     |     |               | SERVICE REMARKS -- |
| 120160                                                    | CHECK NO.1 ENGINE PREFLIGHT COMPLETE                       |                                                           |           |     |     |                               |     |     |     |               |                    |
|                                                           |                                                            | MOS                                                       | 2/16/2001 |     |     |                               |     |     |     | TECH :        | INSP :             |
|                                                           |                                                            | HRS                                                       | 7551      |     |     |                               |     |     |     |               | LABOR HRS :        |
|                                                           |                                                            | AFL                                                       | 5515      |     |     |                               |     |     |     |               | SERVICE REMARKS -- |
| 120161                                                    | CHECK NO.2 ENGINE PREFLIGHT COMPLETE                       |                                                           |           |     |     |                               |     |     |     |               |                    |
|                                                           |                                                            | MOS                                                       | 2/16/2001 |     |     |                               |     |     |     | TECH :        | INSP :             |
|                                                           |                                                            | HRS                                                       | 7551      |     |     |                               |     |     |     |               | LABOR HRS :        |
|                                                           |                                                            | AFL                                                       | 5515      |     |     |                               |     |     |     |               | SERVICE REMARKS -- |
| <b>CHAPTER 21-AIR CONDITIONING</b>                        |                                                            |                                                           |           |     |     |                               |     |     |     |               |                    |
| 210622                                                    | INSPECT 35 DEGREE TEMPERATURE SENSOR 35 DEGREE DUCT SENSOR |                                                           |           |     |     |                               |     |     |     |               |                    |
|                                                           |                                                            | MOS                                                       | 1/17/2001 |     |     |                               |     |     |     | TECH :        | INSP :             |
|                                                           |                                                            | HRS                                                       | 7494      |     |     |                               |     |     |     |               | LABOR HRS :        |
|                                                           |                                                            | AFL                                                       | 5466      |     |     |                               |     |     |     |               | SERVICE REMARKS -- |
| 210671                                                    | CLEAN/REPLACE WATER SEPARATOR CONDENSER/FILTER             |                                                           |           |     |     |                               |     |     |     |               |                    |
|                                                           |                                                            | MOS                                                       | 1/17/2001 |     |     |                               |     |     |     | TECH :        | INSP :             |
|                                                           |                                                            | HRS                                                       | 7494      |     |     |                               |     |     |     |               | LABOR HRS :        |
|                                                           |                                                            | AFL                                                       | 5466      |     |     |                               |     |     |     |               | SERVICE REMARKS -- |
| 210681                                                    | CHANGE COOLING TURBINE OIL                                 |                                                           |           |     |     |                               |     |     |     |               |                    |
|                                                           |                                                            | MOS                                                       | 1/17/2001 |     |     |                               |     |     |     | TECH :        | INSP :             |
|                                                           |                                                            | HRS                                                       | 7494      |     |     |                               |     |     |     |               | LABOR HRS :        |
|                                                           |                                                            | AFL                                                       | 5466      |     |     |                               |     |     |     |               | SERVICE REMARKS -- |
| <b>CHAPTER 24-ELECTRICAL POWER</b>                        |                                                            |                                                           |           |     |     |                               |     |     |     |               |                    |
| 240116                                                    | CHANGE NO. 1 STARTER GENERATOR                             |                                                           |           |     |     |                               |     |     |     |               |                    |
| 23065-018-1                                               | 3684                                                       | MOS                                                       | 1/17/2001 | 0   |     | 11/6/2001                     | 10  |     |     | TECH :        | INSP :             |
|                                                           |                                                            | HRS                                                       | 7494      | 0   |     | 7774                          | 280 |     |     | REASON : WORN | LABOR HRS :        |
|                                                           |                                                            | AFL                                                       | 5466      | 0   |     | 5641                          | 175 |     |     | PRICE : 0     |                    |
| 240118                                                    | INSPECT NO. 1 STARTER GENERATOR                            |                                                           |           |     |     |                               |     |     |     |               |                    |



A/C Serial No.: 368 A/C Regn No.: N368MD Model:1124A WESTWIND  
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

Report Date **11-APR-2002**

Compliance

From 01/01/2001

To 4/11/2002

| ITEM NO<br>PART NO.               | DESCRIPTION<br>SERIAL NO.                       | COMPONENT INSTALLED AND/OR<br>SERVICE/INSPECTION COMPLIED |           |     |     | COMPONENT TIMES AFTER REMOVAL |     |     |     | TECH : | INSP : |
|-----------------------------------|-------------------------------------------------|-----------------------------------------------------------|-----------|-----|-----|-------------------------------|-----|-----|-----|--------|--------|
|                                   |                                                 | C/W                                                       | TSN       | TSO | TSR | C/W                           | TSN | TSO | TSR |        |        |
|                                   |                                                 | MOS                                                       | 6/26/2001 |     |     |                               |     |     |     |        |        |
|                                   |                                                 | HRS                                                       | 7687      |     |     |                               |     |     |     |        |        |
|                                   |                                                 | AFL                                                       | 5594      |     |     |                               |     |     |     |        |        |
| 240121                            | CHECK NO. 1 STARTER GENERATOR                   | BRUSH WEAR/TENSION                                        |           |     |     |                               |     |     |     |        |        |
|                                   |                                                 | MOS                                                       | 6/26/2001 |     |     |                               |     |     |     |        |        |
|                                   |                                                 | HRS                                                       | 7687      |     |     |                               |     |     |     |        |        |
|                                   |                                                 | AFL                                                       | 5594      |     |     |                               |     |     |     |        |        |
| 240123                            | INSPECT NO. 1 STARTER GENERATOR                 | SPLINE                                                    |           |     |     |                               |     |     |     |        |        |
|                                   |                                                 | MOS                                                       | 6/26/2001 |     |     |                               |     |     |     |        |        |
|                                   |                                                 | HRS                                                       | 7687      |     |     |                               |     |     |     |        |        |
|                                   |                                                 | AFL                                                       | 5594      |     |     |                               |     |     |     |        |        |
| 240128                            | INSPECT NO. 2 STARTER GENERATOR                 |                                                           |           |     |     |                               |     |     |     |        |        |
|                                   |                                                 | MOS                                                       | 6/26/2001 |     |     |                               |     |     |     |        |        |
|                                   |                                                 | HRS                                                       | 7687      |     |     |                               |     |     |     |        |        |
|                                   |                                                 | AFL                                                       | 5594      |     |     |                               |     |     |     |        |        |
| 240131                            | CHECK NO. 2 STARTER GENERATOR                   | BRUSH WEAR/TENSION                                        |           |     |     |                               |     |     |     |        |        |
|                                   |                                                 | MOS                                                       | 6/26/2001 |     |     |                               |     |     |     |        |        |
|                                   |                                                 | HRS                                                       | 7687      |     |     |                               |     |     |     |        |        |
|                                   |                                                 | AFL                                                       | 5594      |     |     |                               |     |     |     |        |        |
| 240133                            | INSPECT NO. 2 STARTER GENERATOR                 | SPLINE                                                    |           |     |     |                               |     |     |     |        |        |
|                                   |                                                 | MOS                                                       | 6/26/2001 |     |     |                               |     |     |     |        |        |
|                                   |                                                 | HRS                                                       | 7687      |     |     |                               |     |     |     |        |        |
|                                   |                                                 | AFL                                                       | 5594      |     |     |                               |     |     |     |        |        |
| 240161                            | CHECK LEFT BATTERY                              | ELECTROLYTE LEVEL                                         |           |     |     |                               |     |     |     |        |        |
|                                   |                                                 | MOS                                                       | 1/17/2001 |     |     |                               |     |     |     |        |        |
|                                   |                                                 | HRS                                                       | 7494      |     |     |                               |     |     |     |        |        |
|                                   |                                                 | AFL                                                       | 5466      |     |     |                               |     |     |     |        |        |
| 240166                            | DEEP CYCLE LEFT BATTERY                         |                                                           |           |     |     |                               |     |     |     |        |        |
|                                   |                                                 | MOS                                                       | 6/26/2001 |     |     |                               |     |     |     |        |        |
|                                   |                                                 | HRS                                                       | 7687      |     |     |                               |     |     |     |        |        |
|                                   |                                                 | AFL                                                       | 5594      |     |     |                               |     |     |     |        |        |
| 240176                            | CHECK RIGHT BATTERY                             | ELECTROLYTE LEVEL                                         |           |     |     |                               |     |     |     |        |        |
|                                   |                                                 | MOS                                                       | 1/17/2001 |     |     |                               |     |     |     |        |        |
|                                   |                                                 | HRS                                                       | 7494      |     |     |                               |     |     |     |        |        |
|                                   |                                                 | AFL                                                       | 5466      |     |     |                               |     |     |     |        |        |
| 240181                            | DEEP CYCLE RIGHT BATTERY                        |                                                           |           |     |     |                               |     |     |     |        |        |
|                                   |                                                 | MOS                                                       | 6/26/2001 |     |     |                               |     |     |     |        |        |
|                                   |                                                 | HRS                                                       | 7687      |     |     |                               |     |     |     |        |        |
|                                   |                                                 | AFL                                                       | 5594      |     |     |                               |     |     |     |        |        |
| 240203                            | FUNCTIONALLY CHECK EXTERNAL POWER RECEPTACLE    | BATTERY TEMPERATURE AND WARNING SYSTEM                    |           |     |     |                               |     |     |     |        |        |
|                                   |                                                 | MOS                                                       | 1/17/2001 |     |     |                               |     |     |     |        |        |
|                                   |                                                 | HRS                                                       | 7494      |     |     |                               |     |     |     |        |        |
|                                   |                                                 | AFL                                                       | 5466      |     |     |                               |     |     |     |        |        |
| <b>CHAPTER 26-FIRE PROTECTION</b> |                                                 |                                                           |           |     |     |                               |     |     |     |        |        |
| 260169                            | VISUAL INSPECTION COCKPIT PORTABLE EXTINGUISHER | COCKPIT FIRE EXTINGUISHER                                 |           |     |     |                               |     |     |     |        |        |
|                                   |                                                 | MOS                                                       | 6/26/2001 |     |     |                               |     |     |     |        |        |
|                                   |                                                 | HRS                                                       | 7687      |     |     |                               |     |     |     |        |        |
|                                   |                                                 | AFL                                                       | 5594      |     |     |                               |     |     |     |        |        |
| 260174                            | INSPECT COCKPIT PORTABLE EXTINGUISHER           | COCKPIT FIRE EXTINGUISHER                                 |           |     |     |                               |     |     |     |        |        |
|                                   |                                                 | MOS                                                       | 1/17/2001 |     |     |                               |     |     |     |        |        |
|                                   |                                                 | HRS                                                       | 7494      |     |     |                               |     |     |     |        |        |
|                                   |                                                 | AFL                                                       | 5466      |     |     |                               |     |     |     |        |        |



A/C Serial No.: 368 A/C Regn No.: N368MD Model:1124A WESTWIND  
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

Report Date **11-APR-2002**

Compliance From 01/01/2001 To 4/11/2002

| ITEM NO<br>PART NO.               | DESCRIPTION<br>SERIAL NO.                     | COMPONENT INSTALLED AND/OR<br>SERVICE/INSPECTION COMPLIED |     |     |     | COMPONENT TIMES AFTER REMOVAL |     |                 |     |
|-----------------------------------|-----------------------------------------------|-----------------------------------------------------------|-----|-----|-----|-------------------------------|-----|-----------------|-----|
|                                   |                                               | C/W                                                       | TSN | TSO | TSR | C/W                           | TSN | TSO             | TSR |
| 260180                            | VISUAL INSPECTION CABIN PORTABLE EXTINGUISHER | CABIN FIRE EXTINGUISHER                                   |     |     |     |                               |     |                 |     |
|                                   | MOS                                           | 6/26/2001                                                 |     |     |     |                               |     |                 |     |
|                                   | HRS                                           | 7687                                                      |     |     |     |                               |     |                 |     |
|                                   | AFL                                           | 5594                                                      |     |     |     |                               |     |                 |     |
|                                   |                                               |                                                           |     |     |     | TECH :                        |     | INSP :          |     |
|                                   |                                               |                                                           |     |     |     |                               |     | LABOR HRS :     |     |
|                                   |                                               |                                                           |     |     |     |                               |     | SERVICE REMARKS | --  |
| 260184                            | INSPECT CABIN PORTABLE EXTINGUISHER           | CABIN FIRE EXTINGUISHER                                   |     |     |     |                               |     |                 |     |
|                                   | MOS                                           | 1/17/2001                                                 |     |     |     |                               |     |                 |     |
|                                   | HRS                                           | 7494                                                      |     |     |     |                               |     |                 |     |
|                                   | AFL                                           | 5466                                                      |     |     |     |                               |     |                 |     |
|                                   |                                               |                                                           |     |     |     | TECH :                        |     | INSP :          |     |
|                                   |                                               |                                                           |     |     |     |                               |     | LABOR HRS :     |     |
|                                   |                                               |                                                           |     |     |     |                               |     | SERVICE REMARKS | --  |
| <b>CHAPTER 27-FLIGHT CONTROLS</b> |                                               |                                                           |     |     |     |                               |     |                 |     |
| 270158                            | INSPECT RUDDER TRIM TAB                       | FREEPLAY                                                  |     |     |     |                               |     |                 |     |
|                                   | MOS                                           | 1/17/2001                                                 |     |     |     |                               |     |                 |     |
|                                   | HRS                                           | 7494                                                      |     |     |     |                               |     |                 |     |
|                                   | AFL                                           | 5466                                                      |     |     |     |                               |     |                 |     |
|                                   |                                               |                                                           |     |     |     | TECH :                        |     | INSP :          |     |
|                                   |                                               |                                                           |     |     |     |                               |     | LABOR HRS :     |     |
|                                   |                                               |                                                           |     |     |     |                               |     | SERVICE REMARKS | --  |
| 270193                            | INSPECT LEFT ELEVATOR                         | SKIN SEPARATION                                           |     |     |     |                               |     |                 |     |
|                                   | MOS                                           | 1/17/2001                                                 |     |     |     |                               |     |                 |     |
|                                   | HRS                                           | 7494                                                      |     |     |     |                               |     |                 |     |
|                                   | AFL                                           | 5466                                                      |     |     |     |                               |     |                 |     |
|                                   |                                               |                                                           |     |     |     | TECH :                        |     | INSP :          |     |
|                                   |                                               |                                                           |     |     |     |                               |     | LABOR HRS :     |     |
|                                   |                                               |                                                           |     |     |     |                               |     | SERVICE REMARKS | --  |
| 270203                            | INSPECT RIGHT ELEVATOR                        | SKIN SEPARATION                                           |     |     |     |                               |     |                 |     |
|                                   | MOS                                           | 1/17/2001                                                 |     |     |     |                               |     |                 |     |
|                                   | HRS                                           | 7494                                                      |     |     |     |                               |     |                 |     |
|                                   | AFL                                           | 5466                                                      |     |     |     |                               |     |                 |     |
|                                   |                                               |                                                           |     |     |     | TECH :                        |     | INSP :          |     |
|                                   |                                               |                                                           |     |     |     |                               |     | LABOR HRS :     |     |
|                                   |                                               |                                                           |     |     |     |                               |     | SERVICE REMARKS | --  |
| 270213                            | LUBRICATE ELEVATOR ATTACH POINTS              |                                                           |     |     |     |                               |     |                 |     |
|                                   | MOS                                           | 1/17/2001                                                 |     |     |     |                               |     |                 |     |
|                                   | HRS                                           | 7494                                                      |     |     |     |                               |     |                 |     |
|                                   | AFL                                           | 5466                                                      |     |     |     |                               |     |                 |     |
|                                   |                                               |                                                           |     |     |     | TECH :                        |     | INSP :          |     |
|                                   |                                               |                                                           |     |     |     |                               |     | LABOR HRS :     |     |
|                                   |                                               |                                                           |     |     |     |                               |     | SERVICE REMARKS | --  |
| 270214                            | LUBRICATE AFT HINGE FITTING BEARINGS          |                                                           |     |     |     |                               |     |                 |     |
|                                   | MOS                                           | 1/17/2001                                                 |     |     |     |                               |     |                 |     |
|                                   | HRS                                           | 7494                                                      |     |     |     |                               |     |                 |     |
|                                   | AFL                                           | 5466                                                      |     |     |     |                               |     |                 |     |
|                                   |                                               |                                                           |     |     |     | TECH :                        |     | INSP :          |     |
|                                   |                                               |                                                           |     |     |     |                               |     | LABOR HRS :     |     |
|                                   |                                               |                                                           |     |     |     |                               |     | SERVICE REMARKS | --  |
| 270215                            | LUBRICATE FORWARD SCISSOR ASSEMBLY            |                                                           |     |     |     |                               |     |                 |     |
|                                   | MOS                                           | 1/17/2001                                                 |     |     |     |                               |     |                 |     |
|                                   | HRS                                           | 7494                                                      |     |     |     |                               |     |                 |     |
|                                   | AFL                                           | 5466                                                      |     |     |     |                               |     |                 |     |
|                                   |                                               |                                                           |     |     |     | TECH :                        |     | INSP :          |     |
|                                   |                                               |                                                           |     |     |     |                               |     | LABOR HRS :     |     |
|                                   |                                               |                                                           |     |     |     |                               |     | SERVICE REMARKS | --  |
| 270237                            | INSPECT LEFT FLAP/VANE                        | LEFT FLAP VANE                                            |     |     |     |                               |     |                 |     |
|                                   | MOS                                           | 1/17/2001                                                 |     |     |     |                               |     |                 |     |
|                                   | HRS                                           | 7494                                                      |     |     |     |                               |     |                 |     |
|                                   | AFL                                           | 5466                                                      |     |     |     |                               |     |                 |     |
|                                   |                                               |                                                           |     |     |     | TECH :                        |     | INSP :          |     |
|                                   |                                               |                                                           |     |     |     |                               |     | LABOR HRS :     |     |
|                                   |                                               |                                                           |     |     |     |                               |     | SERVICE REMARKS | --  |
| 270240                            | INSPECT LEFT FLAP/VANE                        | LEFT FLAP HINGE AND BEARING 200 HOURS                     |     |     |     |                               |     |                 |     |
|                                   | MOS                                           | 1/17/2001                                                 |     |     |     |                               |     |                 |     |
|                                   | HRS                                           | 7494                                                      |     |     |     |                               |     |                 |     |
|                                   | AFL                                           | 5466                                                      |     |     |     |                               |     |                 |     |
|                                   |                                               |                                                           |     |     |     | TECH :                        |     | INSP :          |     |
|                                   |                                               |                                                           |     |     |     |                               |     | LABOR HRS :     |     |
|                                   |                                               |                                                           |     |     |     |                               |     | SERVICE REMARKS | --  |
| 270242                            | INSPECT RIGHT FLAP/VANE                       | RIGHT FLAP HINGE AND BEARING 200 HOURS                    |     |     |     |                               |     |                 |     |
|                                   | MOS                                           | 1/17/2001                                                 |     |     |     |                               |     |                 |     |
|                                   | HRS                                           | 7494                                                      |     |     |     |                               |     |                 |     |
|                                   | AFL                                           | 5466                                                      |     |     |     |                               |     |                 |     |
|                                   |                                               |                                                           |     |     |     | TECH :                        |     | INSP :          |     |
|                                   |                                               |                                                           |     |     |     |                               |     | LABOR HRS :     |     |
|                                   |                                               |                                                           |     |     |     |                               |     | SERVICE REMARKS | --  |
| 270247                            | INSPECT RIGHT FLAP/VANE                       |                                                           |     |     |     |                               |     |                 |     |
|                                   | MOS                                           | 1/17/2001                                                 |     |     |     |                               |     |                 |     |
|                                   | HRS                                           | 7494                                                      |     |     |     |                               |     |                 |     |
|                                   | AFL                                           | 5466                                                      |     |     |     |                               |     |                 |     |
|                                   |                                               |                                                           |     |     |     | TECH :                        |     | INSP :          |     |
|                                   |                                               |                                                           |     |     |     |                               |     | LABOR HRS :     |     |
|                                   |                                               |                                                           |     |     |     |                               |     | SERVICE REMARKS | --  |
| 270335                            | OPERATIONAL CHECK                             | SPEED BRAKES AND LIFT DUMPERS                             |     |     |     |                               |     |                 |     |



A/C Serial No.: 368 A/C Regn No.: N368MD Model:1124A WESTWIND  
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

Report Date 11-APR-2002

Compliance From 01/01/2001 To 4/11/2002

| ITEM NO<br>PART NO.                       | DESCRIPTION<br>SERIAL NO.                                                 | COMPONENT INSTALLED AND/OR<br>SERVICE/INSPECTION COMPLIED |     |     |     | COMPONENT TIMES AFTER REMOVAL |     |     |     | TECH : | INSP : |
|-------------------------------------------|---------------------------------------------------------------------------|-----------------------------------------------------------|-----|-----|-----|-------------------------------|-----|-----|-----|--------|--------|
|                                           |                                                                           | C/W                                                       | TSN | TSO | TSR | C/W                           | TSN | TSO | TSR |        |        |
|                                           | MOS                                                                       | 1/17/2001                                                 |     |     |     |                               |     |     |     |        |        |
|                                           | HRS                                                                       | 7494                                                      |     |     |     |                               |     |     |     |        |        |
|                                           | AFL                                                                       | 5466                                                      |     |     |     |                               |     |     |     |        |        |
| <b>CHAPTER 28-FUEL</b>                    |                                                                           |                                                           |     |     |     |                               |     |     |     |        |        |
| 281150                                    | CHECK OPERATION OF FUEL BOOST PUMPS                                       |                                                           |     |     |     |                               |     |     |     |        |        |
|                                           | MOS                                                                       | 1/17/2001                                                 |     |     |     |                               |     |     |     |        |        |
|                                           | HRS                                                                       | 7494                                                      |     |     |     |                               |     |     |     |        |        |
|                                           | AFL                                                                       | 5466                                                      |     |     |     |                               |     |     |     |        |        |
| <b>CHAPTER 29-HYDRAULIC POWER</b>         |                                                                           |                                                           |     |     |     |                               |     |     |     |        |        |
| 290143                                    | INSPECT/LUBRICATE NO. 1 HYDRAULIC PUMP NO.1 ENGINE HYDRAULIC PUMP SPLINES |                                                           |     |     |     |                               |     |     |     |        |        |
|                                           | MOS                                                                       | 1/17/2001                                                 |     |     |     |                               |     |     |     |        |        |
|                                           | HRS                                                                       | 7494                                                      |     |     |     |                               |     |     |     |        |        |
|                                           | AFL                                                                       | 5466                                                      |     |     |     |                               |     |     |     |        |        |
| 290178                                    | INSPECT/LUBRICATE NO. 2 HYDRAULIC PUMP NO.2 ENGINE HYDRAULIC PUMP SPLINES |                                                           |     |     |     |                               |     |     |     |        |        |
|                                           | MOS                                                                       | 1/17/2001                                                 |     |     |     |                               |     |     |     |        |        |
|                                           | HRS                                                                       | 7494                                                      |     |     |     |                               |     |     |     |        |        |
|                                           | AFL                                                                       | 5466                                                      |     |     |     |                               |     |     |     |        |        |
| 950920                                    | ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN                              |                                                           |     |     |     |                               |     |     |     |        |        |
|                                           | MOS                                                                       | 1/17/2001                                                 |     |     |     |                               |     |     |     |        |        |
|                                           | HRS                                                                       | 7494                                                      |     |     |     |                               |     |     |     |        |        |
|                                           | AFL                                                                       | 5466                                                      |     |     |     |                               |     |     |     |        |        |
| <b>CHAPTER 30-ICE AND RAIN PROTECTION</b> |                                                                           |                                                           |     |     |     |                               |     |     |     |        |        |
| 300147                                    | INSPECT PILOT WINDSHIELD CYCLING CONTACTOR                                |                                                           |     |     |     |                               |     |     |     |        |        |
|                                           | MOS                                                                       | 1/17/2001                                                 |     |     |     |                               |     |     |     |        |        |
|                                           | HRS                                                                       | 7494                                                      |     |     |     |                               |     |     |     |        |        |
|                                           | AFL                                                                       | 5466                                                      |     |     |     |                               |     |     |     |        |        |
| 300150                                    | INSPECT COPILOT WINDSHIELD CYCLING CONTACTOR                              |                                                           |     |     |     |                               |     |     |     |        |        |
|                                           | MOS                                                                       | 1/17/2001                                                 |     |     |     |                               |     |     |     |        |        |
|                                           | HRS                                                                       | 7494                                                      |     |     |     |                               |     |     |     |        |        |
|                                           | AFL                                                                       | 5466                                                      |     |     |     |                               |     |     |     |        |        |
| 300163                                    | INSPECT WINDSHIELD WIPER ASSEMBLY                                         |                                                           |     |     |     |                               |     |     |     |        |        |
|                                           | MOS                                                                       | 1/17/2001                                                 |     |     |     |                               |     |     |     |        |        |
|                                           | HRS                                                                       | 7494                                                      |     |     |     |                               |     |     |     |        |        |
|                                           | AFL                                                                       | 5466                                                      |     |     |     |                               |     |     |     |        |        |
| 300170                                    | OPERATIONAL TEST P2T2 SENSOR HEATER                                       |                                                           |     |     |     |                               |     |     |     |        |        |
|                                           | MOS                                                                       | 1/17/2001                                                 |     |     |     |                               |     |     |     |        |        |
|                                           | HRS                                                                       | 7494                                                      |     |     |     |                               |     |     |     |        |        |
|                                           | AFL                                                                       | 5466                                                      |     |     |     |                               |     |     |     |        |        |
| 910361                                    | ACCOMPLISH SB 1124-30-036 PART II BULLETIN                                |                                                           |     |     |     |                               |     |     |     |        |        |
|                                           | MOS                                                                       | 1/17/2001                                                 |     |     |     |                               |     |     |     |        |        |
|                                           | HRS                                                                       | 7494                                                      |     |     |     |                               |     |     |     |        |        |
|                                           | AFL                                                                       | 5466                                                      |     |     |     |                               |     |     |     |        |        |
| <b>CHAPTER 32-LANDING GEAR</b>            |                                                                           |                                                           |     |     |     |                               |     |     |     |        |        |
| 320106                                    | LUBRICATE NOSE GEAR ASSEMBLY NOSE GEAR/DOORS                              |                                                           |     |     |     |                               |     |     |     |        |        |
|                                           | MOS                                                                       | 1/17/2001                                                 |     |     |     |                               |     |     |     |        |        |
|                                           | HRS                                                                       | 7494                                                      |     |     |     |                               |     |     |     |        |        |
|                                           | AFL                                                                       | 5466                                                      |     |     |     |                               |     |     |     |        |        |
| 320156                                    | INSPECT/CLEAN/LUBRICATE NOSE GEAR LEFT WHEEL BEARINGS                     |                                                           |     |     |     |                               |     |     |     |        |        |
|                                           | MOS                                                                       | 1/17/2001                                                 |     |     |     |                               |     |     |     |        |        |
|                                           | HRS                                                                       | 7494                                                      |     |     |     |                               |     |     |     |        |        |
|                                           | AFL                                                                       | 5466                                                      |     |     |     |                               |     |     |     |        |        |



A/C Serial No.: 368 A/C Regn No.: N368MD Model:1124A WESTWIND  
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

Report Date **11-APR-2002**

Compliance From 01/01/2001 To 4/11/2002

| ITEM NO<br>PART NO. | DESCRIPTION<br>SERIAL NO.                                                                     | COMPONENT INSTALLED AND/OR<br>SERVICE/INSPECTION COMPLIED |     |     |     | COMPONENT TIMES AFTER REMOVAL |     |                 |     |
|---------------------|-----------------------------------------------------------------------------------------------|-----------------------------------------------------------|-----|-----|-----|-------------------------------|-----|-----------------|-----|
|                     |                                                                                               | C/W                                                       | TSN | TSO | TSR | C/W                           | TSN | TSO             | TSR |
| 320158              | INSPECT/CLEAN/LUBRICATE NOSE GEAR RIGHT WHEEL BEARINGS                                        |                                                           |     |     |     |                               |     |                 |     |
|                     | MOS                                                                                           | 1/17/2001                                                 |     |     |     |                               |     |                 |     |
|                     | HRS                                                                                           | 7494                                                      |     |     |     |                               |     |                 |     |
|                     | AFL                                                                                           | 5466                                                      |     |     |     |                               |     |                 |     |
|                     |                                                                                               |                                                           |     |     |     | TECH :                        |     | INSP :          |     |
|                     |                                                                                               |                                                           |     |     |     |                               |     | LABOR HRS :     |     |
|                     |                                                                                               |                                                           |     |     |     |                               |     | SERVICE REMARKS | --  |
| 320201              | INSPECT NOSE GEAR (A)                                                                         |                                                           |     |     |     |                               |     |                 |     |
|                     | MOS                                                                                           | 1/17/2001                                                 |     |     |     |                               |     |                 |     |
|                     | HRS                                                                                           | 7494                                                      |     |     |     |                               |     |                 |     |
|                     | AFL                                                                                           | 5466                                                      |     |     |     |                               |     |                 |     |
|                     |                                                                                               |                                                           |     |     |     | TECH :                        |     | INSP :          |     |
|                     |                                                                                               |                                                           |     |     |     |                               |     | LABOR HRS :     |     |
|                     |                                                                                               |                                                           |     |     |     |                               |     | SERVICE REMARKS | --  |
| 320606              | LUBRICATE LEFT MAIN GEAR ASSEMBLY LEFT MAIN GEAR                                              |                                                           |     |     |     |                               |     |                 |     |
|                     | MOS                                                                                           | 1/17/2001                                                 |     |     |     |                               |     |                 |     |
|                     | HRS                                                                                           | 7494                                                      |     |     |     |                               |     |                 |     |
|                     | AFL                                                                                           | 5466                                                      |     |     |     |                               |     |                 |     |
|                     |                                                                                               |                                                           |     |     |     | TECH :                        |     | INSP :          |     |
|                     |                                                                                               |                                                           |     |     |     |                               |     | LABOR HRS :     |     |
|                     |                                                                                               |                                                           |     |     |     |                               |     | SERVICE REMARKS | --  |
| 320676              | INSPECT/LUBRICATE LEFT MAIN GEAR INBOARD WHEEL HALF LEFT MAIN GEAR INBOARD WHEEL BEARINGS     |                                                           |     |     |     |                               |     |                 |     |
|                     | MOS                                                                                           | 1/17/2001                                                 |     |     |     |                               |     |                 |     |
|                     | HRS                                                                                           | 7494                                                      |     |     |     |                               |     |                 |     |
|                     | AFL                                                                                           | 5466                                                      |     |     |     |                               |     |                 |     |
|                     |                                                                                               |                                                           |     |     |     | TECH :                        |     | INSP :          |     |
|                     |                                                                                               |                                                           |     |     |     |                               |     | LABOR HRS :     |     |
|                     |                                                                                               |                                                           |     |     |     |                               |     | SERVICE REMARKS | --  |
| 320680              | INSPECT/LUBRICATE LEFT MAIN GEAR OUTBOARD WHEEL HALF LEFT MAIN GEAR OUTBOARD WHEEL BEARINGS   |                                                           |     |     |     |                               |     |                 |     |
|                     | MOS                                                                                           | 1/17/2001                                                 |     |     |     |                               |     |                 |     |
|                     | HRS                                                                                           | 7494                                                      |     |     |     |                               |     |                 |     |
|                     | AFL                                                                                           | 5466                                                      |     |     |     |                               |     |                 |     |
|                     |                                                                                               |                                                           |     |     |     | TECH :                        |     | INSP :          |     |
|                     |                                                                                               |                                                           |     |     |     |                               |     | LABOR HRS :     |     |
|                     |                                                                                               |                                                           |     |     |     |                               |     | SERVICE REMARKS | --  |
| 320691              | INSPECT LEFT MAIN GEAR/WELL (A)                                                               |                                                           |     |     |     |                               |     |                 |     |
|                     | MOS                                                                                           | 1/17/2001                                                 |     |     |     |                               |     |                 |     |
|                     | HRS                                                                                           | 7494                                                      |     |     |     |                               |     |                 |     |
|                     | AFL                                                                                           | 5466                                                      |     |     |     |                               |     |                 |     |
|                     |                                                                                               |                                                           |     |     |     | TECH :                        |     | INSP :          |     |
|                     |                                                                                               |                                                           |     |     |     |                               |     | LABOR HRS :     |     |
|                     |                                                                                               |                                                           |     |     |     |                               |     | SERVICE REMARKS | --  |
| 321106              | LUBRICATE RIGHT MAIN GEAR ASSEMBLY RIGHT MAIN GEAR                                            |                                                           |     |     |     |                               |     |                 |     |
|                     | MOS                                                                                           | 1/17/2001                                                 |     |     |     |                               |     |                 |     |
|                     | HRS                                                                                           | 7494                                                      |     |     |     |                               |     |                 |     |
|                     | AFL                                                                                           | 5466                                                      |     |     |     |                               |     |                 |     |
|                     |                                                                                               |                                                           |     |     |     | TECH :                        |     | INSP :          |     |
|                     |                                                                                               |                                                           |     |     |     |                               |     | LABOR HRS :     |     |
|                     |                                                                                               |                                                           |     |     |     |                               |     | SERVICE REMARKS | --  |
| 321176              | INSPECT/LUBRICATE RIGHT MAIN GEAR INBOARD WHEEL HALF RIGHT MAIN GEAR INBOARD WHEEL BEARINGS   |                                                           |     |     |     |                               |     |                 |     |
|                     | MOS                                                                                           | 1/17/2001                                                 |     |     |     |                               |     |                 |     |
|                     | HRS                                                                                           | 7494                                                      |     |     |     |                               |     |                 |     |
|                     | AFL                                                                                           | 5466                                                      |     |     |     |                               |     |                 |     |
|                     |                                                                                               |                                                           |     |     |     | TECH :                        |     | INSP :          |     |
|                     |                                                                                               |                                                           |     |     |     |                               |     | LABOR HRS :     |     |
|                     |                                                                                               |                                                           |     |     |     |                               |     | SERVICE REMARKS | --  |
| 321180              | INSPECT/LUBRICATE RIGHT MAIN GEAR OUTBOARD WHEEL HALF RIGHT MAIN GEAR OUTBOARD WHEEL BEARINGS |                                                           |     |     |     |                               |     |                 |     |
|                     | MOS                                                                                           | 1/17/2001                                                 |     |     |     |                               |     |                 |     |
|                     | HRS                                                                                           | 7494                                                      |     |     |     |                               |     |                 |     |
|                     | AFL                                                                                           | 5466                                                      |     |     |     |                               |     |                 |     |
|                     |                                                                                               |                                                           |     |     |     | TECH :                        |     | INSP :          |     |
|                     |                                                                                               |                                                           |     |     |     |                               |     | LABOR HRS :     |     |
|                     |                                                                                               |                                                           |     |     |     |                               |     | SERVICE REMARKS | --  |
| 321191              | INSPECT RIGHT MAIN GEAR OUTBOARD WHEEL HALF RIGHT MAIN GEAR/WELL (A)                          |                                                           |     |     |     |                               |     |                 |     |
|                     | MOS                                                                                           | 1/17/2001                                                 |     |     |     |                               |     |                 |     |
|                     | HRS                                                                                           | 7494                                                      |     |     |     |                               |     |                 |     |
|                     | AFL                                                                                           | 5466                                                      |     |     |     |                               |     |                 |     |
|                     |                                                                                               |                                                           |     |     |     | TECH :                        |     | INSP :          |     |
|                     |                                                                                               |                                                           |     |     |     |                               |     | LABOR HRS :     |     |
|                     |                                                                                               |                                                           |     |     |     |                               |     | SERVICE REMARKS | --  |
| 322113              | CHANGE LEFT MAIN GEAR BRAKE                                                                   |                                                           |     |     |     |                               |     |                 |     |
| 5002805-3           | 12153-6                                                                                       |                                                           |     |     |     | 1/17/2001                     |     |                 |     |
|                     | MOS                                                                                           |                                                           |     |     |     |                               |     |                 |     |
|                     | HRS                                                                                           |                                                           |     |     |     | 7494                          |     |                 |     |
|                     | AFL                                                                                           |                                                           |     |     |     | 5466                          |     |                 |     |
|                     |                                                                                               |                                                           |     |     |     | TECH :                        |     | INSP :          |     |
|                     |                                                                                               |                                                           |     |     |     | REASON : WORN                 |     | LABOR HRS :     |     |
|                     |                                                                                               |                                                           |     |     |     | PRICE : 0                     |     |                 |     |
| 322116              | INSPECT/CHECK LEFT MAIN GEAR BRAKE LEFT BRAKE LININGS                                         |                                                           |     |     |     |                               |     |                 |     |
|                     | MOS                                                                                           | 1/17/2001                                                 |     |     |     |                               |     |                 |     |
|                     | HRS                                                                                           | 7494                                                      |     |     |     |                               |     |                 |     |
|                     | AFL                                                                                           | 5466                                                      |     |     |     |                               |     |                 |     |
|                     |                                                                                               |                                                           |     |     |     | TECH :                        |     | INSP :          |     |
|                     |                                                                                               |                                                           |     |     |     |                               |     | LABOR HRS :     |     |
|                     |                                                                                               |                                                           |     |     |     |                               |     | SERVICE REMARKS | --  |
| 322128              | CHANGE RIGHT MAIN GEAR BRAKE                                                                  |                                                           |     |     |     |                               |     |                 |     |
| 5002805-3           | 1140                                                                                          |                                                           |     |     |     | 1/17/2001                     |     |                 |     |
|                     | MOS                                                                                           |                                                           |     |     |     |                               |     |                 |     |
|                     | HRS                                                                                           |                                                           |     |     |     | 7494                          |     |                 |     |
|                     | AFL                                                                                           |                                                           |     |     |     | 5466                          |     |                 |     |
|                     |                                                                                               |                                                           |     |     |     | TECH :                        |     | INSP :          |     |
|                     |                                                                                               |                                                           |     |     |     | REASON : WORN                 |     | LABOR HRS :     |     |
|                     |                                                                                               |                                                           |     |     |     | PRICE : 0                     |     |                 |     |



A/C Serial No.: 368 A/C Regn No.: N368MD Model:1124A WESTWIND  
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

Report Date **11-APR-2002**

Compliance From 01/01/2001 To 4/11/2002

| ITEM NO<br>PART NO.          | DESCRIPTION<br>SERIAL NO.                                                                         | COMPONENT INSTALLED AND/OR<br>SERVICE/INSPECTION COMPLIED |     |     |     | COMPONENT TIMES AFTER REMOVAL |     |     |                    |
|------------------------------|---------------------------------------------------------------------------------------------------|-----------------------------------------------------------|-----|-----|-----|-------------------------------|-----|-----|--------------------|
|                              |                                                                                                   | C/W                                                       | TSN | TSO | TSR | C/W                           | TSN | TSO | TSR                |
| 322131                       | INSPECT/CHECK RIGHT MAIN GEAR BRAKE RIGHT BRAKE LININGS                                           |                                                           |     |     |     |                               |     |     |                    |
|                              | MOS                                                                                               | 1/17/2001                                                 |     |     |     |                               |     |     |                    |
|                              | HRS                                                                                               | 7494                                                      |     |     |     |                               |     |     |                    |
|                              | AFL                                                                                               | 5466                                                      |     |     |     |                               |     |     |                    |
|                              |                                                                                                   |                                                           |     |     |     | TECH :                        |     |     | INSP :             |
|                              |                                                                                                   |                                                           |     |     |     |                               |     |     | LABOR HRS :        |
|                              |                                                                                                   |                                                           |     |     |     |                               |     |     | SERVICE REMARKS -- |
| 322156                       | INSPECT/CLEAN LEFT ANTI-SKID DETECTOR                                                             |                                                           |     |     |     |                               |     |     |                    |
|                              | MOS                                                                                               | 1/17/2001                                                 |     |     |     |                               |     |     |                    |
|                              | HRS                                                                                               | 7494                                                      |     |     |     |                               |     |     |                    |
|                              | AFL                                                                                               | 5466                                                      |     |     |     |                               |     |     |                    |
|                              |                                                                                                   |                                                           |     |     |     | TECH :                        |     |     | INSP :             |
|                              |                                                                                                   |                                                           |     |     |     |                               |     |     | LABOR HRS :        |
|                              |                                                                                                   |                                                           |     |     |     |                               |     |     | SERVICE REMARKS -- |
| 322171                       | INSPECT/CLEAN RIGHT ANTI-SKID DETECTOR                                                            |                                                           |     |     |     |                               |     |     |                    |
|                              | MOS                                                                                               | 1/17/2001                                                 |     |     |     |                               |     |     |                    |
|                              | HRS                                                                                               | 7494                                                      |     |     |     |                               |     |     |                    |
|                              | AFL                                                                                               | 5466                                                      |     |     |     |                               |     |     |                    |
|                              |                                                                                                   |                                                           |     |     |     | TECH :                        |     |     | INSP :             |
|                              |                                                                                                   |                                                           |     |     |     |                               |     |     | LABOR HRS :        |
|                              |                                                                                                   |                                                           |     |     |     |                               |     |     | SERVICE REMARKS -- |
| 322174                       | OPERATIONAL CHECK ANTI-SKID LIGHTS                                                                |                                                           |     |     |     |                               |     |     |                    |
|                              | MOS                                                                                               | 1/17/2001                                                 |     |     |     |                               |     |     |                    |
|                              | HRS                                                                                               | 7494                                                      |     |     |     |                               |     |     |                    |
|                              | AFL                                                                                               | 5466                                                      |     |     |     |                               |     |     |                    |
|                              |                                                                                                   |                                                           |     |     |     | TECH :                        |     |     | INSP :             |
|                              |                                                                                                   |                                                           |     |     |     |                               |     |     | LABOR HRS :        |
|                              |                                                                                                   |                                                           |     |     |     |                               |     |     | SERVICE REMARKS -- |
| 322206                       | FUNCTIONAL TEST EMERGENCY GEAR EXTENSION CONTROL CABLE                                            |                                                           |     |     |     |                               |     |     |                    |
|                              | MOS                                                                                               | 1/17/2001                                                 |     |     |     |                               |     |     |                    |
|                              | HRS                                                                                               | 7494                                                      |     |     |     |                               |     |     |                    |
|                              | AFL                                                                                               | 5466                                                      |     |     |     |                               |     |     |                    |
|                              |                                                                                                   |                                                           |     |     |     | TECH :                        |     |     | INSP :             |
|                              |                                                                                                   |                                                           |     |     |     |                               |     |     | LABOR HRS :        |
|                              |                                                                                                   |                                                           |     |     |     |                               |     |     | SERVICE REMARKS -- |
| <b>CHAPTER 33-LIGHTS</b>     |                                                                                                   |                                                           |     |     |     |                               |     |     |                    |
| 330228                       | CHARGE EMERGENCY LIGHT BATTERY                                                                    |                                                           |     |     |     |                               |     |     |                    |
|                              | MOS                                                                                               | 6/26/2001                                                 |     |     |     |                               |     |     |                    |
|                              | HRS                                                                                               | 7687                                                      |     |     |     |                               |     |     |                    |
|                              | AFL                                                                                               | 5594                                                      |     |     |     |                               |     |     |                    |
|                              |                                                                                                   |                                                           |     |     |     | TECH :                        |     |     | INSP :             |
|                              |                                                                                                   |                                                           |     |     |     |                               |     |     | LABOR HRS :        |
|                              |                                                                                                   |                                                           |     |     |     |                               |     |     | SERVICE REMARKS -- |
| <b>CHAPTER 34-NAVIGATION</b> |                                                                                                   |                                                           |     |     |     |                               |     |     |                    |
| 340121                       | DRAIN PITOT/STATIC SYSTEM                                                                         |                                                           |     |     |     |                               |     |     |                    |
|                              | MOS                                                                                               | 1/17/2001                                                 |     |     |     |                               |     |     |                    |
|                              | HRS                                                                                               | 7494                                                      |     |     |     |                               |     |     |                    |
|                              | AFL                                                                                               | 5466                                                      |     |     |     |                               |     |     |                    |
|                              |                                                                                                   |                                                           |     |     |     | TECH :                        |     |     | INSP :             |
|                              |                                                                                                   |                                                           |     |     |     |                               |     |     | LABOR HRS :        |
|                              |                                                                                                   |                                                           |     |     |     |                               |     |     | SERVICE REMARKS -- |
| 344616                       | INSPECT EMERGENCY GYRO POWER SUPPLY BATTERY EMERGENCY POWER SUPPLY BATTERY/STAND-BY ATTITUDE GYRO |                                                           |     |     |     |                               |     |     |                    |
|                              | MOS                                                                                               | 6/26/2001                                                 |     |     |     |                               |     |     |                    |
|                              | HRS                                                                                               | 7687                                                      |     |     |     |                               |     |     |                    |
|                              | AFL                                                                                               | 5594                                                      |     |     |     |                               |     |     |                    |
|                              |                                                                                                   |                                                           |     |     |     | TECH :                        |     |     | INSP :             |
|                              |                                                                                                   |                                                           |     |     |     |                               |     |     | LABOR HRS :        |
|                              |                                                                                                   |                                                           |     |     |     |                               |     |     | SERVICE REMARKS -- |
| <b>CHAPTER 52-DOORS</b>      |                                                                                                   |                                                           |     |     |     |                               |     |     |                    |
| 520106                       | INSPECT/LUBRICATE CABIN ENTRANCE DOOR                                                             |                                                           |     |     |     |                               |     |     |                    |
|                              | MOS                                                                                               | 1/17/2001                                                 |     |     |     |                               |     |     |                    |
|                              | HRS                                                                                               | 7494                                                      |     |     |     |                               |     |     |                    |
|                              | AFL                                                                                               | 5466                                                      |     |     |     |                               |     |     |                    |
|                              |                                                                                                   |                                                           |     |     |     | TECH :                        |     |     | INSP :             |
|                              |                                                                                                   |                                                           |     |     |     |                               |     |     | LABOR HRS :        |
|                              |                                                                                                   |                                                           |     |     |     |                               |     |     | SERVICE REMARKS -- |
| 520116                       | OPERATIONAL CHECK CABIN ENTRANCE DOOR                                                             |                                                           |     |     |     |                               |     |     |                    |
|                              | MOS                                                                                               | 1/17/2001                                                 |     |     |     |                               |     |     |                    |
|                              | HRS                                                                                               | 7494                                                      |     |     |     |                               |     |     |                    |
|                              | AFL                                                                                               | 5466                                                      |     |     |     |                               |     |     |                    |
|                              |                                                                                                   |                                                           |     |     |     | TECH :                        |     |     | INSP :             |
|                              |                                                                                                   |                                                           |     |     |     |                               |     |     | LABOR HRS :        |
|                              |                                                                                                   |                                                           |     |     |     |                               |     |     | SERVICE REMARKS -- |
| <b>CHAPTER 53-FUSELAGE</b>   |                                                                                                   |                                                           |     |     |     |                               |     |     |                    |
| 530101                       | INSPECT FUSELAGE (A)                                                                              |                                                           |     |     |     |                               |     |     |                    |
|                              | MOS                                                                                               | 1/17/2001                                                 |     |     |     |                               |     |     |                    |
|                              | HRS                                                                                               | 7494                                                      |     |     |     |                               |     |     |                    |
|                              | AFL                                                                                               | 5466                                                      |     |     |     |                               |     |     |                    |
|                              |                                                                                                   |                                                           |     |     |     | TECH :                        |     |     | INSP :             |
|                              |                                                                                                   |                                                           |     |     |     |                               |     |     | LABOR HRS :        |
|                              |                                                                                                   |                                                           |     |     |     |                               |     |     | SERVICE REMARKS -- |
| 530116                       | INSPECT NOSE COMPARTMENT (A)                                                                      |                                                           |     |     |     |                               |     |     |                    |



A/C Serial No.: 368 A/C Regn No.: N368MD Model:1124A WESTWIND  
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

Report Date **11-APR-2002**

Compliance From 01/01/2001 To 4/11/2002

| ITEM NO<br>PART NO.               | DESCRIPTION<br>SERIAL NO.                                                          | COMPONENT INSTALLED AND/OR<br>SERVICE/INSPECTION COMPLIED |           |     |     | COMPONENT TIMES AFTER REMOVAL |     |     |     | TECH : | INSP :             |
|-----------------------------------|------------------------------------------------------------------------------------|-----------------------------------------------------------|-----------|-----|-----|-------------------------------|-----|-----|-----|--------|--------------------|
|                                   |                                                                                    | C/W                                                       | TSN       | TSO | TSR | C/W                           | TSN | TSO | TSR |        |                    |
|                                   |                                                                                    | MOS                                                       | 1/17/2001 |     |     |                               |     |     |     |        |                    |
|                                   |                                                                                    | HRS                                                       | 7494      |     |     |                               |     |     |     |        | LABOR HRS :        |
|                                   |                                                                                    | AFL                                                       | 5466      |     |     |                               |     |     |     |        | SERVICE REMARKS -- |
| 530131                            | INSPECT COCKPIT (A)                                                                | MOS                                                       | 1/17/2001 |     |     |                               |     |     |     |        |                    |
|                                   |                                                                                    | HRS                                                       | 7494      |     |     |                               |     |     |     |        | LABOR HRS :        |
|                                   |                                                                                    | AFL                                                       | 5466      |     |     |                               |     |     |     |        | SERVICE REMARKS -- |
| 530146                            | INSPECT CABIN (A)                                                                  | MOS                                                       | 1/17/2001 |     |     |                               |     |     |     |        |                    |
|                                   |                                                                                    | HRS                                                       | 7494      |     |     |                               |     |     |     |        | LABOR HRS :        |
|                                   |                                                                                    | AFL                                                       | 5466      |     |     |                               |     |     |     |        | SERVICE REMARKS -- |
| 530161                            | INSPECT REAR COMPARTMENT (A)                                                       | MOS                                                       | 1/17/2001 |     |     |                               |     |     |     |        |                    |
|                                   |                                                                                    | HRS                                                       | 7494      |     |     |                               |     |     |     |        | LABOR HRS :        |
|                                   |                                                                                    | AFL                                                       | 5466      |     |     |                               |     |     |     |        | SERVICE REMARKS -- |
| <b>CHAPTER 54-NACELLES/PYLONS</b> |                                                                                    |                                                           |           |     |     |                               |     |     |     |        |                    |
| 540101U                           | INSPECT NO. 1 ENGINE NACELLE/PYLON (A)                                             | MOS                                                       | 1/17/2001 |     |     |                               |     |     |     |        |                    |
|                                   |                                                                                    | HRS                                                       | 7494      |     |     |                               |     |     |     |        | LABOR HRS :        |
|                                   |                                                                                    | AFL                                                       | 5466      |     |     |                               |     |     |     |        | SERVICE REMARKS -- |
| 540121U                           | INSPECT NO. 2 ENGINE NACELLE/PYLON (A)                                             | MOS                                                       | 1/17/2001 |     |     |                               |     |     |     |        |                    |
|                                   |                                                                                    | HRS                                                       | 7494      |     |     |                               |     |     |     |        | LABOR HRS :        |
|                                   |                                                                                    | AFL                                                       | 5466      |     |     |                               |     |     |     |        | SERVICE REMARKS -- |
| <b>CHAPTER 55-STABILIZERS</b>     |                                                                                    |                                                           |           |     |     |                               |     |     |     |        |                    |
| 550101                            | INSPECT EMPENNAGE (A)                                                              | MOS                                                       | 1/17/2001 |     |     |                               |     |     |     |        |                    |
|                                   |                                                                                    | HRS                                                       | 7494      |     |     |                               |     |     |     |        | LABOR HRS :        |
|                                   |                                                                                    | AFL                                                       | 5466      |     |     |                               |     |     |     |        | SERVICE REMARKS -- |
| 550656                            | CHECK HORIZONTAL STABILIZER AFT SPAR SPLICE-HINGE FITTING OUTBOARD LUGS FOR CRACKS | MOS                                                       | 1/17/2001 |     |     |                               |     |     |     |        |                    |
|                                   |                                                                                    | HRS                                                       | 7494      |     |     |                               |     |     |     |        | LABOR HRS :        |
|                                   |                                                                                    | AFL                                                       | 5466      |     |     |                               |     |     |     |        | SERVICE REMARKS -- |
| <b>CHAPTER 57-WINGS</b>           |                                                                                    |                                                           |           |     |     |                               |     |     |     |        |                    |
| 570101                            | INSPECT LEFT WING (A)                                                              | MOS                                                       | 1/17/2001 |     |     |                               |     |     |     |        |                    |
|                                   |                                                                                    | HRS                                                       | 7494      |     |     |                               |     |     |     |        | LABOR HRS :        |
|                                   |                                                                                    | AFL                                                       | 5466      |     |     |                               |     |     |     |        | SERVICE REMARKS -- |
| 570106                            | INSPECT LEFT AILERON BELLCRANK                                                     | MOS                                                       | 1/17/2001 |     |     |                               |     |     |     |        |                    |
|                                   |                                                                                    | HRS                                                       | 7494      |     |     |                               |     |     |     |        | LABOR HRS :        |
|                                   |                                                                                    | AFL                                                       | 5466      |     |     |                               |     |     |     |        | SERVICE REMARKS -- |
| 570116                            | INSPECT RIGHT WING (A)                                                             | MOS                                                       | 1/17/2001 |     |     |                               |     |     |     |        |                    |
|                                   |                                                                                    | HRS                                                       | 7494      |     |     |                               |     |     |     |        | LABOR HRS :        |
|                                   |                                                                                    | AFL                                                       | 5466      |     |     |                               |     |     |     |        | SERVICE REMARKS -- |
| 570120                            | INSPECT RIGHT AILERON BELLCRANK                                                    | MOS                                                       | 1/17/2001 |     |     |                               |     |     |     |        |                    |
|                                   |                                                                                    | HRS                                                       | 7494      |     |     |                               |     |     |     |        | LABOR HRS :        |
|                                   |                                                                                    | AFL                                                       | 5466      |     |     |                               |     |     |     |        | SERVICE REMARKS -- |
| <b>CHAPTER 71-POWER PLANT</b>     |                                                                                    |                                                           |           |     |     |                               |     |     |     |        |                    |



A/C Serial No.: 368 A/C Regn No.: N368MD Model:1124A WESTWIND  
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

Report Date **11-APR-2002**

Compliance From 01/01/2001 To 4/11/2002

| ITEM NO<br>PART NO. | DESCRIPTION<br>SERIAL NO.    | COMPONENT INSTALLED AND/OR<br>SERVICE/INSPECTION COMPLIED |           |     |     | COMPONENT TIMES AFTER REMOVAL |     |     |     | TECH : | INSP : |
|---------------------|------------------------------|-----------------------------------------------------------|-----------|-----|-----|-------------------------------|-----|-----|-----|--------|--------|
|                     |                              | C/W                                                       | TSN       | TSO | TSR | C/W                           | TSN | TSO | TSR |        |        |
| 710650U             | -- INSP #1 ENG INLET NACELLE |                                                           |           |     |     |                               |     |     |     |        |        |
|                     |                              | MOS                                                       | 1/17/2001 |     |     |                               |     |     |     |        |        |
|                     |                              | HRS                                                       | 7494      |     |     |                               |     |     |     |        |        |
|                     |                              | AFL                                                       | 5466      |     |     |                               |     |     |     |        |        |
| 713650U             | -- INSP #2 ENG INLET NACELLE |                                                           |           |     |     |                               |     |     |     |        |        |
|                     |                              | MOS                                                       | 1/17/2001 |     |     |                               |     |     |     |        |        |
|                     |                              | HRS                                                       | 7494      |     |     |                               |     |     |     |        |        |
|                     |                              | AFL                                                       | 5466      |     |     |                               |     |     |     |        |        |