



CAMP SYSTEMS INTERNATIONAL, LLC
LONG ISLAND MAC ARTHUR AIRPORT
999 MARCONI AVE.
RONKONKOMA, NY 11779

POSTAL

R&S AIRCRAFT INVESTMENTS, LLC
ATTN: YANDELL ROGERS III
P.O. BOX 43
HOUSTON, TX 77001-0043



ModelName: 1124A WESTWIND 368
RegNo: N368MD

PLEASE FILL IN THE INFORMATION REQUESTED BELOW AND RETURN CARD TO
CAMP SYSTEMS, INT'L.

1124 WESTWIND 368

AIRCRAFT MODEL _____

Y 05/02 UNITED STATES OF AMERICA _____

RECORD PRESENT:

AIRCRAFT HOURS _____ **LANDINGS** _____

NO. 1 ENG. HOURS _____ **CYCLES** _____

NO. 2 ENG. HOURS _____ **CYCLES** _____

NO. 3 ENG. HOURS _____ **CYCLES** _____

NO. 4 ENG. HOURS _____ **CYCLES** _____

APU HOURS _____ **STARTS** _____

DATE _____

OWNER: R&S AIRCRAFT INVESTMENTS, LLC
ADDRESS: P.O. BOX 43 HOUSTON TX 77001-0043

OPERATOR: R&S AIRCRAFT INVESTMENTS, LLC
ADDRESS: P.O. BOX 43 HOUSTON TX 77001-0043

PHONE: 713-830-9584
FAX: 713-918-5925

PHONE: 713-830-9584
FAX: 713-918-5925

AIRCRAFT

S/N: 368 **REG NO:** N368MD **MODEL:** 1124A WESTWIND **MANUFACTURER:** GULFSTREAM AEROSPACE CORPORATION

NOTE:
INSPECTION PROGRAM: 3
CERTIFICATE DATE: 11-FEB-1982

UOM	LAST ACTUAL	LAST ACTUAL DATE
HRS	7806	28-FEB-2002
AFL	5706	28-FEB-2002

ENGINE NO. 1

S/N: P-77482 **PART NO:** 3072500-2 **MODEL:** TFE731-3 **MANUFACTURER:** HONEYWELL

INSTALLED DATE: 4/3/1989
A/C HRS: 4215
ENGINE HRS: 3972
ENGINE CYCLES: 2456

UOM	LAST ACTUAL	LAST ACTUAL DATE
HRS	7806	28-FEB-2002
ENC	0	
(AFL)	5706	28-FEB-2002

ENGINE NO. 2

S/N: P77488 **PART NO:** 3072500-2 **MODEL:** TFE731-3 **MANUFACTURER:** HONEYWELL

INSTALLED DATE: 5/31/1993
A/C HRS: 5278
ENGINE HRS: 5227
ENGINE CYCLES: 3867

UOM	LAST ACTUAL	LAST ACTUAL DATE
HRS	7806	28-FEB-2002
ENC	0	
(AFL)	5706	28-FEB-2002



AIRCRAFT Status Report (Work Packages)

Aircraft Model - 1124 WESTWIND
 Owner Name R&S AIRCRAFT INVESTMENTS, LLC
 A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PKG NUMBER	UNIT	ACT	INTERVAL TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
AIRCRAFT												
CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS												
+ 050150U	200 HOUR INSPECTION PKG 1 in PKG 2, 3	MOS HRS/MSC AFL	R		200					26-JUN-2001 7687 5594	7887	31
	REF:											
+ 050300U	400/200 HOUR INSPECTION PKG 2 in PKG 3	MOS HRS/MSC AFL	R		400					26-JUN-2001 7687 5594	8087	45.5
	REF:											
+ 050600U	800/400/200 HOUR INSPECT PKG 3	MOS HRS/MSC AFL	R		800			-38		26-JUL-2000 7325 5360	8087	45.5
	REF:											
+ 057110U	150HR #1 ENGINE INSP NO. 1 PKG 4	MOS HRS/MSC AFL			150					26-JUN-2001 7687 5594		E1 1.5
	REF:											
+ 057110U	150HR #2 ENGINE INSP NO. 2 PKG 5	MOS HRS/MSC AFL			150					26-JUN-2001 7687 5594		E2 1
	REF:											
+ 057120U	300HR #1 ENGINE INSP NO. 1 PKG 6	MOS HRS/MSC AFL			300					16-FEB-2001 7551 5515		E1
	REF:											
+ 057120U	300HR #2 ENGINE INSP NO. 2 PKG 7	MOS HRS/MSC AFL			300					16-FEB-2001 7551 5515		E2
	REF:											

Engine Model- TFE731-3

Report Date **11-APR-2002**

Owner Name R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PKG NUMBER	UNIT	ACT INTERVAL TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
			TSN	TSO	TSR	TSI	ADJ				
ENGINE NO. 1											
CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS											
+ 057110U	NO. 1 ENGINE - 150HR #1 ENGINE INSP										
	PKG 4 in PKG 4,6, 6	MOS						26-JUN-2001			
	REF:	HRS/MS	150					7687	7837	1	
		ENC						5594			
		(AFL)									
+ 057120U	NO. 1 ENGINE - 300HR #1 ENGINE INSP										
	PKG 6 in PKG 6	MOS						16-FEB-2001			
	REF:	HRS/MS	300					7551	7851	1.5	
		ENC						5515			
		(AFL)									

Report Date **11-APR-2002**

Engine Model - TFE731-3

Owner Name R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PKG NUMBER	UNIT	ACT INTERVAL TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
			TSN	TSO	TSR	TSI	ADJ				
ENGINE NO. 2											
CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS											
+ 057110U	NO. 2 ENGINE - 150HR #2 ENGINE INSP PKG 5 in PKG 5,7, 7	MOS HRS/MSC		150					26-JUN-2001 7687	7837	1
	REF:	ENC (AFL)						5594			
+ 057120U	NO. 2 ENGINE - 300HR #2 ENGINE INSP PKG 7 in PKG 7	MOS HRS/MSC		300					16-FEB-2001 7551	7851	1.5
	REF:	ENC (AFL)						5515			

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
AIRCRAFT								
CHAPTER 00 INFORMATION								
000004U	-- ICON HEALTH AND FITNESS	MOS					11-FEB-1982	
		HRS/MS	N/R			0		
	REF:	AFL				0		
CHAPTER 10 PARKING, MOORING, STORE AND RET TO SERV								
+ 100310	CHECK AIRWORTHY DIRECTIVES	MOS					26-JUN-2001	
10.010	PKG 1, 2, 3	HRS/MS	200			7687		
	REF: NO REF	AFL				5594		
+ 100320	CHECK SERVICE BULLETINS	MOS					26-JUN-2001	
10.020	PKG 1, 2, 3	HRS/MS	200			7687		
	REF: NO REF	AFL				5594		
+ 100330	CHECK SERVICE LETTERS	MOS					26-JUN-2001	
10.030	PKG 1, 2, 3	HRS/MS	200			7687		
	REF: NO REF	AFL				5594		
CHAPTER 12 SERVICING								
+ 120160	CHECK NO.1 ENGINE PREFLIGHT COMPLETE	MOS					26-JUN-2001	E1
12.020	PKG 4	HRS/MS	150			7687		
	REF: AMM 5-21-00	AFL				5594		
+ 120161	CHECK NO.2 ENGINE PREFLIGHT COMPLETE	MOS					26-JUN-2001	E2
12.020	PKG 5	HRS/MS	150			7687		
	REF: AMM 5-21-00	AFL				5594		
+ 120150	CHECK PRE-FLIGHT	MOS					26-JUN-2001	
12.010	PKG 1, 2, 3	HRS/MS	200			7687		
	REF: AMM 5-30-00	AFL				5594		
CHAPTER 21 AIR CONDITIONING								
210280	CHECK BLEED AIR DUCT OVERPRESSURE SWITCH	MOS					26-JUL-2000	F3
21.270	PKG 3	HRS/MS	800			7325		
	REF: AMM 21-00-00	AFL				5360		
+ 210276	OPERATIONAL CHECK PRESSURIZATION SWITCHES AND VALVES	MOS					26-JUN-2001	F3
21.030	PKG 2, 3	HRS/MS	400			7687		
	REF: AMM 21-00-00	AFL				5594		
210641	ANTICIPATOR, TEMPERATURE SENSOR	MOS					11-FEB-1982	F4
21.310	548486-1	HRS/MS	O/C	0		0		
	SN-UNKNOWN	AFL				0		
	REF: AMM 21-60-00							

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
210673 21.430	ASPIRATOR, ENVIRONMENTAL CONTROL SYSTEM PN SN-UNKNOWN REF: AMM 21-50-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0	F5	
210661 21.350	BULB, CABIN TEMPERATURE INDICATOR SENSOR PN SN-UNKNOWN REF: AMM 21-60-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0	F4	
210626 21.450	CONTROL BOX, CABIN TEMPERATURE 548482-5 030C154 REF: AMM 21-60-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0	F4	
210118 21.360	CONTROL UNIT, BLEED AIR CONTROL RIGHT 3213894-4-1 P402C REF: NO REF	MOS HRSMSC AFL	O/C		0					06-NOV-1990 4731 3324	F5	
210108 21.360	CONTROL UNIT, BLEED AIR LEFT 32131894-4-1 P336C REF: NO REF	MOS HRSMSC AFL	O/C							06-NOV-1990 4731 3324	F5	
210176 21.180	CONTROLLER, CABIN AIR PRESSURE 130398-3 31340 REF: AMM 21-30-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0	F3 \$1455. 3	
210178 21.480	CLEAN FILTER PKG 3 REF: AMM 21-30-00	MOS HRSMSC AFL	800							26-JUL-2000 7325 5360	F3	
210606 21.240	EXCHANGER, REFRIGERATION UNIT HEAT PN SN-UNKNOWN REF: AMM 21-50-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0	F5 20	
210636 21.300	FAN, CABIN TEMPERATURE 5783661-5 120713 REF: AMM 21-60-00	MOS HRSMSC AFL	O/C							04-APR-1996 5747 4430	F4 \$302.	
210206 21.390	INDICATOR, CABIN ALTITUDE/PRESSURE 4883747-1 495 REF: AMM 21-31-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0	F3	
210208 21.400	INDICATOR, CABIN RATE-OF-CLIMB 4883788 SN-UNKNOWN REF: AMM 21-31-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0	F3	

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL



AIRCRAFT Status Report

Report Date **11-APR-2002**

Aircraft Model - **1124 WESTWIND**
 Owner Name - **R&S AIRCRAFT INVESTMENTS, LLC**
 A/C Serial #: **368 A/C Reg. #: N368MD**

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
210633	INDICATOR, CABIN TEMPERATURE										F3	
21.410	883767-501	MOS								11-FEB-1982		
	197	HRS/MSC	O/C	0					0			
	REF: AMM 21-60-00	AFL							0			
210156	PLENUM, MIXING										F4	
21.160	5-783584-1	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C	0					0			
	REF: NO REF	AFL							0			
210241	REGULATOR, ABSOLUTE AIR PRESSURE LOWER										F3	
21.200	102466-1	MOS								11-FEB-1982		
	1203419	HRS/MSC	O/C	0					0		4	
	REF: AMM 21-30-00	AFL							0			
210221	REPLACE LOWER INLET AIR FILTER ELEMENT										F3	
21.080	PKG 3	MOS								26-JUL-2000		
	1203419	HRS/MSC	800						7325			
	REF: AMM 21-30-00	AFL							5360			
210236	REGULATOR, ABSOLUTE AIR PRESSURE UPPER										F3	
21.200	102466-1	MOS								11-FEB-1982		
	313613	HRS/MSC	O/C	0					0		4	
	REF: AMM 21-30-00	AFL							0			
210621	REGULATOR, PNEUMATIC PRESSURE										F5	
21.280	PN	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C	0					0			
	REF: AMM 21-50-00	AFL							0			
210246	RELAY, PNEUMATIC										F3	
21.210	107312-2	MOS								22-OCT-1982	\$383.	
	11-9440	HRS/MSC	O/C	0					482		4	
	REF: AMM 21-30-00	AFL										
210619	SENSOR, 35 DEGREE TEMPERATURE										F5	
21.420	783649-1	MOS								11-FEB-1982		
	071C730	HRS/MSC	O/C	0					0			
	REF: AMM 21-50-00	AFL							0			
+ 210622	INSPECT 35 DEGREE DUCT SENSOR										F5	
21.420	PKG 1, 2, 3	MOS								26-JUN-2001		
		HRS/MSC	200						7687			
	REF: AMM 21-50-00	AFL							5594			
210631	SENSOR, CABIN TEMPERATURE										F4	
21.460	548484-1	MOS								11-FEB-1982		
	070C482	HRS/MSC	O/C	0					0			
	REF: AMM 21-60-00	AFL							0			
210646	SENSOR, HIGH TEMPERATURE										F4	
21.320	627962-2	MOS								11-FEB-1982		
	011C955	HRS/MSC	O/C	0					0			
	REF: AMM 21-60-00	AFL							0			

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
210665 21.440	SENSOR, REFRIGERATION TEMPERATURE CONTROL 3783649-1 11166 REF: NO REF	MOS HRS/MSC AFL	O/C	0						03-NOV-1984 2044	F3	
210666 21.050	SEPARATOR, WATER 179510-1 31535 REF: AMM 21-70-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F5	
+ 210671 21.050	CLEAN/REPLACE CONDENSER/FILTER PKG 1, 2, 3 REF: AMM 21-70-00	MOS HRS/MSC AFL	200							26-JUN-2001 7687 5594	F5 1	
210286 21.380	SWITCH, CABIN AIR SELECTOR 823073-501 8128133 REF: NO REF	MOS HRS/MSC AFL	O/C	0 0						11-FEB-1982 0 0	F3	
210656 21.340	SWITCH, OVERPRESSURE 3-783646-2 194 REF: AMM 21-60-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F5	
210651 21.330	SWITCH, OVERTEMPERATURE 3-783645-1 211 REF: AMM 21-60-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F4	
210623 21.440	TANK, AUXILIARY ENVIRONMENTAL CONTROL SYSTEM VOLUME 131358-1 311533 REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F2	
210677 21.290	TURBINE, COOLING 572375-2 56-133 REF: AMM 21-50-00	MOS HRS/MSC AFL	O/C		0					15-MAR-1995 5585 4260	F5	
210681 21.290	CHANGE OIL PKG 1, 2, 3 REF: AMM 21-50-00	MOS HRS/MSC AFL	200							26-JUN-2001 7687 5594	F5	
210601 21.230	UNIT, REFRIGERATION 3783648-1 120-333 REF: AMM 21-50-00	MOS HRS/MSC AFL	O/C	0						21-AUG-1983 1200 667	F5	
210616 21.260	VALVE, 35 DEGREE TEMPERATURE CONTROL 898730-1 SN-UNKNOWN REF: AMM 21-50-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F5	

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
210121 21.060	VALVE, AIR CONDITIONING PRESSURE RELIEF 3-783644-1 162 REF: AMM 21-11-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F5	
210101 21.010	VALVE, BLEED AIR SWITCHING LEFT 3783647-3 P511 REF: AMM 21-11-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F5 \$1698.	
+ 210102 21.500	VISUALLY INSPECT PKG 2, 3 REF: AMM 5-20-05	MOS HRS/MSC AFL	400							26-JUN-2001 7687 5594	F5	
210111 21.010	VALVE, BLEED AIR SWITCHING RIGHT 3783647-3 P506 REF: AMM 21-11-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F5 \$1698.	
+ 210112 21.500	VISUALLY INSPECT PKG 2, 3 REF: AMM 5-20-05	MOS HRS/MSC AFL	400							26-JUN-2001 7687 5594	F5	
210146 21.130	VALVE, CABIN AIR CHECK LEFT PN SN-UNKNOWN REF: AMM 21-20-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F4	
210151 21.130	VALVE, CABIN AIR CHECK RIGHT PN SN-UNKNOWN REF: AMM 21-20-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F4	
210153 21.370	VALVE, COLD AIR CHECK PN SN-UNKNOWN REF: AMM 21-20-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F5	
210166 21.150	VALVE, CONDITION AIR PILOT PN SN-UNKNOWN REF: AMM 21-20-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F3	
210143 21.470	VALVE, EMERGENCY AIR CHECK PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F5	
210141 21.120	VALVE, EMERGENCY AIR SHUTOFF 321760-2-1 P1222 REF: AMM 21-14-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F5 \$1099.	

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
210161	VALVE, FLOOD DUCT										F4	
21.140	PN	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MS	O/C	0					0			
	REF: AMM 21-20-00	AFL							0			
210136	VALVE, GROUND BY-PASS										F5	
21.110	4-783622-1	MOS							11-FEB-1982		\$1099.	
	P4380	HRS/MS	O/C	0					0			
	REF: AMM 21-13-00	AFL							0			
210211	REPLACE UPPER INLET AIR FILTER ELEMENT										F3	
21.080	PKG 3	MOS							26-JUL-2000			
		HRS/MS	800						7325			
	REF: AMM 21-30-00	AFL							5360			
210611	VALVE, HOT AIR										F5	
21.250	321760-2-1	MOS							11-FEB-1982		\$1099.	
	P1108	HRS/MS	O/C	0					0			
	REF: AMM 21-60-00	AFL							0			
210158	VALVE, HOT AIR CHECK										F4	
21.380	PN	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MS	O/C	0					0			
	REF: NO REF	AFL							0			
210226	VALVE, ISOBARIC SHUTOFF										F3	
21.070	3-783105	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MS	O/C	0					0			
	REF: AMM 21-30-00	AFL							0			
210171	VALVE, MANUAL DEFOG										F3	
21.170	PN	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MS	O/C	0					0			
	REF: AMM 21-20-00	AFL							0			
210181	VALVE, MANUAL DUMP										F3	
21.190	5-723018-401	MOS							11-FEB-1982			
	21563	HRS/MS	O/C	0					0			
	REF: AMM 21-30-00	AFL							0			
210186	VALVE, NORMAL OUTFLOW										F4	
21.040	130374-6	MOS							11-FEB-1982			
	110870	HRS/MS	O/C	0					0			
	REF: AMM 21-30-00	AFL							0			
210256	VALVE, PRESSURE SOLENOID LOWER										F3	
21.220	3783686	MOS							11-FEB-1982			
	175	HRS/MS	O/C	0					0			
	REF: AMM 21-30-00	AFL							0			
210251	VALVE, PRESSURE SOLENOID UPPER										F3	
21.220	3783686	MOS							11-FEB-1982			
	214	HRS/MS	O/C	0					0			
	REF: AMM 21-30-00	AFL							0			

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
210131 21.100	VALVE, RAM AIR SHUTOFF 398712-1-1 P222 REF: AMM 21-12-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F5	
210196 21.040	VALVE, SAFETY OUTFLOW 103278-8 11905 REF: AMM 21-30-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F4	
210261 21.160	VENTURI, AIRFLOW 131052-1 703075 REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F3	
210266 21.090	INSPECT/CLEAN SCREEN REF: NO REF	MOS HRS/MSC AFL	O/C							11-FEB-1982 0 0	F3	
CHAPTER 22	AUTO FLIGHT											
220166 22.020	AMPLIFIER, NO.1 AUTOPILOT SERVO 622-3108-016 2120LNR REF: AMM 22-10-03	MOS HRS/MSC AFL	O/C							27-AUG-1996	F3 1	
220156 22.050	COMPUTER, AUTO PILOT 522-2901-016 2198 REF: AMM 22-13-13	MOS HRS/MSC AFL	O/C			4165 3382				15-FEB-1995 5554 4242	F3	
220163 22.040	COMPUTER, AUTOPILOT YAW DAMPER 622-3167-028 4078 REF: AMM 22-10-05	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F3	
221021 22.030	CONTROLLER, AIR DATA NO. 1 590A-3J SN-UNKNOWN REF: AMM 22-10-04	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F3	
+ 340146 34.050 ASSOCIATED	LEAK CHECK LEFT STATIC SYSTEM REF: AMM 34-10-01	MOS HRS/MSC AFL	24							18-JAN-2001 7494 5466	MANDATORY F1 18-JAN-2003	
+ 340151 34.050 ASSOCIATED	LEAK CHECK RIGHT STATIC SYSTEM REF: AMM 34-10-01	MOS HRS/MSC AFL	24							18-JAN-2001 7494 5466	MANDATORY F1 18-JAN-2003	
221031 22.030	CONTROLLER, AIR DATA NO. 2 590A-3J1 SN-UNKNOWN REF: AMM 22-10-04	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F3	

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
+ 340146	LEAK CHECK LEFT STATIC SYSTEM									MANDATORY	F1	
34.050		MOS	24						18-JAN-2001	18-JAN-2003		
	ASSOCIATED	HRS/MSC							7494			
	REF: AMM 34-10-01	AFL							5466			
+ 340151	LEAK CHECK RIGHT STATIC SYSTEM									MANDATORY	F1	
34.050		MOS	24						18-JAN-2001	18-JAN-2003		
	ASSOCIATED	HRS/MSC							7494			
	REF: AMM 34-10-01	AFL							5466			
222001	CONTROLLER, ALTITUDE PRESELECT										F3	
22.090	622-2923-066	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C	0					0			
	REF: NO REF	AFL		0					0			
220161	CONTROLLER, AUTOPILOT										F3	
22.010	792-6348-002	MOS							11-FEB-1982			
	2759	HRS/MSC	O/C	0					0		1	
	REF: AMM 22-10-02	AFL							0			
220181	MOUNT, AUTOPILOT AILERON SERVO										F5	
22.080	792-6783-001	MOS							11-FEB-1982			
	1191	HRS/MSC	O/C	0					0			
	REF:	AFL							0			
220191	MOUNT, AUTOPILOT ELEVATOR SERVO										F5	
22.080	792-6783-001	MOS							11-FEB-1982			
	1160	HRS/MSC	O/C	0					0			
	REF:	AFL							0			
220201	MOUNT, AUTOPILOT RUDDER SERVO										F5	
22.080	792-6783-001	MOS							11-FEB-1982			
	1166	HRS/MSC	O/C	0					0			
	REF:	AFL							0			
220150	PANEL, AUTOPILOT										F3	
22.060	622-0141-023	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C						0			
	REF: AMM 22-11-02	AFL							0			
220176	SERVO, AUTOPILOT AILERON										F5	
22.070	792-6781-001	MOS							15-FEB-1995			
	726	HRS/MSC	O/C		5554				5554			
	REF: AMM 22-10-06(1124),22-11-07(1124A)	AFL			4242				4242			
220186	SERVO, AUTOPILOT ELEVATOR										F5	
22.070	792-6781-001	MOS							15-FEB-1995			
	791	HRS/MSC	O/C		5554				5554			
	REF: AMM 22-10-06(1124),22-11-07(1124A)	AFL			4242				4242			
220196	SERVO, AUTOPILOT RUDDER										F5	
22.070	792-6781-001	MOS							11-FEB-1982			
	3915	HRS/MSC	O/C	0					0			
	REF: AMM 22-10-06(1124),22-11-07(1124A)	AFL							0			
CHAPTER 23 COMMUNICATIONS												

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Report Date **11-APR-2002**

Aircraft Model - **1124 WESTWIND**
Owner Name - **R&S AIRCRAFT INVESTMENTS, LLC**
A/C Serial #: **368** A/C Reg. #: **N368MD**

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
230450U	-- REPLACE BEACON BATTERY	MOS								17-OCT-1998	?	
	REF:	HRS/MSC								6520		
		AFL								4889		
+ 230218	INSPECT/CHECK STATIC DISCHARGE WICK RESISTANCE	MOS								26-JUN-2001		F1
23.120	PKG 2, 3	HRS/MSC	400							7687		
	REF: AMM 23-60-00	AFL								5594		
230166	RENEW FCC RADIO/TELEPHONE LICENSE	MOS	60							27-OCT-1999	27-OCT-2004	F3
23.100		HRS/MSC								6961		
	REF: See Workcard	AFL								5135		
238004U	-- INTERCOM, COPILOTS NAT LTD	MOS								15-APR-1993		
	AA80-020	HRS/MSC	O/C							5252		
	9688	AFL								3907		
	REF:											
238006U	-- INTERCOM, PILOTS NAT LTD.	MOS								15-APR-1993		
	AA80020	HRS/MSC	O/C	0						5252		
	9689	AFL								3907		
	REF:											
230111	AMPLIFIER, HF POWER	MOS								26-SEP-1995		F3
23.030	622-2883-001	HRS/MSC	O/C							5707		
	1033	AFL								4380		
	REF: AMM REF BELOW											
230156	ANTENNA, RADIO/TELEPHONE	MOS								11-FEB-1982		F1
23.110	121-0011-000	HRS/MSC	O/C	0						0		
	3272	AFL								0		
	REF: AMM 23-21-00											
230136	ANTENNA, VHF BLADE	MOS								11-FEB-1982		F1
23.070	DMC-81-1	HRS/MSC	O/C	0						0		
	387	AFL								0		
	REF: AMM 23-20-00											
230131	ANTENNA, VHF FIN CAP	MOS								11-FEB-1982		F1
23.060	VFS-10-90-2	HRS/MSC	O/C	0						0		5
	866	AFL								0		
	REF: AMM 23-20-00											
230399	BEACON, VOICE RECORDER	MOS								09-NOV-1996		T1
23.130	DK-100	HRS/MSC	O/C							5951		
	DL4928	AFL								4589		
	REF: NO REF											
230171	CONTROL, COMMUNICATION 1	MOS								09-JAN-1986		F3
23.140	622-4523-011	HRS/MSC	O/C	0						2812		
	SN-UNKNOWN	AFL								1743		
	REF: NO REF											

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
230181 23.140	CONTROL, COMMUNICATION 2 622-4523-003 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0					09-JAN-1986 2812 1743	F3	
230196 23.150	CONTROL, NO.1 AUDIO CENTER 522-3763-001 3747 REF: AMM 23-50-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982 0 0	F3	
230201 23.150	CONTROL, NO.2 AUDIO CENTER 522-3763-001 3749 REF: AMM 23-50-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982 0 0	F3	
230116 23.040	COUPLER, HF ANTENNA 622-2884-001 2427 REF: AMM REF BELOW	MOS HRS/MSC AFL	O/C	5702 4372					16-AUG-1995 5702 4372	F3	
230101 23.010	PANEL, HF CONTROL 622-4545-001 SN-UNKNOWN REF: AMM REF BELOW	MOS HRS/MSC AFL	O/C	0					11-FEB-1982 0 0	F3	
230106 23.020	RECEIVER/EXCITER, HF 622-5337-001 1554 REF: AMM REF BELOW	MOS HRS/MSC AFL	O/C						26-SEP-1995 5707 4380	F3	
230151 23.100	RECEIVER/TRANSMITTER, RADIO/TELEPHONE 400-0033-000 603 REF: AMM 23-21-00	MOS HRS/MSC AFL	O/C						29-JUL-1994 5472 4150	F3	
230206 23.130	RECORDER, COCKPIT VOICE 89094-003111 A01001 REF: NO REF	MOS HRS/MSC AFL	O/C						16-AUG-1995 5702 4372	T1	
230400 23.130	CLEAN/TEST BEACON REF: NO REF	MOS HRS/MSC AFL	6						06-NOV-2001 7774 5641	06-MAY-2002 T1	
230207 23.130	REPLACE BATTERY REF: NO REF	MOS HRS/MSC AFL							17-OCT-1998 6520 4889	? T1	
230121 23.050	TRANSCIVER, VHF NO. 1 622-1334-002 4589 REF: AMM 23-20-00	MOS HRS/MSC AFL	O/C	0					24-JUN-1991 4880 3495	F3	

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
230126	TRANSCIVER, VHF NO. 2										F3	
23.050	622-1879-002	MOS								28-MAY-1991		
	16718	HRS/MS	O/C							4877		
	REF: AMM 23-20-00	AFL								3493		
230146	UNIT, RADIO/TELEPHONE CABIN										F4	
23.090	400-0030-004	MOS								06-FEB-1989		
	77790	HRS/MS	O/C				0			4149		
	REF: AMM 23-21-00	AFL								2658		
230141	UNIT, RADIO/TELEPHONE COCKPIT										F3	
23.080	400-0032-002	MOS								11-FEB-1982		
	2506	HRS/MS	O/C				0			0		
	REF: AMM 23-21-00	AFL								0		
230191	UNIT, UHF COMMUNICATION REMOTE DISPLAY										F3	
23.140	622-1945-011	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C				0			0		
	REF: NO REF	AFL					0			0		
CHAPTER 24 ELECTRICAL POWER												
+ 241653	CHECK CIRCUIT BREAKER RESISTANCE/INSPECT BUS										F3	
24.140	PKG 3	MOS								26-JUL-2000		
		HRS/MS	800							7325		
	REF: AMM 24-50-00	AFL								5360		
+ 241655	INSPECT DISTRIBUTION BUS CIRCUIT BREAKER										F3	
24.150	PKG 3	MOS								26-JUL-2000		
		HRS/MS	800							7325		
	REF: AMM 24-50-00	AFL								5360		
+ 241657	INSPECT TEST PRIORITY BUS DIODES										F3	
24.160	PKG 3	MOS								26-JUL-2000		
		HRS/MS	800							7325		
	REF: AMM 24-50-00	AFL								5360		
240156	BATTERY, LEFT										F2	
24.030	4833517-1	MOS								09-NOV-1996	\$2100.	
	8812674	HRS/MS	O/C							5951	1	
	REF: AMM 24-30-00	AFL								4589		
240168	ANALYZE										F2	
24.030		MOS								09-NOV-1996		
		HRS/MS	C/C							5951		
	REF: NO REF	AFL								4589		
+ 240161	CHECK ELECTROLYTE LEVEL										F2	
24.030	PKG 1, 2, 3	MOS								26-JUN-2001		
		HRS/MS	200							7687	1	
	REF: AMM 12-10-06	AFL								5594		
240166	DEEP CYCLE										F2	
24.030	PKG 1, 2, 3	MOS								06-NOV-2001		
		HRS/MS	200							7774	2	
	REF: AMM 12-10-06	AFL								5641		

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
240171	BATTERY, RIGHT									F2	
24.020	4833517-1	MOS						09-NOV-1996		\$2100.	
	8506152	HRS/MSC	O/C					5951		1	
	REF: AMM 24-30-00	AFL						4589			
240184	ANALYZE									F2	
24.020		MOS						09-NOV-1996			
		HRS/MSC	C/C					5951			
	REF: NO REF	AFL						4589			
+ 240176	CHECK ELECTROLYTE LEVEL									F2	
24.020	PKG 1, 2, 3	MOS						26-JUN-2001			
		HRS/MSC	200					7687		1	
	REF: AMM 12-10-06	AFL						5594			
240181	DEEP CYCLE									F2	
24.020	PKG 1, 2, 3	MOS						06-NOV-2001			
		HRS/MSC	200					7774		2	
	REF: AMM 12-10-06	AFL						5641			
240111	BLOWER, INVERTER COOLING									F2	
24.100	M125J-9A1	MOS						11-FEB-1982			
	200	HRS/MSC	O/C			0		0			
	REF: AMM 24-20-00	AFL						0			
240136	BOX, D.C. CONTACTOR LEFT									F5	
24.050	PN	MOS						11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C			0		0			
	REF: NO REF	AFL						0			
240141	BOX, D.C. CONTACTOR RIGHT									F5	
24.050	PN	MOS						11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C			0		0			
	REF: NO REF	AFL						0			
240146	CONTROL UNIT, GENERATOR NO. 1									F5	
24.040	5833515-1	MOS						30-NOV-1989			
	6681927M1	HRS/MSC	O/C					4430		1	
	REF: AMM 24-30-00	AFL						2987			
240151	CONTROL UNIT, GENERATOR NO. 2									F5	
24.040	5833515-1	MOS						01-MAY-1990			
	663958M1	HRS/MSC	O/C					4578		1	
	REF: AMM 24-30-00	AFL						3154			
240116	GENERATOR, STARTER NO. 1									OVERHAUL	E1
24.010	23065-018-1	MOS						06-NOV-2001			\$813.
	3684	HRS/MSC	1000					7774	?	1	
	REF: AMM 80-10-00	AFL						5641			
+ 240121	CHECK BRUSH WEAR/TENSION										E1
24.010	PKG 4	MOS						06-NOV-2001			
		HRS/MSC	150					7774		.5	
	REF: See Workcard	AFL						5641			

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
+ 240118 24.170	INSPECT PKG 4 REF: AMM 5-21-00	MOS HRS/MSC AFL	150							06-NOV-2001 7774 5641	E1	
+ 240123 24.010	INSPECT SPLINE PKG 4 REF: AMM	MOS HRS/MSC AFL	150							06-NOV-2001 7774 5641	E1 1	
240126 24.010	GENERATOR, STARTER NO. 2 23065-018-1 2562 REF: AMM 80-10-00	MOS HRS/MSC AFL	1000							06-NOV-2001 7774 5641	OVERHAUL E2 \$813. 1	
+ 240131 24.010	CHECK BRUSH WEAR/TENSION PKG 5 REF: See Workcard	MOS HRS/MSC AFL	150							06-NOV-2001 7774 5641	E2	
+ 240128 24.170	INSPECT PKG 5 REF: AMM 5-21-00	MOS HRS/MSC AFL	150							06-NOV-2001 7774 5641	E2	
+ 240133 24.010	INSPECT SPLINE PKG 5 REF: AMM 80-10-00	MOS HRS/MSC AFL	150							06-NOV-2001 7774 5641	E2 1	
240196 24.050	INDICATOR, BATTERY TEMPERATURE 4883754-501 1955 REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F3	
240101 24.080	INVERTER, NO. 1 6833508-501 C0253094 REF: AMM 24-20-00	MOS HRS/MSC AFL	O/C	0						12-JUL-1989 4305 2845	F2 \$1150. 1	
240106 24.080	INVERTER, NO. 2 6833508-501 1135 REF: AMM 24-20-00	MOS HRS/MSC AFL	O/C	0						09-DEC-1985 2762 1713	F2 \$1150. 1	
241651 24.120	METER, VOLT/AMP 6883091-513 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0		
241601 24.130	POWER SUPPLY, VHF EMERGENCY COMMUNICATION 501-1015-02 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0		

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
241606 24.130	INSPECT BATTERY	MOS								11-OCT-1990		
	REF: NO REF	HRS/MSC AFL	O/C							4718 3309		
240211 24.060	RECEPTACLE, EXTERNAL POWER	MOS								11-FEB-1982	F1	
	PN	HRS/MSC AFL	O/C	0						0 0		
+ 240203 24.070	FUNCTIONALLY CHECK BATTERY TEMPERATURE AND WARNING SYSTEM	MOS								26-JUN-2001	F3	
	PKG 1, 2, 3	HRS/MSC AFL	200							7687 5594		
	REF: AMM 24-40-00											
240186 24.030	THERMISTOR, BATTERY LEFT	MOS								11-JAN-1989	F2	
	PN	HRS/MSC AFL	O/C	0						4127 2632		
	REF: See Workcard											
240191 24.020	THERMISTOR, BATTERY RIGHT	MOS								11-JAN-1989	F2	
	PN	HRS/MSC AFL	O/C	0						4127 2632		
	REF: NO REF											
240103 24.090	VOLTMETER, AC LEFT	MOS								11-FEB-1982	F3	
	3883035-501	HRS/MSC AFL	O/C	0						0 0		
	HH9400											
	REF: NO REF											
240108 24.090	VOLTMETER, AC RIGHT	MOS								11-FEB-1982	F3	
	3883035-501	HRS/MSC AFL	O/C	0						0 0		
	JC1215											
	REF: NO REF											
240143 24.110	VOLTMETER, DC LEFT	MOS								11-FEB-1982	F3	
	6883091-505	HRS/MSC AFL	O/C	0						0 0		
	H69513											
	REF: NO REF											
240148 24.110	VOLTMETER, DC RIGHT	MOS								25-FEB-1994	F3	
	6883091-505	HRS/MSC AFL	O/C	0						5408 4066		
	JD1421											
	REF: NO REF											
CHAPTER 25	EQUIPMENT/FURNISHINGS											
+ 250162 25.050	INSPECT FIRST AID KIT	MOS	12							06-NOV-2001	06-NOV-2002	
	REF: NO REF	HRS/MSC AFL								7774 5641		
+ 250156 25.050	INSPECT LIFE PRESERVERS	MOS	12							06-NOV-2001	06-NOV-2002	
	REF: NO REF	HRS/MSC AFL								7774 5641		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
250141 25.040	DISPLAY, CABIN INFORMATION 32940-004 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL								11-FEB-1982 0 0	F4	
250146 25.040	OPERATIONAL CHECK REF: NO REF	MOS HRS/MSC AFL								11-FEB-1982 0 0	F4	
250116 25.020	INERTIA REEL, COPILOT PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL								11-FEB-1982 0 0	F3	
250111 25.020	INERTIA REEL, PILOT PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL								11-FEB-1982 0 0	F3	
250106 25.010	SEAT, COPILOT 1024-0 SN-UNKNOWN REF: AMM 25-10-01	MOS HRS/MSC AFL								11-FEB-1982 0 0	F3	
250101 25.010	SEAT, PILOT 1025-0 SN-UNKNOWN REF: AMM 25-10-01	MOS HRS/MSC AFL								11-FEB-1982 0 0	F3	
250131 25.030	SEATBELT, COPILOT PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL								11-FEB-1982 0 0	F3	
250121 25.030	SEATBELT, PILOT PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL								11-FEB-1982 0 0	F3	
250166 25.060	TRANSMITTER, EMERGENCY LOCATOR 607690-2 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL								11-FEB-1982 0 0	F4	
CHAPTER 26	FIRE PROTECTION											
+ 260186 26.020	OPERATIONAL CHECK FIRE PROTECTION SYSTEM PKG 2, 3 REF: AMM 26-00-00	MOS HRS/MSC AFL								26-JUN-2001 7687 5594	F3	
+ 260148 26.010	REPLACE LEFT FIRE EXTINGUISHER NO.1 CARTRIDGE REF: AMM 26-20-00	MOS HRS/MSC AFL								17-JAN-2001 17-JAN-2005	F5	

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
+ 260153 26.010	REPLACE LEFT FIRE EXTINGUISHER NO.2 CARTRIDGE	MOS	48								SCRAP 17-JAN-2005	F5
	REF: AMM 26-20-00	HRS/MS AFL										
+ 260158 26.015	REPLACE RIGHT FIRE EXTINGUISHER NO.1 CARTRIDGE	MOS	48								SCRAP 17-JAN-2005	F5
	REF: AMM 26-20-00	HRS/MS AFL										
+ 260163 26.015	REPLACE RIGHT FIRE EXTINGUISHER NO.2 CARTRIDGE	MOS	48								SCRAP 17-JAN-2005	F5
	REF: AMM 26-20-00	HRS/MS AFL										
260176 26.030	EXTINGUISHER, CABIN PORTABLE MODEL 2-10	MOS				13					21-JAN-1989	F4
	U-329516	HRS/MS AFL	O/C			0					4131 2636	
	REF: AMM 5-10-00											
260182 26.030	DISCHARGE VALVE OVERHAUL AND REFILL CABIN FIRE EXINGUISHER	MOS	72								06-NOV-2001 7774 5641	06-NOV-2007 F3
	REF: MSC SIL 1124-25-059R1	HRS/MS AFL										
260183 26.030	HYDROSTATIC TEST CABIN FIRE EXTINGUISHER	MOS	144								01-JAN-1995 01-JAN-2007	F4
	REF: See Workcard	HRS/MS AFL										
+ 260184 26.030	INSPECT CABIN FIRE EXTINGUISHER PKG 1, 2, 3	MOS	200								26-JUN-2001 7687 5594	F4
	REF: AMM 26-20-00	HRS/MS AFL										
+ 260180 26.060	VISUAL INSPECTION CABIN FIRE EXTINGUISHER	DAYS	30								06-NOV-2001 7774 5641	06-DEC-2001 F3
	REF: NO REF	HRS/MS AFL										
260181 26.030	WEIGHT CHECK CABIN FIRE EXTINGUISHER	MOS	12								26-JUN-2001 7687 5594	26-JUN-2002 F4
	REF: AMM 5-10-00	HRS/MS AFL										
260166 26.030	EXTINGUISHER, COCKPIT PORTABLE MODEL 2-10	MOS				13					21-JAN-1989	F3
	U-329659	HRS/MS AFL	O/C			0					4131 2636	
	REF: AMM 5-10-00											
260172 26.030	DISCHARGE VALVE OVERHAUL AND REFILL COCKPIT FIRE EXTINGUISHER	MOS	72								06-NOV-2001 7774 5641	06-NOV-2007 F3
	REF: MSC SIL 1124-25-059R1	HRS/MS AFL										

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
260173 26.030	HYDROSTATIC TEST COCKPIT FIRE EXTINGUISHER	MOS	144							01-JAN-1995	01-JAN-2007	F3
	REF: MSC SIL 1124-25-059R1	HRS/MS AFL										
+ 260174 26.030	INSPECT COCKPIT FIRE EXTINGUISHER PKG 1, 2, 3	MOS								26-JUN-2001		F3
	REF: AMM 26-20-00	HRS/MS AFL	200							7687 5594		
+ 260169 26.060	VISUAL INSPECTION COCKPIT FIRE EXTINGUISHER	DAYS	30							06-NOV-2001	06-DEC-2001	F3
	REF: NO REF	HRS/MS AFL								7774 5641		
260171 26.030	WEIGHT CHECK COCKPIT FIRE EXTINGUISHER	MOS	12							26-JUN-2001	26-JUN-2002	F3
	REF: AMM 5-10-00	HRS/MS AFL								7687 5594		
260111 26.010	EXTINGUISHER, FIRE LEFT 3643507-1 02447C1	MOS						0		11-FEB-1982		F5 \$795.
	REF: AMM 26-20-00	HRS/MS AFL	O/C					0		0		
260121 26.010	HYDROSTATIC TEST	MOS	60								MANDATORY	F5
	REF: AMM 5-10-00	HRS/MS AFL								06-NOV-2001	06-NOV-2006	
+ 260146 26.010	RECORD DATE STAMPED ON NEW CARTRIDGE (SERVICE LIFE)	MOS	72							17-JAN-2001	17-JAN-2007	F5
	REF: AMM 26-20-00	HRS/MS AFL								7774 5641		
+ 260151 26.010	RECORD DATE STAMPED ON NEW CARTRIDGE (SERVICE LIFE)	MOS	72							17-JAN-2001	17-JAN-2007	F5
	REF: AMM 26-20-00	HRS/MS AFL										
+ 260148 26.010 ASSOCIATED	REPLACE LEFT FIRE EXTINGUISHER NO.1 CARTRIDGE	MOS	48							17-JAN-2001	17-JAN-2005	F5
	REF: AMM 26-20-00	HRS/MS AFL										
+ 260153 26.010 ASSOCIATED	REPLACE LEFT FIRE EXTINGUISHER NO.2 CARTRIDGE	MOS	48							17-JAN-2001	17-JAN-2005	F5
	REF: AMM 26-20-00	HRS/MS AFL										
260116 26.010	WEIGHT CHECK	MOS								17-JAN-2001		F5
	REF: See Workcard	HRS/MS AFL	O/C							7494 5466		

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
260126	EXTINGUISHER, FIRE RIGHT										F5	
26.015	23700004	MOS							10-JAN-1994		\$795.	
	02429C1	HRS/MSC	O/C			0			5382			
	REF: AMM 26-20-00	AFL							4036			
260136	HYDROSTATIC TEST									MANDATORY	F5	
26.015		MOS	60						07-APR-1999	07-APR-2004		
		HRS/MSC							6727			
	REF: AMM 5-10-00	AFL							4999			
+ 260156	RECORD DATE STAMPED ON NEW CARTRIDGE (SERVICE LIFE)									LIFE LIMIT	F5	
26.015		MOS	72						17-JAN-2001	17-JAN-2007		
		HRS/MSC										
	REF: AMM 26-20-00	AFL										
+ 260161	RECORD DATE STAMPED ON NEW CARTRIDGE (SERVICE LIFE)									LIFE LIMIT	F5	
26.015		MOS	72						17-JAN-2001	17-JAN-2007		
		HRS/MSC										
	REF: AMM 26-20-00	AFL										
+ 260158	REPLACE RIGHT FIRE EXTINGUISHER NO.1 CARTRIDGE									SCRAP	F5	
26.015		MOS	48						17-JAN-2001	17-JAN-2005		
	ASSOCIATED	HRS/MSC										
	REF: AMM 26-20-00	AFL										
+ 260163	REPLACE RIGHT FIRE EXTINGUISHER NO.2 CARTRIDGE									SCRAP	F5	
26.015		MOS	48						17-JAN-2001	17-JAN-2005		
	ASSOCIATED	HRS/MSC										
	REF: AMM 26-20-00	AFL										
260131	WEIGHT CHECK										F5	
26.015		MOS							17-JAN-2001			
		HRS/MSC	O/C						7494			
	REF: See Workcard	AFL							5466			
260101	FIRE DETECTOR, LEFT										E1	
26.040	4643506-3	MOS							11-FEB-1982			
	19491	HRS/MSC	O/C			0			0			
	REF: AMM 26-10-00	AFL							0			
260106	FIRE DETECTOR, RIGHT										E2	
26.040	4643506-3	MOS							11-FEB-1982			
	19503	HRS/MSC	O/C			0			0			
	REF: AMM 26-10-00	AFL							0			
260141	INDICATOR, EXTINGUISHER DISCHARGE										F5	
26.050	PN	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C			0			0			
	REF: NO REF	AFL							0			
CHAPTER 27	FLIGHT CONTROLS											
+ 270271	ADJUST/TEST FLAP COMPARATOR										F3	
27.430	PKG 3	MOS							26-JUL-2000			
		HRS/MSC	800						7325			
	REF: AMM 27-50-00	AFL							5360			

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
+ 270140 27.070	CHECK AILERON CONTROL SYSTEM FREEPLAY PKG 3	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360		F5	
	REF: AMM 27-10-00											
+ 270341 27.440	CHECK CABLE TENSION AFT FUSELAGE PKG 2, 3	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594		F5	
	REF: AMM 27-00-00											
+ 270340 27.440	CHECK CABLE TENSION FLIGHT/PASSENGER COMPARTMENT PKG 3	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360		F3	
	REF: AMM 27-00-00											
+ 270280 27.230	CLEAN/INSPECT/LUBRICATE LEFT INBOARD/OUTBOARD FLEXIBLE SHAFT PKG 3	MOS HRS/MSC AFL	1200						16-FEB-2001 7551 5515	8751	W1	
	REF: AMM 27-50-00											
+ 270285 27.230	CLEAN/INSPECT/LUBRICATE RIGHT INBOARD/OUTBOARD FLEXIBLE SHAFT PKG 3	MOS HRS/MSC AFL	1200						16-FEB-2001 7551 5515	8751	W2	
	REF: AMM 27-50-00											
+ 270248 27.200	FUNCTIONAL CHECK FLAP TIME EXCEED RELAY PKG 2, 3	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594		F3	
	REF: AMM 27-50-00											
+ 270211 27.500	INSPECT SCISSORS ASSEMBLY PKG 2, 3	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594		T1	
	REF: See Workcard											
+ 270351 27.380	INSPECT/LUBRICATE PRESSURE SEALS PKG 3	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360		F4	
	REF: AMM 12-20-00											
270214 27.195	LUBRICATE AFT HINGE FITTING BEARINGS PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594		T1	
	REF: NO REF											
270179 27.350	LUBRICATE CONTROL COLUMNS PKG 3	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360		F3	
	REF: AMM 12-20-00											
270213 27.190	LUBRICATE ELEVATOR ATTACH POINTS PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594		T1	
	REF: AMM 12-20-00											

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
270346 27.360	LUBRICATE FLIGHT CONTROL FORWARD/AFT BELLCRANKS PKG 3	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360		F4	
	REF: AMM 12-20-00											
270215 27.195	LUBRICATE FORWARD SCISSOR ASSEMBLY PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594		T1	
	REF: NO REF											
270356 27.370	LUBRICATE GUST LOCK PKG 3	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360		F3	
	REF: AMM 12-20-00											
270176 27.340	LUBRICATE RUDDER PEDAL ARMS PKG 3	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360		F3	
	REF: AMM 12-20-00											
+ 270335 27.280	OPERATIONAL CHECK SPEED BRAKES AND LIFT DUMPERS PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594		F2	
	REF: AMM 27-60-00											
270145 27.045	STATIC FRICTION TEST AILERON AND RUDDER PKG 3	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360			
	REF: AMM 27-00-00											
270210 27.570	VISUAL INSPECT ELEVATOR CONTROL BELLCRANK ASSEMBLY PKG 3	MOS HRS/MSC AFL	60 5000						16-JUN-1997 6135 4707	16-JUN-2002 11135		
	REF: AMM 5-10-00											
270331 27.320	ACCUMULATOR, LIFT DUMPER RIGHT WING INBOARD 3-713515-501	MOS HRS/MSC AFL	O/C			0			11-FEB-1982 0 0		W2	
	SN-UNKNOWN											
	REF: AMM 27-60-00											
270116 27.060	ACTUATOR, AILERON TRIM TAB 5793500-1	MOS HRS/MSC AFL	O/C						09-NOV-1996 5951 4589		W1	
	REF: AMM 27-10-00											
270251 27.210	ACTUATOR, FLAP LEFT INBOARD 1390T100-5	MOS HRS/MSC AFL	10000						16-JUN-1997 6135 4707	LIFE LIMIT ?	W1 \$1006. 8	
	REF: AMM 27-50-00											
270256 27.220	ACTUATOR, FLAP LEFT OUTBOARD 1391T100-7	MOS HRS/MSC AFL	10000			0			06-APR-1998 6346 4787	OVERHAUL 16346	W1 \$1046.	
	REF: AMM 27-50-00											

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL



AIRCRAFT Status Report

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
270261 27.210	ACTUATOR, FLAP RIGHT INBOARD 193544-1 749A REF: AMM 27-50-00	MOS HRSMSC AFL	10000	0					15-JUL-1986 3201 1972	OVERHAUL 13201	W2 \$1006. 8	
270266 27.220	ACTUATOR, FLAP RIGHT OUTBOARD 193544-502 120 REF: AMM 27-50-00	MOS HRSMSC AFL	10000	0				22-OCT-1982 482	LIFE LIMIT 10482	W2 \$1046.		
270216 27.170	ACTUATOR, HORIZONTAL STABILIZER TRIM 21164-005 0481-11AA REF: AMM 27-40-00	MOS HRSMSC AFL	2500	0				06-APR-1998 6346 4787	OVERHAUL 7287	T1 \$4158.		
+ 270217 27.170	INSPECT PKG 2, 3 REF: See Workcard	MOS HRSMSC AFL	400					26-JUN-2001 7687 5594		T1		
270328 27.310	ACTUATOR, LIFT DUMPER LEFT WING INBOARD 3-713515-501 SN-UNKNOWN REF: AMM 27-60-00	MOS HRSMSC AFL	O/C	0				11-FEB-1982 0 0		W1		
270326 27.310	ACTUATOR, LIFT DUMPER LEFT WING OUTBOARD 3-713515-501 SN-UNKNOWN REF: AMM 27-60-00	MOS HRSMSC AFL	O/C	0				11-FEB-1982 0 0		W1		
270333 27.320	ACTUATOR, LIFT DUMPER RIGHT WING OUTBOARD 3-713515-501 SN-UNKNOWN REF: AMM 27-60-00	MOS HRSMSC AFL	O/C	0				11-FEB-1982 0 0		W2		
270166 27.090	ACTUATOR, LOWER RUDDER TRIM 5793500-501 3219 REF: AMM 27-20-00	MOS HRSMSC AFL	O/C	0				11-FEB-1982 0 0		T1 \$1000. 16		
270301 27.260	ACTUATOR, SPEED BRAKE LEFT 3713515-503 1L-466P REF: AMM 27-60-00	MOS HRSMSC AFL	O/C	0				11-FEB-1982 0 0		W1		
270306 27.260	ACTUATOR, SPEED BRAKE RIGHT 3713515-503 1L-470P REF: AMM 27-60-00	MOS HRSMSC AFL	O/C	0				11-FEB-1982 0 0		W2		
270161 27.090	ACTUATOR, UPPER RUDDER TRIM 5793500-503 5220 REF: AMM 27-20-00	MOS HRSMSC AFL	O/C	0				11-FEB-1982 0 0		T1 \$1000. 16		

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
270101 27.010	AILERON, LEFT 5183003-407-2 4376 REF: AMM 27-10-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982 0 0		W1	
+ 270140 27.070 ASSOCIATED	CHECK AILERON CONTROL SYSTEM FREELAY PKG 3 REF: AMM 27-10-00	MOS HRS/MSC AFL		800					26-JUL-2000 7325 5360		F5	
+ 270264 27.550	CLEAN/CHECK LEFT GUIDE ROLLERS PKG 2, 3 REF: AMM 5-20-03	MOS HRS/MSC AFL		400					26-JUN-2001 7687 5594		W1	
SB 1124-27-100 R2 L/H RODS ASSOCIATED	FLIGHT CONTROLS SERVICE BULLETIN REF: BULLETINS Method of Compliance: OPEN	MOS HRS/MSC AFL		A/R					0 0		W1	
SB 1124-27-129 LEFT AILERON ASSOCIATED	FLIGHT CONTROLS SERVICE BULLETIN REF: BULLETINS Method of Compliance: OPEN	MOS HRS/MSC AFL		600					26-JUL-2000 7325 5360	7925	W1	
+ 570106 57.020	INSPECT BELLCRANK PKG 1, 2, 3 REF: AMM 5-20-03	MOS HRS/MSC AFL		200					26-JUN-2001 7687 5594		W1	
+ 270262 27.540	INSPECT LEFT EXTERNAL PUSH-PULL TUBE PKG 2, 3 REF: AMM 5-20-03	MOS HRS/MSC AFL		400					26-JUN-2001 7687 5594		W1	
AD 1996-24-11 LEFT AILERON ASSOCIATED	TO PREVENT EXCESSIVE WEAR OF THE AILERON PUSH-PULL TUBE, WHICH COULD RESULT IN UNEVEN MOVEMENT OF THE CONTROL WHEEL, PERFORATION OF THE AILERON PUSH-PULL TUBE, AND CONSEQUENT REDUCED ROLL CONTROL OF THE AIRPLANE AIRWORTHINESS DIRECTIVE REF: AD Method of Compliance: OPEN	MOS HRS/MSC AFL		600					26-JUL-2000 7325 5360	7925	W1	
AD 1992-12-02 LEFT AILERON ASSOCIATED	TO PREVENT REDUCED CONTROLLABILITY OF THE AIRPLANE AIRWORTHINESS DIRECTIVE REF: AD Method of Compliance: OPEN	MOS HRS/MSC AFL		150					0 0		W1	
270106 27.010	AILERON, RIGHT 5183003-406-2 4376 REF: AMM 27-10-00	MOS HRS/MSC AFL	O/C	0					11-FEB-1982 0 0		W2	

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
+ 270140 27.070 ASSOCIATED	CHECK AILERON CONTROL SYSTEM FREEPLAY PKG 3 REF: AMM 27-10-00	MOS HRS/MSC AFL	800							26-JUL-2000 7325 5360	F5	
+ 270265 27.550	CLEAN/CHECK RIGHT GUIDE ROLLERS PKG 2, 3 REF: AMM 5-20-03	MOS HRS/MSC AFL	400							26-JUN-2001 7687 5594	W2	
SB 1124-27-100 R2 R/H RODS ASSOCIATED	FLIGHT CONTROLS SERVICE BULLETIN REF: BULLETINS Method of Compliance: OPEN	MOS HRS/MSC AFL	A/R						0 0		W2	
SB 1124-27-129 RIGHT AILERON ASSOCIATED	FLIGHT CONTROLS SERVICE BULLETIN REF: BULLETINS Method of Compliance: OPEN	MOS HRS/MSC AFL	600						26-JUL-2000 7325 5360	7925	W2	
+ 270263 27.540	INSPECT RIGHT EXTERNAL PUSH-PULL TUBE PKG 2, 3 REF: AMM 5-20-03	MOS HRS/MSC AFL	400							26-JUN-2001 7687 5594	W2	
AD 1996-24-11 RIGHT AILERON ASSOCIATED	TO PREVENT EXCESSIVE WEAR OF THE AILERON PUSH-PULL TUBE, WHICH COULD RESULT IN UNEVEN MOVEMENT OF THE CONTROL WHEEL, PERFORATION OF THE AILERON PUSH-PULL TUBE, AND CONSEQUENT REDUCED ROLL CONTROL OF THE AIRPLANE AIRWORTHINESS DIRECTIVE REF: AD Method of Compliance: OPEN	MOS HRS/MSC AFL	600						26-JUL-2000 7325 5360	7925	W2	
AD 1992-12-02 RIGHT AILERON ASSOCIATED	TO PREVENT REDUCED CONTROLLABILITY OF THE AIRPLANE AIRWORTHINESS DIRECTIVE REF: AD Method of Compliance: OPEN	MOS HRS/MSC AFL	150						0 0		W2	
270291 27.250	BRAKE, SPEED LEFT 5-203007-507 SN-UNKNOWN REF: AMM 27-60-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	W1	
+ 270335 27.280 ASSOCIATED	OPERATIONAL CHECK SPEED BRAKES AND LIFT DUMPERS PKG 1, 2, 3 REF: AMM 27-60-00	MOS HRS/MSC AFL	200							26-JUN-2001 7687 5594	F2	
270296 27.250	BRAKE, SPEED RIGHT 5-203007-506 SN-UNKNOWN REF: AMM 27-60-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	W2	

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
					TSN	TSO	TSR	TSI	ADJ				
+ 270335		OPERATIONAL CHECK SPEED BRAKES AND LIFT DUMPERS										F2	
	27.280	PKG 1, 2, 3	MOS							26-JUN-2001			
		ASSOCIATED	HRS/MSA	200						7687			
		REF: AMM 27-60-00	AFL							5594			
270138		CHAIN, AILERON LEFT										F3	
	27.080	3533516-1	MOS							11-FEB-1982			
		SN-UNKNOWN	HRS/MSA	O/C	0					0			
		REF: AMM 27-30-00	AFL							0			
270139		CHAIN, AILERON RIGHT										F3	
	27.080	3533516-1	MOS							11-FEB-1982			
		SN-UNKNOWN	HRS/MSA	O/C	0					0			
		REF: AMM 27-30-00	AFL							0			
270186		COLUMN, CONTROL COPILOT										F3	
	27.140	PN	MOS							11-FEB-1982			
		SN-UNKNOWN	HRS/MSA	O/C	0					0			
		REF: AMM 27-30-00	AFL							0			
270181		COLUMN, CONTROL PILOT										F3	
	27.140	PN	MOS							11-FEB-1982			
		SN-UNKNOWN	HRS/MSA	O/C	0					0			
		REF: AMM 27-30-00	AFL							0			
270191		ELEVATOR, LEFT										T1	
	27.150	5463012-401-1	MOS							11-FEB-1982			
		4381	HRS/MSA	O/C	0					0			
		REF: AMM 27-30-00	AFL							0			
+ 270193		INSPECT SKIN SEPARATION										T1	
	27.150	PKG 1, 2, 3	MOS							26-JUN-2001			
			HRS/MSA	200						7687			
		REF: AMM 27-30-00	AFL							5594			
270213		LUBRICATE ELEVATOR ATTACH POINTS										T1	
	27.190	PKG 1, 2, 3	MOS							26-JUN-2001			
		ASSOCIATED	HRS/MSA	200						7687			
		REF: AMM 12-20-00	AFL							5594			
270210		VISUAL INSPECT ELEVATOR CONTROL BELLCRANK ASSEMBLY											
	27.570		MOS	60						16-JUN-1997	16-JUN-2002		
		ASSOCIATED	HRS/MSA	5000						6135	11135		
		REF: AMM 5-10-00	AFL							4707			
270201		ELEVATOR, RIGHT										T1	
	27.150	5463012-402-1	MOS							11-FEB-1982			
		4381	HRS/MSA	O/C	0					0			
		REF: AMM 27-30-00	AFL							0			
+ 270203		INSPECT SKIN SEPARATION										T1	
	27.150	PKG 1, 2, 3	MOS							26-JUN-2001			
			HRS/MSA	200						7687			
		REF: AMM 27-30-00	AFL							5594			

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
270213	LUBRICATE ELEVATOR ATTACH POINTS									T1	
27.190	PKG 1, 2, 3	MOS						26-JUN-2001			
ASSOCIATED		HRS/MSC	200					7687			
	REF: AMM 12-20-00	AFL						5594			
270210	VISUAL INSPECT ELEVATOR CONTROL BELLCRANK ASSEMBLY										
27.570		MOS	60					16-JUN-1997	16-JUN-2002		
ASSOCIATED		HRS/MSC	5000					6135	11135		
	REF: AMM 5-10-00	AFL						4707			
270233	FLAP ASSEMBLY, CONTROL BOX									F3	
27.490	2813521-	MOS						11-FEB-1982			
	286	HRS/MSC	O/C	0				0			
	REF: NO REF	AFL		0				0			
270236	FLAP/VANE, LEFT									W1	
27.200	5193502-401	MOS						11-FEB-1982			
	4369	HRS/MSC	O/C	0				0			
	REF: AMM 27-50-00	AFL						0			
+ 270248	FUNCTIONAL CHECK FLAP TIME EXCEED RELAY									F3	
27.200	PKG 2, 3	MOS						26-JUN-2001			
ASSOCIATED		HRS/MSC	400					7687			
	REF: AMM 27-50-00	AFL						5594			
+ 270240	INSPECT LEFT FLAP HINGE AND BEARING 200 HOURS									W1	
27.200	PKG 1, 2, 3	MOS						26-JUN-2001			
		HRS/MSC	200					7687			
	REF: AMM 27-50-00	AFL						5594			
+ 270244	INSPECT LEFT FLAP HINGE AND BEARING 800 HOURS									W1	
27.200	PKG 3	MOS						26-JUL-2000			
		HRS/MSC	800					7325			
	REF: AMM 27-50-00	AFL						5360			
+ 270237	INSPECT LEFT FLAP VANE									W1	
27.200	PKG 1, 2, 3	MOS						26-JUN-2001			
		HRS/MSC	200					7687			
	REF: AMM 27-50-00	AFL						5594			
+ 270238	TAP TEST LEFT FLAP									W1	
27.200	PKG 2, 3	MOS						26-JUN-2001			
		HRS/MSC	400					7687		.5	
	REF: AMM 27-50-00	AFL						5594			
270241	FLAP/VANE, RIGHT									W2	
27.200	5193502-402	MOS						11-FEB-1982			
	4370	HRS/MSC	O/C	0				0			
	REF: AMM 27-50-00	AFL						0			
+ 270248	FUNCTIONAL CHECK FLAP TIME EXCEED RELAY									F3	
27.200	PKG 2, 3	MOS						26-JUN-2001			
ASSOCIATED		HRS/MSC	400					7687			
	REF: AMM 27-50-00	AFL						5594			

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
+ 270247 27.200	INSPECT PKG 1, 2, 3	MOS HRS/MSC AFL	200							26-JUN-2001 7687 5594	W1	
	REF: AMM 27-50-00											
+ 270242 27.200	INSPECT RIGHT FLAP HINGE AND BEARING 200 HOURS PKG 1, 2, 3	MOS HRS/MSC AFL	200							26-JUN-2001 7687 5594	W2	
	REF: AMM 27-50-00											
+ 270245 27.200	INSPECT RIGHT FLAP HINGE AND BEARING 800 HOURS PKG 3	MOS HRS/MSC AFL	800							26-JUL-2000 7325 5360	W2	
	REF: AMM 27-50-00											
+ 270243 27.200	TAP TEST PKG 2, 3	MOS HRS/MSC AFL	400							26-JUN-2001 7687 5594	W2 .5	
	REF: AMM 27-50-00											
270276 27.400	GEARBOX, COMPARATOR LEFT 5-703541-501 SN-UNKNOWN REF: AMM 27-50-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	W1 \$1570.	
+ 270271 27.430 ASSOCIATED	ADJUST/TEST FLAP COMPARATOR PKG 3	MOS HRS/MSC AFL	800							26-JUL-2000 7325 5360	F3	
	REF: AMM 27-50-00											
270281 27.400	GEARBOX, COMPARATOR RIGHT 5-703541-502 SN-UNKNOWN REF: AMM 27-50-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	W2	
+ 270271 27.430 ASSOCIATED	ADJUST/TEST FLAP COMPARATOR PKG 3	MOS HRS/MSC AFL	800							26-JUL-2000 7325 5360	F3	
	REF: AMM 27-50-00											
270121 27.030	INDICATOR, AILERON TRIM TAB 3883026-515 S0451 REF: AMM 27-10-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F3	
271101 27.470	INDICATOR, ANGLE-OF-ATTACK LEFT 3883765-501 JN1 066 REF: AMM 34-10-05	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F3	
271106 27.470	INDICATOR, ANGLE-OF-ATTACK RIGHT 3883765-501 SN-UNKNOWN REF: AMM 34-10-05	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F3	

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
270288 27.420	INDICATOR, FLAP POSITION COPILOT 6883739-1 SN-UNKNOWN REF: AMM 27-50-00	MOS HRS/MSA AFL	O/C	0						11-FEB-1982 0 0	F3	
270286 27.420	INDICATOR, FLAP POSITION PILOT 6883789-1 81090110 REF: AMM 27-50-00	MOS HRS/MSA AFL	O/C	0						11-FEB-1982 0 0	F3 \$338.	
270226 27.160	INDICATOR, HORIZONTAL STABILIZER TRIM 3883026-525 T0119 REF: AMM 27-40-00	MOS HRS/MSA AFL	O/C	0						11-FEB-1982 0 0	F3 \$306.	
270171 27.120	INDICATOR, RUDDER TRIM 3883026-517 T0163 REF: AMM 27-20-00	MOS HRS/MSA AFL	O/C	0						11-FEB-1982 0 0	F3	
270224 27.185	JACKSCREW, HORIZONTAL STABILIZER ACTUATOR NO.1 21164-005 (ACT.ASSY) 0481-11A REF: NO REF	MOS HRS/MSA AFL		0			10000			06-APR-1998 6346 4787	LIFE LIMIT T1 14787	
270225 27.185	JACKSCREW, HORIZONTAL STABILIZER ACTUATOR NO.2 21164-005 (ACT.ASSY) 0481-11AA REF: NO REF	MOS HRS/MSA AFL		0			10000			06-APR-1998 6346 4787	LIFE LIMIT T1 14787	
270318 27.290	LIFT DUMPER, LEFT WING INBOARD 3713515-501 1L-900 REF: AMM 27-60-00	MOS HRS/MSA AFL	O/C	0						11-FEB-1982 0 0	W1	
270316 27.290	LIFT DUMPER, LEFT WING OUTBOARD 3713515-501 1L687P REF: AMM 27-60-00	MOS HRS/MSA AFL	O/C	0						11-FEB-1982 0 0	W1	
270321 27.300	LIFT DUMPER, RIGHT WING INBOARD 3713515-501 1L862P REF: AMM 27-60-00	MOS HRS/MSA AFL	O/C	0						11-FEB-1982 0 0	W2	
270323 27.300	LIFT DUMPER, RIGHT WING OUTBOARD 5-203007-510 1L881P REF: AMM 27-60-00	MOS HRS/MSA AFL	O/C	0						11-FEB-1982 0 0	W2	
270119 27.450	MOTOR, AILERON TRIM PN SN-UNKNOWN REF: NO REF	MOS HRS/MSA AFL	O/C	0						11-FEB-1982 0 0	W1	

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
270246 27.180	MOTOR, FLAP PRIME 193543-1 160 REF: AMM 27-50-00	MOS HRS/MSC AFL	10000		0				06/01/1993	01-DEC-1992 5188 3829	OVERHAUL 15188	F5 \$4235. 1
270221 27.460	MOTOR, PRIMARY HORIZONTAL STABILIZER PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C		0					11-FEB-1982 0 0		T1
270169 27.450	MOTOR, RUDDER TRIM PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C		0					11-FEB-1982 0 0		T1
270223 27.460	MOTOR, SECONDARY HORIZONTAL STABILIZER PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C		0					11-FEB-1982 0 0		T1
270274 27.410	POTENTIOMETER, LINEAR LEFT 833523-501 SN-UNKNOWN REF: AMM 27-50-00	MOS HRS/MSC AFL	O/C							10-AUG-1986 3515		W1
270282 27.410	POTENTIOMETER, LINEAR RIGHT 833523-501 589 REF: AMM 27-50-00	MOS HRS/MSC AFL	O/C							10-AUG-1986 3515		W2
270128 27.530	ROD, CONTROL LEFT AILERON 513506-503 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C							11-FEB-1982 0 0		W1
+ 270080 27.530	X-RAY INSPECT LEFT AILERON CONTROL ROD ASSEMBLIES SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	60 5000							16-JUN-1997 6135 4707	16-JUN-2002 11135	W1
270129 27.535	ROD, CONTROL RIGHT AILERON 513506-503 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C							11-FEB-1982 0 0		W2
+ 270081 27.535	X-RAY INSPECT ASSEMBLY SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	60 5000							16-JUN-1997 6135 4707	16-JUN-2002 11135	W2
270141 27.100	RUDDER, 5423026-402-2 4370 REF: AMM 27-20-00	MOS HRS/MSC AFL	O/C		0					11-FEB-1982 0 0		T1

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
+ 270150 27.560	X-RAY INSPECT CONTROL ROD ASSEMBLY	MOS	60							16-JUN-1997	16-JUN-2002	T1
		HRS/MS	5000						6135		11135	
	REF: NO REF	AFL							4707			
270279 27.230	SHAFT, FLEXIBLE INBOARD LEFT 193545-501	MOS								11-FEB-1982		LIFE LIMIT
	1200269	HRS/MS	10000	0					0		10000	
	REF: AMM 27-50-00	AFL							0			
+ 270280 27.230	CLEAN/INSPECT/LUBRICATE LEFT INBOARD/OUTBOARD FLEXIBLE SHAFT	MOS								16-FEB-2001		
ASSOCIATED		HRS/MS	1200						7551		8751	
	REF: AMM 27-50-00	AFL							5515			
270284 27.240	SHAFT, FLEXIBLE INBOARD RIGHT 193545-505	MOS								11-FEB-1982		LIFE LIMIT
	1200241	HRS/MS	10000	0					0		10000	
	REF: AMM 27-50-00	AFL							0			
+ 270285 27.230	CLEAN/INSPECT/LUBRICATE RIGHT INBOARD/OUTBOARD FLEXIBLE SHAFT	MOS								16-FEB-2001		
ASSOCIATED		HRS/MS	1200						7551		8751	
	REF: AMM 27-50-00	AFL							5515			
270278 27.230	SHAFT, FLEXIBLE OUTBOARD LEFT 193545-501	MOS								11-FEB-1982		LIFE LIMIT
	1200446	HRS/MS	10000	0					0		10000	
	REF: AMM 27-50-00	AFL							0			
+ 270280 27.230	CLEAN/INSPECT/LUBRICATE LEFT INBOARD/OUTBOARD FLEXIBLE SHAFT	MOS								16-FEB-2001		
ASSOCIATED		HRS/MS	1200						7551		8751	
	REF: AMM 27-50-00	AFL							5515			
270283 27.240	SHAFT, FLEXIBLE OUTBOARD RIGHT 193545-501	MOS								11-FEB-1982		LIFE LIMIT
	1200514	HRS/MS	10000	0					0		10000	
	REF: AMM 27-50-00	AFL							0			
+ 270285 27.230	CLEAN/INSPECT/LUBRICATE RIGHT INBOARD/OUTBOARD FLEXIBLE SHAFT	MOS								16-FEB-2001		
ASSOCIATED		HRS/MS	1200						7551		8751	
	REF: AMM 27-50-00	AFL							5515			
270126 27.040	TAB, AILERON SERVO 5-183005-505	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0					0			
	REF: AMM 27-10-00	AFL							0			
270111 27.020	TAB, AILERON TRIM 5-183005-503	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0					0			
	REF: AMM 27-10-00	AFL							0			

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
270156 27.110	TAB, RUDDER TRIM PN	MOS								11-FEB-1982	T1	
	SN-UNKNOWN REF: AMM 27-20-00	HRS/MSC AFL	O/C	0						0 0		
+ 270158 27.130	INSPECT FREEPLAY PKG 1, 2, 3	MOS								26-JUN-2001	T1	
	REF: AMM 27-20-00	HRS/MSC AFL	200							7687 5594		
271111 27.480	TRANSMITTER, ANGLE-OF-ATTACK LEFT SLZ7259	MOS								06-APR-1998	W1	
	KE1 141 REF: AMM 34-10-05	HRS/MSC AFL	O/C							6346 4787		
271116 27.480	TRANSMITTER, ANGLE-OF-ATTACK RIGHT SLZ-9280	MOS								11-FEB-1982	W2	
	SN-UNKNOWN REF: AMM 34-10-05	HRS/MSC AFL	O/C	0						0 0		
270231 27.390	TRANSMITTER, TRIM POSITION INDICATOR 8TJ39-BAR-2	MOS								11-FEB-1982	T1	
	T1353 REF: AMM 27-40-00	HRS/MSC AFL	O/C	0						0 0	\$543.	
270336 27.330	VALVE, LIFT DUMPER CONTROL 723573-1	MOS								11-FEB-1982	F5	
	698 REF: AMM 27-60-00	HRS/MSC AFL	O/C	0						0 0	\$362.	
270311 27.270	VALVE, SPEED BRAKE CONTROL 723573-1	MOS								11-FEB-1982	F5	
	845 REF: AMM 27-60-00	HRS/MSC AFL	O/C	0						0 0	\$362.	
270136 27.050	WHEEL, CONTROL COPILOT 5-533060-35	MOS								11-FEB-1982	F3	
	SN-UNKNOWN REF: AMM 27-10-00	HRS/MSC AFL	O/C	0						0 0		
270131 27.050	WHEEL, CONTROL PILOT 5-533060-37	MOS								11-FEB-1982	F3	
	SN-UNKNOWN REF: AMM 27-10-00	HRS/MSC AFL	O/C	0						0 0		
CHAPTER 28	FUEL											
+ 281150 28.010	CHECK OPERATION OF FUEL BOOST PUMPS PKG 1, 2, 3	MOS								26-JUN-2001	F5	
	REF: AMM 28-00-00	HRS/MSC AFL	200							7687 5594		
+ 281603 28.090	FUNCTIONAL CHECK FUEL DUMP SYSTEM	MOS								22-FEB-2000	F5	
	REF: AMM 28-00-00	HRS/MSC AFL	1200							7107 5232	8307	

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
+ 281602 28.090	OPERATIONAL CHECK FUEL DUMP SYSTEM PKG 3	MOS HRSMSC AFL	800							26-JUL-2000 7325 5360	F5	
281101 28.200	INDICATOR, FUEL QUANTITY LEFT 6883707-1 359 REF: AMM 28-00-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0	F3 \$444. 1	
281106 28.200	INDICATOR, FUEL QUANTITY RIGHT 6883707-1 361 REF: AMM 28-40-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0	F3 \$444. 1	
281108 28.210	INDICATOR, FUEL STATUS 6883710-501 173 REF: NO REF	MOS HRSMSC AFL	O/C							11-FEB-1982	F3	
280626 28.160	PROBE, LEFT TIP TANK 6653505-519 227 REF: AMM 28-40-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0	W1	
280616 28.140	PROBE, LEFT WING INBOARD 5653505-507 207 REF: AMM 28-40-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0	W1	
280621 28.140	PROBE, LEFT WING OUTBOARD 5653505-505 214 REF: AMM 28-40-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0	W1	
280646 28.160	PROBE, RIGHT TIP TANK 6653505-519 233 REF: AMM 28-40-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0	W2	
280636 28.150	PROBE, RIGHT WING INBOARD 5653505-507 266 REF: AMM 28-40-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0	W2	
280641 28.150	PROBE, RIGHT WING OUTBOARD 5653505-505 235 REF: AMM 28-40-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0	W2	
280611 28.130	PROBE, FUSELAGE LEFT 3653505-509 224 REF: AMM 28-40-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0	F5	

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
280631 28.130	PROBE, FUSELAGE RIGHT 6653505-509	MOS								11-FEB-1982	F5	
	291	HRS/MS	O/C	0					0			
	REF: AMM 28-40-00	AFL							0			
280126 28.020	PUMP, ALTERNATE BOOST LEFT 5653744-505	MOS								11-FEB-1982	W1	
	T514	HRS/MS	O/C	0					0			
	REF: AMM 28-20-00	AFL							0			
280128 28.020	CHECK BRUSH WEAR	MOS								11-FEB-1982	W1	
		HRS/MS	O/C						0			
	REF: See Workcard	AFL							0			
+ 281150 28.010	CHECK OPERATION OF FUEL BOOST PUMPS PKG 1, 2, 3	MOS								26-JUN-2001	F5	
	ASSOCIATED	HRS/MS	200						7687			
	REF: AMM 28-00-00	AFL							5594			
280136 28.020	PUMP, ALTERNATE BOOST RIGHT 5653744	MOS								30-OCT-1989	W2	
	853	HRS/MS	O/C						4401			
	REF: AMM 28-20-00	AFL							2956			
280138 28.020	CHECK BRUSH WEAR	MOS								11-FEB-1982	W2	
		HRS/MS	O/C						0			
	REF: See Workcard	AFL							0			
+ 281150 28.010	CHECK OPERATION OF FUEL BOOST PUMPS PKG 1, 2, 3	MOS								26-JUN-2001	F5	
	ASSOCIATED	HRS/MS	200						7687			
	REF: AMM 28-00-00	AFL							5594			
280161 28.110	PUMP, FUSELAGE JET LEFT 3-653015	MOS								11-FEB-1982	F5	
	1095	HRS/MS	O/C	0					0			
	REF: AMM 28-20-00	AFL							0			
280166 28.110	PUMP, FUSELAGE JET RIGHT 3-653015	MOS								11-FEB-1982	F5	
	1099	HRS/MS	O/C	0					0			
	REF: AMM 28-20-00	AFL							0			
280181 28.100	PUMP, JET LEFT TIP TANK 3-653015	MOS								11-FEB-1982	W1	
	1309	HRS/MS	O/C	0					0			
	REF: AMM 28-20-00	AFL							0			
280186 28.100	PUMP, JET RIGHT TIP TANK 3-653015	MOS								11-FEB-1982	W2	
	1311	HRS/MS	O/C	0					0			
	REF: AMM 28-20-00	AFL							0			

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
280167 28.230	PUMP, LONG RANGE BOOST 653009-513 SN-UNKNOWN REF: AMM 28-50-00	MOS HRSMSC AFL	O/C							11-FEB-1982	F4	
280121 28.010	PUMP, MAIN BOOST LEFT 2070C01T3 T-330 REF: AMM 28-20-00	MOS HRSMSC AFL	O/C		0					24-APR-2000 7233 5301	W1	
280123 28.010	CHECK BRUSH WEAR REF: NO REF	MOS HRSMSC AFL	O/C							24-APR-2000 7233 5301	W1	
+ 281150 28.010 ASSOCIATED	CHECK OPERATION OF FUEL BOOST PUMPS PKG 1, 2, 3 REF: AMM 28-00-00	MOS HRSMSC AFL	200							26-JUN-2001 7687 5594	F5	
280131 28.010	PUMP, MAIN BOOST RIGHT 2070C01T3 T1222 REF: AMM 28-20-00	MOS HRSMSC AFL	O/C		0					26-AUG-1992 5151 3777	W2	
280133 28.010	CHECK BRUSH WEAR REF: See Workcard	MOS HRSMSC AFL	O/C							26-AUG-1992 5151 3777	W2	
+ 281150 28.010 ASSOCIATED	CHECK OPERATION OF FUEL BOOST PUMPS PKG 1, 2, 3 REF: AMM 28-00-00	MOS HRSMSC AFL	200							26-JUN-2001 7687 5594	F5	
281121 28.210	SIGNAL CONDITIONER, FUEL 883711-501 157 REF: NO REF	MOS HRSMSC AFL	O/C		0					11-FEB-1982 0 0	F2	
280281 28.190	SWITCH, FUEL FLOAT LEFT 833006 A966 REF: NO REF	MOS HRSMSC AFL	O/C		0					11-FEB-1982 0 0	F5	
280286 28.190	SWITCH, FUEL FLOAT RIGHT 833006 A920 REF: NO REF	MOS HRSMSC AFL	O/C		0					11-FEB-1982 0 0	F5	
281141 28.170	SWITCH, LOW-LEVEL WARNING LEFT 3833006 SN-UNKNOWN REF: AMM 28-40-00	MOS HRSMSC AFL	O/C		0					11-FEB-1982 0 0	F5	

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
281146 28.170	SWITCH, LOW-LEVEL WARNING RIGHT 3833006 SN-UNKNOWN REF: AMM 28-40-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F5	
281139 28.240	SWITCH, PRESSURE(LONG RANGE) 833010-518 A-149 REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F4	
280250 28.220	TANK, FUEL (LONG RANGE) CMA61032-501 NSN REF: AMM 28-50-00	MOS HRS/MSC AFL			0					07-DEC-1989 4437 2994	F5	
281110 28.240	TRANSMITTER, QUANTITY (LONG RANGE) DA515A050 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F4	
280191 28.090	VALVE, DUMP LEFT 3653014 168 REF: AMM 28-30-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	W1 \$725.	
+ 281603 28.090 ASSOCIATED	FUNCTIONAL CHECK FUEL DUMP SYSTEM REF: AMM 28-00-00	MOS HRS/MSC AFL	1200							22-FEB-2000 7107 5232	8307 F5	
+ 281602 28.090 ASSOCIATED	OPERATIONAL CHECK FUEL DUMP SYSTEM PKG 3 REF: AMM 28-00-00	MOS HRS/MSC AFL	800							26-JUL-2000 7325 5360	F5	
280196 28.090	VALVE, DUMP RIGHT 3653014 31360 REF: AMM 28-30-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	W2 \$725.	
+ 281603 28.090 ASSOCIATED	FUNCTIONAL CHECK FUEL DUMP SYSTEM REF: AMM 28-00-00	MOS HRS/MSC AFL	1200							22-FEB-2000 7107 5232	8307 F5	
+ 281602 28.090 ASSOCIATED	OPERATIONAL CHECK FUEL DUMP SYSTEM PKG 3 REF: AMM 28-00-00	MOS HRS/MSC AFL	800							26-JUL-2000 7325 5360	F5	
280141 28.040	VALVE, FIREWALL SHUTOFF LEFT 3653012 L38199 REF: AMM 28-20-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	E1	

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
280151 28.040	VALVE, FIREWALL SHUTOFF RIGHT 3-653012 L35008 REF: AMM 28-20-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	E2 \$725.	
280251 28.050	VALVE, FUEL AUTO SHUTOFF LEFT 3653669 0114 REF: AMM 28-10-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F5	
280256 28.050	VALVE, FUEL AUTO SHUTOFF RIGHT 3653669 0087 REF: AMM 28-10-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F5	
280106 28.030	VALVE, FUEL INTERCONNECT AFT 3653014 31395 REF: AMM 28-10-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F5 \$725.	
280101 28.030	VALVE, FUEL INTERCONNECT FORWARD AV16B1683 L18181 REF: AMM 28-10-00	MOS HRS/MSC AFL	O/C							16-JUN-1997 6135 4707	F5 \$725.	
280261 28.060	VALVE, FUEL PILOT LEFT 3653671 7732 REF: AMM 28-10-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F5	
280266 28.060	VALVE, FUEL PILOT RIGHT 3653671 7728 REF: AMM 28-10-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F5	
280194 28.070	VALVE, FUEL PRECHECK LEFT PN SN-UNKNOWN REF: AMM 28-10-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F5	
280203 28.070	VALVE, FUEL PRECHECK RIGHT PN SN-UNKNOWN REF: AMM 28-10-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F5	
280206 28.180	VALVE, FUEL SOLENOID LEFT MS-29527-1 744 REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F5	
280211 28.180	VALVE, FUEL SOLENOID RIGHT MS-29527-1 752 REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F5	

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
280171	VALVE, FUEL TRANSFER LEFT										F5
28.120	4653572	MOS							11-FEB-1982		\$805.
	101	HRS/MSC	O/C		0				0		
	REF: AMM 28-20-00	AFL							0		
280176	VALVE, FUEL TRANSFER RIGHT										F5
28.120	4653572	MOS							11-FEB-1982		\$805.
	126	HRS/MSC	O/C		0				0		
	REF: AMM 28-20-00	AFL							0		
280290	VALVE, SINGLE POINT REFUEL ADAPTER										F5
28.250	3653670	MOS							11-FEB-1982		
	205	HRS/MSC	O/C						0		
	REF: NO REF	AFL							0		
280271	VALVE, SINGLE POINT REFUEL VENT LEFT										F5
28.080	3653672	MOS							11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C		0				0		
	REF: AMM 28-10-00	AFL							0		
280276	VALVE, SINGLE POINT REFUEL VENT RIGHT										F5
28.080	3653672	MOS							11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C		0				0		
	REF: AMM 28-10-00	AFL							0		
CHAPTER 29	HYDRAULIC POWER										
290221	ACCUMULATOR, EMERGENCY										F5
29.080	3713008	MOS							11-FEB-1982		\$472.
	601	HRS/MSC	O/C		0				0		
	REF: AMM 29-20-00	AFL							0		
290151	ACCUMULATOR, LEFT HYDRAULIC										F5
29.130	4-713569-1	MOS							11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C		0				0		
	REF: NO REF	AFL							0		
290186	ACCUMULATOR, RIGHT HYDRAULIC										F5
29.130	4-713569-1	MOS							11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C		0				0		
	REF: NO REF	AFL							0		
290261	ATTENUATOR, NO.1 ENG HYDRAULIC										F5
29.040	3713562-1	MOS							11-FEB-1982		
	0601	HRS/MSC	O/C		0				0		
	REF: AMM 29-10-00	AFL							0		
290266	ATTENUATOR, NO.2 ENG HYDRAULIC										F5
29.040	3713562-1	MOS							11-FEB-1982		
	0591	HRS/MSC	O/C		0				0		
	REF: AMM 29-10-00	AFL							0		
290119	CHECK VALVE, RESERVOIR BLEED AIR										F5
29.180	PN	MOS							11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C		0				0		
	REF: NO REF	AFL							0		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
290248 29.110	FUSE, EMERGENCY HYDRAULIC 3713047 3383 REF: AMM 29-30-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0	F2	
290246 29.100	GAUGE, EMERGENCY HYDRAULIC PRESSURE 4883746-1 SN-UNKNOWN REF: AMM 29-30-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0	F3	
290148 29.140	GAUGE, LEFT ACCUMULATOR PRESSURE 7253014-501 SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0	F5	
290183 29.140	GAUGE, RIGHT ACCUMULATOR PRESSURE 7253014-501 SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0	F5	
290236 29.160	INDICATOR, HYDRAULIC PRESSURE 4883746-1 8007104 REF: AMM 29-30-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0	F3	
290211 29.060	PUMP, EMERGENCY HYDRAULIC 3713010-505 13747 REF: AMM 29-20-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0	F5 \$805.	
290215 29.110	FUNCTIONAL TEST EMERGENCY HYDRAULIC FUSE REF: AMM 29-30-06	MOS HRSMSC AFL	36 1200							30-NOV-1999 6991 5163	30-NOV-2002 8191	
290141 29.120	PUMP, HYDRAULIC NO. 1 5713524-507 B1-58 REF: AMM 29-10-00	MOS HRSMSC AFL	O/C		0					09-OCT-1990 4718 3309	E1	
+ 290143 29.120	INSPECT/LUBRICATE NO.1 ENGINE HYDRAULIC PUMP SPLINES PKG 1, 2, 3 REF: AMM 29-10-00	MOS HRSMSC AFL	200							26-JUN-2001 7687 5594	E1 1	
290176 29.120	PUMP, HYDRAULIC NO. 2 5713524-507 A2-84 REF: AMM 29-10-00	MOS HRSMSC AFL	O/C		0					04-FEB-1994 5390 4040	E2 1	
+ 290178 29.120	INSPECT/LUBRICATE NO.2 ENGINE HYDRAULIC PUMP SPLINES PKG 1, 2, 3 REF: AMM 29-10-00	MOS HRSMSC AFL	200							26-JUN-2001 7687 5594	E2 1	

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
290121	REGULATOR, RESERVOIR AIR PRESSURE									F5	
29.050	3713015	MOS							11-FEB-1982	\$1046.	
	509	HRS/MSC	O/C		0				0		
	REF: AMM 29-10-00	AFL							0		
290118	CLEAN/CHECK HYDRAULIC RESERVOIR AIR PRESSURE CHECK VALVE									F5	
29.050	PKG 2, 3	MOS							26-JUN-2001		
	509	HRS/MSC	400						7687		
	REF: AMM 5-20-00	AFL							5594		
+ 290131	INSPECT/REPLACE RESERVOIR AIR PRESSURE FILTER									F5	
29.050	PKG 3	MOS							26-JUL-2000		
		HRS/MSC	800						7325		
	REF: AMM 29-10-00	AFL							5360		
+ 290116	INSPECT/REPLACE RESERVOIR AIR VENT FILTER									F5	
29.050	PKG 3	MOS							26-JUL-2000		
	509	HRS/MSC	800						7325		
	REF: AMM 29-10-10	AFL							5360		
290171	REPLACE NO.1 ENGINE HIGH PRESSURE HYDRAULIC FILTER ELEMENT									F5	
29.050	PKG 3	MOS							26-JUL-2000		
		HRS/MSC	800						7325		
	REF: AMM 29-10-10	AFL							5360		
290206	REPLACE NO.2 ENGINE HIGH PRESSURE HYDRAULIC FILTER ELEMENT									F5	
29.050	PKG 3	MOS							26-JUL-2000		
		HRS/MSC	800						7325		
	REF: AMM 29-10-10	AFL							5360		
290101	RESERVOIR, HYDRAULIC									F5	
29.010	5713014-505	MOS							11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C		0				0		
	REF: AMM 29-10-00	AFL							0		
290106	REPLACE FILTER									F5	
29.010	PKG 3	MOS							26-JUL-2000		
		HRS/MSC	800						7325		
	REF: AMM 29-10-00	AFL							5360		
290226	SWITCH, EMERGENCY HYDRAULIC PRESSURE									F5	
29.090	4833010-515	MOS							11-FEB-1982		
	872	HRS/MSC	O/C		0				0		
	REF: AMM 29-20-00	AFL							0		
290241	SWITCH, NO.1 LOW HYDRAULIC PRESSURE WARNING									F5	
29.170	4713533-1	MOS							11-FEB-1982		
	798	HRS/MSC	O/C		0				0	1	
	REF: AMM 29-30-00	AFL							0		
290243	SWITCH, NO.2 LOW HYDRAULIC PRESSURE WARNING									F5	
29.170	4713533-1	MOS							11-FEB-1982		
	788	HRS/MSC	O/C		0				0		
	REF: AMM 29-30-00	AFL							0		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
290231	TRANSMITTER, HYDRAULIC PRESSURE										F5	
29.150	3883028	MOS								11-FEB-1982	\$507.	
	8005119	HRS/MS	O/C	0					0			
	REF: AMM 29-30-00	AFL							0			
290133	VALVE, BLEED RETURN										F5	
29.180	PN	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0					0			
	REF: NO REF	AFL							0			
290216	VALVE, EMERGENCY THERMAL RELIEF										F5	
29.070	4713011-1	MOS								11-FEB-1982		
	1L82	HRS/MS	O/C	0					0			
	REF: NO REF	AFL							0			
290138	VALVE, HYDRAULIC PRESSURE RELIEF										F5	
29.190	373596-501	MOS								11-FEB-1982		
	158	HRS/MS	O/C	0					0			
	REF: NO REF	AFL							0			
290146	VALVE, LEFT HYDRAULIC SHUTOFF										E1	
29.020	713020-	MOS								11-FEB-1982	\$322.	
	080	HRS/MS	O/C	0					0			
	REF: AMM 29-10-00	AFL							0			
290136	VALVE, MANUAL HIGH-PRESSURE RELIEF										F5	
29.030	3723628	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0					0			
	REF: NO REF	AFL							0			
290181	VALVE, RIGHT HYDRAULIC SHUTOFF										E2	
29.020	713020-	MOS								11-FEB-1982	\$322.	
	074	HRS/MS	O/C	0					0			
	REF: AMM 29-10-00	AFL							0			
290271	VALVE, THERMAL HYDRAULIC RELIEF										F5	
29.190	3713554	MOS								11-FEB-1982		
	0168	HRS/MS	O/C	0					0			
	REF: NO REF	AFL							0			
CHAPTER 30	ICE AND RAIN PROTECTION											
+ 300133	FUNCTIONAL CHECK PNEUMATIC DE-ICER BOOTS										F3	
30.100	PKG 3	MOS								26-JUL-2000		
		HRS/MS	800						7325			
	REF: AMM 30-10-00	AFL							5360			
+ 300150	INSPECT COPILOT WINDSHIELD CYCLING CONTACTOR										F3	
30.140	PKG 1, 2, 3	MOS								26-JUN-2001		
		HRS/MS	200						7687			
	REF: AMM 30-40-00	AFL							5594			
+ 300147	INSPECT PILOT WINDSHIELD CYCLING CONTACTOR										F3	
30.140	PKG 1, 2, 3	MOS								26-JUN-2001		
		HRS/MS	200						7687			
	REF: AMM 30-40-00	AFL							5594			

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
+ 300163	INSPECT WINDSHIELD WIPER ASSEMBLY										
30.160	PKG 1, 2, 3	MOS						26-JUN-2001			
	REF: AMM 30-40-00	HRS/MSA	200					7687			
		AFL						5594			
300170	OPERATIONAL TEST P2T2 SENSOR HEATER										
30.150	PKG 1, 2, 3	MOS						26-JUN-2001			
	REF: AMM 30-20-00	HRS/MSA	200					7687			
		AFL						5594			
300165	REPLACE WIPER BLADE ELEMENT										
	NOTE: IT IS RECOMMENDED TO REPLACE WIPER BLADE ELEMENT EVERY 6 MONTHS OR 250 HOURS.										
30.170		MOS						06-NOV-2001			
	REF: AMM 30-40-00	HRS/MSA						7774			
		AFL						5641			
300101	CHECK VALVE, DE-ICER LEFT									F4	
30.010	PN	MOS						11-FEB-1982			
	SN-UNKNOWN	HRS/MSA	O/C	0				0			
	REF: AMM 30-10-00	AFL						0			
+ 300102	INSPECT									F4	
30.010	PKG 2, 3	MOS						26-JUN-2001			
	REF: AMM 30-10-00	HRS/MSA	400					7687			
		AFL						5594			
300103	CHECK VALVE, DE-ICER RIGHT									F4	
30.010	PN	MOS						11-FEB-1982			
	SN-UNKNOWN	HRS/MSA	O/C	0				0			
	REF: AMM 30-10-00	AFL						0			
+ 300104	INSPECT									F4	
30.010	PKG 2, 3	MOS						26-JUN-2001			
	REF: AMM 30-10-00	HRS/MSA	400					7687			
		AFL						5594			
300146	CONTROLLER, WINDSHIELD TEMPERATURE LEFT									F3	
30.110	HYLZ9661	MOS		0				22-FEB-2000			
	982B	HRS/MSA	O/C	0				7107			
	REF: AMM 30-40-00	AFL		0				5232			
300148	CONTROLLER, WINDSHIELD TEMPERATURE RIGHT									F3	
30.110	833034-1	MOS						11-FEB-1982			
	SN-UNKNOWN	HRS/MSA	O/C	0				0			
	REF: AMM 30-40-00	AFL						0			
300111	EJECTOR, AIR									F4	
30.030	850278-1	MOS						11-FEB-1982			
	RF3295	HRS/MSA	O/C	0				0			
	REF: AMM 30-10-00	AFL						0			
300156	MOTOR, WINDSHIELD WIPER LEFT									F3	
30.130	XW21126-315-R32	MOS		0				26-JUL-2000		\$354.	
	2-22826	HRS/MSA	O/C	0				7325		7	
	REF: AMM 30-40-00	AFL		0				5360			

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
300161 30.130	MOTOR, WINDSHIELD WIPER RIGHT 5823099-402 213743 REF: AMM 30-40-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0	F3	
300106 30.020	REGULATOR, PRESSURE 4753042-501 3300U REF: AMM 30-10-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0	F4 \$403.	
300116 30.040	SWITCH, PRESSURE 3753045-507 287 REF: AMM 30-10-00	MOS HRSMSC AFL	O/C	0						31-OCT-1992 5170 3802	F4	
300141 30.090	SWITCH, PRESSURE INDICATOR NO. 1 ENGINE 12299 SN-UNKNOWN REF: AMM 30-20-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0	E1	
300144 30.090	SWITCH, PRESSURE INDICATOR NO. 2 ENGINE 12299 1246 REF: AMM 30-20-00	MOS HRSMSC AFL	O/C	0				06/29/1993		29-DEC-1992 5203 4938	E2	
300121 30.050	SWITCH, VACUUM 3-753064-501 277 REF: AMM 30-10-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0	F4	
300151 30.120	SWITCH, WINDSHIELD THERMOSTAT LEFT PN SN-UNKNOWN REF: AMM 30-40-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0	F3	
300153 30.120	SWITCH, WINDSHIELD THERMOSTAT RIGHT PN SN-UNKNOWN REF: AMM 30-40-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0	F3	
300131 30.070	TIMER, DE-ICER 3-753046-1 G426 REF: AMM 30-10-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0	F4	
300126 30.060	VALVE, DISTRIBUTOR 753511-1 41359U REF: AMM 30-10-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0	F4	
300136 30.080	VALVE, NO. 1 NACELLE ANTI-ICE F10A-5-SCP-102-5 193RW REF: AMM 30-20-00	MOS HRSMSC AFL	O/C	0						30-JAN-1984 1468 908	E1	

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
300138 30.080	VALVE, NO.2 NACELLE ANTI-ICE F10A-5-SCP-102-5 8100435 REF: AMM 30-20-00	MOS HRS/MSC AFL	O/C	0					12-OCT-1983 1321 810	E2	
CHAPTER 31 INDICATING/RECORDING SYSTEMS											
310101 31.010	CLOCK, COCKPIT DIGITAL 811-B 15324 REF: NO REF	MOS HRS/MSC AFL	O/C	0					11-FEB-1982 0 0	F3	
CHAPTER 32 LANDING GEAR											
321189U 32.400	-- REPL SPARE MAIN WHEEL BLT BLEED BRAKE SYSTEM	MOS HRS/MSC AFL	O/C						26-NOV-1989 4427 2984	L2	
320678 32.550	DYE PENETRANT CHECK LEFT WHEEL AXLE PKG 2, 3	MOS HRS/MSC AFL	O/C						17-JAN-2001 7494 5466	L1	
321178 32.550	DYE PENETRANT CHECK RIGHT WHEEL AXLE PKG 2, 3	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594	L2	
+ 322176 32.420	FUNCTIONAL CHECK ANTI-SKID DETECTOR SYSTEM PKG 2, 3	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594	F3 1	
+ 322211 32.450	FUNCTIONAL TEST EMERGENCY GEAR EXTENSION PKG 3	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360	F3	
+ 322206 32.440	FUNCTIONAL TEST EMERGENCY GEAR EXTENSION CONTROL CABLE PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594	F3 1	
+ 322191 32.430	FUNCTIONAL TEST LANDING GEAR (NORMAL) PKG 2, 3	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594	F3	
+ 322201 32.430	FUNCTIONAL TEST LANDING GEAR FREE FALL PKG 2, 3 REF: See Workcard	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594	F3	

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
+ 320691 32.020	INSPECT LEFT MAIN GEAR/WELL (A) PKG 1, 2, 3	MOS HRS/MSC AFL	200							26-JUN-2001 7687 5594	L1 1.5	
	REF: AMM 5-20-04											
+ 320201 32.0101	INSPECT NOSE GEAR (A) PKG 1, 2, 3	MOS HRS/MSC AFL	200							26-JUN-2001 7687 5594	L3 1.5	
	REF: AMM 5-20-01											
+ 320206 32.0102	INSPECT NOSE GEAR (B) PKG 2, 3	MOS HRS/MSC AFL	400							26-JUN-2001 7687 5594	L3	
	REF: AMM 5-20-01											
+ 322156 32.410	INSPECT/CLEAN LEFT ANTI-SKID DETECTOR PKG 1, 2, 3	MOS HRS/MSC AFL	200							26-JUN-2001 7687 5594	L1 1	
	REF: AMM 5-20-04											
+ 322171 32.410	INSPECT/CLEAN RIGHT ANTI-SKID DETECTOR PKG 1, 2, 3	MOS HRS/MSC AFL	200							26-JUN-2001 7687 5594	L2 1	
	REF: AMM 5-20-04											
320607 32.570	LUBRICATE LEFT ACTUATOR BOLTS PKG 2, 3	MOS HRS/MSC AFL	400							26-JUN-2001 7687 5594	L1	
	REF: AMM 5-20-04/SL WW-2494R3											
321107 32.570	LUBRICATE RIGHT ACTUATOR BOLTS PKG 2, 3	MOS HRS/MSC AFL	400							26-JUN-2001 7687 5594	L2	
	REF: AMM 5-20-04/SL WW-2494R3											
+ 322174 32.425	OPERATIONAL CHECK ANTI-SKID LIGHTS PKG 1, 2, 3	MOS HRS/MSC AFL	200							26-JUN-2001 7687 5594	F3 .5	
	REF: AMM 32-44-00											
320686 32.180	REPLACE LEFT MAIN WHEEL BOLTS	MOS HRS/MSC AFL	O/C							09-NOV-1996 5951 4589	L1	
	REF: NO REF											
321186 32.180	REPLACE RIGHT MAIN WHEEL BOLTS	MOS HRS/MSC AFL	O/C							09-NOV-1996 5951 4589	L2	
	REF: NO REF											
320186 32.150	RIG STEERING SYSTEM	MOS HRS/MSC AFL	C/C							11-FEB-1982 0 0	L3	
	REF: AMM 32-50-00											

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEMNO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION			COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR			
320621	AXLE, PISTON ROD FORK/ LEFT								L1
32.220	ES12908-503	MOS					11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C	0			0		
	REF: AMM 32-20-01	AFL					0		
321121	AXLE, PISTON ROD FORK/ RIGHT								L2
32.220	ES12908-504	MOS					11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C	0			0		
	REF: AMM 32-20-01	AFL					0		
321611	BOTTLE, EMERGENCY STORAGE							LIFE LIMIT	F5
32.350	3753015-501	MOS	288	0			11-FEB-1982	11-FEB-2006	
	07510A1	HRS/MSC		0			0		1
	REF: AMM 32-30-12	AFL		0			0		
+ 321616	CHECK LANDING GEAR EMERGENCY SYSTEM PRESSURE								F5
32.350	PKG 2, 3	MOS					26-JUN-2001		
		HRS/MSC	400				7687		
	REF: AMM 12-10-04	AFL					5594		
+ 321613	HYDROSTATIC TEST								F5
32.350		MOS	36				26-OCT-1999	26-OCT-2002	
		HRS/MSC					6961		
	REF: AMM 32-30-12	AFL					5135		
320171	BRACE ASSEMBLY, DRAG NOSE GEAR								L3
32.240	PN	MOS					11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C	0			0		
	REF: AMM 32-20-02	AFL					0		
320173	ADJUST PRELOAD								L3
32.240		MOS					11-FEB-1982		
		HRS/MSC	C/C				0		
	REF: AMM 32-20-02	AFL					0		
320611	BRACE ASSEMBLY, SIDE/JURY LEFT MAIN GEAR								L1
32.230	EA1681-503	MOS					11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C	0			0		
	REF: AMM 32-10-02	AFL					0		
320616	ADJUST LEFT JURY BRACE PRELOAD								L1
32.230		MOS					11-FEB-1982		
		HRS/MSC	C/C				0		
	REF: AMM 32-10-02	AFL					0		
321111	BRACE ASSEMBLY, SIDE/JURY RIGHT MAIN GEAR								L2
32.230	EA1681-503	MOS					11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C	0			0		
	REF: AMM 32-10-02	AFL					0		
321116	ADJUST RIGHT JURY BRACE PRELOAD								L2
32.230		MOS					11-FEB-1982		
		HRS/MSC	C/C				0		
	REF: AMM 32-10-02	AFL					0		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date **11-APR-2002**

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
320232 32.600	BRACKET, LOWER STEERING NOSE GEAR A0122360300-001 SN-UNKNOWN REF: AMM 32-50-08	MOS HRS/MSC AFL	O/C						22-FEB-2000 7107 5232	L3	
+ 320238 32.600	INSPECT REF: AMM 32-50-08	MOS HRS/MSC AFL	1600						22-FEB-2000 7107 5232	L3 8707	
SB 1124-32-139 LOWER ASSOCIATED	LANDING GEAR SERVICE BULLETIN REF: Method of Compliance: OPEN	MOS HRS/MSC AFL	A/R						0 0		
320231 32.600	BRACKET, UPPER STEERING NOSE GEAR A01223603000-001 SN-JNKOWN REF: AMM 32-50-08	MOS HRS/MSC AFL	O/C						22-FEB-2000 7107 5232	L3	
+ 320237 32.600	INSPECT REF: AMM 32-50-08	MOS HRS/MSC AFL	1600						22-FEB-2000 7107 5232	L3 8707	
SB 1124-32-139 UPPER ASSOCIATED	LANDING GEAR SERVICE BULLETIN PKG 3 REF: Method of Compliance: OPEN	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360	8125	
322113 32.390	BRAKE, LEFT MAIN GEAR 5002805-3 21139-1 REF: AMM 32-43-01	MOS HRS/MSC AFL	O/C	0	0	0			17-JAN-2001 7494 5466	L1 \$1978. 2	
322136 32.400 ASSOCIATED	BLEED BRAKE SYSTEM REF: AMM 32-43-00	MOS HRS/MSC AFL	O/C						17-JAN-2001 7494 5466	L2	
+ 322116 32.390	INSPECT/CHECK LEFT BRAKE LININGS PKG 1, 2, 3 REF: AMM 32-43-01	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594	L1 1	
322128 32.390	BRAKE, RIGHT MAIN GEAR 5002805-3 JAN86-531 REF: AMM 32-43-01	MOS HRS/MSC AFL	O/C	0	0	0			17-JAN-2001 7494 5466	L2 \$1978. 2	
322136 32.400 ASSOCIATED	BLEED BRAKE SYSTEM REF: AMM 32-43-00	MOS HRS/MSC AFL	O/C						17-JAN-2001 7494 5466	L2	

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
+ 322131 32.390	INSPECT/CHECK RIGHT BRAKE LININGS PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594	L2 1	
	REF: AMM 32-43-01	AFL									
322141 32.490	CONTROL BOX, ANTI-SKID 5-823519-503	MOS HRS/MSC AFL	O/C	0					11-FEB-1982 0 0	F5 2	
	REF: AMM 32-44-01	AFL									
+ 322176 32.420 ASSOCIATED	FUNCTIONAL CHECK ANTI-SKID DETECTOR SYSTEM PKG 2, 3	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594	F3 1	
	REF: AMM 32-44-00	AFL									
320121 32.060	CYLINDER, ACTUATOR NOSE GEAR 5713059-505	MOS HRS/MSC AFL	O/C	0					11-FEB-1982 0 0	L3 \$483. 3	
	REF: AMM 32-30-06	AFL									
320646 32.310	CYLINDER, AFT ACTUATING LEFT MAIN GEAR 5713061-505	MOS HRS/MSC AFL	O/C						09-JUN-1989 4274 2800	L1 \$443.	
	SN-UNKNOWN	HRS/MSC									
	REF: AMM 32-30-03	AFL									
321146 32.310	CYLINDER, AFT ACTUATING RIGHT MAIN GEAR 5713061-505	MOS HRS/MSC AFL	O/C		0				13-NOV-1995 5718 4397	L2 \$443.	
	REF: AMM 32-30-03	AFL									
320641 32.300	CYLINDER, FORWARD ACTUATING LEFT MAIN GEAR 5713061-505	MOS HRS/MSC AFL	O/C	0					11-FEB-1982 0 0	L1 \$443.	
	REF: AMM 32-30-03	AFL									
321141 32.300	CYLINDER, FORWARD ACTUATING RIGHT MAIN GEAR 5713061-505	MOS HRS/MSC AFL	O/C	0					11-FEB-1982 0 0	L2 \$443.	
	REF: AMM 32-30-03	AFL									
320181 32.140	CYLINDER, STEERING ACTUATING LEFT 4713096-509	MOS HRS/MSC AFL	O/C	0					11-FEB-1982 0 0	L3 5	
	REF: AMM 32-50-02	AFL									
320184 32.140	CYLINDER, STEERING ACTUATING RIGHT 4713096-509	MOS HRS/MSC AFL	O/C	0					11-FEB-1982 0 0	L3 5	
	REF: AMM 32-50-02	AFL									
320651 32.260	CYLINDER, UNLOCK LEFT MAIN GEAR 4713058-505	MOS HRS/MSC AFL	O/C	0					11-FEB-1982 0 0	L1	
	REF: AMM 32-30-05	AFL									

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
321151 32.260	CYLINDER, UNLOCK RIGHT MAIN GEAR 4713058-505 1091 REF: AMM 32-30-05	MOS HRS/MS AFL	O/C	0					11-FEB-1982 0 0	L2	
320126 32.070	CYLINDER, UNLOCK NOSE GEAR 4713005-501 0567 REF: AMM 32-30-08	MOS HRS/MS AFL	O/C		0			06/08/1995 08-DEC-1994 5526 4218		L3	
322151 32.410	DETECTOR, ANTI-SKID LEFT MAIN GEAR 5-713513-503 200 REF: AMM 32-44-06	MOS HRS/MS AFL	O/C	0				13-JUL-1988 3978 2511		L1 \$1064. 1	
+ 322176 32.420 ASSOCIATED	FUNCTIONAL CHECK ANTI-SKID DETECTOR SYSTEM PKG 2, 3 REF: AMM 32-44-00	MOS HRS/MS AFL	400					26-JUN-2001 7687 5594		F3 1	
+ 322156 32.410 ASSOCIATED	INSPECT/CLEAN LEFT ANTI-SKID DETECTOR PKG 1, 2, 3 REF: AMM 5-20-04	MOS HRS/MS AFL	200					26-JUN-2001 7687 5594		L1 1	
+ 322174 32.425 ASSOCIATED	OPERATIONAL CHECK ANTI-SKID LIGHTS PKG 1, 2, 3 REF: AMM 32-44-00	MOS HRS/MS AFL	200					26-JUN-2001 7687 5594		F3 .5	
322166 32.410	DETECTOR, ANTI-SKID RIGHT MAIN GEAR 5-713513-504 553 REF: AMM 32-44-06	MOS HRS/MS AFL	O/C	0				17-DEC-1983 1454 878		L2 \$1064. 1	
+ 322176 32.420 ASSOCIATED	FUNCTIONAL CHECK ANTI-SKID DETECTOR SYSTEM PKG 2, 3 REF: AMM 32-44-00	MOS HRS/MS AFL	400					26-JUN-2001 7687 5594		F3 1	
+ 322171 32.410 ASSOCIATED	INSPECT/CLEAN RIGHT ANTI-SKID DETECTOR PKG 1, 2, 3 REF: AMM 5-20-04	MOS HRS/MS AFL	200					26-JUN-2001 7687 5594		L2 1	
+ 322174 32.425 ASSOCIATED	OPERATIONAL CHECK ANTI-SKID LIGHTS PKG 1, 2, 3 REF: AMM 32-44-00	MOS HRS/MS AFL	200					26-JUN-2001 7687 5594		F3 .5	
322111 32.380	FUSE, BRAKE HYDRAULIC LEFT 3-713047 1797 REF: AMM 32-43-04	MOS HRS/MS AFL	O/C	0				11-FEB-1982 0 0		W1	

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
322126 32.380	FUSE, BRAKE HYDRAULIC RIGHT 3-713047 3371 REF: AMM 32-43-04	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	W2	
320601 32.210	GEAR ASSEMBLY, MAIN LEFT 400-144-511 1L195 REF: AMM 32-10-01	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	L1	
320631 32.470	CHECK MAIN GEAR PARALLELISM REF: AMM 32-10-01	MOS HRS/MSC AFL	C/C							11-FEB-1982 0 0	L1	
320634 32.480	CHECK LEFT MAIN GEAR CLEARANCE REF: AMM 32-10-01	MOS HRS/MSC AFL	C/C							11-FEB-1982 0 0	L1	
+ 322211 32.450 ASSOCIATED	FUNCTIONAL TEST EMERGENCY GEAR EXTENSION PKG 3 REF: AMM 32-30-00	MOS HRS/MSC AFL	800							26-JUL-2000 7325 5360	F3	
+ 322208 32.440 ASSOCIATED	FUNCTIONAL TEST EMERGENCY GEAR EXTENSION CONTROL CABLE PKG 1, 2, 3 REF: AMM 32-30-00	MOS HRS/MSC AFL	200							26-JUN-2001 7687 5594	F3 1	
+ 322191 32.430 ASSOCIATED	FUNCTIONAL TEST LANDING GEAR (NORMAL) PKG 2, 3 REF: AMM 32-30-00	MOS HRS/MSC AFL	400							26-JUN-2001 7687 5594	F3	
+ 322201 32.430 ASSOCIATED	FUNCTIONAL TEST LANDING GEAR FREE FALL PKG 2, 3 REF: See Workcard	MOS HRS/MSC AFL	400							26-JUN-2001 7687 5594	F3	
SL WW-2494 R3 LEFT ASSOCIATED	LANDING GEAR SERVICE LETTER REF: See Workcard Method of Compliance: OPEN	MOS HRS/MSC AFL	300							26-JUN-2001 7687 5594	L1 7987	
320606 32.030	LUBRICATE LEFT MAIN GEAR PKG 1, 2, 3 REF: AMM 12-20-00	MOS HRS/MSC AFL	200							26-JUN-2001 7687 5594	L1 .5	
320636 32.040	SERVICE LEFT MAIN GEAR SHOCK STRUT PKG 2, 3 REF: AMM 12-10-04	MOS HRS/MSC AFL	400							26-JUN-2001 7687 5594	L1 2	

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO	WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
SL	WW-24103 LEFT	SERVICE LETTER							L1
	ASSOCIATED		MOS						
		REF:	HRS/MSC	A/R			0		
		Method of Compliance: OPEN	AFL				0		
321101		GEAR ASSEMBLY, MAIN RIGHT							L2
32.210		400-144-512	MOS				11-FEB-1982		
		1L195	HRS/MSC	O/C	0		0		
		REF: AMM 32-10-01	AFL				0		
321134		CHECK RIGHT MAIN GEAR CLEARANCE							L2
32.480			MOS				11-FEB-1982		
		REF: AMM 32-10-01	HRS/MSC	C/C			0		
			AFL				0		
+ 322211		FUNCTIONAL TEST EMERGENCY GEAR EXTENSION							F3
32.450		PKG 3	MOS				26-JUL-2000		
	ASSOCIATED		HRS/MSC	800			7325		
		REF: AMM 32-30-00	AFL				5360		
+ 322206		FUNCTIONAL TEST EMERGENCY GEAR EXTENSION CONTROL CABLE							F3
32.440		PKG 1, 2, 3	MOS				26-JUN-2001		
	ASSOCIATED		HRS/MSC	200			7687		1
		REF: AMM 32-30-00	AFL				5594		
+ 322191		FUNCTIONAL TEST LANDING GEAR (NORMAL)							F3
32.430		PKG 2, 3	MOS				26-JUN-2001		
	ASSOCIATED		HRS/MSC	400			7687		
		REF: AMM 32-30-00	AFL				5594		
+ 322201		FUNCTIONAL TEST LANDING GEAR FREE FALL							F3
32.430		PKG 2, 3	MOS				26-JUN-2001		
	ASSOCIATED		HRS/MSC	400			7687		
		REF: See Workcard	AFL				5594		
SL	WW-2494 R3 RIGHT	LANDING GEAR SERVICE LETTER							L2
	ASSOCIATED		MOS				26-JUN-2001		
		REF: See Workcard	HRS/MSC	300			7687	7987	
			AFL				5594		
321106		LUBRICATE RIGHT MAIN GEAR							L2
32.030		PKG 1, 2, 3	MOS				26-JUN-2001		
			HRS/MSC	200			7687		.5
		REF: AMM 12-20-00	AFL				5594		
SL	WW-24103 RIGHT	SERVICE LETTER							L2
	ASSOCIATED		MOS						
		REF:	HRS/MSC	A/R			0		
		Method of Compliance: OPEN	AFL				0		
321136		SERVICE RIGHT MAIN GEAR SHOCK STRUT							L2
32.040		PKG 2, 3	MOS				26-JUN-2001		
			HRS/MSC	400			7687		2
		REF: AMM 12-10-04	AFL				5594		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
320101 32.050	NOSE GEAR ASSEMBLY, 400-143-511 1L184 REF: AMM 32-20-01	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	L3	
320179 32.580	INSPECT NOSE STEERING CABLES PKG 3 REF: AMM 32-50-07	MOS HRS/MSC AFL		800						26-JUL-2000 7325 5360	L1	
320120 32.520	INSPECT OUTER STRUT BODY FORGING REF: AMM 32-20-01	MOS HRS/MSC AFL		1200						22-FEB-2000 7107 5232	L3	
320118 32.540	INSPECT/LUBRICATE UPPER/LOWER STRUT BEARINGS BODY REF: AMM 32-20-01	MOS HRS/MSC AFL		24 1200						22-FEB-2000 7107 5232	L3	
320106 32.030	LUBRICATE NOSE GEAR/DOORS PKG 1, 2, 3 REF: AMM 12-20-00	MOS HRS/MSC AFL		200						26-JUN-2001 7687 5594	L3	
320180 32.590	LUBRICATE NOSE STEERING CONTROL CABLES PKG 3 REF: AMM 12-20-00	MOS HRS/MSC AFL		800						26-JUL-2000 7325 5360	L1	
SB 900280 ASSOCIATED	SB WW 24-28A SERVICE BULLETIN REF: See Workcard Method of Compliance: OPEN	MOS HRS/MSC AFL		1200						22-FEB-2000 7107 5232	L3	
320116 32.040	SERVICE SHOCK STRUT PKG 2, 3 REF: AMM 12-10-04	MOS HRS/MSC AFL		400						26-JUN-2001 7687 5594	L3	
320172 32.240	TEST DRAG BRACE DOWNLOCK TENSION PKG 3 REF: AMM 32-20-02	MOS HRS/MSC AFL		800						26-JUL-2000 7325 5360	L3	
+ 320110 32.560	X-RAY INSPECT NOSE GEAR SHAFT AND DOOR ASSEMBLIES REF: AMM 5-10-00	MOS HRS/MSC AFL		60 5000						16-JUN-1997 6135 4707	L3	
321603 32.200	SELECTOR, GEAR VALVE 713025-501 IL-41 REF: NO REF	MOS HRS/MSC AFL	O/C	0				06/09/1995	09-DEC-1994	5526 4218	F3	

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date **11-APR-2002**

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
320661 32.280	SWITCH, DOWNLOCK LEFT MAIN GEAR 4-823051 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	L1	
320663 32.280	ADJUST REF: AMM 32-60-00	MOS HRS/MSC AFL	C/C							11-FEB-1982 0 0	L1	
320131 32.080	SWITCH, DOWNLOCK NOSE GEAR 4-823012-501 SN-UNKNOWN REF: AMM 32-60-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	L3	
320133 32.080	ADJUST REF: AMM 32-60-00	MOS HRS/MSC AFL	C/C							11-FEB-1982 0 0	L3	
321161 32.280	SWITCH, DOWNLOCK RIGHT MAIN GEAR 4-823051 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	L2	
321163 32.280	ADJUST REF: AMM 32-60-00	MOS HRS/MSC AFL	C/C							11-FEB-1982 0 0	L2	
320666 32.290	SWITCH, GROUND CONTACT LEFT MAIN GEAR 4-823051 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	L1	
320668 32.290	ADJUST REF: AMM 32-60-00	MOS HRS/MSC AFL	C/C							11-FEB-1982 0 0	L1	
320141 32.100	SWITCH, GROUND CONTACT NOSE GEAR 4-823053-501 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	L3	
320143 32.100	ADJUST REF: AMM 32-60-00	MOS HRS/MSC AFL	C/C							11-FEB-1982 0 0	L3	
321166 32.290	SWITCH, GROUND CONTACT RIGHT MAIN GEAR 4-823024-505 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	L2	

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
321168 32.290	ADJUST	MOS								11-FEB-1982	L2	
	REF: AMM 32-60-00	HRS/MSC AFL	C/C						0 0			
320656 32.270	SWITCH, UPLOCK LEFT MAIN GEAR 3-823003	MOS								11-FEB-1982	L1	
	SN-UNKNOWN REF: NO REF	HRS/MSC AFL	O/C	0					0 0			
320658 32.270	ADJUST	MOS								11-FEB-1982	L1	
	REF: AMM 32-60-00	HRS/MSC AFL	C/C						0 0			
320136 32.090	SWITCH, UPLOCK NOSE GEAR 3-823003	MOS								11-FEB-1982	L3	
	SN-UNKNOWN REF: AMM 32-60-00	HRS/MSC AFL	O/C	0					0 0			
320138 32.090	ADJUST	MOS								11-FEB-1982	L3	
	REF: AMM 32-60-00	HRS/MSC AFL	C/C						0 0			
321156 32.270	SWITCH, UPLOCK RIGHT MAIN GEAR 3-823003	MOS								11-FEB-1982	L2	
	SN-UNKNOWN REF: NO REF	HRS/MSC AFL	O/C	0					0 0			
321158 32.270	ADJUST	MOS								11-FEB-1982	L2	
	REF: AMM 32-60-00	HRS/MSC AFL	C/C						0 0			
320681 32.180	TIRE, LEFT MAIN GEAR 249K83-3	MOS							0	09-NOV-1996	L1	
	SN-UNKNOWN REF: AMM 32-41-00	HRS/MSC AFL	O/C	0					5951 4589		2	
321181 32.190	TIRE, RIGHT MAIN GEAR 249K83-3	MOS							0	09-NOV-1996	L2	
	SN-UNKNOWN REF: AMM 32-41-00	HRS/MSC AFL	O/C	0					5951 4589		2	
320161 32.110	TIRE, LEFT NOSE GEAR 164F43-2	MOS							0	22-NOV-1995	L3	
	31162139 REF: AMM 32-42-00	HRS/MSC AFL	O/C	0					5720 4401			
320166 32.120	TIRE, RIGHT NOSE GEAR 164F43-2	MOS							0	29-NOV-1995	L3	
	22051064 REF: AMM 32-42-00	HRS/MSC AFL	O/C	0					5720 4401			

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
320626 32.250	UPLOCK, LEFT MAIN GEAR 5-173057-501 SN-UNKNOWN REF: AMM 32-32-04	MOS HRSMSC AFL	O/C	0					11-FEB-1982 0 0	L1	
321126 32.250	UPLOCK, RIGHT MAIN GEAR 5-173057-502 SN-UNKNOWN REF: AMM 32-30-04	MOS HRSMSC AFL	O/C	0					11-FEB-1982 0 0	L2	
320176 32.130	VALVE ASSEMBLY, STEERING BA1801-2 1L185 REF: AMM 32-50-01	MOS HRSMSC AFL	O/C	0					11-FEB-1982 0 0	L3	
322146 32.500	VALVE, ANTI-SKID CONTROL LEFT 5723578-1 313A REF: AMM 32-44-02	MOS HRSMSC AFL	O/C	0					11-FEB-1982 0 0	F5	
322149 32.500	CLEAN FILTERS REF: AMM 32-41-00	MOS HRSMSC AFL	1200					22-FEB-2000 7107 5232	8307	F5	
+ 322176 32.420 ASSOCIATED	FUNCTIONAL CHECK ANTI-SKID DETECTOR SYSTEM PKG 2, 3 REF: AMM 32-44-00	MOS HRSMSC AFL	400					26-JUN-2001 7687 5594		F3 1	
322161 32.500	VALVE, ANTI-SKID CONTROL RIGHT 5723578-1 503A REF: AMM 32-44-02	MOS HRSMSC AFL	O/C	0				11-FEB-1982 0 0		F5	
322169 32.500	CLEAN FILTERS REF: AMM 32-41-00	MOS HRSMSC AFL	1200					22-FEB-2000 7107 5232	8307	F5	
+ 322176 32.420 ASSOCIATED	FUNCTIONAL CHECK ANTI-SKID DETECTOR SYSTEM PKG 2, 3 REF: AMM 32-44-00	MOS HRSMSC AFL	400					26-JUN-2001 7687 5594		F3 1	
322106 32.370	VALVE, BRAKE SHUTTLE LEFT 4-713066 2752 REF: AMM 32-43-03	MOS HRSMSC AFL	O/C	0				11-FEB-1982 0 0		W1	
322121 32.370	VALVE, BRAKE SHUTTLE RIGHT 4-713066 2775 REF: AMM 32-43-03	MOS HRSMSC AFL	O/C	0				11-FEB-1982 0 0		W2	

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
321606 32.340	VALVE, EMERGENCY GEAR EXTENSION 874521B SN-UNKNOWN REF: AMM 32-30-11	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F5	
321601 32.320	VALVE, LANDING GEAR CONTROL 4753036 372 REF: AMM 32-30-01	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F2 \$644. 25	
320177 32.170	VALVE, NOSE STEERING SOLENOID 713557-501 SN-UNKNOWN REF: AMM 32-50-00	MOS HRS/MSC AFL	O/C							11-FEB-1982 0 0	L3	
320191 32.160	OPERATIONAL CHECK NOSE STEERING REF: AMM 32-50-00	MOS HRS/MSC AFL	C/C							11-FEB-1982 0 0	L3	
322181 32.510	VALVE, PARKING MOTOR 3-713551 L34900 REF: AMM 32-44-03	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F5	
+ 322176 32.420 ASSOCIATED	FUNCTIONAL CHECK ANTI-SKID DETECTOR SYSTEM PKG 2, 3 REF: AMM 32-44-00	MOS HRS/MSC AFL		400						26-JUN-2001 7687 5594	F3 1	
322101 32.360	VALVE, POWER BRAKE 5713001-501 617AB REF: AMM 32-43-02	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F2 \$1932. 5	
320221 32.330	VALVE, SHUTTLE NOSE GEAR 4713066 SN-UNKNOWN REF: AMM 32-30-07	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	L3	
320671 32.180	WHEEL HALF, INBOARD LEFT MAIN GEAR 5002806-2 JUN89-537 REF: AMM 32-41-00	MOS HRS/MSC AFL	O/C							09-NOV-1996 5951 4589	L1 1	
320681 32.180 ASSOCIATED	CHANGE LEFT MAIN GEAR TIRE 249K83-3 SN-UNKNOWN REF: AMM 32-41-00	MOS HRS/MSC AFL	O/C	0 0 0						09-NOV-1996 5951 4589	L1 2	
320672 32.180 ASSOCIATED	CHANGE LEFT MAIN GEAR OUTBOARD WHEEL HALF 5002806-2 JUN89-537 REF: AMM 32-41-00	MOS HRS/MSC AFL	O/C							09-NOV-1996 5951 4589	L1 1	

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
320678	DYE PENETRANT CHECK LEFT WHEEL AXLE										L1	
32.550	PKG 2, 3	MOS							26-JUN-2001			
	ASSOCIATED	HRS/MSC	400						7687			
	REF: AMM 5-20-04	AFL							5594			
+ 320691	INSPECT LEFT MAIN GEAR/WELL (A)										L1	
32.020	PKG 1, 2, 3	MOS							26-JUN-2001			
	ASSOCIATED	HRS/MSC	200						7687	1.5		
	REF: AMM 5-20-04	AFL							5594			
+ 322156	INSPECT/CLEAN LEFT ANTI-SKID DETECTOR										L1	
32.410	PKG 1, 2, 3	MOS							26-JUN-2001			
	ASSOCIATED	HRS/MSC	200						7687	1		
	REF: AMM 5-20-04	AFL							5594			
+ 320676	INSPECT/LUBRICATE LEFT MAIN GEAR INBOARD WHEEL BEARINGS										L1	
32.180	PKG 1, 2, 3	MOS							26-JUN-2001			
	ASSOCIATED	HRS/MSC	200						7687	1		
	REF: AMM 32-41-00	AFL							5594			
+ 322174	OPERATIONAL CHECK ANTI-SKID LIGHTS										F3	
32.425	PKG 1, 2, 3	MOS							26-JUN-2001			
	ASSOCIATED	HRS/MSC	200						7687	.5		
	REF: AMM 32-44-00	AFL							5594			
320686	REPLACE LEFT MAIN WHEEL BOLTS										L1	
32.180		MOS							09-NOV-1996			
	ASSOCIATED	HRS/MSC	O/C						5951			
	REF: NO REF	AFL							4589			
321171	WHEEL HALF, INBOARD RIGHT MAIN GEAR										L2	
32.190	5002806-2	MOS							09-NOV-1996			
	MAR84-662	HRS/MSC	O/C						5951	1		
	REF: AMM 32-41-00	AFL							4589			
321181	CHANGE RIGHT MAIN GEAR TIRE										L2	
32.190	249K83-3	MOS				0			09-NOV-1996			
	ASSOCIATED	HRS/MSC	O/C			0			5951	2		
	REF: AMM 32-41-00	AFL				0			4589			
321172	CHANGE RIGHT MAIN GEAR OUTBOARD WHEEL HALF										L2	
32.190	5002806-2	MOS							09-NOV-1996			
	ASSOCIATED	HRS/MSC	O/C						5951	1		
	MAR84-662	HRS/MSC	O/C						5951			
	REF: AMM 32-41-00	AFL							4589			
321178	DYE PENETRANT CHECK RIGHT WHEEL AXLE										L2	
32.550	PKG 2, 3	MOS							26-JUN-2001			
	ASSOCIATED	HRS/MSC	400						7687			
	REF: AMM 5-20-04	AFL							5594			
+ 322171	INSPECT/CLEAN RIGHT ANTI-SKID DETECTOR										L2	
32.410	PKG 1, 2, 3	MOS							26-JUN-2001			
	ASSOCIATED	HRS/MSC	200						7687	1		
	REF: AMM 5-20-04	AFL							5594			

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
+ 321176	INSPECT/LUBRICATE RIGHT MAIN GEAR INBOARD WHEEL BEARINGS										L2	
32.180	PKG 1, 2, 3	MOS							26-JUN-2001			
	REF: AMM 32-41-00	HRS/MSC	200						7687		1	
		AFL							5594			
+ 322174	OPERATIONAL CHECK ANTI-SKID LIGHTS										F3	
32.425	PKG 1, 2, 3	MOS							26-JUN-2001			
ASSOCIATED		HRS/MSC	200						7687		.5	
	REF: AMM 32-44-00	AFL							5594			
321186	REPLACE RIGHT MAIN WHEEL BOLTS										L2	
32.180		MOS							09-NOV-1996			
ASSOCIATED		HRS/MSC	O/C						5951			
	REF: NO REF	AFL							4589			
320672	WHEEL HALF, OUTBOARD LEFT MAIN GEAR										L1	
32.180	5002806-2	MOS							09-NOV-1996			
	JUN89-537	HRS/MSC	O/C						5951		1	
	REF: AMM 32-41-00	AFL							4589			
320681	CHANGE LEFT MAIN GEAR TIRE										L1	
32.180	249K83-3	MOS				0			09-NOV-1996			
ASSOCIATED	SN-UNKNOWN	HRS/MSC	O/C			0			5951		2	
	REF: AMM 32-41-00	AFL				0			4589			
320678	DYE PENETRANT CHECK LEFT WHEEL AXLE										L1	
32.550	PKG 2, 3	MOS							26-JUN-2001			
ASSOCIATED		HRS/MSC	400						7687			
	REF: AMM 5-20-04	AFL							5594			
+ 320691	INSPECT LEFT MAIN GEAR/WELL (A)										L1	
32.020	PKG 1, 2, 3	MOS							26-JUN-2001			
ASSOCIATED		HRS/MSC	200						7687		1.5	
	REF: AMM 5-20-04	AFL							5594			
+ 322156	INSPECT/CLEAN LEFT ANTI-SKID DETECTOR										L1	
32.410	PKG 1, 2, 3	MOS							26-JUN-2001			
ASSOCIATED		HRS/MSC	200						7687		1	
	REF: AMM 5-20-04	AFL							5594			
+ 320680	INSPECT/LUBRICATE LEFT MAIN GEAR OUTBOARD WHEEL BEARINGS										L1	
32.180	PKG 1, 2, 3	MOS							26-JUN-2001			
		HRS/MSC	200						7687			
	REF: AMM 32-41-00	AFL							5594			
+ 322174	OPERATIONAL CHECK ANTI-SKID LIGHTS										F3	
32.425	PKG 1, 2, 3	MOS							26-JUN-2001			
ASSOCIATED		HRS/MSC	200						7687		.5	
	REF: AMM 32-44-00	AFL							5594			
320686	REPLACE LEFT MAIN WHEEL BOLTS										L1	
32.180		MOS							09-NOV-1996			
ASSOCIATED		HRS/MSC	O/C						5951			
	REF: NO REF	AFL							4589			

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
321172	WHEEL HALF, OUTBOARD RIGHT MAIN GEAR										L2	
32.190	5002806-2	MOS								09-NOV-1996		
	MAR84-662	HRS/MSC	O/C							5951	1	
	REF: AMM 32-41-00	AFL								4589		
321181	CHANGE RIGHT MAIN GEAR TIRE										L2	
32.190	249K83-3	MOS								09-NOV-1996		
ASSOCIATED	SN-UNKNOWN	HRS/MSC	O/C							5951	2	
	REF: AMM 32-41-00	AFL								4589		
321178	DYE PENETRANT CHECK RIGHT WHEEL AXLE										L2	
32.550	PKG 2, 3	MOS								26-JUN-2001		
ASSOCIATED		HRS/MSC	400							7687		
	REF: AMM 5-20-04	AFL								5594		
+ 321191	INSPECT RIGHT MAIN GEAR/WELL (A)										L2	
32.020	PKG 1, 2, 3	MOS								26-JUN-2001		
		HRS/MSC	200							7687	1.5	
	REF: AMM 5-20-04	AFL								5594		
+ 322171	INSPECT/CLEAN RIGHT ANTI-SKID DETECTOR										L2	
32.410	PKG 1, 2, 3	MOS								26-JUN-2001		
ASSOCIATED		HRS/MSC	200							7687	1	
	REF: AMM 5-20-04	AFL								5594		
321180	INSPECT/LUBRICATE RIGHT MAIN GEAR OUTBOARD WHEEL BEARINGS										L2	
32.180	PKG 1, 2, 3	MOS								26-JUN-2001		
		HRS/MSC	200							7687	1	
	REF: AMM 32-41-00	AFL								5594		
+ 322174	OPERATIONAL CHECK ANTI-SKID LIGHTS										F3	
32.425	PKG 1, 2, 3	MOS								26-JUN-2001		
ASSOCIATED		HRS/MSC	200							7687	.5	
	REF: AMM 32-44-00	AFL								5594		
321186	REPLACE RIGHT MAIN WHEEL BOLTS										L2	
32.180		MOS								09-NOV-1996		
ASSOCIATED		HRS/MSC	O/C							5951		
	REF: NO REF	AFL								4589		
320146	WHEEL, LEFT NOSE GEAR										L3	
32.110	41874	MOS								22-NOV-1995		
	APR66-109	HRS/MSC	O/C					0		5720	4	
	REF: AMM 32-42-00	AFL								4401		
320161	CHANGE NOSE GEAR LEFT TIRE										L3	
32.110	164F43-2	MOS								22-NOV-1995		
ASSOCIATED	31162139	HRS/MSC	O/C					0		5720		
	REF: AMM 32-42-00	AFL								4401		
+ 320156	INSPECT/CLEAN/LUBRICATE BEARINGS										L3	
32.110	PKG 1, 2, 3	MOS								26-JUN-2001		
		HRS/MSC	200							7687	1.5	
	REF: AMM 5-20-01	AFL								5594		

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
320151	WHEEL, RIGHT NOSE GEAR									L3	
32.120	9541874	MOS							29-NOV-1995		
	OCT75-641	HRS/MSC	O/C		0				5720	4	
	REF: AMM 32-42-00	AFL							4401		
320166	CHANGE NOSE GEAR RIGHT TIRE									L3	
32.120	164F43-2	MOS							29-NOV-1995		
ASSOCIATED	22051064	HRS/MSC	O/C		0				5720		
	REF: AMM 32-42-00	AFL							4401		
+ 320158	INSPECT/CLEAN/LUBRICATE BEARINGS									L3	
32.120	PKG 1, 2, 3	MOS							26-JUN-2001		
		HRS/MSC	200						7687	1.5	
	REF: AMM 5-20-01	AFL							5594		
CHAPTER 33	LIGHTS										
330226	BATTERY, EMERGENCY LIGHT									F4	
33.100	AD-2058	MOS			0				06-OCT-1998		
	SN-UNKNOWN	HRS/MSC	O/C		0				6520		
	REF: AMM 33-50-00	AFL			0				4889		
330320	INVERTER, LIGHT POWER (CF-38-3)									F2	
33.070	CF-38-3	MOS							11-FEB-1982		
	291	HRS/MSC	O/C		0				0		
	REF: NO REF	AFL							0		
330111	LIGHT, TAIL CONE									F1	
33.020	4-823006-501	MOS							11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C		0				0		
	REF: AMM 33-40-00	AFL							0		
330161	LIGHT, ANTI-COLLISION LOWER									F1	
33.030	G-9950-11	MOS						10/28/1989	28-APR-1989	\$635.	
	11709	HRS/MSC	O/C						4240		
	REF: AMM 33-40-00	AFL							2767		
330156	LIGHT, ANTI-COLLISION UPPER									T1	
33.030	G9950-11	MOS			0				26-JUL-2000	\$635.	
	11709	HRS/MSC	O/C		0				7325		
	REF: AMM 33-40-00	AFL			0				5360		
330221	LIGHT, EMERGENCY									F4	
33.090	3-823551-503	MOS							11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C		0				0		
	REF: AMM 33-50-00	AFL							0		
330226	CHANGE EMERGENCY LIGHT BATTERY									F4	
33.100	AD-2058	MOS			0				06-OCT-1998		
ASSOCIATED	SN-UNKNOWN	HRS/MSC	O/C		0				6520		
	REF: AMM 33-50-00	AFL			0				4889		
330228	CHARGE BATTERY									F4	
33.100		MOS	3						06-NOV-2001	06-FEB-2002	
		HRS/MSC	200						7774	7974	
	REF: AMM 12-10-06	AFL							5641		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
330136 33.060	LIGHT, LANDING LEFT 5-213004-1 SN-UNKNOWN REF: AMM 33-40-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0	W1	
330146 33.060	LIGHT, LANDING RIGHT 5-213004-2 SN-UNKNOWN REF: AMM 33-40-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0	W2	
330101 33.010	LIGHT, POSITION LEFT WING 301085-1 4224 REF: AMM 33-40-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0	W1	
330106 33.010	LIGHT, POSITION RIGHT WING 301085-2 5772 REF: AMM 33-40-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0	W2	
330166 33.040	LIGHT, STROBE LEFT WING 31-3172-1 SN-UNKNOWN REF: AMM 33-40-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0	W1	
330171 33.040	LIGHT, STROBE RIGHT WING 31-3172-1 SN-UNKNOWN REF: AMM 33-40-00	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0	W2	
330116 33.050	LIGHT, TAXI LEFT 5-823521-1 GE-4587 REF: AMM 33-40-00	MOS HRSMSC AFL	O/C							30-AUG-1989 4350 2898	L1	
330126 33.050	LIGHT, TAXI RIGHT 5-823521-2 GE-4587 REF: AMM 33-40-00	MOS HRSMSC AFL	O/C							30-AUG-1989 4350 2898	L2	
330505 33.085	POWER SUPPLY, 60-2799-1 SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL	O/C							11-FEB-1982 0 0	W1	
330241 33.080	POWER SUPPLY, NO. 1 60-2799-1 6701 REF: NO REF	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0	W1	
330246 33.080	POWER SUPPLY, NO. 2 60-2799-1 SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL	O/C	0						25-APR-1984 1641 1010	W2	

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
330522 33.085	POWER SUPPLY, NO.4 60-2799-1 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL								11-FEB-1982 0 0	W2	
330325 33.070	UNIT, LIGHT POWER (CV-38) CV-38 6125 REF: NO REF	MOS HRS/MSC AFL								11-FEB-1982 0 0	F2	
CHAPTER 34 NAVIGATION												
340121 34.060	DRAIN PITOT/STATIC SYSTEM PKG 1, 2, 3 REF: AMM 34-10-00	MOS HRS/MSC AFL	200							26-JUN-2001 7687 5594	F2 1.5	
340111 34.040	LEAK CHECK LEFT PITOT SYSTEM REF: AMM 34-10-01	MOS HRS/MSC AFL	O/C							26-MAR-1996	F1	
+ 340146 34.050	LEAK CHECK LEFT STATIC SYSTEM REF: AMM 34-10-01	MOS HRS/MSC AFL	24							18-JAN-2001 7494 5466	MANDATORY F1 18-JAN-2003	
340116 34.040	LEAK CHECK RIGHT PITOT SYSTEM REF: AMM 34-10-01	MOS HRS/MSC AFL	O/C							11-FEB-1982 0 0	F1	
+ 340151 34.050	LEAK CHECK RIGHT STATIC SYSTEM REF: AMM 34-10-01	MOS HRS/MSC AFL	24							18-JAN-2001 7494 5466	MANDATORY F1 18-JAN-2003	
343141 34.390	SWING CHECK NO.1 COMPASS REF: AMM 34-20-08	MOS HRS/MSC AFL	O/C							11-FEB-1982 0 0	F3	
343186 34.390	SWING CHECK NO.2 COMPASS REF: AMM 34-20-08	MOS HRS/MSC AFL	O/C							11-FEB-1982 0 0	F3	
345101 34.490	ADVISORY, FLIGHT PROFILE 622-4569-001 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F3	
345629 34.310	ALERTER, ALTITUDE 540-25100-004 SN-UNKNOWN REF: AMM 34-10-03	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F3	

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
341111 34.071	ALTIMETER, COPILOT 4883778-501 3008 REF: NO REF	MOS HRSMSC AFL	O/C	0					11-FEB-1982 0 0	F3	
+ 340151 34.050 ASSOCIATED	LEAK CHECK RIGHT STATIC SYSTEM REF: AMM 34-10-01	MOS HRSMSC AFL	24						18-JAN-2001 7494 5466	MANDATORY F1 18-JAN-2003	
+ 341116 34.071	TEST FAR 91.411 REF:	MOS HRSMSC AFL	24						18-JAN-2001 7494 5466	MANDATORY F3 18-JAN-2003	
341101 34.070	ALTIMETER, PILOT 622-3975-003 1323 REF: AMM 34-10-03	MOS HRSMSC AFL	O/C	0					11-FEB-1982 0 0	F3	
+ 340146 34.050 ASSOCIATED	LEAK CHECK LEFT STATIC SYSTEM REF: AMM 34-10-01	MOS HRSMSC AFL	24						18-JAN-2001 7494 5466	MANDATORY F1 18-JAN-2003	
+ 341106 34.070	TEST FAR 91.411 REF:	MOS HRSMSC AFL	24						18-JAN-2001 7494 5466	MANDATORY F3 18-JAN-2003	
341121 34.075	ALTIMETER, STAND-BY 622-3975-003 SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL	O/C	0					11-FEB-1982 0 0	F3	
+ 340146 34.050 ASSOCIATED	LEAK CHECK LEFT STATIC SYSTEM REF: AMM 34-10-01	MOS HRSMSC AFL	24						18-JAN-2001 7494 5466	MANDATORY F1 18-JAN-2003	
+ 340151 34.050 ASSOCIATED	LEAK CHECK RIGHT STATIC SYSTEM REF: AMM 34-10-01	MOS HRSMSC AFL	24						18-JAN-2001 7494 5466	MANDATORY F1 18-JAN-2003	
343176 34.170	ANNUNCIATOR, COMPASS COPILOT PN SN-UNKNOWN REF: AMM 34-20-08	MOS HRSMSC AFL	O/C	0					11-FEB-1982 0 0	F3	
343131 34.170	ANNUNCIATOR, COMPASS PILOT PN SN-UNKNOWN REF: AMM 34-20-08	MOS HRSMSC AFL	O/C	0					11-FEB-1982 0 0	F3	

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
346681 34.640	ANTENNA, #1 VLF 10085-2 6025 REF: AMM 34-60-02	MOS HRS/MSC AFL	O/C	0						03-APR-1989 4215 2745	F5	
347681 34.570	ANTENNA, GLIDESLOPE DMN-25-1 1896 REF: AMM 34-50-01	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F2	
346611 34.350	ANTENNA, NO.1 ADF LOOP 522-3761-001 4428 REF: AMM 34-50-03/04	MOS HRS/MSC AFL	O/C	0						31-JAN-1986 2855 1770	F1	
346131 34.330	ANTENNA, NO.1 ATC TRANSPONDER DMNI-50-6 323 REF: AMM 34-50-06	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F1	
347121 34.360	ANTENNA, NO.1 DME 4-873127-501 3234 REF: AMM 34-50-02	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F1 2	
348111 34.660	ANTENNA, NO.1 LRN 42804-000100-00 1346 REF: AMM 34-60-04	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F5	
346206 34.550	ANTENNA, NO.1 MARKER BEACON DMN-27-1/A 1919 REF: AMM 34-50-01	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F5	
346546 34.580	ANTENNA, NO.1 VOR DMN-4-15-3/D 10987 REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F5	
346636 34.350	ANTENNA, NO.2 ADF LOOP 522-3761-001 SN-UNKNOWN REF: AMM 34-50-03/04	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F1	
346136 34.330	ANTENNA, NO.2 ATC TRANSPONDER DMNI-50-6 3259 REF: AMM 34-50-06	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F1	
347621 34.360	ANTENNA, NO.2 DME 4-873127-503 3242 REF: AMM 34-50-02	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F1 2	

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date **11-APR-2002**

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
348114 34.700	ANTENNA, NO.2 LRN 42804-000100-00 SN-UNKNOWN REF: AMM 34-60-04	MOS HRSMSC AFL	O/C	0					11-FEB-1982 0 0		
346216 34.550	ANTENNA, NO.2 MARKER BEACON PN SN-UNKNOWN REF: AMM 34-50-01	MOS HRSMSC AFL	O/C	0					11-FEB-1982 0 0	F5	
346576 34.600	ANTENNA, NO.2 VOR DMN-4-15-3A 10993 REF: NO REF	MOS HRSMSC AFL	O/C	0					11-FEB-1982 0 0	F3	
345626 34.340	ANTENNA, RADIO ALTIMETER RECEIVER 522-4140-001 509 REF: AMM 34-10-04	MOS HRSMSC AFL	O/C	0					11-FEB-1982 0 0	F1	
345621 34.340	ANTENNA, RADIO ALTIMETER TRANSMIT 622-4550-001 459 REF: AMM 34-10-04	MOS HRSMSC AFL	O/C	0					11-FEB-1982 0 0	F1	
345831 34.520	ANTENNA, WEATHER RADAR 622-2504-001 270 REF: AMM 34-40-01,-02,-03,-04	MOS HRSMSC AFL	O/C	5222 3870				04/19/1993	19-FEB-1993 5222 3870	F2	
344611 34.370	BATTERY, EMERGENCY GYRO POWER SUPPLY 501-1075-05PS823A/T 1186 REF:	MOS HRSMSC AFL	O/C						06-APR-1998 6346 4787	F5 1	
344621 34.370	DEEP CYCLE POWER SUPPLY GNS-500 NAV SYSTEM MSC BFG SL-80J/JET TP-329	MOS HRSMSC AFL	O/C						06-APR-1998 6346 4787	F5	
+ 344616 34.370	INSPECT EMERGENCY POWER SUPPLY BATTERY/STAND-BY ATTITUDE GYRO REF: AMM NO REF	MOS HRSMSC AFL	3 200						06-NOV-2001 7774 5641	06-FEB-2002 7974	F5
347626 34.150	BOX, DME DUAL CONTROL PN SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL	O/C	0					11-FEB-1982 0 0	F2 1	
347641 34.580	BOX, HORIZONTAL SITUATION INDICATOR CONTROL 622-4569-001 SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL	O/C	0					11-FEB-1982 0 0	F4	

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
346551 34.590	BOX, NO.1 VOR CONTROL 622-2899-012 SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL								11-FEB-1982 0 0	F3	
346581 34.590	BOX, NO.2 VOR CONTROL DMN-4-15-3/D SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL								11-FEB-1982 0 0	F3	
342601 34.100	COMPASS, STAND-BY MAGNETIC 2-883023-501 1A234 REF: NO REF	MOS HRSMSC AFL								11-FEB-1982 0 0	F3	
342611 34.100	SWING CHECK REF: CMM	MOS HRSMSC AFL								11-FEB-1982 0 0	F3	
343113 34.440	COMPENSATOR, NO.1 656767 81082033 REF: NO REF	MOS HRSMSC AFL								11-FEB-1982 0 0	F3	
343158 34.440	COMPENSATOR, NO.2 656767 81092117 REF: NO REF	MOS HRSMSC AFL								11-FEB-1982 0 0	F3	
344131 34.220	COMPUTER, FLIGHT COPILOT 622-5224-005 SN-UNKNOWN REF: AMM 4-20-04/21-04	MOS HRSMSC AFL								11-FEB-1982 0 0	F2	
343631 34.220	COMPUTER, FLIGHT PILOT 622-5224-004 5128 REF: AMM 4-20-04/21-04	MOS HRSMSC AFL								11-FEB-1982 0 0	F2 1	
340201 34.460	COMPUTER, NAVIGATION 622-5107-001 SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL								11-FEB-1982 0 0	F3	
343671 34.480	COMPUTER, NO.1 AIR DATA 622-5465-214 1080 REF: AMM 22-20-00	MOS HRSMSC AFL								26-MAR-1996	F3	
+ 343672 34.480	CALIBRATE FAR 91.411 REF: See Workcard	MOS HRSMSC AFL	24							18-JAN-2001 7494 5466	MANDATORY F3 18-JAN-2003	

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
341604	COMPUTER, SAT TAS										F3	
34.410	630-30980-135	MOS								11-FEB-1982		
	1589	HRS/MSC	O/C	0					0			
	REF: NO REF	AFL		0					0			
346616	CONTROL, NO.1 ADF										F3	
34.260	622-4526-003	MOS								11-FEB-1982		
	10601	HRS/MSC	O/C	0					0			
	REF: NO REF	AFL							0			
346641	CONTROL, NO.2 ADF										F3	
34.260	PN	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C	0					0			
	REF: NO REF	AFL							0			
346251	CONTROLLER, NO.1 NAVIGATION										F3	
34.470	622-4524-079	MOS								14-JAN-1992		
	7898	HRS/MSC	O/C	5012					5012			
	REF: NO REF	AFL		3648					3648			
346261	CONTROLLER, NO.2 NAVIGATION										F3	
34.470	622-4524-079	MOS						07/15/1992		15-JAN-1992		
	7863	HRS/MSC	O/C						5012			
	REF: NO REF	AFL							3648			
346141	CONTROLLER, TRANSPONDER										F4	
34.540	622-4527-011	MOS								11-FEB-1982		
	6475	HRS/MSC	O/C	0					0			
	REF: NO REF	AFL		0					0			
346306	CONVERTER, NAV RECEIVER/VHF POWER										F3	
34.460	622-2093-001	MOS								11-FEB-1982		
	17233	HRS/MSC	O/C	0					0			
	REF: NO REF	AFL		0					0			
347201	CONVERTER, NO.1 DME SYNCHRO										F3	
34.650	622-1920-001	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C	0					0			
	REF: AMM 34-50-02	AFL		0					0			
347211	CONVERTER, NO.2 DME SYNCHRO										F3	
34.650	622-1920-001	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C	0					0			
	REF: AMM 34-50-02	AFL		0					0			
341096	CONVERTER, RADIO ALTIMETER										F3	
34.420	995-29400-112	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C	0					0			
	REF: NO REF	AFL		0					0			
343641	COUPLER, NO.1 FLIGHT DIRECTOR MODE										F2	
34.230	161E-2A	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C	0					0			
	REF: AMM 22-03-06	AFL							0			

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
348146 34.740	COUPLER, NO.1 LRN 42807-001 100-001 1585 REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0		
344141 34.230	COUPLER, NO.2 FLIGHT DIRECTOR MODE 161E-2A SN-UNKNOWN REF: AMM 22-03-06	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F2	
348151 34.740	COUPLER, NO.2 LRN 42807-001 100-001 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0		
345833 34.530	DISH, WEATHER RADAR FLAT ANT-318 270 REF: AMM 34-40-01	MOS HRS/MSC AFL	O/C	5222 3870				04/19/1993		19-FEB-1993 5222 3870	F2	
348116 34.670	DISPLAY, NO.1 LRN CONTROL 622-5493-001 040 REF: AMM 34-60-04	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0		
348121 34.670	DISPLAY, NO.2 LRN CONTROL 622-5493-001 SN-UNKNOWN REF: AMM 34-60-04	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0		
345631 34.300	GENERATOR, TONE (ALERTER) 540-25100-004 SN-UNKNOWN REF: AMM 34-10-03	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F3	
343101 34.110	GYRO, NO.1 DIRECTIONAL 622-4176-004 871 REF: AMM 34-20-08	MOS HRS/MSC AFL	O/C		0			04/02/1992		02-OCT-1991 4931 3454	F4	
343106 34.110	BENCH CHECK REF: CMM	MOS HRS/MSC AFL	O/C							11-FEB-1982 0 0	F4	
343651 34.200	GYRO, NO.1 VERTICAL 792-6694-001 6381 REF: AMM 34-20-07(1124/A),34-21-05(1124A)	MOS HRS/MSC AFL	O/C	0						06-JAN-1986 2808 1739	F3 2	
343146 34.110	GYRO, NO.2 DIRECTIONAL 2587193-43 81095980 REF: AMM 34-20-08	MOS HRS/MSC AFL	O/C	0						24-SEP-1987 3737 2345	F4	

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
343151 34.110	BENCH CHECK	MOS								11-FEB-1982	F4	
	REF: CMM	HRS/MSC AFL	O/C							0 0		
344151 34.200	GYRO, NO.2 VERTICAL 792-6694-001	MOS								11-FEB-1982	F3	
	SN-UNKNOWN REF: AMM 34-20-07(1124/A),34-21-05(1124A)	HRS/MSC AFL	O/C	0						0 0		
347611 34.140	INDICATOR, DME COPILOT PN	MOS								11-FEB-1982	F3	
	SN-UNKNOWN REF: NO REF	HRS/MSC AFL	O/C	0						0 0		
347111 34.140	INDICATOR, DME PILOT PN	MOS								11-FEB-1982	F3	
	SN-UNKNOWN REF: NO REF	HRS/MSC AFL	O/C	0						0 0		
344101 34.280	INDICATOR, FLIGHT DIRECTOR COPILOT 622-4808-004	MOS								11-FEB-1982	F3	
	SN-UNKNOWN REF: AMM 4-20-01/21-02	HRS/MSC AFL	O/C	0						0 0		
343601 34.280	INDICATOR, FLIGHT DIRECTOR PILOT 622-4808-004	MOS								11-FEB-1982	F3	
	823 REF: AMM 4-20-01/21-02	HRS/MSC AFL	O/C	0						0 0		
341601 34.080	INDICATOR, LEFT MACH/AIRSPEED 622-4382-013	MOS								07-APR-1987	F3	
	1302 REF: NO REF	HRS/MSC AFL	O/C	0						3676 2288		
341606 34.080	CALIBRATE	MOS								10-APR-1990	F3	
	REF: CMM	HRS/MSC AFL	O/C							4560 3132		
340111 34.040	LEAK CHECK LEFT PITOT SYSTEM	MOS								26-MAR-1996	F1	
	ASSOCIATED REF: AMM 34-10-01	HRS/MSC AFL	O/C									
+ 340146 34.050	LEAK CHECK LEFT STATIC SYSTEM	MOS	24							18-JAN-2001	MANDATORY F1	
	ASSOCIATED REF: AMM 34-10-01	HRS/MSC AFL								7494 5466	18-JAN-2003	
342090 34.380	INDICATOR, LEFT VERTICAL NAV/SPEED 622-4782-003/VNI-80	MOS								22-OCT-1982	F3	
	SN-UNKNOWN REF: NO REF	HRS/MSC AFL	O/C	0						482		

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
342101	INDICATOR, LEFT VERTICAL SPEED										F3
34.090	4883748-1	MOS							11-FEB-1982		\$486.
	640	HRS/MSC	O/C		0				0		
	REF: AMM 34-10-03	AFL							0		
342106	BENCH CHECK										F3
34.090		MOS							11-FEB-1982		
		HRS/MSC	O/C						0		
	REF: See Workcard	AFL							0		
+ 340146	LEAKCHECK LEFT STATIC SYSTEM									MANDATORY	F1
34.050		MOS	24						18-JAN-2001	18-JAN-2003	
	ASSOCIATED	HRS/MSC							7494		
	REF: AMM 34-10-01	AFL							5466		
342801	INDICATOR, NO.1 GYRO ATTITUDE										F3
34.430	4020531-170	MOS							25-MAR-1991		
	80110830	HRS/MSC	O/C		0				4830		
	REF: NO REF	AFL							3441		
347651	INDICATOR, NO.1 HORIZONTAL SITUATION										F3
34.560	622-4176-004	MOS							10-MAR-1987		
	871	HRS/MSC	O/C		0				3623		
	REF: AMM 4-20-02/21-02	AFL							2255		
342811	INDICATOR, NO.2 GYRO ATTITUDE										F3
34.430	4020531-170	MOS							19-MAR-1991		
	6020225	HRS/MSC	O/C						4827		
	REF: NO REF	AFL							3439		
347655	INDICATOR, NO.2 HORIZONTAL SITUATION										F3
34.560	622-4176-004	MOS							11-FEB-1982		
	1854	HRS/MSC	O/C		0				0		
	REF: AMM 4-20-02/21-02	AFL							0		
340601	INDICATOR, OUTSIDE AIR TEMPERATURE										F3
34.380	4883753-3	MOS							14-APR-1984		
	64128-13	HRS/MSC	O/C		0				1645		
	REF: NO REF	AFL									
345611	INDICATOR, RADIO ALTIMETER										F3
34.250	521-29007-203	MOS							11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C		0				0		
	REF: NO REF	AFL							0		
343166	INDICATOR, RADIO MAGNETIC COPILOT										F3
34.160	622-2506-002	MOS							14-DEC-1986		
	1546	HRS/MSC	O/C		0				3484		1
	REF: AMM 34-50-05	AFL							2157		
343121	INDICATOR, RADIO MAGNETIC PILOT										F3
34.160	622-2506-002	MOS							05-NOV-1986		
	1213	HRS/MSC	O/C		0				3385		1
	REF: AMM 34-50-05	AFL							2098		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
341056 34.400	INDICATOR, RATE OF CLIMB COPILOT 229-0324-010 SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0	F3	
341046 34.400	INDICATOR, RATE OF CLIMB PILOT 622-7689-003 166 REF: NO REF	MOS HRSMSC AFL	O/C	0						31-MAY-1993 5278 3928	F3	
341611 34.080	INDICATOR, RIGHT MACH/AIRSPEED 883615-513 149 REF: NO REF	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0	F3	
341616 34.080	CALIBRATE REF: CMM VENDOR	MOS HRSMSC AFL	O/C							11-FEB-1982 0 0	F3	
340116 34.040 ASSOCIATED	LEAK CHECK RIGHT PITOT SYSTEM REF: AMM 34-10-01	MOS HRSMSC AFL	O/C							11-FEB-1982 0 0	F1	
+ 340151 34.050 ASSOCIATED	LEAK CHECK RIGHT STATIC SYSTEM REF: AMM 34-10-01	MOS HRSMSC AFL	24							18-JAN-2001 7494 5466	MANDATORY 18-JAN-2003 F1	
342111 34.090	INDICATOR, RIGHT VERTICAL SPEED RCS-60-IL-10 MD12158 REF: AMM 34-10-03	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0	F3 \$486.	
342116 34.090	BENCH CHECK REF: See Workcard	MOS HRSMSC AFL	O/C							11-FEB-1982 0 0	F3	
+ 340151 34.050 ASSOCIATED	LEAK CHECK RIGHT STATIC SYSTEM REF: AMM 34-10-01	MOS HRSMSC AFL	24							18-JAN-2001 7494 5466	MANDATORY 18-JAN-2003 F1	
341605 34.410	INDICATOR, SAT TAS 622-2294-002 SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL	O/C	0						11-FEB-1982 0 0	F3	
344601 34.290	INDICATOR, STAND-BY HORIZON 501-1105-03 6010212 REF: AMM 34-20-09	MOS HRSMSC AFL	O/C	0						18-NOV-1984 2085 1284	F3	

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
345801 34.500	INDICATOR, WEATHER RADAR 622-4331-001 176 REF: AMM 34-40-01,-02,-03,-04	MOS HRS/MSC AFL				0			09/18/1993	18-MAR-1993 5231 3880	F3	
347101 34.270	INTERROGATOR, NO.1 DME 622-1233-001 13710 REF: AMM 34-50-02	MOS HRS/MSC AFL				0				11-FEB-1982 0 0	F2	
347601 34.270	INTERROGATOR, NO.2 DME 622-1233-001 15123 REF: AMM 34-50-02	MOS HRS/MSC AFL				0				11-FEB-1982 0 0	F2	
343663 34.190	PANEL, NO.1 FLIGHT GUIDANCE 622-2313-029 2661 REF: AMM 34-21-03	MOS HRS/MSC AFL				0				11-FEB-1982 0 0	F3	
343665 34.190	PANEL, NO.2 FLIGHT GUIDANCE 622-2265-030 SN-UNKNOWN REF: AMM 34-21-03	MOS HRS/MSC AFL				0				11-FEB-1982 0 0	F3	
345811 34.540	PANEL, WEATHER RADAR CONTROL DCP-320 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL				0				11-FEB-1982 0 0	F3	
340126 34.020	PORT, LEFT HEATED STATIC 3-883053-501 SN-UNKNOWN REF: AMM 34-10-01	MOS HRS/MSC AFL				0				11-FEB-1982 0 0	F1	
340121 34.060 ASSOCIATED	DRAIN PITOT/STATIC SYSTEM PKG 1, 2, 3 REF: AMM 34-10-00	MOS HRS/MSC AFL						200		26-JUN-2001 7687 5594	F2 1.5	
+ 340146 34.050 ASSOCIATED	LEAK CHECK LEFT STATIC SYSTEM REF: AMM 34-10-01	MOS HRS/MSC AFL						24		18-JAN-2001 7494 5466	MANDATORY 18-JAN-2003 F1	
340131 34.030	PORT, LEFT UNHEATED STATIC 4-883050 SN-UNKNOWN REF: AMM 34-10-01	MOS HRS/MSC AFL				0				11-FEB-1982 0 0	F1	
340121 34.060 ASSOCIATED	DRAIN PITOT/STATIC SYSTEM PKG 1, 2, 3 REF: AMM 34-10-00	MOS HRS/MSC AFL						200		26-JUN-2001 7687 5594	F2 1.5	

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
+ 340146 34.050 ASSOCIATED	LEAK CHECK LEFT STATIC SYSTEM REF: AMM 34-10-01	MOS HRS/MSC AFL	24						18-JAN-2001 7494 5466	MANDATORY 18-JAN-2003	F1	
340136 34.020	PORT, RIGHT HEATED STATIC 3-883053-502 SN-UNKNOWN REF: AMM 34-10-01	MOS HRS/MSC AFL	O/C	0					11-FEB-1982 0 0		F1	
340121 34.060 ASSOCIATED	DRAIN PITOT/STATIC SYSTEM PKG 1, 2, 3 REF: AMM 34-10-00	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594		F2 1.5	
+ 340151 34.050 ASSOCIATED	LEAK CHECK RIGHT STATIC SYSTEM REF: AMM 34-10-01	MOS HRS/MSC AFL	24						18-JAN-2001 7494 5466	MANDATORY 18-JAN-2003	F1	
340141 34.030	PORT, RIGHT UNHEATED STATIC 4-883050 SN-UNKNOWN REF: AMM 34-10-01	MOS HRS/MSC AFL	O/C	0					11-FEB-1982 0 0		F1	
340121 34.060 ASSOCIATED	DRAIN PITOT/STATIC SYSTEM PKG 1, 2, 3 REF: AMM 34-10-00	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594		F2 1.5	
+ 340151 34.050 ASSOCIATED	LEAK CHECK RIGHT STATIC SYSTEM REF: AMM 34-10-01	MOS HRS/MSC AFL	24						18-JAN-2001 7494 5466	MANDATORY 18-JAN-2003	F1	
340606 34.380	PROBE, OUTSIDE AIR TEMPERATURE MS28038-1 9223 REF: NO REF	MOS HRS/MSC AFL	O/C	0					11-FEB-1982 0 0		F1	
347659 34.740	PROGRAMMER, RNS 622-5110-001 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0					11-FEB-1982 0 0			
346601 34.130	RECEIVER, NO.1 ADF 622-2362-001 8945 REF: AMM 34-50-03/04	MOS HRS/MSC AFL	O/C	0					11-FEB-1982 0 0		F4 1	
346301 34.450	RECEIVER, NO.1 VHF NAVIGATION 622-0876-001 16803 REF: AMM 34-50-01	MOS HRS/MSC AFL	O/C	0					11-FEB-1982 0 0		F3	

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
346536 34.580	RECEIVER, NO.1 VOR PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0					11-FEB-1982 0 0	F3	
346626 34.130	RECEIVER, NO.2 ADF 622-2362-001 8946 REF: AMM 34-50-03/04	MOS HRS/MSC AFL	O/C	0					06-APR-1985 2317 1423	F4	
346311 34.450	RECEIVER, NO.2 VHF NAVIGATION 622-0876-001 SN-UNKNOWN REF: AMM 34-50-01	MOS HRS/MSC AFL	O/C	0 0					11-FEB-1982 0 0	F3	
346566 34.600	RECEIVER, NO.2 VOR PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0					11-FEB-1982 0 0	F3	
345608 34.420	RECEIVER, RADIO ALTIMETER 622-3201-001 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0 0					11-FEB-1982 0 0	F3	
346201 34.540	RECEIVER/TRANSMITTER, MARKER BEACON PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0 0					11-FEB-1982 0 0	F3	
345601 34.240	RECEIVER/TRANSMITTER, RADIO ALTIMETER 622-3201-001 3652 REF: AMM 34-10-04	MOS HRS/MSC AFL	O/C	0					11-FEB-1982 0 0	F2	
345821 34.510	RECEIVER/TRANSMITTER, WEATHER RADAR 622-4022-001 2126 REF: AMM 34-40-01,-02,-03,-04	MOS HRS/MSC AFL	O/C						12-APR-1995 5613 4281	F3	
344161 34.210	SELECTOR, MODE COPILOT 614E-23R SN-UNKNOWN REF: AMM 34-20-03	MOS HRS/MSC AFL	O/C	0					11-FEB-1982 0 0	F3	
343661 34.210	SELECTOR, MODE PILOT 614E-20R SN-UNKNOWN REF: AMM 34-20-03	MOS HRS/MSC AFL	O/C	0					11-FEB-1982 0 0	F3 1	
343677 34.490	SELECTOR, NO.1 REMOTE 622-4178-003 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0 0					11-FEB-1982 0 0	F3	

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
344177 34.490	SELECTOR, NO.2 REMOTE 622-4178-003 SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL								11-FEB-1982 0 0		
344121 34.180	SENSOR, RATE-OF-TURN COPILOT 622-0181-001 SN-UNKNOWN REF: AMM 22-11-05(1124A), 34-20-06(1124)	MOS HRSMSC AFL								11-FEB-1982 0 0	F3	
343621 34.180	SENSOR, RATE-OF-TURN PILOT 772-5140-001 3984 REF: AMM 22-11-05(1124A), 34-20-06(1124)	MOS HRSMSC AFL								05-OCT-1983 1300 794	F3	
346101 34.320	TRANSPONDER, NO.1 ATC 622-1270-001 9608 REF: AMM 34-50-06	MOS HRSMSC AFL						06/11/1996		11-DEC-1995 5726 4410	F3 1	
346106 34.320	BENCH CHECK REF: See Workcard	MOS HRSMSC AFL								25-SEP-1991	F3	
+ 346111 34.320	TEST FAR 91.413 REF: CMM FAR 91.413	MOS HRSMSC AFL	24							18-JAN-2001 7494 5466	MANDATORY 18-JAN-2003 F3	
346116 34.320	TRANSPONDER, NO.2 ATC 622-1270-001 13112 REF: AMM 34-50-06	MOS HRSMSC AFL								11-FEB-1982 0 0	F3 3	
346121 34.320	BENCH CHECK REF: CMM VENDOR MM	MOS HRSMSC AFL								25-SEP-1991	F3 4	
+ 346126 34.320	TEST FAR 91.413 REF: CMM FAR 91.413	MOS HRSMSC AFL	24							18-JAN-2001 7494 5466	MANDATORY 18-JAN-2003 F3	
340101 34.010	TUBE, LEFT PITOT 4883049-1 59912 REF: AMM 34-10-01	MOS HRSMSC AFL								11-FEB-1982 0 0	F1	
340121 34.060 ASSOCIATED	DRAIN PITOT/STATIC SYSTEM PKG 1, 2, 3 REF: AMM 34-10-00	MOS HRSMSC AFL	200							26-JUN-2001 7687 5594	F2 1.5	

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
340111	LEAK CHECK LEFT PITOT SYSTEM	MOS								F1	
34.040	ASSOCIATED	HRS/MSC	O/C						26-MAR-1996		
	REF: AMM 34-10-01	AFL									
340106	TUBE, RIGHT PITOT	MOS								F1	
34.010	4883049-1	HRS/MSC	O/C	0					11-FEB-1982		
	58348	AFL						0			
	REF: AMM 34-10-01							0			
340121	DRAIN PITOT/STATIC SYSTEM	MOS								F2	
34.060	PKG 1, 2, 3	HRS/MSC	200						26-JUN-2001		
	ASSOCIATED	AFL						7687		1.5	
	REF: AMM 34-10-00							5594			
340116	LEAK CHECK RIGHT PITOT SYSTEM	MOS								F1	
34.040	ASSOCIATED	HRS/MSC	O/C						11-FEB-1982		
	REF: AMM 34-10-01	AFL						0			
								0			
346648	UNIT, CONTROL DISPLAY PROCESS	MOS								F3	
34.460	622-2899-016	HRS/MSC	O/C	0					11-FEB-1982		
	SN-UNKNOWN	AFL						0			
	REF: NO REF							0			
348165	UNIT, FMS AUXILIARY EQUIPMENT	MOS								F3	
34.770	622-5615-001/AEU-90	HRS/MSC	O/C						10/27/1989	27-JUL-1989	
	92	AFL						4311			
	REF: AMM 34-60-03							2856			
348160	UNIT, FMS COMPUTER RECEIVER	MOS								F3	
34.760	622-5614-020/CRU-90	HRS/MSC	O/C						12-FEB-1990		
	52	AFL						4504			
	REF: AMM 34-60-03							3073			
348170	UNIT, FMS CONTROL DISPLAY	MOS								F3	
34.790	622-5611-001/CDU-90	HRS/MSC	O/C	0					11-FEB-1982		
	040	AFL						0			
	REF: AMM 34-60-03							0			
348175	UNIT, FMS DATA ENTRY	MOS								F3	
34.780	622-5613-001/DEU-90	HRS/MSC	O/C	0					16-AUG-1984		
	183	AFL						1890			
	REF: NO REF										
348155	UNIT, FMS RADIO TUNING	MOS								F3	
34.750	622-5612-007/RTU-90	HRS/MSC	O/C	0					10-MAR-1987		
	50	AFL						3623			
	REF: AMM 34-60-03							2255			
348136	UNIT, NO. 1 LRN EQUIPMENT	MOS								F3	
34.690	622-5494-001	HRS/MSC	O/C	0					11-FEB-1982		
	SN-UNKNOWN	AFL						0			
	REF: AMM 34-60-04							0			

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
348126 34.680	UNIT, NO.1 LRN RECEIVER COMP 622-5492-001 SN-UNKNOWN REF: AMM 34-60-04	MOS HRS/MSC AFL								11-FEB-1982 0 0		
348141 34.690	UNIT, NO.2 LRN EQUIPMENT 622-5494-001 SN-UNKNOWN REF: AMM 34-60-04	MOS HRS/MSC AFL								11-FEB-1982 0 0		
348131 34.720	UNIT, NO.2 LRN RECEIVER COMP 622-5494-001 SN-UNKNOWN REF: AMM 34-60-04	MOS HRS/MSC AFL								11-FEB-1982 0 0		
346651 34.610	UNIT, VLF CONTROL DISPLAY 10060-6 2579 REF: AMM 34-10-06	MOS HRS/MSC AFL								24-SEP-1987 3737 2345	F3	
346671 34.630	UNIT, VLF OPTIONAL EQUIPMENT 10600-2-210 2695 REF: AMM 34-60-02	MOS HRS/MSC AFL						0		05-SEP-1989 4355 2904	F3	
346661 34.620	UNIT, VLF RECEIVER COMPUTER 10050-4-4A-3140 1937 REF: AMM 34-60-02	MOS HRS/MSC AFL						0		05-SEP-1989 4355 2904	F5	
343111 34.120	VALVE, NO.1 FLUX 2594484 81096488 REF: AMM 34-20-01	MOS HRS/MSC AFL						0		11-FEB-1982 0 0	W1	
343156 34.120	VALVE, NO.2 FLUX 2594484 81096489 REF: AMM 34-20-08	MOS HRS/MSC AFL						0		11-FEB-1982 0 0	W2	
CHAPTER 35	OXYGEN											
350101 35.010	CYLINDER, OXYGEN 6350A25-EE-Z 49928W REF: AMM 35-00-00	MOS HRS/MSC AFL	288					0		04-FEB-1982	LIFE LIMIT 04-FEB-2006	F2
350106 35.010	HYDROSTATIC TEST REF: AMM 35-00-00	MOS HRS/MSC AFL	36 3000							26-JUL-2000 7325 5360	26-JUL-2003 10325	F2
350141 35.040	GAUGE, OXYGEN PRESSURE PN SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL						0		11-FEB-1982 0 0		F3

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
350126	INDICATOR, OXYGEN DISCHARGE										F1	
35.040	118082	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C	0					0			
	REF: NO REF	AFL							0			
350181	MASK, PASSENGER OXYGEN L1										F4	
35.080	PN	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C	0					0			
	REF: NO REF	AFL							0			
350191	MASK, PASSENGER OXYGEN L2										F4	
35.080	PN	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C	0					0			
	REF: NO REF	AFL							0			
350201	MASK, PASSENGER OXYGEN R1										F4	
35.090	PN	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C	0					0			
	REF: NO REF	AFL							0			
350211	MASK, PASSENGER OXYGEN R2										F4	
35.090	PN	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C	0					0			
	REF: NO REF	AFL							0			
350221	MASK, PASSENGER OXYGEN R3										F4	
35.090	PN	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C	0					0			
	REF: NO REF	AFL							0			
350246	OUTLET, THERAPEUTIC OXYGEN										F4	
35.120	23599-11	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C	0					0			
	REF: NO REF	AFL							0			
350158	REGULATOR, MASK COPILOT									OVERHAUL	F3	
35.120	MC-1013-02	MOS	72	0					09-NOV-1996	09-NOV-2002		
	8161	HRS/MSC							5951			
	REF: NO REF	AFL							4589			
+ 350169U	CHECK										F3	
35.070		MOS	12						26-JUN-2001	26-JUN-2002		
		HRS/MSC	600						7687	8287		
	REF: AMM 35-00-00	AFL							5594			
350148	REGULATOR, MASK PILOT									OVERHAUL	F3	
35.120	MC-1013-02	MOS	72	0					09-NOV-1996	09-NOV-2002		
	7750	HRS/MSC		0					5951			
	REF: NO REF	AFL		0					4589			
+ 350166U	CHECK										F3	
35.070		MOS	12						26-JUN-2001	26-JUN-2002		
		HRS/MSC	600						7687	8287		
	REF: AMM 35-00-00	AFL							5594			

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
350241	REGULATOR, OXYGEN DEMAND CONTROL PANEL (PURITAN) COPILOT										F3	
35.110	101202-11	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0					0			
	REF: AMM 35-10-00	AFL							0			
350236	REGULATOR, OXYGEN DEMAND CONTROL PANEL (PURITAN) PILOT										F3	
35.110	101202-11	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0					0			
	REF: AMM 35-10-00	AFL							0			
350116	REGULATOR, PRESSURE REDUCER										F3	
35.030	112031-06	MOS								11-FEB-1982	\$970.	
	670A	HRS/MS	O/C	0					0		8	
	REF: AMM 35-00-00	AFL							0			
350136	SWITCH, ALTITUDE PRESSURE										F3	
35.060	101800	MOS								11-FEB-1982		
	8024154	HRS/MS	O/C	0					0			
	REF: AMM 35-00-00	AFL							0			
350231	SYSTEM, PASSENGER OXYGEN SUPPLY										F3	
35.100	5753004-400	MOS								11-FEB-1982	\$950.	
	189	HRS/MS	O/C	0					0		6	
	REF: AMM 35-20-00	AFL							0			
350163	INSPECT/SERVICE OXYGEN SYSTEM										F3	
35.140	189	MOS								13-NOV-1995		
	REF: AMM 35-00-00	HRS/MS	O/C						5718			
		AFL							4397			
+ 350243	TEST										F4	
35.130	PKG 3	MOS								26-JUL-2000		
	REF: AMM 35-00-00	HRS/MS	800						7325			
		AFL							5360			
350103	VALVE, OXYGEN CYLINDER										F2	
35.150	6350-A25-DDC	MOS								11-DEC-1984		
	SN-UNKNOWN	HRS/MS	O/C						2119			
	REF: NO REF	AFL							1302			
350111	VALVE, OXYGEN FILLER										F1	
35.020	26875-48	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0					0			
	REF: AMM 35-00-00	AFL							0			
350131	VALVE, OXYGEN SHUTOFF										F2	
35.050	110115	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MS	O/C	0					0			
	REF: AMM 35-00-00	AFL							0			
350108	VALVE, TOGGLE										F2	
35.150	170001	MOS								11-FEB-1982		
	8894	HRS/MS	O/C	0					0			
	REF: NO REF	AFL							0			
CHAPTER 49 AIRBORNE AUXILIARY POWER												

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
49APU1	APU, PN SN-UNKNOWN REF:	MOS HRSMSC AFL	E/C									
CHAPTER 52	DOORS											
520181 52.020	LUBRICATE CABIN ENTRANCE STEP REF: AMM 12-20-00	MOS HRSMSC AFL	O/C						11-FEB-1982 0 0		F4	
520161 52.040	DOOR, COMPARTMENT CMA21212-002 SN-UNKNOWN REF: AMM 52-30-00	MOS HRSMSC AFL	O/C	0					11-FEB-1982 0 0		F5	
520171 52.050	DOOR, COMPARTMENT REAR BAGGAGE CMA22211-001 SN-UNKNOWN REF: AMM 52-30-01	MOS HRSMSC AFL	O/C	0					11-FEB-1982 0 0		F5	
520101 52.010	DOOR, ENTRANCE CABIN 333045-505 SN-UNKNOWN REF:	MOS HRSMSC AFL	O/C	0					11-FEB-1982 0 0		F4	
+ 520106 52.010	INSPECT/LUBRICATE PKG 1, 2, 3 REF: AMM 52-10-00/12-20-00	MOS HRSMSC AFL	200						26-JUN-2001 7687 5594		F4	
+ 520116 52.010	OPERATIONAL CHECK PKG 1, 2, 3 REF: AMM 52-10-00	MOS HRSMSC AFL	200						26-JUN-2001 7687 5594		F4	
520136 52.030	HATCH, EMERGENCY EXIT LEFT 5-33 3031-501 SN-UNKNOWN REF: AMM 52-20-00	MOS HRSMSC AFL	O/C	0					11-FEB-1982 0 0		F4	
+ 520141 52.030	INSPECT/LUBRICATE SEAL PKG 3 REF: See Workcard	MOS HRSMSC AFL	800						26-JUL-2000 7325 5360		F4	
520146 52.030	HATCH, EMERGENCY EXIT RIGHT 5-33 3031-501 SN-UNKNOWN REF: AMM 52-20-00	MOS HRSMSC AFL	O/C	0					11-FEB-1982 0 0		F4	
+ 520151 52.030	INSPECT/LUBRICATE SEAL PKG 3 REF: See Workcard	MOS HRSMSC AFL	800						26-JUL-2000 7325 5360		F4	

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
520166 52.060	SEAL, COMPARTMENT DOOR CMA21212-057 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F5	
520173 52.060	SEAL, COMPARTMENT DOOR REAR BAGGAGE CMA22211-006 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F5	
520126 52.010	SEAL, ENTRANCE DOOR CABIN 333045-181 SN-UNKNOWN REF: AMM 52-10-00	MOS HRS/MSC AFL	O/C	0						01-DEC-1995 5727 4410	F4	
520176 52.020	STEP, ENTRANCE CABIN 5-123580-1 SN-UNKNOWN REF: AMM 52-60-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F4	
CHAPTER 53 FUSELAGE												
+ 530121 53.0202	INSPECT NOSE COMPARTMENT (B) PKG 2, 3 REF: AMM 5-20-01,-05	MOS HRS/MSC AFL	400							26-JUN-2001 7687 5594	F2	
+ 530300 53.170	INSPECT AFT FUSELAGE STRUCTURE REF: AMM 5-40-02	MOS HRS/MSC AFL	4800							24-AUG-1993 5326 3975	MANDATORY F5 10126	
+ 530235 53.120	INSPECT AFT PRESSURE BULKHEAD AFT WEBS REF: AMM 5-40-01	MOS HRS/MSC AFL	15000								MANDATORY F5 15000	
+ 530230 53.110	INSPECT AFT PRESSURE BULKHEAD FORWARD WEBS. REF: AMM 5-40-01	MOS HRS/MSC AFL	9600								MANDATORY F5 9600	
+ 530250 53.150	INSPECT AFT PRESSURE BULKHEAD J-BEAM SPLICE FROM CABIN SIDE REF: AMM 5-40-01	MOS HRS/MSC AFL	9600								MANDATORY F5 9600	
+ 530255 53.160	INSPECT AFT PRESSURE BULKHEAD J-BEAM SPLICE FROM FUEL COMPARTMENT REF: AMM 5-40-01	MOS HRS/MSC AFL	15000								MANDATORY F5 15000	
+ 530240 53.130	INSPECT AFT PRESSURE BULKHEAD PERIPHERAL SECTION FROM CABIN SIDE. REF: AMM 5-40-01	MOS HRS/MSC AFL	9600								MANDATORY F5 9600	

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEMNO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
+ 530245 53.140	INSPECT AFT PRESSURE BULKHEAD PERIPHERAL SECTION FROM FUEL COMPARTMENT	MOS HRS/MSC AFL	15000							MANDATORY	F5	
	REF: AMM 5-40-01	AFL								15000		
+ 530176 53.060	INSPECT AUXILIARY FUEL TANK STRUCTURE	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360		F5	
	REF: AMM 5-20-09	AFL										
+ 530146 53.0401	INSPECT CABIN (A)	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594		F4	
	REF: AMM 5-20-02	AFL										
+ 530156 53.0402	INSPECT CABIN (C)	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360		F4	
	REF: AMM 5-20-02	AFL										
+ 530131 53.0301	INSPECT COCKPIT (A)	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594		F3	
	REF: AMM 5-20-02,-03	AFL										
+ 530136 53.0302	INSPECT COCKPIT (B)	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594		F3	
	REF: AMM 5-20-02	AFL										
+ 530141 53.0303	INSPECT COCKPIT (C)	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360		F3	
	REF: AMM 5-20-02	AFL										
+ 530220 53.100	INSPECT ENTRY DOOR STOPS	MOS HRS/MSC AFL	5400						24-AUG-1993 5326 3975	MANDATORY 10726	F4	
	REF: AMM 5-40-01	AFL										
+ 530205 53.180	INSPECT FORWARD TO AFT MAIN FRAME	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360	8125	F4	
	REF: AMM 5-40-01	AFL										
+ 530200 53.080	INSPECT FORWARD TO AFT PRESSURE BULKHEAD-FUSELAGE	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360	MANDATORY 8125	F4	
	REF: AMM 5-40-01	AFL										
+ 530101 53.010	INSPECT FUSELAGE (A)	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594		F1	
	REF: AMM 5-20-02	AFL										

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
+ 530210 53.090	INSPECT FUSELAGE SKINS FLIGHT COMPARTMENT SIDE WINDOW	MOS HRS/MSC AFL	4800						24-AUG-1993 5326 3975	MANDATORY 10126	F4	
	REF: AMM 5-40-01											
+ 530116 53.0201	INSPECT NOSE COMPARTMENT (A) PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594		F2	
	REF: AMM 5-20-01,-05											
+ 530161 53.0501	INSPECT REAR COMPARTMENT (A) PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594		F5	
	REF: AMM 5-20-05											
+ 530166 53.0502	INSPECT REAR COMPARTMENT (B) PKG 2, 3	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594		F5	
	REF: AMM 5-20-05											
531101 53.070	CONE, NOSE F10A-5-RD5-20000-7 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	O/C	0					11-FEB-1982 0 0		F2	
CHAPTER 54 NACELLES/PYLONS												
+ 540200 54.020	INSPECT ENGINE SUPPORT INSTALLATION	MOS HRS/MSC AFL	4800						24-AUG-1993 5326 3975	MANDATORY 10126		
	REF: AMM 5-40-04											
+ 540101U 54.0101	INSPECT NO. 1 ENGINE NACELLE/PYLON (A) PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594		E1	
	REF: AMM 5-20-07,-08/12-02-00											
+ 540106U 54.0102	INSPECT NO. 1 ENGINE NACELLE/PYLON (B) PKG 2, 3	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594		E1 3	
	REF: AMM 5-20-07,-08/12-02-00											
+ 540111U 54.0103	INSPECT NO. 1 ENGINE NACELLE/PYLON (C) PKG 3	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360		E1	
	REF: AMM 5-20-07,-08/12-02-00											
+ 540121U 54.0101	INSPECT NO. 2 ENGINE NACELLE/PYLON (A) PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594		E2	
	REF: AMM 5-20-07,-08/12-02-00											
+ 540126U 54.0102	INSPECT NO. 2 ENGINE NACELLE/PYLON (B) PKG 2, 3	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594		E2 3	
	REF: AMM 5-20-07,-08/12-02-00											

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
+ 540131U 54.0103	INSPECT NO. 2 ENGINE NACELLE/PYLON (C) PKG 3	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360	E2	
CHAPTER 55 STABILIZERS											
+ 550101 55.0101	INSPECT EMPENNAGE (A) PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594	T1	
REF: AMM 5-20-07,-08/12-02-00											
+ 550106 55.0102	INSPECT EMPENNAGE (B) PKG 2, 3	MOS HRS/MSC AFL	400						26-JUN-2001 7687 5594	T1	
REF: AMM 5-20-06/12-20-00											
+ 550200 55.060	INSPECT EMPENNAGE (MAJOR)	MOS HRS/MSC AFL	4800						24-AUG-1993 5326 3975	MANDATORY T1	
REF: AMM 5-40-03											
550651 55.030	STABILIZER, HORIZONTAL 5453015-4 13-1 SN-UNKNOWN	MOS HRS/MSC AFL	O/C	0					11-FEB-1982 0 0	T1	
REF: AMM 55-10-00											
550656 55.040	CHECK AFT SPAR SPLICE-HINGE FITTING OUTBOARD LUGS FOR CRACKS PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594	T1	
REF: AMM 55-10-00											
550658 55.050	CHECK ASSEMBLY RADIAL/AXIAL PLAY PKG 3	MOS HRS/MSC AFL	800						26-JUL-2000 7325 5360	T1	
REF: See Workcard											
270214 27.195 ASSOCIATED	LUBRICATE AFT HINGE FITTING BEARINGS PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594	T1	
REF: NO REF											
270215 27.195 ASSOCIATED	LUBRICATE FORWARD SCISSOR ASSEMBLY PKG 1, 2, 3	MOS HRS/MSC AFL	200						26-JUN-2001 7687 5594	T1	
REF: NO REF											
SB 1124-55-097 ASSOCIATED	STABILIZER SCISSR SERVICE BULLETIN	MOS HRS/MSC AFL	A/R						0 0	T1	
REF: See Workcard											
Method of Compliance: OPEN											
550601 55.020	STABILIZER, VERTICAL 5413027-4 11 SN-UNKNOWN	MOS HRS/MSC AFL	O/C	0					11-FEB-1982 0 0	T1	
REF: See Workcard											
CHAPTER 56 WINDOWS											

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
561601 56.075	WINDOW, EMERGENCY EXIT NO.L3 LEFT PN SN-UNKNOWN REF: AMM 56-20-00	MOS HRSMSC AFL	O/C	0					11-FEB-1982 0 0	F4	
561606 56.075	WINDOW, EMERGENCY EXIT NO.R4 RIGHT PN SN-UNKNOWN REF: AMM 56-20-00	MOS HRSMSC AFL	O/C	0					11-FEB-1982 0 0	F4	
560601 56.050	WINDOW, NO.L1 LEFT 5-343016-501 SN-UNKNOWN REF: AMM 56-20-00	MOS HRSMSC AFL	O/C	0					11-FEB-1982 0 0	F4	
560606 56.060	WINDOW, NO.L2 LEFT 5-343016-501 SN-UNKNOWN REF: AMM 56-20-00	MOS HRSMSC AFL	O/C	0					11-FEB-1982 0 0	F4	
560611 56.070	WINDOW, NO.L4 LEFT 5-343016-501 SN-UNKNOWN REF: AMM 56-20-00	MOS HRSMSC AFL	O/C	0					11-FEB-1982 0 0	F4	
560616 56.080	WINDOW, NO.L5 LEFT 5-343016-501 SN-UNKNOWN REF: AMM 56-20-00	MOS HRSMSC AFL	O/C	0					11-FEB-1982 0 0	F4	
561101 56.050	WINDOW, NO.R1 RIGHT 5-343016-501 SN-UNKNOWN REF: AMM 56-20-00	MOS HRSMSC AFL	O/C	0					11-FEB-1982 0 0	F4	
561106 56.060	WINDOW, NO.R2 RIGHT 5-343016-501 SN-UNKNOWN REF: AMM 56-20-00	MOS HRSMSC AFL	O/C	0					11-FEB-1982 0 0	F4	
561111 56.070	WINDOW, NO.R3 RIGHT 5-343016-501 SN-UNKNOWN REF: AMM 56-20-00	MOS HRSMSC AFL	O/C	0					11-FEB-1982 0 0	F4	
561116 56.080	WINDOW, NO.R5 RIGHT 5-343016-501 SN-UNKNOWN REF: AMM 56-20-00	MOS HRSMSC AFL	O/C	0					11-FEB-1982 0 0	F4	
561121 56.080	WINDOW, NO.R6 RIGHT 5-343016-501 SN-UNKNOWN REF: AMM 56-20-00	MOS HRSMSC AFL	O/C	0					11-FEB-1982 0 0	F4	

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
560121	WINDOW, OVERHEAD										F3	
56.040	5-34 3021-1	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C	0					0			
	REF: AMM 56-10-02	AFL		0					0			
560126	WINDOW, OVERHEAD										F3	
56.040	5-34 3021-2	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C	0					0			
	REF: AMM 56-10-02	AFL		0					0			
560116	WINDOW, SIDE COPILOT										F3	
56.030	5-34 3003-501	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C	0					0			
	REF: AMM 56-10-04	AFL		0					0			
+ 560118	INSPECT										F3	
56.030	PKG 3	MOS								26-JUL-2000		
		HRS/MSC	800						7325			
	REF: See Workcard	AFL							5360			
560111	WINDOW, SIDE PILOT										F3	
56.030	5-34 3017-505	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C	0					0			
	REF: AMM 56-10-03	AFL		0					0			
+ 560112	INSPECT										F3	
56.030	PKG 3	MOS								26-JUL-2000		
		HRS/MSC	800						7325			
	REF: AMM 56-10-03	AFL							5360			
560107	WINDSHIELD, INNER COPILOT										F3	
56.020	5343035	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C	0					0			
	REF: AMM 56-10-01	AFL		0					0			
560102	WINDSHIELD, INNER PILOT										F3	
56.020	5343035	MOS								11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C	0					0			
	REF: AMM 56-10-01	AFL		0					0			
560106	WINDSHIELD, OUTER COPILOT										F3	
56.010	PPG 343030-2	MOS								26-AUG-2000		
	99064H0109	HRS/MSC	O/C	0					7352			
	REF: AMM 56-10-01	AFL		0					5381			
560101	WINDSHIELD, OUTER PILOT										F3	
56.010	343030-1	MOS								22-FEB-2000		
	98342H0422	HRS/MSC	O/C	0					7107			
	REF: AMM 56-10-01	AFL		0					5232			
CHAPTER 57	WINGS											
+ 570220	INSPECT LEFT OUTER WING PANELS										MANDATORY W1	
57.050		MOS								24-AUG-1993		
		HRS/MSC	4800						5326	10126		
	REF: AMM 5-40-05	AFL							3975			

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
+ 570101	INSPECT LEFT WING (A)										W1	
57.0101	PKG 1, 2, 3	MOS							26-JUN-2001			
	REF: AMM 5-20-03	HRS/MS AFL	200						7687 5594		1.5	
+ 570104	INSPECT LEFT WING (B)										W1	
57.0102	PKG 2, 3	MOS							26-JUN-2001			
	REF: AMM 5-20-03	HRS/MS AFL	400						7687 5594			
+ 570200	INSPECT LEFT WING STRUCTURE										MANDATORY W1	
57.040		MOS								15000		
	REF: AMM 5-40-05	HRS/MS AFL	15000									
+ 570120	INSPECT RIGHT AILERON BELLCRANK										W2	
57.020	PKG 1, 2, 3	MOS							26-JUN-2001			
	REF: AMM 5-20-03	HRS/MS AFL	200						7687 5594			
+ 570221	INSPECT RIGHT OUTER WING PANELS										MANDATORY W2	
57.050		MOS							24-AUG-1993			
	REF: AMM 5-40-05	HRS/MS AFL	4800						5326 3975	10126		
+ 570116	INSPECT RIGHT WING (A)										W2	
57.0101	PKG 1, 2, 3	MOS							26-JUN-2001			
	REF: AMM 5-20-03	HRS/MS AFL	200						7687 5594		1.5	
+ 570119	INSPECT RIGHT WING (B)										W2	
57.0102	PKG 2, 3	MOS							26-JUN-2001			
	REF: AMM 5-20-03	HRS/MS AFL	400						7687 5594			
+ 570201	INSPECT RIGHT WING STRUCTURE										MANDATORY W2	
57.040		MOS								15000		
	REF: AMM 5-40-05	HRS/MS AFL	15000									
570031	TANK, TIP LEFT										W1	
57.030	5213003-405	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MS AFL	O/C	0					0 0			
	REF: AMM 57-20-00											
570041	TANK, TIP RIGHT										W2	
57.030	5213003-406	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MS AFL	O/C	0					0 0			
	REF: AMM 57-20-00											
CHAPTER 71	POWER PLANT											
+ 710650U	-- INSP #1 ENG INLET NACELLE										E1	
	PKG 1, 2, 3	MOS							26-JUN-2001			
	REF:	HRS/MS AFL	200						7687 5594			

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
+ 713650U	-- INSP #2 ENG INLET NACELLE PKG 1, 2, 3	MOS							26-JUN-2001	E2	
	REF:	HRS/MSC AFL	200					7687 5594			
71EN1	ENGINE, NO. 1 3072500-2	MOS									
	P-77482	HRS/MSC	E/C								
	REF:	AFL									
71EN2	ENGINE, NO. 2 3072500-2	MOS									
	P77488	HRS/MSC	E/C								
	REF:	AFL									
CHAPTER 73	ENGINE FUEL AND CONTROL										
731101U	COMPUTER, FUEL CONT ENG #1 2101144-1	MOS						03-APR-1989	F5	\$4400.	
	SN-UNKNOWN	HRS/MSC	O/C	3972				4215		3	
	REF:	AFL		2456				2745			
733601U	COMPUTER, FUEL CONT ENG #2 2101144-1	MOS						31-MAY-1989	F5	\$4400.	
	51-2172	HRS/MSC	O/C	4215				4265		3	
	REF:	AFL		2745				2793			
732106U	INDICATOR, FUEL FLO ENG #1 6-883708-1	MOS						30-JUL-1986	F3	\$372.	
	SN-UNKNOWN	HRS/MSC	O/C	3209				3209			
	REF:	AFL		1976				1976			
734606U	INDICATOR, FUEL FLO ENG #2 6-883708-1	MOS						30-JUL-1986	F3	\$372.	
	SN-UNKNOWN	HRS/MSC	O/C	3017				3209			
	REF:	AFL		1772				1976			
CHAPTER 75	AIR										
750116	SENSOR, TEMPERATURE INLET 3070816-2	MOS						03-APR-1989	E1		
75.030	SN-UNKNOWN	HRS/MSC	O/C	3972				4215			
	REF: See Workcard	AFL		2456				2745			
750616	SENSOR, TEMPERATURE INLET 3070816-2	MOS						31-MAY-1989	E2		
75.030	15594	HRS/MSC	O/C	1592				4265			
	REF: See Workcard	AFL						2793			
CHAPTER 77	ENGINE INDICATING										
771606	INDICATOR, (N1) LOW-PRESURE NO. 2 ENGINE 6-883619-1	MOS						11-FEB-1982	F3	\$1100.	
77.020	4162	HRS/MSC	O/C	0				0			
	REF: AMM 77-00-00	AFL						0			

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
770106 77.020	INDICATOR, (N1) LOW PRESSURE NO. 1 ENGINE 6883619-1 SN-UNKNOWN REF: AMM 77-00-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F3 \$1100.	
770606 77.040	INDICATOR, (N2) HIGH-PRESSURE NO. 1 ENGINE 6883620-1 SN-UNKNOWN REF: AMM 77-00-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F3	
772106 77.040	INDICATOR, (N2) HIGH-PRESSURE NO. 2 ENGINE 6-883620-1 SN-UNKNOWN REF: AMM 77-00-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F3	
771106 77.060	INDICATOR, ITT NO. 1 ENGINE 6883621-503 R0097 REF: AMM 77-00-00	MOS HRS/MSC AFL	O/C		0					31-MAY-1993 5278 3928	F3 \$507.	
772606 77.060	INDICATOR, ITT NO. 2 ENGINE 6883621-503 R0031R REF: AMM 77-00-00	MOS HRS/MSC AFL	O/C		0					31-MAY-1993 5278 3928	F3 \$507.	
CHAPTER 78	EXHAUST											
+ 780119 78.140	CHECK #1 THRUST REVERSER SECONDARY LATCH SOLENOID SWITCH PKG 3 REF: AMM 78-30-00	MOS HRS/MSC AFL	800							26-JUL-2000 7325 5360	E1	
+ 780120 78.140	CHECK #2 THRUST REVERSER SECONDARY LATCH SOLENOID SWITCH PKG 3 REF: AMM 78-30-00	MOS HRS/MSC AFL	800							26-JUL-2000 7325 5360	E2	
+ 780116 78.110	OPERATIONAL CHECK NO.1 THRUST REVERSER PKG 3 REF: AMM 78-30-00	MOS HRS/MSC AFL	800							26-JUL-2000 7325 5360	E1	
+ 780616 78.110	OPERATIONAL CHECK NO.2 THRUST REVERSER PKG 3 REF: AMM 78-30-00	MOS HRS/MSC AFL	800							26-JUL-2000 7325 5360	E2	
780156 78.040	ACCUMULATOR, THRUST REVERSER 4723565-1 SN-UNKNOWN REF: AMM 78-34-00	MOS HRS/MSC AFL	O/C	0						11-FEB-1982 0 0	F5	
780146 78.020	ACTUATOR, THRUST REVERSER NO. 1 F10A-5-SCH203-1 0419 REF: AMM 78-34-00	MOS HRS/MSC AFL	O/C	0						02-JAN-1987 3504 2168	E1	

Aircraft Model - 1124 WESTWIND

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
780646	ACTUATOR, THRUST REVERSER NO. 2										E2	
78.020	F10A-5-SCH203-1	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C	0					0			
	REF: AMM 78-34-00	AFL							0			
780161	BOTTLE, THRUST REVERSER GAS STORAGE									LIFE LIMIT	F5	
78.050	3753015-501	MOS	288	0					11-FEB-1982	11-FEB-2006		
	07511A1	HRS/MSC										
	REF: AMM 78-34-00	AFL										
+ 780163	HYDROSTATIC TEST										F5	
78.050		MOS	36						26-OCT-1999	26-OCT-2002		
		HRS/MSC							6961			
	REF: See Workcard	AFL							5135			
780131	CONTROL ASSEMBLY, THROTTLE RETARDER FEEDBACK NO. 1									LIFE LIMIT	E1	
78.090	F10A-5SCP203-1	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	10000	0					0	10000		
	REF: AMM 78-32-00	AFL							0			
780136	CLEAN/LUBRICATE NO.1 THROTTLE RETARDER CABLE AND CASING										E1	
78.090		MOS	36						06-NOV-2001	06-NOV-2004		
		HRS/MSC							7774			
	REF: AMM 12-20-00	AFL							5641			
780631	CONTROL ASSEMBLY, THROTTLE RETARDER FEEDBACK NO. 2									LIFE LIMIT	E2	
78.090	F10A-5SCP203-2	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	10000	0					0	10000		
	REF: AMM 78-32-00	AFL							0			
780636	CLEAN/LUBRICATE NO.2 THROTTLE RETARDER CABLE AND CASING										E2	
78.090		MOS	36						06-NOV-2001	06-NOV-2004		
		HRS/MSC							7774			
	REF: AMM 78-32-00	AFL							5641			
780171	RELEASE VALVE, THRUST REVERSER										F5	
78.070	3723581-1	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C	0					0			
	REF: AMM 78-34-00	AFL							0			
780158	SWITCH, THRUST REVERSER LOW-PRESSURE										F5	
78.080	4713533-1	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C	0					0			
	REF: AMM 78-34-00	AFL							0			
780141	THRUST REVERSER ASSEMBLY, NO. 1										E1	
78.010	F10A-5-B20202-1	MOS							11-FEB-1982			
	SN-UNKNOWN	HRS/MSC	O/C	0					0			
	REF: NO REF	AFL							0			
+ 780148	INSPECT									INSPECT	E1	
78.130		MOS							20-AUG-1991			
		HRS/MSC	5000						4906	9906		
	REF: See Workcard	AFL										

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
780143 78.100	LUBRICATE PKG 3	MOS HRSMSC AFL	800						26-JUL-2000 7325 5360		E1	
780641 78.011	REF: AMM 12-20-00 THRUST REVERSER ASSEMBLY, NO. 2 F10A-5-B20202-2 SN-UNKNOWN REF: NO REF	MOS HRSMSC AFL	O/C	0					11-FEB-1982 0 0		E2	
+ 780648 78.130	INSPECT	MOS HRSMSC AFL	5000						20-AUG-1991 4906	INSPECT 9906	E2	
780643 78.100	REF: See Workcard LUBRICATE PKG 3	MOS HRSMSC AFL	800						26-JUL-2000 7325 5360		E2	
780166 78.060	VALVE, RELIEF PN SN-UNKNOWN REF: AMM 78-34-00	MOS HRSMSC AFL	O/C	0					11-FEB-1982 0 0		F5	
780151 78.030	VALVE, THRUST REVERSER CONTROL NO. 1 723573 525 REF: AMM 78-34-00	MOS HRSMSC AFL	O/C	0					08-APR-1987 3684 2293		F5 \$588. 2	
780651 78.030	VALVE, THRUST REVERSER CONTROL NO. 2 723573 SN-UNKNOWN REF: AMM 78-34-00	MOS HRSMSC AFL	O/C	0					11-FEB-1982 0 0		F5 \$588. 2	
CHAPTER 79	OIL											
791121U	IND, PRESS/TEMP ENG #1 6-883706-1 SN-UNKNOWN REF:	MOS HRSMSC AFL	O/C	0					11-FEB-1982 0 0		F3 \$805.	
792621U	IND, PRESS/TEMP ENG #2 6-883706-1 SN-UNKNOWN REF:	MOS HRSMSC AFL	O/C	0					11-FEB-1982 0 0		F3 \$805.	
790616U	VALVE, OIL TEMP ENG #1 157 025-2 SN-UNKNOWN REF:	MOS HRSMSC AFL	O/C	3972 2456					03-APR-1989 4215 2745		E1	
792116U	VALVE, OIL TEMP ENG #2 157 025-2 SN-UNKNOWN REF:	MOS HRSMSC AFL	O/C	4215					31-MAY-1989 4265 2793		E2	

Engine Model - TFE731-3

Report Date **11-APR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT----- TSN TSO TSR TSI ADJ	INSTALLATION	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
ENGINE NO. 1									
CHAPTER 71 POWER PLANT									
710140U	NO. 1 ENGINE - -- RUN ADJ/TEST #1 ENG	MOS						13-NOV-1999	
	REF:	HRS/MSC	C/C				6961		
		ENC					5135		
		(AFL)							
+ 714010	NO. 1 ENGINE - CHECK ELECTRICAL WIRES AND CONNECTIONS	MOS						26-JUL-2000	
71.040		HRS/MSC	800				7325	8125	
	REF: EMM 72-00-00	ENC					5360		
		(AFL)							
+ 715010	NO. 1 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS	MOS						26-JUL-2000	
71.050		HRS/MSC	800				7325	8125	
	REF: EMM 72-00-00	ENC					5360		
		(AFL)							
+ 710130	NO. 1 ENGINE - INSPECT FAN ROTOR ASSEMBLY BLADES	MOS						16-FEB-2001	
71.020	PKG 6, 6	HRS/MSC	300				7551		.5
	REF: EMM 72-00-00	ENC					5515		
		(AFL)							
+ 710120	NO. 1 ENGINE - MAJOR PERIODIC INSPECTION	MOS						13-NOV-1999	
71.010		HRS/MSC	1400				6961	8361	
	REF: EMM 72-00-00	ENC					5135		
		(AFL)							
710110U	NO. 1 ENGINE - ENGINE, #1	MOS						03-APR-1989	
	3072500-2	HRS/MSC	O/C	3972			4215		
	P-77482	ENC					2745		
	REF:	(AFL)		2456					
CHAPTER 72 ENGINE									
+ 724120	NO. 1 ENGINE - INSPECT COMBUSTION PLENUM CASE	MOS						13-NOV-1999	
72.030		HRS/MSC	1400				6961	8361	
	REF: EMM 72-40-04	ENC					5135		
		(AFL)							
+ 723110	NO. 1 ENGINE - INSPECT COMPRESSOR CORE	MOS						26-APR-1994	
72.010		HRS/MSC	4200				5442	9642	
	REF: NO REF	ENC					4106		
		(AFL)							

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Report Date **11-APR-2002**

Engine Model - **TFE731-3**
Owner Name - **R&S AIRCRAFT INVESTMENTS, LLC**
A/C Serial #: **368** A/C Reg. #: **N368MD**

ITEMNO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION TSN TSO TSR TSI ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
+ 727110 72.300	NO. 1 ENGINE - PERIODIC INSPECT FAN SUPPORT ASSEMBLY REF: EMM 72-70-06	MOS HRS/MSC ENC (AFL)	4200			26-APR-1994 5442 4106	9642	
724110 72.020	NO. 1 ENGINE - CASE, COMBUSTION PLENUM 3072443-4 IP8088 REF: NO REF	MOS HRS/MSC ENC (AFL)	O/C	3972		03-APR-1989 4215 2456		
+ 724120 72.030 ASSOCIATED	NO. 1 ENGINE - INSPECT COMBUSTION PLENUM CASE REF: EMM 72-40-04	MOS HRS/MSC ENC (AFL)	1400			13-NOV-1999 6961 5135	8361	
725050 72.090	NO. 1 ENGINE - DISC, FAN ROTOR 3073563-2 970322902451 REF: NO REF	MOS HRS/MSC ENC (AFL)	10000	0		13-NOV-1999 6961 5135	LIFE LIMIT 15135	
725060 72.100	NO. 1 ENGINE - DISC, STAGE 1 LOW PRESSURE COMPRESSOR 3072395 1-12112-1531 REF: NO REF	MOS HRS/MSC ENC (AFL)	10000	2456		03-APR-1989 4215 2745	LIFE LIMIT 10289	
725010 72.040	NO. 1 ENGINE - DISC, STAGE 1 LOW PRESSURE TURBINE 3072352-4 0-03229-1212 REF: NO REF	MOS HRS/MSC ENC (AFL)	3000	0		12-JUL-1991 4879 3494	LIFE LIMIT 6494	
725070 72.110	NO. 1 ENGINE - DISC, STAGE 2 LOW PRESSURE COMPRESSOR 3072396 1-12112-429 REF: NO REF	MOS HRS/MSC ENC (AFL)	10000	2456		03-APR-1989 4215 2745	LIFE LIMIT 10289	
725020 72.050	NO. 1 ENGINE - DISC, STAGE 2 LOW PRESSURE TURBINE 3072351-5 1-03226-1486 REF: NO REF	MOS HRS/MSC ENC (AFL)	3000	0		20-MAY-1993 5278 3928	LIFE LIMIT 6928	
725080 72.120	NO. 1 ENGINE - DISC, STAGE 3 LOW PRESSURE COMPRESSOR 3072397 0-12112-4057 REF: NO REF	MOS HRS/MSC ENC (AFL)	10000	2456		03-APR-1989 4215 2745	LIFE LIMIT 10289	

Engine Model - TFE731-3

Report Date **11-APR-2002**

Owner Name - **R&S AIRCRAFT INVESTMENTS, LLC**

A/C Serial #: **368** A/C Reg. #: **N368MD**

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
725030 72.060	NO. 1 ENGINE - DISC, STAGE 3 LOW PRESSURE TURBINE 3074097-1 975332202025 REF: NO REF	MOS HRSMSC ENC (AFL)	7000	0						13-NOV-1999 6961	LIFE LIMIT	
725090 72.130	NO. 1 ENGINE - DISC, STAGE 4 LOW PRESSURE COMPRESSOR 3072398 0-03160-3697 REF: NO REF	MOS HRSMSC ENC (AFL)		3972						5135 4215	12135 LIFE LIMIT	
725160 72.200	NO. 1 ENGINE - DUCT, TURBINE INTERSTAGE TRANSITION 3072318 SN-UNKNOWN REF: EMM 72-50-05	MOS HRSMSC ENC (AFL)	O/C	2456						2745 4215	10289	
726110 72.250	NO. 1 ENGINE - GEARBOX, ACCESSORY 3070003-5 SN-UNKNOWN REF: EMM 72-60-01	MOS HRSMSC ENC (AFL)	O/C	3972						2745 4215	03-APR-1989	
+ 726120 72.260	NO. 1 ENGINE - INSPECT REF: EMM 72-60-02	MOS HRSMSC ENC (AFL)	4200							26-APR-1994 5442	9642	
726130 72.270	NO. 1 ENGINE - GEARBOX, TRANSFER 3070093-3 P-2768 REF: EMM 72-60-01	MOS HRSMSC ENC (AFL)	O/C	0						03-APR-1989 4215		
725110 72.150	NO. 1 ENGINE - IMPELLER, HIGH PRESSURE 3073398-1 4-23365-1094 REF: NO REF	MOS HRSMSC ENC (AFL)	10000	3972						2745 4215	LIFE LIMIT 10289	
725180 72.220	NO. 1 ENGINE - NOZZLE, STAGE 1 LOW PRESSURE TURBINE 3072319-11 990134506659 REF: NO REF	MOS HRSMSC ENC (AFL)	O/C	0						13-NOV-1999 6961		
725140 72.180	NO. 1 ENGINE - PLATE, HIGH PRESSURE ROTOR SEAL 3072411-1 7-18040-2569 REF: NO REF	MOS HRSMSC ENC (AFL)	10000	3816 2507						5135 6961	LIFE LIMIT 12628	

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Engine Model - TFE731-3
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date **11-APR-2002**

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
725040	NO. 1 ENGINE - ROTOR, HIGH PRESSURE TURBINE									LIFE LIMIT		
72.070	3072316 1-18040-598 REF: EMM 72-50-06	MOS HRS/MS ENC (AFL)			3972				03-APR-1989 4215 2745			
			7000		2456					7289		
725170	NO. 1 ENGINE - SEAL PLATE, STAGE 1 LOW PRESSURE TURBINE											
72.210	3073552 SN-UNKNOWN REF: NO REF	MOS HRS/MS ENC (AFL)	O/C						11-FEB-1982 0 0			
725190	NO. 1 ENGINE - SEAL, LOW PRESSURE TURBINE ROTATING AIR											
72.230	3073355 SN-UNKNOWN REF: NO REF	MOS HRS/MS ENC (AFL)	O/C		0 0 0				0 0 0			
725120	NO. 1 ENGINE - SEAL, ROTATING											
72.160	3072729-1 0-23 151-343 REF: NO REF	MOS HRS/MS ENC (AFL)	O/C		0 0 0				12-JUL-1991 4879 3494			
725150	NO. 1 ENGINE - SHAFT, FAN DRIVE											
72.190	3071955-3 1P-39726 REF: NO REF	MOS HRS/MS ENC (AFL)	O/C		3972 2456				03-APR-1989 4215 2745			
725130	NO. 1 ENGINE - SHAFT, HIGH PRESSURE SHOULDERED									LIFE LIMIT		
72.170	3072545-1 1P-39446 REF: NO REF	MOS HRS/MS ENC (AFL)			3972				03-APR-1989 4215 2745			
			12000		3456					11289		
725191	NO. 1 ENGINE - SUPPORT, LOW PRESSURE TURBINE ROTATING AIR SEAL											
72.240	3073764 SN-UNKNOWN REF: NO REF	MOS HRS/MS ENC (AFL)	O/C									
725091	NO. 1 ENGINE - TIE ROD, LOW PRESSURE											
72.140	3073049-1 1P-15433 REF: EMM 72-30-10	MOS HRS/MS ENC (AFL)	O/C		3972 2456				03-APR-1989 4215 2745			
CHAPTER 73	ENGINE FUEL AND CONTROL											
+ 731120	NO. 1 ENGINE - REMOVE AND REPLACE FILTER ELEMENT											
73.020	PKG 6, 6 REF: EMM 73-21-02	MOS HRS/MS ENC (AFL)	300						16-FEB-2001 7551 5515			

Engine Model - TFE731-3

Report Date 11-APR-2002

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
732110 73.060	NO. 1 ENGINE - CONTROL UNIT, FUEL 3070800-8 SN-UNKNOWN REF: EMM 73-20-01	MOS HRS/MSC ENC (AFL)	O/C	3972						18-MAY-1989 4215		
732120 73.070 ASSOCIATED	NO. 1 ENGINE - CHANGE PRESSURE LIMITER VALVE 3070685-4 SN-UNKNOWN REF: NO REF	MOS HRS/MSC ENC (AFL)	O/C	3972						2745 03-APR-1989 4215		
731150 73.050	NO. 1 ENGINE - COOLER, FUEL/OIL 158610-5 SN-UNKNOWN REF: EMM 79-20-07	MOS HRS/MSC ENC (AFL)	O/C	3972						2745 03-APR-1989 4215		
731140 73.040	NO. 1 ENGINE - HEATER, FUEL 158670-3 SN-UNKNOWN REF: EMM 73-10-04	MOS HRS/MSC ENC (AFL)	O/C	3972						2745 03-APR-1989 4215		
731110 73.010	NO. 1 ENGINE - PUMP, ENGINE FUEL 3070850-8 SN-UNKNOWN REF: EMM 73-20-01	MOS HRS/MSC ENC (AFL)	O/C	3972						2745 03-APR-1989 4215		
+ 731120 73.020 ASSOCIATED	NO. 1 ENGINE - REMOVE AND REPLACE FILTER ELEMENT PKG 6, 6 REF: EMM 73-21-02	MOS HRS/MSC ENC (AFL)	300							16-FEB-2001 7551 5515		
732160 73.110	NO. 1 ENGINE - TRANSMITTER, FUEL FLOW 6883709-1 564 REF: NO REF	MOS HRS/MSC ENC (AFL)	O/C	0						06-MAY-1992 5105 3725		
731130 73.030	NO. 1 ENGINE - VALVE, FLOW DIVIDER/DRAIN 394366-4 SN-UNKNOWN REF: NO REF	MOS HRS/MSC ENC (AFL)	O/C	3972						2745 03-APR-1989 4215		
732110 73.060 ASSOCIATED	NO. 1 ENGINE - CHANGE FUEL CONTROL UNIT 3070800-8 SN-UNKNOWN REF: EMM 73-20-01	MOS HRS/MSC ENC (AFL)	O/C	3972						2745 18-MAY-1989 4215		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Engine Model - TFE731-3

Report Date **11-APR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
732120	NO. 1 ENGINE - CHANGE PRESSURE LIMITER VALVE											
73.070	3070685-4	MOS							03-APR-1989			
ASSOCIATED	SN-UNKNOWN	HRS/MSC	O/C	3972					4215			
	REF: NO REF	ENC										
		(AFL)		2456					2745			
732120	NO. 1 ENGINE - VALVE, PRESSURE LIMITER											
73.070	3070685-4	MOS							03-APR-1989			
	SN-UNKNOWN	HRS/MSC	O/C	3972					4215			
	REF: NO REF	ENC										
		(AFL)		2456					2745			
732140	NO. 1 ENGINE - VALVE, SOLENOID CONTROL											
73.090	109696-3-1	MOS							03-APR-1989			
	SN-UNKNOWN	HRS/MSC	O/C	3972					4215			
	REF: EMM 76-10-01	ENC										
		(AFL)		2456					2745			
732130	NO. 1 ENGINE - VALVE, SURGE BLEED											
73.080	978812-4-1	MOS							03-APR-1989			
	SN-UNKNOWN	HRS/MSC	O/C	3972					4215			
	REF: EMM 76-10-01	ENC										
		(AFL)		2456					2745			
CHAPTER 74	IGNITION											
+ 742120	NO. 1 ENGINE - INSPECT 6 O'CLOCK IGNITER PLUG											
74.040		MOS							26-JUL-2000			
		HRS/MSC	800						7325	8125		
	REF: EMM 74-00-01	ENC										
		(AFL)							5360			
+ 742140	NO. 1 ENGINE - INSPECT 7 O'CLOCK IGNITER PLUG											
74.060		MOS							26-JUL-2000			
		HRS/MSC	800						7325	8125		
	REF: EMM 74-00-01	ENC										
		(AFL)							5360			
+ 741120	NO. 1 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM											
74.020		MOS							26-JUL-2000			
		HRS/MSC	800						7325	8125	1	
	REF: EMM 74-00-01	ENC										
		(AFL)							5360			
742110	NO. 1 ENGINE - IGNITER PLUG, 6 O'CLOCK											
74.030	3071589-2	MOS							03-APR-1989			
	SN-UNKNOWN	HRS/MSC	O/C	3972					4215			
	REF: EMM 72-00-00	ENC										
		(AFL)		2456					2745			
+ 742120	NO. 1 ENGINE - INSPECT 6 O'CLOCK IGNITER PLUG											
74.040		MOS							26-JUL-2000			
ASSOCIATED		HRS/MSC	800						7325	8125		
	REF: EMM 74-00-01	ENC										
		(AFL)							5360			

Engine Model - TFE731-3

Report Date **11-APR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
742130	NO. 1 ENGINE - IGNITER PLUG, 7 O'CLOCK											
74.050	3071589-2	MOS							03-APR-1989			
	SN-UNKNOWN	HRS/MSC	O/C		3972				4215			
	REF: EMM 72-00-00	ENC										
		(AFL)			2456				2745			
+ 742140	NO. 1 ENGINE - INSPECT 7 O'CLOCK IGNITER PLUG											
74.060		MOS							26-JUL-2000			
ASSOCIATED		HRS/MSC	800						7325	8125		
	REF: EMM 74-00-01	ENC										
		(AFL)							5360			
741110	NO. 1 ENGINE - UNIT, IGNITION											
74.010	3070378-2	MOS							03-APR-1989			
	SN-UNKNOWN	HRS/MSC	O/C		3972				4215			
	REF: EMM 72-00-00	ENC										
		(AFL)			2456				2745			
+ 741120	NO. 1 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM											
74.020		MOS							26-JUL-2000			
ASSOCIATED		HRS/MSC	800						7325	8125	1	
	REF: EMM 74-00-01	ENC										
		(AFL)							5360			
CHAPTER 75	AIR											
751010	NO. 1 ENGINE - VALVE, ANTI-ICE SHUTOFF											
75.010	978944-1-1	MOS							03-APR-1989			
	SN-UNKNOWN	HRS/MSC	O/C		3972				4215			
	REF: EMM 75-10-01	ENC										
		(AFL)			2456				2745			
CHAPTER 77	ENGINE INDICATING											
772110	NO. 1 ENGINE - HARNESS, ITT THERMOCOUPLE											
77.030	3073595-1	MOS							12-JUL-1991			
	1-20219-407	HRS/MSC	O/C		0				4879			
	REF: EMM 77-20-01	ENC										
		(AFL)							3494			
771120	NO. 1 ENGINE - TRANSDUCER, HIGH PRESSURE (N2)											
77.020	3070722-2	MOS							03-APR-1989			
	SN-UNKNOWN	HRS/MSC	O/C		3972				4215			
	REF: EMM 77-10-05	ENC										
		(AFL)			2456				2745			
771110	NO. 1 ENGINE - TRANSDUCER, LOW PRESSURE (N1)											
77.010	3071928-5	MOS							03-APR-1989			
	SN-UNKNOWN	HRS/MSC	O/C		3972				4215			
	REF: EMM 77-10-03	ENC										
		(AFL)			2456				2745			
CHAPTER 79	OIL											

Report Date **11-APR-2002**

Engine Model - TFE731-3
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
+ 790110 79.010	NO. 1 ENGINE - ANALYZE ENGINE OIL PKG 4, 4,6, 6	MOS HRS/MSC ENC (AFL)	150						26-JUN-2001 7687	1	
	REF: EMM 72-00-00								5594		
790120 79.020	NO. 1 ENGINE - CHANGE OIL	MOS HRS/MSC ENC (AFL)	1400						13-NOV-1999 6961	8361	
	REF: See Workcard								5135		
+ 790130 79.030	NO. 1 ENGINE - INSPECT CHIP DETECTOR PKG 4, 4,6, 6	MOS HRS/MSC ENC (AFL)	150						26-JUN-2001 7687		
	REF: EMM 72-00-00								5594		
792150 79.080	NO. 1 ENGINE - COOLER, OIL LOWER LEFT 159900-1	MOS HRS/MSC ENC (AFL)	O/C	3972					03-APR-1989 4215		
	SN-UNKNOWN REF: EMM 79-20-09			2456					2745		
792160 79.090	NO. 1 ENGINE - COOLER, OIL LOWER RIGHT 159910-1	MOS HRS/MSC ENC (AFL)	O/C	3972					03-APR-1989 4215		
	SN-UNKNOWN REF: EMM 79-20-09			2456					2745		
792140 79.070	NO. 1 ENGINE - COOLER, OIL UPPER 158600-4	MOS HRS/MSC ENC (AFL)	O/C	3972					03-APR-1989 4215		
	SN-UNKNOWN REF: EMM 79-20-09			2456					2745		
792110 79.040	NO. 1 ENGINE - PUMP, OIL 3071949-7	MOS HRS/MSC ENC (AFL)	O/C	3972					03-APR-1989 4215		
	SN-UNKNOWN REF: EMM 79-20-03			2456					2745		
790120 79.020 ASSOCIATED	NO. 1 ENGINE - CHANGE OIL	MOS HRS/MSC ENC (AFL)	1400						13-NOV-1999 6961	8361	
	REF: See Workcard								5135		
793120 79.120	NO. 1 ENGINE - SWITCH, OIL PRESSURE 3833518	MOS HRS/MSC ENC (AFL)	O/C	3972					03-APR-1989 4215		
	SN-UNKNOWN REF: NO REF			2456					2745		

Engine Model - TFE731-3

Report Date **11-APR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
793110	NO. 1 ENGINE - TRANSMITTER, OIL PRESSURE											
79.110	101-412-80-13	MOS								03-APR-1989		
	SN-UNKNOWN	HRS/MSC	O/C				3972			4215		
	REF: NO REF	ENC										
		(AFL)					2456			2745		
792120	NO. 1 ENGINE - VALVE, OIL FILTER BYPASS											
79.050	307 0000NP69	MOS								03-APR-1989		
	SN-UNKNOWN	HRS/MSC	O/C				3972			4215		
	REF: EMM 79-30-01	ENC										
		(AFL)					2456			2745		
792130	NO. 1 ENGINE - VALVE, PRESSURE BREATHER											
79.060	307 1564-8	MOS								18-MAY-1989		
	SN-UNKNOWN	HRS/MSC	O/C							4215		
	REF: EMM 79-20-02	ENC										
		(AFL)								2745		

Engine Model - TFE731-3
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date **11-APR-2002**

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
ENGINE NO. 2												
CHAPTER 71												
POWER PLANT												
710140U	NO. 2 ENGINE - -- RUN ADJ/TEST #2 ENG	MOS								31-MAY-1993		
	REF:	HRS/MSC	C/C							5278		
		ENC								3928		
		(AFL)										
+ 714010	NO. 2 ENGINE - CHECK ELECTRICAL WIRES AND CONNECTIONS	MOS								26-JUL-2000		
71.040		HRS/MSC	800							7325	8125	
	REF: EMM 72-00-00	ENC								5360		
		(AFL)										
+ 715010	NO. 2 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS	MOS								26-JUL-2000		
71.050		HRS/MSC	800							7325	8125	
	REF: EMM 72-00-00	ENC								5360		
		(AFL)										
+ 710130	NO. 2 ENGINE - INSPECT FAN ROTOR ASSEMBLY BLADES	MOS								16-FEB-2001		
71.020	PKG 7, 7	HRS/MSC	300							7551	.5	
	REF: EMM 72-00-00	ENC								5515		
		(AFL)										
+ 710120	NO. 2 ENGINE - MAJOR PERIODIC INSPECTION	MOS								17-OCT-1998		
71.010		HRS/MSC	1400							6520	7920	
	REF: EMM 72-00-00	ENC								4889		
		(AFL)										
710110U	NO. 2 ENGINE - ENGINE, #2	MOS								31-MAY-1993		
	3072500-2	HRS/MSC	O/C			5227				5278		
	P77488	ENC								3867		
	REF:	(AFL)										
										3928		
CHAPTER 72												
ENGINE												
+ 724120	NO. 2 ENGINE - INSPECT COMBUSTION PLENUM CASE	MOS								17-SEP-1998		
72.030		HRS/MSC	1400							6520	7920	
	REF: EMM 72-40-04	ENC								4889		
		(AFL)										
+ 723110	NO. 2 ENGINE - INSPECT COMPRESSOR CORE	MOS								17-OCT-1998		
72.010		HRS/MSC	4200							6520	10720	
	REF: NO REF	ENC								4889		
		(AFL)										

Engine Model - TFE731-3

Report Date **11-APR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME-----AT-----	INSTALLATION	COMPLIANCE	DISPOSITION	AREA
WORKCARD	PART NUMBER/PKG SERIAL NUMBER			TSN TSO TSR TSI ADJ			NEXT DUE	PRICE LABOR HRS
+ 727110	NO. 2 ENGINE - PERIODIC INSPECT FAN SUPPORT ASSEMBLY							
72.300		MOS				17-MAY-1989		
		HRS/MSC	4200			4265	8465	
	REF: EMM 72-70-06	ENC				2793		
		(AFL)						
724110	NO. 2 ENGINE - CASE, COMBUSTION PLENUM							
72.020		MOS				31-MAY-1989		
	3072443-4	HRS/MSC	O/C	4215		4265		
	OP-52337	ENC						
	REF: NO REF	(AFL)		2745		2793		
+ 724120	NO. 2 ENGINE - INSPECT COMBUSTION PLENUM CASE							
72.030		MOS				17-SEP-1998		
ASSOCIATED		HRS/MSC	1400			6520	7920	
	REF: EMM 72-40-04	ENC				4889		
		(AFL)						
725050	NO. 2 ENGINE - DISC, FAN ROTOR						LIFE LIMIT	
72.090		MOS				20-MAY-1993		
	3073539-2	HRS/MSC		4087		5278		
	0-18040-4768	ENC						
	REF: NO REF	(AFL)	4100	2660		3928	5368	
725060	NO. 2 ENGINE - DISC, STAGE 1 LOW PRESSURE COMPRESSOR						LIFE LIMIT	
72.100		MOS				31-MAY-1989		
	3072395	HRS/MSC		4215		4265		
	1-12112-1647	ENC						
	REF: NO REF	(AFL)	10000	2745		2793	10048	
725010	NO. 2 ENGINE - DISC, STAGE 1 LOW PRESSURE TURBINE						LIFE LIMIT	
72.040		MOS		0		20-MAY-1993		
	3072351-5	HRS/MSC		0		5278		
	1-03229-1486	ENC						
	REF: NO REF	(AFL)	3000	0		3928	6928	
725070	NO. 2 ENGINE - DISC, STAGE 2 LOW PRESSURE COMPRESSOR						LIFE LIMIT	
72.110		MOS				31-MAY-1989		
	3072396	HRS/MSC		4215		4265		
	1-12112-581	ENC						
	REF: NO REF	(AFL)	10000	2745		2793	10048	
725020	NO. 2 ENGINE - DISC, STAGE 2 LOW PRESSURE TURBINE						LIFE LIMIT	
72.050		MOS		0		20-MAY-1993		
	3072542-5	HRS/MSC		0		5278		
	1-03229-1277	ENC						
	REF: NO REF	(AFL)	3000	0		3928	6928	
725080	NO. 2 ENGINE - DISC, STAGE 3 LOW PRESSURE COMPRESSOR						LIFE LIMIT	
72.120		MOS				31-MAY-1989		
	3072397	HRS/MSC		4215		4265		
	0-12112-1718	ENC						
	REF: NO REF	(AFL)	10000	2745		2793	10048	

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Report Date **11-APR-2002**

Engine Model - TFE731-3
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
725030 72.060	NO. 2 ENGINE - DISC, STAGE 3 LOW PRESSURE TURBINE 3072544-2 6-18040-4905 REF: NO REF	MOS HRSMSC ENC (AFL)			0				31-MAY-1989 4265	LIFE LIMIT	
			3000		0			2793	5793		
725090 72.130	NO. 2 ENGINE - DISC, STAGE 4 LOW PRESSURE COMPRESSOR 3072398 0-12112-3229 REF: NO REF	MOS HRSMSC ENC (AFL)			4215			31-MAY-1989 4265		LIFE LIMIT	
			10000		2745			2793	10048		
725160 72.200	NO. 2 ENGINE - DUCT, TURBINE INTERSTAGE TRANSITION 3072318 SN-UNKNOWN REF: EMM 72-50-05	MOS HRSMSC ENC (AFL)		O/C				31-MAY-1989 4265			
								2793			
726110 72.250	NO. 2 ENGINE - GEARBOX, ACCESSORY 3070003-5 P-948 REF: EMM 72-60-01	MOS HRSMSC ENC (AFL)		O/C	4215			31-MAY-1989 4265			
					2745			2793			
+ 726120 72.260	NO. 2 ENGINE - INSPECT REF: EMM 72-60-02	MOS HRSMSC ENC (AFL)		4200				17-MAY-1989 4265	8465		
								2793			
726130 72.270	NO. 2 ENGINE - GEARBOX, TRANSFER 3070093-3 P-3691 REF: EMM 72-60-01	MOS HRSMSC ENC (AFL)		O/C	4215			31-MAY-1989 4265			
					2745			2793			
725110 72.150	NO. 2 ENGINE - IMPELLER, HIGH PRESSURE 3073394-1 0-23369-4190 REF: NO REF	MOS HRSMSC ENC (AFL)			0			31-MAY-1989 4265		LIFE LIMIT	
			10000		0			2793	12793		
725180 72.220	NO. 2 ENGINE - NOZZLE, STAGE 1 LOW PRESSURE TURBINE 3072319 SN-UNKNOWN REF: NO REF	MOS HRSMSC ENC (AFL)		O/C				31-MAY-1989 4265			
								2793			
725140 72.180	NO. 2 ENGINE - PLATE, HIGH PRESSURE ROTOR SEAL 3072411-1 1-18040-5077 REF: NO REF	MOS HRSMSC ENC (AFL)			4215			31-MAY-1989 4265		LIFE LIMIT	
			10000		2745			2793	10048		

Engine Model - TFE731-3

Report Date **11-APR-2002**

Owner Name - **R&S AIRCRAFT INVESTMENTS, LLC**
A/C Serial #: 368 A/C Reg. #: N368MD

ITEMNO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
725040	NO. 2 ENGINE - ROTOR, HIGH PRESSURE TURBINE									LIFE LIMIT	
72.070	3072316	MOS							31-MAY-1989		
	1-18040-451	HRS/MSC				4215			4265		
	REF: EMM 72-50-06	ENC									
		(AFL)	7000			2745			2793	7048	
725170	NO. 2 ENGINE - SEAL PLATE, STAGE 1 LOW PRESSURE TURBINE										
72.210	3073552	MOS							11-FEB-1982		
	SN-UNKNOWN	HRS/MSC	O/C						0		
	REF: NO REF	ENC							0		
		(AFL)									
725190	NO. 2 ENGINE - SEAL, LOW PRESSURE TURBINE ROTATING AIR										
72.230	3073355	MOS				0					
	SN-UNKNOWN	HRS/MSC	O/C			0			0		
	REF: NO REF	ENC							0		
		(AFL)				0					
725120	NO. 2 ENGINE - SEAL, ROTATING										
72.160	3072729-1	MOS							31-MAY-1989		
	7-23151-1814	HRS/MSC	O/C			0			4265		
	REF: NO REF	ENC									
		(AFL)				0			2793		
725150	NO. 2 ENGINE - SHAFT, FAN DRIVE										
72.190	3071955-3	MOS							31-MAY-1989		
	IP-41464	HRS/MSC	O/C			4215			4265		
	REF: NO REF	ENC									
		(AFL)				2745			2793		
725130	NO. 2 ENGINE - SHAFT, HIGH PRESSURE SHOULDERED									LIFE LIMIT	
72.170	3072545-1	MOS							31-MAY-1989		
	1P-39469	HRS/MSC				4215			4265		
	REF: NO REF	ENC									
		(AFL)	12000			2745			2793	12048	
725191	NO. 2 ENGINE - SUPPORT, LOW PRESSURE TURBINE ROTATING AIR SEAL										
72.240	3073764	MOS									
	SN-UNKNOWN	HRS/MSC	O/C								
	REF: NO REF	ENC									
		(AFL)									
725091	NO. 2 ENGINE - TIE ROD, LOW PRESSURE										
72.140	3073049-1	MOS							31-MAY-1989		
	1P-15412	HRS/MSC	O/C			4215			4265		
	REF: EMM 72-30-10	ENC									
		(AFL)				2745			2793		
CHAPTER 73	ENGINE FUEL AND CONTROL										
+ 731120	NO. 2 ENGINE - REMOVE AND REPLACE FILTER ELEMENT										
73.020	PKG 7, 7	MOS							16-FEB-2001		
		HRS/MSC	300						7551		
	REF: EMM 73-21-02	ENC									
		(AFL)							5515		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Engine Model - TFE731-3

Report Date **11-APR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
732110 73.060	NO. 2 ENGINE - CONTROL UNIT, FUEL 3070800-2 A3593PT REF: EMM 73-20-01	MOS HRS/MSC ENC (AFL)	O/C							31-MAY-1989 4265 2793		
732120 73.070 ASSOCIATED	NO. 2 ENGINE - CHANGE PRESSURE LIMITER VALVE 3070685-4 A6760 REF: NO REF	MOS HRS/MSC ENC (AFL)	O/C	4215						31-MAY-1989 4265 2793		
731150 73.050	NO. 2 ENGINE - COOLER, FUEL/OIL 158610-7 21-3736 REF: EMM 79-20-07	MOS HRS/MSC ENC (AFL)	O/C	4215						31-MAY-1989 4265 2793		
731140 73.040	NO. 2 ENGINE - HEATER, FUEL 158670-3 71-2903 REF: EMM 73-10-04	MOS HRS/MSC ENC (AFL)	O/C	4215						31-MAY-1989 4265 2793		
731110 73.010	NO. 2 ENGINE - PUMP, ENGINE FUEL 3070850-8 MX364112 REF: EMM 73-20-01	MOS HRS/MSC ENC (AFL)	O/C	4215						31-MAY-1989 4265 2793		
+ 731120 73.020 ASSOCIATED	NO. 2 ENGINE - REMOVE AND REPLACE FILTER ELEMENT PKG 7, 7 REF: EMM 73-21-02	MOS HRS/MSC ENC (AFL)	300							16-FEB-2001 7551 5515		
732160 73.110	NO. 2 ENGINE - TRANSMITTER, FUEL FLOW 883709-1 SN-UNKNOWN REF: NO REF	MOS HRS/MSC ENC (AFL)	O/C	4215						31-MAY-1989 4265 2793		
731130 73.030	NO. 2 ENGINE - VALVE, FLOW DIVIDER/DRAIN 394366-4 SN-UNKNOWN REF: NO REF	MOS HRS/MSC ENC (AFL)	O/C	4215						31-MAY-1989 4265 2793		
732110 73.060 ASSOCIATED	NO. 2 ENGINE - CHANGE FUEL CONTROL UNIT 3070800-2 A3593PT REF: EMM 73-20-01	MOS HRS/MSC ENC (AFL)	O/C							31-MAY-1989 4265 2793		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

Engine Model - TFE731-3

Report Date **11-APR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
732120	NO. 2 ENGINE - CHANGE PRESSURE LIMITER VALVE										
73.070	3070685-4	MOS							31-MAY-1989		
ASSOCIATED	A6760	HRS/MSC	O/C		4215				4265		
	REF: NO REF	ENC									
		(AFL)			2745				2793		
732120	NO. 2 ENGINE - VALVE, PRESSURE LIMITER										
73.070	3070685-4	MOS							31-MAY-1989		
	A6760	HRS/MSC	O/C		4215				4265		
	REF: NO REF	ENC									
		(AFL)			2745				2793		
732140	NO. 2 ENGINE - VALVE, SOLENOID CONTROL										
73.090	109696-3-1	MOS							31-MAY-1989		
	P-3683	HRS/MSC	O/C		4215				4265		
	REF: EMM 76-10-01	ENC									
		(AFL)			2745				2793		
732130	NO. 2 ENGINE - VALVE, SURGE BLEED										
73.080	978812-4-1	MOS							31-MAY-1989		
	P-3683	HRS/MSC	O/C		4215				4265		
	REF: EMM 76-10-01	ENC									
		(AFL)			2745				2793		
CHAPTER 74	IGNITION										
+ 742120	NO. 2 ENGINE - INSPECT 6 O'CLOCK IGNITER PLUG										
74.040		MOS							26-JUL-2000		
		HRS/MSC	800						7325	8125	
	REF: EMM 74-00-01	ENC									
		(AFL)							5360		
+ 742140	NO. 2 ENGINE - INSPECT 7 O'CLOCK IGNITER PLUG										
74.060		MOS							26-JUL-2000		
		HRS/MSC	800						7325	8125	
	REF: EMM 74-00-01	ENC									
		(AFL)							5360		
+ 741120	NO. 2 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM										
74.020		MOS							26-JUL-2000		
		HRS/MSC	800						7325	8125	
	REF: EMM 74-00-01	ENC								1	
		(AFL)							5360		
742110	NO. 2 ENGINE - IGNITER PLUG, 6 O'CLOCK										
74.030	3071589-2	MOS							17-OCT-1998		
	SN-UNKNOWN	HRS/MSC	O/C						6520		
	REF: EMM 72-00-00	ENC									
		(AFL)							4889		
+ 742120	NO. 2 ENGINE - INSPECT 6 O'CLOCK IGNITER PLUG										
74.040		MOS							26-JUL-2000		
ASSOCIATED		HRS/MSC	800						7325	8125	
	REF: EMM 74-00-01	ENC									
		(AFL)							5360		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L

Report Date **11-APR-2002**

Engine Model - TFE731-3
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
742130 74.050	NO. 2 ENGINE - IGNITER PLUG, 7 O'CLOCK 3071589-2	MOS							09-NOV-1996		
	SN-UNKNOWN REF: EMM 72-00-00	HRS/MS ENC (AFL)	O/C					5951		4589	
+ 742140 74.060 ASSOCIATED	NO. 2 ENGINE - INSPECT 7 O'CLOCK IGNITER PLUG REF: EMM 74-00-01	MOS HRS/MS ENC (AFL)	800					26-JUL-2000 7325	8125	5360	
741110 74.010	NO. 2 ENGINE - UNIT, IGNITION 3070378-2	MOS						31-MAY-1989			
	SN-UNKNOWN REF: EMM 72-00-00	HRS/MS ENC (AFL)	O/C	1142				4265		2793	
+ 741120 74.020 ASSOCIATED	NO. 2 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM REF: EMM 74-00-01	MOS HRS/MS ENC (AFL)	800					26-JUL-2000 7325	8125	1 5360	
CHAPTER 75	AIR										
751010 75.010	NO. 2 ENGINE - VALVE, ANTI-ICE SHUTOFF 978944-1-1	MOS						31-MAY-1989			
	SN-UNKNOWN REF: EMM 75-10-01	HRS/MS ENC (AFL)	O/C	4215				4265		2793	
CHAPTER 77	ENGINE INDICATING										
772110 77.030	NO. 2 ENGINE - HARNESS, ITT THERMOCOUPLE 3071849-3	MOS						31-MAY-1989			
	9-20219-358 REF: EMM 77-20-01	HRS/MS ENC (AFL)	O/C					4265		2793	
771120 77.020	NO. 2 ENGINE - TRANSDUCER, HIGH PRESSURE (N2) 3070722-2	MOS						31-MAY-1989			
	SN-UNKNOWN REF: EMM 77-10-05	HRS/MS ENC (AFL)	O/C	4215				4265		2793	
771110 77.010	NO. 2 ENGINE - TRANSDUCER, LOW PRESSURE (N1) 3071928-5	MOS						31-MAY-1989			
	SN-UNKNOWN REF: EMM 77-10-03	HRS/MS ENC (AFL)	O/C	4215				4265		2793	
CHAPTER 79	OIL										

Engine Model - TFE731-3

Report Date **11-APR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
+ 790110 79.010	NO. 2 ENGINE - ANALYZE ENGINE OIL PKG 5, 5,7, 7	MOS HRS/MSC ENC (AFL)	150							26-JUN-2001 7687	1	
	REF: EMM 72-00-00									5594		
790120 79.020	NO. 2 ENGINE - CHANGE OIL	MOS HRS/MSC ENC (AFL)	1400							17-OCT-1998 6520	7920	
	REF: See Workcard									4889		
+ 790130 79.030	NO. 2 ENGINE - INSPECT CHIP DETECTOR PKG 5, 5,7, 7	MOS HRS/MSC ENC (AFL)	150							26-JUN-2001 7687		
	REF: EMM 72-00-00									5594		
792150 79.080	NO. 2 ENGINE - COOLER, OIL LOWER LEFT 159900-1 SN-UNKNOWN REF: EMM 79-20-09	MOS HRS/MSC ENC (AFL)	O/C							31-MAY-1989 4265		
										2793		
792160 79.090	NO. 2 ENGINE - COOLER, OIL LOWER RIGHT 159910-1 SN-UNKNOWN REF: EMM 79-20-09	MOS HRS/MSC ENC (AFL)	O/C	4215						31-MAY-1989 4265		
										2793		
792140 79.070	NO. 2 ENGINE - COOLER, OIL UPPER 158600-4 SN-UNKNOWN REF: EMM 79-20-09	MOS HRS/MSC ENC (AFL)	O/C	4215						31-MAY-1989 4265		
										2793		
792110 79.040	NO. 2 ENGINE - PUMP, OIL 3071949-7 0683 REF: EMM 79-20-03	MOS HRS/MSC ENC (AFL)	O/C							31-MAY-1989 4265		
										2793		
790120 79.020 ASSOCIATED	NO. 2 ENGINE - CHANGE OIL REF: See Workcard	MOS HRS/MSC ENC (AFL)	1400							17-OCT-1998 6520	7920	
										4889		
793120 79.120	NO. 2 ENGINE - SWITCH, OIL PRESSURE 3-833518 1041 REF: NO REF	MOS HRS/MSC ENC (AFL)	O/C	482						31-MAY-1989 4265		
										2793		

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:30 AM

COPYRIGHT 2001 CAMP SYSTEMS INTL

Engine Model - TFE731-3

Report Date **11-APR-2002**

Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ				
793110	NO. 2 ENGINE - TRANSMITTER, OIL PRESSURE											
79.110	101-412-80-13	MOS								31-MAY-1989		
	SN-UNKNOWN	HRS/MSC	O/C	4215						4265		
	REF: NO REF	ENC (AFL)								2793		
792120	NO. 2 ENGINE - VALVE, OIL FILTER BYPASS											
79.050	3070000NP69	MOS								31-MAY-1989		
	SN-UNKNOWN	HRS/MSC	O/C	4215						4265		
	REF: EMM 79-30-01	ENC (AFL)								2793		
792130	NO. 2 ENGINE - VALVE, PRESSURE BREATHER											
79.060	3075323-1	MOS								04-FEB-1994		
	6376	HRS/MSC	O/C		0					5390		
	REF: EMM 79-20-02	ENC (AFL)								4040		

Report Date **11-APR-2002**

Aircraft Model - **1124 WESTWIND**
Owner Name - **R&S AIRCRAFT INVESTMENTS, LLC**
A/C Serial #: **368** A/C Reg. #: **N368MD**

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
AIRCRAFT											
AD 1974-08-09 R2	AIRWORTHINESS DIRECTIVE TO PREVENT POSSIBLE FIRES THAT COULD RESULT FROM SMOKING MATERIALS BEING DROPPED INTO LAVATORY PAPER OR LINEN WASTE RECEPTACLES									F4	
		MOS						17-JAN-2001			
		HRS/MSC	1000					7494	8494		
		AFL						5466			
	REF:										
	Method of Compliance: OPEN										
AD 1989-12-08	AIRWORTHINESS DIRECTIVE TO DETECT CRACKS IN THE HINGE LUGS OF THE HORIZONTAL STABILIZER AFT SPAR SPLICE FITTING (HINGE ASSEMBLY)										
		MOS						17-JAN-2001			
		HRS/MSC	300					7494	7794		
		AFL						5466			
	REF: See Workcard										
	Method of Compliance: OPEN										
AD 1998-24-11 LEFT AILERON	AIRWORTHINESS DIRECTIVE TO PREVENT EXCESSIVE WEAR OF THE AILERON PUSH-PULL TUBE, WHICH COULD RESULT IN UNEVEN MOVEMENT OF THE CONTROL WHEEL, PERFORATION OF THE AILERON PUSH-PULL TUBE, AND CONSEQUENT REDUCED ROLL CONTROL OF THE AIRPLANE									W1	
		MOS						26-JUL-2000			
		HRS/MSC	600					7325	7925		
		AFL						5360			
	REF: AD										
	Method of Compliance: OPEN										
SB 1124-27-129 LEFT AILERON	FLIGHT CONTROLS SERVICE BULLETIN									W1	
		MOS						26-JUL-2000			
ASSOCIATED		HRS/MSC	600					7325	7925		
		AFL						5360			
	REF: BULLETINS										
	Method of Compliance: OPEN										
AD 1996-24-11 RIGHT AILERON	AIRWORTHINESS DIRECTIVE TO PREVENT EXCESSIVE WEAR OF THE AILERON PUSH-PULL TUBE, WHICH COULD RESULT IN UNEVEN MOVEMENT OF THE CONTROL WHEEL, PERFORATION OF THE AILERON PUSH-PULL TUBE, AND CONSEQUENT REDUCED ROLL CONTROL OF THE AIRPLANE									W2	
		MOS						26-JUL-2000			
		HRS/MSC	600					7325	7925		
		AFL						5360			
	REF: AD										
	Method of Compliance: OPEN										
SB 1124-27-129 RIGHT AILERON	FLIGHT CONTROLS SERVICE BULLETIN									W2	
		MOS						26-JUL-2000			
ASSOCIATED		HRS/MSC	600					7325	7925		
		AFL						5360			
	REF: BULLETINS										
	Method of Compliance: OPEN										
AD 1998-06-10	AIRWORTHINESS DIRECTIVE TO PREVENT FAILURE OF THE HYDRAULIC FUSE TO OPERATE PROPERLY IN THE EVENT OF AN EXTERNAL LEAK DOWNSTREAM OF THE FUSE, WHICH COULD RESULT IN LOSS OF HYDRAULIC SYSTEMS										
		MOS	36					06-NOV-2001	06-NOV-2004		
		HRS/MSC	1200					7774	8974		
		AFL						5641			
	REF: AD										
	Method of Compliance: OPEN										

Aircraft Model - 1124 WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
AD 2002-01-26	AIRWORTHINESS DIRECTIVE TO PREVENT FAILURE OF ATTACHMENT BOLTS DUE TO FATIGUE, WHICH COULD RESULT IN SEPARATION OF THE ENGINE INLET COWL AND AFT NACELLE, AND CONSEQUENT DAMAGE TO THE HORIZONTAL OR VERTICAL STABILIZER	MOS							MANDATORY		
		HRS/MSC	DUE						50		
	REF:	AFL									
	Method of Compliance: OPEN										
SB ASB1124-54A-138	SERVICE BULLETIN	MOS							MANDATORY		
	ASSOCIATED	HRS/MSC	A/R								
	REF:	AFL									
	Method of Compliance: OPEN										
SB 1124-27-129 LEFT AILERON	SERVICE BULLETIN FLIGHT CONTROLS	MOS						26-JUL-2000		W1	
		HRS/MSC	600					7325	7925		
		AFL						5360			
	REF: BULLETINS										
	Method of Compliance: OPEN										
SB 1124-27-129 RIGHT AILERON	SERVICE BULLETIN FLIGHT CONTROLS	MOS						26-JUL-2000		W2	
		HRS/MSC	600					7325	7925		
		AFL						5360			
	REF: BULLETINS										
	Method of Compliance: OPEN										
SB 1124-30-036 PART II	SERVICE BULLETIN ICE AND RAIN PROTECTION PKG 1, 2, 3	MOS						26-JUN-2001		F3	
		HRS/MSC	150					7687	7837		
		AFL						5594			
	REF: See Workcard										
	Method of Compliance: OPEN										
SB 1124-32-139 UPPER	SERVICE BULLETIN LANDING GEAR PKG 3	MOS						26-JUL-2000			
		HRS/MSC	800					7325	8125		
		AFL						5360			
	REF:										
	Method of Compliance: OPEN										
SB 1124-55-020 R2	SERVICE BULLETIN STABILIZERS PKG 2, 3	MOS						26-JUN-2001		T1	
		HRS/MSC	300					7687	7987		
		AFL						5594			
	REF: See Workcard										
	Method of Compliance: OPEN										
SB 900280	SERVICE BULLETIN SB WW 24-28A	MOS						22-FEB-2000		L3	
		HRS/MSC	1200					7107			
		AFL						5232			
	REF: See Workcard										
	Method of Compliance: OPEN										
SB 972850U	SERVICE BULLETIN SB 731-A72-3668 #1 ENG	MOS								RECOMMENDED 31-DEC-2002	
		HRS/MSC	A/R								
	REF:	AFL									

? - Insufficient Information
+ Task exists in FAA Manual
4/12/2002 12:26:41 AM

COPYRIGHT 2001 CAMP SYSTEMS INT'L



AIRCRAFT Status Report (AD/SI)

Aircraft Model - 1124 WESTWIND
 Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
 A/C Serial #: 368 A/C Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
SB 972851U	SERVICE BULLETIN SB 731-A72-3688 #2 ENG	MOS							RECOMMENDED		
	REF:	HRS/MS AFL	A/R						31-DEC-2002		
SB 972B40U	SERVICE BULLETIN GSBA72-3569 R/E FAN ROTOR	MOS									
	REF:	HRS/MS AFL	A/R						5722		
SL WW-2492	SERVICE LETTER HYD HOSE INSP PKG 1, 2, 3	MOS						26-JUN-2001			
	REF:	HRS/MS AFL	200					7687	7887		
	Method of Compliance: OPEN							5594			
SL WW-2494 R3 LEFT	SERVICE LETTER LANDING GEAR	MOS						26-JUN-2001		L1	
	REF: See Workcard	HRS/MS AFL	300					7687	7987		
	Method of Compliance: OPEN							5594			
SL WW-2494 R3 RIGHT	SERVICE LETTER LANDING GEAR	MOS						26-JUN-2001		L2	
	REF: See Workcard	HRS/MS AFL	300					7687	7987		
	Method of Compliance: OPEN							5594			

Engine Model - TFE731-3
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

Report Date **11-APR-2002**

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
ENGINE NO. 1											
AD 2000-15-09	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE HPC IMPELLER										
		MOS							10-OCT-2000		
		HRS/MS	4200								
	REF:	ENC									
	Method of Compliance: OPEN										
AD 2001-23-09	NO. 1 ENGINE - AIRWORTHINESS DIRECTIVE TO PREVENT FAILURE OF THE FAN ROTOR DISC DUE TO FATIGUE CRACKING IN THE DOVETAIL SLOTS								MANDATORY		
		MOS							31-DEC-2002		
		HRS/MS	DUE								
	REF:	ENC									
	Method of Compliance: OPEN										
SB TFE731-A72-3668	NO. 1 ENGINE - REMOVE FAN ROTOR DISC FROM SERVICE SERVICE BULLETIN								MANDATORY		
		MOS							31-DEC-2002		
	ASSOCIATED	HRS/MS	A/R								
	REF: BULLETINS	ENC									
	Method of Compliance: OPEN										

Report Date **11-APR-2002**

Engine Model - TFE731-3
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC
A/C Serial #: 368 A/C Reg. #: N368MD

ITEM NO WORKCARD	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL	TIME-----AT-----INSTALLATION					COMPLIANCE	DISPOSITION NEXT DUE	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
ENGINE NO. 2											
AD 2000-15-09	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE HPC IMPELLER										
		MOS								10-OCT-2000	
		HRS/MS	4200								
	REF:	ENC									
	Method of Compliance: OPEN										
AD 2001-23-09	NO. 2 ENGINE - AIRWORTHINESS DIRECTIVE TO PREVENT FAILURE OF THE FAN ROTOR DISC DUE TO FATIGUE CRACKING IN THE DOVETAIL SLOTS								MANDATORY		
		MOS								31-DEC-2002	
		HRS/MS	DUE								
	REF:	ENC									
	Method of Compliance: OPEN										
SB TFE731-A72-3668	NO. 2 ENGINE - REMOVE FAN ROTOR DISC FROM SERVICE SERVICE BULLETIN								MANDATORY		
		MOS								31-DEC-2002	
	ASSOCIATED	HRS/MS	A/R								
	REF: BULLETINS	ENC									
	Method of Compliance: OPEN										

OWNER: R&S AIRCRAFT INVESTMENTS, LLC
ADDRESS: P.O. BOX 43 HOUSTON TX 77001-0043

OPERATOR: R&S AIRCRAFT INVESTMENTS, LLC
ADDRESS: P.O. BOX 43 HOUSTON TX 77001-0043

PHONE: 713-830-9584
FAX: 713-918-5925

PHONE: 713-830-9584
FAX: 713-918-5925

PROJECTED : 2 MOS. to 11-JUN-2002

AIRCRAFT

S/N: 368 **REG NO:** N368MD **MODEL:** 1124A WESTWIND **MANUFACTURER:** GULFSTREAM AEROSPACE CORPORATION

NOTE:
INSPECTION PROGRAM: 3
CERTIFICATE DATE: 11-FEB-1982

UOM	LAST ACTUAL	LAST ACTUAL DATE	PROJECTED
HRS	7806	28-FEB-2002	7926.8
AFL	5706	28-FEB-2002	5827

ENGINE NO. 1

S/N: P-77482 **PART NO:** 3072500-2 **MODEL:** TFE731-3 **MANUFACTURER:** HONEYWELL

INSTALLED DATE: 4/3/1989
A/C HRS: 4215
ENGINE HRS: 3972
ENGINE CYCLES: 2456

UOM	LAST ACTUAL	LAST ACTUAL DATE	PROJECTED
HRS	7806	28-FEB-2002	7926.8
ENC	0		0
(AFL)	5706	28-FEB-2002	5827

ENGINE NO. 2

S/N: P77488 **PART NO:** 3072500-2 **MODEL:** TFE731-3 **MANUFACTURER:** HONEYWELL

INSTALLED DATE: 5/31/1993
A/C HRS: 5278
ENGINE HRS: 5227
ENGINE CYCLES: 3867

UOM	LAST ACTUAL	LAST ACTUAL DATE	PROJECTED
HRS	7806	28-FEB-2002	7926.8
ENC	0		0
(AFL)	5706	28-FEB-2002	5827

Aircraft Model - 1124A WESTWIND

Serial #: 368 Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO	WORK CARD	TASK DESCRIPTION	UNIT	INTERVAL TIME-----AT-----INSTALLATION				COMPLIANCE	DISPOSITION	TIME	AREA
				WORK ORDER	PART NUMBER/PKG SERIAL NUMBER	TSN	TSO				
										LABOR	
								(ENH)	AFH (xEXT)	OVD = Overdue	
R	AD 2000-15-09	NO. 1 ENGINE - HPC IMPELLER AIRWORTHINESS DIRECTIVE									
			MOS					10-OCT-2000		New Reqmt	
		REF:	DUE NEXT	HRS/MSC	4200						
			ENC								
R	AD 2000-15-09	NO. 2 ENGINE - HPC IMPELLER AIRWORTHINESS DIRECTIVE									
			MOS					10-OCT-2000		New Reqmt	
		REF:	DUE NEXT	HRS/MSC	4200						
			ENC								
R	260169	VISUAL INSPECTION COCKPIT PORTABLE EXTINGUISHER	COCKPIT FIRE EXTINGUISHER							F3	
	26.060		DAYS	30			06-NOV-2001	06-DEC-2001		OVD	
		REF: NO REF	HRS/MSC				7774				
			AFL				5641				
R	260180	VISUAL INSPECTION CABIN PORTABLE EXTINGUISHER	CABIN FIRE EXTINGUISHER							F3	
	26.060		DAYS	30			06-NOV-2001	06-DEC-2001		OVD	
		REF: NO REF	HRS/MSC				7774				
			AFL				5641				
R	330228	CHARGE EMERGENCY LIGHT BATTERY								F4	
	33.100		MOS	3			06-NOV-2001	06-FEB-2002		OVD	
		REF: AMM 12-10-06	HRS/MSC	200			7774	7974		168	
			AFL				5641				
R	344616	INSPECT EMERGENCY GYRO POWER SUPPLY BATTERY	EMERGENCY POWER SUPPLY BATTERY/STAND-BY ATTITUDE GYRO							F5	
	34.370		MOS	3			06-NOV-2001	06-FEB-2002		OVD	
		REF: AMM NO REF	HRS/MSC	200			7774	7974		168	
			AFL				5641				
R	320118	INSPECT/LUBRICATE NOSE GEAR ASSEMBLY	UPPER/LOWER STRUT BEARINGS BODY							L3	
	32.540		MOS	24			22-FEB-2000	22-FEB-2002		OVD	
		REF: AMM 32-20-01	HRS/MSC	1200			7107	8307		501	
			AFL				5232				
R	230400	CLEAN/TEST COCKPIT VOICE RECORDER	BEACON							T1	
	23.130		MOS	6			06-NOV-2001	06-MAY-2002		0.8	
		REF: NO REF	HRS/MSC				7774				
			AFL				5641				

Total Labor Hours
Total Price :

R - Task was due on previous due lists
(xEXT) - Extension incorporated in the next due calculation

Maintenance Due List/Time Remaining - AIRCRAFT(HOURS)

Aircraft Model - 1124A WESTWIND

Serial #: 368 Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO	WORK CARD	TASK DESCRIPTION	UNIT	INTERVAL TIME-----AT-----INSTALLATION				COMPLIANCE	DISPOSITION	TIME	AREA
				TSN	TSO	TSR	WARR EXP				
	WORK ORDER	PART NUMBER/PKG SERIAL NUMBER						(ENH) AFH (xEXT)	OVD = Overdue	LABOR	
R	AD 2002-01-26	TO PREVENT FAILURE OF ATTACHMENT BOLTS DUE TO FATIGUE, WHICH COULD RESULT IN SEPARATION OF THE ENGINE INLET COWL AND AFT NACELLE, AND CONSEQUENT DAMAGE TO THE HORIZONTAL OR VERTICAL STABILIZER AIRWORTHINESS DIRECTIVE						MANDATORY			
		REF:	MOS						50	New Reqmt	
			HRS/MSC	DUE							
			AFL								
R	AD 1989-12-08	TO DETECT CRACKS IN THE HINGE LUGS OF THE HORIZONTAL STABILIZER AFT SPAR SPLICE FITTING (HINGE ASSEMBLY) AIRWORTHINESS DIRECTIVE									
		REF: See Workcard	MOS				17-JAN-2001				
			HRS/MSC	300			7494	7794		OVD	
			AFL				5466				
R	SB 1124-30-036 PART II	ICE AND RAIN PROTECTION SERVICE BULLETIN								F3	
		REF: See Workcard	MOS				26-JUN-2001				
			HRS/MSC	150			7687	7837		31	
			AFL				5594				
R	057110U	NO. 1 ENGINE - 150HR #1 ENGINE INSP									
		REF:	MOS				26-JUN-2001				
			HRS/MSC	150			7687	7837		31 1	
			ENC (AFL)				5594				
R	057110U	NO. 2 ENGINE - 150HR #2 ENGINE INSP									
		REF:	MOS				26-JUN-2001				
			HRS/MSC	150			7687	7837		31 1	
			ENC (AFL)				5594				
R	057120U	NO. 1 ENGINE - 300HR #1 ENGINE INSP									
		REF:	MOS				16-FEB-2001				
			HRS/MSC	300			7551	7851		45 1.5	
			ENC (AFL)				5515				
R	057120U	NO. 2 ENGINE - 300HR #2 ENGINE INSP									
		REF:	MOS				16-FEB-2001				
			HRS/MSC	300			7551	7851		45 1.5	
			ENC (AFL)				5515				
R	050150U	200 HOUR INSPECTION									
		REF:	MOS				26-JUN-2001				
			HRS/MSC	200			7687	7887		81 31	
			AFL				5594				
R	SL WW-2492	HYD HOSE INSP SERVICE LETTER									
		REF:	MOS				26-JUN-2001				
			HRS/MSC	200			7687	7887		81	
			AFL				5594				
	710120	NO. 2 ENGINE - MAJOR PERIODIC INSPECTION									
	71.010	REF: EMM 72-00-00	MOS				17-OCT-1998				
			HRS/MSC	1400			6520	7920		114	
			ENC (AFL)				4889				

R - Task was due on previous due lists
(xEXT) - Extension incorporated in the next due calculation

ITEM NO WORK CARD WORK ORDER	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL TIME-----AT-----INSTALLATION				COMPLIANCE WARR EXP	DISPOSITION NEXT DUE		TIME REMAINING OVD = Overdue	AREA PRICE LABOR
			TSN	TSO	TSR			(ENH)	AFH (xEXT)		
724120 72.030	NO. 2 ENGINE - INSPECT COMBUSTION PLENUM CASE	MOS HRS/MSC ENC (AFL)	1400				17-SEP-1998 6520 4889	7920	114		
	REF: EMM 72-40-04										
790120 79.020	NO. 2 ENGINE - CHANGE OIL	MOS HRS/MSC ENC (AFL)	1400				17-OCT-1998 6520 4889	7920	114		
	REF: See Workcard										
AD 1996-24-11 LEFT AILERON	TO PREVENT EXCESSIVE WEAR OF THE AILERON PUSH-PULL TUBE, WHICH COULD RESULT IN UNEVEN MOVEMENT OF THE CONTROL WHEEL, PERFORATION OF THE AILERON PUSH-PULL TUBE, AND CONSEQUENT REDUCED ROLL CONTROL OF THE AIRPLANE AIRWORTHINESS DIRECTIVE	MOS HRS/MSC AFL	600				26-JUL-2000 7325 5360	7925	119	W1	
	REF: AD										
AD 1996-24-11 RIGHT AILERON	TO PREVENT EXCESSIVE WEAR OF THE AILERON PUSH-PULL TUBE, WHICH COULD RESULT IN UNEVEN MOVEMENT OF THE CONTROL WHEEL, PERFORATION OF THE AILERON PUSH-PULL TUBE, AND CONSEQUENT REDUCED ROLL CONTROL OF THE AIRPLANE AIRWORTHINESS DIRECTIVE	MOS HRS/MSC AFL	600				26-JUL-2000 7325 5360	7925	119	W2	
	REF: AD										
SB 1124-27-129 LEFT AILERON	FLIGHT CONTROLS SERVICE BULLETIN	MOS HRS/MSC AFL	600				26-JUL-2000 7325 5360	7925	119	W1	
	REF: BULLETINS										
SB 1124-27-129 RIGHT AILERON	FLIGHT CONTROLS SERVICE BULLETIN	MOS HRS/MSC AFL	600				26-JUL-2000 7325 5360	7925	119	W2	
	REF: BULLETINS										

Total Labor Hours 36:0

Total Price :

R - Task was due on previous due lists
(xEXT) - Extension incorporated in the next due calculation



Maintenance Due List/Time Remaining - AIRCRAFT(AFL)

Aircraft Model - 1124A WESTWIND

Serial #: 368 Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO	TASK DESCRIPTION	UNIT	INTERVAL TIME-----AT-----INSTALLATION				COMPLIANCE	DISPOSITION	TIME	AREA
			TSN	TSO	TSR	WARR EXP				
WORK CARD	PART NUMBER/PKG						(ENH)	AFH (xEXT)	OVD = Overdue	LABOR
WORK ORDER	SERIAL NUMBER									
R	SB 972B40U	SERVICE BULLETIN G-SBA72-3569 R/E FAN ROTOR								
			MOS							
			HRS/MS	A/R						
			AFL					5722		16

REF:
Total Labor Hours
Total Price :

R - Task was due on previous due lists
(xEXT) - Extension incorporated in the next due calculation



Maintenance Due List/Time Remaining - ENGINE((AFL))

Aircraft Model - 1124A WESTWIND

Serial #: 368 Reg. #: N368MD

Report Date 11-APR-2002

ITEM NO	TASK DESCRIPTION	UNIT	INTERVAL TIME-----AT-----INSTALLATION				COMPLIANCE	DISPOSITION	TIME	AREA
			WORK CARD	PART NUMBER/PKG	TSN	TSO				
WORK ORDER	SERIAL NUMBER						(ENH) AFH (xEXT)	OVD = Overdue	LABOR	
R 725050	NO. 2 ENGINE - CHANGE FAN ROTOR DISC									
72.090	3073539-2 0-18040-4768 REF: NO REF	MOS HRS/MSC ENC (AFL)	4100	2660		20-MAY-1993 5278 3928		5368	OVD	
R 725030	NO. 2 ENGINE - CHANGE STAGE 3 LOW PRESSURE TURBINE DISC									
72.060	3072544-2 6-18040-4905 REF: NO REF	MOS HRS/MSC ENC (AFL)	3000	0		31-MAY-1989 4265 2793		5793	87	

Total Labor Hours
Total Price :

R - Task was due on previous due lists
(xEXT) - Extension incorporated in the next due calculation

OWNER: R&S AIRCRAFT INVESTMENTS, LLC
ADDRESS: P.O. BOX 43 HOUSTON TX 77001-0043

OPERATOR: R&S AIRCRAFT INVESTMENTS, LLC
ADDRESS: P.O. BOX 43 HOUSTON TX 77001-0043

PHONE: 713-830-9584
FAX: 713-918-5925

PHONE: 713-830-9584
FAX: 713-918-5925

PROJECTED : 2 MOS. to 11-AUG-2002

EXTENDED DUE LIST - FOR PLANNING PURPOSES ONLY - Scheduled Work Cards were not issued with this Report.

AIRCRAFT

S/N: 368 **REG NO:** N368MD **MODEL:** 1124A WESTWIND **MANUFACTURER:** GULFSTREAM AEROSPACE CORPORATION

NOTE:
INSPECTION PROGRAM: 3
CERTIFICATE DATE: 11-FEB-1982

UOM	LAST ACTUAL	LAST ACTUAL DATE	PROJECTED
HRS	7806	28-FEB-2002	7996.8
AFL	5706	28-FEB-2002	5897

ENGINE NO. 1

S/N: P-77482 **PART NO:** 3072500-2 **MODEL:** TFE731-3 **MANUFACTURER:** HONEYWELL

INSTALLED DATE: 4/3/1989
A/C HRS: 4215
ENGINE HRS: 3972
ENGINE CYCLES: 2456

UOM	LAST ACTUAL	LAST ACTUAL DATE	PROJECTED
HRS	7806	28-FEB-2002	7996.8
ENC	0		0
(AFL)	5706	28-FEB-2002	5897

ENGINE NO. 2

S/N: P77488 **PART NO:** 3072500-2 **MODEL:** TFE731-3 **MANUFACTURER:** HONEYWELL

INSTALLED DATE: 5/31/1993
A/C HRS: 5278
ENGINE HRS: 5227
ENGINE CYCLES: 3867

UOM	LAST ACTUAL	LAST ACTUAL DATE	PROJECTED
HRS	7806	28-FEB-2002	7996.8
ENC	0		0
(AFL)	5706	28-FEB-2002	5897



Extended Due List - AIRCRAFT(CALENDAR)

Aircraft Model - 1124A WESTWIND

Serial #: 368 Reg. #: N368MD

Report Date 11-APR-2002

EXTENDED DUE LIST - FOR PLANNING PURPOSE ONLY - Scheduled Work Cards were not issued with this Report.

ITEM NO WORK CARD WORK ORDER	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL TIME-----AT-----INSTALLATION				COMPLIANCE	DISPOSITION		AREA PRICE LABOR
			TSN	TSO	TSR	WARR EXP		NEXT DUE (ENH)	AFH (xEXT)	
270080	X-RAY INSPECT LEFT AILERON CONTROL ROD LEFT AILERON CONTROL ROD ASSEMBLIES								W1	
27.530	513506-503 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	60 5000			16-JUN-1997 6135 4707	16-JUN-2002 11135			
270081	X-RAY INSPECT RIGHT AILERON CONTROL ROD ASSEMBLY								W2	
27.535	513506-503 SN-UNKNOWN REF: NO REF	MOS HRS/MSC AFL	60 5000			16-JUN-1997 6135 4707	16-JUN-2002 11135			
270150	X-RAY INSPECT RUDDER CONTROL ROD ASSEMBLY								T1	
27.560	REF: NO REF	MOS HRS/MSC AFL	60 5000			16-JUN-1997 6135 4707	16-JUN-2002 11135			
270210	VISUAL INSPECT ELEVATOR CONTROL BELLCRANK ASSEMBLY									
27.570	REF: AMM 5-10-00	MOS HRS/MSC AFL	60 5000			16-JUN-1997 6135 4707	16-JUN-2002 11135			
320110	X-RAY INSPECT NOSE GEAR ASSEMBLY NOSE GEAR SHAFT AND DOOR ASSEMBLIES								L3	
32.560	REF: AMM 5-10-00	MOS HRS/MSC AFL	60 5000			16-JUN-1997 6135 4707	16-JUN-2002 11135			
260171	WEIGHT CHECK COCKPIT PORTABLE EXTINGUISHER COCKPIT FIRE EXTINGUISHER								F3	
26.030	REF: AMM 5-10-00	MOS HRS/MSC AFL	12			26-JUN-2001 7687 5594	26-JUN-2002			
260181	WEIGHT CHECK CABIN PORTABLE EXTINGUISHER CABIN FIRE EXTINGUISHER								F4	
26.030	REF: AMM 5-10-00	MOS HRS/MSC AFL	12			26-JUN-2001 7687 5594	26-JUN-2002			
350166U	CHECK PILOT OXYGEN MASK								F3	
35.070	REF: AMM 35-00-00	MOS HRS/MSC AFL	12 600			26-JUN-2001 7687 5594	26-JUN-2002 8287			
350169U	CHECK COPILOT OXYGEN MASK								F3	
35.070	REF: AMM 35-00-00	MOS HRS/MSC AFL	12 600			26-JUN-2001 7687 5594	26-JUN-2002 8287			

Total Labor Hours
Total Price :

R - Task was due on previous due lists
(xEXT) - Extension incorporated in the next due calculation

Aircraft Model - 1124A WESTWIND

Serial #: 368 Reg. #: N368MD

Report Date 11-APR-2002

EXTENDED DUE LIST - FOR PLANNING PURPOSE ONLY - Scheduled Work Cards were not issued with this Report.

ITEM NO WORK CARD WORK ORDER	TASK DESCRIPTION PART NUMBER/PKG SERIAL NUMBER	UNIT	INTERVAL TIME-----AT-----INSTALLATION				COMPLIANCE	DISPOSITION		AREA PRICE LABOR
			TSN	TSO	TSR	WARR EXP		NEXT DUE (ENH)	AFH (xEXT)	
R 330228 33.100	CHARGE EMERGENCY LIGHT BATTERY	MOS HRS/MSC AFL	3 200				06-NOV-2001 7774 5641	06-FEB-2002 7974	F4	
	REF: AMM 12-10-06									
R 344616 34.370	INSPECT EMERGENCY GYRO POWER SUPPLY BATTERY EMERGENCY POWER SUPPLY BATTERY/STAND-BY ATTITUDE GYRO	MOS HRS/MSC AFL	3 200				06-NOV-2001 7774 5641	06-FEB-2002 7974	F5	
	REF: AMM NO REF									
SB 1124-55-020 R2	STABILIZERS SERVICE BULLETIN	MOS HRS/MSC AFL	300				26-JUN-2001 7687 5594	7987	T1	
	REF: See Workcard									
SL WW-2494 R3 LEFT	LANDING GEAR SERVICE LETTER	MOS HRS/MSC AFL	300				26-JUN-2001 7687 5594	7987	L1	
	REF: See Workcard									
SL WW-2494 R3 RIGHT	LANDING GEAR SERVICE LETTER	MOS HRS/MSC AFL	300				26-JUN-2001 7687 5594	7987	L2	
	REF: See Workcard									

Total Labor Hours
Total Price :

R - Task was due on previous due lists
(xEXT) - Extension incorporated in the next due calculation

A/C Serial No.: 368 A/C Regn No.: N368MD Model:1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

Report Date **11-APR-2002**

Compliance From 01/01/2001 To 4/11/2002

ITEM NO PART NO.	DESCRIPTION SERIAL NO.	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED				COMPONENT TIMES AFTER REMOVAL				TECH :	INSP :	LABOR HRS :	SERVICE REMARKS
		C/W	TSN	TSO	TSR	C/W	TSN	TSO	TSR				
CHAPTER 05-TIME LIMITS/MAINTENANCE CHECKS													
050150U	200 HOUR INSPECTION												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
CHAPTER 10-PARKING, MOORING, STORE AND RET TO SERV													
100310	CHECK AIRWORTHY DIRECTIVES												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
100320	CHECK SERVICE BULLETINS												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
100330	CHECK SERVICE LETTERS												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
CHAPTER 12-SERVICING													
120150	CHECK PRE-FLIGHT												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
120160	CHECK NO.1 ENGINE PREFLIGHT COMPLETE												
		MOS	2/16/2001										
		HRS	7551										
		AFL	5515										
120161	CHECK NO.2 ENGINE PREFLIGHT COMPLETE												
		MOS	2/16/2001										
		HRS	7551										
		AFL	5515										
CHAPTER 21-AIR CONDITIONING													
210622	INSPECT 35 DEGREE TEMPERATURE SENSOR 35 DEGREE DUCT SENSOR												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
210671	CLEAN/REPLACE WATER SEPARATOR CONDENSER/FILTER												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
210681	CHANGE COOLING TURBINE OIL												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
CHAPTER 24-ELECTRICAL POWER													
240116	CHANGE NO. 1 STARTER GENERATOR												
23065-018-1	3684	MOS	1/17/2001	0			11/6/2001	10					
		HRS	7494	0			7774	280		TECH :			
		AFL	5466	0			5641	175		REASON : WORN			
										PRICE : 0			
240118	INSPECT NO. 1 STARTER GENERATOR												

A/C Serial No.: 368 A/C Regn No.: N368MD Model:1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

Report Date 11-APR-2002

Compliance From 01/01/2001 To 4/11/2002

ITEM NO PART NO.	DESCRIPTION SERIAL NO.	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED				COMPONENT TIMES AFTER REMOVAL					
		C/W	TSN	TSO	TSR	C/W	TSN	TSO	TSR		
		MOS	6/26/2001							TECH :	INSP :
		HRS	7687								LABOR HRS :
		AFL	5594								SERVICE REMARKS --
240121	CHECK NO. 1 STARTER GENERATOR	BRUSH WEAR/TENSION									
		MOS	6/26/2001							TECH :	INSP :
		HRS	7687								LABOR HRS :
		AFL	5594								SERVICE REMARKS --
240123	INSPECT NO. 1 STARTER GENERATOR	SPLINE									
		MOS	6/26/2001							TECH :	INSP :
		HRS	7687								LABOR HRS :
		AFL	5594								SERVICE REMARKS --
240128	INSPECT NO. 2 STARTER GENERATOR										
		MOS	6/26/2001							TECH :	INSP :
		HRS	7687								LABOR HRS :
		AFL	5594								SERVICE REMARKS --
240131	CHECK NO. 2 STARTER GENERATOR	BRUSH WEAR/TENSION									
		MOS	6/26/2001							TECH :	INSP :
		HRS	7687								LABOR HRS :
		AFL	5594								SERVICE REMARKS --
240133	INSPECT NO. 2 STARTER GENERATOR	SPLINE									
		MOS	6/26/2001							TECH :	INSP :
		HRS	7687								LABOR HRS :
		AFL	5594								SERVICE REMARKS --
240161	CHECK LEFT BATTERY	ELECTROLYTE LEVEL									
		MOS	1/17/2001							TECH :	INSP :
		HRS	7494								LABOR HRS :
		AFL	5466								SERVICE REMARKS --
240166	DEEP CYCLE LEFT BATTERY										
		MOS	6/26/2001							TECH :	INSP :
		HRS	7687								LABOR HRS :
		AFL	5594								SERVICE REMARKS --
240176	CHECK RIGHT BATTERY	ELECTROLYTE LEVEL									
		MOS	1/17/2001							TECH :	INSP :
		HRS	7494								LABOR HRS :
		AFL	5466								SERVICE REMARKS --
240181	DEEP CYCLE RIGHT BATTERY										
		MOS	6/26/2001							TECH :	INSP :
		HRS	7687								LABOR HRS :
		AFL	5594								SERVICE REMARKS --
240203	FUNCTIONALLY CHECK EXTERNAL POWER RECEPTACLE	BATTERY TEMPERATURE AND WARNING SYSTEM									
		MOS	1/17/2001							TECH :	INSP :
		HRS	7494								LABOR HRS :
		AFL	5466								SERVICE REMARKS --
CHAPTER 26-FIRE PROTECTION											
260169	VISUAL INSPECTION COCKPIT PORTABLE EXTINGUISHER	COCKPIT FIRE EXTINGUISHER									
		MOS	6/26/2001							TECH :	INSP :
		HRS	7687								LABOR HRS :
		AFL	5594								SERVICE REMARKS --
260174	INSPECT COCKPIT PORTABLE EXTINGUISHER	COCKPIT FIRE EXTINGUISHER									
		MOS	1/17/2001							TECH :	INSP :
		HRS	7494								LABOR HRS :
		AFL	5466								SERVICE REMARKS --

A/C Serial No.: 368 A/C Regn No.: N368MD Model:1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

Report Date 11-APR-2002

Compliance From 01/01/2001 To 4/11/2002

ITEM NO PART NO.	DESCRIPTION SERIAL NO.	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED				COMPONENT TIMES AFTER REMOVAL				TECH :	INSP :	LABOR HRS :	SERVICE REMARKS
		C/W	TSN	TSO	TSR	C/W	TSN	TSO	TSR				
260180	VISUAL INSPECTION CABIN PORTABLE EXTINGUISHER	MOS	6/26/2001										
		HRS	7687										
		AFL	5594										
260184	INSPECT CABIN PORTABLE EXTINGUISHER	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
CHAPTER 27-FLIGHT CONTROLS													
270158	INSPECT RUDDER TRIM TAB	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
270193	INSPECT LEFT ELEVATOR	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
270203	INSPECT RIGHT ELEVATOR	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
270213	LUBRICATE ELEVATOR ATTACH POINTS	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
270214	LUBRICATE AFT HINGE FITTING BEARINGS	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
270215	LUBRICATE FORWARD SCISSOR ASSEMBLY	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
270237	INSPECT LEFT FLAP/VANE	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
270240	INSPECT LEFT FLAP/VANE	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
270242	INSPECT RIGHT FLAP/VANE	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
270247	INSPECT RIGHT FLAP/VANE	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
270335	OPERATIONAL CHECK												

A/C Serial No.: 368 A/C Regn No.: N368MD Model:1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

Report Date 11-APR-2002

Compliance

From 01/01/2001

To 4/11/2002

ITEM NO PART NO.	DESCRIPTION SERIAL NO.	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED				COMPONENT TIMES AFTER REMOVAL				TECH :	INSP :	LABOR HRS :	SERVICE REMARKS
		C/W	TSN	TSO	TSR	C/W	TSN	TSO	TSR				
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
CHAPTER 28-FUEL													
281150	CHECK OPERATION OF FUEL BOOST PUMPS												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
CHAPTER 29-HYDRAULIC POWER													
290143	INSPECT/LUBRICATE NO. 1 HYDRAULIC PUMP NO.1 ENGINE HYDRAULIC PUMP SPLINES												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
290178	INSPECT/LUBRICATE NO. 2 HYDRAULIC PUMP NO.2 ENGINE HYDRAULIC PUMP SPLINES												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
950920	ACCOMPLISH SL WW-2492 HYD HOSE INSP BULLETIN												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
CHAPTER 30-ICE AND RAIN PROTECTION													
300147	INSPECT PILOT WINDSHIELD CYCLING CONTACTOR												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
300150	INSPECT COPILOT WINDSHIELD CYCLING CONTACTOR												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
300163	INSPECT WINDSHIELD WIPER ASSEMBLY												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
300170	OPERATIONAL TEST P2T2 SENSOR HEATER												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
910361	ACCOMPLISH SB 1124-30-036 PART II BULLETIN												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
CHAPTER 32-LANDING GEAR													
320106	LUBRICATE NOSE GEAR ASSEMBLY NOSE GEAR/DOORS												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
320156	INSPECT/CLEAN/LUBRICATE NOSE GEAR LEFT WHEEL BEARINGS												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										

A/C Serial No.: 368 A/C Regn No.: N368MD Model:1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

Report Date 11-APR-2002

Compliance From 01/01/2001 To 4/11/2002

ITEM NO PART NO.	DESCRIPTION SERIAL NO.	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED				COMPONENT TIMES AFTER REMOVAL				TECH :	INSP :	SERVICE REMARKS
		C/W	TSN	TSO	TSR	C/W	TSN	TSO	TSR			
320158	INSPECT/CLEAN/LUBRICATE NOSE GEAR RIGHT WHEEL BEARINGS	MOS	1/17/2001									
		HRS	7494									
		AFL	5466									--
320201	INSPECT NOSE GEAR (A)	MOS	1/17/2001									
		HRS	7494									
		AFL	5466									--
320606	LUBRICATE LEFT MAIN GEAR ASSEMBLY LEFT MAIN GEAR	MOS	1/17/2001									
		HRS	7494									
		AFL	5466									--
320676	INSPECT/LUBRICATE LEFT MAIN GEAR INBOARD WHEEL HALF LEFT MAIN GEAR INBOARD WHEEL BEARINGS	MOS	1/17/2001									
		HRS	7494									
		AFL	5466									--
320680	INSPECT/LUBRICATE LEFT MAIN GEAR OUTBOARD WHEEL HALF LEFT MAIN GEAR OUTBOARD WHEEL BEARINGS	MOS	1/17/2001									
		HRS	7494									
		AFL	5466									--
320691	INSPECT LEFT MAIN GEAR/WELL (A)	MOS	1/17/2001									
		HRS	7494									
		AFL	5466									--
321106	LUBRICATE RIGHT MAIN GEAR ASSEMBLY RIGHT MAIN GEAR	MOS	1/17/2001									
		HRS	7494									
		AFL	5466									--
321176	INSPECT/LUBRICATE RIGHT MAIN GEAR INBOARD WHEEL HALF RIGHT MAIN GEAR INBOARD WHEEL BEARINGS	MOS	1/17/2001									
		HRS	7494									
		AFL	5466									--
321180	INSPECT/LUBRICATE RIGHT MAIN GEAR OUTBOARD WHEEL HALF RIGHT MAIN GEAR OUTBOARD WHEEL BEARINGS	MOS	1/17/2001									
		HRS	7494									
		AFL	5466									--
321191	INSPECT RIGHT MAIN GEAR OUTBOARD WHEEL HALF RIGHT MAIN GEAR/WELL (A)	MOS	1/17/2001									
		HRS	7494									
		AFL	5466									--
322113	CHANGE LEFT MAIN GEAR BRAKE	MOS				1/17/2001						
5002805-3	12153-6	HRS				7494						
		AFL				5466						
322116	INSPECT/CHECK LEFT MAIN GEAR BRAKE LEFT BRAKE LININGS	MOS	1/17/2001									
		HRS	7494									
		AFL	5466									--
322128	CHANGE RIGHT MAIN GEAR BRAKE	MOS				1/17/2001						
5002805-3	1140	HRS				7494						
		AFL				5466						

A/C Serial No.: 368 A/C Regn No.: N368MD Model:1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

Report Date 11-APR-2002

Compliance

From 01/01/2001

To 4/11/2002

ITEM NO PART NO.	DESCRIPTION SERIAL NO.	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED				COMPONENT TIMES AFTER REMOVAL				TECH :	INSP :	LABOR HRS :	SERVICE REMARKS
		C/W	TSN	TSO	TSR	C/W	TSN	TSO	TSR				
322131	INSPECT/CHECK RIGHT MAIN GEAR BRAKE RIGHT BRAKE LININGS	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
322156	INSPECT/CLEAN LEFT ANTI-SKID DETECTOR	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
322171	INSPECT/CLEAN RIGHT ANTI-SKID DETECTOR	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
322174	OPERATIONAL CHECK ANTI-SKID LIGHTS	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
322206	FUNCTIONAL TEST EMERGENCY GEAR EXTENSION CONTROL CABLE	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
CHAPTER 33-LIGHTS													
330228	CHARGE EMERGENCY LIGHT BATTERY	MOS	6/26/2001										
		HRS	7687										
		AFL	5594										
CHAPTER 34-NAVIGATION													
340121	DRAIN PITOT/STATIC SYSTEM	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
344616	INSPECT EMERGENCY GYRO POWER SUPPLY BATTERY EMERGENCY POWER SUPPLY BATTERY/STAND-BY ATTITUDE GYRO	MOS	6/26/2001										
		HRS	7687										
		AFL	5594										
CHAPTER 52-DOORS													
520106	INSPECT/LUBRICATE CABIN ENTRANCE DOOR	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
520116	OPERATIONAL CHECK CABIN ENTRANCE DOOR	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
CHAPTER 53-FUSELAGE													
530101	INSPECT FUSELAGE (A)	MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
530116	INSPECT NOSE COMPARTMENT (A)												

A/C Serial No.: 368 A/C Regn No.: N368MD Model:1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

Report Date **11-APR-2002**

Compliance From 01/01/2001 To 4/11/2002

ITEM NO PART NO.	DESCRIPTION SERIAL NO.	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED				COMPONENT TIMES AFTER REMOVAL				TECH :	INSP :	LABOR HRS :	SERVICE REMARKS
		C/W	TSN	TSO	TSR	C/W	TSN	TSO	TSR				
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
530131	INSPECT COCKPIT (A)												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
530146	INSPECT CABIN (A)												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
530161	INSPECT REAR COMPARTMENT (A)												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
CHAPTER 54-NACELLES/PYLONS													
540101U	INSPECT NO. 1 ENGINE NACELLE/PYLON (A)												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
540121U	INSPECT NO. 2 ENGINE NACELLE/PYLON (A)												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
CHAPTER 55-STABILIZERS													
550101	INSPECT EMPENNAGE (A)												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
550656	CHECK HORIZONTAL STABILIZER AFT SPAR SPLICE-HINGE FITTING OUTBOARD LUGS FOR CRACKS												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
CHAPTER 57-WINGS													
570101	INSPECT LEFT WING (A)												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
570106	INSPECT LEFTAILERON BELLCRANK												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
570116	INSPECT RIGHT WING (A)												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										
570120	INSPECT RIGHTAILERON BELLCRANK												
		MOS	1/17/2001										
		HRS	7494										
		AFL	5466										

CHAPTER 71-POWER PLANT

A/C Serial No.: 368 A/C Regn No.: N368MD Model:1124A WESTWIND
Owner Name - R&S AIRCRAFT INVESTMENTS, LLC

Report Date 11-APR-2002

Compliance From 01/01/2001 To 4/11/2002

ITEM NO PART NO.	DESCRIPTION SERIAL NO.	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED				COMPONENT TIMES AFTER REMOVAL					
		C/W	TSN	TSO	TSR	C/W	TSN	TSO	TSR		
710650U	-- INSP #1 ENG INLET NACELLE									TECH :	INSP :
		MOS	1/17/2001								LABOR HRS :
		HRS	7494								SERVICE REMARKS --
		AFL	5466								
713650U	-- INSP #2 ENG INLET NACELLE									TECH :	INSP :
		MOS	1/17/2001								LABOR HRS :
		HRS	7494								SERVICE REMARKS --
		AFL	5466								