

TAILWIND INSPECTION, INC.
REPAIR SERVICES FOR THE AIRCRAFT INDUSTRY
3260 N SHERIDAN ROAD
TULSA, OK 74115
918.832.0700 FAX 918.832.0755
FAA CRS T0WR995N

W.O. NO: 6141

NONDESTRUCTIVE TESTING REPORT


INSPECTION TYPE: RT UT ET MT PT VT

| | |
|---|---------------------------------------|
| CUSTOMER: AVIATION SERVICES UNLIMITED | LOCATION: OKLAHOMA CITY, OK |
| MANUFACTURER: IAI | MODEL: WESTWIND 1124A |
| REGISTRATION: N83SG | SERIAL NUMBER: 368 |
| TOTAL HOURS: 9086.3 | TOTAL LANDINGS: 6515 |
| DATE INSPECTED: 3/18/08 | DATE OF MANUFACTURE:: NA |
| INSPECTION PROCEDURE/SPECIFICATION AS PER WW1124A NDT MANUAL PROCEDURES LISTED. | |
| EQUIPMENT/CALIBRATION/STANDARDS USED LORAD LPX 160 TUBE, AGFA D4 PB FILM | |

DISCREPANCIES/RESULTS

| |
|---|
| PERFORMED THE FOLLOWING X-RAY INSPECTIONS AS PER PROCEDURES LISTED: |
| PART 2 27-10-00 AILERON CONTROL SYSTEM RODS: NO DISCREPANCIES. |
| PART 2 27-20-00 RUDDER CONTROL SYSTEM RODS: NO DISCREPANCIES. |
| PART 2 32-20-00 NOSE LANDING GEAR DOOR CONTROL RODS: NO DISCREPANCIES |
| END OF REPORT. |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |

Tailwind Inspection, Inc. hereby certifies that the work accomplished herein has been performed in accordance with the applicable Federal Aviation Regulations and is approved for return to service with regard to the inspection(s) performed unless discrepancies are noted.

| | | |
|---|-------------|---------|
|  | II | 3/18/08 |
| SIGNATURE OF INSPECTOR <small>FOR TAILWIND INSPECTION, INC. - FAA CERTIFIED REPAIR STATION T0WR995N</small> | CERT. LEVEL | DATE |



TAILWIND INSPECTION, INC.
 NDT SERVICES FOR THE AIRCRAFT INDUSTRY
 3260 N SHERIDAN ROAD
 TULSA, OK 74115
 918.832.0700 FAX 918.832.0755
 FAA CRS T0WR995N

WORK ORDER NO: 6141
18016

WORK ORDER FORM

| | | | |
|--|---------------------------------|--|-------------------------------|
| COMPANY: AVIATION SERVICES UNLIMITED | | DATE: 3/18/08 | |
| PURCHASE ORDER No: 20516 | | CONTACT: WAYNEO'BERG | |
| LOCATION: OKLAHOMA CITY, OK | | PHONE/FAX: 405-787-8111 / 405-787-0010 | |
| AIRCRAFT: IAI | MODEL: WESTWIND 1124A | SERIAL NUMBER: 368 | REGISTRATION: N83SG |

| QTY | DESCRIPTION |
|----------|--|
| | PERFORMED THE FOLLOWING X-RAY INSPECTIONS AS PER IAI WW 1124A |
| | NDT MANUAL PROCEDURES LISTED: |
| 1 | PART 2 27-10-00 AILERON CONTROL SYSTEM RODS |
| 1 | PART 2 27-20-00 RUDDER CONTROL SYSTEM RODS |
| 1 | PART 2 32-20-00 NOSE LANDING GEAR DOOR CONTROL RODS |
| | |
| 1 | TRAVEL AND EXPENSES TO CUSTOMER FACILITY INCLUDED. |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

NOTE: CHARGES FOR ADDITIONAL WORK PERFORMED AND/OR STAND-BY TIME AS NOTED ABOVE WILL BE ADDED TO YOUR ORIGINAL QUOTATION

CUSTOMER REPRESENTATIVE _____ DATE _____

Tailwind Inspection, Inc. certifies that the items listed have been inspected in accordance with the manufacturer's specifications and/or Tailwind Inspection, Inc. NDE Procedures Manual. We, as the contractor, shall not be held liable for loss, damage, injury, or death arising from or subsequent to the performance of an inspection. In all cases liability shall be limited to the amount charged in this work order. By signing this work order, you, as the customer or customer's agent, agree to pay in cash when the work is completed or on terms satisfactory to you, and until paid, such obligation shall constitute a lien on the aircraft or parts listed hereon. You also agree to pay legal interest upon any past due, delinquent account for the work provided herein, as well as collection costs including reasonable attorney's fees, and hereby waive all rights to claim exemption under any state laws.